



September 27, 2000

T10/00-300 revision 2

To: John Lohmeyer, chairperson, T10
From: Bob Snively
Date: September 27, 2000
Subject: Installation of corrections in FCP-2

Document T10/00-150r6 documents the resolution of the comments submitted during the balloting on revision 04 of the FCP-2 document. This document indicates how the resolutions were installed in the subsequent revisions of the FCP-2 document.

Headers in red indicate comments that are considered to require particularly careful review.

Headers in blue indicate technical or editorial comments that have been installed in the document without any concerns being identified by the editor.

This revision includes the actions taken at the September 11, 2000 meeting of the SCSI command and protocol working group. The actions include both corrections and approvals of all those items flagged with a red header in T10/300-r1.

1 Comments from Crossroads Systems, Inc.

The following comments accompanied the ballot from Neil Wanamaker of Crossroads Systems, Inc.

1.1 Crossroads 1 (E): Global

There are hanging paragraphs at the beginning of many chapters (4,5,6,7,8...). These will require changes for ISO.

Response:

Accepted.

Installation: Corrected in clauses 2, 3, 5, 6, 7, 8, 9, 10, 11, 12, Annex A, Annex C, Annex D, Annex E, Annex F, and Annex G

1.2 Crossroads 2 (E): Foreword

The committee lists are void (or nearly so).

Response:

Accepted.

Installation:

Installed in Foreword. **NCITS committee list will be installed later.**

1.3 Crossroads 3 (E): 2.2

FC-PH-2 is an approved standard. The next four are under development by T11. This section also needs an X3-ectomy.

Response:

Brocade Communications Systems, Inc.
1901 Guadalupe Parkway n San Jose, CA 95131
T 408.487.8000 n F 408.487.8101
www.brocade.com

Accepted.

Installation:

Installed as requested. Note that the FC-PH-x documents were all replaced with references to FC-FS.

1.4 Crossroads 4 (E): 2.3

The first sentence refers to a singular reference; there are two. SFF-8045 also appears twice (strike the first).

Response:

Accepted:

Installation:

Installed as requested.

1.5 Crossroads 5 (T): 3.1.7

This doesn't match the definition in SAM-2.

Response:

Accepted. SAM-2 and FCP-2 will change the term "command byte count" to "data buffer size". (March 6, 2000).

Installation:

Installed as approved. Note that a change is still required in SAM-2 to complete the alignment.

1.6 Crossroads 6 (E): 3.2, FCP-2

X3.

Response:

Accepted.

Installation:

Removed FCP-2 reference as unnecessary.

1.7 Crossroads 7 (E): 4.2 Par 6

I would suggest inclusion of a note about residual data handling.

Response:

Accepted in principle. Editorial details need to be worked out. At the June 7, 2000 FCP-2 working group meeting, the following update was accepted.

Specifically, what is asked for is a note about the fact that the response may include other information which is neither a protocol error, nor a bad SCSI status, such as underrun/overrun conditions.

Installation:

Installed as requested.

1.8 Crossroads 8 (E): 4.2 Par 7

After "proper status" in first sentence, add parenthetical note (i.e., INTERMEDIATE or INTERMEDIATE CONDITION MET).

Response:

Accepted.

Installation:

Installed as requested.

1.9 Crossroads 9 (E): 4.2 Par 7

After "an IU that allows command linking" add parenthetical note (i.e., not last sequence of exchange).

Response:

The second sentence actually refers to a particular IU type, I5. This will be clarified. This response was accepted in the June 7, 2000 working group meeting.

Installation:

Installed as requested.

1.10 Crossroads 10 (T): 4.2 Par 7

This paragraph does not appear to allow breaking linking by presentation of an error or busy status.

Response:

The concern is accepted, although some work remains on the resolution.

At the meeting of March 6, 2000, the following partial resolutions were agreed upon:

The first two sentences of the offending paragraph will be corrected to include the possible case for breaking a command link.

There is an implication that linked commands are indivisible. After careful review of SAM-2, I find no evidence that linked commands must be executed without allowing other tasks to enter the enabled and current states.

There was some discussion about whether or not linked commands can be ended by a BUSY status. SAM-2 indicates that linking can be broken by BUSY status.

Wording from SAM-2, pdf page 68, concerning Intermediate Status will be incorporated as appropriate.

This response was accepted by the balloter at the June 7, 2000 working group meeting.

Installation:

Added the following text to 4.2, with few other changes.

SAM-2 defines the cases that interrupt and terminate a series of linked commands. In those cases, the FCP_RSP of the last command in the set of linked commands shall be transmitted using the IU that does not allow command linking, I4.

1.11 Crossroads 11 (E): 4.2 last par

Add mention of 3d party/extended copy operations.

Response:

Accepted. Wording remains to be worked out.

Installation:

The following wording was added:

For host to host communications, either one of the communicating pair can take on the SCSI initiator role. For device to device communications, used to implement extended copy and other third-party operations, the SCSI initiator role is adopted by the managing device.

1.12 Crossroads 12 (T): 4.4 par 1

Last sentence should read "confirmed completion is allowed by an initiator". The PRLI contains no information about the target's ability to deal with FCP_CONF.

Response:

The target should not request a function that is not supported by an initiator. The sentence will be: "PRLI parameters are used to determine that confirmed completion is allowed by an initiator and may be requested by a target communicating with that initiator." (Accepted March 6, 2000)

It was discussed that there may need to be separate indications for initiators and targets in the PRLI about supporting FCP_CONF. After close examination, it was determined that the bit only applied to the initiator function. Note that section 6.2.6.8 or other parts of 6.2 may also need to be corrected to reflect this.

Installation:

The change in 4.4 was made as requested.

After review, no changes were required in 6.2.6.8.

1.13 Crossroads 13 (E): 4.5 Par 3

In first sentence, after "both the initiator and target", add parenthetical note (i.e., by setting RETRY in PRLI).

Response:

Accepted, but with editorial improvement.

Installation:

Installed as agreed.

1.14 Crossroads 14 (E/T): 4.5 Par 3 and many subsequent places

Reference to FCP-2 ELS, rather than FC-4 Link Data Request.

Response:

I believe the correct terms should be FCP-2 Link Service Request and FCP-2 Link Service Reply. I will always write the appropriate term out, avoiding any non-standard abbreviations. This response was agreed to in the June 7, 2000 working group meeting.

Installation:

Installed in 4.5, 6.3.5, and several sections of clause 12.

1.15 Crossroads 15 (E/T): 4.7 Par 2

Third sentence should read: Task management functions that use the FCP_CMND IU end with an FCP_RSP IU that indicates whether it was correctly completed.

Response:

Accepted.

Installation:

Installed. Note that "correctly completed" is different than the original "correctly accepted" requirement, but is consistent with SAM-2.

1.16 Crossroads 16 (E): Table 4 (second page)

Column headings not required on second page.

Response:

Accepted.

Installation:

Installed as requested.

1.17 Crossroads 17 (E): Table 4 Note 2

The reference to "the SCSI initiator" actually refers to the initiator issuing the task management function. An alternate initiator has no knowledge of the clearing action until a subsequent command has been issued (and receives a Unit Attention), and so cannot be expected to perform ABTS for the associated exchanges.

Response:

Note 2 refers only to open sequences, not to outstanding exchanges. A reference will be provided here to clause 9.1.1.4 for the proper management of exchanges with no open sequences. In addition, the work being done on a new status byte by Charles Binford will clarify part of this problem, including the notification to an unsuspecting initiator that its tasks have been destroyed.

Installation:

The reference was installed in note 2.

1.18 Crossroads 18 (E): 4.9

The header is in all lower case.

Response:

The heading will be changed to read: "Process login/logout".

Installation:

Installed as requested.

1.19 Crossroads 19 (E): 5.3 Par 1

The last half of the paragraph seems to imply that targets will discover reconfiguration events and this will drive his discovery of a changed initiator address.

In real life, targets do not typically register for events like RSCN, and do not probe for initiators. Normally, the change in initiator address is discovered by a new PLOGI from an entity having the same WWN but a new S_ID.

Suggest that the paragraph simply refer to the effect of receipt of a PLOGI from an entity having the same WWN as an object holding a persistent reservation.

Response:

The wording does not require the target to detect such behavior, nor does it specify the mechanism used to detect the reconfiguration. As you point out, it will usually be a new PLOGI that finally notifies the target of the change.

After discussion, the working group agreed on June 7, 2000 that a new PLOGI/PRLI with same WWN but a different port address shall be recognized as evidence that the initiator identifier has changed (the old conundrum of "if the port recognizes an error occurred...").

Installation:

Installed as approved.

1.20 Crossroads 20 (E): 5.4, Table 9

The third line of the note should read "I3 allows..."

Response:
Accepted.
Installation:
Installed as requested.

1.21 Crossroads 21 (T): 6.2 Par 3

6.2.7.1 suggests that an ACC with Image Pair Established = 0 may also indicate that the PRLI request is not accepted (this behavior has been observed in the wild).

Response:

I believe that the intent of the different cases is that:

- a) LS_RJT means that the PRLI ELS was not accepted, either because it was invalid or because PRLI is not supported.
- b) Image Pair Established = 0 means that the command was accepted, but that the image pair was not established, perhaps because the parameters were invalid, perhaps because the conditions in the target or initiator did not allow the establishment of the pair.

Installation:

In section 6.3.1, the following text was installed:

A link service reject (LS_RJT) indicates that the PRLI request is ~~not accepted~~ not supported or is incorrectly formatted.

The previous sentence is also modified to indicate that the PRLI accept may also indicate lack of acceptance.

In section 6.3.8.2, the text remains unchanged:

If this bit is set to 0, the image pair was not established. The **ACCEPT RESPONSE CODE** has additional information.

1.22 Crossroads 22 (T): 6.2.5 Par 1

The behavior if the change in parameters does not affect any outstanding exchanges is not specified (see (24) below).

Response:

At the March 6, 2000 committee meeting, it was decided that the paragraph should be rewritten to clarify explicitly what would happen under three conditions:

What would happen if the page of parameters was presented with the same values?

At present, this is explicitly a case where no operation is affected, but the text should be modified as above.

What would happen if the page of parameters was presented with different values, but no exchanges existed for that image pair?

At present, this is explicitly a case where Unit Attention is offered on the next command for that image pair.

What would happen if the page of parameters was presented with different values, but exchanges existed for that image pair?

At present, this is specified in Table 4, where it indicates that open sequences and exchanges for the modified image pair are cleared.

At present, these ideas are scattered across paragraphs 1 and 2. The paragraphs need to be consolidated and rewritten.

At the April 5, 2000 meeting, it was decided that this should be simplified. Image pairs are always reset and their exchanges cleared. This is true for binding PRLIs, not for informational PRLIs. An implicit logout, together with the appropriate clearing actions, is performed. See also 5.7.

Note that this behavior is not specified in FC-FS.

Installation:

These two paragraphs were significantly rewritten as follows:

Immediately after the execution of any new or repeated binding PRLI, both members of all image pairs successfully established shall have the same state as they would have after a hard reset or a power on with respect to each other. All clearing actions specified in 4.9 shall be performed. Tasks, reservations, status, and MODE SELECT parameters for other image pairs are not affected. A Unit Attention condition (Sense Key = 6) with an Additional Sense Code of Reset Occurred (ASC = 29, ASCQ = 00) shall be established for the image pair's target and initiator. A target port shall not generate a unit attention condition for initiators in other image pairs.

If the change in parameters affects any outstanding FCP exchanges, those exchanges shall be terminated by the initiator using a recovery abort operation. A recovery qualifier may be established after the recovery abort, temporarily restricting the choice of OX_ID values. Only actions for image pairs that are being referenced by the PRLI are affected.

1.23 Crossroads 23 (T): 6.2.5 Par 2

The description of Unit Attention does not match SPC/SAM (Inquiry, Request Sense) behavior.

Response:

The PRLI acts like a power-on reset, so the corresponding Unit Attention is provided.

At the March 6, 2000 committee meeting, it was pointed out that this should be corrected to indicate that the Unit Attention condition was established. All behavior after that is standard and already specified.

Installation:

See 1.22.

1.24 Crossroads 24 (T): 6.2.5 Par 2 last sentence

This statement conflicts with 4.7 table 4, which indicates that all open FCP sequences and all open tasks are terminated on receipt of a PRLI, and that device reservations are cleared (CRN also cleared).

Response:

Table 4.7 needs to be corrected to reflect this behavior. See 9.20 Sun 20.

The proper management also needs to be corrected. See 1.22 Crossroads.

Installation:

Reviewing this in FCP-2 revision 4, I did not identify the problem. After the corrections installed in revision 4a, I found that these now appear consistent.

1.25 Crossroads 25 (E): 6.2.5 last par

Non-acknowledged class responders are not to terminate an exchange with ABTS (some later section). Normal practice (see 12.7) is to return a LOGO in this case.

Response:

Accepted. This was accepted in the April 5, 2000 meeting.

Installation:

After reviewing FC-FS, it is not clear whether or not LOGO actually terminates sequences. The only abnormal sequence/exchange termination mechanism appears to be ABTS. I believe both options should be left open. I have forced initiators to use ABTS. See 1.22 Crossroads.

1.26 Crossroads 26 (E): 6.2.6.7 Par 3 (p.26)

LS_RJT should be FCP_RJT (see 8).

Response:

Accepted.

Installation:

Installed as requested.

1.27 Crossroads 27 (T): 6.2.6.8 (p.26)

There are existing implementations that require targets to set CONFIRMED COMPLETION ALLOWED. Do we want to legitimize this behavior?

Response:

No. Targets should still be able to work, although with less rapid recovery and with more unrecoverable errors, even if the initiator does not choose to support confirmed completion. No change is required to the document.

Installation:

No change was made.

1.28 Crossroads 28 (E): 8. (p. 31 et. seq.)

Either put 8.1 after 8.2, 8.3 (as an instantiation of the general case), adding a generic 8.1 on FC-4 Link Data Frames, or make 8.2, 8.3 specific to SRR responses.

Response:

Accepted. Clause 8.1 will be placed after clause 8.2 and 8.3.

Installation:

This was complicated by taking in the REC FCP FC-4 Link Service. The ordering was changed to:

- 8.1 List of services (Accept was removed)
- 8.2 REC and REC ACC
- 8.3 SRR and SRR ACC
- 8.4 FCP FC-4 Reject

The FCP FC-4 ACC was already defined in 8.1, and the payloads defined in 8.2 and 8.3. At the same time, the words “concise exchange status” were removed, since they are really simply the payload of the REC ACC.

1.29 Crossroads 29 (E): 8 First sentence (p. 31)

The type field should be shown as 08h as everywhere else. Should R_CTL be binary or hex?

Response:

The type field should be shown as hexadecimal, although FC-FS shows them as binary.

R_CTL is actually composed of two 4-bit fields, expressed in FC-FS as binary values. They will remain expressed in binary.

Installation:

No change was required.

1.30 Crossroads 30 (E): 8. Table 15 (p.31)

Column header refers to bits 31-24. Should indicate of what.

Response:

Accepted. The bits are Word 0 of the payload, similar to FC-FS Table 49, pdf page 168.

Installation:

Added specification of word 0 in the header.

1.31 Crossroads 31 (E): 8.1 Par 1 (p.31)

Should read "or request retransmission of information".

Response:

Accepted.

Installation:

Installed as requested.

1.32 Crossroads 32 (E): 8.1 Pars 2, 3 (p.31)

Par 2 refers to reason code hex '09', par 3 to reason code 00092A00h. These should be made consistent (and be either reason code & explanation or reason code).

Response:

Accepted. They shall both use reason code and explanation. The explanation for the case defined in the second paragraph will be: 17h, Invalid OX_ID-RX_ID combination.

Installation:

After considerable study, the T10 convention of using the names of the reason code and reason code explanation was used. The explanation cod "invalid OX_ID-RX_ID combination" is 03h in FC-FS, so that value was selected. Since the data was fully contained in the reject definitions, the text and table 18 were removed.

1.33 Crossroads 33 (E): 8.1 top of page 33

Should have heading Reject Payload:

Table 18 header should indicate reason code & explanation.

Response:

Accepted. These will be taken from FC-FS pdf page 187.

Installation:

See 1.32

1.34 Crossroads 34 (T): 8.1 top of page 33

Should have reason code for request not supported.

Response:

That is covered in Table 20. During the March 6, 2000 committee meeting, the committee decided that no change is required. Other comments may require additional text in this area.

Installation:

No change was required beyond 1.32.

1.35 Crossroads 35 (E) 8.2, 8.3 (p33)

No indication of remaining payload (or note that it isn't to be returned on SRR ACC/RJT).

Response:

The remainder of the ACC/RJT payload will be defined in a manner similar to 15.5.2 of FC-FS.

Installation:

After performing the other corrections, the payload was completely specified in the table, so that there was no question of what was contained in it.

1.36 Crossroads 36 (T) 8.3 (Reason Code Descriptions) (p34)

It appears from the description that 01h and 0Bh mean the same; Table 20 suggests otherwise.

Response:

This needs to be verified against FC-FS. My impression is that 01 means that the ELS is in an invalid format, which may include invalid operation codes. 0B means that the ELS operation code, while known (maybe valid or maybe invalid), is not one of those supported by the device. The distinction should be made clearer in the text by removing the word "supported" from the 01 description.

The committee assigned me an action item to request this correction in FC-FS. I have posted document T11/00-184v0 to address this problem.

Installation:

Installed as requested. Note that 184v0 has not yet been installed in FC-FS and I have asked Jim Nelson to fix that.

1.37 Crossroads 37 (T) 9.1.1.2 (p 37)

In out-of-order fabric cases, this means that an initiator must wait R_A_TOV after issuing the last FCP_CMND affected by the task management function before issuing a task management function, else the command might arrive after the task management function. This requirement could be made unnecessarily if CRNs applied to TM functions.

Response:

There is no guaranteed order between the actual execution of task management functions and the state of commands in the target in the SAM or SAM-2 documents. Because of this, there is no need to create ordering procedures. In addition, Task Management functions are designed to correct behavior when ordering has already failed. No change is required in section 9.1.1.2.

The committee requested the following additional changes in the March 6, 2000 meeting:

Section 4.3 needs to add Abort Task Set and Clear Queue to the list of task management functions that clear CRN.

Table 4 on page 13 needs to add Abort Task Set and Clear Queue to the list of items that clear CRN.

Section 9.1.1.4 needs to either contain similar wording or refer to table 4. In the interest of avoiding diverging definitions, I believe the wording of most of the detailed task management functions should reference table 4 for most of the clearing operations.

Installation:

No change is required in 4.3, since it references the clearing actions in tables 4 and 5.

In table 5, CRN is cleared to one for all SCSI initiators by CLEAR TASK SET.

In table 5, CRN is cleared for the aborting initiator only by ABORT TASK SET.

In 9.1.1.4, the clearing actions in table 5 are referenced.

1.38 Crossroads 38 (T) 9.1.1.3 (Ordered) (p 37)

The third sentence of the ORDERED_Q description indicates that sequential delivery must (shall??) be used to ensure correct ordering. Precise delivery would also meet the requirements of ORDERED_Q operation.

Response:

The assured ordering associated with waiting for completion is an alternate mechanism for assuring precise delivery when the precise delivery function is not implemented. The availability of this alternate mechanism will be made clear.

At the March 6, 2000 meeting, the committee requested that this be moved to the model, section 4.3. The text would make clear that there are three valid mechanisms for assuring proper ordered behavior:

- 1) In-order delivery is required of the fabric at login time.
- 2) CRN is specified in the mode page.
- 3) Command completion is awaited before issuing the next command.

The text in 9.1.1.3 would then reference the model.

After further review in the June 7, 2000 working group, it was pointed out that in order fabric delivery is not sufficient to guarantee in-order execution. It must be removed from the list.

Installation:

Option 3 above is now included in sub-clause 4.3. Sub-clause 9.1.1.3 is modified to reference sub-clause 4.3.

1.39 Crossroads 39 (T) 9.1.1.3 (Untagged) (p 37)

5.6.9 indicates that targets aren't required to detect this. These sections should be made consistent (and probably in the direction of SAM).

Response:

The individual tagging by Fibre Channel protocols makes truly overlapped commands impossible. However, SAM specifies that you can only have one command with the attribute of Untagged at a time. This is expected to be verified by FCP-2 devices.

In the March 6, 2000 meeting, the committee further requested that the last sentence of the Untagged attribute be removed. No other change is required.

Installation:

Installed as approved.

1.40 Crossroads 40 (E) 9.1.1.4 (pp 38 - 40)

In the definition of each of the function bits the phrase "the xxx bit is mandatory" should be replaced by "Support of the xxxx bit is mandatory".

Response:

Accepted.

Installation:

Installed as requested.

1.41 Crossroads 41 (T) 9.2 par 3 (p 42)

Change "...precisely that amount of data." to "...precisely that amount of data in a single sequence" (or FCP_DATA IU).

Response:

Accepted. See 3.8.

Installation:

After review, the third paragraph was combined and rewritten into the first for improved clarity.

1.42 Crossroads 42 (T) 9.3 par 4 last sentence (p 43)

9.2 indicates that all but the first data IU are preceded by FCP_XFER_RDYs.

Response:

The comment is correct. This sentence will be corrected accordingly.

Installation:

Installed as requested.

1.43 Crossroads 43 (T) 9.4 par 2 second sentence (p 44)

Many devices return RSP_LEN_VALID (and equal to 8) on all completions. Are these to be made non-compliant?

Response:

Considerable discussion occurred as a result of this question at the March 6, 2000 meeting. The following conclusions were reached:

- 1) There was agreement that such devices are non-compliant. The text should be changed to read:
Bytes 10 and 11 ~~are normally~~ shall be 0 upon successful completion of a FCP I/O Operation, indicating that no other information is present in the FCP_RSP. (done)
- 2) It was pointed out that the text should also indicate that, if FCP_RESP_VALID=1, the STATUS field shall be ignored. (done)
- 3) The text must be reviewed to be sure that Task Management explicitly requires a valid FCP_RESP field to present the completion state. If this is not explicitly stated, the text must be modified to include that. (done)
- 4) The text of 9.4.10, next to the last sentence, is incomplete and should be modified to read:
The task management function may or may not have been performed by the target if a RSP_CODE ~~value other than 0~~ is returned or if no FCP_RSP is returned before the Exchange is aborted. (done)
- 5) In table 28 of section 9.4.10, the words "No failure or" are deleted from the first row. (done)

Installation:

In addition to the requested modifications above, the following was added to 9.4.11:

Operations started by a task management function may continue after the FCP_RSP for the task management has been delivered.

1.44 Crossroads 44 (T) 9.4.7 par 3 (p 46)

The value should be FCP_DL - highest offset of any byte transmitted -1.

Response:

Accepted.

Installation:

Installed as requested.

1.45 Crossroads 45 (T) 9.4.11 par 1 (p. 48)

COMMAND TERMINATED status is no longer in SAM-2.

Response:

Accepted.

Installation:

Installed as requested.

1.46 Crossroads 46 (E) 12.5.2, 12.6.1, 12.7, F.2 (pp. 68-69, 109-110)

There are numerous references to NL_Port; this material also applies to N_Ports.

Response:

Accepted in principle. Note that the proper term, defined in 3.1.19 and further explained in 4.1, is FCP_Port for most of these cases. A search and global correction will be made.

Affected clauses:

Corrections were installed in the following clauses: 5.1, 6.2.5, 6.3, 12.5.2, 12.7, B.3.1, F.1, F.2,

1.47 Crossroads 47 (T) 12.6.1. last par (p 69)

The implication of the penultimate sentence is that if the target is not on a remote loop that it is connected on a local loop. This is not a valid inference; switches don't deal real well with Selective Reset LIPs.

Response:

The committee, in their March 6, 2000 meeting, discussed in more detail the overall content and structure of the second level recovery clause. This is also relevant to 5.22 LSI. The following conclusions were reached.

1) At present, second level recovery is mandatory. Instead, the committee indicated that the text should recommend that second level recovery not be performed and that an appropriate ABTS-LS or ABTX should be performed to clear the exchange resources.

2) If a device chooses to go beyond simply giving up, it should use FC-FS recovery mechanisms, not detailed here. In most cases, those mechanisms are so vaguely defined that interoperability may be a challenge.

3) If the ABTS-LS fails, it may be appropriate to recommend a link level reset, but this was not made as a firm statement.

4) The text should be restructured to clearly relate 12.1.1 with 12.5. The text of 12.1.2 should be clearly related to the actual recovery techniques, including the text of 12.6.

This response was approved by the committee in the April 5, 2000 meeting as part of the analysis of 5.22 LSI and 5.23.

Installation:

Section 12.6.1 is changed as follows:

If a response to an ABTS is not received within 2xR_A_TOV_{ELS}, the SCSI Initiator may send the ABTS again, attempt other retry operations allowed by FC-FS, or explicitly logout the SCSI Target. shall:

a) ~~send the ABTS again.~~

If those retry operations attempted are unsuccessful, a response to the second ABTS is not received within 2xR_A_TOV_{ELS}, the SCSI Initiator shall explicitly logout (FC-PH Logout, LOGO) the SCSI Target. ~~If the~~

~~SCSI Target is not on a remote loop, the SCSI Initiator may issue the Selective Reset LIP (LIP,AL_PD,AL_PS) to reset the SCSI Target.~~ All outstanding Exchanges with that SCSI Target are terminated at the SCSI Initiator.

1.48 Crossroads 48 (T) 12.7 last sentence (p 69)

The last sentence should read something like: "If any other FCP-level frame is received before PLOGI or PRLI, the sequence receives a P_RJT, with reason not logged in if F_CTL indicated first sequence, else reason invalid F_CTL."

Response:

At the March 6, 2000 meeting, the committee agreed upon the following modifications:

- 1) The last sentence ("For the action taken...TBD") of 12.7 should be deleted.
- 2) The third paragraph of clause 12.7 should be modified to read as follows:

~~If a SCSI Target receives an FCP_DATA Sequence from a SCSI Initiator with which it has not successfully completed Process Login (PRLI), it shall discard all Frames of that Sequence and may send PR-LO.~~

If a SCSI device receives a frame of category 0001b or 0011b (solicited data or solicited control) and the SCSI device is has not performed a successful explicit or implicit PLOGI and PRLI with the source of the frame, the SCSI device shall discard and ignore the content of the frame. If the PLOGI is not completed, the SCSI device may transmit a LOGO extended link service request to the source of the unexpected frame. If the PLOGI is completed, but the PRLI is not completed, the SCSI device may transmit a PRLO extended link service request to the source of the unexpected frame.

- 3) The last paragraph of clause 6.2.5 conflicts with the proposed text of 12.7. The offending paragraph in 6.2.5 will be deleted.

Installation:

The changes were installed as described. Affected clauses include 12.7 and 6.2.5.

1.49 Crossroads 49 (E) B.2.1 (p 77)

Is there any action that will cause this to be included in FC-FS?

Response:

I don't know. I will check.

I checked. There was no such reference. I have prepared document T11/00-284v0 (T10/00-230r0) to address this and any other similar questions.

Installation:

Completed. The section is now installed in FC-FS and can be removed from annex B.

1.50 Crossroads 50 (E) C.1.6, Table C.6 (p 83)

The first response might have a parenthetical note (INTERMEDIATE or INTERMEDIATE CONDITION MET).

Response:

Accepted.

Installation:

Installed as requested.

1.51 Crossroads 51 (E) I.1 bullet c (p 117)

..should read "return FCP_RSP for the task management function..."

Response:

Accepted.

Installation:

Annex I is deleted. See 9.145 Sun 145.

1.52 Crossroads 52 (E) after J.1.5 (p 120)

There should be a J.1.6 "ABTS changes" with reference to B.2.1.

Response:

Accepted.

Installation:

The changes are now included in FC-FS and need not be referenced in Annex J. Annex J is deleted.

1.53 Crossroads 53 (E) after page 120

There is a curious page after page 120 that could be omitted.

Response:

Accepted.

Installation:

Installed as requested.

2 ENDL

The following comments accompanied the ballot from Ralph O. Weber of ENDL Associates. Mr. Weber indicates that all these comments are editorial.

2.1 ENDL-1 FCP/FCP-2 (Editorial)

In the Introduction list of clauses, some clauses are said to discuss or define information for FCP while others are said to cover FCP-2. Is it realistic to have some clauses describing FCP features and other clauses describing FCP-2 features? It seems to me that all clauses should discuss one or the other, either the protocol being described is FCP or FCP-2. FCP-2 ought to be one document describing one protocol, not one document describing two protocols. Note also, that if FCP-2 chosen for use throughout, the second paragraph of the Introduction needs to be changed too.

Response:

Accepted.

Installation:

Installed as requested. The selected word is FCP for all but references to this standard.

2.2 ENDL-2 T10/T11 (Editorial)

Clause 2.2 first sentence. Change from: "At the time of publication, the following referenced standards were still under development by X3T10." to: "At the time of publication, the following referenced standards were still under development by T10 and T11." Note that several of the standards listed below this sentence are T11 projects.

Response:

Accepted.

Installation:

Installed as requested.

2.3 ENDL-3 (Editorial)

Clause 2.2 last paragraph first sentence. Change from: "Copies of these X3T10 draft documents are available for purchase from Global Engineering Documents." to: "Copies of these T10 and T11 draft documents are available for purchase from Global Engineering Documents." Same comment as ENDL-2.

Response:

Accepted.

Installation:

Installed as requested.

2.4 ENDL-4 (Editorial)

Clause 2.2 last paragraph first sentence: "Copies of these X3T10 draft documents are available for purchase from Global Engineering Documents." Would it not be better to provide pointers to the T10 and T11 web sites? Even if Global Engineering is still maintaining copies of T10 and T11 committee drafts documents, the web sites must be more up to date.

Response:

Accepted.

Installation:

Installed as requested.

2.5 ENDL-5 (Editorial)

Clause 3 only paragraph. It seems appropriate and helpful to add a sentence to this paragraph that describes the references in square brackets that appear in some definitions.

Response:

Accepted.

Installation:

Changed to plain English.

2.6 ENDL-6 (Technical)

Clause 3.1.13. It looks like the definition of data overlay is proposal a change to SAM-2, yet I know of no pending or approved proposals to make a change of this nature. SAM-2 r11 does not contain the word 'overlay' and there are not pending proposals to add the word 'overlay' that I know of.

It may also be that no SAM-2 changes are necessary. Clause 5.3.1 in both SAM and SAM-2 contains the following statement: "If an SCSI protocol supports random buffer access, as described below, the offset and byte count specified for each data segment to be transferred may overlap." This statement appears to cover the needs of the FCP-2 3.1.13 definition of data overlay. Perhaps all that is required to tie the knot here are editorial changes to the data overlay definition, with the following replacement definition seeming adequate to me: "Data overlay occurs when random buffer access capability is used to transfer data to or from the same the same area of application client buffer more than once during the same command. [ANSI X3.270]"

Response:

Accepted in principle. After review of the work done at the March 6, 2000 committee meeting, it appears that there may actually be two separate functions at work here with different requirements and definitions.

SAM-2 defines “random buffer access capability”. This is really the function enabled by the Enable Modify Data Pointers function. This breaks down into two types of random buffer access capability, one where the data is transmitted only once for each allowed data pointer value, the other where data is transmitted more than once for at least one allowed data pointer value. The first functionality is typically associated with re-ordering transfers to improve performance, while second functionality is more often associated with retries required by device level error recovery.

Neither of these is related to the FCP-2 retry functionality, which retransmits data nominally for the same data pointer value, but at a logical level before the data has been transferred to or from the buffer on behalf of the SCSI protocol. This function is not “data overlay”.

To properly encompass this idea, the following changes need to be made.

3.1.13, redefine data overlay (done)

data overlay: The use of random buffer access capability where data is transmitted using the same data pointer value more than one time during a data delivery action.

New glossary section, define random buffer access capability (done)

random buffer access: The occurrence of device server data transfer requests that request data transfers to or from segments of the application client's buffer which have an arbitrary offset and extent.

Section 6.2.6.7, removes “data overlay” from retry function, delete last paragraph. (done)

~~If the image pair is allowed to use the retransmission capability, overlay of data as defined for SRR shall be allowed regardless of the state of the DATA OVERLAY ALLOWED bit.~~

Section 6.2.6.9, rewrite “data overlay allowed” paragraph. (done)

When this bit is set to 1, the process defined by the page is indicating that its initiator function has the capability of supporting data overlay. When the bit is set to 0, the initiator function does not have the capability of performing data overlay. The bit shall be 0 for devices having only target function. If the initiator function supports data overlay, then a target may optionally perform random buffer access that performs a transfer to or from the same offset in transfer FCP_DATA IUs that are moving data from or to the application client buffer more than once during execution of a command.

Data transmission requested by the initiator during the optional retry procedures defined by this standard is managed by the initiator. Such data retransmissions are not considered data overlays, even if retransmission occurs to the same offset in the application client buffer.

~~If the RETRY bit is set to 1, data overlay shall be allowed as defined for SRR regardless of the state of the DATA OVERLAY ALLOWED bit. Any other use of data overlay shall be allowed only by the DATA OVERLAY ALLOWED bit.~~

DATA OVERLAY ALLOWED is a PRLI capability that is only defined for the initiator function.

Section 9.3, no rewrite is required by this comment, although paragraph 7 does need some clarification. (no change)

Section 10.1.1.7, rewrite to use the proper term of “random buffer access”.

The ENABLE MODIFY DATA POINTERS (EMDP) bit indicates whether or not the target may use the random buffer access capability to reorder FCP_DATA IUs for a single SCSI command. If the EMDP bit is zero, the target shall generate continuously increasing DATA_RO values for each FCP_DATA sequence for a single SCSI command. If the EMDP bit is one, the target may transfer the FCP_DATA IUs for a single SCSI command in any order. An EMDP bit of zero prohibits data overlay, even if it is allowed by the state of the PRLI DATA OVERLAY ALLOWED bit. This bit does not affect the order of frames within a sequence. The EMDP function is optional for all FCP-2 devices.

~~If the RETRY bit is one (see 6.2.6.7), data overlay and pointer modification shall be allowed as defined for SRR regardless of the state of the EMDP bit.~~

Installation:

Installed as requested.

2.7 ENDL-7 (Technical)

Clauses 3.1.25 and 3.1.26. It is difficult to see the difference between 3.1.25 (logical unit identifier) and 3.1.26 (logical unit number). SAM and SAM-2 differentiate these two objects by stating that a logical unit identifier is a combination of a target identifier and a logical unit number, i.e., a logical unit number is a constituent of a logical unit identifier. Following the SAM lead, 3.1.25 should read: "Identifier used by an initiator to reference the logical unit and the target that contains that logical unit. [ANSI X3.270]"

Response:

Analysis by the committee in their March 6, 2000 meeting indicated that the term "logical identifier" was used only two times in section 9.1.1. The term will be changed to "logical unit" and the glossary definition of logical unit identifier will be removed. This was accepted by the commenter in a June 2, 2000 e-mail.

Installation:

Installed as approved in 9.1.1 and 3.1.26.

2.8 ENDL-8 (Editorial)

Clause 3.1.27. Regarding the following definition: "A mode of operation on a Loop where MCM circuits are established between one or more MCM L_Port pairs without arbitration." What's a 'Loop'? There is no definition for a 'Loop'. Either add a definition for 'Loop' or change 'Loop' to 'arbitrated loop' which would reasonably be a definition from FC-AL, incorporated here by reference.

Response:

MCM has been removed from FC-AL-3. The MCM related terms will be removed from the glossary.

Installation:

Installed as requested.

In addition, the MCM values were removed from the Fibre Channel Port Control mode page and associated text.

2.9 ENDL-9 (Technical)

Clause 3.1.41. The definition of tag is incomplete as written: "The initiator-specified component of the task identifier." The task attribute is equally well an initiator-specified component of a task identifier. A more correct definition would be: "The initiator-specified component of a task identifier that uniquely identifies one task among the several tasks coming from that initiator."

Also, it might be helpful to add FCP-2 specific information to the definition. The following sentence is proposed for addition at the end of the definition text: "In FCP-2, tag is the contents of the OX_ID field in the FCP-2 frame header."

Response:

The first paragraph of the comment is accepted. The second paragraph of the tag attempts to include portions of the standard in the definitions, and should not be included. This response was approved the committee on March 6, 2000.

Installation:

Installed as approved.

2.10 ENDL-10 (Editorial)

Clause 3.2. The usage of CRN as an abbreviation for Command Reference Number is pervasive enough to justify addition of an abbreviation definition, suggest: "CRN Command Reference Number (see 4.3)"

Response:

Accepted.

Installation:

Installed as requested.

2.11 ENDL-11 (Editorial)

Clause 3.4 second sentence. Change from: "These words and terms are defined either in or in the text where they first appear." to: "These words and terms are defined either in 3.1 or in the text where they first appear."

Response:

Accepted.

Installation:

Installed as requested.

2.12 ENDL-12 (Editorial)

Clause 3.4 second paragraph. In so far as I can tell the following editorial convention is not observed in 90% or more FCP-2: "The names of fields are in small uppercase (e.g., ALLOCATION LENGTH). When a field name is a concatenation of acronyms, uppercase letter may be used for readability (e.g., NORMACA). Normal case is used when the contents of a field are being discussed. Fields containing only one bit are usually referred to as the NAME bit instead of the NAME field."

For example, all the fields in the FCP Frame Header (Table 10 and subsequent text) are normal height all caps. The fields in the FCP service parameter page, PRLI request (Table 11) are in small caps, but the first letter of each field name is in full height cap even though I can see no readability reason to do this. Bit (field) names such as EPDC and PS are in full height caps, and spelled out acronyms such as enable precise delivery checking (following Table 31) are in small caps with occasional full height caps.

These problems are most egregious in the Disconnect-Reconnect mode page definition, where the use of full height caps is in direct conflict with the notation used in SPC-2.

FCP-2 should be carefully reviewed and modified to make the use of small caps match the description in the paragraph shown above. Also, the notation for field names in the Disconnect-Reconnect mode page should be made consistent with the notation found in SPC-2.

Response:

Accepted in principle. An additional sentence will be added to clause 3.4, second paragraph to say: Where fields defined in another standard are referenced in this standard, the capitalization conventions of this standard are used.

This was accepted in a June 2, 2000 e-mail from the balloter.

Installation:

This was installed as approved. Note that I believe the added text meant to apply to the capitalization conventions of the *other* standard, not *this* standard.

Information units were added to the convention for all caps.

Words fixed:

All FC-FS field names were left in small caps, but capitalized as in the proper document.

Task attributes are all capitalized as in SAM-2.

Task management functions are all capitalized as in SAM-2.

There are a few cases where IUs are included in field names. The IU remains capitalized in that case, while the rest of the field name is in small caps.

The bits in the Disconnect/Reconnect mode page are mapped where possible to the same format as the SPC-2 document.

Abbreviation used in field names are in small caps, which is a change.

Most changes were confined to clauses 6, 9, and 10.

2.13 ENDL-13 (Editorial)

Clause 3.4 second paragraph second sentence. Change from: "NORMACA" to "NormACA" with the letters appearing in lower case appearing as small capitals. (Small caps can't be represented in plain text.)

Response:

Accepted. This will be done consistent with SPC-2.

Installation:

Installed as requested.

2.14 ENDL-14 (Editorial)

Clause 4.1 paragraph just before Table 1. Regarding the following wording: "The FCP-2 device and task management protocols define the mapping of the SCSI functions defined in SAM and SAM-2 to the FC-FS. ... The I/O Operation defined by ANSI X3.270 is mapped into an exchange."

SAM is identically the same thing as ANSI X3.270 and referring to the one document by two different names in the same paragraph can only serve to obfuscate the meaning of FCP-2. Pick one identifier and use it with religious consistency. I prefer SAM, or better still SAM-2.

I believe there is a similar problem with using FC-PH and ANSI X3.230 as synonyms.

Response:

Accepted. See 4.29.

Installation:

Installed as requested.

2.15 ENDL-15 (Editorial)

Clause 4.1 paragraph just before Table 1. The following wording: "The FCP-2 device and task management protocols define the mapping of the SCSI functions defined in SAM and SAM-2 to the FC-PH." leads the reader to believe that a mapping for the SAM-2 task management functions will appear soon (probably in Table 1). This is not the case and the task management mapping does not appear until clause 4.7 (some five pages hence). I believe that the most natural way to guide the reader to the right clause would be the addition of the following sentence between the current second and third sentences of the paragraph: "4.7 defines the mapping for task management functions." After this addition and other corrections discussed above, the paragraph would read:

"The FCP-2 device and task management protocols define the mapping of the SCSI functions defined in SAM-2 to ~~the FC-PH~~ the Fibre Channel interface defined by FC-FS. Link control is performed by standard FC-FS protocols. ~~The FCP-2 is based on a two-level paradigm. 4.7 defines the~~

~~mapping for task management functions. The task management functions defined by SAM-2 are mapped as described in 4.7 of this standard.~~ The I/O Operation defined by SAM-2 is mapped into a Fibre Channel exchange. The request and response primitives of an I/O Operation are mapped into information units. ~~Link control is performed by standard FC-PH protocols. This is as~~ shown in table 1."

Response:

Accepted in principle. See adjustments above.

Installation:

Installed as accepted.

2.16 ENDL-16 (Editorial)

Clause 4.2 first and second sentences. The following seems to be wanting to reference SAM-2: "An application client begins a FCP I/O Operation when it provides to the FCP a request for an Execute command service." However, the wording fails to match SAM-2 (or SAM) and there is no specific reference to SAM-2. Better wording would be: "An application client begins a FCP I/O Operation when it invokes an Execute Command remote procedure call (described in SAM-2)."

Similarly, the second sentence ("A single request or a list of linked requests may be presented to the software interface of the FCP.") needs work to correlate with SAM-2. Better wording would be: "The Execute Command call conveys a single request or a list of linked requests from the application client to the FCP service delivery subsystem."

Response:

Accepted.

Installation:

Installed as requested.

2.17 ENDL-17 (Editorial)

Clause 4.2 second paragraph second sentence. Here's another almost correct reference to SAM-2: "The FCP_CMND payload is the Send SCSI Command service request and starts the FCP I/O Operation." Better wording would be:

"The FCP_CMND payload is the Send SCSI Command protocol service request (described in SAM-2) and starts the FCP I/O Operation."

Response:

Accepted.

Installation:

Installed as requested.

2.18 ENDL-18 (Editorial)

Clause 4.2 third paragraph. Since every paragraph thus far in this clause has tied the FCP actions to SAM-2 defined protocol services, why not do the same in this paragraph. Suggest adding the following sentence before the sentence that begins: "Exactly one FCP_DATA IU ...": "The FCP_XFER_RDY and FCP_DATA payloads constitute the Receive Data-Out protocol service request and Data-Out Received service confirmation described in SAM-2."

Response:

Accepted.

Installation:

Installed one sentence earlier in the document.

2.19 ENDL-19 (Editorial)

Clause 4.2 forth paragraph. As with ENDL-18, why not tie the FCP operations to the SAM-2 defined protocol services in this paragraph? Suggest adding the following sentence at the end of the paragraph: "The FCP_DATA payload constitutes the Send Data-In protocol service request described in SAM-2."

Response:

Accepted.

Installation:

Installed as requested.

2.20 ENDL-20 (Editorial)

Clause 4.2 first sentence after note. Here's another almost correct reference to SAM-2: "After all the data has been transferred, the device server transmits the Send Command Complete service response by requesting the transmission of an IU containing the FCP_RSP payload." Better wording would be: "After all the data has been transferred, the device server transmits the Send Command Complete protocol service response (described in SAM-2) by requesting the transmission of an IU containing the FCP_RSP payload."

Response:

Accepted.

Installation:

Installed as requested.

2.21 ENDL-21 (Editorial)

Clause 4.2 second sentence after note. The following sentence offers a plethora of opportunities to deepen the coordination between FCP-2, SAM-2, and SPC-2: "That payload contains the SCSI status and, if an unusual condition has been detected, the SCSI REQUEST SENSE information describing the condition." Suggest the following rewrite: "That payload contains the SCSI status and, if the SCSI status is CHECK CONDITION, the autosense data describing the condition."

The change from "unusual condition" to "CHECK CONDITION" status is justified because the only time sense data can appear in the FCP_RSP payload is when the SCSI status is CHECK CONDITION (with autosense). If the sense data is returned in response to a REQUEST SENSE command or as the result of Asynchronous Event Reporting, it will appear in an FCP_DATA payload.

To augment the change from "REQUEST SENSE information" to "autosense data", the following definitions should be added:

"3.1.x autosense data: Sense data (see 3.1.y) that is returned in the FCP_RSP IU payload."

"3.1.y sense data: Data returned to an application client as a result of an autosense operation, asynchronous event report, or REQUEST SENSE command (see SPC-2)."

Also throughout FCP-2, all uses of "SCSI REQUEST SENSE information" should be replaced with "autosense data". The only uses I found were the two occurrences in clause 4.2 first paragraph after note (one noted here and the other noted in comment ENDL-21).

Note: acceptance of this comment also obligates SPC-2 to make its definition of "sense data" consistent with the definition shown above. The editor agreed in the September 11, 2000 meeting that the definitions were consistent.

Response:

Accepted.

Installation:

Installed as requested. The changes were installed in 3.1.x, 3.1.y, 4.2, 9.4.1, 9.4.12, 12.4.1.7,

2.22 ENDL-22 (Editorial)

Clause 4.2 fifth sentence after note. The following sentence needs changes for clarity and to coordinate with SAM-2: "The SCSI logical unit determines whether additional commands will be performed in the FCP I/O Operation." Better wording would be: "The device server determines whether additional linked commands will be performed in the FCP I/O Operation."

In my mind, the device server is the entity that processes the command(s) within a task (thus the first change). Additionally, this sentence is referring to the relationship between several linked commands in a single task, not to the relationship between several different unlinked commands (each in their own task). That needs to be clarified.

I am aware that you have received another comment on this sentence requesting that "logical unit" be changed to "task manager". That comment would be correct if the sentence were referring to several unlinked commands. Since the sentence is referring to linked commands, the change requested here is correct.

Response:

Accepted.

Installation:

Installed as requested.

2.23 ENDL-23 (Editorial)

Clause 4.2 last sentence in first paragraph after note. The verb number in these following sentence is wrong: "If an FCP protocol error occurred during execution of the command, the FCP_RSP payload carry the FCP Response information instead of the SCSI status and SCSI REQUEST SENSE information." There is but one FCP_RSP payload, so it "carries" the information. If there were several payloads, they would "carry" the information. Also, this is the only other occurrence of "SCSI REQUEST SENSE information" that I could find. My preferred wording is: "If an FCP protocol error occurred during execution of the command, the FCP_RSP payload carries the FCP Response information instead of the SCSI status and autosense data."

Response:

Accepted.

Installation:

Installed as requested.

2.24 ENDL-24 (Editorial)

Clause 4.2 first sentence in second paragraph after note (in r4 this is the paragraph at the top of PDF page 70). The following sentence needs changes to coordinate with SAM-2: "When the command is completed, returned information is used to prepare and return the Execute Command service confirmation information to the software that requested the operation." Better wording would be: "When the command is completed, returned information is used to prepare and return the Command Complete Received protocol service confirmation to the application client that requested the operation."

Response:

Accepted.

Installation:

Installed as requested.

2.25 ENDL-25 (Editorial)

Clause 4.2 last sentence in second paragraph after note. If one is to follow the nomenclature in SAM-2 clause 4.12, then the following sentence needs changes: "The SCSI target can optionally request confirmation of the status delivery, as described in 4.4." In SAM-2 "confirmation" is a protocol service action between the initiator LLP and ULP layers. The protocol service being described here is an "indication" and that "indication" occurs between the target LLP and ULP layers. Thus, I think the better wording would be: "The device server can optionally request a protocol service indication that confirms delivery of the FCP_RSP payload, as described in 4.4."

Response:

Accepted.

Installation:

Installed as requested.

2.26 ENDL-26 (Editorial)

Clause 4.2 last sentence in the clause. A substantial FCP-2/SPC-2 cleanup is needed in and around the following sentence (and now seems like as good a time as any to do the work): "For Asynchronous Event Notification, the peripheral device takes on the SCSI initiator role to inform the host, in its target role, that an asynchronous event has occurred."

The SAM-2 (and for that matter SAM) name for this feature is AER (Asynchronous Event Reporting) and FCP-2 should be using that name. The intention (as I remember it) has always been that SPC (now SPC-2) should define AEN (Asynchronous Event Notification) as a specific implementation of AER. If this comment is accepted, SPC-2 will be obliged to hold up its end of the bargain and define AEN (I have material ready for a proposal to make the change SPC-2).

In FCP-2, the sentence shown above should be deleted and the following new paragraph should be added at the end of clause 4.2.

"FCP-2 implements Asynchronous Event Reporting (see SAM-2) using the Asynchronous Event Notification (AEN) model in SPC-2. The AEN model reports asynchronous events by requiring that the peripheral device take on the SCSI initiator role to deliver the asynchronous event sense data to the host, which is required to act as a SCSI target using the processor device model for the duration of the AEN reporting process."

Response:

Accepted.

Installation:

Installed as requested.

2.27 ENDL-27 (Editorial)

Clause 4.3 second paragraph last sentence. The following is not the way cross references are handled in SCSI documents: "See "10.1.2" on page 53." The accepted wording is: "See 10.1.2." Note the removal of both the page reference and the quotation marks.

Response:

Accepted.

Installation:

Installed as requested.

2.28 ENDL-28 (Editorial)

Clause 4.3 third paragraph first sentence. Regarding the following: "Precise delivery of SCSI commands uses the COMMAND REFERENCE NUMBER (CRN) in the FCP_CMND IU." The SCSI editorial convention is that the use of small caps for COMMAND REFERENCE NUMBER requires that it be followed by the word field. Also, if ENDL-10 has been accepted then the definition of the CRN abbreviation need not appear in this sentence. Thus the preferred wording would be: "Precise delivery of SCSI commands uses the COMMAND REFERENCE NUMBER field in the FCP_CMND IU." with the usage of small caps being as currently exists in the document, not as shown here (small caps cant be represented in plain text).

Response:

Accepted.

Installation:

Installed as requested.

2.29 ENDL-29 (Editorial)

Clause 4.3 third paragraph second sentence. There are a couple of problems in the following: "For each device server having the EPDC bit set to one, the application client places a monotonically increasing one byte integer in the CRN field for each command that is transmitted that also requires precise delivery." Is the integer signed or (more probably) unsigned? Also, the abbreviation CRN is used almost universally to mean the content of the field not the name of the field, therefore, CRN should be replaced with small caps COMMAND REFERENCE NUMBER field. Better wording would be: "For each device server having the EPDC bit set to one, the application client places a monotonically increasing one byte unsigned integer in the COMMAND REFERENCE NUMBER field for each command requiring precise delivery that is transmitted." Remember, COMMAND REFERENCE NUMBER is in small caps. The use of small caps for the EPDC bit is covered by comment ENDL-12.

Response:

Accepted.

Installation:

Installed as requested.

2.30 ENDL-30 (Technical)

Clause 4.4 third, forth and fifth paragraphs. I have several problems with the following paragraphs:

"The confirmed completion function may be used to confirm that a SCSI initiator has received an FCP_RSP reporting a SCSI CHECK CONDITION status, together with accompanying sense information. The SCSI target requests in an FCP_RSP IU containing CHECK CONDITION status and sense information that an FCP_CONF be returned by the Initiator. Upon receiving the FCP_CONF, the SCSI target can be assured that the initiator has the information necessary to perform stateful(sic) recovery and can then discard its own copy of the information. If the FCP_CONF is not returned, the SCSI target may be requested by the initiator to retransmit the FCP_RSP, assuring eventual receipt of the critical information by the initiator.

"The confirmed completion function may be used to confirm that a queued SCSI command has been completed and that the completion information has been successfully transferred to the initiator. The SCSI target requests in an FCP_RSP IU that an FCP_CONF be returned by the

initiator. That allows subsequent queued stateful(sic) operations to be performed, since the FCP_CONF confirms that the FCP_RSP has been received by the initiator. If the FCP_CONF is not returned, the SCSI target may be requested by the initiator to retransmit the status information, assuring proper synchronization of the state of operations on the initiator and target.

"The confirmed completion function may be used to confirm that a SCSI initiator has received an FCP_RSP if a target process requires confirmation that the initiator has accepted the FCP_RSP completion information."

First, the fact that "The confirmed completion function may be used to confirm that a SCSI initiator has received an FCP_RSP" is repeated three times, once at the beginning of each paragraph. Surely, this is rhetorical overkill.

Second, 9.4.1 has no requirement that FCP_CONF_REQ be set to 1 only when the status is CHECK CONDITION (as implied by the first paragraph). As far as I can tell from 9.4.1, it is perfectly valid for a device server to set FCP_CONF_REQ to 1 when the status is GOOD. So, all the bluster about CHECK CONDITION status and sense data is misleading and could result in incompatible implementations.

Third, I can find no mechanism to support the last sentence of the first paragraph: "If the FCP_CONF is not returned, the SCSI target may be requested by the initiator to retransmit the FCP_RSP, assuring eventual receipt of the critical information by the initiator." It looks to me like the target may voluntarily elect to retransmit the FCP_RSP IU, but I can find no mechanism for an initiator to use to request the retransmission.

Forth, the second paragraph appears to be missing a step. Read literally as it currently is written, the mere act of setting the FCP_CONF_REQ bit to 1 in an FCP_RSP IU is sufficient to verify to the target that the FCP_RSP IU was received by the initiator. Read the second and third sentences in the second paragraph carefully.

Fifth, stateful is not in the Random House Unabridged Dictionary second edition, neither is it in the FCP-2 glossary. It appears to be a word with no meaning.

Sixth, we find here yet another name for autosense data, to wit "sense information", that needs to be replaced with term "autosense data" defined in comment ENDL-21.

With all of this in mind, the following wording seems better for the three paragraphs:

"The confirmed completion function may be used by a SCSI target to confirm that a SCSI initiator has received an FCP_RSP IU. If the confirmed completion function is supported by the initiator, a target may it whenever verification is required that the initiator has accepted the FCP_RSP IU and the information contained therein. Requirements on a target to maintain queued commands state information or autosense data after transmitting the FCP_RSP IU are examples of instances where use of the confirmed completion function may be useful, since successful completion of the confirmed completion function may allow the target to discard such state information and data.

"The target requests in an FCP_RSP IU that an FCP_CONF be returned by the initiator. Upon detecting the confirmed completion request in an FCP_RSP IU, the initiator shall transmit an FCP_CONF IU. Receipt of the FCP_CONF IU verifies to the target that the FCP_RSP has been received by the initiator."

Response:

The following resolutions were reached in the March 6, 2000 meeting of the committee.

- 1) The word "stateful" will be changed to "state dependent".

- 2) It will be clarified editorially that the third, fourth, and fifth paragraphs are 3 separate reasons one might choose to use FCP_CONF.
- 3) The description of the operation of FCP_CONF will be separated from the descriptions of why it may be used.
- 4) "sense information" s/b "autosense data" (See 2.21)
- 5) The third comment above addresses the possibility that the recovery of a missing FCP_CONF may not be defined in the recovery process. I believe it is correctly defined, but will review the text to be sure.

Installation:

Installed as approved. Note that this is a rather large editorial change.

2.31 ENDL-31 (Editorial)

Clause 4.5 last sentence in the clause. I do not understand the following: "Those targets that have agreed to support the data retransmission capability shall support REC." With whom did the targets agree? What specifically is the data retransmission capability? If it is correct, the following would be better wording: "Targets that support SRR shall also support REC."

Response:

Accepted in principle. This should point instead to the successful negotiation in PRLI for the proper state of the RETRY bit.

Installation:

Installed as approved.

2.32 ENDL-32 (Editorial)

Clause 4.7 first sentence. While it is true that the preponderance of task management functions abort or terminate tasks, the following statement is not really true: "An application client requests a task management function when a task or some group of tasks must be aborted or terminated." Borrowing from the wording in SAM-2 (and SAM), the following wording is better: "An application client requests a task management function to control explicitly the execution of one or more tasks." In the context of FCP-2, the following might be even better: "An application client requests a task management function to control explicitly the execution of one or more FCP I/O Operations."

Response:

Accepted second wording.

Installation:

Installed as approved.

2.33 ENDL-33 (Editorial)

Clause 4.7 second paragraph third sentence. The following statement is not true for task management functions that are initiated as FC-PH link services: "A task management function ends with an FCP_RSP IU that indicates whether it was correctly accepted." Better wording would be: "A task management function that begins with an FCP_CMND IU ends with an FCP_RSP IU that indicates whether it was correctly accepted."

Response:

Accepted. Other comments also affect this wording.

Installation:

Installed with one minor change. The FCP_RSP indicates completion, not acceptance, as required by SAM-2

2.34 ENDL-34 (Editorial)

Clause 4.7 Table 3. Would it be possible to add a references column to Table 3?

Response:

Accepted.

Installation:

No. All are in the same section, already referenced.

2.35 ENDL-35 (Editorial)

Clause 9.4 second sentence. If comment ENDL-21 is accepted, then change "... REQUEST SENSE information" to "... autosense data".

Response:

Accepted.

Installation:

See 2.21.

2.36 ENDL-36 (Editorial)

Clause 9.4.11 first sentence. If comment ENDL-21 is accepted, change this sentence from: "The FCP_SNS_INFO field contains the information specified by ANSI X3.301 for presentation by the REQUEST SENSE command." to: "The FCP_SNS_INFO field contains the autosense data (see SAM-2 and SPC-2)."

Response:

Accepted.

Installation:

See 2.21.

2.37 ENDL-37 (Technical)

Clause 9.4.11 second sentence. The COMMAND TERMINATED status became obsolete when the TERMINATE TASK task management function was made obsolete. FCP-2 has removed TERMINATE TASK from the Task management flags in the FCP_CMND IU, but the removal of the COMMAND TERMINATED status was overlooked in the following: "The proper FCP_SNS_INFO shall be presented when the SCSI status byte of CHECK CONDITION or COMMAND TERMINATED is presented as specified by ANSI X3.270." Better wording would be: "The proper FCP_SNS_INFO shall be presented when the SCSI status byte of CHECK CONDITION is presented as specified by SAM-2."

Response:

Accepted and approved by the committee in the meeting of March 6, 2000.

Installation:

Installed as requested.

2.38 ENDL-38 (Editorial)

Clause A.1 third paragraph. The sentence describing Table A.1 indicates that the table contains much more information than the table actually contains. Better wording would be: "See table A.1 for the mapping of objects and identifiers used in this standard to the equivalent remote procedure call terms and definitions used in the SCSI Architecture Model-2 standard."

Response:

Accepted.

Installation:

Installed as requested.

2.39 ENDL-39 (Technical)

Clause A.1 Table A.1, equivalence to task identifier. SAM-2 (and SAM) require that a task identifier include an initiator identifier. Since it appears that a fully qualified exchange identifier may not include an address identifier of initiator port, it is possible that a task identifier is equivalent to a fully qualified exchange identifier plus an address identifier of initiator port. Note: I had a similar concern about the SAM-2 requirement that a task identifier include a logical unit identifier (whose main component of interest here is a logical unit number). However, it appears that all logical units share the set of fully qualified exchange identifiers associated with one initiator/target pair. Therefore, the fully qualified exchange identifier implicitly includes the logical unit identifier (and LUN).

Note: I believe that SAM-2 (and SAM) contain a bug in the definition of task identifier and will bring a proposal on the subject to the next Protocol WG meeting.

Response:

The March 6, 2000 meeting requested that the solution to SAM-2 be completed before resolving this comment. The SAM-2 document is expected to be T10/00-140R2, which will require some rewrite of Annex A. this was accepted in a June 2, 2000 teleconference with the commentor. This also applies to comments 2.40 through 2.56.

Installation:

If this information has no usefulness, this annex should be removed. However, I believe that the corrected version of Table A.1 sufficiently neuters this so that SAM-2 corresponds correctly.

2.40 ENDL-40 (Editorial)

Clause A.1 Table A.1, equivalence to task address. Using the argument found in comment ENDL-39, there is no need for a task address to contain a logical unit number, as is currently shown in Table A.1. However, SAM-2 (and SAM) contains a trick in the definition of task address. The logical unit identifier is a key component of the task address. The logical unit identifier contains two parts; a target identifier and a logical unit number. Thus, task address must contain a target identifier. Since it appears that a fully qualified exchange identifier may not include an address identifier of target port, it is possible that a task address is equivalent to a fully qualified exchange identifier plus an address identifier of target port.

Response:

This needs to be reviewed after ENDL-39 is resolved. The fully qualified exchange identifier actually does include an address identifier of the exchange destination port, which is the target port.

Installation:

The nexus definition is used to clarify this.

2.41 ENDL-41 (Editorial)

Clause A.1 Table A.1, usage of object identifier. SAM-2 is so tied up in object definitions that I'd prefer not to have FCP-2 referencing an object identifier. My first response is object, what object. Please consider changing "object identifier" to "task management function object identifier".

Also, a SAM-2 object identifier can be any one of the following: target identifier, logical unit identifier, or task address. The equivalence list in FCP-2 covers the target identifier (first entry) and task address (second entry) with the possible exception of problems noted in ENDL-

39. The third entry fits none of the SAM-2 objects covered by the object identifier. To fully fit the SAM-2 list of objects covered by the object identifier, the third entry should be deleted and a new second entry should be added reading as follows: "or address identifier of target port + logical unit number".

I believe that a fully acceptable alternative would be to delete the object identifier row entirely and add a new row giving "address identifier of target port + logical unit number" as the FCP-2 equivalent of SAM-2 "logical unit identifier". This would have the effect of defining all the objects covered by the object identifier, and would leave the definition of what objects can be an object identifier to SAM-2. Note: SAM-2 might need to be a little clearer about the definition of an object identifier.

Response:

Accepted, but will require study as the change is actually made.

Installation:

Last two rows deleted.

2.42 ENDL-42 (Editorial)

Clause A.1 Table A.1, usage of object address. SAM-2 is so tied up in object definitions that I'd prefer not to have FCP-2 referencing an object address. My first response is object, what object. Please consider changing "object address" to "task management protocol service object address".

Also, a SAM-2 object address can be any one of the following: target identifier, logical unit identifier, or task address. The equivalence list in FCP-2 covers the target identifier (first entry) and task address (second entry) with the possible exception of problems noted in ENDL-39. The third entry fits none of the SAM-2 objects covered by the object identifier. To fully fit the SAM-2 list of objects covered by the object identifier, the third entry should be deleted and a new second entry should be added reading as follows: "or address identifier of target port + logical unit number".

As with ENDL-41, I believe an equally acceptable alternative is to add a table row showing the equivalence for SAM-2 logical unit identifier (see ENDL-41 for details of the new row) and delete the row for object address.

Response:

Accepted, but will require study as the change is actually made.

Installation:

Last two rows deleted.

2.43 ENDL-43 (Editorial)

Clause A.1 Table A.1. In notes 1 and 2, change "SCSI-3 Primary Commands" to "SCSI Primary Commands-2".

Response:

Accepted. It may be that the abbreviation can be used here.

Installation:

SPC-2 was used.

2.44 ENDL-44 (Editorial)

Several A.x clauses Tables A.3, A.4 and A.5. The heading for the third column looks like a cut and paste error: "SCSI Interlocked Protocol Service Interface procedure call". Better wording would be "FCP-2 Service Interface procedure call".

Response:
Accepted.
Installation:
Installed as requested.

2.45 ENDL-45 (Editorial)

Clause A.3 Table A.3. There are nomenclature problems in the names listed in the second column: "send SCSI command request, send SCSI command indication, send SCSI command response, and send SCSI command confirmation". To coordinate properly with SAM-2, the entries in the second column should read: "Send SCSI Command request, SCSI Command Received indication, Send Command Complete response, and Command Complete Received confirmation".

Response:
Accepted.
Installation:
Table was completely remanufactured to capture SAM-2, revision 14.

2.46 ENDL-46 (Editorial)

Clause A.3 Table A.3. The "[sense data]" parameter should be added to the response and confirmation procedure calls.

Response:
Accepted.
Installation:
Installed as requested.

2.47 ENDL-47 (Editorial)

Clause A.3 Table A.3. The following note should be added to Table A.3: "Since FCP-2 requires the use of autosense for all SCSI command operations, the Autosense Request parameter has been omitted from the request and indication procedure calls."

Response:
Accepted.
Installation:
I included it as non-optional instead.

2.48 ENDL-48 (Editorial)

Clause A.4. To better coordinate with SAM-2, the title of this clause should be "Data Transfer Protocol Services".

Response:
Accepted.
Installation:
Installed as requested.

2.49 ENDL-49 (Editorial)

Clause A.4.1. I don't understand the need for the two sentences and two paragraphs that appear before Table A.4, to wit:

"The data-in delivery service is a two step confirmed service that provides the means to transfer a parameter list or data from a device server to an initiator.

"Processing the execute command procedure call for a data-in delivery service shall be composed of the 2 step confirmed service shown in table A.4."

It seems to me that the following would be sufficient:

"The data-in delivery service is a two step confirmed service (see table A.4) that provides the means to transfer a parameter list or data from a device server to an initiator."

Response:

Accepted.

Installation:

Installed as requested.

2.50 ENDL-50 (Editorial)

Clause A.4.1 Table A.4. There are nomenclature problems in the names listed in the second column: "data-in delivery request and data-in delivery confirmation". To coordinate properly with SAM-2, the entries in the second column should read: "Send Data-In request and Data-In Delivered confirmation".

Response:

Accepted.

Installation:

Completely redone to meet SAM-2 revision 14.

2.51 ENDL-51 (Editorial)

Clause A.4.2. I don't understand the need for the two sentences and two paragraphs that appear before Table A.5, to wit:

"The data-out delivery service is a two step confirmed service that provides the means to transfer a parameter list or data from an initiator to a device server.

"Processing the execute command procedure call for a data-out delivery service shall be composed of the 2 step confirmed service shown in table A.5."

It seems to me that the following would be sufficient:

"The data-out delivery service is a two step confirmed service (see table A.5) that provides the means to transfer a parameter list or data from an initiator to a device server."

Response:

Accepted.

Installation:

Installed as requested.

2.52 ENDL-52 (Editorial)

Clause A.4.2 Table A.5. There are nomenclature problems in the names listed in the second column: "data-out delivery request and data-out delivery confirmation". To coordinate properly with SAM-2, the entries in the second column should read: "Receive Data-Out request and Data-Out Received confirmation".

Response:

Accepted.

Installation:

Installed as requested, complete with new information from SAM-2 rev 14.

2.53 ENDL-53 (Editorial)

Clause A.5. The || symbol has two meanings in the prototype procedure call. The first usage is intended to mean "or" and the second usage is intended to delineate the beginning of the output parameters. The second usage is consistent with the usage of || elsewhere in FCP-2 and throughout SAM-2. The first usage is inappropriate and a different nomenclature must be found. A nomenclature that is consistent with SAM-2 would be to make the first procedure call parameter object identifier and add the following sentence after the procedure call text: "Depending on the task management function being call, the object identifier is one of the following: a fully qualified exchange identifier, an address identifier of target port, or an address identifier of target port + logical unit number."

Response:

Accepted.

Installation:

Installed as redefined for SAM-2, revision 14.

Note that the only objectionable portion remaining after repairing all the service requests and responses was the text in A.4.1. That text no longer exists in SAM-2 and was deleted from here too.

2.54 ENDL-54 (Editorial)

Clause A.5.1 first sentence. Curiously enough, a statement such as the following usually precedes a table showing the multi-step process: "This standard handles task management functions as a four step confirmed service that provides the means to transfer task management functions to a task manager." Recommend addition of a table showing the four step confirmed service process used by task management functions.

Response:

Accepted.

Installation:

This was referenced to SAM-2, since I saw no benefit in replicating the text of clause 6 in this document.

2.55 ENDL-55 (Editorial)

Clauses A.5.1.1 through A.5.1.7. All of these clauses are obvious cut and paste text from SPI-x. They must be modified to describe FCP-2 aspects of the task management functions. Note: particular care must be taken in modifying clause A.5.1.1, since the ABORT TASK task management function relies on an FC-PH primitive, not on a flag bit in the FCP_CMND IU.

Response:

Accepted.

Installation:

These were deleted entirely, since I saw no benefit in replicating the text of 9.1.2.4 and 9.1.3.

2.56 ENDL-56 (Editorial)

Clause A.5.1.8. This clause can be removed. SAM-2 does not define a WAKEUP task management function, that function is unique to SPI-x. Therefore, FCP-2 need not contain any discussion of the WAKEUP task management function.

Response:

Accepted.

Installation:

Installed as requested. There is also no “reset service delivery system”, so it was also deleted.

3 Comments from Hewlett Packard

The following comments accompanied the ballot for Hewlett Packard from Geoff Fisher (GF), from Stewart Wyatt (SW), and from Matt Wakeley.

3.1 HP/GF 1. [t] (Editorial)

SPC2r13a Table 168 - Protocol specific LUN page (Page Code 18h) defines byte 2 as bits 7 - 4 reserved and bits 3 - 0 as the PROTOCOL IDENTIFIER. Table 169 then defines the PROTOCOL IDENTIFIER as 0 for Fibre Channel (FCPn). In FCP2r4, Table 31 Fibre Channel Logical Unit Control page (18h) defines byte 2 as all bits Reserved (Originally noted this in FCP2r3 Table 25). FCP2r4 therefore conflicts with SPC2r13a.

Response:

The field will be relabeled so that the 0 value will be parsed to the same format as that carried by SPC-2. Reviewed and accepted by the meeting of March 6, 2000.

Installation:

Installed as requested.

3.2 HP/GF 2. [t] (Editorial)

Similarly SPC2r13a Table 170 - Protocol specific port page (Page Code 19h) defines byte 2 as bits 7 - 4 reserved and bits 3 - 0 as the PROTOCOL IDENTIFIER. Table 169 defines the PROTOCOL IDENTIFIER as 0 for Fibre Channel (FCPn). In FCP2r4, Table 32 Fibre Channel Logical Port Control page (19h) defines byte 2 as all bits Reserved (Originally noted this in FCP2r3 Table 26). FCP2r4 therefore conflicts again with SPC2r13a.

Response:

The field will be relabeled so that the 0 value will be parsed to the same format as that carried by SPC-2. Reviewed and accepted by the meeting of March 6, 2000.

Installation:

Installed as requested.

3.3 HP/GF 3. [t] (Editorial)

Also in FCP2r4 Table 32 Byte 1 the Page Length is specified as (06h) whereas it should be (0Eh) for the conventional (n-1) length, also wrong in FCP2r3.

Response:

With the removal of the MCM functions, the original value is correct again.

Installation:

Installed as approved.

3.4 HP/SW 4. [t] (Editorial)

Page 24, 6.2.5 New or repeated PRLI, last sentence of first paragraph: "A recovery qualifier may be established after the recovery abort, temporarily restricting the choice of OX_ID values." Should this statement also include RX_ID values, if they are valid?

Response:

The sentence will be changed to read:

A recovery qualifier may be established after the recovery abort, temporarily restricting the choice of OX_ID values by the initiator and RX_ID values by the target.

Installation:

Installed as approved.

3.5 HP/SW 5. [t] (Editorial)

Page 46, 9.4.7 FCP_RESID: The effect of sequence error recovery defined in this document on FCP_RESID is not explicitly defined in this clause. I believe that if an error occurs which is successfully recovered using the procedures described in clause 12, that no residuals should be reported. A case in point would be when a target transferred a read data sequence, which the initiator detected an error in. As part of the error recovery the target resends the same sequence, which is successfully received by the initiator. The target reports successful status and no residuals even though the target sent the sequence twice.

Response:

The comment was withdrawn. The second to the last paragraph of clause 9.3 addresses the question.

Installation:

Installed as requested.

3.6 HP/SW 6. [t] (Editorial)

a Page 52, clause 10.1.1.6 Maximum Burst Size Field: My understanding of the relationship between SCSI and Fibre Channel (see Table 1, SCSI and FCP-2 functions, on page 7 of the FCP-2) is that a SCSI burst is equal to one FCP_DATA IU. If that is true, then the Maximum Burst Size Field specifies the maximum length of an FCP_Data IU. This definition states what it isn't (an interconnect tenancy), notes that it is required, but fails to define what it is. A precise definition is needed. I believe the definition is, "The maximum length of an FCP_DATA read sequence or the maximum amount of data a target can request in an FCP_XFER_RDY". If I am in error we do need to define a mode page parameter that does specify the maximum FCP_DATA IU length.

Response:

The comment forgets the first sentence, which provides the required definition. No change is required.

Installation:

No change required.

3.7 HP/SW 7. [t] (Technical)

Page 111, annex G.2 Table G.1 Clarification - The SEQ_CNT content, "SEQ_CNT if last Frame transmitted in an Open Sequence + 1. If no Sequence is open then SEQ_CNT = zero" If no sequence is open and the PLOGI Common Service Parameter SEQ_CNT = 1, should Frame Header SEQ_CNT still be equal to zero? This violates the common usage model of this parameter. If this is intended, it needs to be explicitly stated.

Response:

FC-FS, clause 15.2.2.2, states that the proper value for SEQ_CNT for the case where no sequence is open is either one greater than the last frame transmitted or zero. The text will be modified to reflect this. Note that this section is supposed to be informative and should reflect the values defined by FC-FS.

This response was accepted in the June 7, 2000 meeting.

Installation:

Installed as approved.

3.8 HP/MW 8. [t] (Editorial)

3.1.21 - the definition of Information Unit seems to imply that all the data in a "phase" must be transmitted in a single sequence. Isn't it possible to send FCP_DATA in multiple sequences instead of just one? For example, if a long transfer is to be performed, a device or initiator may choose to break the transfer up into multiple smaller sequences instead of just on long sequence. Is this allowed by this definition? This is implied by the sequence streaming notes in tables 8 and 9.

Response:

After further review at the March 6, 2000 meeting, the text is apparently correct. No change is required.

It was pointed out that there may be no text in the document that explicitly requires a sequence and an information unit to have a 1:1 relationship. The text will be searched out and verified.

Installation:

The following text was placed in section 5.4.

Each information unit shall be contained in a single Sequence. Each Sequence carrying an FCP information unit shall contain only one IU.

3.9 HP/MW 9. [t] (Technical)

4.8, table 4 - should a normal LIP (non resetting) be included?

Response:

This comment was discussed in the March 6, 2000 meeting. The following conclusions were reached:

- 1) LIP with successful discovery is not a clearing action. This will be added to Note 3 in the table.
- 2) LIP with successful fabric discovery is also not a clearing action. This will also be included in the same note.
- 3) OLS does not cause a reset in a fabric environment where the subsequent FLOGIN has also been successful. However, OLS in a point-to-point environment is a clearing action.
- 4) LR/LRR has properties similar to OLS.
- 5) Table 4 is becoming unmanageably large. It was suggested that it be cut into two tables, one for link actions and the other for protocol actions.

Installation:

Installed as approved. Note that this is a big change and needs review.

3.10 HP/MW 10. [t] (Editorial)

5.1, table 6 - why is "R" required in the RX_ID field for target identification? Isn't it optional? See 5.10.

Response:

This comment was discussed in the March 6, 2000 meeting. The conclusion was that the table should be deleted. The third sentence of the first paragraph should be expanded to indicate that the FQXID is initiator address identifier, target address identifier, OX_ID, and RX_ID. It should be farther expanded to indicate that RX_ID is required for certain recovery capabilities and if it has been successfully assigned by the target.

Installation:

Installed as approved.

3.11 HP/MW 11. [t] (Editorial)

5.6.9 defines the value of the OX_ID as the tag defined in ANSI X3.270. X3.270 defines the tag as 64 bits, but the OX_ID is only 32 bits.

Response:

This comment was discussed in the March 6, 2000 meeting. The conclusion was that the sentence in 5.6.9, "The value of the ... X3.270." should be deleted. In addition, in the glossary, section 3.1.41, the OX_ID should be defined as the initial tag and the OX_ID/RX_ID is the tag. See 2.9.

The editor will try to identify any other places where this problem may appear.

Installation:

Correction of 5.6.9 was made as proposed.

3.12 HP/MW 12. [t] (Technical)

5.6.11 defines RLTV_OFF as "not required". However, 9.3 (3rd paragraph) states "If more than one FCP_DATA IU is used to transfer the data, the RLTV_OFF is used to ensure that the SCSI data is reassembled in the proper order." It seems to me that 5.6.11 should define RLTV_OFF as required.

Response:

This comment was discussed in the March 6, 2000 meeting. The conclusion was that the relative offset was required to be generated by the sequence initiator. There are still two reassembly methods specified by FC-PH, one using sequence count, the other using relative offset. However, the tools to do either must always be provided to the recipient.

Installation:

Installed in 5.6.11 with considerable modifications to correct the ambiguous retry problem.

3.13 HP/MW 13. [t] (Technical)

6.2.5, last paragraph "Acknowledged class responders will close the exchange with P_RJT and an indication that process login is required." This is defining ACK and P_RJT to report FC-4 errors. ACK, P_RJT and P_BSY are only defined as FC-2 acknowledgements to signify the deliverability of a sequence or not. This requirement would require a FC-2 to deliver a sequence to an FC-4, that would then indicate to the FC-2 that it is ok to send an ACK or P_RJT. Acknowledged classes of service should work the same as unacknowledged classes - send an ABTS. This also requires a change to J.1.4.

Response:

The comment was discussed at the March 6, 2000 meeting. The offending paragraph has been deleted (See 1.48). The change to J.1.4 has also been requested by another comment, which requests that Annex J be deleted (see 9.146 Sun 146). This comment may require further review.

This response was accepted in the June 7, 2000 meeting.

Installation:

No additional change was required.

3.14 HP/MW 14. [t] (Technical)

8.2 indicates that the Accept FC-4 Link Service is sent to indicate that the request "has been completed". So, in the case of the SRR, is the accept sent before the retransmitted data, or after? The error recovery procedures indicate the accept is sent before the retransmitted data, but the definition implies after.

Response:

The committee decided on March 6, 2000 that the ACC only indicates that the request has been successfully received and that the target intends to transmit the data. The data is transmitted after the request is accepted. The text will be clarified.

Installation:

Installed as requested.

3.15 HP/MW 15. [t] (Technical)

10.1.3.2 (DTIPE) - the definition says that the port shall wait in a non-participating state with the bypass set, but shall respond to LPE addressed to its hard address. This conflicts with FC-AL-2, which indicates that a node has to be in the participating (but bypassed) state to respond to an LPE. That is, since the node will respond to an alpha, its participate flag must be set. Suggest removing the word "nonparticipating".

Response:

The comment is accepted and the text will be changed accordingly. This resolution was approved at the March 6, 2000 meeting.

Installation:

Installed as requested.

3.16 HP/MW 16. [t] (Technical)

11 table 35 & 11.3, RR_TOV. Since a recipient of an REC as R_A_TOV (ELS) time to reply to an REC, it seems like RR_TOV should be $3 * (REC_TOV + R_A_TOV (ELS))$ when $retry = 1$.

Response:

A proposal by Carl Zeitler (T11/00-145v0) indicates that the actual value should be $7 * REC_TOV$. This change was approved on March 6, 2000.

After further study, Carl has determined that the correct value is actually $3 * REC_TOV$ now that the simplified second level recovery is used. This was approved in the June 7, 2000 working group meeting.

Installation:

No change is required.

3.17 HP/MW 17. [t] (Technical)

11.4, table 36, 2nd row, "(optional timer restart)". Why is this optional?

Response:

At the March 6, 2000 meeting, the committee resolved the comment in the following manner:

In Table 36:

Change "timer starts after" to "timer starts or restarts after" (done)

Change "Reply sequence" to "FCP_RSP" (done)

Change second column, second row to same description as first and third row (done)

The question was asked, but not answered, about whether or not it was appropriate to allow a single timer to be used, such that REC_TOV functions would be very short. At present, a single timer may be used, but no REC may occur before REC_TOV.

The REC-TOV time-out diagrams may also need to be corrected to match with these tables.

This response was accepted in the June 7, 2000 meeting.

Installation:

The changes described above were made. In addition, an extraneous REC_TOV was removed from what will become Figure C.7. In Figure C.17, the REC is shown as starting from FCP_RSP. It should actually start from FCP_CMND.

3.18 HP/MW ?25. [t] (Technical)

12.3.3, at the end of "(by indicating that the Initiator...", should add "and all bytes not transferred" to differentiate between a lost FCP_XFER_RDY and a lost FCP_RSP requesting an FCP_CONF.

Response:

This was discussed and partially resolved at the March 6, 2000 meeting.

Charles Binford requested that a table be created to relate REC ACC to the SRR and to the actual recovery state.

Sections 12.3.3 shows the recovery for XFER_RDY, but does not indicate how to differentiate this case from the case described in 12.3.4.

This response was tentatively accepted in the June 7, 2000 meeting.

Installation:

The sentence in clause 12.3.3 was changed to read:

If the ACC for an REC indicates that an FCP_XFER_RDY was sent by the Target (by indicating that the Initiator holds Sequence Initiative, that all bytes were not transferred, and that the Exchange is not complete), but not received by the Initiator, issue an SRR Extended Link Service Frame in a new Exchange to request retransmission of the FCP_XFER_RDY (R_CTL = data descriptor).

This should allow for the proper differentiation.

The table requested by Charles Binford has not been created.

3.19 HP/MW 18. [t] (Technical)

12.6.1, 12.6.2, 12.6.3.a The text indicates that if an ABTS fails, the initiator may explicitly logout the target. If the response to REC and SRR fails three times, is a logout also performed? Maybe not, since the aborting of the REC/SRR would be done by ABTS, and if that fails, the target is logged out.

Response:

See 1.47. (Approved March 6, 2000)

Installation:

See 1.47.

3.20 HP/MW 19. [t] (Editorial)

12.7 "If a SCSI Target receives an FCP_CMND from an NL_Port with which it has not successfully completed Process Login (PRLI), it shall discard the FCP_CMND and send PRLO to the SCSI Initiator." This conflicts with 6.2.5: "Devices may have default PRLI information provided at the time the device is installed in the configuration. Such devices do not require the execution of a PRLI to perform normal FCP operations."

Response:

After review by the committee on March 6, 2000, it was considered unnecessary to make any change.

Installation:

After re-examining the paragraphs, they were changed to indicated "explicit or implicit" as a modifier for the Process Login and PLOGI, similar to the paragraph on receipt of SCSI frames.

3.21 HP/MW 20. [t] (Editorial)

12.7, end of section, there is a "TBD". Need to specify the TBD.

Response:

See 1.48. Resolution accepted March 6, 2000.

Installation:

See 1.48.

3.22 HP/MW 21. [t] (Technical)

B.3.1, page 79, last sentence of section, what does the "Data Transfer Count" mean to a target that sends REC in response to a lost FCP_CONF? Since REC can be used by other FC-4s, perhaps this section should be defined in more generic terms?

Response:

The following recommendations were made by the committee on March 6, 2000.

The Data Transfer Count is protocol dependent. Where the Data Transfer Count is specified for FCP-2 operation, the count is the highest displacement that the device knows has been transmitted.

For the REC associated with FCP_CONF, the data transfer count is set to 0 and treated as ignored, because the only requirement is that the existence of the exchange be verified.

Installation:

REC was moved into FCP-2 as an FCP FC-4 Link Service. Section B.3.1 may be removed from this annex.

I reviewed them for consistency. I have removed the reference to FC-FS for additional FCP_RJT reason codes. I have made other minor editorial improvements. All other information from B.3.1 is already installed correctly in clause 8.

3.23 HP/MW 22. [t] (Technical)

Figure D.7 and D.8 - "(or a Relative Offset smaller than the Relative Offset specified in the SRR in order to be aligned on an appropriate boundary in the Target)." conflicts with 12.3.5: "the Target transmits an FCP_XFER_RDY with the Relative Offset parameter specified by the SRR" and conflicts with 12.3.3: "retransmit the FCP_XFER_RDY in a new Sequence containing the same Relative Offset as the originally transmitted FCP_XFER_RDY."

Response:

Accepted. The parenthetical statement is deleted. Approved March 6, 2000.

Action:

Included in draft of annex D, rev 5.

3.24 HP/MW 23. [t] (Technical)

Figure D.14. In this example, the ACC to the SRR was lost. But what if the target resent the data requested by the SRR? Can the initiator imply that the ACC was sent, or must it abort the SRR and reperform it, causing the target to resend the data again?

Response:

This figure must be verified against T11/99-722v1. At present, figure 14b of this series of figures needs to reevaluate SRR every time. Approved March 6, 2000, but may require more review.

This response was tentatively accepted in the June 7, 2000 meeting.

Installation:

There is text provided in 12.4.1.7 that appears to address this by making it the initiator's choice about how to retry this. The obvious thing to do is wait for the data transfer to complete and then to an REC to find out how things went before retransmitting the SRR. No change is required.

3.25 HP/SW 24. [e] (Editorial)

Introduction page xiv and xv: The introduction has not been undated since the previous revision. It does not reflect the new clause 7 and the 4 additions to the annex.

Response:

Accepted.

Installation:

Installed as requested.

3.26 HP/SW 25. [e] (Editorial)

Page 6, Clause 3.4 Editorial conventions: First paragraph, second sentence, "These words and terms are defined either in or in the text where they first appear." This sentence doesn't make sense: "in or in" where?

Response:

Accepted.

Installation:

Corrected as requested.

3.27 HP/SW 26. [e] (Editorial)

Page 8, clause 4.2 Device Management, last paragraph on the page: The term "SCSI REQUEST SENSE information" should be "SENSE data" (two occurrences). See SAM-2 clause 3.1.84.

Response:

Accepted. See 2.21. the proper word is "autosense data".

Installation:

Installed as approved.

3.28 HP/SW 27. [e] (Editorial)

Page 12, clause 4.7 Task management, last sentence of first paragraph: Other references in this document have been to clause numbers. This reference lists the page without the clause.

Reformatting could make this reference become erroneous. Suggest that the reference be to clause 9.1.1.4.

Response:

Accepted.

Installation:

Installed as approved.

3.29 HP/SW 28. [e] (Editorial)

Page 18, clause 5.4 information units, first paragraph last sentence references annex B. This appears to be in error. Should it reference annex C?

Response:

Accepted.

Installation:

Installed as requested.

3.30 HP/SW 29. [e] (Editorial)

Page 19, notes to Table 9. The first note states that I2 is obsolete. The third note states that, "I2 and I3 allow optional sequence streaming ..." Since I2 is obsolete the third note should not reference I2, only I3.

Response:

Accepted.

Installation:

Installed as requested.

3.31 HP/SW 30. [e] (Editorial)

Page 30, 7.1 Query - Get port Identifiers (GID_FT): The first sentence has an extraneous "a" at the beginning of the second line.

Response:

Accepted.

Installation:

Installed as requested.

3.32 HP/SW 31. [e] (Editorial)

Page 30, Table 13; page 34, Table 20; page 35, Table 21: There is a formatting problem that is visible both on the screen and when printed. The table cell lines obscure the top of the text.

Response:

Accepted.

Installation:

Installed as requested.

3.33 HP/SW 32. [e] (Editorial)

Page 34, clause 8.2, under the bold text "FCP_RJT Reason explanation": There is an extra carriage return separating the two lines in this paragraph.

Response:

Accepted.

Installation:

Installed as requested.

3.34 HP/SW 33. [e] (Editorial)

Page 43, clause 9.3 FCP_DATA IU, seventh paragraph: This paragraph states, "If the PRLI service parameter DATA OVERLAY ALLOWED for the initiator is 1, the target may request that data be overlaid. If the PRLI service parameter DATA OVERLAY ALLOWED is 0, the target shall not request that data be overlaid." This sentence appears to be inconsistent with clause 6.2.6.9 Word 3, Bit 6: DATA OVERLAY ALLOWED, where any exception is made to allow error recovery when RETRY = 1. I would suggest modifying the second sentence to read: "If the PRLI service parameter DATA OVERLAY ALLOWED is 0, the target shall not request that data be overlaid except as is described elsewhere in this document when the PRLI RETRY but is set to 1 and the device is performing FCP-2 error recovery."

Response:

Accepted. See 2.6.

Installation:

The sentence “ Data retransmission as part of an error recovery process is not considered data overlay, even if retransmission occurs to the same offset in the application client buffer.” was placed to clarify paragraph 7.

3.35 HP/SW 34. [e] (Editorial)

Page 48, clause 9.4.11, FCP_SNS_INFO: The first sentence states, " The FCP_SNS_INFO field contains the information specified by ANSI X3.301 for presentation by the REQUEST SENSE command." To be technically consistent with SAM-2 the term "data" should be used instead of "information". Also the data is provided by an autosense operation not by a REQUEST SENSE command. I think the sentence should be more accurately written as, "THE FCP_SNS_INFO field contains the sense data specified by ANSI X3.301 delivered by an autosense operation." See SAM-2 3.1.84. My understanding is that the request sense command is not used in FCP.

Response:

Accepted. See 2.21.

Installation:

See 2.21

3.36 HP/SW 35. [e] (Editorial)

Page 51, clause 10.1.1 Disconnect-Reconnect mode page, immediately after Table 30, the term "interconnect tenancy" is defined. Rather than consistently using this term, an undefined but assumably synonymous term "link tenancy" is used in several places. A search and replace should be performed to make the document consistent. Three occurrences of the "link tenancy" term are on page 52 in the final sentences of clauses 10.1.1.3 Bus Inactivity Limit, 10.1.1.4 Disconnect Time Limit and 10.1.1.5 Connect Time Limit. Another occurrence is on page 53, clause 10.1.1.8 Access fairness management bits, second to last sentence.

Response:

Accepted.

Installation:

Installed as requested.

3.37 HP/SW 36. [e] (Editorial)

Page 62, clause 12.1.2 Sequence level error recovery: There is an extra line between the title and the text.

Response:

Accepted.

Installation:

Extra line removed.

3.38 HP/SW 37. [e] (Editorial)

Page 63, clause 12.2.2 Error mechanisms for acknowledged class of Service: The term "class" in the title should be "classes". Also the first sentence in the text should end in a colon instead of a period. The second sentence, "The Exchange originator (SCSI Initiator) shall initiate error detection and recovery described in 12.3 for the following:" should state, "The Exchange originator (usually the SCSI Initiator) shall detect an error and initiate recovery described..." The original sentence implies some circular activity where an error initiates error detection. Finally a comment that may not be particularly relevant, there is at least one case where a SCSI target is an exchange originator, that is for a LOGO.

Response:

Accepted. Review is requested of the committee.

This response was tentatively accepted in the June 7, 2000 meeting.

Installation:

The intent of the editorial changes was included, but a slightly different wording was selected. The new wording restricts the recovery to FCP behaviors, so LOGO recovery was not counted.

3.39 HP/SW 38. [e] (Editorial)

Page 67, 12.5.1 SCSI Initiator Abort of Exchange behavior and 12.5.2 SCSI Target Abort of Exchange behavior: These titles are ambiguous - is it Initiator/Target or exchange behavior that is to be addressed? I think better titles would be SCSI Initiator/Target procedure for aborting Exchanges.

Response:

Accepted in principle.

Installation:

Changed as suggested.

3.40 HP/SW 39. [e] (Editorial)

Page 82, annex C.1.4, Table C.4 - FCP read operation with FCP_XFER_RDY disabled, example. The title of the table does not reflect the FCP-2 requirement to disable FCP_XFER_RDY. The title could be changed by dropping the reference to the FCP_XFER_RDY. The new title would be, "FCP read operation, example. Alternately some explanatory text could be provided.

Response:

Accepted in principle.

Installation:

Installed as requested.

3.41 HP/SW 40. [e] (Editorial)

Page 84, annex C.1.7, Table C.7, second to bottom entry in left column. Redundant bracket at end of statement, " [indicate command completion]]".

Response:

Accepted.

Installation:

Installed as requested.

3.42 HP/SW 41. [e] (Editorial)

Page 111, annex G.2 Table G.1 ABTS Frame. Formatting error - the table outlines are missing.

Response:

Accepted.

Installation:

Installed as requested.

3.43 HP/SW 42. [e] (Editorial)

Page 112,113, annex G, Table G.2, G.3 and G.4. The text is too high in the table cells.

Response:

Accepted.

Installation:

Installed as requested.

3.44 HP/AT 43. [e] (Editorial)

Page 8, clause 4.2 Device management, last paragraph on page 8, last sentence: "...the FCP_RSP payload carry the FCP response..." carry should be carries.

Response:

Accepted.

Installation:

Installed as requested.

3.45 HP/AT 44. [e] (Editorial)

Page 68, clause 12.5.2 Target Abort of Exchange behavior, middle paragraph of clause: "Reinstate Recover Qualifier (RRQ)", Recover should be Recovery.

Response:

Accepted.

Installation:

Changed as requested.

3.46 HP/MW 45. [e] (Editorial)

3.1.127 needs to reference NCITS 1304-D.

Response:

Accepted in principle. Mnemonics will be used.

Installation:

3.1.27 was deleted as part of the removal of MCM functions.

3.47 HP/MW 46. [e] (Editorial)

3.3.5 "indicated" should be "indicates".

Response:

Accepted.

Installation:

Installed as requested.

3.48 HP/MW 47. [e] (Editorial)

3.3.6 "indicated" should be "indicates".

Response:

Accepted.

Installation:

Installed as requested.

3.49 HP/MW 48. [e] (Editorial)

3.3.6 "standards" should be "standard".

Response:

Accepted.

Installation:

Installed as requested.

3.50 HP/MW 49. [e] (Editorial)

3.2 CMR - suggest removing "project".

Response:

Accepted.

Installation:

Removed as part of the removal of MCM.

3.51 HP/MW 50. [e] (Editorial)

4.5, 2nd paragraph "Request Exchange Concise" should be "Read Exchange Concise".

Response:

Accepted.

Installation:

Installed as requested.

3.52 HP/MW 51. [e] (Editorial)

5.4, table 9, 3rd note, I2 is obsolete and should be removed from the note.

Response:

Accepted.

Installation:

Installed as requested.

3.53 HP/MW 52. [e] (Editorial)

5.6.2 and 5.6.3.a The D_ID and S_ID are defined in terms that the exchange originator is always the initiator. However, the target is allowed to originate exchanges, for example when it sends an REC. Suggest simply using the FC-PH definitions.

Response:

Accepted.

Installation:

Restricted the definitions to FCP-2 Device_Data frames. Other sections define the FCP-2 FC-4 Link Services issues.

3.54 HP/MW 53. [?] (Technical)

6.2.5, 2nd paragraph. Says: "Immediately after the execution of the first PRLI, both members of all image pairs shall have the same state as they would have after a hard reset or a power on with respect to each other." I think the sentence should say "Immediately before..." (not after).

Response:

This was reviewed by the committee on March 6, 2000. Note that some parameters are not reset. While it may be explicit enough in the subsequent paragraph, this text will be reviewed again. Note that some Mode pages apply per initiator, while other pages apply per target.

This response was accepted in the June 7, 2000 meeting.

Installation:

This was rewritten to resolve other comments and, as a result, resolved this also. The clearing table in clause 4 was referenced for this purpose.

3.55 HP/MW 54. [e] (Editorial)

9.1, table 22 - FCP-1 defined bytes 8-11 as the "Control Field". Do we want to do away with this?

Response:

Yes. At an earlier revision of the document, flattening of the tables was requested. Collections of bits are no longer labeled with such secondary descriptions unless necessary.

Installation:

No change was required.

3.56 HP/MW 55. [e] (Editorial)

9.1.2.2 - should indicate that bit 0 in the PARM field is set to 0 for this ABTS. (other areas of the document specify when to set the bit to 1)

Response:

Accepted in principle. The actual fields will be reviewed.

Installation:

This was moved to 12.3.2. The text now reads:

The SCSI initiator terminating the exchange sends an ABTS sequence to the D_ID of the target of the exchange being terminated. The ABTS sequence shall have the Parameter field set to ABORT EXCHANGE.

3.57 HP/MW 56. [e] (Editorial)

9.4, table 26 - FCP-1 defined bytes 8-11 as the "FCP Status". Do we want to do away with this?

Response:

Yes. At an earlier revision of the document, flattening of the tables was requested. Collections of bits are no longer labeled with such secondary descriptions unless necessary.

Installation:

No change required.

3.58 HP/MW 57. [e] (Editorial)

11.3. I do not understand what "... and always appropriate to ADISC address discovery time." means.

Response:

The intent is to point out that the timer for REC_TOV should not be incremented during the time that LIP and address verification are taking place due to a temporary link error. No change is proposed.

The original question apparently questioned when REC could be performed relative to post-initialization authentication. All ELSs except ADISC, PDISC, FAN, PLOGI, and FLOGI are ignored until address authentication is complete with the initiator/target pair. This may require further corrections to FC-FS or some other document.

This response was accepted in the June 7, 2000 meeting.

Installation:

No change is required.

3.59 HP/MW 58. [e] (Editorial)

12.3.2 typo "interal".

Response:

Accepted. The word should be "interval".

Installation:

Installed as suggested.

3.60 HP/MW 59. [e] (Editorial)

12.3.4, "A command that was terminated before execution by a CHECK CONDITION with FCP_CONF requested may have the same REC values as a command for which an FCP_RSP...". This FCP_RSP should be FCP_XFER_RDY.

Response:

Accepted. Wasn't this covered somewhere else?

This response was accepted in the June 7, 2000 meeting.

Installation:

The requested change was made.

3.61 HP/MW 60. [e] (Editorial)

B.1 "FC-PH" should be "FC-FS".

Response:

Accepted.

Installation:

Annex B deleted.

3.62 HP/MW 61. [e] (Editorial)

B.3.1, page 79, accept payload, should say "The Responder Address Identifier is set to..." (add the word "to").

Response:

Accepted.

Installation:

Installed in 8.2.

3.63 HP/MW 62. [e] (Editorial)

Annex E: E.2 should reference figure E.2, and the figure renamed figure E.2 (there are two figure E.1s). The same thing applies to E.3.

Response:

Accepted.

Installation:

One is a table, while two are figures. Appropriate references are applied.

3.64 HP/MW 63. (Editorial)

Annex G, all references to figures should be references to tables.

Response:

Accepted.

Installation:

Installed as requested.

3.65 HP/MW 64. (Editorial)

[e] list of figures duplicated on last page of document.

Response:

Accepted.

Installation:

Installed as requested.

4 Comments from IBM

The following comments accompanied the ballot of IBM Corporation, prepared by George Penokie.

The notation 'Page xx' refers to all pages in the standard not roman numeral xx. All comments are editorial unless indicated with a '(T)' at the start of the comment. The technical comments are IBM comments 1, 138, 202, 205, 322, 521, 538, 546, 572, 636, and 693.

4.1: IBM comment from George Penokie (Technical)

(T) Page 13 - table 4 - There is another operation that needs to be added to this table. It involves the result of an XDWRITE command that is saved in the target until an XDREAD command is issued. The normal sequence goes like this:

An initiator does an XDWRITE command.

The target reserves resources for saving the XOR result so it can read out via an XDREAD command.

An initiator issues an XDREAD command to retrieve the result of the XOR. This does not have to be the same initiator that issued the original XDWRITE.

The target frees up the resource.

The problem is there is not definition in as to what the target is supposed to do with the reserved XOR data if the initiator that issued the XDWRITE command logs out before an XDREAD command occurs. Since the XDWRITE/XDREAD commands can come from any initiator we can't just throw away the data when an initiator logs out.

I propose a new row be added to table 4 to describe the clearing actions that are required to occur on the reserved XOR data. This row should require that the reserved XOR data only be cleared only if there is a target power cycle, reset LIP, log out only if all initiators are logged out, TPRLO, SCSI target reset, or a SCSI logical unit reset.

Response:

The comment is accepted and the appropriate changes will be made. This action was approved at the April 5, 2000 meeting.

In an e-mail dated 6/19/00, George Penokie requested the following modification to this question.

IBM's comment number 1 requested a row be added to table 4 to handle XOR data clearing actions. It has been pointed out to me that the requested action on log out should be changed to remove the XOR data on a log out from the initiator that issued the original XDWRITE rather than holding the XOR data until all initiators are logged out. The reason is because, in this case, a log out should be treated the same as an Abort Task Set and an Abort Task Set clears the XOR data. As a result I would like to modify IBM's comment 1 from:

'I propose a new row be added to table 4 to describe the clearing actions that are required to occur on the reserved XOR data. This row should require that the reserved XOR data only be cleared only if there is a target power cycle, reset LIP, log out only if all initiators are logged out, TPRLO, SCSI target reset, or a SCSI logical unit reset.'

to:

I propose a new row be added to table 4 to describe the clearing actions that are required to occur on the reserved XOR data. This row should require that the reserved XOR data only be cleared only if there is a target power cycle, reset LIP, log out from the initiator that originated the XDWRITE command, TPRLO, SCSI target reset, or a SCSI logical unit reset.

The editor accepts this correction.

Installation:

Installed as requested.

4.2: IBM comment from George Penokie (Editorial)

Page xx - Throughout this standard the use of the small caps notation is erratic. Small caps should always be used when the name of a field or bit is being used (e.g. the BSST bit when set to 1 or the GO FIND SOUP field indicates). Small caps is not used when describing the contents of a field (e.g., a go find soup value of 54 is not value). I have commented where on many of the instances where small caps should have been used or where they were used but should not have been used but a general seep of the standard should be made to correct those errors.

Response:

Accepted.

Installation:

Installed as requested, except where other conventions were applicable.

PDF Page 1

4.3: IBM comment from George Penokie (Editorial)

Page i - At the bottom of the page the 'Reference number' is overlapping the bar and is difficult to read.

Response:

Accepted.

Installation:

Installed as requested.

PDF Page 2

4.4: IBM comment from George Penokie (Editorial)

Page ii -The address of the t10 vice chair should be changed from 2B7 to Z9V.

Response:

Accepted.

Installation:

Installed as requested.

4.5: IBM comment from George Penokie (Editorial)

Page ii - All 'X3T10's need to be changed to 'T10'.

Response:

Accepted.

Installation:

Installed as requested.

4.6: IBM comment from George Penokie (Editorial)

Page ii - The SCSI bulletin board information should be removed

Response:

Accepted.

Installation:

Installed as requested.

4.7: IBM comment from George Penokie (Editorial)

Page xx - Any capitals on the words 'Initiator' and 'Target' should be made non-capitals (i.e., initiator, target). In general there are numerous cases where words are capitalized throughout this standard. Most, if not all, of those words should not be capitalized. I have pointed out many of these in the first part of the standard as examples but this is a general comment on the entire standard not just the places that I have indicated.

Response:

Accepted.

Installation:

Corrected in all locations.

Note that FC-FS requires capitalization of “Sequence Initiator”. This was approved in the September 11, 2000 meeting.

4.8: IBM comment from George Penokie (Editorial)

Page ii - What is 'Fibre Channel Physical and Signaling Interface'? Should this be the name of this standard? If not then what is it?

Response:

This is the actual name of the FC-PH standard. I suggest changing this to “Fibre Channel family of standards.” This resolution was approved at the April 5, 2000 meeting.

Installation:

Installed as requested.

4.9: IBM comment from George Penokie (Editorial)

Page ii - Why is the statement 'The second revision includes additional mandatory and optional requirements.' here it adds nothing to the abstract and should be removed.

Response:

Accepted. It is appropriate to indicate why a second version is being prepared instead of simply using the first version. The offending sentence will be replaced with: “The second version adds optional retransmission, task ordering, and confirmation capabilities.” This resolution was approved at the April 5, 2000 meeting.

Installation:

Installed as approved.

PDF Page 3

4.10: IBM comment from George Penokie (Editorial)

Page iii -The document revision history should be removed.

Response:

Accepted.

Installation:

Installed as requested.

PDF Page 13

4.11: IBM comment from George Penokie (Editorial)

Page xx - Is the reference to FC-PH really a reference to FC-PH-2, FC-PH-3, DAM-1, DAM-2 or the new FC-PI and FC-FS. Through out this standard there are references to the various FC-PH standards. In many cases it is not clear as to which version of FC-PH is being referred to. I suggest all references be changed to reference FC-FS. I do not believe there are any

references to the FC-PI part of FC-PH but if there are then FC-PI should be used as the reference.

Response:

Accepted.

Installation:

FC-FS is universally referenced instead of FC-PH.

4.12: IBM comment from George Penokie (Editorial)

Page xiii - The term 'Fibre Channel ' should not be capitalized.

Response:

In all Fibre Channel documents and at all times, Fibre Channel is capitalized. I believe we should maintain that convention. The comment is not accepted.

See 4.46: IBM comment from George Penokie.

This resolution was accepted in the March 6, 2000 meeting.

Installation:

No change is made.

4.13: IBM comment from George Penokie (Editorial)

Page xiii - There is no list of names for t10.

Response:

Accepted.

Installation:

Installed as requested.

PDF Page 14

4.14: IBM comment from George Penokie (Editorial)

Page xiv - There is no list of names for NCITS.

Response:

Accepted.

Installation:

This is installed as part of the editorial process for release by NCITS.

4.15: IBM comment from George Penokie (Editorial)

Page xiv - X3 needs to be changed to NCITS.

Response:

Accepted.

Installation:

Installed as requested.

4.16: IBM comment from George Penokie (Editorial)

Page xiv - The statement ' This document describes...' should be 'This standard describes...'. ..

Response:

Accepted.

Installation:

Installed as requested.

4.17: IBM comment from George Penokie (Editorial)

Page xiv - The statement 'This document describes the protocol for using Fibre Channel FC-PH Exchanges and Information Units to implement the SCSI Fibre Channel Protocol (FCP) and optional extensions to that protocol.' Is completely unclear and needs to be rewritten.

Response:

Accepted.

Installation:

Installed as requested.

4.18: IBM comment from George Penokie (Editorial)

The term 'Information Unit' should not be capitalized.

Response:

Accepted. FC-FS is inconsistent about its capitalization policy with respect to “information unit”. This needs to be raised as an editorial issue to FC-FS. The convention selected for FCP-2 and provided to FC-FS will be to use “information unit” in lower case and to use the abbreviation “IU” in upper case. This will be addressed for FC-FS in T10-00-230r1.

After being addressed in FC-FS, the Fibre Channel working group elected to reject this solution and require that Information Unit always be capitalized in both FC-FS and FCP-2.

Installation:

No change required in clause 12.

Changes made in many sections to install the proper capitalization.

4.19: IBM comment from George Penokie (Editorial)

Page xiv - The statement 'into 11 major clauses' should be 'into 11 clauses'. All clauses are major anything else is a subclause.

Response:

Accepted.

Installation:

Installed as requested.

4.20: IBM comment from George Penokie (Editorial)

Page xiv - Once you start using the acronym FCP you should continue to use it not Fibre Channel Protocol.

Response:

Accepted in principle. I believe that FCP-2 should be used to reference this standard. The protocol should be referred to as “the Fibre Channel protocol” or perhaps “the FC protocol” at all times. This resolution was accepted at the meeting on April 5, 2000.

Installation:

Additional cases have been identified:

When referring to the FCP and FCP-2 standards, the terms “the FCP standard” or “this standard” should be used, respectively.

When referring to devices compliant with the standard, the term “FCP-2 device” should be used.

When referring to the protocol defined by this standard, the term “FCP-2 protocol” should be used.

This has been corrected in 12,

This should also be installed in the glossary.

PDF Page 15

4.21: IBM comment from George Penokie (Editorial)

Page xv - Once you start using the acronym FCP you should continue to use it not Fibre Channel Protocol.

Response:

See 4.20.

4.22: IBM comment from George Penokie (Editorial)

Page xv - What is a temporary annex? It must be removed or not removed because it cannot be changed after the standard is forwarded.

Response:

Accepted.

Installation:

Removed as requested.

4.23: IBM comment from George Penokie (Editorial)

Page xv - There is a statement that 3 annexes have been removed and then it goes on to tell what those were and where they went. There are several problems with this.

1-You use FCP here to mean the FCP standard but in other places it means either the FCP or FCP-2. This needs to be resolved.

2-You reference specific clauses in a standard. This is almost always going to be incorrect. Only the standard should be referenced.

The best solution to this problem would be to totally removed any comments about the removed annexes.

Response:

Accepted. See also 4.20.

Installation:

Removed as requested.

4.24: IBM comment from George Penokie (Editorial)

Page xv - I would be best to change all references from SAM to SAM-2.

Response:

Accepted in principle. There may be a few things that SAM provides that SAM-2 does not provide, so references must be verified. Any exceptions will be listed here.

Installation:

All were changed to SAM-2.

4.25: IBM comment from George Penokie (Editorial)

Page xv - You should change the statement 'SCSI-3 family' to 'SCSI family'.

Response:

Accepted.

Installation:

Installed as requested.

PDF Page 17

4.26: IBM comment from George Penokie (Editorial)

I believe it would be much less confusing if the name of this standard was change to 'Fibre Channel Protocol for SCSI, Second Version'. The term 'revision' makes me think of document revision numbers (e.g., Rev. 02, 03).

Response:

Accepted.

Installation:

Installed as requested.

4.27: IBM comment from George Penokie (Editorial)

Page 1 - The statement 'This standard defines a second revision of the ...' should be 'This standard defines a second version of the ...'

Response:

Accepted.

Installation:

Installed as requested.

4.28: IBM comment from George Penokie (Editorial)

Page 1 - The statement 'This standard defines a second revision of the ...' should be 'This standard defines a second version of the ...'

Response:

Accepted.

Installation:

Installed as requested.

PDF Page 18

4.29: IBM comment from George Penokie (Editorial)

Page xx - In many, but not all, cases standards are referenced by the ANSI number. This is not very useful to the reader. These should be changed to the standards acronym throughout the standard.

Response:

Accepted. The following changes will be made to the document: All references will use the mnemonic to specify the referenced standard. All mnemonics will be included in the sub-clause on abbreviations, together with the official title of the document. The sub-clause on abbreviations will point to the appropriate sub-clause on references.

Installation:

Installed as requested.

4.30: IBM comment from George Penokie (Editorial)

Page 2 - section 3.1.10 - I believe B comes before C so the BMCM definition should be moved to the correct alpha position.

Response:

The MCM function has been removed from FC-AL-3. These definitions and related text will be removed.

Installation:

Installed as approved.

4.31: IBM comment from George Penokie (Editorial)

Page 2 - section 2.2 - The project number of FC-FS is 1331D not 3111D.

Response:

Accepted.

Installation:

Installed as requested.

4.32: IBM comment from George Penokie (Editorial)

Page 3 - section 3.1.17 - The term 'Execute Command' should not be capitalized.

Response:

The convention established for callable procedures in SAM-2 requires their capitalization. This will continue to be used in FCP-2 as well. This resolution was accepted in the April 5, 2000 meeting.

Installation:

No change required.

4.33: IBM comment from George Penokie (Editorial)

Page 3 - section 3.1.20 - When did tokens become part of FC? Address would be a better term.

Response:

Accepted.

Installation:

The text was changed to refer to a “set of addresses and values”, since not all are addresses.

4.34: IBM comment from George Penokie (Editorial)

Page 3 - section 3.1.23 - Replace token with address.

Response:

Accepted.

Installation:

Installed as requested.

4.35: IBM comment from George Penokie (Editorial)

Page 3 - section 3.1.30 - Another reference to FC-PH where it should be a reference to all the FC-PH standards.

Response:

Accepted in principle. The references will be to FC-FS. This resolution was accepted in the April 5, 2000 meeting.

Installation:

Installed as approved.

4.36: IBM comment from George Penokie (Editorial)

The terms Exchange, Originator, and Responder should not be capitalized.

Response:

In all Fibre Channel documents, and at all times, these terms are capitalized. I believe we should maintain that convention. The comment is not accepted. This resolution was reluctantly accepted in the April 5, 2000 meeting. Because of this reluctance, I will raise the issue in T11/00-284v1.

This convention was rejected by the FC-FS working group in their June 2000 meeting. FC-FS capitalization conventions shall be used.

Installation:

Verified in 1, 2, 3, 4, 5, 6, 7, 8, 9, 10, 11, 12, A, B, C, D, E, F, G, H, and I.

4.37: IBM comment from George Penokie (Editorial)

Page 3 - section 3.1.32 - The reference to 'Responder Exchange Identifier' should be replaced with a subclause number.

Response:
Accepted.
Installation:
Installed as requested.

PDF Page 20

4.38: IBM comment from George Penokie (Editorial)

Page 4 - section 3.1.34 - Another reference to FC-PH where it should be a reference to all the FC-PH standards.

Response:
Accepted.
Installation:
Installed as requested.

4.39: IBM comment from George Penokie (Editorial)

Page 4 - section 3.2 - The FCP-2 abbreviation does not need the ANSI document reference. And if it stays the TBD needs to be removed.

Response:
Accepted.
Installation:
Installed as requested.

4.40: IBM comment from George Penokie (Editorial)

Page 4 - section 3.2 - I cannot believe the fibre channel is wholly defined in a single standard. This reference should be removed.

Response:
Accepted in principle. The text will be changed to reference the document name.
Installation:
FC-PH and all its companion documents is replaced with FC-FS, which does indeed define the entire FC behavior.

PDF Page 21

4.41: IBM comment from George Penokie (Editorial)

Page 5 - section 3.2 - SCSI-2 - What is ANS X3.131-1994? I believe it should be ANSI X3.131-1994.

Response:
Accepted.
Installation:
SCSI-2 reference is deleted.

4.42: IBM comment from George Penokie (Editorial)

Page 5 - section 3.2 - SCSI-2 - This is an abbreviations list but this does not tell what SCSI-2 is. It should be changed to 'Small Computer System Interface-2'.

Response:
Accepted.
Installation:
SCSI-2 reference is deleted.

4.43: IBM comment from George Penokie (Editorial)

Page 5 - section 3.2 - SCSI-3 - This is an abbreviations list but this does not tell what SCSI-3 is. It should be changed to 'Small Computer System Interface-3'. Also there is no single SCSI-3 standard so the current reference is incorrect.

Response:

Accepted.

Installation:

The description was changed to:

Small Computer System Interface-3, the SCSI architecture specified by SAM-2 and extended by the companion documents referenced in SAM-2.

PDF Page 22

4.44: IBM comment from George Penokie (Editorial)

Page 6 - section 3.4 - The bit order and byte order should be specified here not by reference to another document.

Response:

Accepted.

Installation:

The paragraph indicating bit significance in the diagrams was installed from FC-FS. The actual bit and byte order is specified in a somewhat lengthy section including 11.7 of FC-FS, which will not be moved into FCP-2.

4.45: IBM comment from George Penokie (Editorial)

Page 6 - section 3.4 - The following ISO editorial conventions need to be added in and followed: Decimals are indicated with a comma (e.g., two and one half is represented as 2,5). Decimal numbers having a value exceeding 999 are represented with a space (e.g., 24 255).

Response:

Accepted.

Installation:

Installed as requested.

PDF Page 23

4.46: IBM comment from George Penokie (Editorial)

If fibre channel was changed to FC every where except the first occurrence then the issue about capitalizing fibre channel would be resolved.

Response:

Not accepted. See 4.12.

Installation:

No change was made.

4.47: IBM comment from George Penokie (Editorial)

Page 7 - section 4.4 - The statement 'In the FCP-2 document N_Ports...' should be 'In this standard N_Ports...'.

Response:

Accepted.

Installation:

Installed as requested.

4.48: IBM comment from George Penokie (Editorial)

Section 4 - There are several references to standards that use the ANSI number all these should be changed to reference the standards name.

Response:

Accepted.

Installation:

Installed as requested.

4.49: IBM comment from George Penokie (Editorial)

Page 7 - section 4.1 - There is a reference to a specific annex outside this standard that should be removed.

Response:

Accepted.

Installation:

Installed as requested.

4.50: IBM comment from George Penokie (Editorial)

Page xx - There are several references to 'SAM and SAM-2' this implies that these two standards are both needed when you only need one or the other. The best thing to do is to reference only one; SAM-2 is preferred.

Response:

Accepted.

Installation:

Installed as requested.

4.51: IBM comment from George Penokie (Editorial)

Page 7 - section 4.1 - The sentence that contains the reference to CAM is not necessary and should be removed. This would then allow the removal of CAM from the normative reference list.

Response:

Accepted.

Installation:

Installed as requested.

4.52: IBM comment from George Penokie (Editorial)

Page 7 - section 4.1 - The word 'paradigm' should be replaced with 'structure' or some such word.

Response:

Accepted.

Installation:

The offending sentence was not helpful and was removed.

PDF Page 24

4.53: IBM comment from George Penokie (Editorial)

Page 8 - section 4.1 - The term '65535' should be '65 535'.

Response:

Accepted.

Installation:

Installed as requested.

4.54: IBM comment from George Penokie (Editorial)

Page 8 - section 4.2 - The term Execute should not be capitalized.

Response:

Accepted.

Installation:

The word was changed to Execute Command for consistency with SAM-2, pdf page 64, clause 5. This was approved in the September 11, 2000 meeting.

4.55: IBM comment from George Penokie (Editorial)

Page 8 - section 4.2 - Again SAM-2 is not an incremental standard to SAM therefore only one should be listed here and in other places throughout this standard.

Response:

Accepted.

Installation:

Installed as requested.

4.56: IBM comment from George Penokie (Editorial)

Page 8 - section 4.2 - The term Send should not be capitalized.

Response:

Accepted.

Installation:

The word was changed to Send SCSI Command service for consistency with SAM-2, pdf page 69, sub-clause 5.3. This was approved in the September 11, 2000 working group meeting.

4.57: IBM comment from George Penokie (Editorial)

Page 8 - section 4.2 - A cross-reference to the section that explains about FQXIDs would be helpful at this point in the document.

Response:

Accepted.

Installation:

Installed as requested.

4.58: IBM comment from George Penokie (Editorial)

Page 8 - section 4.2 - The document should be de-whiched. For example in this section the statement '...initiator to indicate which portion of the data.., should be changed to '...initiator to indicate the portion of the data...'.
'

Response:

Accepted.

Installation:

Installed in all sections identified by a search of FCP-2 revision 4.

4.59: IBM comment from George Penokie (Editorial)

Page 8 - section 4.2 - The sentence 'Exactly one FCP_DATA IU follows each FCP_XFER_RDY IU.' should be changed to 'One FCP_DATA IU shall follow each FCP_XFER_RDY IU.'

Response:

Accepted.

Installation:

Installed as requested.

4.60: IBM comment from George Penokie (Editorial)

Page 8 - section 4.2 - What is the statement 'other mechanisms for controlling the data transfer.' supposed to mean? Do you mean 'mechanisms outside the scope of this standard'? If so then say it that way.

Response:

Accepted.

Installation:

Installed as requested.

4.61: IBM comment from George Penokie (Editorial)

Page 8 - section 4.2 - All note should be numbered. But this note should be remove and a list of obsolete things placed in one place, preferably in the Scope clause.

Response:

Accepted.

Installation:

The note was deleted. This function is defined as obsolete in 6.3.7.14.

4.62: IBM comment from George Penokie (Editorial)

Page 8 - section 4.2 - What exactly is an 'unusual condition'? Would this be an error condition or something else; it is not clear at all. "Unusual conditions' need to be defined or replaced with something that is defined.

Response:

Accepted.

Installation:

The unusual condition is CHECK CONDITION. The corresponding change was made.

4.63: IBM comment from George Penokie (Editorial)

Page 8 - section 4.2 and other places - The term 'Operation ' should not be capitalized.

Response:

Accepted.

This response was accepted in the June 7, 2000 meeting.

Installation:

Installed as requested.

4.64: IBM comment from George Penokie (Editorial)

Page 8 and 9 - section 4.2 - This entire section contains descriptions of sequences of operations that occur written in paragraphs. This is difficult to read and understand. It would be much clearer if the operations were placed in lists were each step was a new list entry.

Response:

Accepted.

Installation:

After review of the section, it is not clear that a list structure would improve the clarity. No change was made. This was approved in the September 11, 2000 working group meeting.

4.65: IBM comment from George Penokie (Editorial)

Page 8 - section 4.2 - 'Send Command Complete' should not be capitalized.

Response:

This will be reviewed in the context of SAM-2 and capitalized consistently with that standard. The editor of SAM-2 indicates this term is capitalized in SAM-2.

This response was accepted in the June 7, 2000 meeting.

Installation:

No change required.

4.66: IBM comment from George Penokie (Technical)

Page 8 - section 4.2 - The statement 'The SCSI logical unit determines whether ...' is not correct, it is the task manager that controls the command sequencing..

Response:

Actually, if I interpret SAM-2 correctly, the task manager performs task management functions on the task set, while the device server orders the entry of the task into the various stages of execution. As a result, the text should read "The SCSI device server for the logical unit determines...".

This response was accepted in the June 7, 2000 meeting.

Installation:

Installed as approved.

PDF Page 25

4.67: IBM comment from George Penokie (Editorial)

Page 9 - section 4.2 - The statement '...confirmation information to the software that requested...' should be '...confirmation information to the application client that requested...'.

Response:

Accepted.

Installation:

Installed as requested.

4.68: IBM comment from George Penokie (Editorial)

Page 9 - section 4.2 - Unlike editors, standards do not have emotions. The statement '...performed the desired operations with the..' should be changed to '...performed the requested operations with the...'

Response:

Accepted.

Installation:

Installed as requested.

4.69: IBM comment from George Penokie (Editorial)

Page 9 - section 4.2 - The statement 'The Flag bit defined by SAM for linked commands is obsolete in FCP-2.' should be removed and a list of obsolete things placed in one place, preferably in the Scope clause

Response:

Accepted.

Installation:

The statement was deleted. The list of obsolete things containing the Flag bit actually belongs in another standard, if anywhere. No such list was created.

4.70: IBM comment from George Penokie (Editorial)

Page 9 - section 4.2 The term Flag in the statement ' The Flag bit defined by SAM...' should be in small caps as it is the name of a field.

Response:

Accepted.

Installation:

The offending phrase was deleted.

4.71: IBM comment from George Penokie (Editorial)

Page 9 - section 4.2 - The statement '...of the particular SCSI devices and ..' should be changed to '...of the SCSI device...'

Response:

Accepted.

Installation:

Installed as requested.

4.72: IBM comment from George Penokie (Editorial)

Page 9 - section 4.2 - I/O operations are not between a host and a peripheral subsystem. I/O operations are between application clients and device servers. This needs to be fixed in the last paragraph of section 4.2.

Response:

Accepted.

Installation:

The text was changed to clarify that this is an implementation example. The wording “host” and “peripheral device” was retained. This was approved in the September 11, 2000 working group.

4.73: IBM comment from George Penokie (Editorial)

Page 9 - section 4.2 - Asynchronous Event Notification should not be capitalized.

Response:

The definition in SAM-2 chooses to use these terms capitalized. Unless SAM-2 changes, the FCP-2 document should not change. The SAM-2 editor indicates these terms should not be capitalized. This will be verified.

This response was accepted in the June 7, 2000 meeting.

Installation:

Installed as requested.

4.74: IBM comment from George Penokie (Editorial)

Page 9 - section 4.3 - The statement 'for the proper operation and error recovery of a device server' should be removed as it carries no value in a standard.

Response:

The statement will be modified to indicate more clearly that it can be done under any conditions. An explanation of the possible benefits of this should also be included here so that people can understand why they might choose to do this. The “will” should be removed.

This response was tentatively accepted in the June 7, 2000 meeting.

Installation:

Installed with editorial modifications.

4.75: IBM comment from George Penokie (Editorial)

Page 9 - section 4.3 - The statement 'In many cases, SCSI communications between an application client and a device server are stateless. In such applications, verification...' shows bias. It should be changed to 'In applications where SCSI communications between an application client and a device server are stateless, verification...'

Response:

Accepted.

Installation:

Installed as requested.

4.76: IBM comment from George Penokie (Editorial)

Page 9 - section 4.3 - The statement 'For those special cases where checking for the precise delivery of SCSI...' should be changed to 'In applications where checking for the precise delivery of SCSI...'

Response:

Accepted.

Installation:

See 4.74. A different change was made.

4.77: IBM comment from George Penokie (Editorial)

Page 9 - section 4.3 - The cross-reference contains a page number. This is not the proper form. The page number should be removed.

Response:

Accepted.

Installation:

Installed as requested.

4.78: IBM comment from George Penokie (Editorial)

Page 9 - section 4.3 - All the following except LUN should not be capitalized - Target Reset, LUN Reset, or Fibre Channel Login or Process Login..

Response:

SAM-2 chooses to make Target Reset and LUN Reset all upper case. FCP-2 will follow the same convention.

FC-FS chooses to use the abbreviations for Fibre Channel Login (PLOGI, FLOGI). FCP-2 will follow the same convention.

FC-FS chooses to capitalize Process Login. FCP-2 will follow the same convention.

The question will be formally asked for FC-FS in T11/00-284v1 to make sure this is correct.

This response was accepted in the June 7, 2000 meeting.

Installation:

The following corrected capitalizations were made throughout the document:

TARGET RESET, LOGICAL UNIT RESET, PLOGI, FLOGI, Process Login, Process Logout.

4.79: IBM comment from George Penokie (Editorial)

Page 9 - section 4.3 - There is a 'will' that needs to be changed into a 'shall'.

Response:

Accepted.

Installation:

Installed as requested.

4.80: IBM comment from George Penokie (Editorial)

Page xx - section xx - The term 'FCP I/O Operation' is stated to be the same as 'FCP exchange' but both are used throughout the standard. One term should be used in all cases. Pick one and change all others to match it. There also are places where the term 'task' seems to be being used where FCP exchange or FCP I/O operation may be better (e.g., table 4).

Response:

Accepted.

Installation:

Upon review, all cases where FCP I/O Operation is used indicate the performance of a SCSI I/O Operation. All cases where FCP exchange is used indicate the presence of a Fibre Channel exchange. I did not find any cases where these should be changed.

The September 11, 2000 working group suggested providing the following definitions in the glossary:

FCP Exchange - A SCSI I/O Operation for the Fibre Channel FC-2 layer. (See FC-FS.)

FCP I/O Operation - A SCSI I/O Operation for the Fibre Channel FC-4 layer, as defined in this standard.

Installed as agreed.

4.81: IBM comment from George Penokie (Editorial)

Page 9 - section 4.3 - The information about what things cause the CRN to be cleared is also in table 4. It appears that table 4 is more precise. The sentence 'The integer begins with a value of one after any Target Reset, LUN Reset, or Fibre Channel Login or Process Login occurs.' should be replaced with 'See table 5 for the actions that cause the CRN field to be set to 1.'

Response:

Accepted.

Installation:

Installed as requested.

PDF Page 26

4.82: IBM comment from George Penokie (Editorial)

Page 10 - section 4.3 - The 1,2,3 list should be an a,b,c list as there is not required order to the things listed.

Response:

Accepted.

Installation:

Installed as requested.

4.83: IBM comment from George Penokie (Technical)

Page 10 - section 4.3 - number 6 - There is no such thing as an execution queue. You may mean 'all tasks are in the ended state as defined by SAM-2' but in any case the term 'execution queue' needs to be replaced with a valid term.

Response:

Accepted in principle. SAM-2 has several different definitions for the possible states that a task may enter when condition 6) is present. The following wording is proposed, which also changes rule 5:

5) The device server shall not accept a command with a nonzero CRN into the dormant or enabled state until after all commands with a previous CRN have been received by the device server. The commands shall be assumed to be received in the order of increasing CRN, highest CRN last. The order of execution of the commands shall be managed by the normal task set management algorithms.

6) The device server shall accept any valid command with a CRN of 0 into the dormant or enabled state regardless of whether or not all commands with a nonzero CRN have been received. The order of execution of the commands shall be managed by the normal task set management algorithms.

This response was accepted in the June 7, 2000 meeting.

Installation:

Installed as approved.

4.84: IBM comment from George Penokie (Editorial)

Page 10 - section 4.3 - The statement 'Any command, including such initialization commands as INQUIRY, TEST UNIT READY, and MODE SENSE/ SELECT may always use a CRN of zero if the state of the EPDC bit is not known or if precise delivery is not...' First states 'Any command' then gives a list of some commands, why?. What is the point in saying 'any command' if you are going to qualify it. The statement should read 'Any command may use a CRN of zero if the state....'

Response:

Explanation is desirable as to some of the reasons for and possible uses of CRN values of zero. It will further be clarified that these are only examples. It was suggested that they should be included in a note.

This response was accepted in the June 7, 2000 meeting.

Installation:

Installed as approved.

4.85: IBM comment from George Penokie (Editorial)

Page 10 - section 4.4 - The word can needs to be removed.

Response:

Accepted.

Installed as requested.

4.86: IBM comment from George Penokie (Editorial)

Page 10 - section 4.4 - The statement 'Upon receiving the FCP_CONF, the SCSI target can be assured that the initiator has the information necessary to perform stateful recovery and can then discard its own copy of the information.' Should be changed to ' Upon receiving the FCP_CONF, the SCSI target shall (or may?) discard its own copy of the information. The removed wording add no information to the standard.

Response:

Accepted.

Installation:

Installed as requested.

4.87: IBM comment from George Penokie (Editorial)

Page 10 - section 4.4 - All information should be assumed to be 'critical' therefore it need not be stated as such. Remove the word 'critical' .

Response:

Accepted.

Installation:

Installed as requested.

4.88: IBM comment from George Penokie (Editorial)

Page 10 - section 4.3 - item 1 - The information about what things cause the CRN to be cleared is also in table 4. It appears that table 4 is more precise. The statement 'A PRLI, Target Reset task management function, and LUN Reset task management function shall reset the CRN to be transmitted....' should be replaced with 'See table 5 for the actions that cause the CRN to be transmitted '.

Response:

Accepted.

Installation:

Installed as requested.

PDF Page 27

4.89: IBM comment from George Penokie (Editorial)

Page 11 - section 4.4 - The term 'intermediate status' needs to be written as 'INTERMEDIATE status'.

Response:

Accepted.

Installation:

Installed as requested.

4.90: IBM comment from George Penokie (Editorial)

Page 11 - section 4.4 - The 1,2 list should be an a,b list there is no order to the items in the list.

Response:

Accepted.

Installation:

Installed as requested.

4.91: IBM comment from George Penokie (Editorial)

Page 11- Section 4.6 - table 2 - MODE SENSE should be MODE SENSE command.

Response:

Accepted.

Installation:

Installed as requested.

4.92: IBM comment from George Penokie (Editorial)

Page 11- Section 4.6 - table 2 - What is 'none' supposed to mean?

Response:

Accepted. "None" will be replaced with "Not required".

Installation:

Installed as accepted.

4.93: IBM comment from George Penokie (Editorial)

Page 11- Section 4.6 - table 2 - Why is there a blank row in this table?

Response:

Accepted.

Installation:

Installed as requested.

PDF Page 28

4.94: IBM comment from George Penokie (Editorial)

Page 12 - section 4.7 - The page number on the cross reference needs to be removed.

Response:

Accepted.

Installation:

Installed as requested.

4.95: IBM comment from George Penokie (Editorial)

Page 12 - section 4.8 - The statement 'cleared to its default or power-on value...' is not really correct. In many cases information is cleared to its saved values which in many cases is not the same as the default. Also, power-on value is not a good description. I think the best thing to say would be 'most recent saved value'.

Response:

Accepted.

Installation:

Installed "default, saved, or initial value".

4.96: IBM comment from George Penokie (Editorial)

Page 12 - section 4.8 - Sequences and exchanges should not be capitalized.

Response:

At present, FC-FS capitalizes Sequence and Exchange. Correction of this has been requested in T10/00-230v1.

Installation:

The FC-FS conventions require Sequence and Exchange to be capitalized. No change is required.

4.97: IBM comment from George Penokie (Editorial)

Page 12 - table 3 - The term 'SCSI-3 function' should be 'SAM-2 function'.

Response:

Accepted.

Installation:

Corrected as requested, 3 places.

PDF Page 29

4.98: IBM comment from George Penokie (Editorial)

Page 13 - table 4 - The term 'TPRLO' is not defined or a referenced made as to where it is defined. This needs to be fixed.

Response:

Accepted.

Installation:

Installed in note 5.

4.99: IBM comment from George Penokie (Editorial)

Page 13 - table 4 - The the clearing actions for TPRLO and SCSI target reset are identical. Why have both?

Response:

The two operations are widely disparate in source and independently happen to have the same clearing actions for all the listed items. This may or may not be true for any future additions to the table. No change is required.

This response was accepted in the June 7, 2000 meeting.

Installation:

No change is required.

4.100: IBM comment from George Penokie (Editorial)

Page 13 - table 4 - The terms 'SCSI initiator port', L_Ports, SCSI initiators, and ports all seem to be the same thing. One term should be used or the deferences between these terms clearly stated.

Response:

Accepted.

Installation:

All were changed to SCSI initiator ports. L_Ports are a special case and apply to any loop port.

4.101: IBM comment from George Penokie (Editorial)

Page 13 - table 4 - The terms 'tasks', 'FCP exchanges', and 'I/O Operations' seem to be the same thing. Only one name should be used.

Response:

Accepted.

Installation:

No change. See 4.80.

4.102: IBM comment from George Penokie (Editorial)

Page 13 - table 4 - The row entry 'only for ports of specified TYPE' should be removed as this standard only defines one TYPE (i.e., SCSI). No other TYPE applies.

Response:

PRLI can be performed for non-SCSI devices while SCSI devices are present. As a result, the case can occur and should be considered. No change will be made.

It was proposed that this instead be included in the column header.

This response was tentatively accepted in the June 7, 2000 meeting.

Installation:

After further review, I believe the present definition is complete, correct, and clear. No change was made.

At the September 11, 2000 working group, the following additional suggestions were agreed upon, affecting both this comment and the next.

- a) Target Power On shall remain as a link function, not a SCSI function. It needs to be removed from the second clearing table.
- b) The LIP columns should refer instead to cases where discovery has failed. This applies to all LIPs.
- c) OLS requires a new login and should be treated like the LOGI/LOGO column.
- d) Note 15 of the first clearing table applies only to OLS. the FLOGIN must be successful and have the same F_Port name and fabric name. For point-to-point topologies, discovery is not possible.
- e) LRR/LR only resets credit and should not reset any other functions. It will not be included in the table.

f) Reset LIP should be reviewed to make sure it affects only the addressed port. FC-PLDA indicates:

Upon recognition of LIP(AL_PD,AL_PS) the NL_Port designated by AL_PD shall perform the appropriate resetting actions specified in table 16. All other L_Ports shall treat this as LIP(F7,AL_PS). SCSI Targets are prohibited from issuing this LIP.

It indicates (as best I can interpret) in table 16 of FC-PLDA that, while only the selected port is reset, the reset is so complete that states associated with all initiators logged into that port are cleared.

Table 4 appears to correctly reflect these behaviors.

g) The phrase “Only for SCSI initiator port initiating action” should be changed to “Only for the initiator port associated with the action”.

h) The titles of the second clearing table needs to be corrected. The title of the columns in table 4 was changed to “FC link action effecting FCP target object”, and the title in table 5 was changed to “FCP-2 SCSI initiator action effecting target object”. The title of the second clearing table was changed to “Clearing effects of SCSI initiator actions”.

j) Note 8 should be changed to include the requirement that it applies to an FCP-2 type device. The row associated with type can then be removed.

4.103: IBM comment from George Penokie (Editorial)

Page 13 - table 4 - The 'N' in the TPRLO column/for all logged-in SCSI initiator ports should be a 'Y' when the 'only for ports of specified TYPE' row is removed.

Response:

See 4.102. No change is required.

It was proposed that this instead be included in the column header.

This response was tentatively accepted in the June 7, 2000 meeting.

Installation:

After further review, I believe the present definition is complete, correct, and clear. No change was made.

The resolutions of 4.103 also resolve this question.

4.104: IBM comment from George Penokie (Editorial)

Page 13 - table 4 - In several places a statement like 'for all xxxx SCSI initiator ports' is made. The meaning of this is not clear. Does it mean for all initiators on all the ports connected either physically or logically to the device on which the port resides or only those initiator ports that reside on the same physical loop? The current wording could be interpreted either way.

Response:

Accepted.

Installation:

An additional introductory sentence was provided with the following text:

Rows indicating an effect for all initiator ports have the specified effect on all ports, regardless of the link that attaches the initiator port to the target.

4.105: IBM comment from George Penokie (Editorial)

Page 13 - table 4 - The 'Y' in columns LOGO, PLOGI and PRLI, PRLO row PRLI parameters cleared only for port initiating action should be '-'. Because the operation on the port is the login or logout so there can be no specified tasks going on.

Response:

Logouts can be executed for ports even when tasks are going on. As a result, clearing parameters must still be considered. No change will be made.

This response was accepted in the June 7, 2000 meeting.

Installation:

No change was made.

4.106: IBM comment from George Penokie (Editorial)

Page 13 - table 4 - The 'N' and 'Y' in column LOGO, PLOGI rows for 'SCSI target mode page parameters restored from saved pages' should both reference note 12.

Response:

Accepted.

Installation:

Installed as requested.

4.107: IBM comment from George Penokie (Editorial)

Page 13 - table 4 - The row 'pre-existing SCSI, UA, and deferred error conditions cleared only of port initiating action' it is not clear that these actions only apply for any pre-existing conditions that were caused by the initiating initiator. (i.e., if there is an ACA and an initiator logs in that is not the initiator that caused the ACA the ACA will not be cleared.) This needs to be made clear.

Response:

Accepted.

Installation:

I believe this is clear from the fact that they are not cleared except for the port initiating the function. No change was made.

This item was further discussed in the September 11, 2000 working group meeting. In the case of ACA, the state exists for a single I_T_L nexus and the state modifies the behavior of any other I_T_L nexus with the same value of L. In the case of deferred errors, the condition is related to a causing initiator, but may be passed to more than one initiator and may be passed to the wrong initiator. This is made clear in SPC-2, PDF page 175. The discussion determined that no additional changes to the table were required to resolve this problem.

4.108: IBM comment from George Penokie (Editorial)

Page 13 - table 4 - The term 'UA' is not defined and should be changed to 'unit attention' in all cases.

Response:

Accepted.

Installation:

Installed as requested.

4.109: IBM comment from George Penokie (Editorial)

Page 13 - table 4 - It is not clear if the clearing actions causes the CRN to be set to 1 or 0. This needs to be specified.

Response:

Accepted.

Installation:

Placed in row definition. Note that this is also indicated in the referencing sections.

4.110: IBM comment from George Penokie (Editorial)

Page 14 - table 4 - note 4 - The statement '...,not the entire SCSI target.' contains no useful information and should be deleted.

Response:

Accepted.

Installation:

Installed as requested.

4.111: IBM comment from George Penokie (Editorial)

Page 14 - table 4 - note 5 - The statements 'Global bit = '1b'. If the Global bit ='0b',...' should be 'GLOBAL is set to 1. IF the GLOBAL bit is set to 0,....' Global should be in small caps. Also there is no indication as to where the global bit is defined. This needs to be added.

Response:

Accepted.

Installation:

Installed as requested. This is in FC-FS.

4.112: IBM comment from George Penokie (Editorial)

Page 14 - table 4 - note 8 - The statement '...only "establish image pair"=1.' is unclear. What is an establish image pair and where is it defined?

Response:

Accepted.

Installation:

The reference to 6.3.7.5 was provided.

4.113: IBM comment from George Penokie (Editorial)

Page 14 - table 4 - note 11 - The term 'APTPL' is not defined. It needs to be defined a reference added to where it is defined.

Response:

Accepted.

Installation:

A reference to SPC-2 was provided. The term was also placed in the "abbreviations" list.

4.114: IBM comment from George Penokie (Editorial)

Page 14 - table 4 - note 12 - The statement '...of proper management of mode pages.' should be 'of management of mode pages.' The term 'proper' should be deleted from here ~~and are~~ in the table 5 heading.

Response:

Accepted.

Installation:

Installed as requested.

4.115: IBM comment from George Penokie (Editorial)

Page 14 - table 5 - The two entries labeled 'discard current mode pages' should be changed to 'not specified'. There is no reason to force the device to discard current mode pages or do any other action with mode pages at this point.

Response:

Accepted. See 6.51.

Installation:

Installed as requested.

Note that T10-00-342r0 also references this issue. At the time, the thought was to specify the PRLI unshared case as “unspecified”, but after further study, I have used “use saved or default mode pages”.

4.116: IBM comment from George Penokie (Editorial)

Page 13 - table 4 - note 13 - This note attempts to give, what appears to be, a reason for an implicit logout may happen. This is more confusing than helpful. The reason should be removed and just the reference should be specified.

Response:

Accepted.

Installation:

Installed as requested.

PDF Page 31

4.117: IBM comment from George Penokie (Editorial)

Page 15 - Section 4.10 - The reference to ANSI X3.230 should be changed to the common name of that standard.

Response:

Accepted.

Installation:

Installed as requested.

PDF Page 32

4.118: IBM comment from George Penokie (Editorial)

Page 16 - section 5.1 - The word 'uniquely' should be deleted in 2 places. The term does add any information to the standards requirements.

Response:

Accepted.

Installation:

Installed as required.

4.119: IBM comment from George Penokie (Editorial)

Page 16 - section 5.1 - The statement ...'defined in the following table...' should reference the exact table.

Response:

Accepted.

Installation:

The table was deleted and the text corrected.

4.120: IBM comment from George Penokie (Editorial)

Page 16 - section 5.1 - The statement '...parameters that uniquely identify the exchange between the initiator and target.' should be replaced with '...the fully qualified exchange identifier (FQXID).' Then replace the next sentence with 'The FQXID is defined in table xxx.' Of course there is another possibility and that is that there are some other undefined parameters

in addition to the S_ID and D_ID. If that is the case then they should be stated and not left to the reader imagination. If that is the case then the second sentence still needs to be modified but how depends on the answers.

Response:

Accepted.

Installation:

Rewritten to combine the two offending sentences.

4.121: IBM comment from George Penokie (Editorial)

Page 16 - section 5.1 - The term Required should not be capitalized.

Response:

Accepted.

Installation:

The table and the offending sentence have been deleted.

4.122: IBM comment from George Penokie (Editorial)

Page 16 - section 5.1 - LUs are not inside ports. The statement '...internal to an addressed NL_Port...' should be deleted from the sentence.

Response:

Accepted.

Installation:

Installed as requested.

4.123: IBM comment from George Penokie (Editorial)

Page 16 - section 5.1 - You have been using the term FCP I/O operation and the term exchange independently up to this point. Now it appears you are equating it to an exchange. Are these two term interchangeable? If so then only one should be used exclusively except for possibly a single definition were both terms are used.

Response:

Accepted.

Installation:

They are two different views using a common identifying tool, the FQXID. The Exchange is the FC construct carrying the protocol elements of the FCP I/O Operation. This was clarified.

4.124: IBM comment from George Penokie (Editorial)

Page 16 - section 5.1 - In one sentence three undefined terms appear; logical initiator, logical target, and process associator. These terms need to be defined.

Response:

Accepted.

Installation:

The offending sentence was deleted along with the use of Process Associators.

4.125: IBM comment from George Penokie (Editorial)

Page 16 - section 5.1 - I did not know targets were a form of intelligent life! The sentence: 'The target is required to be cognizant of the OX_ID to perform error recovery and task management functions.' should be changed to: 'In order to perform error recovery and task management functions SCSI device servers shall support the OX_ID address identifier.'

Response:

Device servers are not slings either. Accepted in principle, but using the verb "record".

Installation:

After further review, the term “uses” seemed most appropriate.

4.126: IBM comment from George Penokie (Editorial)

Page 16 - section 5.1 - table 6 - The definition of 'R' should be in the table not part of the text outside the table.

Response:

Accepted.

Installation:

The offending table was deleted.

4.127: IBM comment from George Penokie (Editorial)

Page 16 - section 5.1 - table 6 - There is a blank cell under RX_ID; what does that mean?

Response:

Accepted in principle. The table is removed. See 3.10.

Installation:

The offending table was deleted.

4.128: IBM comment from George Penokie (Editorial)

Page 16 - section 5.2 - The first three sentences would read better if rewritten as follows: 'Any third-party SCSI command parameters that contain 64-bit fields (e.g., COPY command, and RESERVE command) that define access to other SCSI devices through FCP_Ports shall format the 64-bit field as defined in table 7.

Response:

Accepted.

Installation:

The following text was used instead:

SCSI commands (e.g., the COPY and RESERVE commands) that use the 64-bit THIRD-PARTY DEVICE ID defined by SPC-2 shall use the FCP third-party device id format defined in table 7 to identify the third-party target.

4.129: IBM comment from George Penokie (Editorial)

Page 16 - section 5.1 - table 6 - What is a 'basic operation'? I see no explanation of what it is or does. On needs to be added.

Response:

Accepted.

Installation:

The offending table was deleted.

PDF Page 33

4.130: IBM comment from George Penokie (Editorial)

Page 17 - sections 5.2.1, 5.2.2, and 5.2.3 - There is no need for these sections. Normally the fields are defined in paragraphs under the table. If these sections remain then you have to eliminate the hanging text and table between 5.2 and 5.2.1 by putting that information into a section 5.2.1 and incrementing the remaining 5.2.x sections.

Response:

Accepted. The text will be integrated into 5.2 as necessary and deleted as possible.

Installation:

Divisions were eliminated. Process Associator text was deleted.

4.131: IBM comment from George Penokie (Editorial)

Page 17 - section 5.2.1 and throughout the document - All italics should be removed and replace with normal text.

Response:

Accepted.

Installation:

Offending text was deleted. The remainder of the document had already been searched for the use of italics in bit definitions.

4.132: IBM comment from George Penokie (Editorial)

Page 17 - section 5.2.1 - The statement 'If this bit is set...' should be changed to 'If the process associator value (PA_VAL) bit is set...'. Without this change I have no idea what 'this bit' is. and The second 'If this bit...' should be 'If the PA_VAL bit ...'

Response:

Accepted.

Installation:

The offending text was deleted.

4.133: IBM comment from George Penokie (Editorial)

Page 17 - section 5.2.2 - The statement 'This field defines..' should be changed to 'The FCP_Port identifier field defines...'.
The offending text was deleted.

Response:

Accepted.

Installation:

Installed as requested.

4.134: IBM comment from George Penokie (Editorial)

Page 17 - section 5.2.3 - The statement 'If the PA_VAL bit indicates that this field is valid, the field defines the..' should be 'If the PA_VAL bit is set to 1, the process associator field defines the'

Response:

Accepted.

Installation:

The offending text is deleted.

4.135: IBM comment from George Penokie (Editorial)

Page 17 - section 5.3 - The statement 'According to FC-PH...' should be 'As specified in FC-PH...'

Response:

Accepted in principle. FC-PH should be FC-FS.

Installation:

Installed as requested.

4.136: IBM comment from George Penokie (Editorial)

Page 17 - section 5.3 - In one sentence 2 terms are used for the same thing; address identifier and S_ID. This is confusing to the reader. Only one name for one thing should be used. Pick one and use it constantly throughout the document.

Response:

Accepted.

Installation:

In this particular case, address identifier is the proper term. Installed as requested.

4.137: IBM comment from George Penokie (Editorial)

Page 17 - section 5.3 - Remove the statement '(page code 83h)'. That information is not important to this standard and can be found in SPC-2.

Response:

Accepted.

Installation:

Installed as requested.

4.138: IBM comment from George Penokie

(T) Page 17 - section 5.3 - The statement: 'For FCP-2 devices with a single LUN, the world-wide unique name of the LUN may be the same as the world-wide unique name for the Fibre Channel node.' should be changed to 'For FCP-2 devices with a LUN 0, the world-wide unique name of the LUN 0 may be the same as the world-wide unique name for the Fibre Channel node.' This change will have no effect on devices covered under the current definition but would give guidance to multi-LUN devices as to what the node should be.

Response:

Accepted. The following wording improvement was provided in the April 5, 2000 meeting:

For devices compliant with this standard and having a LUN 0, the world wide name of the LUN 0 may be the same as the world wide name for the Fibre Channel node.

In addition, the following editorial change was agreed upon:

The words used shall be "world wide name" (three words, all lower case). Glossary entries for world wide name, world wide port name, and world wide node name will be provided. Abbreviations of WW-PN, WWNN, and WWN will be defined. These conventions will be used throughout the document.

Installation:

The following terms, extracted from the official FC-FS glossary were defined in the glossary by 8.22:

Worldwide_Name: A Name_Identifier which is worldwide unique, and represented by a 64 bit unsigned binary value.

Name_Identifier: A 64 bit identifier, with a 60 bit value preceded with a 4 bit Net-work_Address_Authority Identifier, used to identify entities in Fibre Channel such as N_Port, Node, F_Port, or Fabric (see Table 28 and Table 29).

Node_Name: A Name_Identifier associated with a Node.

Port_Name: A Name_Identifier associated with an N_Port or an NL_Port.

The text was rewritten to make proper use of this in section 5.3.

WWN was added to the abbreviations.

4.139: IBM comment from George Penokie (Editorial)

Page 17 - section 5.3 - I would like to see everything relating to persistent reservation in this section placed in a section that only deals with persistent reservation. Putting it in this section is confusing. It may also need to be expanded somewhat to make it clear as to how WWIDs relate to Persistent reservation.

Response:

There should be only two items related to persistent reservation in FCP-2:

- a) This section on maintaining information based on WWN.
- b) The clearing actions in table 4.

Concentrating those two items in one place and taking them away from their more natural location would not clarify the document. No change is proposed. In the June 7, 2000 working group meeting, it was suggested that this description should be expanded.

Installation:

The rewrite should have clarified some of these issues, but no other change was made.

PDF Page 34

4.140: IBM comment from George Penokie (Editorial)

Page 18 - section 5.4 - table 8 - key - The references to specific subclauses in other standards should be removed.

Response:

Accepted.

Installation:

Installed as requested.

4.141: IBM comment from George Penokie (Editorial)

Page 18 - section 5.4 - table 8 - key - The H and T need to be added to the key list not hidden in the explanation of a different key.

Response:

Accepted.

Installation:

Installed as requested.

4.142: IBM comment from George Penokie (Editorial)

Page 18 - section 5.4 - table 8 - notes - The should be a cross-reference to table 9 after the statement '..an I5 frame...'

Response:

Accepted.

Installation:

Installed as requested.

4.143: IBM comment from George Penokie (Editorial)

Page 18 - section 5.4 - table 8 - 'Note' should be 'Notes'

Response:

Accepted.

Installation:

Installed as requested.

PDF Page 35

4.144: IBM comment from George Penokie (Editorial)

Page 19 - section 5.4 - table 9 - All the comments on table 8 apply to table 9 except for the cross-reference.

Response:

Accepted.

Installation:

Installed as requested.

4.145: IBM comment from George Penokie (Editorial)

Page 19 - section 5.5 - The statement 'The FCP needs only...' should be changed to 'The FCP requires only...'

Response:

Accepted.

Installation:

Installed as requested.

4.146: IBM comment from George Penokie (Editorial)

Page 19 - section 5.5 - There are references to specific annexes in another standard that must be removed.

Response:

Accepted.

Installation:

Installed as requested.

4.147: IBM comment from George Penokie (Editorial)

Page 19 - section 5.5 - I assume the '.' between FC_PH_SEQUENCE_TAG.indication should not be there..

Response:

This is the value used in the service definition of FC-FS, annex R. No change will be made. This resolution was accepted in the June 7, 2000 working group meeting.

Installation:

No change was made.

PDF Page 36

4.148: IBM comment from George Penokie (Editorial)

Page 20 - section 5.6 - table 10 - There is a format problem with the table in that the right side is missing some of its double-lines.

Response:

Accepted.

Installation:

Installed as requested.

4.149: IBM comment from George Penokie (Editorial)

Pages 20 and 21 - sections 5.6.1 to 5.6.11. - Although I can see a benefits to doing it this way normally the field definitions are not separated from a table by sections. The sections should be removed. However, if this comment is rejected then the hanging text and table must be removed in the same manor as described in a previous comment.

Response:

Accepted in principle. The hanging text will be removed.

Installation:

Installed as requested.

4.150: IBM comment from George Penokie (Editorial)

Pages 20 and 21 - sections 5.6.2, 5.6.3, 5.6.6 and 5.6.7 - All these sections have the same problem. They do not tell the reader what is in the field, instead they define terms which have already be defined elsewhere in the standard. To fix this the should all be changed to read for example: The D_ID field identifies the D_ID of the destination of the frame.

Response:

For those fields having a definition in other locations, the definition will be referenced. For example:

The D_ID field contains the D_ID (see 3.1.14 and 3.2).

Installation:

The text improvement is installed. The references are in the abbreviations section, which probably is implicit, so no references were installed.

PDF Page 37

4.151: IBM comment from George Penokie (Editorial)

Page 21 - section 5.6.11 - There is no such thing as a 'SCSI-3 application client'. I assume this should be 'application client'.

Response:

Accepted.

Installation:

Installed as requested.

4.152: IBM comment from George Penokie (Editorial)

Page 21 - section 5.6.11 - The statement 'other FC-PH information' is not clear. What other information is being referred to? This should be changed to 'FC-PH information' unless the 'other' can be more completely defined.

Response:

Accepted.

Installation:

Offending text was deleted during rewrite.

4.153: IBM comment from George Penokie (Editorial)

Page 21 - Section 5.6.9 and 5.9.10 - The term element is used in relation to FQXID but in the section that defines FQXID there is not description of elements. Maybe it should be '..is a part of the FQXID.' or '... is one of the identifiers contained within the FQXID.'

Response:

Accepted.

Installation:

Installed as requested.

PDF Page 38

4.154: IBM comment from George Penokie (Editorial)

Page 22 - section 6 - The paragraphs between the 6 header and 6.1 header are hanging and should be fixed.

Response:

Accepted.

Installation:

Installed as requested.

4.155: IBM comment from George Penokie (Editorial)

Page 22 - section 6 - In the following sentence it is not clear what '... and summarized below.' is supposed to mean. 'The protocol also includes the process login and process logout extended link services in ANSI X3.297 and summarized below.'

Response:

Accepted.

Installation:

Clarified as requested.

4.156: IBM comment from George Penokie (Editorial)

Page 22 - section 6 - The statement '...may require new login procedures.' Makes it should like this standard is going to define some new login procedures. I do not think this is the case. Maybe it should state '...may require login.'

Response:

Accepted.

Installation:

Text changed to read:

Devices introduced into a configuration or modifications in the addressing or routing of the configuration may require ~~new~~ repeating those login procedures.

4.157: IBM comment from George Penokie (Editorial)

Page 22 - section 6.1 - The term 'Process' should not be capitalized.

Response:

Accepted. This is routinely, but inconsistently, violated in FC-FS. This will be added to the document T10/00-230r1.

Installation:

Following the FC-FS conventions, Process Login will be capitalized.

4.158: IBM comment from George Penokie (Editorial)

Page 22 - section 6.1 - The statement '(LS_Command code = "20" hexadecimal)' should be removed as it is defined in the referenced standard.

Response:

Accepted.

Installation:

Installed as requested.

4.159: IBM comment from George Penokie (Editorial)

Page 22 - section 6.1 - The statement '...capabilities to be announced by the...' should be replaced with '...capabilities to be reported by the...'. This change assumes that FC does not have a PA system to make announcements over.

Response:

Accepted.

Installation:

Installed as requested.

4.160: IBM comment from George Penokie (Editorial)

Page 22 - section 6.1 - The term 'image pair' should be added to the definitions section.

Response:

Accepted.

Installation:

Installed as requested.

4.161: IBM comment from George Penokie (Editorial)

Page 22 - section 6.1 - In the statement '...PRLI can reject the command...' it is not at all clear what command is being rejected. So what command is being rejected?

Response:

Accepted. The command is the PRLI ELS.

Installation:

Installed as requested.

4.162: IBM comment from George Penokie (Editorial)

Page 22 - section 6.1 - The text '...LS_Command code = "21" hexadecimal...' should be removed as it is defined in the referenced standard.

Response:

Accepted.

Installation:

Installed as requested.

4.163: IBM comment from George Penokie (Editorial)

Page 22 - section 6.1 - The 1,2,3 list should be an a,b,c list.

Response:

Accepted.

Installation:

Installed as requested.

4.164: IBM comment from George Penokie (Editorial)

Page 22 - section 6.1 - The statement '...is exchanged enabling subsequent...' would be clearer if it stated '...is exchanged during the process login enabling subsequent...'

Response:

Accepted.

Installation:

Installed as requested.

4.165: IBM comment from George Penokie (Editorial)

Page 22 - section 6.1 - The term 'explicitly' should be deleted. There is no difference between explicitly establishes a relationship and establishes a relationship.

Response:

Accepted.

Installation:

Installed as requested.

4.166: IBM comment from George Penokie (Editorial)

Page 22 - section 6.1 - The term 'modes of operation' seems to be equal to the term 'capabilities' used else where in this section. Replace 'modes of operation' with 'capabilities'.

Response:

Accepted.

Installation:

The word “modes of operation” occurs in two contexts. The first is corrected as requested. The second is changed to performing one of two “actions”.

4.167: IBM comment from George Penokie (Editorial)

Page 22 - section 6.1 - The sentence: 'Such capabilities include channel or device (FC-SB), initiator or target (FCP), and similar values.' should be replaced with something like: '(e.g., indication if node is a channel or device (FC-SB), an initiator or target (this standard), and similar values).

Response:

Accepted.

Installation:

Installed text was:

Capabilities include parameters indicating channel or device (FC-SB), initiator or target (FCP), and similar characteristics.

4.168: IBM comment from George Penokie (Editorial)

Page 22 - section 6.1 - The following sentence 'Requirements include values such as the parameters controlling the FCP IUs that must be used.' should be replaced with something like '(e.g., parameters controlling the FCP IUs that must be used).

Response:

Accepted.

Installation:

The text was modified to read:

Requirements include values such as the parameters controlling the FCP functions that may be used between members of an image pair.

4.169: IBM comment from George Penokie (Editorial)

Page 22 - section 6.1 - The term Parameter should not be capitalized.

Response:

Accepted.

Installation:

In this case, since the collective service parameters are being discussed instead of the Service Parameter page, the requested change was installed.

4.170: IBM comment from George Penokie (Editorial)

Page 22 - section 6.2 - The paragraphs between sections 6.2 and 6.2.1 are hanging.

Response:

Accepted.

Installation:

Installed as requested.

4.171: IBM comment from George Penokie (Editorial)

Page 22 - section 6.2 - The statement '...according to the rules below.' is not specific. It needs to indicate by cross reference in which subclauses the rules are located.

Response:

Accepted.

Installation:

The relevant text is immediately following, so the reference was simply removed.

4.172: IBM comment from George Penokie (Editorial)

Page 22 - section 6.1 - item 2 - Is this 'service parameter information' or some other form on 'information' . The current statement implies there is some, unspecified, type of information for the Binding mode.

Response:

Accepted.

Installation:

Installed as requested.

4.173: IBM comment from George Penokie (Editorial)

Page 22 - section 6.1 - There should be a reference to table 4 which contains the clearing actions relating to PRLI and PRLO.

Response:

Accepted.

Installation:

Installed as requested.

PDF Page 39

4.174: IBM comment from George Penokie (Technical)

Page 23 - section 6.2 - Are the same PRLI parameters and codes defined in two different standards? If so then which one has priority when then is a conflict?

Response.

At present, some of these parameters are defined in FC-FS (FC-PH-2). FCP-2 will reference those parameters and codes in FC-FS, only providing additional constraining information where necessary. The FCP-2 will reference FC-FS.

This resolution was accepted in the June 7, 2000 working group meeting.

Installation:

Clean-up of the text was required in 6.3.7.2, 6.3.7.3, 6.3.7.4, 6.3.7.5, and 6.3.8.2.

4.175: IBM comment from George Penokie (Editorial)

Page 23 - section 6.2.1 and else where - The term Process Associator should not be capitalized.

Response:

Accepted. See T10/00-230r2.

Installation:

Following the FC-FS conventions, the term shall be Process_Associator.

4.176: IBM comment from George Penokie (Editorial)

Page 23 - section 6.2.1 - The statement '...shall return exactly one page..' should be changed to '...shall return one page...' The is no additional information carried in the word exactly.

Response:

Accepted.

Installation:

Installed as requested.

4.177: IBM comment from George Penokie (Editorial)

Page 23 - section 6.2.1 and others - What is a 'service parameter page'? What is in it and where is it defined?

Response:

Accepted.

Installation:

These parameters are defined in FC-FS, as referenced. No change is required.

4.178: IBM comment from George Penokie (Editorial)

Page 23 - section 6.2.1 and others - The term 'page' is used several times without a clear definition of what a 'page' is, what it contains, and where it is defined.

Response:

Accepted.

Installation:

This is defined in FC-FS. References to the FC-FS definition of PRLI and all its parameters, including the Service Parameter pages, are included in the first sub-clause of this clause.

4.179: IBM comment from George Penokie (Editorial)

Page 23 - section 6.2.1 - In the statement 'Use if this mechanism requires...' I assume you mean 'Use of process associators requires...'. If so it should be changed if not the mechanism needs to be stated.

Response:

Accepted.

Installation:

This text is removed because of the removal of Process Associators from FCP-2.

4.180: IBM comment from George Penokie (Editorial)

Page 23 - section 6.2.1 - The statement 'precise and detailed' should be removed as it add no value to the sentence it is in.

Response:

Accepted.

Installation:

Installed as requested.

4.181: IBM comment from George Penokie (Editorial)

Page 23 - section 6.2.1 - The sentence 'That information may be obtained by mechanisms outside the scope of the FCP or may be obtained by performing a PRLI requesting informative communication. needs to be restated as 'That information may be obtained by performing a PRLI requesting informative communication or by other mechanisms outside the scope of the this standard.'

Response:

Accepted.

Installation:

Installed as requested.

4.182: IBM comment from George Penokie (Technical)

Page 23 - section 6.2.1 and others - So in addition to undefined service parameter pages and pages this section also has undefined service pages. All this needs to be cleared up.

Response:

Accepted.

This resolution was accepted in the June 7, 2000 working group meeting.

Installation:

All text was corrected to “FCP Service Parameter page”.

4.183: IBM comment from George Penokie (Editorial)

Page 23 - section 6.2.1 - The term 'informative communications' does not seem to be defined anywhere. What is it?

Response:

Accepted.

Installation:

Changed to “an informative action” as defined earlier in the clause.

4.184: IBM comment from George Penokie (Editorial)

Page 23 - section 6.2.2 - The sentence 'In the ACC, the service parameter pages shall be returned using the same originator PA and invalid responder PA indication.' Seems incomplete. The same originator PA and invalid responder PA indication as what? (i.e., The same as what?)

Response:

Accepted.

Installation:

Deleted during rewrite that removed Process Associators.

4.185: IBM comment from George Penokie (Editorial)

Page 23 - section 6.2.2 - Now we have binding communications which is not defined to go along with informative communications. What are all these forms of communication?

Response:

Accepted.

Installation:

The word is changed to binding action to match the previous definition.

4.186: IBM comment from George Penokie (Editorial)

Page 23 - sections 6.2.1 and others - The acronym PA as suddenly appeared and it is not defined anywhere. I assume it stands for process associator but it could be anything. I recommend PA be replaced with process associator in all cases (assuming that's what it stands for).

Response:

Accepted.

Installation:

Installed as requested.

4.187: IBM comment from George Penokie (Editorial)

Page 23 - section 6.2.3 - The statement 'The request pages...' should be 'The requested pages...'.

Response:

Accepted.

Installation:

Deleted by the removal of Process Associators from FCP-2.

4.188: IBM comment from George Penokie (Editorial)

Page 23 - section 6.2.3 - Now we have binding communications which is not defined to go along with informative communications. What are all these forms of communication?

Response:

Accepted. Text will be provided to clarify this.

Installation:

See 4.185.

PDF Page 40

4.189: IBM comment from George Penokie (Editorial)

Page 24 - section 6.2.5 - To add to the list of unknown pages this section now references a PRLI page. The same questions apply; What's in it, and where is it defined?

Response:

Accepted. This will be clarified.

Installation:

See 4.185.

4.190: IBM comment from George Penokie (Editorial)

Page 24 - section 6.2.5 - The following sentence is unclear as to the information it is conveying. 'A new PRLI page to an already established image pair replaces the previous parameters with new PRLI parameters.' I believe the following would be better 'A new PRLI page that references an already established image pair replaces the previous parameters with the new PRLI parameters.'

Response:

Accepted.

Installation:

Offending text was removed during rewrite associated with removing Process_Associators.

4.191: IBM comment from George Penokie (Editorial)

Page 24 - sections 6.2.5 - In my long standing war against excess executions I would like the following statement; 'Immediately after the execution of the first PRLI...' changed to 'After the completion of the first PRLI...' The term 'immediately' cannot be quantified and therefore should be removed where ever used.

Response:

Accepted.

Installation:

Installed as requested.

4.192: IBM comment from George Penokie (Editorial)

Page 24 - section 6.2.5 - The 'will' needs to be replaced with a shall.

Response:

Accepted.

Installation:

Corrected by rewrite to remove Process_Associator.

4.193: IBM comment from George Penokie (Editorial)

Page 24 - section 6.2.5 - The statement 'The MODE SELECT parameters will assume their default or saved states...' should be changed to 'The MODE SELECT parameters shall be set to their default or saved values...'

Response:

Accepted.

Installation:

Removed during installation of pointer to clearing action table.

4.194: IBM comment from George Penokie (Editorial)

Page 24 - section 6.2.5 - The statement '... for all image pair.' should be '...for all image pairs.'

Response:

Accepted.

Installation:

Removed during installation of pointer to clearing action table.

4.195: IBM comment from George Penokie (Editorial)

Page 24 - section 6.2.5 - The statements '(Sense Key = 6)' and '(ASC=29,ASCQ=00)' should be removed as they are defined in other standards.

Response:

Accepted.

Installation:

Installed as requested.

4.196: IBM comment from George Penokie (Editorial)

Page 24 - sections 6.2.5 - The 'which' should be replaced with a 'that'..

Response:

Accepted.

Installation:

Installed as requested.

4.197: IBM comment from George Penokie (Editorial)

Page 24 - section 6.2.5 - The statement 'first attempt to communication' seem vague. Do you mean 'the first SCSI task sent'? If so change the words should be changed.

Response:

Accepted.

Installation:

Removed during rewrite to remove Process_Associator.

4.198: IBM comment from George Penokie (Editorial)

Page 24 - section 6.2.5 - The term 'reset state' is not correct. It should be 'reset condition'.

Response:

Accepted.

Installation:

Sentence is rewritten to refer instead to performing clearing actions and establishing the unit attention condition.

4.199: IBM comment from George Penokie (Editorial)

Page 24 - section 6.2.5 - The statement; 'Devices may have default PRLI information provided at the time the device is installed in the configuration.' should be changed to 'Devices may have default PRLI information provided in a manor outside the scope of this standard.'

Response:

Accepted.

Installation:

Installed as requested.

4.200: IBM comment from George Penokie (Editorial)

Page 24 - section 6.2.5 - The statement; 'If a device has no such default parameters and...' should be changed to 'If a device has no default parameters and...'

Response:

Accepted.

Installation:

Corrected by another comment.

4.201: IBM comment from George Penokie (Editorial)

Page 24 - section 6.2.5 - The statement '...if no PRLI has been performed since power on or the last PRLO,...' does not talk about reset. Is this intentional?

Response:

Accepted. This needs to be clarified.

Installation:

Clarified by a different comment resolution.

4.202: IBM comment from George Penokie (Technical)

(T) Page 24 - section 6.2.5 - The statement ...'will close the exchange with an ABTS or ABTX ELS.'" is in direct conflict with PLDA which states that a target shall never initiate an ABTS. PLDA states that in this case the target does a PRLO. Because many devices have been implemented to the PLDA this standard should be made to match it. This section is also in direct conflict with section 12.7.

Response:

Accepted. See 1.25. This was agreed upon in the April 5, 2000 meeting.

Installation:

Corrected by 1.25 and 1.22.

4.203: IBM comment from George Penokie (Editorial)

Page 24 - section 6.2.5 - The term 'ABTX ' is only used one time in this standard. It needs to be defined or a reference added to where it is defined.

Response:

Accepted.

Installation:

The reference was removed as part of the rewrite of 6.2.5.

PDF Page 41

4.204: IBM comment from George Penokie (Editorial)

Page 25 - section 6.2.6 - table 11 and 12 - The entry 'hexadecmial '08', SCSI FCP' should be changed to 'SCSI FCP (08h)'.

Response:

Accepted.

Installation:

Installed as requested.

4.205: IBM comment from George Penokie (Technical)

(T) Page 25 - section 6.2.6 - table 11 and 12 - One of the obsolete entries has a requirement. How can something that is obsolete have a requirement? The requirement should be removed.

Response:

In the April 5, 2000 meeting of the committee, the decision was to leave Read XFER_RDY Disabled defined, but to make the “0” state of the bit obsolete.

Installation:

Installed as approved.

4.206: IBM comment from George Penokie (Editorial)

Page 25 - section 6.2.6 - The information between 6.2.6 and 6.2.6.1 is hanging and needs to be unhung.

Response:

Accepted.

Installation:

Installed as requested.

4.207: IBM comment from George Penokie (Editorial)

Page 25 -27 - sections 6.2.6.x - These section titles should be removed. I suggest making them into run in headers (like the definitions list) which would keep the identity of the sections and get rid of the hung information.

Response:

Accepted.

Installation:

Installed as requested.

4.208: IBM comment from George Penokie (Editorial)

Page 25 - section 6.2.6.1 - The statement 'The value of hexadecimal '08' in this byte...' needs to be changed to 'The value 08h in this byte...'

Response:

Accepted.

Installation:

Installed as requested.

PDF Page 42

4.209: IBM comment from George Penokie (Editorial)

Page 26 - section 6.2.6.5 - The term 'originator process associator' is in small caps when it is not the name of the field but the contents of the field. The term should be in normal text not caps.

Response:

Accepted.

Installation:

Installed as requested.

4.210: IBM comment from George Penokie (Editorial)

Page 26 - section 6.2.6.6 - The term 'responder process associator' is in small caps when it is not the name of the field but the contents of the field. The term should be in normal text not caps.

Response:

Accepted.

Installation:

Installed as requested.

4.211: IBM comment from George Penokie (Editorial)

Page 26 - section 6.2.6.7 - Here we are again back to the 'page' name. I assume this is the 'FCP service parameter page, PRLI request' but it is not clear if that is the case or not.

Response:

Accepted.

Installation:

This was corrected by the rewrite for another comment.

4.212: IBM comment from George Penokie (Editorial)

Page 26 - section 6.2.6.7 - The following sentence would be clearer if made into 2 sentences as shown. Original sentence: 'If the process has both initiator and target capabilities, the RETRY bit shall apply to both and SRR may be both transmitted by and accepted by the process.' New sentences: If the process has both initiator and target capabilities, the RETRY bit shall apply to both. In addition SRR may be both transmitted by and accepted by the process.

Response:

Accepted.

Installation:

Installed as requested.

4.213: IBM comment from George Penokie (Editorial)

Page 26 - sections 6.2.6.8 to 6.2.6.11 - Here we are again back to the 'page' name. I assume this is the 'FCP service parameter page, PRLI request' but it is not clear if that is the case or not

Response:

Accepted.

Installation:

Installed as requested.

4.214: IBM comment from George Penokie (Editorial)

Page 26 - section 6.2.6.8 - It is not clear what the 'its' in the statement '...is indicating that its initiator function...' is referring to.

Response:

Accepted.

Installation:

Rewritten to clarify the referent.

4.215: IBM comment from George Penokie (Editorial)

Page 26 - section 6.2.6.7 - It is not clear what the 'it' in the statement '...is indicating that it supports as an initiator function...' is referring to.

Response:

Accepted.

Installation:

Rewritten to clarify the referent.

4.216: IBM comment from George Penokie (Editorial)

Page 26 - section 6.2.6.9 - It is not clear what the 'its' in the statement '...is indicating that its initiator function...' is referring to.

Response:

Accepted.

Installation:

Rewritten to clarify the referent.

4.217: IBM comment from George Penokie (Editorial)

Page 26 - section 6.2.6.8 - last sentence - The term 'confirmed completion allowed' is in small caps when it is not being used as the name of a bit. The term should be in normal text not caps in this case.

Response:

Accepted.

Installation:

Rewritten to clarify reference to bit.

4.218: IBM comment from George Penokie (Editorial)

Page 26 - section 6.2.6.8 - The term 'bit' is used in several cases with no name associated with the bit. The should be fixed in all cases. Bit should never stand alone as it may become unclear as to which bit is being referred to.

Response:

Accepted.

Installation:

Corrected in all locations identified.

4.219: IBM comment from George Penokie (Editorial)

Page 26 - section 6.2.6.9 - The term 'bit' is used in several cases with no name associated with the bit. The should be fixed in all cases. Bit should never stand alone as it may become unclear as to which bit is being referred to.

Response:

Accepted.

Installation:

Corrected throughout clause 6

4.220: IBM comment from George Penokie (Editorial)

Page 26 - section 6.2.6.9 - last paragraph - The term 'data overlay allowed' is in small caps when it is not being used as the name of a bit. The term should be in normal text not caps in this case..

Response:

Accepted.

Installation:

The wording was modified to reference the bit.

4.221: IBM comment from George Penokie (Editorial)

Page 26 - section 6.2.6.10 and 6.2.6.11 - It is not clear what the 'it' in the statement '...is indicating that it operates as a SCSI ...' is referring to.

Response:

Accepted.

Installation:

Installed as requested.

4.222: IBM comment from George Penokie (Editorial)

Page 26 - section 6.2.6.10 - last sentence - The term 'initiator function ' is in small caps when it is not being used as the name of a bit. The term should be in normal text not caps in this case.

Response:

Accepted.

Installation:

Installed as requested.

4.223: IBM comment from George Penokie (Editorial)

Page 26 - section 6.2.6.11 - 3rd sentence - The term 'target function ' is in small caps when it is not being used as the name of a bit. The term should be in normal text not caps in this case.

Response:

Accepted.

Installation:

Installed as requested.

PDF Page 43

4.224: IBM comment from George Penokie (Editorial)

Page 27 - section 6.2.6.11 - The statement 'Both bits 4 and 5 may be set.' should be changed to 'Both the initiator function bit and the target function bit may be set.' This makes it clear which bits are being talked about.

Response:

Accepted.

Installation:

Installed as requested.

4.225: IBM comment from George Penokie (Editorial)

Page 27 - section 6.2.6.11 - The statement 'If neither bit is set...' should be 'If neither the target function bit or the initiator function bit is set...'.

Response:

Accepted.

Installation:

Installed as requested.

4.226: IBM comment from George Penokie (Editorial)

Page 27 - section 6.2.6.11 - The statement; '...with a PRLI ACCEPT RESPONSE CODE of 1000b (Invalid service parameters for page) indication.' should be changed to 'with a PRLI accept reason code of INVALID SERVICE PARAMETERS OF PAGE indication.

Response:

Accepted.

Installation:

Installed as requested.

4.227: IBM comment from George Penokie (Editorial)

Page 27 - section 6.2.6.12 - This bit is marked as obsolete so what is it doing being defined. This section should be removed.

Response:

Accepted in principle.

Installation:

Installed as agreed upon.

4.228: IBM comment from George Penokie (Editorial)

Page 27 - section 6.2.6.13 - The statement '..may be not used before the first FCP_DATA IU...' mean. I believe it should be '... may not be used before the first FCP_DATA IU...' or '... shall not be used before the first FCP_DATA IU...'

Response:

Accepted.

Installation:

Installed as requested.

4.229: IBM comment from George Penokie (Editorial)

Page 27 - sections 6.2.6.13 The term 'Operation' should not be capitalized.

Response:

Accepted.

Installation:

Process_Associators are removed from FCP-2.

4.230: IBM comment from George Penokie (Editorial)

Page 27 - section 6.2.6.13 The statement 'after the first one' is redundant and should be removed.

Response:

Accepted.

Installation:

Installed as requested.

4.231: IBM comment from George Penokie (Editorial)

Page 27 - section 6.2.6.13 - In the following statement the term SCSI write is used, but this seems to be the only place a read or write is noted as being a SCSI write or read. The SCSI should be removed here or added in everywhere else. '...then all FCP I/O Operations performing SCSI writes between the FCP_Ports shall operate without using the FCP_XFER_RDY IU before the first FCP_DATA IU.'

Response:

Accepted.

Installation:

SCSI write is the preferred term and will be used where identified.

PDF Page 44

4.232: IBM comment from George Penokie (Editorial)

Page 28 - section 6.2.7.1 - The statement; 'IMAGE PAIR ESTABLISHED is valid only if bit 13 was set to 1...' should be 'IMAGE PAIR ESTABLISHED bit shall only be valid if the IMAGE PAIR ESTABLISHED bit was set to 1...'

Response:

Accepted.

Installation:

This was changed to a reference to the definition in FC-FS.

4.233: IBM comment from George Penokie (Editorial)

Page 28 - section 6.2.7.1 - The statement 'If this bit...' should be 'If the IMAGE PAIR ESTABLISHED bit...'.

Response:

Accepted.

Installation:

Installed as requested.

4.234: IBM comment from George Penokie (Editorial)

Page 28 - section 6.2.7.1 - The statement 'If set to...' should be 'If the IMAGE PAIR ESTABLISHED bit is set to...'.

Response:

Accepted.

Installation:

Installed as requested.

PDF Page 45

4.235: IBM comment from George Penokie (Editorial)

Page 29 - section 6.2.7.2 - The statement 'This 4-bit value is defined....' should be 'The PRLI ACCEPT RESPONSE CODE field is defined...'.

Response:

Accepted.

Installation:

Installed as requested.

4.236: IBM comment from George Penokie (Editorial)

Page 29 - section 6.3 - The statement 'Only the specified image pairs are logged out...' should be 'Only the image pairs specified in the ??? are logged out...'.

Response:

Accepted.

Installation:

The offending sentence was removed when Process_Associators were removed.

4.237: IBM comment from George Penokie (Editorial)

Page 29 - section 6.3 - To add to the list of unknown pages this section now references a PRLO page. The same questions apply; What's in it, and where is it defined,

Response:

Accepted.

Installation:

Installed as requested.

4.238: IBM comment from George Penokie (Editorial)

Page 29 - section 6.3 - The term process associator should not be capitalized.

Response:

Accepted. This is routinely, but inconsistently, violated in FC-FS. This will be added to the document T10/00-230r1.

Installation:

Installed as agreed.

4.239: IBM comment from George Penokie (Editorial)

Page 29 - section 6.3 - The acronym PA as suddenly appeared and it is not defined anywhere. I assume it stands for process associator but it could be anything. I recommend PA be replaced with process associator in all cases (assuming that's what it standards for).

Response:

Accepted.

Installation:

Installed as requested.

4.240: IBM comment from George Penokie (Editorial)

Page 29 - section 6.3 - last sentence - The term 'accept response coeds' is in small caps when it is not being used as the name of a field. The term should be in normal text not caps in this case.

Response:

Accepted.

Installation:

Installed as requested.

PDF Page 46

4.241: IBM comment from George Penokie (Editorial)

Page 30 - section 7 - The term 'NCTIS project 1356-D, FC-GS-3' need only state 'FC-GS-3'.

Response:

Accepted.

Installation:

Installed as accepted.

4.242: IBM comment from George Penokie (Editorial)

Page 30 - section 7 - The information between section 7 and 7.1 is hanging.

Response:

Accepted.

Installation:

Installed as requested.

4.243: IBM comment from George Penokie (Editorial)

Page 30 - section 7.1 - tables 13 and 14 - The text in the cells needs space between the cell lines and the text.

Response:

Accepted.

Installation:

Rewritten by response to 8.52.

4.244: IBM comment from George Penokie (Editorial)

Page 30 - section 7.1 - Why is the term 'TYPE' in all caps. I believe it should not have any caps.

Response:

Accepted in principle. This will be verified against FC-FS.

This resolution was accepted in the June 7, 2000 working group meeting.

Installation:

The word is “TYPE” in FC-FS. Rewritten by response to 8.52.

4.245: IBM comment from George Penokie (Editorial)

Page 30 - section 7.1 - The following sentence is not clear and does not contain a proper table reference: 'The returned information contains a list header and a list of 4-byte values, described in FC-GS-3 as in the following table.' Something like this would be better: 'The returned information contains a list header and a list of 4-byte values as shown in table 13.'

Response:

Accepted.

Installation:

Rewritten by response to 8.52.

4.246: IBM comment from George Penokie (Editorial)

Page 30 - section 7.1 - table 13 - The title of the first column is 'item' but the text above the table seems to indicate that column should be titled 'list header'. If that is not the case then some other change must be made.

Response:

Accepted.

Installation:

Rewritten by response to 8.52.

4.247: IBM comment from George Penokie (Editorial)

Page 30 - section 7.1 - table 13 - I assume that the '...' means there can be any number of these 4 byte entries but it would be cleared if the '...' was vertical rather than horizontal.

Response:

Accepted.

Installation:

Rewritten by response to 8.52.

4.248: IBM comment from George Penokie (Editorial)

Page 30 - section 7.1 - The statement '...as in the following table' should be '...as shown in table 14.'

Response:

Accepted.

Installation:

Rewritten by response to 8.52.

4.249: IBM comment from George Penokie (Editorial)

Page 30 - section 7.1 - table 14 - The first column should be hex values (e.g., 0h, 1h, 2h, 3h) or binary values (e.g., 0001b, 0010b, 0011b).

Response:

Accepted.

Installation:

Rewritten by response to 8.52.

4.250: IBM comment from George Penokie (Editorial)

Page 30 - section 7.1 - table 13 -The 'rrr' is not defined. What does it stand for?

Response:

Accepted.

Installation:

Rewritten by response to 8.52.

4.251: IBM comment from George Penokie (Editorial)

Page 30 - section 7 - The term 'Name Server' should not be capitalized.

Response:

Accepted in principle. This will be verified against the appropriate documents and corrections requested.

Installation:

For consistency with FC-GS-3, the word “Name Server” must be capitalized.

4.252: IBM comment from George Penokie (Editorial)

Page 30 - section 7.2 - The term 'NCTIS project 1356-D, FC-GS-3' need only state 'FC-GS-3'.

Response:

Accepted.

Installation:

Rewritten by response to 8.52.

4.253: IBM comment from George Penokie (Editorial)

Page 30 - section 7.2 - The term 'NCTIS project 1236-D, SPC-2' need only state 'SPC-2'.

Response:

Accepted.

Installation:

Rewritten by response to 8.52.

4.254: IBM comment from George Penokie (Editorial)

Page 30 - section 7.2 - The NCITS Project 1356-D should state the FC-xx-n standard.

Response:

Accepted.

Installation:

Rewritten by response to 8.52.

4.255: IBM comment from George Penokie (Editorial)

Page 30 - section 7.2 and others - Why is the term 'TYPE' in all caps. I believe it should not have any caps

Response:

Accepted in principle. This will be verified for consistency with FC-FS and corrected accordingly.

Installation:

TYPE is presented as all caps in FC-FS. No change will be made.

4.256: IBM comment from George Penokie (Editorial)

Page 30 - section 7.2 - Why is the term 'TYPE' in all caps. I believe it should not have any caps

Response:

Accepted in principle. This will be verified for consistency with FC-FS and corrected accordingly.

Installation:

TYPE is presented as all caps in FC-FS. No change will be made.

4.257: IBM comment from George Penokie (Editorial)

Page 30 - section 7.2 - The statement '(08h as specified by FC-FS)' should be '(as specified by FC-FS)'.

Response:

Accepted.

Installation:

Rewritten by response to 8.52.

4.258: IBM comment from George Penokie (Editorial)

Page 30 - section 7.2 - The term 'Inquiry' should not be capitalized.

Response:

Accepted.

Installation:

According to SPC-2, the term should be all caps. The document was changed accordingly.

4.259: IBM comment from George Penokie (Editorial)

Page 30 - section 7.2 - The terms 'Register and Query' should not be capitalized.

Response:

Accepted.

Installation:

Rewritten by response to 8.52.

PDF Page 47

4.260: IBM comment from George Penokie (Editorial)

Page 31 - section 8 - The term 'TYPE' should be in small caps as it is the name of a field.

Response:

Accepted in principle. This will be verified for consistency with FC-FS.

Installation:

FC-FS uses all full caps for this field, in much the same way that it does for OX_ID and other header fields. This convention will be used by FCP-2. This required correction in 5.6.2, 6.3.5, 6.3.6, and 7.2

4.261: IBM comment from George Penokie (Editorial)

Page 31 - section 8 - The text and table between section 8 and 8.1 is hanging.

Response:

Accepted.

Installation:

Installed as requested.

4.262: IBM comment from George Penokie (Editorial)

Page 31 - sections 8, 8.1, etc. - The terms 'Link Services, Sequences, Information Category, Unable, Relative Offset, Target, Exchange, Payload, Recipient, Vendor Specific' to name a few should not be capitalized.

Response:

Accepted. This will be added to the document T10/00-230r4.

Installation:

These were all verified for consistency with FC-FS or SAM-2 and made consistent. Most are capitalized, including Link Services, Sequence, Information Category, Relative Offset, Exchange, and Payload.

4.263: IBM comment from George Penokie (Editorial)

Page 31 - section - 8 - The statement 'The FCP-2 ELS functions in table 15 are defined in this standard.' would be clearer if it was stated as 'The FCP-2 ELS functions defined by this standard are shown in table 15.'

Response:

Accepted.

Installation:

Installed as requested.

4.264: IBM comment from George Penokie (Editorial)

Page 31 - section 8 - table 15 - There is no reference to where the FCP FC-4 LS Accept and Reject are defined. This should be added into the table.

Response:

Accepted.

Installation:

Installed as requested.

4.265: IBM comment from George Penokie (Editorial)

Page xx - section xx - The usage of the term FCP and FCP-2 seems to be random throughout the standard. This need to be fixed by consistently using one or the other.

Response:

Accepted.

Installation:

The usage of FCP and FCP-2 was reviewed. All cases where the reference was to the protocol independent of whether it was an FCP or FCP-2 function are now defined with FCP. All cases that are unique to FCP-2 behaviors use FCP-2.

4.266: IBM comment from George Penokie (Editorial)

Page 31 - section 8.1 - There is not need to restate the definition of the acronyms. One time is good enough.

Response:

Accepted.

Installation:

Corrected where identified.

4.267: IBM comment from George Penokie (Editorial)

Page 31 - section 8.1 - The statement '...with a reason code hex '09' (i.e. Unable to perform the command request).' should be changed to '...with a reason code of UNABLE TO PERFORM THE COMMAND REQUEST.'

Response:

Accepted.

Installation:

Changed as requested, except that FC-FS typically uses single quotes and I have chosen double quotes.

4.268: IBM comment from George Penokie (Editorial)

Page 31 - section 8.1 - The statement '...with a reason code 00092A00h (i.e. Unable to perform the command request / Unable to supply requested data).' with '...with a reason code of UNABLE TO PERFORM THE COMMAND REQUEST/UNABLE TO SUPPLY REQUESTED DATA.'

Response:

Accepted.

Installation:

Installed with slightly different convention.

4.269: IBM comment from George Penokie (Editorial)

Page 31 - section 8.1 - There is a jump into areas labeled 'Protocol, format, addressing, etc. what no explanation to the read as to what is being talked about. It would be helpful if there were a few words talking about this.

Response:

This is the standard format for describing ELSs in FC-FS. Within the context of that document, this is all clear. This will be explained.

Installation:

This format was actually defined in the introductory material (new 8.1) and can be taken out of the definitions of the link services.

The protocol is clearly described in the introductory paragraphs for each link service and need not be repeated.

4.270: IBM comment from George Penokie (Editorial)

Page 31 - section 8.1 - What is FT_1 supposed to be.

Response:

This is the standard format for describing ELSs in FC-FS. Within the context of that document, this is all clear. This will be explained.

Installation:

See 4.269.

4.271: IBM comment from George Penokie (Editorial)

Page 31 - section 8.1 - The statement '...present a check condition as if it had responded to an Initiator Detected Error with a Restore Pointers message (i.e., Sense Key = 4h, ASC/ASQ = 48h/00h).' should be 'return CHECK CONDITION status with the sense key set to HARDWARE ERROR and an additional sense code of INITIATOR DETECTED ERROR MESSAGE RECEIVED.'

Response:

Accepted.

Installation:

Installed as requested.

PDF Page 48

4.272: IBM comment from George Penokie (Editorial)

Page 32 - section 8.1 - The following statement '...Payload is shown in the following table.' should be '...payload is shown in table 16.

Response:

Accepted.

Installation:

Installed as requested.

4.273: IBM comment from George Penokie (Editorial)

Page 32 - section 8.1 - There is a cross-reference to a section in another standard. The reference [should be deleted?]

Response:

Accepted.

This resolution was accepted in the June 7, 2000 working group meeting.

Installation:

Installed as requested.

4.274: IBM comment from George Penokie (Editorial)

Page 32 - section 8.1 - The statement 'Tables 28, 29; i.e., 05 = Data Descriptor (FCP_XFER_RDY), 07 = Command Status (FCP_RSP), 01 = Solicited Data (FCP_DATA).' should be changed to '... FC-PH (i.e., data descriptor (FCP_XFER_RDY), command status (FCP_RSP), solicited data (FCP_DATA)).'

Response:

Accepted in principle.

Installation:

Installed as requested.

4.275: IBM comment from George Penokie (Editorial)

Page 32 - section 8.1 - The term 'meaningful' should be 'valid'.

Response:

Accepted.

Installation:

Installed as requested.

4.276: IBM comment from George Penokie (Editorial)

Page 32 - section 8.1 - The statement '...set to 01 for...' to ...set to 01h for...'

Response:

Accepted.

Installation:

Installed as requested.

4.277: IBM comment from George Penokie (Editorial)

Page 32 - section 8.1 - The statement '...or to 05 for...' to '...or to 05h for...'

Response:

Accepted.

Installation:

Installed as requested.

4.278: IBM comment from George Penokie (Editorial)

Page 32 - section 8.1 - table 17 - The notation 'hex '02000000' 'needs to be changed to '02000000h'

Response:

Accepted.

Installation:

Installed as requested.

4.279: IBM comment from George Penokie (Editorial)

Page 32 - section 8.1 -table 17 - I can find no reference to this table. All table must have at least one reference to them.

Response:

Accepted.

Installation:

Installed as requested.

4.280: IBM comment from George Penokie (Editorial)

Page 32 - section 8.1 - table 16 - The column numbers under size should be centered.

Response:

Accepted.

Installation:

Installed as requested.

PDF Page 49

4.281: IBM comment from George Penokie (Editorial)

Page 33 - section 8.1 - The following statement '...code is defined below.' should be changed to '...code is defined in table 18.'

Response:

Accepted.

Installation:

Installed as requested.

4.282: IBM comment from George Penokie (Editorial)

Page 33 - section 8.1 - table 18 - The reason code name should be in all caps and the ',' should be replaced with a '/' to make it consistent with the usage above.

Response:

Accepted.

Installation:

Rewritten, separating out the codes for all the FCP FC-4 LS Rejects.

4.283: IBM comment from George Penokie (Editorial)

Page 33 - section 8.2 - The term 'terminate' should be change to 'end'.

Response:

Accepted.

Installation:

Installed as requested, but moved because of rewrite.

4.284: IBM comment from George Penokie (Editorial)

Page 33 - section 8.2 - The statement '(Bit 20)' should be removed.

Response:

Accepted.

Installation:

Deleted as part of the rewrite. Other similar problems were corrected.

4.285: IBM comment from George Penokie (Editorial)

Page 33 - section 8.2 - The statement '...is unique to the link...' should be changed to '...is defined by the link..' or something like that.

Response:

Accepted.

Installation:

Deleted as part of the rewrite.

4.286: IBM comment from George Penokie (Editorial)

Page 33 - section 8.2 - There is a jump into areas labeled 'Protocol, format, addressing, etc. what no explanation to the read as to what is being talked about. In would be helpful if there were a few words talking about this.

Response:

This is the standard format for describing ELSs in FC-FS. Within the context of that document, this is all clear. This will be explained.

Installation:

See 4.269.

4.287: IBM comment from George Penokie (Editorial)

Page 33 - section 8.2 - What is FT_1 supposed to be.

Response:

This is the standard format for describing ELSs in FC-FS. Within the context of that document, this is all clear. This will be explained.

Installation:

See 4.269.

4.288: IBM comment from George Penokie (Editorial)

Page 33 - section 8.2 - The statement '...accepted while the S_ID...' should be changed to '...accepted. The S_ID...'

Response:

Accepted.

Installation:

Deleted as part of rewrite.

4.289: IBM comment from George Penokie (Editorial)

Page 33 - section 8.2 - payload - There should be a cross-reference to where the link service requests are defined.

Response:

Accepted.

Installation:

Deleted as part of rewrite.

4.290: IBM comment from George Penokie (Editorial)

Page 33 - section 8.3 - There is a jump into areas labeled 'Protocol, format, addressing, etc. what no explanation to the read as to what is being talked about. In would be helpful if there were a few words talking about this.

Response:

This is the standard format for describing ELSs in FC-FS. Within the context of that document, this is all clear. This will be explained.

Installation:

See 4.269.

4.291: IBM comment from George Penokie (Editorial)

Page 33 - section 8.2 - What is FT_1 supposed to be.

Response:

This is the standard format for describing ELSs in FC-FS. Within the context of that document, this is all clear. This will be explained.

Installation:

See 4.269.

4.292: IBM comment from George Penokie (Editorial)

Page 33 - section 8.3 - There should be a cross-reference to where the reason codes are defined.

Response:

Accepted.

Installation:

Installed as requested.

4.293: IBM comment from George Penokie

Page 33 - section 8.3 - The sentence 'FCP FC-4 Link Service Reject may be transmitted for a variety of conditions.' has no useful information and should be deleted.

Response:

Accepted in principle.

Installation:

Installed as requested.

4.294: IBM comment from George Penokie (Editorial)

Page 33 - section 8.3 - The statement '...rejected while the S_ID...' should be changed to '...rejected. The S_ID...'

Response:

Accepted.

Installation:

Installed as requested.

4.295: IBM comment from George Penokie (Editorial)

Page 33 - section 8.3 - payload - The statement '...shall indicate the reason for rejecting the request.' should be '...shall contain a reason code (see table 20) for rejecting the request.'

Response:

Accepted.

Installation:

Installed with minor editorial changes.

PDF Page 50

4.296: IBM comment from George Penokie (Editorial)

Page 34 - section 8.3 - table 19 - There is no cross-reference to this table.

Response:

Accepted.

Installation:

Installed as requested.

4.297: IBM comment from George Penokie (Editorial)

Page 34 - section 8.3 - table 20 - The text in the cells is too close to the top row lines. There needs to be space added there.

Response:

Accepted.

Installation:

Installed as requested.

4.298: IBM comment from George Penokie (Editorial)

Page 34 - section 8.3 - table 20 - All the reason codes should be all caps.

Response:

Accepted.

Installation:

This is in conflict with the conventions of FC-FS. I have elected to use lower case with quotation marks as delimiters, which is one of the FC-FS conventions. This is still being worked out with James Nelson.

4.299: IBM comment from George Penokie (Editorial)

Page 34 - section 8.3 - Why are there no section numbers on what appear to be sections (i.e. FCP_RJT Reason Code Descriptions, and FCP_RJT Reason explanation?

Response:

These would then become objectionable hanging paragraphs. This is compatible with the FC-FS formats.

Installation:

No change was made.

4.300: IBM comment from George Penokie (Editorial)

Page 34 - section 8.3 - All the response code should be all caps.

Response:

This needs to be resolved among the editors. I have always found the all-caps format objectionable. It is not the format selected by FC-FS, which prefers all lower case, with the first letter capitalized. All related comments should have the same treatment.

After considerable discussion in the June 7, 2000 working group meeting, it was decided to use all caps for response codes.

Installation:

This is still being worked out among the editors. The latest resolution (mid October) is that the names of codes will be in lower case and enclosed in quotes.

4.301: IBM comment from George Penokie (Editorial)

Page 34 - section 8.3 - Where are the 'rules of the extended link service protocol' specified? There should be a cross-reference to that place.

Response:

Accepted.

Installation:

This is actually any protocol error, and was corrected.

PDF Page 51

4.302: IBM comment from George Penokie (Editorial)

Page 35 - section 8.3 - table 21 -The text in the cells is too close to the top row lines. There needs to be space added there

Response:

Accepted.

Installation:

Installed as requested.

4.303: IBM comment from George Penokie (Editorial)

Page 35 - section 8.3 - table 21 -There are two blank row that should be removed.

Response:

Accepted.

Installation:

Installed as requested.

PDF Page 52

4.304: IBM comment from George Penokie (Editorial)

Page 36 - section 9 - The text between section 9 and 9.1 is hanging.

Response:

Accepted.

Installation:

Installed as requested.

4.305: IBM comment from George Penokie (Editorial)

Page 36 - section 9.1 - The information between section 9.1 and 9.1.1 is hanging.

Response:

Accepted.

Installation:

Installed as requested.

4.306: IBM comment from George Penokie (Editorial)

Page 36 - section 9.1 - The statement '...carries either a SCSI Command to be executed or a task management request to be performed.' would be clearer if it was stated as '...contains either a SCSI Command or a task management request.'

Response:

Accepted.

Installation:

Installed as requested.

4.307: IBM comment from George Penokie (Editorial)

Page 36 -41 - sections 9.1.1.x - These section titles should be removed. I suggest making them into run in headers (like the definitions list) which would keep the identity of the sections and get rid of the hung information.

Response:

Accepted.

Installation:

After further review, there is another layer of run in headers at a lower level. The section levels were retained, but the hanging information was corrected.

4.308: IBM comment from George Penokie (Editorial)

Pages 36 -41 - sections 9.1.1.x - All the descriptions should start out with a statement like: 'The XXXX field contains the xxx is...' For example FCP_LUN would be 'The RCP_LUN field contains the address of the logical unit where the FCP_CMND payload is sent.' Note that this sentence should replace the sentence; ' The FCP logical unit number (FCP_LUN) is the address of the desired logical unit in the attached subsystem.'

Response:

Accepted.

Installation:

Required significant rewrite of the chapter.

4.309: IBM comment from George Penokie (Editorial)

Page 36 - section 9.1.1.1 - The statement '(0000 0000 0000 0000 hexadecimal).' should be removed.

Response:

Accepted.

Installation:

Installed as requested.

4.310: IBM comment from George Penokie (Editorial)

Page 36 - section 9.1.1.1 - The term 'SCSI INQUIRY' should be just 'inquiry'.

Response:

Accepted.

Installation:

Installed as requested. "Information" was changed to "data".

4.311: IBM comment from George Penokie (Editorial)

Page 36 - section 9.1.1.1 - The statement '...can determine the SCSI device type, manufacturer, model of the logical unit, and addressing structure.' should be replaced with '...can, for example, determine the SCSI device type, manufacturer, model of the logical unit, and addressing structure.' The list is not a complete list therefore the 'for example' needs to be added.

Response:

Accepted.

Installation:

Installed as requested.

4.312: IBM comment from George Penokie (Editorial)

Page 36 - section 9.1.1.1 - The statement 'as recommended by SPC-2' carries no additional value and should be removed.

Response:

Accepted.

Installation:

Changed to a reference to SPC-2.

4.313: IBM comment from George Penokie (Editorial)

Page 37 - section 9.1.1.1 - The sentences 'If the FCP_LUN address locates a valid logical unit, the command shall be executed according to standard SCSI behavior. Behavior may include successful execution of the command, presentation of errors associated with the command, or rejection of the command.' Should be condensed to 'If the FCP_LUN address contains a valid logical unit the command shall be routed to the addressed logical unit.' There is no reason to tell the reader how SCSI commands work we have entire standards that do that.

Response:

Accepted in principle.

Installation:

Installed as requested.

4.314: IBM comment from George Penokie (Editorial)

Page 37 - section 9.1.1.1 - The statement '...the responses shall report that...' does not make sense. It should be '... device server shall report that...'

Response:

Accepted.

Installation:

Actually, this is a target function.

4.315: IBM comment from George Penokie (Editorial)

Page 37 - section 9.1.1.1 - The statement '... is provided by the...' should be '...is sent by the...'

Response:

Accepted.

Installation:

Installed as requested.

4.316: IBM comment from George Penokie (Editorial)

Page 37 - section 9.1.1.2 - I believe the following statement is incorrect '...enabled, a zero value of CRN shall be ignored and that command...'. It is not zero value that is ignored but the CRN. To fix this changed the statement to '...enabled, a zero value of CRN indicates the COMMAND REFERENCE NUMBER field shall be ignored and that command

Response:

Accepted.

Installation:

Replaced the offending section with “ enabled, a zero value in the CRN field indicates that command shall not be verified for precise delivery.”

4.317: IBM comment from George Penokie (Editorial)

Page 37 - section 9.1.1.2 - The statement '...the value of CRN shall be ignored...' should be 'the COMMAND REFERENCE NUMBER field shall be ignored...'

Response:

Accepted.

Installation:

Installed as requested.

4.318: IBM comment from George Penokie (Editorial)

Page 37 section 9.1.1.2 - The statement 'special care must be exercised to guarantee successful ordering.' needs to be removed as it is editorial comment.

Response:

Accepted in principle.

Installation:

Ordering is moved to section 4.3, deleting this entirely.

4.319: IBM comment from George Penokie (Editorial)

Page 37 - section 9.1.1.2 - The following sentences 'With a class 2 fabric, special care must be exercised to guarantee successful ordering. Sequential delivery must be requested at login to ensure correct ordering among tasks.' should be changed to 'With a class 2 fabric sequential delivery shall be requested at login to ensure correct ordering among tasks.'

Response:

Other comments have provided alternative structures for this paragraph that are superior.

Installation:

Ordering is moved to section 4.3, deleting this entirely.

4.320: IBM comment from George Penokie (Editorial)

Page 37 section 9.1.1.2 - All the musts must be changed to shalls.

Response:

Accepted in principle. Some may be may.

Installation:

Installed as requested.

4.321: IBM comment from George Penokie (Editorial)

Page 37 - section 9.1.1.2 - All the task attribute descriptions should reference SAM-2.

Response:

Accepted.

Installation:

Installed as requested.

4.322: IBM comment from George Penokie (Technical)

(T) Page 37 - section 9.1.1.2 - The untagged task option should be make obsolete in FCP-2 as it serves no useful purpose.

Response:

This proposal is rejected. SAM-2 unambiguously requires a protocol to support both tagged and untagged tasks. Tape functionality is almost exclusively implemented with untagged tasks. Boot functionality is almost exclusively implemented with untagged tasks. While the use of that attribute may not create a meaningful difference in the behavior of the devices, the attribute will absolutely be used by present day drivers and must be supported. This response was accepted in the April 5, 2000 meeting.

Installation:

No change was made as a result of this comment.

PDF Page 54

4.323: IBM comment from George Penokie (Editorial)

Page 38 - section 9.1.1.4 - The statement '...the FCP_CDB, FCP_DL, TASK ATTRIBUTES, RDDATA, and WRDATA fields and bits are not valid and are ignored.' should be changed to

'...the FCP_CDB field, FCP_DL field, TASK ATTRIBUTE field, RDDATA bit, and WRDATA bit shall be ignored.

Response:

Accepted.

Installation:

Installed as requested.

4.324: IBM comment from George Penokie (Editorial)

Page 38 - section 9.1.1.4 - So what does the target do if more than one task management flag is set? This should be defined.

Response:

Accepted.

Installation:

The proper response code was defined in 9.1.1.

4.325: IBM comment from George Penokie (Editorial)

Page 38 - section 9.1.1.4 - table 24 - The first column should be centered..

Response:

Accepted.

Installation:

Installed as requested.

4.326: IBM comment from George Penokie (Editorial)

Pages 38 -39 - section 9.1.1.4 - All the descriptions of the bits should start out as 'The xxx bit...'. For example; The CLEAR ACA bit...'

Response:

Accepted.

Installation:

Installed as requested.

4.327: IBM comment from George Penokie (Editorial)

Page 38 - section 9.1.1.4 - The term 'states' in the target reset should be 'conditions'.

Response:

Accepted.

Installation:

After review of this comment, I believe “states” is still the correct word.

4.328: IBM comment from George Penokie (Editorial)

Page 38 -39 - section 9.1.1.4 - The statements 'The initiator and target clear all resources that can be cleared unambiguously. Any open exchanges that are in an ambiguous state as defined in the next paragraph shall be terminated using a recovery abort by whichever port detects the ambiguous state. The ports may issue additional recovery abort operations if they are unable to determine in a simple manner whether the state of an FCP I/O operation is ambiguous.' Is very unclear and does not give the read enough guidance as to what resources can be cleared unambiguously or what is a simple manner and what is not.

Response:

Accepted in principle. See related comments.

Installation:

This section was clarified.

4.329: IBM comment from George Penokie (Editorial)

Page 38 - 40 - Section 9.1.1.4 - Some of the target reset, LU reset, clear task set, and abort task set information is defined here and in table 4. It should only be defined in one place and a reference placed in the other. It is not clear which place is better in this case.

Response:

Accepted.

The offending text was replaced with a reference to the proper section containing tables 4 and 5.

PDF Page 55

4.330: IBM comment from George Penokie (Editorial)

Page 39 - section 9.1.1.4 - The note contains a requirement therefore it cannot be a note. Either the note must make part of the text or the requirement removed.

Response:

Accepted.

Installation:

The requirement is changed to a recommendation.

4.331: IBM comment from George Penokie (Editorial)

Page 39 - section 9.1.1.4 - The 1,2,3 list should be an a,b,c list.

Response:

Accepted.

Installation:

The list was removed by references to 4.9.

4.332: IBM comment from George Penokie (Editorial)

Page 39 - section 9.1.1.4 - item 4 - The statement '...similar to those conditions...' means what exactly? How similar do I have to be? Either the conditions are the same as those of power on or they are not. If they are not then how are they different? These questions need to be answered and wording put in so they do not have to be asked.

Response:

Accepted.

Installation:

This was removed by references to the clearing actions tables.

4.333: IBM comment from George Penokie (Editorial)

Page 39 - section 9.1.1.4 - How is the 1,2,3 list different than what is described in SAM-2. The only things that should be described are those that are not already described in SAM-2 anything else should be removed.

Response:

Accepted.

Installation:

This was removed by references to the clearing actions tables.

4.334: IBM comment from George Penokie (Editorial)

Page 39 - section 9.1.1.4 - The statements 'The initiator and target clear all resources that can be cleared unambiguously. Any open exchanges that are in an ambiguous state as defined in the

next paragraph shall be terminated using a recovery abort by whichever port detects the ambiguous state. The ports may issue additional recovery abort operations if they are unable to determine in a simple manner whether the state of an FCP I/O operation is ambiguous.' Is very unclear and does not give the read enough guidance as to what resources can be cleared unambiguously or what is a simple manner and what is not.

Response:

Accepted in principle. See 6.68.

Installation:

The text was clarified.

4.335: IBM comment from George Penokie (Editorial)

Page 39 - section 9.1.1.4 - The note contains a requirement therefore it cannot be a note. Either the note must make part of the text or the requirement removed.

Response:

Accepted.

Installation:

The requirement was changed to a recommendation.

4.336: IBM comment from George Penokie (Editorial)

Page 39 - section 9.1.1.4 - In the logical unit reset descriptions paragraph before the note TARGET RESET is used where it should be LOGICAL UNIT RESET.

Response:

Accepted.

Installation:

Installed as requested.

4.337: IBM comment from George Penokie (Editorial)

Page 39 - section 9.1.1.4 - The statements 'The initiator and target clear all resources that can be cleared unambiguously. Any open exchanges that are in an ambiguous state as defined in the next paragraph shall be terminated using a recovery abort by whichever port detects the ambiguous state. The ports may issue additional recovery abort operations if they are unable to determine in a simple manner whether the state of an FCP I/O operation is ambiguous.' Is very unclear and does not give the read enough guidance as to what resources can be cleared unambiguously or what is a simple manner and what is not.

Response:

Accepted in principle. See 6.68.

Installation:

The text was clarified.

PDF Page 56

4.338: IBM comment from George Penokie (Editorial)

Page 40 - section 9.1.1.4 - The note contains a requirement therefore it cannot be a note. Either the note must make part of the text or the requirement removed.

Response:

Accepted.

Installation:

The requirement was changed to a recommendation.

4.339: IBM comment from George Penokie (Editorial)

Page 40 - section 9.1.1.4 - The note contains a requirement therefore it cannot be a note. Either the note must make part of the text or the requirement removed.

Response:

Accepted.

Installation:

The requirement was changed to a recommendation.

4.340: IBM comment from George Penokie (Editorial)

Page 40 - section 9.1.1.4 - The statements 'The initiator and target clear all resources that can be cleared unambiguously. Any open exchanges that are in an ambiguous state as defined in the next paragraph shall be terminated using a recovery abort by whichever port detects the ambiguous state. The ports may issue additional recovery abort operations if they are unable to determine in a simple manner whether the state of an FCP I/O operation is ambiguous.' Is very unclear and does not give the read enough guidance as to what resources can be cleared unambiguously or what is a simple manner and what is not.

Response:

Accepted in principle. See 6.68.

Installation:

The text was clarified.

4.341: IBM comment from George Penokie (Editorial)

Page 40 - section 9.1.1.6 - The statement 'SCSI read-type operation' should be 'SCSI read operation'. I do not recall ever seeing a read-type operation in SCSI.

Response:

Accepted.

Installation:

Installed as requested.

4.342: IBM comment from George Penokie (Editorial)

Page 40 - section 9.1.1.7 - What is the target supposed to do if the FCP_DL is not 0 when both read data and write data bits are set to 0? What is the target supposed to do if both the read data and write data bits are set to 1? These error conditions need to be specified.

Response:

Accepted.

Installation:

The error code is a RS_CODE of FCP_CMD fields invalid. This is documented in 9.1.1.

4.343: IBM comment from George Penokie (Editorial)

Page 40 - section 9.1.1.8 - The statement 'the actual CDB to be interpreted by' should be 'the CDB to be sent to '.

Response:

Accepted.

Installation:

Installed as requested.

4.344: IBM comment from George Penokie (Editorial)

Page 40 - section 9.1.1.8 - The statement '..is not valid and is ignored...' should be just '...shall be ignored...'.

Response:

Accepted.

Installation:

Installed as requested.

4.345: IBM comment from George Penokie (Editorial)

Page 40 - section 9.1.1.8 - The last two paragraphs should be deleted as they contain no information that is not already in SAM-2. They should be replaced with a 'As defined in SPC-2' statement.

Response:

Accepted.

Installation:

Installed as requested. The statements about bytes beyond the CDB and about the Flag bit are retained.

PDF Page 57

4.346: IBM comment from George Penokie (Editorial)

Page 41 - section 9.1.1.9 - The statement 'The contents of the field shall be those bytes of an extended CDB beyond the first 16 bytes of the CDB as defined in the SCSI command standards.' should be replaced with 'The contents of the ADDITIONAL_FCP_CDB field are defined in the SCSI command standards.'

Response:

Accepted.

Installation:

After review, this change was not installed. There is no standard definition of which bytes are “additional” in a CDB. That information is only carried in the protocol documents.

4.347: IBM comment from George Penokie (Editorial)

Page 41 - section 9.1.1.9 - The term 'expected' implies the number of bytes to transfer is uncertain. Removing the term will remove the uncertainty.

Response:

Accepted.

Installation:

Installed as requested. Note that the uncertainty remains.

4.348: IBM comment from George Penokie (Editorial)

Page 41 - section 9.1.1.10 - The statement 'The parameter is...' should be 'The FCP_DL field contains ...'.

Response:

Accepted.

Installation:

Installed as requested.

4.349: IBM comment from George Penokie (Editorial)

Page 41 - section 9.1.2 - This seems like a very odd place to put this information. It appears to be more like model type information that should be placed in the model sections.

Response:

Accepted.

Installation:

It is really error recovery information and was moved to chapter 12.

4.350: IBM comment from George Penokie (Editorial)

Page 41 - section 9.1.2.1 - The information in this section seems disjointed and I am not sure what point is trying to be made. Something needs to be added to make it clearer what is being described.

Response:

Accepted.

Installation:

The section was clarified and re-organized.

4.351: IBM comment from George Penokie (Editorial)

Page 41 - section 9.1.2.2 - The sentence 'The following protocol has been selected for simplicity, completeness, and robustness.' is an interesting opinion but does not belong in a standard. It should be replaced with 'The following protocol shall be followed during a recovery abort:'

Response:

Accepted.

Installation:

Removed during rewrite in clause 12.

4.352: IBM comment from George Penokie (Editorial)

Page 41 - section 9.1.2.2 - The statement '...ABTS sequence is generated...' should be 'ABTS sequence shall be generated...'.

Response:

Accepted.

Installation:

Installed as requested.

4.353: IBM comment from George Penokie (Editorial)

Page 41 - section 9.1.2.2 - The term 'FFFF h' is used. It should be 'FFFFh'. (i.e., not space between the last F and the h.

Response:

Accepted.

Installation:

Installed as requested.

4.354: IBM comment from George Penokie (Editorial)

Page 41 - section 9.1.2.2 - The statement '...reason code of "logical error/invalid OX_ID/RX_ID combination"...' should be '...reason code of LOGICAL ERROR/INVALID OX_ID/RX_ID COMBINATION.'

Response:

Accepted.

Installation:

Installed as requested, except using FC-FS conventions.

4.355: IBM comment from George Penokie (Editorial)

Page 41 - section 9.1.2.2 - In the statement '...the L_S bit set in the...' it is not clear what the bit is set to. This needs to be corrected.

Response:

Accepted.

Installation:

Installed as requested, but in FCP-2 12.3.3.

4.356: IBM comment from George Penokie (Editorial)

Page 41 - section 9.1.2.2 - The indented paragraphs should be an a,b,c list.

Response:

Accepted.

Installation:

Installed as requested, but in FCP-2 12.3.

4.357: IBM comment from George Penokie (Editorial)

Page 41 - Section 9.1.2.1 - Some of the abort task set information is defined here and in table 4. It should only be defined in one place and a reference placed in the other. It is not clear which place is better in this case.

Response:

Accepted.

Installation:

I believe this is better explained now in clause 12.

PDF Page 58

4.358: IBM comment from George Penokie (Editorial)

Page 42 - section 9.2 - The term 'write type command' should be change to 'write command' in all occurrences.

Response:

Accepted.

Installation:

Installed as requested.

4.359: IBM comment from George Penokie (Editorial)

Page 42 - section 9.2 - What is a SCSI-3 data delivery service? Do you mean a SAM-2 data delivery service?

Response:

Accepted.

Installation:

Installed as requested.

4.360: IBM comment from George Penokie (Editorial)

Page 42 - section 9.2 - The term 'write XFER_RDY disabled' should be in small caps and are cross-reference added in to tell me where it is defined.

Response:

Accepted.

Installation:

Installed as requested.

4.361: IBM comment from George Penokie (Editorial)

Page 42 - section 9.2 - The term 'write XFER_RDY disabled' that is in small caps should be in normal non-cap text.

Response:

Accepted.

Installation:

Installed as requested.

4.362: IBM comment from George Penokie (Editorial)

Page 42 - section 9.2 - The term 'planned' should be deleted.

Response:

Accepted.

Installation:

Planned replaced with established.

4.363: IBM comment from George Penokie (Editorial)

Page 42 - section 9.2 - The statement '...entire FCP_DL bytes of data.' should be changed to '...number of bytes indicated in the FCP_DL field.'

Response:

Accepted.

Installation:

Installed as required, with minor additional editorial corrections.

4.364: IBM comment from George Penokie (Editorial)

Page 42 - section 9.2 - The obsolete function should only be listed in one place in the front of the document. Remove the reference to the obsolete function from this place.

Response:

Accepted.

Installation:

Installed as requested.

4.365: IBM comment from George Penokie (Editorial)

Page 42 - section 9.2 - The information between 9.2 and 9.2.1 is hanging information.

Response:

Accepted.

Installation:

Installed as requested.

4.366: IBM comment from George Penokie (Editorial)

Page 42-43 - sections 9.2.x - These section titles should be removed. I suggest making them into run in headers (like the definitions list) which would keep the identity of the sections and get rid of the hung information.

Response:

Accepted.

Installation:

As corrected, there is no reason to remove them. No change was made.

4.367: IBM comment from George Penokie (Editorial)

Page 42 - section 9.2.1 - There needs to be a cross reference to where the RLTV_OFF field is defined.

Response:

Accepted.

Installation:

The term was replaced by the relative offset contents of the PARAMETER field.

4.368: IBM comment from George Penokie (Editorial)

Page 42 - section 9.2.1 - The term 'disconnect-reconnect mode page' should be 'disconnect-reconnect page'.

Response:

Accepted.

Installation:

Installed as requested.

4.369: IBM comment from George Penokie (Editorial)

Page 42 - section 9.2.1 - The term 'SCSI-3 application client' should be 'SAM-3 application client'.

Response:

Accepted. (SAM-2?)

This resolution was accepted in the June 7, 2000 working group meeting.

Installation:

Installed as requested.

4.370: IBM comment from George Penokie (Editorial)

Page 42 - section 9.2.2 - The term 'exact' should be deleted.

Response:

Accepted.

Installation:

Installed as requested.

4.371: IBM comment from George Penokie (Editorial)

Page 42 - section 9.2.2 - The statement 'SCSI data delivery' should be 'SAM-3 data delivery'.

Response:

Accepted. (SAM-2)

Installation:

Installed as requested.

4.372: IBM comment from George Penokie (Editorial)

Page 42 - section 9.2.2 - The statement 'The value is this field...' should be 'The value in the BURST_LEN field...'.

Response:

Accepted.

Installation:

Installed as requested.

4.373: IBM comment from George Penokie (Editorial)

Page 42 - section 9.2.2 - The statement '...MODE SELECT/MODE SENSE.' should be 'MODE SELECT command and MODE SENSE command'.

Response:
Accepted.
Installation:
Installed as requested.

PDF Page 59

4.374: IBM comment from George Penokie (Editorial)

Page 43 - section 9.3 - The sentence 'The disconnect/reconnect page is examined and set by the MODE SENSE and MODE SELECT commands.' should be deleted as that is stated in other standards.

Response:
Accepted.
Installation:
Installed as requested.

4.375: IBM comment from George Penokie (Editorial)

Page 43 - section 9.3 - The statement '...shall post the error code indicating...' is made but no specific error code is listed. What is 'the' error code?

Response:
Accepted.
Installation:
Installed as requested.

4.376: IBM comment from George Penokie (Editorial)

Page 43 - section 9.3 - The following statement is unclear and I don't know how to fix it but it does need to be fixed. '...and the subsequent FCP_DATA IU has a lowest RLTV_OFF that differs from the DATA_RO of the FCP_XFER_RDY,...'

Response:
Accepted.
Installation:
The change needed was to change "subsequent" to "requested".

4.377: IBM comment from George Penokie (Editorial)

Page 43 - section 9.3 - The term 'exact' in the statement '...payload that indicates the exact location and length of the data delivery.' adds no value to the standard and should be removed.

Response:
Accepted.
Installation:
Installed as requested.

4.378: IBM comment from George Penokie (Editorial)

Page 43 - section 9.3 - The statement '...(an operation that uses the Data In action,...' needs a ')'.
'

Response:
Accepted.
Installation:
Installed as requested.

4.379: IBM comment from George Penokie (Editorial)

Page 43 - section 9.3 - The statement '...FC_RSP IU shall contain the FCP_RESID_UNDER bit.' should be stated as '...FC_RSP IU shall contain an FCP_RESID_UNDER bit set to 1.'

Response:

Accepted.

Installation:

Installed as requested.

4.380: IBM comment from George Penokie (Editorial)

Page 43 - section 9.3 - The term 'always' in the statement '...initiator shall always have available...' add on value and should be deleted.

Response:

Accepted.

Installation:

Installed as requested.

4.381: IBM comment from George Penokie (Editorial)

Page 43 - section 9.3 - The statement '...setting the FCP_RESID_OVER bit in the FC_RSP IU.' should be '...setting the FCP_RESID_OVER bit to 1 in the FC_RSP IU.'

Response:

Accepted.

Installation:

Installed as requested.

4.382: IBM comment from George Penokie (Editorial)

Page 43 - section 9.3 - The statement '...disconnect-reconnect mode page...' should be '...disconnect-reconnect page...'

Response:

Accepted.

Installation:

Installed as requested.

4.383: IBM comment from George Penokie (Editorial)

Page 43 - section 9.3 - A undefined term 'sets of data' has suddenly appeared. What are 'sets of data' supposed to be.

Response:

Accepted.

Installation:

Offending sentence deleted and second offending sentence repaired.

4.384: IBM comment from George Penokie (Editorial)

Page 43 - section 9.3 - The following sentence has to 'not's in it that make it difficult to understand. It should be rewritten. 'The target shall not request that sets of data in the middle of a transfer not be transferred.'

Response:

Accepted.

Installation:

The offending sentence was deleted because it was covered by the previous sentence.

4.385: IBM comment from George Penokie (Editorial)

Page 43 - section 9.3 - The statement 'The manner in which a SCSI Initiator determines that the correct amount of data is returned is outside the scope of this standard.' should be rewritten to 'The method used by the SCSI initiator to determine the correct amount of data is returned is vendor specific.'

Response:

Accepted in principle. FC typically avoids vendor specific.

Installation:

Installed as requested.

4.386: IBM comment from George Penokie (Editorial)

Page 43 - section 9.3 - The sentence 'Data that has been retransmitted and overlaid shall be counted only once.' states 'shall be counted only once' what does this mean? I see no reference to a counter in any other part of this section.

Response:

Accepted in principle. This is part of the overlaid data description problem.

Installation:

The sentence was changed to read "Data that has been retransmitted and overlaid shall be counted only once for the purposes of calculating residual values."

PDF Page 60

4.387: IBM comment from George Penokie (Editorial)

Page 44 - section 9.3 - The following sentence 'The mechanisms vary with which Class of Service is being used and what service parameters are in effect.' should be rewritten to 'The mechanisms vary with the Class of Service being used and the service parameters in effect.'

Response:

Accepted.

Installation:

Installed as requested.

4.388: IBM comment from George Penokie (Editorial)

Page 44 -section 9.3 - The statement 'ANSI X3.230 specifies the mechanisms by which an IU shall be transferred.' should be 'The FC-PH standard specifies the mechanisms for transferring IUs.'

Response:

Accepted.

Installation:

Installed as requested.

4.389: IBM comment from George Penokie (Editorial)

Page 44 - section 9.4 - Why is the term 'information unit' now being using instead of 'IU'. Pick one or the other and only use that one.

Response:

Accepted.

Installation:

Installed as requested.

4.390: IBM comment from George Penokie (Editorial)

Page 44 - section 9.4 - When do bytes 10 and 11 being not indicate a successful completion? If there are no cases then the term 'normally' should be deleted. If there are cases then they should be stated or a reference added to where it is explained.

Response:

Accepted.

Installation:

Installed as requested.

4.391: IBM comment from George Penokie (Editorial)

Page 44 - section 9.4 - The statement '...either byte 10 or byte 11 should be examined by the application client to determine...' should be '...either byte 10 or byte 11 should cause the application client to examine the fields in the FCP_RSP IU to determine...'

Response:

Accepted.

Installation:

Installed as requested.

4.392: IBM comment from George Penokie (Editorial)

Page 44 - section 9.4 - The term 'executed' in the statement '..for each command executed.' should be executed.

Response:

Accepted.

Installation:

Installed as requested.

4.393: IBM comment from George Penokie (Editorial)

Page 44 - section 9.4 - The statement 'The Flag bit defined by SAM for command linking is obsolete in FCP-2.' should be moved to section that list obsolete things and deleted from here.

Response:

Accepted in principle. This was located here in FCP, so the location is familiar.

Installation:

Installed as requested. No list is required.

4.394: IBM comment from George Penokie (Editorial)

Page 44 - section 9.4 - The information between 9.4 and 9.4.1 is hanging.

Response:

Accepted.

Installation:

Installed as requested.

PDF Page 61

4.395: IBM comment from George Penokie (Editorial)

Page 45 -48 - sections 9.4.x - These section titles should be removed. I suggest making them into run in headers (like the definitions list) which would keep the identity of the sections and get rid of the hung information.

Response:

Accepted.

Installation:

No change was made.

4.396: IBM comment from George Penokie (Editorial)

Page xx - table xx - There are two notations used for labeling reserved bytes. One uses all small caps (the preferred) and the other uses normal text with first letter capitalized. Pick one and make them all the same.

Response:

Accepted.

Installation:

Installed as small caps for fields and as normal text with the first letter capitalized for groups.

4.397: IBM comment from George Penokie (Editorial)

Page 45 - section 9.4 - table 26 - Byte 10 - bits 5-7 have no information as to what they are. I assume they are reserved and should be labeled as such.

Response:

Accepted.

Installation:

Installed as requested.

4.398: IBM comment from George Penokie (Editorial)

Page 45 - section 9.4.1 - The statement 'FCP_CONF_REQ, when 1, indicates...' should be 'An FCP_CONF_REQ bit of 1 indicates...' This form should be followed in all the bit descriptions.

Response:

Accepted.

Installation:

Installed as requested.

4.399: IBM comment from George Penokie (Editorial)

Page 45 - section 9.4.1 - The statement 'FCP_CONF_REQ, when 0, indicates...' should be 'An FCP_CONF_REQ bit of 0 indicates...' This form should be followed in all the bit descriptions.

Response:

Accepted.

Installation:

Installed as requested.

PDF Page 62

4.400: IBM comment from George Penokie (Editorial)

Page 46 - section 9.4.7 - The statement 'If the FCP_RESID_UNDER or the...' should be 'If the FCP_RESID_UNDER bit or the...'

Response:

Accepted.

Installation:

Installed as requested.

4.401: IBM comment from George Penokie (Editorial)

Page 46 - section 9.4.7 - The statement 'If the FCP_RESID_UNDER bit is set, a transfer...' should be 'If the FCP_RESID_UNDER bit is set to 1, a transfer...';

Response:

Accepted.

Installation:

Installed as requested.

4.402: IBM comment from George Penokie (Editorial)

Page 46 - section 9.4.7 - The statement '..equal to: FCP_DL - highest offset of any byte transmitted' is not clear. Is it $a=b-c$ or something else. If this is an equation then it needs to be stated more clearly than it is.

Response:

Accepted.

Installation:

Made into an equation.

4.403: IBM comment from George Penokie (Editorial)

Page 46 - section 9.4.7 - The statement 'If the FCP_RESID_OVER bit is set, the transfer...' should be 'If the FCP_RESID_OVER bit is set to 1, the transfer...';

Response:

Accepted.

Installation:

Installed as required.

4.404: IBM comment from George Penokie (Editorial)

Page 46 - section 9.4.7 - The statement '...equal to: (Transfer length required by command) - FCP_DL' is not clear. Is it $a=b-c$ or something else. If this is an equation then it needs to be stated more clearly than it is

Response:

Accepted.

Installation:

Made into an equation.

PDF Page 64

4.405: IBM comment from George Penokie (Editorial)

Page 48 - section 9.4.10 - table 27 - Why is this table in a format that is different than other table that have the same type of information (e.g., table 26). This table should be changed to make it like the others.

Response:

Accepted.

Installation:

Installed as requested.

4.406: IBM comment from George Penokie (Editorial)

Page 48 - section 9.4.10 - table 28 - The values in the value column should all be in the format xxh and the term 'hexadecimal' should be removed from the header.

Response:

Accepted.

Installation:

Installed as requested.

4.407: IBM comment from George Penokie (Editorial)

Page 48 - section 9.4.10 - table 28 - All the RDP_CODES should be all caps.

Response:

Accepted in principle. See 4.300.

Installation:

Uses a lower case convention.

4.408: IBM comment from George Penokie (Editorial)

Page 48 - section 9.4.10 - The statement 'Values 04 and 05 are not...' should be 'Values 04h and 05h are not...'.

Response:

Accepted.

Installation:

Installed as requested.

PDF Page 66

4.409: IBM comment from George Penokie (Editorial)

Page 50 - section 10 - The information between section 10 and 10.1 is hanging.

Response:

Accepted.

Installation:

Installed as requested. Note that there is a redundant level of indexing that is removed.

4.410: IBM comment from George Penokie (Editorial)

Page 50 - section 10.1 - The information between section 10.1 and 10.1.1 is hanging.

Response:

Accepted.

Installation:

Installed as requested.

4.411: IBM comment from George Penokie (Editorial)

Page 50 - section 10.1 - The statement 'This clause describes...' is not correct in that the statement is in a subclause. A better was to say it would be 'Clause 10 describes...'

Response:

Accepted.

Installation:

Installed as requested.

4.412: IBM comment from George Penokie (Editorial)

Page 50 - section 10.1 - The term 'influence' should be removed in its first use and changed to 'control' in its second use.

Response:

Accepted.

Installation:

Installed as requested.

4.413: IBM comment from George Penokie (Editorial)

Page 50 - section 10.1.1 - I do not believe the sentence 'The name for this mode page (disconnect-reconnect) comes from the SCSI-2 parallel bus definitions.' contains a useful information and should be deleted.

Response:

Accepted.

Installation:

Installed as requested.

4.414: IBM comment from George Penokie (Editorial)

Page 50 - section 10.1.1 - The statement 'This clause specifies which parameters defined...' should be changed to 'This subclause specifies the parameters defined...'

Response:

Accepted.

Installation:

Installed as requested.

4.415: IBM comment from George Penokie (Editorial)

Page 50 - section 10.1.1 - The sentences 'The application client and initiator communicate to determine what values are most appropriate for a device server. The device server communicates the parameter values in this mode page to the Target Role Agent, normally the Fibre Channel interface circuitry. This communication is internal to the target device and is outside the scope of SCSI-3.' talk about actions that are outside the control of this standard and therefore it should be removed.

Response:

This is the model for this behavior and should be explained, either here or in another location. Text will be reviewed. After review in the June 7, 2000 working group, the text was modified by deleting the words "application client and".

Installation:

Installed as approved.

4.416: IBM comment from George Penokie (Editorial)

Page 50 - section 10.1.1 - The statement 'If a parameter that is not appropriate for the an FCP-2 SCSI-3 device is nonzero,...' is incorrect and makes no sense. Maybe it should be 'If a field or bit contains a value that is not supported by the FCP-2 device,...'

Response:

Accepted.

Installation:

Installed as requested.

4.417: IBM comment from George Penokie (Editorial)

Page 50 - section 10.1.1 - All the information between 10.1.1 and 10.1.1.1 is hanging.

Response:

Accepted.

Installation:

Installed as requested.

4.418: IBM comment from George Penokie (Editorial)

Page 50 - section 10.1 - There should be a something here about seeing table 4 for how to handle mode pages under various conditions.

Response:

Accepted.

Installation:

After review, the present information seems to be adequate. There is no convenient place to put this information.

PDF Page 67

4.419: IBM comment from George Penokie (Editorial)

Page 51 -53 - sections 10.1.1.x - These section titles should be removed. I suggest making them into run in headers (like the definitions list) which would keep the identity of the sections and get rid of the hung information.

Response:

Accepted in principle.

Installation:

The hanging information was corrected. The headers will remain in the same format.

PDF Page 68

4.420: IBM comment from George Penokie (Editorial)

Page xx - section xx - The term 'device' or 'devices' should be qualified in all cases. In this standard that could be 'FCP-2 devices' or 'FCP-2 SCSI devices' or 'SCSI devices' one should be picked and used throughout the standard.

Response:

Accepted.

Installation:

The term applied is FCP device. This was fixed in all sections.

4.421: IBM comment from George Penokie (Editorial)

Page 52 - section 10.1.1.4 - There is no such thing as a 'target device' there are 'targets' and 'SCSI devices'. In this case the term 'devices' should be deleted.

Response:

Accepted.

Installation:

Installed as requested in 10

4.422: IBM comment from George Penokie (Editorial)

Page 52 - sections 10.1.1.3, 10.1.1.4, and 10.1.1.5 - In the second paragraph in all these section there is a term in small caps that should be in normal text. (i.e., bus inactivity limit, disconnect time limit, and connect time limit).

Response:

Accepted in principle. Text will be reviewed.

Installation:

Corrected by changing these to a reference to the field.

4.423: IBM comment from George Penokie (Editorial)

Page 52 - section 10.1.1.7 - The following wording is different from the rest of the standard. It should always be the same. 'If the xxxx bit is zero/one...' should in all cases be change to 'If the xxxx bit is set to 1/0....'

Response:

Accepted.

Installation:

I believe the wording is more helpful in this context to first define the class of behavior the bit is managing. This is also parallel to the wording in SPC-2.

4.424: IBM comment from George Penokie (Editorial)

Page 52 - section 10.1.1.7 - In the statement 'This bit does not...' it is not clear what bit is being talked about. Change to 'The xxx bit does not...'.

Response:

Accepted.

Installation:

Corrected in all sections of clause 10.

PDF Page 69

4.425: IBM comment from George Penokie (Editorial)

Page 53 - section 10.1.1.7 - There should be a cross-reference to where SRR is defined.

Response:

Accepted.

Installation:

Deleted during rewrite.

4.426: IBM comment from George Penokie (Editorial)

Page 53 - section 10.1.1.8 - What is an FA bit??

Response:

Accepted.

Installation:

Fairness Access (FA) was used to clarify this.

4.427: IBM comment from George Penokie (Editorial)

Page 53 - section 10.1.1.8 - The following wording is different from the rest of the standard. It should always be the same. 'If the xxxx bit is zero/one...' should in all cases be change to 'If the xxxx bit is set to 1/0....

Response:

Accepted.

Installation:

Installed as requested.

4.428: IBM comment from George Penokie (Editorial)

Page 53 - section 10.1.1.9 - The statement '...SPC-2 are not implemented and are reserved for FCP-2 devices.' should be change to '...SPC-2 are reserved in FCP-2 devices.'

Response:

Accepted.

Installation:

Installed as requested.

4.429: IBM comment from George Penokie (Editorial)

Page 53 - section 10.1.1.10 - The statement '...will be transmitted...' should be '...shall be transmitted....'

Response:

Accepted.

Installation:

Installed as requested.

4.430: IBM comment from George Penokie (Editorial)

Page 53 - section 10.1.1.10 - The statement '...but more data must still be transferred...' should be '...but more data is required to be transferred...'

Response:

Accepted.

Installation:

The text was changed to “but more data remains to be transferred”.

4.431: IBM comment from George Penokie (Editorial)

Page 53 - section 10.1.1.10 - The term 'etc.' should be deleted. An etc. in an e.g. list is redundant.

Response:

Accepted.

Installation:

Installed as requested.

4.432: IBM comment from George Penokie (Editorial)

Page 53 - section 10.1.1.10 - The statement 'This value shall...' needs to state which value is being referred to.

Response:

Accepted.

Installation:

Installed as requested.

PDF Page 70

4.433: IBM comment from George Penokie (Editorial)

Page 54 - section 10.1.2 - The statement '...follows the MODE SENSE/MODE SELECT rules...' should be '...follows the MODE SENSE command and MODE SELECT command rules...'

Response:

Accepted.

Installation:

Installed as requested.

4.434: IBM comment from George Penokie (Editorial)

Page 54 - section 10.1.2 - The statement '(See See "4.3" on page 9)' should be changed to '(See 4.3)'.

Response:

Accepted.

Installation:

Installed as requested.

4.435: IBM comment from George Penokie (Editorial)

Page 54 - section 10.1.2 - The following wording is different from the rest of the standard. It should always be the same. 'If the xxxx bit is zero/one...' should in all cases be change to 'If the xxxx bit is set to 1/0....

Response:

Accepted.

Installation:

Installed as requested.

4.436: IBM comment from George Penokie (Editorial)

Page 54 - section 10.1.2 - The statement '...follows the MODE SENSE/MODE SELECT rules...' should be '...follows the MODE SENSE command and MODE SELECT command rules...'

Response:

Accepted.

Installation:

Installed as requested.

4.437: IBM comment from George Penokie (Editorial)

Page 54 - section 10.1.3 - The information between 10.1.3 and 10.1.3.1 is hanging.

Response:

Accepted.

Installation:

Installed as requested.

PDF Page 71

4.438: IBM comment from George Penokie (Editorial)

Page 55 - Section 10.1.3 - table 32 - There are several cells that have no text. I assume these should be marked reserved.

Response:

Accepted.

Installation:

Installed as requested.

4.439: IBM comment from George Penokie (Editorial)

Page 55 - section 10.1.3 - The statement '...follows the MODE SENSE/MODE SELECT rules...' should be '...follows the MODE SENSE command and MODE SELECT command rules...'

Response:

Accepted.

Installation:

Installed as requested.

4.440: IBM comment from George Penokie (Editorial)

Page 55 -58 - sections 10.1.3.x - These section titles should be removed. I suggest making them into run in headers (like the definitions list) which would keep the identity of the sections and get rid of the hung information.

Response:

Accepted.

Installation:

The section titles were preserved.

4.441: IBM comment from George Penokie (Editorial)

Page 54 - section 10.1.3.x - The following wording is different from the rest of the standard. If should always be the same. 'If the xxxx bit is zero/one...' should in all cases be change to 'If the xxxx bit is set to 1/0....

Response:

Accepted.

Installation:

Installed as requested.

4.442: IBM comment from George Penokie (Editorial)

Page 55 - section 10.1.3.1 - The term 'LIP' is not defined anywhere nor is there a cross-reference to where it is defined.

Response:

Accepted. The term should be added to the glossary and to the abbreviations list.

Installation:

The terms were added to the glossary and the abbreviations list.

4.443: IBM comment from George Penokie (Editorial)

Page 55 - section 10.1.3.2 - The term 'loop port enable primitive sequence' is not defined and there are no references to where it is defined.

Response:

Accepted. The term will either be eliminated or referenced in the glossary.

Installation:

The reference to FC-AL-2 is provided in this clause and the abbreviation is defined.

4.444: IBM comment from George Penokie (Editorial)

Page 55 - section 10.1.3.2 - The term 'LPE primitive sequence' is not defined and there are no references to where it is defined.

Response:

Accepted. See previous comment.

Installation:

The term and abbreviation are referenced in this clause.

4.445: IBM comment from George Penokie (Editorial)

Page 55-56 - sections 10.1.3.1 to 10.1.3.3 and 10.1.3.5 to 10.1.3.8 - The following sentence should be first like in section 10.1.3.4 'Targets not attached to an FC-AL loop shall ignore this bit.'

Response:

Accepted in principle.

Installation:

The sentence was placed last in all paragraphs now.

PDF Page 72

4.446: IBM comment from George Penokie (Editorial)

Page 56 - section 10.1.3.3 - The term 'monitoring state' is not defined and there are no references to where it is defined.

Response:

Accepted. The term will either be eliminated or referenced in the glossary.

Installation:

A reference was provided to FC-AL-2 which defines these values.

4.447: IBM comment from George Penokie (Editorial)

Page 56 - section 10.1.3.4 - The term 'LISA phase' is not defined and there are no references to where it is defined.

Response:

Accepted in principle. The term will either be eliminated or referenced in the glossary.

Installation:

The term is now in the abbreviations section and a reference to FC-AL-2 is provided.

4.448: IBM comment from George Penokie (Editorial)

Page 56 - section 10.1.3.4 - The term 'LIFA phase' is not defined and there are no references to where it is defined.

Response:

Accepted in principle. The term will either be eliminated or referenced in the glossary.

Installation:

The term is now in the abbreviations section and a reference to FC-AL-2 is provided.

4.449: IBM comment from George Penokie (Editorial)

Page 56 - section 10.1.3.4 - The term 'LIPA phase' is not defined and there are no references to where it is defined.

Response:

Accepted in principle. The term will either be eliminated or referenced in the glossary.

Installation:

The term is now in the abbreviations section and a reference to FC-AL-2 is provided.

4.450: IBM comment from George Penokie (Editorial)

Page 56 - section 10.1.3.4 - The term 'LIHA phase' is not defined and there are no references to where it is defined.

Response:

Accepted in principle. The term will either be eliminated or referenced in the glossary.

Installation:

The term is now in the abbreviations section and a reference to FC-AL-2 is provided.

4.451: IBM comment from George Penokie (Editorial)

Page 56 - section 10.1.3.5 - The term 'LISM frames' is not defined and there are no references to where it is defined.

Response:

Accepted in principle. The term will either be eliminated or referenced in the glossary.

Installation:

The term is now in the abbreviations section and a reference to FC-AL-2 is provided.

4.452: IBM comment from George Penokie (Editorial)

Page 56 - section 10.1.3.6 - The terms 'address or port discovery' are not defined and there are no references to where they are defined.

Response:

Accepted in principle. The term will either be eliminated or referenced in the glossary.

Installation:

The reference to FC-PLDA and FC-FLA is included inline with the text.

4.453: IBM comment from George Penokie (Editorial)

Page 56 - section 10.1.3.6 - The statement 'A target with a valid fabric login shall ignore this bit.' should be moved out of the center of this paragraph and made into its own paragraph.

Response:

Accepted.

Installation:

Installed as requested.

PDF Page 73

4.454: IBM comment from George Penokie (Editorial)

Page 57 - section 10.1.3.8 - The statement '..fabric loop port, FL_Port, on...' should be '...fabric loop port (FL_Port) on...'

Response:

Accepted.

Installation:

The abbreviation was removed entirely, since this was the only place in the whole document where it was needed.

4.455: IBM comment from George Penokie (Editorial)

Page 57 - section 10.1.3.9 - The following sentence 'The RR_TOV (See "11.3" on page 60.) is defined by bytes 6 and 7 in the following manner.' should be changed to 'The RR_TOV (see 11.3) timer values are defined by bytes 6 and 7 of table 32.'

Response:

Accepted.

Installation:

Installed as requested, with editorial license.

4.456: IBM comment from George Penokie (Editorial)

Page 57 - section 10.1.3.9 - The statement '...RR_TOV value in byte 7 shall..' should be '...RR_TOV value shall..'

Response:

Accepted.

Installation:

Installed as requested.

4.457: IBM comment from George Penokie (Editorial)

Page 57 - section 10.1.3.9 - The sentence 'Those functions are specified by FC-PLDA and by section 11.3 of this standard.' should be 'See 11.3 and FC-PLDA for the RR_TOV time-out functions.'

Response:

Accepted.

Installation:

Installed as requested.

4.458: IBM comment from George Penokie (Editorial)

Page 59 - section 11 - The information between section 11 and 11.1 is hanging.

Response:

Accepted.

Installation:

Installed as requested.

4.459: IBM comment from George Penokie (Editorial)

Page 59 - section 11 - What is the statement 'indicates the implications of timers defined' supposed to mean??

Response:

Accepted in principle. The text will be reviewed.

Installation:

Improved as requested.

4.460: IBM comment from George Penokie (Editorial)

Page 59 - section 11 -table 35 - The text is the cells is too close to the cell tops.

Response:

Accepted.

Installation:

Installed as requested.

4.461: IBM comment from George Penokie (Editorial)

Page 59 - section 11 - table 35 - There appears to be no definition for any of the TOVs. They all should be added into the definitions list. On second look I now see the description column looks to do this. But it would still be a good idea to add the TOVs to the acronym list.

Response:

Accepted.

Installation:

No change was made. The present text seems very clear.

4.462: IBM comment from George Penokie (Editorial)

Page 59 - section 11 - table 35 - There is no key that tells me what a 'R' or 'A' stands for.

Response:

Accepted.

Installation:

Heading was changed to show it means required or allowed.

4.463: IBM comment from George Penokie (Editorial)

Page 59 - section 11 - table 35 - The terms 'public' and 'private' are used but there is no indication as to what they relate to.

Response:

Accepted.

Installation:

They actually apply to the type of loop, which is clarified in section 11. However, this is probably worth putting in the glossary, which was also done.

4.464: IBM comment from George Penokie (Editorial)

Page 59 - section 11 - table 35 - The reference column contains what appear to be references to sections in PLDA. But I see they are not. The confusion is from the reference that list PLDA and 11.3 in one cell. These should be split into 2 cells. It is also not clear if those 2 references apply to both default values or one applies to one and the other the other.

Response:

Accepted.

Installation:

This is actually defined in both places, but since the retry bit only applies in FCP-2, the 11.3 (now 11.4) reference is more correct and will remain.

4.465: IBM comment from George Penokie (Editorial)

Page 59 - section 11 - table 35 - What does the '1:>' in the 'Retry = 1:> 3 X REC_TOV' mean?

Response:

Accepted in principle. The text will be reviewed.

Installation:

It means when the retry bit is equal to one, the value must be as specified. The format was improved to clarify this.

4.466: IBM comment from George Penokie (Editorial)

Page 59 - section 11 - table 35 - What does '>=' mean? I assume it means greater than or equal but without a key to the symbols I do not know for sure.

Response:

Accepted.

Installation:

Installed greater than or equal to mark.

4.467: IBM comment from George Penokie (Editorial)

Page 59 - section 11 - table 35 - In one place you have a caps 'X' with spaces around it and in another a 'x' with no spaces. Do they mean different things? If not then they should both be the same.

Response:

Accepted.

Installation:

Changed X to "times".

4.468: IBM comment from George Penokie (Editorial)

Page 59 - section 11 - table 35 - note 2 - The statement ' SCSI Target devices' should be 'Targets'.

Response:

Accepted.

Installation:

Installed as requested.

4.469: IBM comment from George Penokie (Editorial)

Page 59 - section 11 - table 35 - note 1 - This note is very confusing. I believe this is because it contains unclear references and information that is not relevant to this standard. It should be changed to something like: 'R_A_TOV is defined by FC-PH. FCP-2 defines those default values required by the recovery protocol, deriving the values as described in xxx..FCP-2

defines the default R_A_TOV for sequence qualifiers as 0 for private loops and 10 seconds for public loops. FCP-2 defines the default R_A_TOV for ELS responses as 2 seconds for private loops and 10 seconds for public loops. If extended link services are used to set R_A_TOV, the same value is applied private and public loops. Other FC standards may specify different R_A_TOV default values.'

Response:

Accepted.

Installation:

Installed as requested.

4.470: IBM comment from George Penokie (Editorial)

Page 59 - section 11 - table 35 - note 3 - The statement '...deriving the value as described below:' should be '...that value is derived as follows:'

Response:

Is there really any difference?

Installation:

Installed as requested.

4.471: IBM comment from George Penokie (Editorial)

Page 59 - section 11 - table 35 - note 3 - The list of items should be an a,b,c list.

Response:

Accepted.

Installation:

Installed as requested.

4.472: IBM comment from George Penokie (Editorial)

Page 59 - section 11 - table 35 - note 3 - There is a reference to a specific section in FC-FS that needs to be removed.

Response:

Accepted.

Installation:

Installed as requested.

4.473: IBM comment from George Penokie (Editorial)

Page 59 - section 11 - table 35 - note 4 - The term 'SCSI target' should be 'target'.

Response:

Accepted.

Installation:

Installed as requested.

4.474: IBM comment from George Penokie (Editorial)

Page 59 - section 11 - table 35 - note 5 - The statement '3 X REC_TOV' should be '3 times REC_TOV'.

Response:

Accepted.

Installation:

Installed as requested.

4.475: IBM comment from George Penokie (Editorial)

Page 59 - section 11 - table 35 - In the references column there are no references in some of the row to sections in this document yet there is a section for row. These reference should be added in.

Response:

Accepted.

Installation:

Installed as requested.

4.476: IBM comment from George Penokie (Editorial)

Page 59 - section 11.1 - The statement '...Its use is specified in FC-PH, FC-AL, FC-PLDA, FC-FLA, FC-TAPE and other standards.' should be changed to either list all the standards or just state 'Its use is specified in other FC standards.'

Response:

Accepted.

Installation:

That is all the standards known to include it, so the “other standards” is removed.

4.477: IBM comment from George Penokie (Editorial)

Page 59 - 60 - section 11.1 - The bulleted list should be an a,b,c list.

Response:

Accepted.

Installation:

Installed as requested.

PDF Page 76

4.478: IBM comment from George Penokie (Editorial)

Page xx - section xx - As stated in another comment; one term should be used when talking about a target throughout the standard. There are 2 valid options; target or FCP-2 target. Pick one and change all others to it.

Response:

Accepted.

Installation:

Target and initiator were selected. This made changes in clauses 3, 4, 6, 8, 9, 11, Annex C, Annex D, Annex E, Annex F, Annex G, and Annex H. (New annex numbering)

4.479: IBM comment from George Penokie (Editorial)

Page 60 - section 11.2 - The 'which' should be changed to 'that'.

Response:

Accepted.

Installation:

Installed as requested.

4.480: IBM comment from George Penokie (Editorial)

Page 60 - section 11.2 - The list of items between the () should be (i.e.,).

Response:

Accepted.

Installation:

Used the word composed of, instead.

4.481: IBM comment from George Penokie (Editorial)

Page 60 - section 11.2 - 1st note - The 'shall' needs to be removed from the note or text of the note made into main line text.

Response:

Accepted.

Installation:

The text was brought into the main line of the standard.

4.482: IBM comment from George Penokie (Editorial)

Page 60 - section 11.2 - The term 'FLOGI' is not defined anywhere. It should at least be added to the acronym list.

Response:

Accepted.

Installation:

The abbreviation and a reference to FC-FS were provided in clause 3.

4.483: IBM comment from George Penokie (Editorial)

Page xx - section xx -One term should be used when talking about an initiator throughout the standard. There are 2 valid options; initiator or FCP-2 initiator. Pick one and change all others to it.

Response:

Accepted.

Installation:

The term initiator was selected and placed throughout the document.

4.484: IBM comment from George Penokie (Editorial)

Page 60 - section 11.3 - The term 'LOGO' is not defined. It should at least be added to the acronym list.

Response:

Accepted.

Installation:

Abbreviation placed in clause 3.

4.485: IBM comment from George Penokie (Editorial)

Page 60 - section 11.3 - The statement '(hex '16') should be removed and replaced with a cross reference to the mode pages description.

Response:

Accepted.

Installation:

The corresponding mode page was referenced.

4.486: IBM comment from George Penokie (Editorial)

Page 60 - section 11.3 - The statement '...always appropriate to ADISC address discovery time.' make no sense.

Response:

Accepted.

Installation:

The offending statement was deleted.

PDF Page 77

4.487: IBM comment from George Penokie (Editorial)

Page 61 - section 11.4 - table 36 - It is not clear what is meant by the statement '(optional timer restart)'. Does that mean that the timer may not start when this event occurs or does it mean something else?

Response:

Accepted.

Installation:

The text and table have been clarified.

PDF Page 78

4.488: IBM comment from George Penokie (Editorial)

Page 62 - section 12.1.1 - The statement '..in this chapter..' is not correct and should be change to '..in the following subclauses...' or deleted altogether.

Response:

Accepted.

Installation:

The text was changed to “in the following subclauses”.

4.489: IBM comment from George Penokie (Editorial)

Page 62 - section 12.1.1 - The statement '...of this document.' should be changed to '...of this standard.'

Response:

Accepted.

Installation:

As requested.

4.490: IBM comment from George Penokie (Editorial)

Page 62 - section 12.1.1 - In the statement 'FCP-2 has expanded the error detection...' it is not stated what FCP-2 has expended from. This needs to be stated.

Response:

Accepted.

Installation:

Changed as:

FCP-2 has expanded the error detection capabilities es defined by FCP by allowing the optional use of the REC ELS to monitor the progress of active exchanges.

4.491: IBM comment from George Penokie (Editorial)

Page 62 - section 12.1.2 - The statement '...that will allow..' should be '...that allows...'

Response:

Accepted.

Installation:

Installed as requested. Note that this apparently applies to 12.1.2, not 12.1.1.

4.492: IBM comment from George Penokie (Editorial)

Page 62 - section 12.1.2 - The statement '...shall use and accept the REC and SRR ELSs as required to perform the retransmission unless unusual events have made the recovery features unavailable' has a requirement that is removed with one sentence. If it is not a requirement then the shall should be make into a may or it is a requirement then the 'unusual events' (what ever those are) statement should be removed.

Response:

Accepted.

Installation:

Changed as:

An FCP-2 device that has agreed to perform retransmission shall use and accept the REC and SRR ELSs as required defined by this standard to perform the retransmission~~unless unusual events have made the recovery features unavailable.~~

Note that this also allows various forms of rejects to take place.

4.493: IBM comment from George Penokie (Editorial)

Page 62 - section 12.1.2 - What is meant by the statement '..by this clause.'. Do you mean clause 12 or subclause 12.1.2 or some group of subclauses under clause 12? It should be made clear as to what is being referenced.

Response:

Accepted.

Installation:

This was changed to a reference to clause 12.

4.494: IBM comment from George Penokie (Editorial)

Page 62 - section 12.2 - The text between section 12.2 and 12.2.1 is hanging.

Response:

Accepted.

Installation:

Text was given the heading of "Overview of Initial FCP Error Detection". Similar changes were required in 12.3 and 12.5.

4.495: IBM comment from George Penokie (Editorial)

Page 62 - section 12.2.1 - All the 1,2,3 lists should be an a,b,c lists.

Response:

Accepted.

Installation:

Changed in section 12.2.1 and several other sections.

4.496: IBM comment from George Penokie (Editorial)

Page 62 - section 12.2 - There should be an i.e., within the ()s.

Response:

Accepted.

Installation:

The "i.e." was installed.

4.497: IBM comment from George Penokie (Editorial)

Page 62 - section 12.2 - The statement 'read-type command' should be 'read command'.

Response:

Accepted.

Installation:

As requested in 12.2.2.

4.498: IBM comment from George Penokie (Editorial)

Page 62 - section 12.2 - The statement '...is set to 0b' should be change to '...is set to 0'. This is in line with the notation that has been used up to this point in the standard so there is no point in changing.

Response:

Accepted.

Installation:

Requested change was installed in 12.2.2

4.499: IBM comment from George Penokie (Editorial)

Page 62 -63 - section 12.2.1 - Each item in the list should end with a ';' with the 2nd to the last ending in a ';' and'.

Response:

Accepted.

Installation:

Requested change was installed.

4.500: IBM comment from George Penokie (Editorial)

Page 62 - 69 - The statement 'after expiration of the time-out period' should be change in all cases to 'after xxx_TOV times out ...' this will remove the to post a death notice after the timers expire.

Response:

Accepted.

Installation:

Typical change:

after ~~expiration of the timeout period~~ REC_TOV ~~times out~~ following the sending of FCP_DATA IU(s) and no FCP_RSP or FCP_XFER_RDY IU has been received;

PDF Page 79

4.501: IBM comment from George Penokie (Editorial)

Page 63 - section 12.2.2 - All the 1,2,3 lists should be an a,b,c lists.

Response:

Accepted.

Installation:

Completed as requested.

4.502: IBM comment from George Penokie (Editorial)

Page 63 - section 12.2 - The statement '...is set to 1b' should be change to '...is set to 1'.

Response:

Accepted.

Installation:

Completed as requested.

4.503: IBM comment from George Penokie (Editorial)

Page 63 - section 12.2.2 - Each item in the list should end with a ';' with the 2nd to the last ending in a ';' and'.

Response:

Accepted.

Installation:

Completed as requested. At the same time, all other lists were reviewed and updated accordingly.

4.504: IBM comment from George Penokie (Editorial)

Page 63 - section 12.2 - item 1 - The statement 'for detection of a...' should be 'after detection of a ...'

Response:

Accepted.

Installation:

Completed as requested.

4.505: IBM comment from George Penokie (Editorial)

Page 63 - section 12.2.2 - item 5 - The statement '..an "Abort, Perform ABTS" is...' sounds like a error code. If is then it should state 'an xxxx code of ABORT, PERFORM ABTS is...' where xxx is the name of the error code type.

Response:

Accepted.

Installation:

This is actually from FC-FS and therefore uses the FC-FS capitalization conventions. It is changed to read:

an ACK with the F_CTL Abort Sequence Condition bits set to Abort Sequence, Perform ABTS is received. (See FC-FS)

Similar changes were made in the next paragraph of 12.2.2 and in 12.3.1.

4.506: IBM comment from George Penokie (Editorial)

Page 63 - section 12.2.2 - The statement '(due to a missing ACK)' should be in ', 's not '()'s.

Response:

Accepted.

Installation:

Reworded entire sentence as follows:

~~If the BA_ACC response to an ABTS from a Sequence Initiator (due to a missing ACK) indicates the Sequence was received, no error detection or recovery is required.~~

If an ABTS is transmitted by a Sequence Initiator because it had detected a missing ACK and the BA_ACC response to the ABTS indicates the sequence was correctly received by the Sequence Recipient, no error detection or recovery is required.

PDF Page 80

4.507: IBM comment from George Penokie (Editorial)

Page 64 - section 12.3.4 - All the 1,2,3 lists should be an a,b,c lists

Response:

Accepted.

Installation:

Changed as requested.

4.508: IBM comment from George Penokie (Editorial)

Page 64 - section 12.3.1 - The statement '2x...' should be '2 times...'.

Response:

Accepted.

Installation:

Changed as requested.

4.509: IBM comment from George Penokie (Editorial)

Page 64 - section 12.3.1 - The statement 'If the response is an LS_RJT with a reason code indicating that the function is not supported, treat the Target as a device not supporting error detection using...' is unclear. If the response (to what?)....treat the target (whom is treating the target?) . I am guessing the following is correct: 'If the response to the new exchange is an LS_RJT with a reason code indicating that the function is not supported, the initiator shall assume the target as a device not supporting error detection using...'

Response:

Accepted.

Installation:

The sentence is changed to read:

If the response to the new exchange issuing the REC is an LS_RJT with a reason code indicating that the function is not supported, the initiator shall assume the target is a device not supporting error detection using REC. The device shall perform recovery by aborting the Exchange as documented in 12.5.

4.510: IBM comment from George Penokie (Editorial)

Page 64 - section 12.3.1 - In the statement 'If a proper ACC...' what is an improper ACC etc.?
The statement should read 'If an ACC...'.

Response:

Accepted.

Installation:

Changed as requested.

4.511: IBM comment from George Penokie (Editorial)

Page 64 - section 12.3.2 - The statement in '()'s should start with 'i.e.,'.

Response:

Accepted.

Installation:

Changed as requested.

4.512: IBM comment from George Penokie (Editorial)

Page 64 - section 12.3.2 - The statement '...shall be retransmitted. This is to ensure that...' should be '...shall be retransmitted to ensure that...'

Response:

Accepted.

Installation:

Changed as requested.

4.513: IBM comment from George Penokie (Editorial)

Page 64 - section 12.3.3 - The statement in '()'s should start with 'i.e.,'.

Response:

Accepted.

Installation:

Changed as requested.

4.514: IBM comment from George Penokie (Editorial)

Page 64 - section 12.3.3 - The statement '(r_CTL = data descriptor).' should be changed to 'with R_CTL set to data descriptor.'.

Response:

Accepted.

Installation:

This is already covered by the description of SRR and was deleted.

4.515: IBM comment from George Penokie (Editorial)

Page 64 - section 12.3.3 - The sentence 'When the FCP_XFER_RDY is successfully received, the data is sent, and the operation continues normally.' is not a complete sentence and I do not know how to fix it.

Response:

Accepted.

Installation:

The sentence was changed to read:

After the FCP_XFER_RDY is successfully received, the FCP I/O operation continues normally.

4.516: IBM comment from George Penokie (Editorial)

Page 64 - section 12.3.4 - The statements in '()'s should start with 'i.e.',.

Response:

Accepted.

Installation:

Changed as requested.

PDF Page 81

4.517: IBM comment from George Penokie (Editorial)

Page 65 - section 12.3.4 - Each item in the list should end with a ';' with the 2nd to the last ending in a ';' or'.

Response:

Accepted.

Installation:

Changed as requested.

4.518: IBM comment from George Penokie (Editorial)

Page 65 - section 12.3.4 - The statement '..response and will perform...' should be 'response and shall perform...'

Response:

Accepted.

Installation:

Changed as requested.

4.519: IBM comment from George Penokie (Editorial)

Page xx - All FCP-2 IUs should be labeled as IUs through out the standard. There are many cases where an FCP-2 IU leaves off the IU and it is then not clear if the term is an IU or some new thing.

Response:

Accepted.

Installation:

Repaired in section 4, 8, 9, 10, 11, 12.

4.520: IBM comment from George Penokie (Editorial)

Page 65 - section 12.3.4 - The statement '...terminated before execution by a...' should be '...terminated by a..'. The 'before execution' term is meaningless as there is no definition of what command execution is, when it starts, or when it ends.

Response:

Accepted.

Installation:

Sentence was changed to read:

A command that was terminated prior to transferring data by a CHECK CONDITION requesting the FCP_CONF IU may have the same REC values as a command for which an FCP_XFER_RDY IU was not received by the initiator.

4.521: IBM comment from George Penokie (Technical)

(T) Page 65 - section 12.3.4 - non-tagged queueing should be made obsolete in FCP-2.

Response:

Rejected. See 4.322.

4.522: IBM comment from George Penokie (Editorial)

Page 65 - section 12.3.4 - item 2 - The '3x' should be '3 times'.

Response:

Accepted.

Installation:

Changed as requested.

4.523: IBM comment from George Penokie (Editorial)

Page 65 - section 12.3.4 - item 3 - The statement 'status retention resources are exhausted and the oldest retained status must be flushed from the retention resource.' should be 'no status retention resources are available.' The remaining information in that statement is implementation specific and should be removed.

Response:

Accepted in principle. Text will be reviewed.

Installation:

The offending sentence was changed as follows:

c) status retention resources are exhausted.

Note that this removes the implementation guide-line previously provided.

This resolution was approved in the September 11, 2000 working group meeting.

4.524: IBM comment from George Penokie (Editorial)

Page 65 - section 12.3.5 - The sentence 'As documented in 12.3.9, the Target discards the Sequence in error, but does not initiate any recovery action for Class 3.' should be The Target

discards the Sequence in error, but does not initiate any recovery action for Class 3 (see 12.3.9).'

Response:

Accepted.

Installation:

Changed as requested.

4.525: IBM comment from George Penokie (Editorial)

Page 65 - section 12.3.6 - The statement in '()'s should start with 'i.e.',.

Response:

Accepted.

Installation:

Changed as requested.

4.526: IBM comment from George Penokie (Editorial)

Page 65 - section 12.3.6 - The statement '(R_CTL = solicited data)...' should be changed to 'with R_CTL set to solicited data'.

Response:

Accepted.

Installation:

This is already covered by the description of SRR and was deleted.

PDF Page 82

4.527: IBM comment from George Penokie (Editorial)

Page 66 - section 12.3.6 - The statement '...Sense key 4, ASC/ASQ of 48/00 (Initiator Detected Error message received)).' should be '...sense key of HARDWARE ERROR and an ASC/ASCQ of INITIATOR DETECTED ERROR MESSAGE RECEIVED)).'.

Response:

Accepted.

Installation:

Changed as requested. Note that this was tightened up to be a required status.

4.528: IBM comment from George Penokie (Editorial)

Page 66 - section 12.2.6 - The statement '(retry, allow ULP time out, or return status to ULP)' should be '(e.g. retry, allow ULP time out, or return status to ULP)'.

Response:

Accepted.

Installation:

Changed as requested.

4.529: IBM comment from George Penokie (Editorial)

Page 66 - section 12.3.6 - The statement '...and other internal state'. should be '...and other internal states.'.

Response:

Accepted.

Installation:

Changed as requested.

4.530: IBM comment from George Penokie (Editorial)

Page 66 - section 12.3.6 - The sentence 'As stated in 12.3.9, the SCSI Target does not initiate error recovery for Class 3.' should be 'The SCSI Target shall not initiate error recovery for Class 3 (see 12.3.9).'

Response:

Accepted.

Installation:

Changed as requested.

4.531: IBM comment from George Penokie (Editorial)

Page 66 - section 12.3.7 - The statement '...target will be a LS_RJT..' should be '...target shall be a LS_RJT...'

Response:

Accepted.

Installation:

Changed as requested.

4.532: IBM comment from George Penokie (Editorial)

Page 66 - section 12.3.7 - The statement '...an “Invalid OX_ID-RX_ID combination” reason code explanation.' should be '...the reason code set to INVALID OX_ID-RX_ID COMBINATION'.'

Response:

Accepted.

Installation:

Changed to meet FC-FS capitalization requirements.

4.533: IBM comment from George Penokie (Editorial)

Page 66 - section 12.3.7 - The statement '...FCP_CONF_REQ bit set and...' should be '...FCP_CONF_REQ bit set to 1 and....'.

Response:

Accepted.

Installation:

Changed as requested.

4.534: IBM comment from George Penokie (Editorial)

Page 66 - section 12.3.7 - The statement '...reply will be...' should be '...reply shall be...'

Response:

Accepted.

Installation:

Changed as requested.

4.535: IBM comment from George Penokie (Editorial)

Page 66 -section 12.3.9 - The term 'error policy' shows up here for the first time and there is not indication as to what an 'error policy' is or where it is defined. This needs to be fixed.

Response:

Accepted.

Installation:

Changed to:

If a SCSI Target detects a Sequence error, it shall discard the Sequence(s) based on the exchange error policy specified by the F_CTL Abort Sequence Condition bits in the first frame of the exchange.
(See FC-FS.)

4.536: IBM comment from George Penokie (Editorial)

Page 66 - section 12.3.9 - The statement '(refer to Annex B.2.1)' should be '(see Annex B.2.1)'.

Response:

Accepted.

Installation:

Changed to read (see B.2.1). Later eliminated by subsequent rewrite.

4.537: IBM comment from George Penokie (Editorial)

Page 67 - section 12.3.9 - The note contains requirements that are not allowed in notes. The requirement must be removed.

Response:

Accepted.

Installation:

See 4.538.

4.538: IBM comment from George Penokie (Technical)

(T) - Page 66 - section 12.3.9 - This states targets may issue an ABTS. This should be change to prohibited class-3 device when running in target mode from issuing any ABTSs. This would match the PLDA and most of the implementations.

Response:

This restriction is presently not defined in FCP, but only in FC-PLDA. The proper place to define this is in a profile. No change will be made. After some discussion, was agreed to in the April 5, 2000 meeting.

Installation:

The text was re-written as follows to prohibit the transmission of ABTS by the target for unacknowledged classes of service, but allow it for acknowledged classes of service.

For acknowledged classes of service, if a SCSI Target detects a Sequence error, it may send an ABTS for the Sequence by setting Bit 0 in the ABTS Parameter field to one. (See B.2.1). If a Recovery Qualifier range is returned in the BA_ACC for the ABTS the Target shall send a RRQ ELS after R_A_TOV_SEQ_QUAL times out after receipt of the BA_ACC.

For unacknowledged classes of service, the target shall not attempt recovery for Sequence errors. The target shall depend on Initiator timeouts for recovery.

This resolution was approved in the September 11, 2000 working group meeting.

PDF Page 83

4.539: IBM comment from George Penokie (Editorial)

Page 67 - section 12.4 - Each item in the list should end with a ';' with the 2nd to the last ending in a ';' or'.

Response:

Accepted.

Installation:

Changed as requested.

4.540: IBM comment from George Penokie (Editorial)

Page 67 - section 12.3.9 - Each item in the list should end with a ';' with the 2nd to the last ending in a ';' and'.

Response:

Accepted.

Installation:

Changed as requested.

4.541: IBM comment from George Penokie (Editorial)

Page 67 - section 12.3.9 - The term 'SCSI target authentication' is used for the first time with no reference as to where it is defined or what it is. This needs to be resolved.

Response:

Accepted.

Installation:

The proper terminology is actually “SCSI target Exchange authentication” and is described in FC-PLDA, 10.4. The term is changed to match FC-PLDA and a reference to FC-PLDA is provided.

4.542: IBM comment from George Penokie (Editorial)

Page 67 - section 12.4 - The statement '(refer to Annex B.2.1)' should be '(see Annex B.2.1)'.

Response:

Accepted.

Installation:

The text is changed to read (see B.2.1).

4.543: IBM comment from George Penokie (Editorial)

Page 67 - section 12.4 - The statement '...values are reused quickly and..' should be '...values are reused and...'. The term 'quickly' cannot be quantified so it should be removed.

Response:

Accepted.

Installation:

Actually, quickly means “within R_A_TOV”. The text will be changed to reflect this.

This resolution was approved in the September 11, 2000 working group meeting.

4.544: IBM comment from George Penokie (Editorial)

Page 67 - section 12.5.1 - The sentence 'This subclause does not define the protocol by which multiple SCSI Initiators communicate or synchronize shared peripherals.' should be removed because it adds nothing to the standard. This subclause does not define how to bake bread but we do not state that in the standard.

Response:

Accepted.

Installation:

Sentence is deleted.

4.545: IBM comment from George Penokie (Editorial)

Page 67 - section 12.5 - The text between 12.5 and 12.5.1 is hanging.

Response:

Accepted.

Installation:

Hanging text is identified with a new header.

4.546: IBM comment from George Penokie (Technical)

(T) Page 67 - section - 12.5 - The statement 'All FCP-2 devices shall support the use of ABTS-....' should be changed to 'All FCP-2 SCSI devices when operating as an initiator shall support the use of ABTS-...' this goes along with my other comments on no allowing ABTS for target devices.

Response:

This was intended to specify the requirement that all targets shall accept an ABTS-LS as a recovery abort and that all initiators shall be able to create an ABTS-LS as a recovery abort and as an Abort Task. All other uses of ABTS-LS should be optional, but not prohibited. The text will be changed accordingly. This was accepted in the April 5, 2000 meeting.

Installation:

Note that 4.538 required the change to match FC-PLDA for unacknowledged classes of service. The following text replaces the offending sentence:

All FCP-2 initiators shall be capable of invoking the recovery abort protocol to terminate failing commands for later retry. (See 9.1.2.2.) All FCP-2 targets shall be capable of accepting and completing the recovery abort protocol.

4.547: IBM comment from George Penokie (Editorial)

Page 67 - section 12.5.1 - The statement '...Exchange" bit is received...' should be '...exchange" bit set to one is received...'.

Response:

Accepted.

Installation:

Changed as requested.

4.548: IBM comment from George Penokie (Editorial)

Page 67 - section 12.5.1 - The statement '...after certain task management functions have been executed.' is not clear in that it does not tell which task management functions this applied to. There needs to be a list.

Response:

Accepted.

Installation:

The offending sentences were replaced with:

After the execution of a task management function that clears tasks, recovery abort shall be invoked for all ambiguous Exchanges not successfully terminated with an FCP_RSP IU status byte indicating COMMAND CLEARED. (See 9.1.2.4).

4.549: IBM comment from George Penokie (Editorial)

Page 67 - section 12.5.1 - The '()' in the following statement should be dropped. '(or the data may already be in flight at the time the ABTS was sent)'.

Response:

Accepted.

Installation:

The offending sentence was replaced with:

For example, if ABTS is sent following transmission of a Read command, the SCSI initiator may receive some or all of the requested read data before receiving the BA_ACC to the ABTS.

PDF Page 84

4.550: IBM comment from George Penokie (Editorial)

Page 68 - section 12.5.2 - Each item in the list should end with a ';' with the 2nd to the last ending in a ';' or'.

Response:

Accepted.

Installation:

Changed as requested.

4.551: IBM comment from George Penokie (Editorial)

Page 68 - section 12.5.1 - The statement '...status byte indicating COMMAND CLEARED...' should be '...status set to COMMAND CLEARED...'

Response:

Accepted.

Installation:

Changed as requested.

4.552: IBM comment from George Penokie (Editorial)

Page 68 - section 12.5.1 - The statement '...after certain task management functions have been executed.' is not clear in that it does not tell which task management functions this applies to. There needs to be a list.

Response:

Accepted.

Installation:

See 4.458.

4.553: IBM comment from George Penokie (Editorial)

Page 68 - section 12.5.1 - The statement '...specified LUN on...' should be '...specified logical unit on...'

Response:

Accepted.

Installation:

Changed as requested.

4.554: IBM comment from George Penokie (Editorial)

Page 68 - section 12.5.1. The statement '...(no STATUS returned...' should be '...(i.e., no status returned...'

Response:

Accepted.

Installation:

Changed as requested.

4.555: IBM comment from George Penokie (Editorial)

Page 68 - section 12.5.1 - In the statement 'If a proper BA_ACC...' what is an improper BA_ACC etc.? The statement should read 'If a BA_ ACC...'

Response:

Accepted.

Installation:

Changed as requested.

4.556: IBM comment from George Penokie (Editorial)

Page 68 - section 12.5.1 - The '2x' should be '2 times'.

Response:

Accepted.

Installation:

Changed as requested.

4.557: IBM comment from George Penokie (Editorial)

Page 68 - section 12.5.2 - Item a - In two places - The statement 'in (no PLOGI).' should be 'in (i.e., no PLOGI).'

Response:

Accepted.

Installation:

Changed as requested.

4.558: IBM comment from George Penokie (Editorial)

Page 68 - section 12.5.2 - item b in two places - The statement '...bit set to one if...' should be '...bit set to 1 if...' . This is to maintain consistency within the standard.

Response:

Accepted.

Installation:

Changed as requested.

4.559: IBM comment from George Penokie (Editorial)

Page 68 - section 12.5.2 - item b in two places - The sentence 'The reason code shall be “Logical Error” with a reason code explanation of “Invalid OX_ID/RX_ID combination”.' should be 'The reason code shall be LOGICAL ERROR with a reason code explanation of INVALID OX_ID.RX_ID COMBINATION.'

Response:

Accepted.

Installation:

For consistency with FC-FS, the following text was used:

The reason code shall be logical error with a reason code explanation of Invalid OX_ID-RX_ID combination

4.560: IBM comment from George Penokie (Editorial)

Page 68 - section 12.5.2 - item c in two places - The term 'otherwise' should be deleted as it is implied by the to be added 'or' at the end of item b.

Response:

Accepted.

Installation:

Changed as requested.

4.561: IBM comment from George Penokie (Editorial)

Page 68 - section 12.5.2 - in multiple places - There should be no space between the 'FFFF' and the 'h' as there is now.

Response:

Accepted.

Installation:

Changed as requested.

4.562: IBM comment from George Penokie (Editorial)

Page 68 - section 12.5.2 - In the statement '...upon D_ID || S_ID || OX_ID,...' what is the meaning of the '||'? That symbol is not defined in this standard and should be removed and replaced to the equivalent text.

Response:

Accepted.

Installation:

The offending sentence was changed to:

If the RX_ID is FFFFh, SCSI targets shall qualify the FQXID of the ABTS based only upon the combined values of D_ID, S_ID, and OX_ID, not RX_ID.

4.563: IBM comment from George Penokie (Editorial)

Page 68-69 - section 12.6.1 - in two places - The term '2x' should be replaced with '2 times'.

Response:

Accepted.

Installation:

Changed as requested.

PDF Page 85

4.564: IBM comment from George Penokie (Editorial)

Page 69 - section 12.6.3 - Each item in the list should end with a ';' with the 2nd to the last ending in a ';' and'.

Response:

Accepted.

Installation:

Changed as requested.

4.565: IBM comment from George Penokie (Editorial)

Page 69 - section 12.6.2 - Each item in the list should end with a ';' with the 2nd to the last ending in a ';' and'.

Response:

Accepted.

Changed as requested.

4.566: IBM comment from George Penokie (Editorial)

Page 69 - section 12.6.1 - in two places - The statement inside the '()'s should start with 'i.e.,'.

Response:

Accepted.

Installation:

Changed as requested.

4.567: IBM comment from George Penokie (Editorial)

Page 69 - section 12.6.2 - The term '2x' should be replaced with '2 times'.

Response:

Accepted.

Installation:

Changed as requested.

4.568: IBM comment from George Penokie (Editorial)

Page 69 - section 12.6.3 - The term '2x' should be replaced with '2 times'.

Response:

Accepted.

Installation:

Changed as requested.

4.569: IBM comment from George Penokie (Editorial)

Page 69 - section 12.7 - The statement ...'NL_Port with which it has...' should be changed to '...NL_Port that it has...' in multiple places.

Response:

Accepted.

Changed with slight modification to preserve the meaning.

4.570: IBM comment from George Penokie (Editorial)

Page 69 - section 12.7 - The statement '(PLOGI)' should be '(i.e., PLOGI)' in several places.

Response:

Accepted.

Installation:

Changed as requested.

4.571: IBM comment from George Penokie (Editorial)

(T) - Page 69 - section 12.7 - There is a 'TBD' in this section. There can be no TBDs in a standard.

Response:

Accepted.

Installation:

Changed as requested.

4.572: IBM comment from George Penokie (Technical)

(T) Page 69 - section 12.7 - Several statements in this section are in direct conflict with statements in section 6.2.5. This conflict needs to be resolved. I believe the wording in section 12.7 is more correct.

Response:

This text will be reviewed in detail. Several of these discrepancies are corrected by the resolution of other comments. This was accepted in the April 5, 2000 meeting.

Installation:

See 1.48.

PDF Page 87

4.573: IBM comment from George Penokie (Editorial)

Page 71 - several places - Only one SAM standard should be referenced. I believe this standard would only reference SAM-2.

Response:

Accepted.

Installation:

Installed as requested.

4.574: IBM comment from George Penokie (Editorial)

Page 71 - section A.1 - The editors note needs to be removed.

Response:

Accepted.

Installation:

Installed as requested.

4.575: IBM comment from George Penokie (Editorial)

Page 71 - section a.1 - item c - There needs to be a '.' at the end of the statement in item c.

Response:

Accepted.

Installation:

Installed as requested.

PDF Page 88

4.576: IBM comment from George Penokie (Editorial)

Page 72 - section A.1 - table A.1 - note 3 - The term 'SCSI-3 ' should be replaced with 'SCSI'.

Response:

Accepted.

Installation:

The note is removed, since the error condition does not exist in FCP either.

PDF Page 89

4.577: IBM comment from George Penokie (Editorial)

Page 73 - The symbols used in this annex are not defined. You need to define these symbols in section 3. I suggest you copy section 3.5 out of SPI-3 which has every thing you should need to cover this comment.

Response:

Accepted.

Installation:

Text was taken from SAM-2, 3.6.2.

4.578: IBM comment from George Penokie (Editorial)

Page 73 - section a.4 - The information between a.4 and a.4.1 is hanging.

Response:

Accepted.

Installation:

Installed as requested.

PDF Page 90

4.579: IBM comment from George Penokie (Editorial)

Page - 74 - section a.5 - The information between a.5 and a.5.1 is hanging.

Response:

Accepted.

Installation:

Installed as requested.

4.580: IBM comment from George Penokie (Editorial)

Page 74 - section a.5.1 - The term 'SCSI parallel interface service' should be replaced with 'FCP-2 service'.

Response:

Accepted.

Installation:

Sections were deleted and defined by reference.

4.581: IBM comment from George Penokie (Editorial)

Page 74 - section a.5.1 - The information between a.5.1 and a.5.1.1 is hanging.

Response:

Accepted.

Installation:

Installed as requested.

PDF Page 91

4.582: IBM comment from George Penokie (Editorial)

Page 75 - section a.5.1.1 - a.5.1.7 - Replace the term 'SCSI parallel interface services' with 'FCP-2 services' and the term 'message' with 'flag'.

Response:

Accepted.

Installation:

Text was deleted and defined by reference.

PDF Page 93

4.583: IBM comment from George Penokie (Editorial)

Page 77 - section b.2 - The text between b.2 and b.2.1 is hanging.

Response:

Accepted.

Installation:

Annex B deleted.

4.584: IBM comment from George Penokie (Editorial)

Page 77 - section b.1 - All the text in this section should be removed. This information will not be removed from this standard no matter what happens with other standards because once it is forwarded it cannot be changed.

Response:

Accepted.

Installation:

Deleted as requested.

4.585: IBM comment from George Penokie (Editorial)

Page 77 - section b.2.1 - The statement '...parameter field' should be '...PARAMETER (in small caps) field as shown in table b.1.'

Response:

Accepted.

Installation:

Annex B deleted.

4.586: IBM comment from George Penokie (Editorial)

Page 77 - section b.2.1 - The statement '...determine which behavior...' needs to be de-whicked. I suggest '...determine the behavior...'.

Response:

Accepted.

Installation:

Annex B deleted.

4.587: IBM comment from George Penokie (Editorial)

Page 77 - section b.2.1 - The term 'parameter' should be in small caps.

Response:

Accepted.

Installation:

Annex B deleted.

4.588: IBM comment from George Penokie (Editorial)

Page 77 -section b.2.1 - in two places - The notation 'as described in section x.x.x on page xxx' is used. This need to be changed to 'see x.x.x'.

Response:

Accepted.

Installation:

Annex B deleted.

4.589: IBM comment from George Penokie (Editorial)

Page 77 - section b.2.1 - There is a reference to a clause in another standard; this reference needs to be removed.

Response:

Accepted.

Installation:

Annex B deleted.

4.590: IBM comment from George Penokie (Editorial)

Page 77 - section b.3 - The information between section b.3 and b.3.1 is hanging.

Response:

Accepted.

Installation:

Annex B deleted.

4.591: IBM comment from George Penokie (Editorial)

Page 77 - section b.3 - The information about the values that are frame should be reformatted into a table so the reader has a change of understanding what is required to be set to what value.

Response:

Accepted.

Installation:

Installed as requested in 8.2.

4.592: IBM comment from George Penokie (Editorial)

Page 77 - section b.3 - The statement '.. are defined or modified in this annex.' is not correct. It makes no sense because how can you both define and modify something at the same time either you are defining it or modifying it, so which is it? Also the term 'this annex' must be removed or somehow changed into the term 'subclause' or 'clause'.

Response:

Accepted in principle. The text will be reviewed.

Installation:

Annex B deleted.

4.593: IBM comment from George Penokie (Editorial)

Page 77 - section b.3 - table b.2 - There is a blank row that must be eliminated.

Response:

Accepted.

Installation:

Annex B deleted.

PDF Page 94

4.594: IBM comment from George Penokie (Editorial)

Page 78 - section b.3.1 - The term 'would use' should be 'should use' or 'shall use' depending on your intent which is not clear.

Response:

Accepted.

Installation:

Proper word for this is may. Other related corrections were also made in 8.2

4.595: IBM comment from George Penokie (Editorial)

Page 78 - section b.3.1 - The statement 'To avoid ambiguity in the termination and reuse of exchanges,...' should be deleted. The standard does not have to explain why it makes a requirement, it only needs to clearly state the requirements.

Response:

Accepted.

Installation:

Installed as requested in 8.2.

4.596: IBM comment from George Penokie (Editorial)

Page 78 - section b.3.1 - The statement '...reason code hex '09' (i.e. Unable to perform command request).' should be '...reason code of UNABLE TO PERFORM COMMAND REQUEST.'.

Response:

Accepted.

Installation:

Installed as requested in 8.2.

4.597: IBM comment from George Penokie (Editorial)

Page 78 - section b.3.1 - It is not clear as the interpretation of this format. This needs to be explained so the reader understands what is being defined.

Response:

Accepted.

Installation:

Installed as requested in 8.1, so the explanation is not required.

4.598: IBM comment from George Penokie (Editorial)

Page 78 - section b.3.1 - format - This is no definition of what the term 'FT_1' means.

Response:

Accepted.

Installation:

Installed as requested in 8.1, so the explanation is not required.

4.599: IBM comment from George Penokie (Editorial)

Page 78 - section b.3.1 - payload - The statement '...the following table.' should be '...table b.3.'.

Response:

Accepted.

Installation:

Installed as requested in 8.2.

4.600: IBM comment from George Penokie (Editorial)

Page 78 - section b.3.1 - addressing - The term 'which' needs to be removed.

Response:

Accepted.

Installation:

Installed as requested in 8.2

4.601: IBM comment from George Penokie (Editorial)

Page 78 - section b.3.1 - table b.3 - The term 'hex '13000000"' should be '13000000h'.

Response:

Accepted.

Installation:

Installed as requested in 8.2.

PDF Page 95

4.602: IBM comment from George Penokie (Editorial)

Page 79 - section b.3.1 - accept payload - The statement '...in the table below.' should be '...in table b.4.'..

Response:

Accepted.

Installation:

Installed as requested in 8.2.

4.603: IBM comment from George Penokie (Editorial)

Page 79 - section b.3.1 - accept payload - The statement '...is specified below.' should indicate exactly where it is specified, below could be anywhere from here to the end of the standard.

Response:

Accepted.

Installation:

Installed as requested in 8.2.

4.604: IBM comment from George Penokie (Editorial)

Page 79 - section b.3.1 - table b.4 - The term 'hex '02000000"' should be '02000000h'.

Response:

Accepted.

Installation:

Installed as requested in 8.2.

4.605: IBM comment from George Penokie (Editorial)

Page 79 - section b.3.1 - There is a reference to a section in another standard that must be removed.

Response:

Accepted.

Installation:

Installed as requested in 8.2.

4.606: IBM comment from George Penokie (Editorial)

Page - 79 section b.3.1 - The sentence 'The bits specifying whether the Exchange is complete (Bit 29) and whether the responder holds Sequence Initiative (Bit 30) must be valid; the setting of other bits is not required.' should be changed to 'The xxxx bit and the yyy bit of the zzzz shall be set to x. The settings of the other zzzz bits is ignored.' It is not clear as to what bits are being referred to.

Response:

Accepted.

Installation:

The bits are actually defined in FC-FS by name, and so are not referenced here.

4.607: IBM comment from George Penokie (Editorial)

Page 79 - section b.3.1 - It appears the terms originator address identifier, responder address identifier, and data transfer count are all field names and therefore should be small caps and have the term 'field' after them in the last 3 paragraphs.

Response:

Accepted.

Installation:

Installed as requested in 8.2.

PDF Page 97

4.608: IBM comment from George Penokie (Editorial)

Page 81 - section c.1 - The text between c.1 and c.1.1 is hanging.

Response:

Accepted.

Installation:

Installed as requested.

4.609: IBM comment from George Penokie (Editorial)

Page 81 - section c.1 - The statement 'The following sections...' should be 'This annex...'

Response:

Accepted.

Installation:

Installed as requested.

4.610: IBM comment from George Penokie (Editorial)

Page 81 - section c.1 - The note should be removed and all obsolete information placed in one place in the front of the standard.

Response:

Accepted.

Installation:

Note was deleted.

PDF Page 99

4.611: IBM comment from George Penokie (Editorial)

Page 83 - section c.1.6 - The term 'intermediate status' should be 'INTERMEDIATE status'.

Response:

Accepted.

Installation:

Installed as requested.

PDF Page 105

4.612: IBM comment from George Penokie (Editorial)

Page 88 - section d.1 - The statement '...SCSI devices conforming to this profile.' is not correct. It should be '...SCSI devices conforming to the FCP-2.'.

Response:

Accepted.

Installation:

The preferred wording is “this standard”.

4.613: IBM comment from George Penokie (Editorial)

Page 88 - section d.1 - table d.1 - There is not reference to this table. One needs to be added.

Response:

Accepted.

Installation:

Installed as requested.

4.614: IBM comment from George Penokie (Editorial)

Page 88- 102 - section d.1 - figure d.x - The titles of these figures is at the top of the figure, it should be moved to the bottom of the figure.

Response:

Accepted.

Installation:

Throughout the document, figure and table titles are above the corresponding figures and tables. No change was made.

4.615: IBM comment from George Penokie (Editorial)

Page 89 - figure d.1 - What does the term 'None:' mean? Is it a typo that should be 'Note:' or does it mean 'No error recover'? whichever it is it should be made clear.

Response:

Accepted.

Installation:

Installed as requested.

4.616: IBM comment from George Penokie (Editorial)

Page 92 - figure d.4 - What does the term 'None:' mean? Is it a typo that should be 'Note:' or does it mean 'No error recover'? whichever it is it should be made clear.

Response:

Accepted.

Installation:

Installed as requested.

PDF Page 110

4.617: IBM comment from George Penokie (Editorial)

Page 94 - figure d.6 - What does the term 'None:' mean? Is it a typo that should be 'Note:' or does it mean 'No error recover'? whichever it is it should be made clear.

Response:

Accepted.

Installation:

Installed as requested.

PDF Page 111

4.618: IBM comment from George Penokie (Editorial)

Page 95 - figure d.7 - The '(' and ')' should be deleted.

Response:

Accepted.

Installation:

Installed as requested.

PDF Page 112

4.619: IBM comment from George Penokie (Editorial)

Page 96 - figure d.8 - The '(' and ')' should be deleted.

Response:

Accepted.

Installation:

Installed as requested.

PDF Page 115

4.620: IBM comment from George Penokie (Editorial)

Page 99 - figure d.11 - What does the term 'None:' mean? Is it a typo that should be 'Note:' or does it mean 'No error recover'? whichever it is it should be made clear.

Response:

Accepted.

Installation:

Installed as requested.

PDF Page 116

4.621: IBM comment from George Penokie (Editorial)

Page 100 - figure d.12 - What does the term 'None:' mean? Is it a typo that should be 'Note:' or does it mean 'No error recover'? whichever it is it should be made clear. There is not space between the 1st and 2nd sentences.

Response:

Accepted.

Installation:

Installed as requested.

PDF Page 119

4.622: IBM comment from George Penokie (Editorial)

Page 103 - section e.1 - The statement '...count (FCP_DL - FCP_RESID)...' should be '...count (i.e., FCP_DL - FCP_RESID)...'

Response:

Accepted.

Installation:

Installed as requested.

4.623: IBM comment from George Penokie (Editorial)

Page 103 - section e.1 - The statement '...Initiator will use the...' should be '....initiator uses the...'. You cannot state a requirement in an informative annex.

Response:

Accepted.

Installation:

Installed as requested.

4.624: IBM comment from George Penokie (Editorial)

Page 103 - section e.1 - The statement '...Initiator can detect that...' should be '... initiator detects that...'

Response:

Accepted.

Installation:

Installed as requested.

4.625: IBM comment from George Penokie (Editorial)

Page 103 - section e.1 - table e.1 - This table is not referenced from anywhere. This must be fixed.

Response:

Accepted.

Installation:

Installed as requested.

4.626: IBM comment from George Penokie (Editorial)

Page 103 - section e.2 - The text between e.2 and e.2.1 is hanging.

Response:

Accepted.

Installation:

Installed as requested.

4.627: IBM comment from George Penokie (Editorial)

Page 103 - section e.2 - The statement '...example in Figure e.1 -on page 105,...' should be '...example in figure E.1, ...'.

Response:

Accepted.

Installation:

Installed as requested.

4.628: IBM comment from George Penokie (Editorial)

Page 103 section e.2 - The terms '3000' and '1000' should be '3 000' and '1 000'.

Response:

Accepted.

Installation:

Installed as requested.

4.629: IBM comment from George Penokie (Editorial)

Page 103 - section e.2 - The statement '... Fixed bit set and...' should be '....FIXED bit set to 1 and...'.

Response:

Accepted.

Installation:

Installed as requested.

4.630: IBM comment from George Penokie (Editorial)

Page 103 - section e.2 - The term 'transfer length' should be in small caps.

Response:

Accepted.

Installation:

Installed as requested.

4.631: IBM comment from George Penokie (Editorial)

Page 103 - section e.2 - The statement '(fixed-length block count)' should either be '(i.e., fixed-length block count)' or deleted.

Response:

Accepted.

Installation:

Installed as requested.

4.632: IBM comment from George Penokie (Editorial)

Page 103 - section e.2.1 - There is something very wrong with this section. Although the sentences appear to be complete taken one at a time when put together they do not make any sense. This section needs to be rewritten to make it clear as to what is going on.

Response:

Accepted.

Installation:

I have rewritten this example, but I feel that the entire annex is very suspect and should be deleted. It makes assumptions about device behaviors that are well outside the norm and should not be legitimized by such an annex. In particular, the assumption in figure E.1 that host adapters cannot determine that an RO or SEQ_CNT was missing seems very unlikely. That case also states incorrectly an assumption that a "Complete" exchange can be retried. The case in figure E.2 corresponds very closely to the normal behavior described in the previous annex. For now, I am removing the annex from revision 5 and publishing it as a separate document, pending approval for that action in the T10 meetings.

4.633: IBM comment from George Penokie (Editorial)

Page 103 - section e.2.1 - The term '36000' must be '36 000'.

Response:

Accepted.

Installation:

Installed as requested.

4.634: IBM comment from George Penokie (Editorial)

Page 103 - section e.2.1 - The statement '...count (FCP_DL - FCP_RESID)...' should be '...count (i.e., FCP_DL - FCP_RESID)...'

Response:

Accepted.

Installation:

Installed as requested.

PDF Page 120

4.635: IBM comment from George Penokie (Editorial)

Page 104 - section e.2.2 - The statement '...know which of the...' should be '...know if any of the...'

Response:

Accepted.

Installation:

Installed with editorial modifications.

4.636: IBM comment from George Penokie (Technical)

(T) - Page 104 - section e.2.2 - If untagged queuing is made obsolete then the following sentences and other like it should be deleted. 'For an unqueued Target it would not have asked for an explicit FCP_CONF_REQ in this FCP_RSP with good status. Rather, it would be waiting for an implicit confirm (next command from the same Initiator).'

Response:

Rejected. See 4.322.

Installation:

No change is required.

4.637: IBM comment from George Penokie (Editorial)

Page 104 - section e.2.2 - The statement '...is needed it will not...' should be changed to '...is needed it does not...'.

Response:

Accepted.

Installation:

Installed as requested.

4.638: IBM comment from George Penokie (Editorial)

Page 104 - section e.2.2 - The statement '...Initiator will instead issue...' should be '...initiator instead issues...'.

Response:

Accepted.

Installation:

Installed as requested.

4.639: IBM comment from George Penokie (Editorial)

Page 104 - section e.2.2 - The statement '...the Exchange Completion bit of Complete, and the Sequence Initiative bit indicating...' should be '...the EXCHANGE COMPLETION bit set to 1(?) to indicate completion and the SEQUENCE INITIATIVE bit set to 1(?) to indicate...'.

Response:

Accepted.

Installation:

These values are referenced codes from FC-FS. The text is modified accordingly.

4.640: IBM comment from George Penokie (Editorial)

Page 104 - section e.2.2 - The term 'data transfer count' should be in small caps in 2 places.

Response:

Accepted.

Installation:

Installed as requested.

4.641: IBM comment from George Penokie (Editorial)

Page 104 -section e.2.2 - The term '36000' should be '36 000' in 2 places.

Response:

Accepted.

Installation:

Installed as requested.

4.642: IBM comment from George Penokie (Editorial)

Page 104 - section e.2.2 - The statement '...the Exchange Completion bit of Open, and the Sequence Initiative bit indicating...' should be '...the EXCHANGE COMPLETION bit set to 0(?) to indicate open and the SEQUENCE INITIATIVE bit set to 0(?) to indicate...'.

Response:

Accepted.

Installation:

Installed with minor editorial changes.

4.643: IBM comment from George Penokie (Editorial)

Page 104 - section e.2.2 - The statement '...reason code hex '09' (unable to perform command request)...' should be '...reason code of UNABLE TO PERFORM COMMAND REQUEST...'.
Response:

Accepted.

Installation:

Changed to meet FC-FS conventions.

4.644: IBM comment from George Penokie (Editorial)

Page 104 - section e.2.2 - The statement '...recovery will be necessary.' should be '...recovery becomes necessary.'
Response:

Accepted.

Installation:

Chose to use "recovery is necessary".

4.645: IBM comment from George Penokie (Editorial)

Page 104 - section e.2.2 - The statement '...Initiator will send a Sequence...' should be '...initiator sends a sequence...'.
Response:

Accepted.

Installation:

Installed as requested.

4.646: IBM comment from George Penokie (Editorial)

Page 104 - section e.2.2 - The statement '...payload will have the...; should be '...payload has the...'.
Response:

Accepted.

Installation:

Installed as requested.

4.647: IBM comment from George Penokie (Editorial)

Page 104 - section e.2.2 -The term 'relative offset' should be in small caps.
Response:

Accepted.

Installation:

Installed as requested.

4.648: IBM comment from George Penokie (Editorial)

Page 104 - section e.2.2 - The statement 'This will request...' should be 'This requests...'.
Response:

Accepted.

Installation:

Installed as requested.

4.649: IBM comment from George Penokie (Editorial)

Page 104 - section e.2.2 - The statement '...the FCP_RSP will also be retransmitted.' should be '...the FCP_RDP is also retransmitted.'.

Response:

Accepted.

Installation:

Installed as requested.

4.650: IBM comment from George Penokie (Editorial)

Page 104 - section e.2.2 - The statement '...Initiator has to use Relative...' should be '...initiator uses relative...'.

Response:

Accepted.

Installation:

Installed as requested.

4.651: IBM comment from George Penokie (Editorial)

Page 104 - section e.2.2 - The statement '...Target will then transfer...' should be '...target then transfers...'.

Response:

Accepted.

Installation:

Installed as requested.

4.652: IBM comment from George Penokie (Editorial)

Page 104 - section e.2.2 - The statement '...and then transmit...' should be '...and then transmits...'.

Response:

Accepted.

Installation:

Installed as requested.

4.653: IBM comment from George Penokie (Editorial)

Page 104 - section e.2.2 - The statement '...field will be the same...' should be '...field is the same...'.

Response:

Accepted.

Installation:

Installed as requested.

4.654: IBM comment from George Penokie (Editorial)

Page 104 - section e.2.3 - This section needs to be rewritten as it has several problems. I suggest the following rewrite: 'This method is easy to implement but errors are only detected after the FCP_RSP is processed and then all the data has to be retransmitted. This causes a large performance hit because the media is repositioned and reread. Initiators that only implement this type of discovery should limit the number of blocks transferred in one command in case Link Level recovery is required.'.

Response:

Accepted in principle. The section will be clarified and rewritten.

Installation:

Installed as requested.

4.655: IBM comment from George Penokie (Editorial)

Page 104 - section e.2.2 - The statement '...queued Target, it will generate...' should be '...queued target, it generates...'.

Response:

Accepted.

Installation:

Installed as requested.

PDF Page 121

4.656: IBM comment from George Penokie (Editorial)

Page 105 - 108 - section e.2.3 - figure e.x - The figure title should be after the figure not before.

Response:

Accepted.

Installation:

All figure and table titles in the document are above the figure.

PDF Page 122

4.657: IBM comment from George Penokie (Editorial)

Page 106 - section e.3 - All the comments made on section e.2 also apply to this section.

Response:

Accepted.

Installation:

Installed as requested.

4.658: IBM comment from George Penokie (Editorial)

Page 106 - section e3.1 - There is something very wrong with this section. Although the sentences appear to be complete taken one at a time when put together they do not make any sense. This section needs to be rewritten to make it clear as to what is going on.

Response:

Accepted.

Installation:

The example was rewritten. Note that this case is very similar to figure D.19 in Annex D, but takes a different and equally optional recovery process. I have removed this along with the rest of Annex E. If anyone has a deep love for this, I would propose including it as a second figure right after figure D.19 in Annex D. Otherwise, I will simply leave it out.

4.659: IBM comment from George Penokie (Editorial)

Page 106 - section e.3.2 - The statement '... Target, it will generate...' should be '...target, it generates...'.

Response:

Accepted.

Installation:

Installed as requested.

4.660: IBM comment from George Penokie (Editorial)

Page 106 - section e.3.2 - The statement '...the Exchange Completion bit of Open, and the Sequence Initiative bit indicating...' should be '...the EXCHANGE COMPLETION bit set to 0(?) to indicate open and the SEQUENCE INITIATIVE bit set to 0(?) to indicate...'.
Response:

Accepted.

Installation:

Installed with editorial modifications.

4.661: IBM comment from George Penokie (Editorial)

Page 106 -section e.3.2 - The term '36000' should be '36 000'.
Response:

Accepted.

Installation:

Installed as requested.

4.662: IBM comment from George Penokie (Editorial)

Page 106 - section e.3.2 - The term 'data transfer count' should be in small caps in two places.
Response:

Accepted.

Installation:

Installed as requested.

4.663: IBM comment from George Penokie (Editorial)

Page 106 - section e.3.2 - The statement '...field will indicate...' should be '...field indicates...'.
Response:

Accepted.

Installation:

Installed as requested.

4.664: IBM comment from George Penokie (Editorial)

Page 106 - section e.3.2 - The statement '...point which may...' should be '....point that may...'.
Response:

Accepted.

Installation:

Installed as requested.

4.665: IBM comment from George Penokie (Editorial)

Page 106 - section e.3.2 - The statement '...Initiator can proceed...' should be '...initiator may proceed...'.
Response:

Accepted.

Installation:

Elected to use "initiator proceeds".

4.666: IBM comment from George Penokie (Editorial)

Page 106 - section e.3.2 - The statement '...recovery will be necessary.' should be '...recovery is necessary.'.
Response:

Accepted.

Installation:

Installed as requested.

4.667: IBM comment from George Penokie (Editorial)

Page 106 - section e.3.3 - OK, I give up trying to note all the wills, cans, and musts that are in the section. All wills, cans, and musts must be removed and none can be replaced with a 'shall'.

Response:

Accepted.

Installation:

Installed as requested.

4.668: IBM comment from George Penokie (Editorial)

Page 106 - section e.3.2 - The term 'relative offset' needs to be in small caps when it is the name of a field.

Response:

Accepted.

Installation:

Installed as requested.

4.669: IBM comment from George Penokie (Editorial)

Page 106 - section e.2.3 - The term '15000' must be '15 000' and '16000' must be '16 000'.

Response:

Accepted.

Installation:

Installed as requested.

4.670: IBM comment from George Penokie (Editorial)

Page 106 - section e.3.2 - The statements between the () must begin with 'i.e.,' in two places.

Response:

Accepted.

Installation:

Installed as requested.

4.671: IBM comment from George Penokie (Editorial)

Page 106 - section e.3.3 - The statement 'The Target must be prepared...' should be 'The target is prepared...'

Response:

Accepted.

Installation:

Installed as requested.

4.672: IBM comment from George Penokie (Editorial)

Page 106 - section e.3.3 - The statement '...it must be capable of ignoring...' should be '...it ignores...'

Response:

Accepted.

Installation:

Installed as requested.

4.673: IBM comment from George Penokie (Editorial)

Page 106 - section e.3.3 - The statement '...it must be capable of setting up...' should be 'it sets up...'.

Response:

Accepted.

Installation:

Installed as requested.

4.674: IBM comment from George Penokie (Editorial)

Page 106 - section e.3.3 - The term 'which' should be 'that' in 2 places.

Response:

Accepted.

Installation:

Installed as requested.

4.675: IBM comment from George Penokie (Editorial)

Page 106 - section e.3.3 - There is no indication as to what an 'after status mode' is or where it is defined. This must be corrected.

Installation:

Mode is removed and text used to describe it for both modes referenced in this annex.

PDF Page 123

4.676: IBM comment from George Penokie (Editorial)

Page 107 - section e.3.3 - The sentence 'This method of recovery detects the error much sooner.' does not tell you much sooner that what?

Response:

Accepted.

Installation:

Installed as requested.

4.677: IBM comment from George Penokie (Editorial)

Page 107 - section e.3.3 - The sentence ' Only the data starting at the error must be retransmitted.' seems to be missing something when taking both this sentence and the one before it. It seem like there should only be one sentence with a 'because' between them.

Response:

Accepted.

Installation:

Rewritten significantly.

4.678: IBM comment from George Penokie (Editorial)

Page 107 - section e.3.3 - The statement '...media must be...' should be '...media is...'.

Response:

Accepted.

Installation:

Installed as requested.

PDF Page 125

4.679: IBM comment from George Penokie (Editorial)

Page 109 - section f.1 - The statement '...procedure shall also...' should be 'procedure also...' cannot have requirements in informative information.

Response:

Accepted.

Installation:

Installed as requested. Note that the sentence was wrong in the first place and needed to be corrected.

4.680: IBM comment from George Penokie (Editorial)

Page 109 - section f.1- f.1.1 - f.1.2 - There are several terms in this section that have no definition or reference to a definition. These are: name server, fabric controller, state change notification, WWNN, and WWPN.

Response:

Accepted.

Installation:

Partially resolved by another comment. Some of these are standard Fibre Channel words. WWNN and WWPN are replaced. Name Server is added to the glossary. Fabric Controller is referenced.

4.681: IBM comment from George Penokie (Editorial)

Page 109 - section f.1.1 - item 1 and 7 - section f.1.2 - item 2 - There is a statement 'if needed'. How I determine if the entry is needed or not?

Response:

Accepted.

Installation:

You cannot. It is always needed unless it has already been completed or unless it is implicitly completed. The text is deleted. The text is further watered down to indicate that none of the actions are mandatory and that any may be done by mechanisms outside the standard.

The discovery list was extensively modified because it was incomplete and incorrect.

4.682: IBM comment from George Penokie (Editorial)

Page 109 - section f.1.1 - item 8 - section f.1.2 item 4 - The statement '...EVPD bit set for...' should be '...EVPD bit set to 1 for...'.

Response:

Accepted.

Installation:

Installed as requested.

4.683: IBM comment from George Penokie (Editorial)

Page 109 - section f.1 - The information between f.1 and f.1.1 is hanging.

Response:

Accepted.

Installation:

Installed as requested.

4.684: IBM comment from George Penokie (Editorial)

Page 109 - section f.1.1 - The terms 'domain_ID_scope' and 'area_id_scope' are field names and should be in small caps.

Response:

Accepted.

Installation:

These are defined in FC-GS-3 by an alternate convention. No change was made.

4.685: IBM comment from George Penokie (Editorial)

Page 109 - section f.1.2 - item 1 - The '(' and ')' should be removed and the two statements merged into one sentence.

Response:

Accepted.

Installation:

Installed as requested.

4.686: IBM comment from George Penokie (Editorial)

Page 109 - 110 - section f.2 - There are many 'shall's in this section. They all have to be removed from this informative annex.

Response:

Accepted.

Installation:

Installed as requested.

4.687: IBM comment from George Penokie (Editorial)

Page 109 - 110 - section f.2- f.1.1 - f.1.2 - There are several terms in this section that have no definition or reference to a definition. These are: fabric port name, fabric name, loop fabric address, FAN, port name, node name, address identifier

Response:

Accepted.

Where necessary, these are defined, but in general they are defined by reference to the defining document.

PDF Page 127

4.688: IBM comment from George Penokie (Editorial)

Page 111 - section g.2 - The statement ' ... in figure g.1.' should be '...in table g.1.'.

Response:

Accepted.

Installation:

Installed as requested.

4.689: IBM comment from George Penokie (Editorial)

Page 111-113 - section g.x - table g.x - The text in the cells is touching the top lines of the cells. There needs to be space added there.

Response:

Accepted.

Installation:

Installed as requested.

4.690: IBM comment from George Penokie (Editorial)

Page 111 - table g.1 - The term 'FFFF h' should be 'FFFFh'.

Response:

Accepted.

Installation:

Installed as requested.

4.691: IBM comment from George Penokie (Editorial)

Page 111 - table g.1 - It would be helpful if the bit positions for the Sequence context (bit 23) and the sequence initiative (bit 16) were placed into the sub-field description.

Response:

Accepted.

Installation:

After review, it looked safer to leave the bit positions documented in FC-FS. They were labeled as bits and verified to have the proper spelling.

4.692: IBM comment from George Penokie (Editorial)

Page 111 - section g.2 - All the information between g.1 and g.2.1 is hanging.

Response:

Accepted.

Installation:

Installed as requested.

4.693: IBM comment from George Penokie (Technical)

(T) Page 111 - section g.2 - The statement 'The SCSI initiator or SCSI target may transmit...' should be changed to 'The SCSI initiator may transmit...'. This goes along with the other comments on restricting ABTS to initiators.

Response:

Rejected. See 4.538.

Installation:

No change is required.

PDF Page 128

4.694: IBM comment from George Penokie (Editorial)

Page 112 - table g.2- table g.3 - It would be helpful if the bit positions for the Last_sequence (bit 20) and the sequence context (bit 22) were placed into the sub-field description.

Response:

Accepted.

Installation:

It seemed safer to leave these defined by FC-FS. They were identified as bits and their spelling was checked against FC-FS.

4.695: IBM comment from George Penokie (Editorial)

Page 112 - table g.2 - Change '00 h', '80 h', '0000 h', and 'FFFF h' to '00h', '80h', '0000h' and 'FFFFh'.

Response:

Accepted.

Installation:

Installed as requested.

4.696: IBM comment from George Penokie (Editorial)

Page 112 - section g.2.1 - The statement ' ... in figure g.2.' should be '...in table g.2.'

Response:

Accepted.

Installation:

Installed as requested.

4.697: IBM comment from George Penokie (Editorial)

Page 112 - section g.2.1 - The statement ' ... in figure g.3.' should be '...in table g.3.'

Response:

Accepted.

Installation:

Installed as requested.

4.698: IBM comment from George Penokie (Editorial)

Page 112 - section G.2.2 - The statement 'When it does so, the...' should be 'When it does, the...'

Response:

Accepted.

Installation:

Installed as requested.

PDF Page 129

4.699: IBM comment from George Penokie (Editorial)

Page 113 - section g.2.3 - The statement ' ... in figure g.4.' should be '...in table g.4.'

Response:

Accepted.

Installation:

Installed as requested.

4.700: IBM comment from George Penokie (Editorial)

Page 113 - section g.2.3 - The statement '...Target shall respond with ACC.' should be '...target responds with ACC.'

Response:

Accepted.

Installation:

Installed as requested.

4.701: IBM comment from George Penokie (Editorial)

Page 113 - table g.4 - The term 'FFFF h' should be 'FFFFh'.

Response:

Accepted.

Installation:

Installed as requested.

PDF Page 131

4.702: IBM comment from George Penokie (Editorial)

Page 115 - section H - The statement '...it shall wait until...' should be 'it waits until...'.

Response:

Accepted.

Installation:

Installed as requested. (In 9.4)

4.703: IBM comment from George Penokie (Editorial)

Page 115 - The statement - '... it can return...' should be 'it may return...'.

Response:

Accepted.

Installation:

Installed as requested. (In 9.4)

4.704: IBM comment from George Penokie (Editorial)

Page 115 - The statement '...Target shall return...' should be '...target returns...'.

Response:

Accepted.

Installation:

Installed as requested. (In 4.2)

4.705: IBM comment from George Penokie (Editorial)

Page 115 - The statement 'as required by NCITS 1157-D.' should be '(see SAM-2)'.

Response:

Accepted.

Installation:

Installed as requested. (In 4.2)

4.706: IBM comment from George Penokie (Editorial)

Page 115 - The statement '...Target shall respond...' should be '...target responses...'.

Response:

Accepted.

Installation:

Installed as requested. (In 4.10)

4.707: IBM comment from George Penokie (Editorial)

Page 115 the statement '...reason code “unable to perform command request” and reason explanation “insufficient resources to support Login” as required by NCITS 1311-D.' should be '...a reason code of UNABLE TO PERFORM COMMAND REQUEST and a reason explanation of INSUFFICIENT RESOURCES TO SUPPORT LOGIN (see FC-FS).

Response:

Accepted.

Installation:

Installed with capitalization modifications. (In 4.10)

4.708: IBM comment from George Penokie (Editorial)

Page 115 - The statement '..outside the scope of this profile...' should be '...outside the scope of the standard...'.

Response:

Accepted.

Installation:

Installed as requested. (In 4.10)

PDF Page 133

4.709: IBM comment from George Penokie (Editorial)

Page 117 - The terms 'SCSI Target Reset, Logical Unit Reset, and Clear Task Set' should be all caps.

Response:

Accepted.

Installation:

Annex I is deleted. See 9.145 Sun 145.

4.710: IBM comment from George Penokie (Editorial)

Page 117 - The statement 'The payload shall be zeros...; should be 'The payload is zeros...'.
Response:

Accepted.

Installation:

Annex I is deleted. See 9.145 Sun 145.

4.711: IBM comment from George Penokie (Editorial)

Page 117 - The statement '...(which shall be set equal to 8)...' should be '...(set to 8h)...'.
Response:

Accepted.

Installation:

Annex I is deleted. See 9.145 Sun 145.

4.712: IBM comment from George Penokie (Editorial)

Page 117 - The statement '...Initiators (an FCP_RSP...)' should be '...initiators (e.g., an FCP_RSP...'.
Response:

Accepted.

Installation:

Annex I is deleted. See 9.145 Sun 145.

4.713: IBM comment from George Penokie (Editorial)

Page 117 - The terms 'refer to' should be 'see'.
Response:

Accepted.

Installation:

Annex I is deleted. See 9.145 Sun 145.

PDF Page 135

4.714: IBM comment from George Penokie (Editorial)

Page 119 - section j.1.3 - table h.1 - The terms '1000' , '1001' and '1111' should be '1000b', '1001b', and '1111b'.
Response:

Accepted.

Installation:

Annex J is deleted.

4.715: IBM comment from George Penokie (Editorial)

Page 119 - The statement 'service parameters are invalid' should be in all caps.

Response:

Accepted.

Installation:

Annex J is deleted. The change is installed in FC-FS, without all caps.

4.716: IBM comment from George Penokie (Editorial)

Page 119 - The statement '...an “Invalid Service Parameters” response code of 1000 agree upon.' should be '...an INVALID SERVICE PARAMETERS response code of SERVICE PARAMETERS ARE INVALID agreed to.'

Response:

Accepted.

Installation:

Annex J is deleted.

4.717: IBM comment from George Penokie (Editorial)

Page 119 - section j.1 - The statement '...this document effect text presently standardized in FC-PH-2 which will be corrected...' is nice but cannot be enforced by this standard and should be change to '...this annex effect text presently standardized in other standards that may be corrected in future versions of those standards.'

Response:

Accepted.

Installation:

Annex J is deleted.

4.718: IBM comment from George Penokie (Editorial)

Page 119 - section j.1 - The text between j.1 and j.1.1 is hanging.

Response:

Accepted.

Installation:

Annex J is deleted.

4.719: IBM comment from George Penokie (Editorial)

Page 119 - section j.1.1 - The section has to be deleted. You cannot call out section in another standard and this not only does that it states a specific page.

Response:

Accepted.

Installation:

Annex J is deleted.

4.720: IBM comment from George Penokie (Editorial)

Page 119 - section j.1.2 - The statement 'FC-PH-2 21.11.1.2 incorrectly...' must be changed to 'FC-PH-2 incorrectly...'.

Response:

Accepted.

Installation:

Annex J is deleted.

4.721: IBM comment from George Penokie (Editorial)

Page 119 - section j.1.2 - The statement 'I believe the wording of Annex A of FCP is better, where it says:...' should be 'The wording in annex A of FCP-2 is correct, where it states:...'

Response:

Accepted.

Installation:

Annex J is deleted.

4.722: IBM comment from George Penokie (Editorial)

Page 119 - section j.1.2 - The following sentences cannot be enforced and should be removed: 'All these corrections must be installed in FC-FS.'

Response:

Accepted.

Installation:

Annex J is deleted.

4.723: IBM comment from George Penokie (Editorial)

Page 119 - section j.1.2 - The following sentence, after the section number is removed, restates what was in the first sentence of this section so it should be deleted : Delete 'The same error is repeated in FC-PH-2, section 21.11.1.3.'

Response:

Accepted.

Installation:

Annex J is deleted.

4.724: IBM comment from George Penokie (Editorial)

Page 119 - annex j - I believe this entire annex should be deleted as it is not relevant to this standard. But if it is to stay then the changes indicated below are necessary.

Response:

Accepted.

Installation:

Annex J is deleted.

4.725: IBM comment from George Penokie (Editorial)

Page 119 - section j.1.3 - The sentence 'The document should replace the last line in Table 118 (PRLI accept response code) and Table 123 (PRLO accept response code) with the following two lines:' needs to be replaced with 'The additional PRLI (PRLO) should be placed into the FC-FS standard as indicated in table H.1.'

Response:

Accepted in principle. The annex will be deleted.

Installation:

Annex J is deleted.

PDF Page 136

4.726: IBM comment from George Penokie (Editorial)

Page 120 - section j.2.1 - The sentences list here are editorial and have not place in a standard. They needs to be deleted. 'This value rather meaninglessly requires that a target shall transfer all data for a command and complete the command within a single interconnect tenancy. I believe that 95-348r1 is correct and FC-PLDA is incorrect and have taken this approach in FCP-2.

Response:

Accepted in principle. The annex will be deleted.

Installation:

Annex J is deleted.

4.727: IBM comment from George Penokie (Editorial)

Page 120 - section j.1.5 - The following statement implies something can be removed from a standard after it is processed, this is not the case and the sentence should be removed. 'Section 6.2.5 will be removed when FC-FS has been updated.'

Response:

Accepted in principle. The annex will be deleted.

Installation:

Annex J is deleted.

PDF Page 137

4.728: IBM comment from George Penokie (Editorial)

Page 121 - Why is there a list of figures at the end of the document? They should be in the front of the document not at the end.

Response:

Accepted. This was an error in assembly of the document.

Installation:

Installed as requested.

5 Comments from LSI Logic

The following comments accompanied the ballot from LSI Logic Corporation, prepared by Charles Binford.

5.1 LSI 01: (Editorial)

Page 13 / PDF 29 Section 4.8, Table 4 Cmt Name: Column Order (This is a very minor comment and may be ignored at the editor's discretion.) I believe the readability of the table will be enhanced if the columns were reordered such that actions that had very similar effects where grouped together. Specifically, I suggest moving: - SCSI Logical Unit Reset column to the right of SCSI Target Reset - ABTS w/Last Seq. to the far right hand side.

Response:

Accepted in principle. Will be reviewed.

This resolution was accepted in the June 7, 2000 working group meeting.

Installation:

Installed as requested.

5.2 LSI 02: (Editorial)

Page 13 / PDF 29 Section 4.8, Table 4 Cmt Name: Row alignment (This is a very minor comment and may be ignored at the editor's discretion.) The 'Y's and 'N's of the 'Open FCP Sequences Terminated' rows don't line up well with the descriptions.

(my other comments have a bit more meat to them, really!)

Response:

Accepted.

Installation:

Installed as requested.

5.3 LSI 03: (Editorial)

Page 13 / PDF 29 Section 4.8, Table 4 Cmt Name: Placement of note 12 label The 'N' and 'Y' of the SCSI Target mode page/PRLI-PRLO box reference note 12. I believe that note 12 is applicable to the entire row (not just this specific box) and would be better placed in the row description.

Response:

Accepted.

Installation:

Installed as requested.

5.4 LSI 04: (Technical)

Page 13 / PDF 29 Section 4.8, Table 4 Cmt Name: Wrong value for table entry The value at: row: Prevent Allow Medium Removal / Only for SCSI Initiator port initiating action column: LOGI,PLOGI is currently 'N', it should be 'Y'

Response:

Accepted. This was accepted in the April 5, 2000 meeting.

Installation:

Installed as requested.

5.5 LSI 05: (Editorial)

Page 18 / PDF 34 Section 5.4 Cmt Name: Bad reference The reference to annex B in the first paragraph should be to annex C.

Response:

Accepted.

Installation:

Installed as requested.

5.6 LSI 06: (Technical)

Page 18 / PDF 34 Section 5.4, Table 8 Cmt Name: Obsolete IU T7 The T7 IU is never used and should be marked obsolete. Even if the *initial* xfer-rdy is suppressed with the PRLI bit, each Data-Out is *followed* by an xfer-rdy or status, thus T6 which transfers SI is all that is needed. (Note, a global search for T7 needs to be made, e.g. section 9.3)

Response:

Accepted. This was accepted in the April 5, 2000 meeting.

Installation:

Installed as requested.

5.7 LSI 07: (Technical)

Page 24 / PDF 40 Section 6.2.5, 2nd paragraph Cmt Name: Misleading PRLI requirement At the end of the second paragraph of this section the statement is made that 'Subsequent PRLI operations shall have no effect on FCP operation between two devices except where new requirements are negotiated between the devices.' I hope this is trying to say there is no effect if an image pair is not established by the PRLI. It sounds like the initiator and target are supposed to compare previous setting to current settings and only apply Table 4 if there are any

differences. This would be a mistake. Any PRLI (whether the 1st or the 10th) that has the establish image pair bit should cause the target to 'reset' that initiator's FCP operation as detailed in Table 4 under the PRLI column.

Response:

Accepted in principle. See 1.22. The changes to 1.22 were agreed upon at the April 5, 2000 meeting.

Installation:

Installation of 1.22 should fix this.

5.8 LSI 08: (Technical)

Page 24 / PDF 40 Section 6.2.5, 4th paragraph Cmt Name: Incorrect ABTS requirement. The middle of the 4th paragraph of this section states that 'Non-acknowledged class responders will close the exchange with an ABTS or ABTX ELS.' This is inconsistent with 12.7 of this document and with several years worth of shipping product under PLDA (I don't think our intent for FCP-2 is to invalidate any PLDA behavior). What will really happen is the responder will discard the received frame/sequence, send a PRLO, and let the initiator send the ABTS for cleanup if it chooses.

Response:

Accepted in principle. See 1.25. This response was accepted in the April 5, 2000 meeting.

Installation:

See 1.48.

5.9 LSI 09: (Technical)

Page 29 / PDF 45 Section 6.3 Cmt Name: Multiple Image Pair behavior The last sentence of the first paragraph states 'If any image pairs between the initiator and the host remain after the PRLO, then there is no clearing effect on any task, reservation, mode page parameter or status.' This would make sense to me if the phrase 'for those remaining image pairs' was added to the end of this sentence. The current wording sounds like nothing is cleared until all image pairs are PRLO'd, I don't think that is the intent.

Response:

This comment had originally been accepted. After further discussion in the April 5, 2000 meeting, the acceptance was reconsidered and the comment rejected.

The committee agreed that Process Associators could be removed from FCP-2 if we allow initiator aliasing to instantiate multiple logical initiators behind a single port. Such initiator aliasing would be transparent to FCP-2. This would require more logins during the initialization activity. N_Ports operating in OLD PORT mode would normally not support this capability. A change to FC-FS is required, but no proposal is presently contemplated for this. At the June 7, 2000 working group meeting, it was decided that the text needs to be carefully reviewed for this case.

Installation:

The removal of Process_Associators corrected this issue.

5.10 LSI 10: (Editorial)

Page 30 / PDF 46 Section 7.2, 2nd paragraph Cmt Name: Need to specify which LUN The second paragraph specifies the Inquiry data should be the object supplied. Words should be added to indicate it should be the Inquiry data for LUN 0.

Response:

Accepted.

Installation:

Rewritten by response to 8.52.

5.11 LSI 11: (Editorial)

Page 31 / PDF 47 Section 8.1 Cmt Name: Missing period The last sentence on the page is missing a period.

Response:

Accepted.

Installation:

Installed as requested.

5.12 LSI 12: (Technical)

Page 37 / PDF 53 Section 9.1.1.3 Cmt Name: Ordered Q rules The paragraph explaining Ordered_Q describes in detail the issues of delivering commands in a certain order on a class 2 fabric. If CRN is being used all of this extra work is unnecessary. Therefore I suggest words be added to indicate this is applicable if using CRN==0.

Response:

Accepted in principle. See 1.38. The committee meeting of April 5, 2000 approved this response.

Installation:

See 1.38.

5.13 LSI 13: (Editorial)

Page 43 / PDF 59 Section 9.3, 4th paragraph Cmt Name: XFER_RDY disable clarification The last sentence of the 4th paragraph implies that that *each* FCP_DATA IU is sent without a preceding XFER_RDY if XFER_RDY disable is on in PRLI. Only the *1st* FCP_DATA IU is sent without an XFER_RDY.

Response:

Accepted.

Installation:

Installed as requested.

5.14 LSI 14: (Technical)

Page 43 / PDF 59 Section 9.3, 5th paragraph Cmt Name: _UNDER should be _OVER The second to last sentence in the 5th paragraph incorrectly states the FCP_RESID_UNDER bit should be on. It should say FCP_RESID_OVER.

Response:

Accepted. The committee approved this response in the meeting of April 5, 2000.

Installation:

Installed as requested.

5.15 LSI 15: (Editorial)

Page 63 / PDF 79 Section 12.2.2 4) Cmt Name: Redundant item The 4th item under SCSI Initiator '4) a Sequence error is detected in a Sequence transmitted from a Target to an Initiator.' is redundant with item 3) in the previous classless section. There is no reason to repeat it here. It should be deleted.

Response:

Accepted.

Installation:

Changed as requested.

5.16 LSI 16: (Editorial)

Page 64 / PDF 80 Section 12.3.2, 3rd paragraph Cmt Name: spelling error Second to last sentence should read 'At a minimum interval...', not '... interval...'.

Response:

Accepted.

Installation:

Changed as requested.

5.17 LSI 17: (Technical)

Page 65 / PDF 81 Section 12.3.4 Cmt Name: Paragraph needs expanding / clarification The second paragraph from the top of the is explaining the case where the REC data is ambiguous. However it fails to mention a lost XFER_RDY as one of the cases. Here is what I believe this paragraph should cover: The REC ACC data shows the following information for more than one error case. SI at initiator, 0 or more data transferred, exchange still open. The cases are: - Lost XFER_RDY - Lost FCP_RSP with FCP_CONF requested - Lost FCP_CONF The initiator can differentiate the last two based on local data. However, the intent of the paragraph is to say the initiator can't tell the difference between the first two (for a data-out type command), so it assumes the lost XFER_RDY case and lets the target determine the proper action.

Response:

Accepted in principle. See 3.18. The committee approved this response in the meeting of April 5, 2000. Some work remains in preparing appropriate wording.

Installation:

The paragraph is changed to read:

A command that was terminated prior to transferring data by a CHECK CONDITION requesting the FCP_CONF IU may have the same REC values as a command for which an FCP_XFER_RDY IU was not received by the initiator. For a write command with a non-zero FCP_DL, the parameters for the SRR shall indicate that an FCP_XFER_RDY IU is expected from the target. The target is aware of the actual present state of the transfer and response and shall either retry the FCP_XFER_RDY IU or, if the actual data transfer length for the command was zero, retry the FCP_RSP. ~~perform the correct retry regardless of the retry suggested by the SRR ELS.~~

See also 3.18.

5.18 LSI 18: (Editorial)

Page 66 / PDF 82 Section 12.3.7 12.3.9 Cmt Name: Need new section Sections 12.3.7 and 12.3.9 both deal with target specific recovery, yet they are in the initiator specific 12.3 section. I'd suggest a new section inserted between the current 12.3 and 12.4 that covers FCP Error Recovery (Target, All classes of service). These two sections would be the contents.

Response:

Accepted.

Installation:

These areas were completely reorganized as a result of 9.103 Sun 103. I believe that corrects the issue.

5.19 LSI 19: (Technical)

Page 66 / PDF 82 Section 12.3.7 Cmt Name: Introductory paragraph needed The 4th paragraph jumps into the middle of a scenario. A paragraph is needed that describes the target sending REC to the initiator if it times out waiting on an FCP_CONF.

Response:

Accepted in principle. The committee accepted this response in the meeting of April 5, 2000.

The ladder diagrams provided by Carl Zeitler are an important contribution to this comment.

Installation:

Installed as requested.

5.20 LSI 20: (Editorial)

Page 68 / PDF 84 Section 12.5.1 Cmt Name: COMMAND CLEARED not approved yet

Although I greatly appreciate the confidence the editor has shown in my proposal to the T10 committee concerning the addition of a COMMAND CLEARED status to SAM, it is not yet approved. As such, words similar to the notes in section 9.1.1.4 would be more appropriate.

Response:

Accepted.

Installation:

COMMAND CLEARED is now approved. No additional change is required.

This resolution was approved in the September 11, 2000 working group meeting.

5.21 LSI 21: (Technical)

Page 68 / PDF 84 Section 12.5.2 b) Cmt Name: BA_RJT case stated incorrectly A target must BA_ACC an ABTS if the RX_ID is FFFFh. Item b) does not state this. I'd suggest the following words (new words marked by *). b) the SCSI Target shall return BA_RJT with Last Sequence of Exchange bit set to one if the received ABTS contains *an assigned RX_ID and* a FQXID that is unknown to the SCSI target.

Response:

Accepted. This response was approved in the April 5, 2000 meeting.

Installation:

Changed as requested.

5.22 LSI 22: (Technical)

Page 68 / PDF 84 Section 12.6 Cmt Name: Section too specific I believe the details of second level error recovery do not pose any interoperability problems and should be left to implementers, not spelled out in a standard. I don't want LSI adapters to fail compliance tests if, for example, we choose to use Abort Task Set or Target Reset as part of second- level error recovery instead of the prescribed algorithm. It would be acceptable to leave the current words if the 'shall's were turned into 'may's.

Response:

Accepted in principle. See 1.47. This response was approved in the April 5, 2000 meeting.

Installation:

This was resolved by a series of other comments. See 12.6 and 12.7.

5.23 LSI 23: (Technical)

Page 69 / PDF 85 Section 12.7, 1st paragraph Cmt Name: Need to add PRLI case. The case described in the first paragraph applies equally to PRLI as it does FCP_CMND. Either 'or PRLI' could be inserted after both occurrences of FCP_CMND in the present paragraph, or another paragraph could be added to the section.

Response:

Accepted in principle. See 1.48. This response was accepted in the April 5, 2000 meeting.

Installation:

I believe this was already covered by the second paragraph of 12.7. No change was made.

This resolution was approved in the September 11, 2000 working group meeting.

5.24 LSI 24: (Editorial)

Page 69 / PDF 85 Section 12.7, last paragraph Cmt Name: Can't have 'TBD'. Obviously a standard can not be forwarded with a 'TBD'.

Response:

Accepted.

Installation:

Deleted as requested.

5.25 LSI 25: (Technical)

Page 92-102 / PDF 108- Section Annex D Cmt Name: Misuse of Time-out symbol In many of the diagrams (e.g. D.4, D.7, D.8, etc.) the Timer symbol is used to indicate a cause and effect. For example in figure D.9, the Timer symbol shows that the REC is sent as a result of detecting a missing frame. While this information is useful, it is very confusing to use the same symbol as the Timer symbol. I'd suggest adding a new symbol the drawing conventions (Table D.1) and separate time-out from cause and effect. (The same symbol, only dotted would work nicely.)

Response:

Accepted. This response was approved in the April 5, 2000 meeting.

Actions:

Added new symbol to table D.1. New time-out symbol used in all figures of annex D.

5.26 LSI 26: (Technical)

Page 95-96 / PDF 111-112 Figures D.7, D.8 Cmt Name: Target shall not adjust RO from SRR The text in both figures D.7 and D.8 incorrectly state that the target may adjust the RO to be smaller than what is requested in SRR. These sentences should be removed.

Response:

Accepted. This response was approved in the April 5, 2000 meeting.

Actions:

Parenthetical expressions were deleted. in D.7 and D.8

5.27 LSI 27: (Technical)

Page 109-110 / PDF 125-126 Section Annex F Cmt Name: Device Identification Page references Three places in this annex (F.1.1 8., F1.2 4., and F.3) the "logical unit WWN" value returned in the Inquiry VPD page 83h is referred to as having a WW Port Name component. For the purpose of tracking a Logical Unit, one should only use Identifiers that have an Association field value of 00b. By definition, that identifier will not have a WWPN component. Also, while it is true that some devices may use their FC WWNN (node name) for the LU Identifier, it is not required. Thus any reference to "node name", "port name", (including WWNN and WWPN) should not be used. I'd suggest a generic 'Logical Unit WWN'. (Note: some devices use the Registered, Extended format which is 16 bytes long.)

Response:

Accepted in principle. This response was approved in the April 5, 2000 meeting.

Installation:

The text was rewritten significantly to address the core of this comment. The key term used was "logical unit's Worldwide_Name".

6 Comments from Seagate Technology

The following comments accompanied the ballot response from Seagate Technology, prepared by Gene Milligan. Note that some of these have been renumbered from Seagate's original numbering.

In the June 7, 2000 meeting of the working group, the balloter indicated agreement with all the accepted comments and tentative agreement with all those comments accepted in principle.

6.1: Seagate Page 8 (Editorial)

Note 1; Label: Gene Milligan; Date: 1/12/0 9:36:40 PM 1) There should not be two table ones.

Response:

Accepted.

Installation:

Installed as requested.

6.2: Seagate Page 10 (Editorial)

Note 1; Label: Gene Milligan; Date: 1/12/0 9:40:27 PM 2) In the table of contents Table F.1 is missing a title.

Response:

Accepted.

Installation:

Table F.1 does not exist and the text was corrected.

6.3: Seagate Page 13 (Editorial)

Note 1; Label: Gene Milligan; Date: 1/12/0 9:43:47 PM 3) FCP-2 is not X3.269.

Response:

Accepted.

Installation:

Installed as requested.

6.4: Seagate Page 14 (Editorial)

Note 1; Label: Gene Milligan; Date: 1/12/0 9:52:28 PM 4) Update the introduction to delete 133 Mbps and the normative references to call out a viable PH.

Response:

Accepted.

Installation:

Introduction updated as requested.

6.5: Seagate Page 14 (Editorial)

Note 2; Label: Gene Milligan; Date: 1/12/0 9:57:06 PM 5) In the text of the standard please delete revision designations.

Response:

Accepted.

Installation:

Installed as requested.

6.6: Seagate Page 15 (Editorial)

Note 1; Label: Gene Milligan; Date: 1/12/0 10:05:39 PM 4) Portions of FCP-2 that are written as if this is a revision of FCP should be re-written (e.g., delete discussion of where material that was in FCP is now. Replace second revision with -2 or version two globally.

Response:

Accepted.

Installation:

Installed as requested.

6.7: Seagate Page 15 (Editorial)

Note 2; Label: Gene Milligan; Date: 1/20/0 2:29:24 AM 7) Replace "document" with "standard" and "documents" with "standards" globally.

Response:

Accepted.

Installation:

Installed as requested.

6.8: Seagate Page 17 (Editorial)

Note 1; Label: Gene Milligan; Date: 1/20/0 2:29:32 AM 8) Either delete "FC-4" or add a reference to its definition.

Response:

Accepted.

Installation:

FC-4 was deleted.

6.9: Seagate Page 17 (Editorial)

Note 2; Label: Gene Milligan; Date: 1/20/0 2:29:42 AM 9) In scope and if elsewhere delete "approved" in the text when referring to items in FCP-2.

Response:

Accepted.

Installation:

Installed as requested. Other uses of approved are acceptable, except the title of 2.2, which was changed to "Published standard references".

6.10: Seagate Page 17 (Editorial)

Note 3; Label: Gene Milligan; Date: 1/20/0 2:29:48 AM 10) In Normative References replace "text" with "standard".

Response:

Accepted.

Installation:

Installed as requested. Other uses of the word text were verified.

6.11: Seagate Page 17 (Editorial)

Note 4; Label: Gene Milligan; Date: 1/20/0 2:39:00 AM 11) Should FC-PH-3 be called out as a normative reference? References under development needs to be updated. FC-AL-2 should not be called out as a reference in FC-AL-2. X3T10 is NCITS T10 although it may not be correctly used depending upon the update (e.g., T10 did not develop FC-PH-3.

Why would FC-AL-3 be a reference for FC-AL-2? Why is FC-TAPE a reference?

Response:

Accepted.

Installation:

FC-PH-3 was removed from the references. References under development was updated. T11 was installed in the list of developing committees. FC-AL-3 was removed as a reference. FC-TAPE is referenced because it defines some of the required timer values.

6.12: Seagate Page 18 (Editorial)

Note 1; Label: Gene Milligan; Date: 1/20/0 2:43:34 AM 12) <<Definitions, conventions, abbreviations, acronyms and symbols applicable to this standard are provided, unless they are identical to that described in any referenced standard, in which case they are included by reference. Some definitions from the glossary or body of other standards are included here for easy reference.>> The second sentence contradicts the first. Suggest using SPC-2 as a reference for this introduction.

Response:

Accepted.

Installation:

SPC-2 and SBC-2 both have no such introductory information. The material is deleted.

6.13: Seagate Page 18 (Editorial)

Note 2; Label: Gene Milligan; Date: 1/20/0 4:23:07 PM 13) Some definitions site a standard's acronym and some the number. They should be consistent and the style guides indicate that it should be name and number along with the publication year.

Response:

Accepted.

Installation:

They are consistent. The mnemonic is used.

6.14: Seagate Page 18 (Editorial)

Note 3; Label: Gene Milligan; Date: 1/20/0 4:28:38 PM 14) <<base address: The address of the lowest address byte to be transferred to or from an application client buffer.>> should be "base address: The address of the lowest addressable byte that may be transferred to or from an application client buffer." or "base address: The address of the first addressable byte that may be transferred to or from an application client's buffer."

Response:

Accepted.

Installation:

The text was changed to read "base address: The address of the byte that is transferred to or from the the lowest addressed location in the application client's buffer".

6.15: Seagate Page 18 (Technical)

Note 4; Label: Gene Milligan; Date: 1/20/0 4:44:00 PM 15) Are the FC-AL-3 definitions stable enough to include in FCP-2? Why does CMR have to be dedicated to an MCM circuit as opposed to shared? The BMCM pdf is missing probable underscores.

Response:

MCM and all related functions are now deleted from FC-AL-3, and therefore from FCP-2. This response was approved in the April 5, 2000 meeting.

Installation:

MCM functions are deleted.

6.16: Seagate Page 19 (Editorial)

Note 1; Label: Gene Milligan; Date: 1/21/0 3:59:45 PM 16) Shouldn't the data overlay definition should be for overlapping addresses not exact offsets?

Response:

Accepted.

Installation:

The new text is:

The use of random buffer access capability where data is transmitted using the same data pointer value more than one time during a data delivery action.

6.17: Seagate Page 19 (Editorial)

Note 2; Label: Gene Milligan; Date: 1/21/0 4:03:04 PM 17) Globally check for "which" to see which ones should be replaced with "that".

Response:

Accepted.

Installation:

Installed as requested. See 4.58.

6.18: Seagate Page 19 (Editorial)

Note 3; Label: Gene Milligan; Date: 1/22/0 2:54:32 PM 18) Replace the references to FC-AL with references to FC-AL-2.

Response:

Accepted.

Installation:

Installed as requested.

6.19: Seagate Page 20 (Editorial)

Note 1; Label: Gene Milligan; Date: 1/22/0 2:54:51 PM 19) Change <<The initiator-specified component>> to "An initiator-specified component". There are other components specified by the initiator.

Response:

Accepted.

Installation:

After further review, the following change was made instead.

The initiator-specified component of a task identifier that uniquely identifies one task among the several tasks coming from an initiator to a logical unit.

6.20: Seagate Page 20 (Editorial)

Note 2; Label: Gene Milligan; Date: 1/22/0 3:01:46 PM 20) Change <<[ANSI 1304-D]>> to "[NCITS 1304-D]" globally. Globally change <<this document>> to "this standard".

Response:

Accepted.

Installation:

Changes made as requested in the introduction and forward and clauses 1, 2, 3, 4, 6, 10, 12, and annex C.

6.21: Seagate Page 20 (Editorial)

Note 3; Label: Gene Milligan; Date: 1/22/0 2:56:51 PM 21) The definition of FC-PH conflicts with that of the FC-PH standard.

Response:

Accepted.

Installation:

The definition was corrected in the abbreviations area. FC-PH is no longer referenced.

6.22: Seagate Page 21 (Editorial)

Note 1; Label: Gene Milligan; Date: 1/22/0 3:00:43 PM 22) Should the dash in <<loop initialization fabric assigned - loop initialization sequence>> be "of a"? Otherwise it seems to indicate LIFA means either. Same comment for LIHA, LIPA, and LISA.

Response:

Accepted.

Installation:

The description was changed to read “loop initialization fabric assigned, a step of the loop initialization sequence (See FC-AL-2.)”

6.23: Seagate Page 21 (Editorial)

Note 2; Label: Gene Milligan; Date: 1/22/0 3:06:06 PM 23) Change <<Small Computer System Interface. Either SCSI-2 or SCSI-3.>> to "Small Computer System Interface. Either SCSI-2 or a newer SCSI standard"

Response:

Accepted.

Installation:

Changed to read “Small Computer System Interface, any revision”.

6.24: Seagate Page 21 (Editorial)

Note 3; Label: Gene Milligan; Date: 1/22/0 3:18:09 PM 24) In may and may not replace <<indicated>> with "indicates". In optional change <<this standards>> to "this standard". In reserve replace <<as error>> with "as an error".

Response:

Accepted.

Installation:

Installed as requested.

6.25: Seagate Page 21 (Editorial)

Note 4; Label: Gene Milligan; Date: 1/22/0 3:14:40 PM 25) What guidance is used to choose the label <<ignored>>, <<obsolete>>, or <<reserved>>. Two are clear in other standards but <<ignored>> causes confusion in the meanings.

Response:

Accepted.

Installation:

The definition of the word “ignored” is changed as follows:

A keyword used to describe ~~a an unused~~ bit, byte, word, field or code value ~~that shall not be. The contents or value of an ignored bit, byte, word, field or code value shall not be~~ examined by the receiving SCSI device. ~~and may be set to any value by the transmitting SCSI device The bit, byte, word, field or code value has no meaning in the specified context.~~

6.26: Seagate Page 22 (Editorial)

Note 1; Label: Gene Milligan; Date: 1/22/0 3:19:46 PM 26) In shall delete <<If such a rule is not followed, the results are unpredictable.>>

Response:

Accepted.

Installation:

This wording has been provided for some time in FC documents to express the concept that violations of mandatory behavior are not required to be explicitly checked and may create unpredictable behaviors. No change was made.

6.27: Seagate Page 22 (Editorial)

Note 2; Label: Gene Milligan; Date: 1/22/0 3:24:25 PM 27) Change <<These words and terms are defined either in or in the text where they first appear.>> to "These words and terms are defined either in the glossary or in the text where they first appear." This is the wording found in SAM-2, since the glossary is titled Definitions perhaps we could have chosen a better word (i.e., Definitions).

Response:

Accepted.

Installation:

Installed, with minor editorial adjustments.

6.28: Seagate Page 22 (Editorial)

Note 3; Label: Gene Milligan; Date: 1/22/0 3:28:12 PM 28) <<The names of fields are in small uppercase (e.g., ALLOCATION LENGTH). When a field name is a concatenation of acronyms, uppercase letter may be used for readability (e.g., NORMACA).>> is not the convention followed by other SCSI standards. The SCSI convention, followed by most but not all editors is for field names to use small uppercase. For concatenation the only convention I have noticed is underscores.

Response:

Will review these conventions with the editor of SPC-2.

This resolution was accepted in the June 7, 2000 working group meeting.

Installation:

The present text is consistent with SPC-2, the only standard referenced among the command set documents. No additional changes will be made.

6.29: Seagate Page 22 (Editorial)

Note 4; Label: Gene Milligan; Date: 1/22/0 3:32:31 PM 29) I think <<Lists sequenced by letters (e.g., a-red, b-blue, c-green) show no priority relationship between the listed items. Numbered lists (e.g., 1-red, 2-blue, 3-green) show a priority ordering between the listed items.>> should be "Lists sequenced by letters (e.g., a-red, b-blue, c-green) show no sequential preference between the listed items. Numbered lists (e.g., 1-red, 2-blue, 3-green) show a sequential ordering between the listed items.

Response:

Accepted.

Installation:

Installed with minor editorial adjustments.

6.30: Seagate Page 23 (Editorial)

Note 1; Label: Gene Milligan; Date: 1/22/0 3:40:31 PM 30) Change <<The detailed implementation that supports that stream is not defined, although originator and responder FCP_Ports are assumed to have a common service interface for use by all FC-4s that is similar in characteristics to the service interface defined in annex S of ANSI X3.230.>> to "The detailed implementation that supports the stream is not defined, although originator and responder FCP_Ports are assumed to have a common service interface, for use by all FC-4s, that is similar in characteristics to the service interface defined in annex S of ANSI X3.230." and collect a long sentence prize.

Response:

Accepted.

Installed as requested.

6.31: Seagate Page 23 (Editorial)

Note 2; Label: Gene Milligan; Date: 1/22/0 3:43:47 PM 31) Regarding <<The SCSI Common Access Method [CAM] is one example of a service interface that fulfills the requirements specified in SAM and SAM-2.>> it has been reported that CAM is SCSI-2 compliant but not SAM compliant and thus the CAM-3 project.

Response:

Accepted. Reference will be deleted.

Installation:

Deleted during rewrite for other problems.

6.32: Seagate Page 23 (Editorial)

Note 3; Label: Gene Milligan; Date: 1/24/0 2:10:24 PM 32) In Table 1 Acknowledge Command Complete is not actually a SCSI function is it? Perhaps the column title should be Function or the item should perhaps just be ACK(REQ).

Response:

Accepted.

Installation:

Installed as requested.

6.33: Seagate Page 24 (Editorial)

Note 1; Label: Gene Milligan; Date: 1/27/0 2:46:06 AM 35) Change <<until all data described by the SCSI command is transferred.>> to "until all data describing the SCSI command is transferred."

Response:

This really means the data that the SCSI command intends to transfer. The present text is correct technically, but will be clarified.

This resolution was accepted in the June 7, 2000 working group meeting.

Installation:

Clarified.

6.34: Seagate Page 24 (Technical)

Note 2; Label: Gene Milligan; Date: 1/27/0 2:49:17 AM 36) How does <<The transmission of the initial FCP_XFER_RDY IU may be disabled for those systems having other mechanisms for controlling the data transfer.>> relate to the FCP-2 standard?

Response:

This idea is necessary to indicate that burst management must be performed according to the mode select page or other conventions to prevent overflows. However, it might be possible to make the sentence a bit clearer.

After further discussion, the committee chose, in its April 5, 2000 meeting, to remove the tutorial warning on the grounds that the problem should be obvious to the casual observer. The proposal is accepted.

Installation:

This was clarified as requested in 4.60.

6.35: Seagate Page 24 (Editorial)

Note 3; Label: Gene Milligan; Date: 1/27/0 2:50:46 AM 37) <<Note: FCP_XFER_RDY on read operations is made obsolete in FCP-2.>> Where?

Response:

A forward reference to the IU where it has been removed is desirable here.

Installation:

The offending phrase was removed from here and the correction stands on its own in clause 6.

6.36: Seagate Page 24 (Editorial)

Note 4; Label: Gene Milligan; Date: 1/27/0 2:54:11 AM 38) <<if an unusual condition has been detected,>> What is an unusual condition? Is an error being referred to?

Response:

An unusual condition is a status of CHECK CONDITION. This will be rewritten.

Installation:

Installed as requested.

6.37: Seagate Page 25 (Editorial)

Note 1; Label: Gene Milligan; Date: 1/27/0 3:01:40 AM 38) Globally search on "will" & must and replace with shall or should as appropriate.

Response:

Accepted.

Installation:

Corrected in many places.

6.38: Seagate Page 25 (Editorial)

Note 2; Label: Gene Milligan; Date: 1/27/0 3:04:41 AM 39) What does <<SCSI allows the initiator function in any FCP_Port and the target function in any FCP_Port.>> mean?

Response:

It means that there is no pre-conceived architectural notion that a particular FCP_Port's Fibre Channel properties restrict it to one function or the other. This will be clarified.

Installation:

Installed as requested.

6.39: Seagate Page 25 (Editorial)

Note 3; Label: Gene Milligan; Date: 1/27/0 3:11:35 AM 39) <<For those special cases>> It is in the eye of the beholder what is special.

Response:

The text will be changed to read: "for those mundane cases" :-) Or better yet, the word special will be deleted.

Installation:

The text was clarified.

6.40: Seagate Page 25 (Editorial)

Note 4; Label: Gene Milligan; Date: 1/29/0 2:34:26 PM 40) Delete <<In many cases, SCSI communications between an application client and a device server are stateless. In such applications, verification of the delivery and execution of SCSI commands is often not critical. Any changes in execution sequence caused by link failures or switch latencies are not important and the recovery and retry mechanisms can be executed while other activities are continued by the application client and the device server.>> Search globally on <<can>> and replace with some form of "may".

Response:

Accepted.

Installation:

Installed as requested, involving many chapters.

6.41: Seagate Page 25 (Editorial)

Note 5; Label: Gene Milligan; Date: 1/29/0 2:39:30 PM 41) Change <<For those special cases where checking for the precise delivery of SCSI commands is necessary for the proper operation and error recovery of a device server, FCP-2 defines an additional optional function called precise delivery.>> to "FCP-2 defines an optional function called precise delivery."

Response:

Accepted.

Installation:

Installed as requested, but with additional tutorial information.

6.42: Seagate Page 25 (Editorial)

Note 6; Label: Gene Milligan; Date: 1/29/0 2:41:23 PM Null label.

Response:

No action.

Installation:

No action.

6.43: Seagate Page 25 (Editorial)

Note 7; Label: Gene Milligan; Date: 1/29/0 3:28:58 PM 42) <<in the CRN field for each command that is transmitted that also requires precise delivery. The integer begins with a value of one after any Target Reset, LUN Reset, or Fibre Channel Login or Process Login occurs. After the number of precisely delivered commands causes the integer to increment to 255, the integer will wrap back to a value of one.>> Delete "also". Globally search the normative clauses to replace <<will>> with "shall".

Response:

Accepted.

Installation:

Installed as requested.

6.44: Seagate Page 26 (Technical)

Note 1; Label: Gene Milligan; Date: 1/29/0 3:35:55 PM 43) Rule 5 of precise delivery either makes some special unstated assumption as to what a queue is or fails to precisely define the outcome of the command (e.g., aborted) and in 7 zero is not reserved it has the meaning of not precise delivery. Delete reserved.

Response:

Accepted. This response was approved in the April 5, 2000 meeting.

Installation:

Installed as requested.

6.45: Seagate Page 26 (Technical)

Note 2; Label: Gene Milligan; Date: 1/29/0 3:39:22 PM 44) <<Any command, including such initialization commands as INQUIRY, TEST UNIT READY, and MODE SENSE/SELECT may always use a CRN of zero if the state of the EPDC bit is not known or if precise delivery is not required for that command.>> Delete <<always>> and <<the state of the EPDC bit is not known or if>>. Regardless the result is not precise delivery.

Response:

Accepted. This response was approved in the April 5, 2000 meeting.

Installation:

Installed as requested.

6.46: Seagate Page 26 (Technical)

Note 3; Label: Gene Milligan; Date: 1/29/0 3:41:35 PM 45) <<PRLI parameters are used to determine that confirmed completion is allowed>> Is it <<allowed>> or is it "used"?

Response:

Accepted in principle. See 1.12. This response was approved in the April 5, 2000 meeting.

Installation:

The word "accepted" was selected.

6.47: Seagate Page 27 (Editorial)

Note 1; Label: Gene Milligan; Date: 1/29/0 3:50:09 PM 46) Change <<Some devices have complex or low-performance recovery algorithms that must be performed if data is lost or damaged in the transmission process. Such devices may find it useful to implement the error detection and data retransmission algorithms defined by clause 12.>> to "Data retransmission algorithms are defined in clause 12."

Response:

I believe it is necessary to indicate "why bother". That is the intent of these sentences. No change is made.

After further discussion, the committee elected to accept this comment in principle in the meeting of April 5, 2000. The text will be rewritten to simply reflect the behavior of the devices without providing the editorial.

Installation:

Installed as requested.

6.48: Seagate Page 28 (Technical)

Note 1; Label: Gene Milligan; Date: 1/29/0 3:55:49 PM 47) In Table 3 CLEAR ACA should be Optional but retaining the present note.

Response:

Accepted. This response was approved in the April 5, 2000 meeting.

Installation:

Installed as requested.

6.49: Seagate Page 30 (Editorial)

Note 1; Label: Gene Milligan; Date: 1/29/0 3:59:42 PM 48) Why do 1b and 0b have apostrophe marks?

Response:

Accepted.

Installation:

Installed as requested.

6.50: Seagate Page 30 (Editorial)

Note 2; Label: Gene Milligan; Date: 1/29/0 4:04:20 PM 49) In note 12 delete <<proper>>.

Response:

Accepted.

Installation:

Removed by resolution of a previous comment.

6.51: Seagate Page 30 (Technical)

Note 3; Label: Gene Milligan; Date: 1/29/0 4:04:53 PM 50) What does it mean to discard a mode page?

Response:

The intent of this text is to indicate that the mode pages, together with all other SCSI functions, are not accessible. The state of the mode pages is indeterminate. The text will be modified to read: "SCSI functions not accessible."

After further discussion, the committee chose to indicate that the behavior under these conditions is "not specified". This approach was approved in the April 5, 2000 meeting.

Installation:

Installed as approved.

6.52: Seagate Page 32 (Editorial)

Note 1; Label: Gene Milligan; Date: 1/29/0 4:10:10 PM 51) In Table 6 it is not clear whether the blank is optional or not allowed.

Response:

Accepted.

Installation:

The offending table was deleted.

6.53: Seagate Page 35 (Editorial)

Note 1; Label: Gene Milligan; Date: 1/29/0 9:56:37 PM 52) <<The FCP needs only the standard FC-2 services as described in informative annex S of ANSI X3.230.>> What was the expectation of referencing an informative annex?

Response:

Accepted in principle. All references to services defined in annex S will be either deleted or replaced with descriptive text.

This resolution was accepted in principle in the June 7, 2000 working group meeting.

Installation:

These were referenced by the FC-FS document only, where applicable.

6.54: Seagate Page 37 (Technical)

Note 1; Label: Gene Milligan; Date: 1/30/0 11:52:11 AM 53) <<Since the value of the OX_ID is required by FC-PH to be unique, there is no requirement for an FCP logical unit to check for overlapping commands.>>

Is this correct? In SPI tags are required to be unique but I don't think there is a caveat that they therefore do not need to be checked.

Response:

Accepted in principle. See 1.39. The committee chose in the April 5, 2000 meeting to simply remove the offending sentence.

Installation:

Installed as approved.

6.55: Seagate Page 37 (Editorial)

Note 2; Label: Gene Milligan; Date: 1/30/0 11:57:48 AM 54) Change <<SCSI-3 application client buffer offset>> to "application client's buffer offset".

Response:

Accepted. This will be verified against the SAM-2 definitions.

Installation:

The entity discussed is an object that does not choose to use the possessive. No change was made.

6.56: Seagate Page 38 (Editorial)

Note 1; Label: Gene Milligan; Date: 1/30/0 12:06:06 PM 55) Why is << 20 hexadecimal>> not 20h as in the conventions? Global question regarding values not following the stated convention.

Response:

Accepted.

Installation:

Installed as requested.

6.57: Seagate Page 39 (Editorial)

Note 1; Label: Gene Milligan; Date: 1/30/0 12:16:12 PM 56) I seems inappropriate to require elements outside the scope of the standard. Change <<Use of this mechanism requires that the originator have precise and detailed knowledge of the requirements and capabilities of each image in the responder. That information may be obtained by mechanisms outside the scope of the FCP or may be obtained by performing a PRLI requesting informative communication.>> to "Use of this mechanism assumes that the originator have precise and detailed knowledge of the requirements and capabilities of each image in the responder. That information may be obtained by mechanisms outside the scope of the FCP or may be obtained by performing a PRLI requesting informative communication."

Response:

Accepted.

Installation:

Installed as requested.

6.58: Seagate Page 40 (Technical)

Note 1; Label: Gene Milligan; Date: 1/30/0 12:26:20 PM 57) <<Immediately after the execution of the first PRLI, both members of all image pairs shall have the same state as they would have after a hard reset or a power on with respect to each other. No tasks, reservations or status shall be present in either SCSI device.>>

Does this outlaw Persistent Reservations across power cycles?

Response:

It is certainly not intended to prohibit Persistent Reservations across power cycles. The text will be clarified to distinguish persistent reservations as a special case. This response was approved in the April 5, 2000 meeting.

Installation:

This was corrected by referencing the clearing actions table instead.

6.59: Seagate Page 41 (Editorial)

Note 1; Label: Gene Milligan; Date: 1/30/0 12:34:46 PM 58) Is it correct that the last obsolete in Table 11 is supposed to be set to a decimal one? According to the conventions that would be the case.

Response:

Accepted. See 4.205.

6.60: Seagate Page 42 (Editorial)

Note 1; Label: Gene Milligan; Date: 1/30/0 12:41:54 PM 59) <<the target shall not turn on the FCP_CONF_REQ bit.>> Does this mean enable it or does this mean set it to one?

Response:

This means set to one. The text will be corrected.

Installation:

Installed as requested.

6.61: Seagate Page 43 (Technical)

Note 1; Label: Gene Milligan; Date: 1/30/0 12:46:37 PM 60) << A responder receiving such an invalid page shall notify the originator with a PRLI ACCEPT RESPONSE CODE of 1000b(Invalid service parameters for page) indication.>>

Is this the case if implicit login is in effect?

Response:

This comment was resolved in the May 15, 2000 working group meeting. The offending text is to be rewritten as:

~~An originator receiving such an invalid page shall not perform FCP operations with the responder unless implicit login parameters have been established.~~ A responder receiving such an invalid page shall notify the originator with a PRLI ACCEPT RESPONSE CODE of 1000b(Invalid service parameters for page) indication. An originator receiving such an invalid page shall not perform FCP operations with the responder.

Installation:

Installed as approved.

6.62: Seagate Page 45 (Technical)

Note 1; Label: Gene Milligan; Date: 1/31/0 3:59:52 PM 61) <<No further FCP communication is possible between those two N_Ports.>>

This implies a requirement. Where is the requirement stated or should this be not allowed rather than not possible?

Response:

This is not a requirement. It is a characteristic of devices that are not logged in and have no implicit PRLI capability. The text will be modified to clarify that communication between ports that have logged out depends on implicit login parameters or is outside the standard. This response was accepted in the May 15, 2000 meeting of the FCP-2 working group.

Installation:

Because of other rewrites, this was removed from section 6.3. It appeared desirable to preserve the concept, so the following wording was applied in 6.2.

An FCP initiator and target shall have successfully completed a PRLI that establishes an image pair before any FCP IUs are exchanged. An image pair may also be established by an implicit PRLI established by methods outside the scope of FCP-2. An image pair is removed by a PRLO. If an image pair is not established between an initiator and a target, the initiator and target shall not exchange any FCP-2 IUs. Any FCP-2 IUs received by an initiator or target from an Nx_Port that has not established an image pair with that initiator or target shall be rejected with a P_RJT containing a reject reason code of TYPE NOT SUPPORTED. (See FC-FS.)

6.63: Seagate Page 45 (Technical)

Note 2; Label: Gene Milligan; Date: 1/31/0 4:02:10 PM 62) <<It is not an error to perform a PRLO for an image pair that is not known to the responder.>>

If not known, is it valid?

[note 2 number 62 comments]

Response:

An otherwise validly formatted PRLO with an image pair which does not exist is accepted without error and no action is performed. This kind of thing may happen if more than one application is empowered with image pair management. Note that this becomes mostly harmless when Process Associators are removed, since there can only be one image pair between two ports.

The text will replace "that is not known to the responder." with "that does not exist." This response was accepted in the May 15, 2000 meeting of the FCP-2 working group.

Installation:

Installed as approved.

6.64: Seagate Page 46 (Editorial)

Note 1; Label: Gene Milligan; Date: 1/31/0 4:13:20 PM 62) <<The Name Server for a fabric is defined by NCITS Project 1356-D, FC-GS-3.>> Call out the standard not the project. This needs to be a global change by searching on project.

Response:

Accepted.

Installation:

Rewritten by response to 8.52

6.65: Seagate Page 46 (Editorial)

63) Table 13 needs to have the lettering centered vertically in the rows. This is also the case in several other tables but not all.

Response:

Accepted.

Installation:

Rewritten by response to 8.52

6.66: Seagate Page 47 (Editorial)

Note 1; Label: Gene Milligan; Date: 1/31/0 4:24:13 PM 63) <<In the event that the Target cannot accept the SRR request, the Target shall present a check condition as if it had responded to an Initiator Detected Error with a Restore Pointers message (i.e., Sense Key = 4h, ASC/ASQ = 48h/00h).>>

Why not "In the event that the Target cannot accept the SRR request, the Target shall present a check condition with Sense Key = 4h, ASC/ASQ = 48h/00h?"

Response:

Accepted.

Installation:

Installed as requested by comment from IBM.

6.67: Seagate Page 48 (Editorial)

Note 1; Label: Gene Milligan; Date: 1/31/0 4:29:53 PM 64) Under Table 16 it is not clear where the i.e., ends nor what it applies to. Parenthesis would solve where it ends but what does it apply to - Table 29? Also "and" is missing before 29.

Response:

Accepted.

Installed as requested by comment from IBM.

6.68: Seagate Page 54 (Technical)

Note 1; Label: Gene Milligan; Date: 1/31/0 9:03:03 PM 65) <<The initiator and target clear all resources that can be cleared unambiguously.>>

This appears to be something that should be stated as a requirement. What is the requirement?
Response:

The requirement to be stated is that all resources are cleared as required by the particular task management function. There are now three ways to clear a resource.

a) Using the PLDA convention for Target Reset and related clearing processes. This involves the generation of an ABTS-LS by the initiator for each affected task known to the initiator.

b) For tasks removed from under another initiator, there are two alternative mechanisms for clearing the resources.

1) The task may time out and the initiator may perform an ABTS-LS and restart the task as required.

2) A task that has not yet been started may be terminated with a Unit Attention, indicating to the initiator that resources must be cleared using an ABTS-LS and any required tasks restarted.

c) Tasks may be terminated according to the proposals for TASK CLEARED status, documented by Charles Binford.

This approach was approved by the FCP-2 working group in their meeting of May 15, 2000.

This also applies to 6.69, 6.70, and 6.74.

Installation:

The old text:

The TARGET RESET is transmitted by the initiator (Exchange Originator) using a new Exchange. The initiator and target clear all resources that may be cleared unambiguously. If the target or the initiator do not have enough information to be sure that the Exchange can be cleared without performing a recovery abort, the Exchange is in an ambiguous state. Any open Exchanges that are in an ambiguous state as defined in the next paragraph shall be terminated using a recovery abort by whichever port detects the ambiguous state. The ports may also issue recovery abort operations for other Exchanges.

For a target or initiator FCP_Port, an Exchange is in an ambiguous state if the FCP_Port has Sequence Initiative and there exists an unacknowledged frame for the Sequence or if the FCP_Port has transferred Sequence Initiative but the transfer of the initiative has not been confirmed. For a target FCP_Port, an Exchange is also in an ambiguous state if the Exchange exists between the target FCP_Port and an initiator other than the initiator FCP_Port that performed the TARGET RESET.

SAM-2 has defined TASK ABORTED completion status for tasks terminated by a TARGET RESET task management function if the Control mode page indicates that the TASK ABORTED status is supported. Tasks completed by this mechanism should be considered as cleared unambiguously by the Target or Initiator.

is replaced by the new text:

The TARGET RESET is transmitted by the initiator (Exchange Originator) using a new Exchange. TARGET RESET resets tasks for all initiators and resets all internal states of the target as shown in 4.9. Exchange resources to be cleared may be cleared by one or more of the following mechanisms.

- a) A recovery abort sequence (see 12.3.1) may be generated by the initiator that sent the TARGET RESET for each task known to that initiator.
- b) A task for an initiator other than the initiator that sent the TARGET RESET may be ended in the target. The initiator for that task shall determine by a timeout that the task did not finish. Subsequent retries fail because the task resources have been cleared in the target, so the initiator shall clear the Exchange resources with a recovery abort sequence. See 12.4.1.

- c) A task for an initiator other than the initiator that sent the TARGET RESET may be completed by re-turning SCSI status of CHECK CONDITION with a sense key of UNIT ATTENTION and an ASC/ASCQ of POWER ON, RESET, OR BUS DEVICE RESET OCCURRED. The initiator shall then clear all other tasks for that target using the ABORT TASK task management function. See 9.1.3.

NOTE – SAM-2 has defined TASK ABORTED completion status for tasks terminated by a TARGET RESET task management function if the Control mode page indicates that the TASK ABORTED status is supported.

The same is done with minor modifications for the other related comments.

6.69: Seagate Page 55 (Technical)

Note 1; Label: Gene Milligan; Date: 1/31/0 9:07:56 PM 66) <<The ports may issue additional recovery abort operations if they are unable to determine in a simple manner whether the state of an FCP I/O operation is ambiguous.>>

Simple is in the eye of the beholder. Is there a more specific requirement?

Response:

See 6.68. The word simple will be deleted.

This resolution was accepted in the June 7, 2000 working group meeting.

Installation:

See 6.68.

6.70: Seagate Page 55 (Technical)

Note 2; Label: Gene Milligan; Date: 2/1/0 8:38:43 AM 67) <<For a target FCP_Port, an exchange is also in an ambiguous state if the exchange exists between the target FCP_Port and an initiator other than the initiator FCP_Port that performed the TARGET RESET.>>

This seems strange or is missing context. The implication is that all initiators, to avoid ambiguous state, must issue a TARGET RESET to all targets and perhaps all LUNs. The correction may be as simple as changing the statement to "After a TARGET RESET for a target FCP_Port, an exchange is also in an ambiguous state if the exchange exists between the target FCP_Port and an initiator other than the initiator FCP_Port that performed the TARGET RESET." But it seems beyond the scope of the standard as to whether the exchange is in an ambiguous state since the behavior from a TARGET RESET is well documented in SCSI standards. It appears that FCP-2 is providing excessive overlapped requirements to SAM and the command standards.

Response:

See 6.68

Installation:

See 6.68.

6.71: Seagate Page 55 (Editorial)

Note 3; Label: Gene Milligan; Date: 2/1/0 8:41:20 AM 68) In item (4) delete "similar".

Response:

Accepted.

Installation:

This was rewritten to remove redundancy with SAM-2.

6.72: Seagate Page 55 (Editorial)

Note 4; Label: Gene Milligan; Date: 2/1/0 8:47:52 AM 69) What is a recovery abort? Reading further this might be resolved by a forward reference but the terminology seems vulnerable for being mistaken with normal SCSI terminology.

Response:

Accepted. The term will be placed in the glossary and an appropriate reference will be provided.

Installation:

This was rewritten. Where appropriate, clause 12 was referenced.

6.73: Seagate Page 55 (Editorial)

Note 5; Label: Gene Milligan; Date: 2/1/0 9:03:53 AM 70) The last defining paragraph for the ambiguous state appears to be redundant although ambiguous state still seems ambiguous and I assume could be made less ambiguous. The note is also redundant. The redundancy stems from the organization of reset between TARGET RESET and LOGICAL UNIT RESET text. Perhaps the redundancy is appropriate or perhaps there should be a generic reset definition hooked to the specific differences.

Response:

Accepted in principle.

Installation:

See 6.68.

6.74: Seagate Page 55 (Technical)

Note 6; Label: Gene Milligan; Date: 2/1/0 9:26:41 AM 71) <<The initiator and target clear any resources that can be cleared unambiguously.>> This seems to be a conflict with SAM and the command sets. CLEAR TASK set should clear the task set not selectively clear tasks. This comment also applies to ABORT TASK SET.

Response:

See 6.68

Installation:

See 6.68.

6.75: Seagate Page 56 (Technical)

Note 1; Label: Gene Milligan; Date: 2/1/0 9:31:06 AM 72) How should Read Data and Write Data be set for complex commands such as Write and Verify, third party copy, and some XOR commands?

Response:

For each command, no command does both a read-direction data transfer and a write-direction data transfer. A command may cause other unidirectional commands to be executed on its behalf, but those have a separate command context. No change is required. The response was approved by the May 15, 2000 meeting of the FCP-2 working group.

The balloter requested that the phrasing be verified so that the intent was clear.

Installation:

The editor could not see any way in which the language could be misinterpreted. No change was required.

6.76: Seagate Page 56 (Technical)

Note 2; Label: Gene Milligan; Date: 2/1/0 9:41:09 AM 73) <<The Flag bit previously defined by SAM in the control byte of the CDB is obsolete and shall be set to zero.>>

The definition of obsolete allows implementation according to a prior standard. I think this should be changed to "The Flag bit previously defined by SAM in the control byte of the CDB is obsolete." or to "The Flag bit shall be set to zero."

Response:

After extended discussion, the committee accepted, in its April 5, 2000 meeting, the wording: "The Flag bit shall be set to zero."

Installation:

Installed as requested.

6.77: Seagate Page 57 (Editorial)

Note 1; Label: Gene Milligan; Date: 2/1/0 10:29:49 AM 74) <<The FCP_Port wanting to terminate the exchange generates an ABTS sequence.>> Replace <<wanting to>> with "may">

Response:

Accepted.

Installation:

Wanting has disappeared during the rewrite and moving of the description to 12.

6.78: Seagate Page 57 (Technical)

Note 2; Label: Gene Milligan; Date: 2/1/0 10:35:26 AM 75) <<A Recovery_Qualifier is established if necessary to discard any pending frames for the exchange and to prevent the reuse of the OX_ID and RX_ID for at least R_A_TOV. The BA_ACC shall request that the Recovery_Qualifier cause all frames for all sequences of the exchange to be discarded by setting SEQ_CNT_LO to 0 and SEQ_CNT_HI to FFFF h.>>

Discard is not a defined SCSI process. Should this be cleared or aborted, or should discard have a defined SCSI process? Also the space in <<FFFF h>> needs to be discarded globally.

Response:

This is a description of FC-2 level behavior necessary to properly implement FCP behavior. A glossary entry will be provided for the word "discard".

Installation:

No change was made to the body of the text. The following glossary definition was provided.

discard: The term used in Fibre Channel standards to describe removing a frame or sequence from the destination buffer without making use of the frame or sequence and without notifying upper layers of the receipt of the frame or sequence. See FC-FS.

6.79: Seagate Page 59 (Editorial)

Note 1; Label: Gene Milligan; Date: 2/1/0 10:49:20 AM 76) Change <<the FC_RSP IU shall contain the FCP_RESID_UNDER bit.>> to "the FC_RSP IU shall contain the FCP_RESID_UNDER bit set to one."

Response:

Accepted.

Installation:

Installed as requested.

6.80: Seagate Page 59 (Editorial)

Note 2; Label: Gene Milligan; Date: 2/1/0 10:54:36 AM 77) <<by setting the FCP_RESID_OVER bit in the FC_RSP IU.>> Is the setting convention firm enough or should this be "by setting the FCP_RESID_OVER bit in the FC_RSP IU to one."?

Response:

Accepted in principle. The appropriate text will be reviewed and changed if required.

Installation:

Installed as requested.

6.81: Seagate Page 59 (Technical)

Note 3; Label: Gene Milligan; Date: 2/1/0 11:02:59 AM 78) <<transfer has been terminated, all data between the offset of 0 and the highest offset shall have been transferred. The target shall not request that sets of data in the middle of a transfer not be transferred. If error conditions occur that prevent the transfer of a set of data in the middle of a data transfer, the FCP_SNS_INFO shall indicate that only data from the offset of 0 to the highest offset before the untransferred data space has been transferred.>>

Does this language allow certain applications (e.g., video) to transfer erroneous data?

Response:

Applications are allowed to accept and transmit erroneous data by these statements. However, the target cannot choose to skip any data. Furthermore, it can only invoke the retry capabilities if the various time-out and recovery procedures will not excessively disturb the data transfer rate. No change is required. The response was accepted by the May 15, 2000 meeting of the FCP-2 working group.

Installation:

The wording was improved in this area.

6.82: Seagate Page 61 (Editorial)

Note 1; Label: Gene Milligan; Date: 2/1/0 11:21:46 AM 79) In table 26 bits 5-7 should be reserved in Byte 10. The style of reserved should be standardized.

Two styles are used in table 26.

Response:

Accepted.

Installed as requested.

6.83: Seagate Page 67 (Technical)

Note 1; Label: Gene Milligan; Date: 2/1/0 12:17:45 PM 80) <<An interconnect tenancy is a period of time during which a target device owns or may access the interconnect. For example, on FC-AL loops or Fibre Channel Class 1 connections, a tenancy typically begins when a device successfully opens the connection and ends when the device releases the connection for use by other device pairs.>> The discussion in this subclause does not include how it relates to the disconnect-reconnect page.

Response:

The comment is correct. The paragraph in question defines interconnect tenancy so that the term can be used in several paragraphs in the clause. In the May 15, 2000 working group meeting, the following resolution was reached. The first sentence is a definition and will be moved to the glossary. The remainder of the paragraph is really part of the model and, appropriately edited, will be moved to the model. The word target in this description needs to be corrected to be the target-initiator pair connected during the tenancy.

Installation:

The term is defined in the glossary with a reference to this clause. Since the use is particular to this clause, there is no requirement to place the information in the model.

6.84: Seagate Page 68 (Technical)

Note 1; Label: Gene Milligan; Date: 2/1/0 12:29:51 PM 81) <<The CONNECT TIME LIMIT is not applicable for devices attached to links that do not have the concept of link tenancy.>>

How does the SCSI device know if they have the concept? Wouldn't it be easier to have a value indicate that.

Response:

This is known through the Fibre Channel link characteristics outside the SAM definitions. The individual device can determine from these characteristics whether or not to ignore these parameters.

After considerable discussion, it was decided at the April 5, 2000 meeting to indicate that the paragraph only applies to FC-AL, Class 1, or Class 6 attachments. After further consideration, I believe that change makes the text too closed to future changes in FC-2 layers. I propose that the text be slightly reworded to make use of the definition proposed in 6.83 instead of specifying particular link types.

A particular example is that a target may be on an FL_Port, but the initiator may be on the fabric. The response, accepted on April 5, was modified on May 15, 2000 to include the definition provided in 6.83.

Installation:

After providing the necessary definitions in 6.83, I could not find any necessary changes to be performed.

6.85: Seagate Page 68 (Technical)

Note 2; Label: Gene Milligan; Date: 2/1/0 2:48:20 PM 82) <<The ENABLE MODIFY DATA POINTERS (EMDP) bit indicates whether or not the target may reorder>>

Reorder seems a little strong. I think this should be "The ENABLE MODIFY DATA POINTERS (EMDP) bit indicates whether or not the device server may begin the data transfer at a logical block offset within the requested logical blocks to reduce latency".

Response:

SCSI does not provide any limits on reordering once the EMDP bit is set to one. No change is required.

After further consideration at the April 5, 2000 meeting, the committee chose to accept the comment in principle. However, there is no requirement that devices choose to begin their transfers on logical block boundaries, so wording considering the RO of the first frame of a sequence is probably more appropriate.

After further discussion at the May 15, 2000 meeting, the committee finally chose to make no change and to reject the comment.

Installation:

No change as approved.

6.86: Seagate Page 68 (Technical)

Note 3; Label: Gene Milligan; Date: 2/1/0 2:52:56 PM 83) <<If the EMDP bit is one, the target may transfer the FCP_DATA IUs for a single SCSI command in any order.>> Is it necessary to have this be more than one sequential stream beginning at an offset and wrapping? Is this needed for a scatter gather function?

Response:

SCSI does not provide any limits on reordering once the EMDP bit is set to one. No change is required.

After further consideration at the April 5, 2000 meeting, the committee chose to accept the comment in principle. However, I believe the text is correct as is. In answer to the questions raised by the comment, it is not necessary to restrict the order of streams or the wrapping of streams in the architecture. The FC architected limit is one sequence per exchange at any given instant, and therefore one stream for a particular I/O Operation. The ordering is managed by the target, so memory scatter/gather at the initiator is not part of the function.

After further discussion at the May 15, 2000 meeting, the committee finally chose to make no change and to reject the comment.

Installation:

No change as approved.

6.87: Seagate Page 69 (Editorial)

Note 1; Label: Gene Milligan; Date: 2/1/0 2:58:27 PM 85) The fairness bits should have their names changed to FAA, FAB, and FAC. I am embarrassed to explain why.

Response:

These should be defined as they are in other standards, particularly SPC-2. SPC-2 now defines a Fair Arbitration field. FCP-2 will change the definition to the same format and specify the allowed values in a table. This solution was approved in the April 5, 2000 meeting.

Installation:

Installed as requested. Note that a technical issue was located during the review of this text, requiring important re-wordings.

6.88: Seagate Page 70 (Technical)

Note 1; Label: Gene Milligan; Date: 2/1/0 3:10:23 PM 86) <<If the precise delivery function is not supported by the target, the EPDC bit shall be masked as not changeable and shall follow the MODE SENSE/MODE SELECT rules specified by SPC-2.>>

Why not just not support the page at all if the function is not supported?

Response:

The lack of support of this page will be used to explicitly indicate that precise delivery is not supported. The change is accepted. This was approved in the April 5, 2000 meeting.

Installation:

This was made explicit as one of two options for indicating that precise delivery is not supported.

6.89: Seagate Page 71 (Editorial)

Note 1; Label: Gene Milligan; Date: 2/1/0 3:20:18 PM 87) <<DISABLE TARGET ORIGINATED LOOP INITIALIZATION (DTOLI)>>

The first portion of the clause is in terms of FC-AL and the last portion in terms of FC-AL-2. Was that intended? If so how does the SCSI device determine which it is attached to? If half of the SCSI devices claim compliance to FC-AL and half FC-AL-2 which type of loop is it?

Response:

Accepted.

Installation:

The text was modified to refer to "arbitrated loops" in general. However, the requirement during error recovery is FC-AL-2 compliance if it is capable of detecting loop failures.

6.90: Seagate Page 76 (Technical)

Note 1; Label: Gene Milligan; Date: 2/1/0 4:15:49 PM 88) <<NOTE Using a value of 0 for this time out value assumes that a Sequence Initiator does not transmit any Frames for a Sequence after an ABTS is sent for that Sequence. If a design uses a queuing mechanism for the transmission of Sequences, the queue for a given Sequence shall be empty before an ABTS for that Sequence can be sent, or the act of sending the ABTS purges the queue.>>

The requirement needs to be moved out of the note and into the text or changed to informative rather than a requirement.

Response:

The requirement will be moved into the text. This resolution was accepted in the April 5, 2000 meeting.

Installation:

Installed as requested.

6.91: Seagate Page 76 (Editorial)

Note 2; Label: Gene Milligan; Date: 2/1/0 4:19:37 PM 89) Change <<NOTE SCSI Targets are required to implement R_A_TOV ELS in order to time the expected response to a LOGO or PRLO Extended Link Service.>> to "NOTE R_A_TOV ELS is used to time the expected response to a LOGO or PRLO Extended Link Service."

Response:

Accepted.

Installation:

Installed as requested.

6.92: Seagate Page 78 (Editorial)

Note 1; Label: Gene Milligan; Date: 2/1/0 4:49:21 PM 90) <<Initiators communicating with SCSI devices that do not depend on command ordering or maintaining records of internal device state may simply use the mechanisms described in this chapter to detect the presence of errors, then abort the exchange using an ABORT TASK task management function or a recovery abort function.>>

Delete <<simply>>

Response:

Accepted.

Installation:

The required rewrite removed the offending statement.

6.93: Seagate Page 78 (Editorial)

Note 2; Label: Gene Milligan; Date: 2/1/0 4:52:02 PM 91) Globally search on chapter and replace it with section or even better search on chapter and section and replace them with clause.

Response:

Accepted.

Installation:

Installed as requested in clause 12, annex B. All other cases were corrected by other overlapping comments. The annexes use the new numbering.

6.94: Seagate Page 79 (Editorial)

Note 1; Label: Gene Milligan; Date: 2/1/0 4:57:10 PM 92) <<The Exchange responder (SCSI Target) shall initiate error detection and recovery described in 12.3 for the following:

1) after expiration of the time-out period REC_TOV and an expected FCP_CONF has not been received.

The Exchange responder (SCSI Target) may also initiate error detection and recovery for the following:

1) for detection of a Sequence error (see 12.3.9).>>

Why use lists only one item long rather than a simple sentence?

Response:

Accepted.

Installation:

These one-line lists were incorporated into the text.

6.95: Seagate Page 80 (Editorial)

Note 1; Label: Gene Milligan; Date: 2/1/0 5:02:29 PM 93) Perhaps a spell check should be made. Definitely <<interal>> should not pass a spell check.

Response:

Accepted.

Installation:

Changed as requested.

6.96: Seagate Page 82 (Editorial)

Note 1; Label: Gene Milligan; Date: 2/1/0 5:13:25 PM 94) <<NOTE The profiles for many class 3 Targets indicate that the Target shall not attempt recovery for such cases and shall depend on Initiator time-outs for recovery.>>

Delete this note or change it to eliminate the shalls (e.g. use a from of assumes).

Response:

Accepted.

Installation:

The note was changed to a mandatory condition as requested by 4.538.

6.97: Seagate Page 83 (Editorial)

Note 1; Label: Gene Milligan; Date: 2/1/0 5:18:19 PM 95) <<All FCP-2 devices shall support the use of ABTS-Last Sequence of Exchange (ABTS-LS), which uses ABTS to abort the entire Exchange.>>

Delete this sentence or change the introductory portion of Clause 12 that states that all the recovery protocols are optional.

Response:

This describes the default case without recovery. All devices must be capable of doing this.

In the June 7, 2000 working group it was decided that it will be necessary to clarify that exchange level recovery is always mandatory. This should be clarified in clause 12 of FCP-2.

Installation:

Clause 12.1.1 and 12.1.2 have been rewritten to carry the proper information.

6.98: Seagate Page 83 (Editorial)

Note 2; Label: Gene Milligan; Date: 2/1/0 5:20:06 PM 96) <<This subclause does not define the protocol by which multiple SCSI Initiators communicate or synchronize shared peripherals.>>

I think <<subclause>> should be changed to "standard".

Response:

Accepted.

Installation:

The offending sentence was deleted during the correction of a different comment.

6.99: Seagate Page 83 (Technical)

Note 3; Label: Gene Milligan; Date: 2/1/0 5:35:38 PM 97) <<The ABTS protocol shall be invoked as required by 9.1.1.4 for ambiguous exchanges after certain task management functions have been executed.>>

Which ones are these <<certain ones>>?

Response:

The text will be changed to read "The ABTS protocol shall be invoked after task management functions have been executed as required in 9.1.1.4." This response was accepted at the May 15, 2000 meeting.

Installation:

The offending sentence was corrected during the correction of a different comment.

6.100: Seagate Page 85 (Editorial)

Note 1; Label: Gene Milligan; Date: 2/1/0 5:42:09 PM 98) <<For the action taken on any other received Frame, see TBD.>>

Not ready for prime time.

Response:

Accepted.

Installation:

The offending sentence was deleted during the correction of a different comment.

6.101: Seagate Page 87 (Editorial)

Note 1; Label: Gene Milligan; Date: 2/1/0 5:44:53 PM 99) <<[Editor s Note: This is new text and may still have some small errors in it. Minor revisions to make it consistent with SAM-2 will probably be installed in the next revision of the document.]>>

Then why did the editor talk the Chairman into a letter ballot? Delete this note.

Response:

Accepted.

Installation:

Installed as requested.

6.102: Seagate Page 93 (Technical)

Note 1; Label: Gene Milligan; Date: 2/1/0 5:51:12 PM 101) <<The following extended link services will be specified by a future version of FC-PH. Until that time, they will be specified here for use by all FCP-2 devices, including those specified by the FC-TAPE profile.>>

Delete this subclause.

Response:

This entire clause will be deleted. Document T11/00-284v1 (T10/00-230r1) requests that these functions be included in FC-FS. This resolution was accepted in the May 15, 2000 meeting.

Installation:

Annex B is deleted.

6.103: Seagate Page 95 (Editorial)

Note 1; Label: Gene Milligan; Date: 2/1/0 5:55:23 PM 102) Annex B uses a third style for hex values. One is needed.

Response:

Accepted.

Installed as requested.

6.104: Seagate Page 125 (Editorial)

Note 1; Label: Gene Milligan; Date: 2/1/0 6:04:46 PM 103) Since this is an informative annex change <<The Fabric SCSI device discovery procedure shall also apply to a F/ NL_Port that supplies the required Simple Name Server service functionality.>> to "The Fabric SCSI device discovery procedure is useful with a F/ NL_Port that supplies the required Simple Name Server service functionality." Globally change all the instances of <<shall>> in the informative annexes to an informative construction rather than normative.

Response:

Accepted.

Installation:

Installed as requested.

6.105: Seagate Page 127 (Editorial)

Note 1; Label: Gene Milligan; Date: 2/1/0 6:06:16 PM 104) Delete <<required>> globally in the informative annexes.

Response:

Accepted.

Installation:

Installed as requested in all annexes. Note that required can still be a useful word in some contexts. "Error recovery is not required." (Annex C)

6.106: Seagate Page 131 (Editorial)

Note 1; Label: Gene Milligan; Date: 2/1/0 6:09:51 PM 105) Change <<If a device level error is detected by a SCSI Target while it has Sequence Initiative, the only permissible recovery action is the transmission of FCP_RSP with CHECK CONDITION status and an appropriate Sense Key/ASC/ ASCQ.>> to "If a device level error is detected by a SCSI Target while it has Sequence Initiative, the recommended recovery action is the transmission of FCP_RSP with CHECK CONDITION status and an appropriate Sense Key/ASC/ ASCQ." Globally search the informative annexes for permissible and be sure the text is constructed as informative not normative.

Response:

This is actually a requirement of FCP and FCP-2. The text will be verified to be installed in the normative body and removed from this informative annex.

This resolution was accepted in the June 7, 2000 working group meeting.

Installation:

Installed as approved.

6.107: Seagate Page 135 (Editorial)

Note 1; Label: Gene Milligan; Date: 2/1/0 6:12:23 PM 106) <<Annex J FCP-2 requirements for other standards (normative)>>

Move this annex ahead of the informative annexes.

Response:

This annex will be deleted and text will be formally proposed to correct those documents that are not correct.

This resolution was accepted in the June 7, 2000 working group meeting.

Installation:

Annex J is deleted.

6.108: Seagate Page 135 (Editorial)

Note 2; Label: Gene Milligan; Date: 2/1/0 6:18:41 PM 107) Change <<The changes outlined in this document effect text presently standardized in FC-PH-2 which will be corrected in the publication of FC-FS.>> to "This annex documents exceptions to FC-PH-2." In addition T10 should seek formal approval by T11 of changes required by T10 in the T11 standards.

Response:

This annex will be deleted and text will be formally proposed to correct those documents that are not correct.

Installation:

Annex J is deleted.

6.109: Seagate Page 135 (Editorial)

Note 3; Label: Gene Milligan; Date: 2/1/0 6:19:50 PM 108) <<The second to the last paragraph of section 21.12.1 on page 49 is duplicated. This must be installed in FC-FS.>>

Delete this subclause.

Response:

This annex will be deleted and text will be formally proposed to correct those documents that are not correct.

Installation:

Annex J is deleted.

6.110: Seagate Page 135 (Editorial)

Note 4; Label: Gene Milligan; Date: 2/1/0 6:21:01 PM 109) <<I believe the wording of Annex A of FCP is better, where it says:>>

Not ready for prime time.

Response:

This annex will be deleted and text will be formally proposed to correct those documents that are not correct.

Installation:

Annex J is deleted.

6.111: Seagate Page 135 (Editorial)

Note 5; Label: Gene Milligan; Date: 2/1/0 6:22:09 PM 108) Clean up J.1.3.

Response:

This annex will be deleted and text will be formally proposed to correct those documents that are not correct.

Installation:

Annex J is deleted.

6.112: Seagate Page 136 (Editorial)

Note 1; Label: Gene Milligan; Date: 2/1/0 6:24:12 PM 109) <<At present, this is documented in section 6.2.5. It should be documented instead in FC-FS, section 15.10 or 15.11. Section 6.2.5 will be removed when FC-FS has been updated.>>

Delete this statement (subclause) and move it to a T11 tickler file.

Response:

This annex will be deleted and text will be formally proposed to correct those documents that are not correct.

Installation:

Annex J is deleted.

6.113: Seagate Page 136 (Editorial)

Note 2; Label: Gene Milligan; Date: 2/1/0 6:25:14 PM 110) Clean up J.2.1.

Response:

This annex will be deleted and text will be formally proposed to correct those documents that are not correct.

Installation:

Annex J is deleted.

6.114: Seagate Page 136 (Editorial)

Note 3; Label: Gene Milligan; Date: 2/1/0 6:26:45 PM 111) The table of contents on the last page should be deleted or moved to the table of contents.

Response:

Accepted.

Installation:

Annex J is deleted.

6.115: Seagate Page 136 (Editorial)

Note 4; Label: Gene Milligan; Date: 2/1/0 6:32:32 PM 112) The letter ballot review, in my opinion, clearly indicates the draft was not ready for a letter ballot. T10 has in recent years, stimulated by drafts balloted before there time, made a practice in most cases of conducting editorial review session prior to the forwarding practice. I think the Chair should make this a general practice in the absence of evidence that there is a reason it is not needed. In addition I think the Chair should encourage new editors to attend at least some of the editorial review meetings to have more understanding of the styles required for standards. The action item from Brisbane for a T10 style guide may also help with the editor awareness.

Response:

The balloting was essential to encourage a thorough and critical reading of the recovery procedures. Thank you for contributing to this effort.

Installation:

No additional changes required.

7 Additional comments from Seagate

The following additional comments were received from Seagate, ordered separately

7.1: Seagate Comment 001, editorial, whole document (Editorial)

There are a number of references to FC-PHx and FC-FS documents. If FC-FS is an acceptable reference, the references to the FC-PHx documents should all be changed to reference FC-FS.

Response:

Accepted.

Installation:

Installed as requested.

7.2: Seagate Comment 002, editorial, whole document (Editorial)

Standards are referenced both by number, i.e., X3..., and abbreviation, i.e., SAM-2. An example is page 7, the paragraph above table 1. SAM is referenced as SAM and X3.270.

Response:

Accepted.

Installation:

Installed as requested.

7.3: Seagate Comment 003, editorial?, pdf page 29, Doc Page 13, Table 4

Is the last row, FCP exchange information, different from the second row, Open FCP Sequences Terminated, or row 6, Open Tasks? Is this Exchange information for REC? This affects the requirements for Clear & Abort Task Set. If this is exchange information for REC, the text for REC should be added.

Response:

The chart distinguishes between an FCP-2 I/O Operation exchange and the exchange resources associated with an exchange. Among these rows, some redundancy may be present. The text will be reviewed for redundancy.

This resolution was accepted in the June 7, 2000 working group meeting.

Installation:

I believe that the row associated with “FCP Exchange resources” is completely encompassed in the row “Open Tasks (FCP Exchanges) Aborted”. The row about sequences is not redundant, since sequences can be retried in some cases. The “FCP Exchange resources” row is deleted. Note that in table 5 for the Clear Task Set and Abort Task Set columns, these were not identical.

7.4: Seagate Comment 004, technical, pdf page 32, Doc Page 16, Table 7

The third party address format defined here is new and conflicts with existing implementation. Suggest adding a format field in byte 0. A zero in the field defines the address format below. The PA_VAL could also be used to select the format instead of defining a new field. If PA_VAL is a one, the format is as the new format as in FCP-2 rev 4, If PA_VAL is zero, the format is as below.

Bit	7	6	5	4	3	2	1	0
Byte	0	0	0	0	0	0	0	0
1-4	reserved							
5-7	FCP_Port Identifier							

Response:

What existing implementations have been defined that conflict with this?

In any case, this format is appropriate because process associators have been dropped from FCP-2. This response was accepted in the May 15, 2000 meeting. Apparently, some previous devices have violated this convention and violated the FCP standard. More study will probably be required.

In the June 7, 2000 working group, the balloter withdrew this comment.

Installation:

No change was required.

7.5: Seagate Comment 005, technical, clause 6.2, pdf page 38, Doc page 22, last sentence bottom of page 22, first sentence top of page 23.

A PLRI request may also be rejected in the PRLI ACcept with one of the response codes. An LS_RJT is generally only returned to an improperly formatted PRLI.

Response:

Accepted. See 1.21. This response was accepted in the May 15, 2000 meeting.

Installation:

Installed as requested.

7.6: Seagate Comment 006, technical, pdf page 40, Doc Page 24, clause 6.2.5, last paragraph Also, page 120, J.1.5

The behavior of sending an ABTS in response to FCP frames received without a process login is in conflict with PLDA rev 2.1. Clause 9.7 on doc page 34 requires sending a PRLO. FCP-2 should support the PLDA behavior or a method for discovering an FCP-2 environment (i.e., a login bit) needs to be defined.

Response:

Accepted. See 1.48. This response was accepted in the May 15, 2000 meeting.

Installation:

Installed as described in 1.48.

7.7: Seagate Comment 007, editorial, pdf page 46, Doc Page 30, clause 7, 7.1, 7.2

FC-GS-3 is referenced as NCITS Project 1356-D, FC-GS-3 and FC-GS-3 Suggest simplifying to just FC-GS-3 in:

clause 7 first paragraph,

clause 7.2 first paragraph, and

clause 7.2 third paragraph.

Response:

Accepted.

Installation:

Rewritten by response to 8.52.

7.8: Seagate Comment 008, editorial, pdf page 46, Doc Page 30, clause 7.2

SPC-2 is referenced as NCITS Project 1236 (SPC-2) Suggest simplifying to just SPC-2 in the second paragraph.

Response:

Accepted.

Installation:

Rewritten by response to 8.52.

7.9: Seagate Comment 009, editorial, pdf page 55, Doc Page 39, clause 9.1.1.4, first and second NOTES.

SAM-2 is referenced as NCITS Project 1157-D (SAM-2) Suggest simplifying to just SAM-2 in both notes.

Response:

Accepted.

Installation:

Installed as requested.

7.10: Seagate Comment 010, editorial, pdf page 56, Doc Page 40, clause 9.1.1.4, first and second NOTES.

Same as comment 10. SAM-2 is referenced as NCITS Project 1157-D (SAM-2) Suggest simplifying to just SAM-2 in both notes.

Response:

Accepted.

Installation:

Installed as requested.

7.11: Seagate Comment 011, editorial, pdf page 72, Doc Page 56, clause 10.1.3.4

The sentence "Targets not attached" is before the other text describing the RHA bit. For other bits defined in 10.1.3, this sentence is after the definition text. The ordering should be consistent.

Response:

Accepted.

Installation:

Installed as requested.

7.12: Seagate Comment 012, editorial, whole document

FC-AL-3 is referenced as NCITS 1304-D throughout the document. Suggest changing NCITS 1304-D to FC-AL-3 in the document to be consistent with other references to standards.

Response:

Accepted.

Installation:

Installed as requested.

7.13: Seagate Comment 013, technical, pdf page 78, doc page 62, clause 12.1.1, first and only paragraph

ABORT TASK task management referenced, but is no longer a task management function in FCP-2. It is an additional mechanism. Suggest changing an ABORT TASK task management function to an ABORT TASK function.

Response:

Accepted in principle. The wording will be made consistent with 9.1.2.1. The response was approved in principle in the May 15, 2000 meeting.

Installation:

During rewrite of this text, the term was changed to "recovery abort".

7.14: Seagate (Editorial)

Project: FCP-2 Revision: 4 ClauseSubclause: Introduction PDFPage: 15 DocPage: xv Line: CommentType: Editorial Title: Summary of Clauses and Annexes is Incomplete

Comment: Does not refer to new clause 7, FC 4 specific name server objects. Does not describe all annexes.

SuggestedRemedy: Renumber "Clause 7..." through "Clause 11 ..." to one higher and insert "Clause 7 describes the FC-4 specific name server objects for FCP." Correct and add descriptions of annexes.

Response:

Accepted.

Installation:

Installed as requested.

7.15: Seagate (Editorial)

ClauseSubclause: 4.2 PDFPage: 24 DocPage: 8 Line: 1st line, 4th paragraph of 4.2

CommentType: Editorial Title: Grammar

Comment: Conjunction needed: "...interpretation of the command, has determined..."

SuggestedRemedy: Change to "...interpretation of the command and has determined..."

Response:

Accepted.

Installation:

Installed as requested.

7.16: Seagate (Editorial)

ClauseSubclause: 4.2 PDFPage: 24 DocPage: 8 Line: Next-to-last CommentType: Editorial Title: Grammar

Comment: Subject/verb number disagreement: "FCP_RSP payload carry the FCP Response information"

SuggestedRemedy: Change "carry" to "carries"

Response:

Accepted.

Installation:

Installed as requested.

7.17: Seagate (Editorial)

PDFPage: 25 DocPage: 9 Line: Last line, 2nd paragraph under 4.3 CommentType: Editorial
Title: Specify which FC mode page

Comment: "...Fibre Channel Control page...." is vague.

SuggestedRemedy: Change to "...Fibre Channel Logical Unit Control page...."

Response:

Accepted.

Installation:

Installed as requested.

7.18: Seagate (Editorial)

ClauseSubclause: 4.9 PDFPage: 31 DocPage: 15 Line: 1 CommentType: Editorial Title:
Capitalization

Comment: Capitalize first word of heading

SuggestedRemedy: "login/logout" => "Login/logout"

Response:

Accepted.

Installation:

Installed as requested.

8 Comments from Storage Technology Corporation

The following comments accompanied the ballot from Storage Technology, prepared by Erich Oetting.

8.1: StoreTek Comment # 1 (Editorial)

PDF Page # 1 Paper Page # i Section # Title page Paragraph # 1

Problem: Through out the document the term "X3T10" is being used.

Solution: Replace all current "X3T10" references with "NCITS T10" as necessary.

Response:

Accepted.

Installation:

Corrected in cover material, foreword, and clause 2.

8.2: StoreTek Comment # 2 (Editorial)

PDF Page # 2 Paper Page # ii Section # Points Of Contact Paragraph # X3T10 Chair

Problem: John Lohmeyers Email address is not correct.

Solution: Change it to lohmeier@t10.org

Response:

Accepted.

Installation:

Installed as requested.

8.3: StoreTek Comment # 3 (Editorial)

PDF Page # 2 Paper Page # ii Section # Points Of Contact Paragraph # T10 Reflector

Problem: The two references to "symbios.com" are not correct.

Solution: Replace with "t10.org".

Response:

Accepted.

Installation:

Installed as requested.

8.4: StoreTek Comment # 4 (Editorial)

PDF Page # 2 Paper Page # ii Section # Points Of Contact Paragraph #

Problem: Should the T10 Web Site be listed in this section?

Solution: Add the T10 Web Page as <http://www.t10.org>.

Response:

Accepted.

Installation:

Installed as requested.

8.5: StoreTek Comment # 5 (Editorial)

PDF Page # 2 Paper Page # ii Section # Abstract Paragraph #

Problem: Last sentence in Abstract talks about the second revision instead of this revision.

Solution: Remove the second sentence.

Response:

Accepted.

Installation:

Installed as requested.

8.6: StoreTek Comment # 6 (Editorial)

PDF Page # 5 Paper Page # v Section # Contents Paragraph #

Problem: Extra text after "Forward".

Solution: Remove text in parentheses following Foreword entry.

Response:

Accepted.

Installation:

Installed as requested.

8.7: StoreTek Comment # 7 (Editorial)

PDF Page # 10 Paper Page # x Section # List Of Tables Table # F.1

Problem: There is no Table F.1 on page 110.

Solution: Remove F.1 from the List of Tables.

Response:

Accepted.

Installation:

Installed as requested.

8.8: StoreTek Comment # 8 (Editorial)

PDF Page # 14 Paper Page # xiv Section # Introduction Paragraph # 3

Problem: The number of clauses and annexes is incorrect and their descriptions are incorrect.

Solution: Update as necessary.

Response:

Accepted.

Installation:

The installation is semi-automated and will be finished when the table of contents is updated.

8.9: StoreTek Comment # 9 (Editorial)

PDF Page # 15 Paper Page # xv Section # Introduction Paragraph # ?

Problem: Missing period.

Solution: Add a period at the end of sentence starting "Annex E".

Response:

Accepted.

Installation:

Installed as requested.

8.10: StoreTek Comment # 10 (Editorial)

PDF Page # 15 Paper Page # xv Section # Introduction Paragraph # Last paragraph on page.

Problem: SAM-2 should be referred to by name.

Solution: Change "and subsequent documents" to "and SCSI-3 Architecture Model-2 (SAM-2).

Response:

Accepted.

Installation:

Installed as requested.

8.11: StoreTek Comment # 11 (Editorial)

PDF Page # 17 Paper Page # 1 Section # Scope Paragraph # 1

Problem: Wording.

Solution: Three sentences that start "The FCP-2" should start "FCP-2".

Response:

Accepted.

Installation:

Installed as requested.

8.12: StoreTek Comment # 12 (Editorial)

PDF Page # 17 Paper Page # 1 Section # Scope Paragraph # 1

Problem: Update reference.

Solution: Replace SAM ref. in third sentence with SAM-2.

Response:

Accepted.

Installation:

Installed as requested.

8.13: StoreTek Comment # 13 (Editorial)

PDF Page # 17 Paper Page # 1 Section # Scope Paragraph # 1

Problem: Sentence not needed.

Solution: Remove last sentence of paragraph.

Response:

Accepted.

Installation:

After review, I still think this sentence is required to indicate why FCP-2 was required.

8.14: StoreTek Comment # 14 (Editorial)

PDF Page # 17 Paper Page # 1 Section # 2.2 Paragraph # 2

Problem: Verify the status of these documents.

Solution: Move documents to 2.1 as necessary.

Response:

Accepted.

Installation:

Installed as requested. Many references were changed to reference the most up-to-date document.

8.15: StoreTek Comment # 15 (Editorial)

PDF Page # 17 Paper Page # 1 Section # 2.2 Paragraph #

Problem: Typos in FC-AL-2 ref.

Solution: Add a comma after "revision 7.0", remove period after "FC-AL-2".

Response:

Accepted.

Installation:

Installed as requested.

8.16: StoreTek Comment # 16 (Editorial)

PDF Page # 17 Paper Page # 1 Section # 2.2 Paragraph #

Problem: Typos in FC-AL-3 ref.

Solution: Add a comma and space after "revision 1.0", remove period after "FC-AL-3".

Response:

Accepted.

Installation:

FC-AL-3 was removed from the references.

8.17: StoreTek Comment # 17 (Editorial)

PDF Page # 18 Paper Page # 2 Section # 2.2 Paragraph # Last

Problem: The documents described in this clause are both T10 and T11.

Solution: Remove the "X3T10" from the first sentence.

Response:

Accepted.

Installation:

A previous comment proposed placing both committee names in. That solution was accepted.

8.18: StoreTek Comment # 18 (Editorial)

PDF Page # 18 Paper Page # 2 Section # 2.2 Paragraph # Last

Problem: Missing period.

Solution: Add period after zip code in last sentence.

Response:

Accepted.

Installation:

Installed as requested.

8.19: StoreTek Comment # 19 (Technical)

PDF Page # 18 Paper Page # 2 Section # 3 Paragraph #

Problem: Through out this document terms have been created as FCP_... and are not defined in Clause 3.

Solution: Define all FCP_... terms used in this document in Clause 3.

Response:

Many of these objects are fields. Others are IUs. They are all defined in the proper descriptive area of the text. Traditionally, such fields are not placed in the glossary or abbreviations section, since there are many of them and there is not enough context to define them. No change will be made. This resolution was accepted in the May 15, 2000 meeting.

Installation:

No change was made.

8.20: StoreTek Comment # 20(Editorial)

PDF Page # 19 Paper Page # 3 Section # 3.1.22 Paragraph #

Problem: Inconsistent wording.

Solution: Change "An SCSI" to "A SCSI".

Response:

The convention is to say: "An ess cee ess eye".

Installation:

No change was made.

8.21: StoreTek Comment # 21 (Editorial)

PDF Page # 19 Paper Page # 4 Section # 3.1.42 Paragraph #

Problem: Inconsistent wording.

Solution: Change "An SCSI" to "A SCSI".

Response:

The convention is to say: "An ess cee ess eye".

Installation:

No change was made.

8.22: StoreTek Comment # 22 (Editorial)

PDF Page # 22 Paper Page # 6 Section # 3.2 Paragraph #

Problem: Abbreviations used in the document are not defined.

Solution: Add definitions for WWNN and WWPN to clause 3.2.

Response:

Accepted.

Installation:

The following terms will be defined in the glossary:

Worldwide_Name: A Name_Identifier which is worldwide unique, and represented by a 64 bit unsigned binary value.

Name_Identifier: A 64 bit identifier, with a 60 bit value preceded with a 4 bit Net-work_Address_Authority Identifier, used to identify entities in Fibre Channel such as N_Port, Node, F_Port, or Fabric (see Table 28 and Table 29).

Node_Name: A Name_Identifier associated with a Node.

Port_Name: A Name_Identifier associated with an N_Port or an NL_Port.

These corrected terms are also be applied to Annex F, the only place that WWNN and WWPN are used in the standard.

8.23: StoreTek Comment # 23 (Editorial)

PDF Page # 23 Paper Page # 7 Section # 4.1 Paragraph # 1

Problem: Wording.

Solution: First sentence, change "The Fibre Channel" to "Fibre Channel".

Response:

Accepted.

Installation:

Installed as requested.

8.24: StoreTek Comment # 24 (Editorial)

PDF Page # 23 Paper Page # 7 Section # 4.1 Paragraph # 3

Problem: Wording.

Solution: First sentence, change "The Fibre Channel Arbitrated Loop" to "Fibre Channel Arbitrated Loop".

Response:

Accepted.

Installation:

Installed as requested.

8.25: StoreTek Comment # 25 (Editorial)

PDF Page # 24 Paper Page # 8 Section # 4.2 Paragraph # 5

Problem: Wording.

Solution: Last sentence, change "FCP_RSP payload carry" to "FCP_RSP payload shall carry".

Response:

Accepted.

Installation:

Installed as requested.

8.26: StoreTek Comment # 26 (Technical)

PDF Page # 26 Paper Page # 10 Section # 4.3 Paragraph # Last

Problem: Incomplete list.

Solution: Add REPORT LUNS to the list of initialization commands.

Response:

Accepted. This response was approved by the May 15, 2000 meeting of the FCP-2 working group.

Installation:

Installed as requested.

8.27: StoreTek Comment # 27 (Technical)

PDF Page # 26 Paper Page # 10 Section # 4.4 Paragraph # 4

Problem: The first sentence uses "may" be used in describing queued command completions.

Solution: Either change "may" to "shall" or add text saying link level recovery may not be possible on a queued device.

Response:

Link level recovery for queued devices should still work fine for those devices that are not state dependent and using ordered commands. May is the appropriate word in this context. No change will be made. This response was approved by the May 15, 2000 meeting of the FCP-2 working group.

Installation:

No change made.

8.28: StoreTek Comment # 28 (Editorial)

PDF Page # 27 Paper Page # 11 Section # 4.6 Paragraph #

Problem: Blank entry in Table 2.

Solution: Remove the blank line in Table 2.

Response:

Accepted.

Installation:

Installed as requested.

8.29: StoreTek Comment # 29 (Technical)

PDF Page # 28 Paper Page # 12 Section # 4.7 Paragraph # 1

Problem: First sentence, task management function also applies to Clear ACA.

Solution: Change "must be aborted or terminated" to "must be aborted or terminated, or an ACA condition must be cleared."

Response:

Accepted. This response was approved by the May 15, 2000 meeting of the FCP-2 working group. The word "must" should be replaced with "shall".

Installation:

Installed as approved, except that "shall" really should be "is to be".

8.30: StoreTek Comment # 30 (Editorial)

PDF Page # 28 Paper Page # 12 Section # 4.7 Paragraph # 2

Problem: Typo.

Solution: Capitalize "Table" in last sentence.

Response:

Table is only capitalized when it is the first word in a sentence. This response was approved by the May 15, 2000 meeting of the FCP-2 working group.

Installation:

No change was required.

8.31: StoreTek Comment # 31 (Editorial)

PDF Page # 32 Paper Page # 16 Section # 5.1 Paragraph # 2

Problem: The first sentence uses "NL_Port", this should also apply to N_Ports as well.

Solution: The term "FCP_Port" has already been defined in this document. Replace all remaining "L_Port" and "N_Port" with "FCP_Port" as necessary.

Response:

Accepted.

Installation:

Corrected throughout document.

8.32: StoreTek Comment # 32 (Editorial)

PDF Page # 33 Paper Page # 17 Section # 5.3 Paragraph # 1

Problem: Specify use of initiator WWPN when keeping track of reservations.

Solution: In second sentence, replace "world-wide unique name of each initiator" with "world-wide unique port name of each initiator".

Response:

Accepted.

Installation:

Installed with minor corrections.

8.33: StoreTek Comment # 33 (Editorial)

PDF Page # 33 Paper Page # 17 Section # 5.3 Paragraph # 2

Problem: Requirements for World Wide Names are not clear.

Solution: Replace the last two sentences with, "FCP-2 devices with a single LUN and a single port should not use the same world wide name for the LUN and the port. Devices with more than one LUN or more than one port shall use a unique world wide name for each port and each LUN.

Response:

Accepted in principle. Wording will be reviewed.

Installation:

Installed with major editorial revisions as a result of a different comment.

8.34: StoreTek Comment # 34 (Editorial)

PDF Page # 34 Paper Page # 18 Section # 5.4 Paragraph # 1

Problem: The last sentence refers to Annex "B" incorrectly.

Solution: Replace "B" with "C".

Response:

Accepted.

Installation:

Installed as requested.

8.35: StoreTek Comment # 35 (Technical)

PDF Page # 34 Paper Page # 18 Section # 5.4 Paragraph # 8 & 9

Problem: For any IU that is L (last sequence of exchange) why is SI (sequence initiative) marked as T (transferred) when the exchange is now over?

Solution: Create an SI code of X (don't care) and update these tables as necessary.

Response:

This is normal FC-PH behavior. No change is required. This response was approved by the May 15, 2000 meeting of the FCP-2 working group.

Installation:

No change was made.

8.36: StoreTek Comment # 36 (Technical)

PDF Page # 34 Paper Page # 18 Section # 5.4 Table # 8

Problem: Unfortunate to see that IU's T8, T9, T10, and T11 have been declared obsolete. I (DAP) believe these IU's can aid in performance and resource management and don't see any harm in leaving them in at this time.

Solution: Leave IU's in FCP-2.

Response:

This change has been repeatedly approved by the committee. No change will be made. This response was approved by the May 15, 2000 meeting of the FCP-2 working group.

Installation:

No change is required.

8.37: StoreTek Comment # 37 (Technical)

PDF Page # 35 Paper Page # 19 Section # 5.4 Table # 9

Problem: Unfortunate to see that IU's I6 and I7 have been declared obsolete. I (DAP) believe these IU's can aid in performance and resource management and don't see any harm in leaving them in at this time.

Solution: Leave IU's in FCP-2.

Response:

This change has been repeatedly approved by the committee. No change will be made. This response was approved by the May 15, 2000 meeting of the FCP-2 working group.

Installation:

No change is required.

8.38: StoreTek Comment # 38 (Technical)

PDF Page # 36 Paper Page # 20 Section # 5.6 Table # 10

Problem: Word 1 bits 31-24 are shown as "reserved" when FC-PH-2 Figure 46 has defined them as "CS_CTL".

Solution: Replace "reserved" with "CS_CTL" and add a sub clause describing this field.

Response:

Note that CS_CTL has no interaction with the SCSI mapping of FC-PH. The field will be included, but appropriate notes will indicate that CS_CTL does not participate in the mapping. This response was approved by the May 15, 2000 meeting of the FCP-2 working group.

Installation:

Installed as approved.

8.39: StoreTek Comment # 39 (Technical)

PDF Page # 37 Paper Page # 21 Section # 5.6.11 Paragraph # Sun clause name Problem: The term "RLTV_OFF" is not defined in this document or any other FC documents.

Solution: Either define this term in Clause 3 or replace every occurrence with the FC-PH definition in Clause 18.11.

Response:

The term is defined in FC-FS as "relative offset" or RO. RLTV_OFF will be replaced with RO and both terms (relative offset and RO) will be placed in clause 3. This response was approved by the May 15, 2000 meeting of the FCP-2 working group.

Installation:

Installed as requested with significant modifications.

8.40: StoreTek Comment # 40 (Technical)

PDF Page # 37 Paper Page # 21 Section # 5.6.11 Paragraph #

Problem: Missing restriction for Relative Offset.

Solution: Specify the Relative Offset shall be 0 modulo 4.

Response:

This comment was accepted by the May 15, 2000 meeting of the FCP-2 working group.

Installation:

This restriction was originally placed in clause 9.2.2 as the result of a previous comment. However, it is clearly better here, where it can be made to restrict both reads and writes to the proper behavior, but also reinforce the the fact that only the last frame of the last sequence of data transfer can have a nonn 0 module 4 value. The restriction is placed in this clause. Because clause 9.2.2 actually references a different field, it will remain unchanged.

8.41: StoreTek Comment # 41 (Technical)

PDF Page # 38 Paper Page # 22 Section # 6 Paragraph #

Problem: This clause does not indicate the required order of logins prior to PRLI.

Solution: Add a paragraph that indicates the proper order of logging in. i.e. Flogi, Name Server, Plogi, Prli.

Response:

This specified in FC-FS 17.3 and 17.4 and need not be specified again here. It is also mentioned in some profiles. This is also mentioned in the discovery protocol annex, which is informative. No change should be made. This response was approved by the May 15, 2000 meeting of the FCP-2 working group.

Installation:

No change was required.

8.42: StoreTek Comment # 42 (Technical)

PDF Page # 38 Paper Page # 22 Section # 6.1 Paragraph # 5

Problem: In the description of the process login modes, what controls these modes are not stated.

Solution: Add "(Establish Image Pair = 0)" and "(Establish Image Pair = 1)".

Response:

The text will be reviewed and clarified if required. This response was approved by the May 15, 2000 meeting of the FCP-2 working group.

Installation:

The establish image pair forward reference was installed in 6.2.

8.43: StoreTek Comment # 43 (Editorial)

PDF Page # 38, 39 Paper Page # 22, 23 Section # Paragraph #

Problem: Inconsistent usage.

Solution: Add (or remove) period after all "(See FC-FS)" references.

Response:

Accepted.

Installation:

Installed as requested in 6

8.44: StoreTek Comment # 44 (Technical)

PDF Page # 41 Paper Page # 25 Section # Table # 11

Problem: Command/Data Mixed Allowed and Data/Response Mixed Allowed should not be obsoleted at this time.

Solution: Reactivate these features.

Response:

This change has been repeatedly approved by the committee. No change will be made. This response was approved by the May 15, 2000 meeting of the FCP-2 working group.

Installation:

No change was made.

8.45: StoreTek Comment # 45 (Editorial)

PDF Page # 43 Paper Page # 27 Section # 6.2.6.12 Paragraph # Sun clause name

Problem: The term "XFER_RDY" is not defined in this document.

Solution: Define this term in Clause 3.

Response:

Accepted in principle. The proper term is "FCP_XFER_RDY IU".

Installation:

Section 6 was made consistent. No reference was required, since this is all properly defined in the text of the standard. This also had to be corrected in 9.2,

8.46: StoreTek Comment # 46 (Editorial)

PDF Page # 43 Paper Page # 27 Section # 6.2.6.12 Paragraph # 1

Problem: The "XFER_RDY" is not correct.

Solution: Replace "XFER_RDY" with "FCP_XFER_RDY IU".

Response:

Accepted.

Installation:

Section 6 was made consistent.

8.47: StoreTek Comment # 47 (Editorial)

PDF Page # 43 Paper Page # 27 Section # 6.2.6.13 Paragraph # 1

Problem: Wording.

Solution: Second sentence, replace "may be not used" with "may not be used".

Response:

The words have two separate meanings. The meaning from the first is correct.

This resolution was accepted in the June 7, 2000 working group meeting.

Installation:

This comment was corrected by another comment.

8.48: StoreTek Comment # 48 (Technical)

PDF Page # 44 Paper Page # 28 Section # Table # 12

Problem: Command/Data Mixed Allowed and Data/Response Mixed Allowed should not be obsoleted at this time.

Solution: Reactivate these features.

Response:

This change has been repeatedly approved by the committee. No change will be made. This response was approved by the May 15, 2000 meeting of the FCP-2 working group.

Installation:

No change was made.

8.49: StoreTek Comment # 49 (Editorial)

PDF Page # 44 Paper Page # 28 Section # 6.2.7.1 Paragraph #

Problem: Font.

Solution: "ACCEPT RESPONSE CODE" should not be bold.

Response:

Accepted.

Installation:

The words are presently lower case small caps plain font. No change was required.

8.50: StoreTek Comment # 50 (Editorial)

PDF Page # 46 Paper Page # 30 Section # 7.1 Paragraph # 1

Problem: Wording.

Solution: Change "registered for a the requested" to "registered for the requested"

Response:

Accepted.

Installation:

Rewritten by response to 8.52.

8.51: StoreTek Comment # 51 (Technical)

PDF Page # 46 Paper Page # 30 Section # 7.2 Paragraph # 1 Problem: FC-GS-3 specifies the objects as: - Register FC-4 Descriptors (RFD_ID) - Get FC-4 Descriptors (GFD_ID)

Solution: Use same objects as FC-GS-3.

Response:

Accepted. This response was approved by the May 15, 2000 meeting of the FCP-2 working group.

Installation:

Rewritten by response to 8.52.

8.52: StoreTek Comment # 52 (Technical)

PDF Page # 46 Paper Page # 30 Section # 7.2 Paragraph # 1

Problem: FC-GS-3 specifies the objects by port identifier (i.e. not port name).

Solution: Use port identifier.

Response:

This is now all included in FC-GS-3, but was not at the time this was written. The text will be completely rewritten to reference FC-GS-3 for the Query and Register commands.

Terminology for the FCP specific object will be made consistent with FC-GS-3. This response was approved by the May 15, 2000 meeting of the FCP-2 working group.

Installation:

Totally rewritten to meet these requirements.

8.53: StoreTek Comment # 53 (Technical)

PDF Page # 46 Paper Page # 30 Section # 7.2 Paragraph # 2

Problem: Currently the FCP object would only apply to an FCP Target device. It's not clear who is supposed to issue the Register request either. I can see a benefit if each Target device would Register it's Inquiry data, could this be expanded to the LUN level also?

Solution: Clarify who issues the register request.

Response:

This function should not be expanded to the LUN level. Otherwise, the comment is accepted.

This response was approved by the May 15, 2000 meeting of the FCP-2 working group.

Installation:

Installed as approved. Rewritten by response to 8.52

8.54: StoreTek Comment # 54 (Editorial)

PDF Page # 47 Paper Page # 31 Section # 8 Paragraph # 1

Problem: The last sentence makes reference to "ELS" incorrectly when talking about SRR.

Solution: Replace "ELS" with "FC-4 Link Service" here and through out the document as necessary.

Response:

Accepted.

Installation:

Installed as requested in clauses 4, 8, 11, and 12.

8.55: StoreTek Comment # 55 PDF (Technical)

Page # 47 Paper Page # 31 Section # 8 Table # 15

Problem: The Table and the text do not specify what the "Encoded Value (bits 31-24)" are.

Solution: Add text that indicates they are the first word of the payload of the request or the reply.

Response:

Accepted. This response was approved by the May 15, 2000 meeting of the FCP-2 working group.

Installation:

Installed as requested.

8.56: StoreTek Comment # 56 (Editorial)

PDF Page # 47 Paper Page # 31 Section # 8.1 Paragraph # last

Problem: Missing period.

Solution: Add a period to the end of the last sentence.

Response:

Accepted.

Installation:

Installed as requested.

8.57: StoreTek Comment # 57 (Technical)

PDF Page # 48 Paper Page # 32 Section # 8.1 Payload: Paragraph # 3

Problem: The last sentence indicates recovery shall be on a four-byte boundary. However, nowhere else can I find the approved restriction on fixed block record length of 0 modulo 4.

Solution: Add text detailing the fixed block length restriction into sub clause 5.6.11 and/or create a new sub clause somewhere that defines this.

Response:

Accepted. This response was approved by the May 15, 2000 meeting of the FCP-2 working group.

Installation:

After resolving other comments as well, a similar change was installed in 5.6.11.

8.58: StoreTek Comment # 58 (Editorial)

PDF Page # 49 Paper Page # 33 Section # 8.3 Paragraph # 6

Problem: The last sentence on the page is incomplete and it also appears to be the same as the Table 19 title.

Solution: Complete this sentence and make a reference to table 19.

Response:

Accepted.

Installation:

Corrected by other rewrite requirements.

8.59: StoreTek Comment # 59 (Editorial)

PDF Page # 50 Paper Page # 34 Section # 8.3 Table # 19

Problem: The title of Table 19 needs to be clarified.

Solution: Add "of Payload" to the end of the Table title.

Response:

Accepted.

Installation:

Corrected by other rewrite requirements.

8.60: StoreTek Comment # 60 (Editorial)

PDF Page # 50 Paper Page # 34 Section # 8.3 Paragraph:

Problem: Missing Colon. Solution: Add a colon after "Protocol Error" in Reason Code Descriptions.

Response:

Accepted.

Installation:

Installed as requested.

8.61: StoreTek Comment # 61 (Editorial)

PDF Page # 50 Paper Page # 34 Section # 8.3 Paragraph: Reason explanation

Problem: Wording. Solution: Change "Table 21 shows expanded explanations" to "Table 21 lists the reason code explanations".

Response:

Accepted.

Installation:

Installed as requested.

8.62: StoreTek Comment # 62 (Editorial)

PDF Page # 50 Paper Page # 34 Section # 8.3 Table # 19

Problem: The byte 1 column has the bits incorrectly labeled.

Solution: Change the bits to "23-16".

Response:

Accepted.

Installation:

Installed as requested.

8.63: StoreTek Comment # 63 (Editorial)

PDF Page # 50 Paper Page # 34 Section # 8.3 Table # 20

Problem: This table is not referenced by any text.

Solution: Add a reference to this table under FCP_RJT Reason Code Descriptions.

Response:

Accepted.

Installation:

Installed as requested.

8.64: StoreTek Comment # 64 (Editorial)

PDF Page # 51 Paper Page # 35 Section # 8.3 Table # 21

Problem: The table title is inconsistent with the text that references it.

Solution: Remove "code" from the title.

Response:

Accepted.

Installation:

Installed with minor editorial changes.

8.65: StoreTek Comment # 65 (Editorial)

PDF Page # 51 Paper Page # 35 Section # 8.3 Table # 21

Problem: Blank rows in table.

Solution: Remove two blank rows.

Response:

Accepted.

Installation:

Installed as requested.

8.66: StoreTek Comment # 66 (Editorial)

PDF Page # 52 Paper Page # 36 Section # 9.1 Paragraph # 1

Problem: The last sentence is missing a period.

Solution: Add a period.

Response:

Accepted.

Installation:

Installed as requested.

8.67: StoreTek Comment # 67 (Technical)

PDF Page # 52 Paper Page # 36 Section # 9.1.1.1 Paragraph # 2

Problem: Second sentence text implies that all LUNs must be the same device type.

Solution: Remove the second sentence.

Response:

Accepted. This response was approved by the May 15, 2000 meeting of the FCP-2 working group.

Installation:

Installed as requested. Note that this modifies a previously resolved issue, but appears acceptable there too.

8.68: StoreTek Comment # 68 (Editorial)

PDF Page # 54 Paper Page # 38 Section # 9.1.1.4 Paragraph # Clear ACA section.

Problem: NORMACA should be in small caps.

Solution: Change font for NORMACA in two places.

Response:

Accepted.

Installation:

Installed consistent with SPC-2 as NORMACA.

8.69: StoreTek Comment # 69 (Editorial)

PDF Page # 55 Paper Page # 39 Section # 9.1.1.4 Paragraph # Logical Unit Reset

Problem: In item 6) there is a reference to "(see 4.11)". Clause 4.11 does not exist.

Solution: Correct the reference as necessary.

Response:

Accepted.

Installation:

Removed to resolve a previous comment.

8.70: StoreTek Comment # 70 (Editorial)

PDF Page # 55 Paper Page # 39 Section # 9.1.1.4 Paragraph # Logical Unit Reset section, just before note.

Problem: TARGET RESET should be LOGICAL UNIT RESET.

Solution: Replace TARGET RESET with LOGICAL UNIT RESET.

Response:

Accepted.

Installation:

Installed during rewrite of relevant paragraphs.

8.71: StoreTek Comment # 71 (Technical)

PDF Page # 56 Paper Page # 40 Section # 9.1.1.4 Paragraph # Abort Task Set section, third paragraph.

Problem: Description used in previous task management function should also apply here.

Solution: Change to "For a target FCP_Port, an exchange is also in an ambiguous state if the exchange exists between the target FCP_Port and an initiator other than the initiator FCP_Port that performed the ABORT TASK SET".

Response:

Accepted. This response was approved by the May 15, 2000 meeting of the FCP-2 working group.

Installation:

Installed as part of rewrite for a previous comment.

8.72: StoreTek Comment # 72 (Editorial)

PDF Page # 56 Paper Page # 40 Section # 9.1.1.6 Paragraph # 1

Problem: This sub clause describes the "Read Data" field, but Table 22 has this bit labeled differently.

Solution: Change the sub clause title and text with "RDDATA".

Response:

Accepted.

Installation:

Installed as requested.

8.73: StoreTek Comment # 73 (Editorial)

PDF Page # 56 Paper Page # 40 Section # 9.1.1.7 Paragraph # 1

Problem: This sub clause describes the "Write Data" field but table 22 has this bit labeled differently.

Solution: Change the sub clause title and text with "WRDATA".

Response:

Accepted.

Installation:

Installed as requested.

8.74: StoreTek Comment # 74 (Editorial)

PDF Page # 57 Paper Page # 41 Section # 9.1.2.2 Paragraph # 3 & 4

Problem: There are two references to "FFFF h".

Solution: Remove the space character before the h in these and any other binary or hex numbers used through out the document.

Response:

Accepted.

Installation:

Installed as requested.

8.75: StoreTek Comment # 75 (Editorial)

PDF Page # 58 Paper Page # 42 Section # 9.2.1 Paragraph # Sun clause name

Problem: The term "DATA_RO" is not defined in this document.

Solution: Define this term in Clause 3.

Response:

This value is defined in FC-FS section 12.2 by the somewhat cumbersome name "Offset of data being transferred." The term DATA_RO will be changed to FCP_DATA_RO, for consistency with past implementations and definitions. The term will then be defined using the FC-FS wording.

This resolution was accepted in the June 7, 2000 working group meeting.

Installation:

Installed as requested. Stronger references are provided in 9.2.1 for correlation with FC-FS. The term is also corrected in clause 10.

8.76: StoreTek Comment # 76 (Technical)

PDF Page # 58 Paper Page # 42 Section # 9.2.1 Paragraph #

Problem: Missing restriction on Relative Offset.

Solution: Specify the Relative Offset shall be 0 modulo 4.

Response:

Accepted. This response was approved by the May 15, 2000 meeting of the FCP-2 working group.

Installation:

Installed as approved.

8.77: StoreTek Comment # 77 (Editorial)

PDF Page # 58 Paper Page # 42 Section # 9.2.2 Paragraph # Sun clause name

Problem: The term "BURST_LEN" is not defined in this document.

Solution: Define this term in Clause 3.

Response:

This value is defined in FC-FS section 12.2 by the somewhat cumbersome name "Length of data being transferred." The term BURST_LEN will be changed to FCP_BURST_LEN, for consistency with past implementations and definitions. The term will then be defined using the FC-FS wording.

This resolution was accepted in the June 7, 2000 working group meeting.

Installation:

The term was modified. Since it is used nowhere else in the document and is well defined by the text, there is no need to place it in the glossary.

8.78: StoreTek Comment # 78 (Editorial)

PDF Page # 58 Paper Page # 42 Section # 9.2.2 Paragraph # 2

Problem: There is a reference to "(see 9.3)" that is incorrect.

Solution: Replace the "9.3" with "10.1.1.6".

Response:

Accepted.

Installation:

Installed as requested.

8.79: StoreTek Comment # 79 (Technical)

PDF Page # 59 Paper Page # 43 Section # 9.3 Paragraph # 4

Problem: The last sentence of paragraph conflicts with 9.2 paragraph 2 second sentence. Only true for the first burst, subsequent bursts must use the FCP_XFER_RDY

Solution: Specify the restriction.

Response:

Accepted. This response was approved by the May 15, 2000 meeting of the FCP-2 working group.

Installation:

Installed as requested.

8.80: StoreTek Comment # 80 (Editorial)

PDF Page # 59 Paper Page # 43 Section # 9.3 Paragraph # 5

Problem: There is a reference to 9.4.1 that is incorrect.

Solution: Replace "9.4.1" with "9.4.2".

Response:

Accepted.

Installation:

Installed as requested.

8.81: StoreTek Comment # 81 (Editorial)

PDF Page # 71 Paper Page # 55 Section # 10.1.3.2 Paragraph # Heading

Problem: Spelling error.

Solution: Change "INITIATIED" to "INITIATED"..

Response:

Accepted.

Installation:

Installed as requested.

8.82: StoreTek Comment # 82 (Editorial)

PDF Page # 71 Paper Page # 55 Section # 10.1.3.2 Paragraph # 1

Problem: Typo.

Solution: Change "A LPE primitive sequences addressed..." to "A LPE primitive sequence addressed...".

Response:

Accepted.

Installation:

Installed as requested.

8.83: StoreTek Comment # 83 (Editorial)

PDF Page # 72 Paper Page # 56 Section # 10.1.3.6 Paragraph # 1

Problem: The second to the last sentence needs a reference to FC-TAPE added with FC-PLDA and FC-FLA.

Solution: Add the reference.

Response:

Accepted.

Installation:

Installed as requested.

8.84: StoreTek Comment # 84 (Editorial)

PDF Page # 73 Paper Page # 57 Section # 10.1.3.8 Paragraph # 1

Problem: Style.

Solution: First sentence, change "a fabric loop port, FL_Port, on the loop." to "a fabric loop port (FL_Port), on the loop."

Response:

Accepted.

Installation:

In response to a previous request, the FL_Port abbreviation, used nowhere else in the document, was simply deleted.

8.85: StoreTek Comment # 85 (Editorial)

PDF Page # 73 Paper Page # 57 Section # 10.1.3.8 Paragraph # 1

Problem: The second sentence needs a reference to FC-TAPE added with FC-PLDA.

Solution: Add the reference.

Response:

Accepted.

Installation:

Installed as requested.

8.86: StoreTek Comment # 86 (Editorial)

PDF Page # 73 Paper Page # 57 Section # 10.1.3.10 Paragraph # 2

Problem: Missing reason for ref.

Solution: change "See NCITS 1304-D." to "See NCITS 1304-D for a description of MCM operations."

Response:

All references to MCM are removed. Accepted in principle.

Installation:

Installed as approved.

8.87: StoreTek Comment # 87 (Editorial)

PDF Page # 76 Paper Page # 60 Section # 11.4 Paragraph # 1

Problem: Wording.

Solution: First sentence, change "provide minimum" to provide a minimum".

Response:

Accepted.

Installation:

Installed as requested.

8.88: StoreTek Comment # 88 (Editorial)

PDF Page # 78 Paper Page # 62 Section # 12.1.2 Paragraph # 1

Problem: Format.

Solution: Remove extra blank line between heading and first paragraph.

Response:

Accepted.

Installation:

Changed as requested.

8.89: StoreTek Comment # 89 (Editorial)

PDF Page # 78 Paper Page # 62 Section # 12.1.1 & 12.1.2 Paragraph # 1

Problem: The word "chapter" is used in these paragraphs.

Solution: Replace "chapter" with "clause".

Response:

Accepted.

Installation:

Corrected during rewrite of relevant paragraphs.

8.90: StoreTek Comment # 90 (Editorial)

PDF Page # 78 Paper Page # 63 Section # 12.1.2 Paragraph # 3

Problem: Formatting.

Solution: Third paragraph, appears to be a larger font size. Change it to match others.

Response:

Accepted.

Installation:

Corrected as requested.

8.91: StoreTek Comment # 91 (Editorial)

PDF Page # 78 Paper Page # 62 Section # 12.1.2 Paragraph # 4

Problem: A reference to Annex E needs to be added with Annex D.

Solution: Add "" and Annex E" to the end of the sentence.

Response:

Accepted.

Installation:

Changed as requested.

8.92: StoreTek Comment # 92 (Editorial)

PDF Page # 78 Paper Page # 62 Section # 12.2.1 Paragraph # Step 2

Problem: Wording.

Solution: Change "in an Sequence" to "in a Sequence".

Response:

Accepted.

Installation:

Changed as requested.

8.93: StoreTek Comment # 93 (Editorial)

PDF Page # 78 Paper Page # 62 Section # 12.2.1 Paragraph # Step 4

Problem: Typo.

Solution: Remove space between "0 b".

Response:

Accepted.

Installation:

Changed to read "0".

8.94: StoreTek Comment # 94 (Editorial)

PDF Page # 79 Paper Page # 63 Section # 12.2.2 Paragraph # Third paragraph, Step 4

Problem: Wording.

Solution: Change "in an Sequence" to "in a Sequence".

Response:

Accepted.

Installation:

Corrected by a previous comment that removed the offending text.

8.95: StoreTek Comment # 95 (Technical)

PDF Page # 79 Paper Page # 63 Section # 12.2.2 Paragraph # 4, Step 4

Problem: Missing requirement.

Solution: Indicate the RRQ should be sent after expiration of R_A_TOV.

Response:

Accepted. This response was approved by the May 15, 2000 meeting of the FCP-2 working group.

Installation:

The text is modified as follows:

If an ACK is received with the F_CTL Abort Sequence Condition bits set to Abort Sequence, Perform ABTS, the Sequence Initiator shall send an ABTS for ~~a specified the~~ Sequence. After R_A_TOV times out, an RRQ shall be sent by the Sequence Initiator. ~~followed by an RRQ when the BA_ACC is received for the ABTS.~~

8.96: StoreTek Comment # 96 (Editorial)

PDF Page # 80 Paper Page # 64 Section # 12.3.2 Paragraph # 3

Problem: Spelling error.

Solution: Change "minimum interal" to "minimum interval".

Response:

Accepted.

Installation:

Changed as requested.

8.97: StoreTek Comment # 97 (Editorial)

PDF Page # 80 Paper Page # 64 Section # 12.3.3 Paragraph # 2

Problem: The SRR is being described as an "Extended Link Service".

Solution: Through out the document replace "Extended Link Service" with "FC-4 Link Service".

Response:

Accepted.

Installation:

Corrected in clause 12

8.98: StoreTek Comment # 98 (Editorial)

PDF Page # 83 Paper Page # 67 Section # 12.4 Paragraph # step b.

Problem: Typo.

Solution: Change "FCP_CONF:" to "FCP_CONF;".

Response:

Accepted.

Installation:

Corrected as requested.

8.99: StoreTek Comment # 99 (Editorial)

PDF Page # 84 Paper Page # 68 Section # 12.5.2 Paragraph #

Problem: Typo.

Solution: Change two instances of "FFFF h" to "FFFFh".

Response:

Accepted.

Installation:

Corrected as requested.

8.100: StoreTek Comment # 100 (Editorial)

PDF Page # 85 Paper Page # 69 Section # 12.7 Paragraph # 4

Problem: There is a "see TBD" in the text.

Solution: Replace the TBD with the correct reference.

Response:

Accepted.

Installation:

Deleted as requested.

8.101: StoreTek Comment # 101 (Editorial)

PDF Page # Paper Page # 71 Section # A.1 Paragraph # 2

Problem: Editors notes should not be in released standards.

Solution: Remove the note.

Response:

Accepted.

Installation:

Installed as requested.

8.102: StoreTek Comment # 102 (Technical)

PDF Page # 87 Paper Page # 71 Section # A.1 Paragraph # Table A.1

Problem: The object identifier and object address entries contain the same procedure terms.

Solution: Change one of them?

Response:

They can both be deleted because they are not used anyplace in FCP-2 and because they are fully defined in SAM-2 with terms defined within SAM-2. This response was approved by the May 15, 2000 meeting of the FCP-2 working group.

Installation:

Installed as requested.

8.103: StoreTek Comment # 103 (Technical)

PDF Page # 89 Paper Page # 73 Section # A.3 Paragraph # Table A.3

Problem: What does || in table indicate?

Solution: Each entry in the third column contains a "||". Is there something missing? Also, does a CRN/value and FCP_CONF request belong in this table?

Response:

This symbol has been used in SAM-2 to represent a demarcation between inputs and outputs. Inputs come before the symbol, outputs afterwards. This symbol is undesirable and will be replaced with the text:

command (IN(a,b,c),OUT(x,y,z))

This response was developed and approved by the May 15, 2000 meeting of the FCP-2 working group.

Installation:

Installed as requested.

8.104: StoreTek Comment # 104 (Technical)

PDF Page # 89 Paper Page # 73 Section # A.4 Paragraph #

Problem: What does || indicate?

Solution: A "||" appears inside the procedure call without explanation. Explain or remove.

Response:

This symbol has been used in SAM-2 to represent a demarcation between inputs and outputs. Inputs come before the symbol, outputs afterwards. This symbol is undesirable and will be replaced with the text:

command (IN(a,b,c),OUT(x,y,z))

This response was developed and approved by the May 15, 2000 meeting of the FCP-2 working group.

Installation:

Installed as requested.

8.105: StoreTek Comment # 105 (Technical)

PDF Page # 89 Paper Page # 74 Section # A.4 Table # A.4

Problem: What does || indicate?

Solution: A "||" appears without explanation. Explain or remove.

Response:

This symbol has been used in SAM-2 to represent a demarcation between inputs and outputs. Inputs come before the symbol, outputs afterwards. This symbol is undesirable and will be replaced with the text:

command (IN(a,b,c),OUT(x,y,z))

This response was developed and approved by the May 15, 2000 meeting of the FCP-2 working group.

Installation:

Installed as requested.

8.106: StoreTek Comment # 106 (Technical)

PDF Page # 89 Paper Page # 74 Section # A.5 Paragraph #

Problem: What does || indicate?

Solution: A "||" appears inside the procedure call without explanation. Explain or remove.

Response:

This symbol has been used in SAM-2 to represent a demarcation between inputs and outputs. Inputs come before the symbol, outputs afterwards. This symbol is undesirable and will be replaced with the text:

command (IN(a,b,c),OUT(x,y,z))

This response was developed and approved by the May 15, 2000 meeting of the FCP-2 working group.

Installation:

Installed as requested.

8.107: StoreTek Comment # 107 (Editorial)

PDF Page # 90 Paper Page # 74 Section # A.5.1 Paragraph # 2

Problem: The second sentence makes reference to SCSI "parallel" interface.

Solution: Remove the "parallel" reference.

Response:

Accepted.

Installation:

Installed as requested.

8.108: StoreTek Comment # 108 (Editorial)

PDF Page # 91 Paper Page # 75 Section # A.5.1.1 - A.5.1.7 Paragraph # 1

Problem: The first sentence of each of these sub clauses makes reference to SCSI "parallel" interface.

Solution: Remove the "parallel" reference.

Response:

Accepted.

Installation:

Installed as requested.

8.109: StoreTek Comment # 109 (Editorial)

PDF Page # 98 Paper Page # 82 Section # C.1.4 Table # C.4

Problem: Missing note.

Solution: Add note contained in clause C.1.1.

Response:

Accepted.

Installation:

Installed as requested.

8.110: StoreTek Comment # 110 (Editorial)

PDF Page # 99 Paper Page # 79 Section # B.3.1 Paragraph # ? Problem:

Typo after "Accept payload:" header.

Solution: Remove the "-" before the sentence.

Response:

Accepted.

Installation:

Installed as requested in 8.2.

8.111: StoreTek Comment # 111 (Editorial)

PDF Page # 105 Paper Page # 89 Section # D Paragraph # Heading

Problem: Improve wording.

Solution: Change heading to "Examples of error detection and recovery actions".

Response:

Accepted.

Action:

Title was changed to "Error detection and recovery action examples".

8.112: StoreTek Comment # 112 (Editorial)

PDF Page # 111 Paper Page # 95 Section # Annex D Figure # D.7

Problem: The last sentence of the error recovery text in the figure body "(or a Relative...)" is incorrect.

Solution: Remove "(or a Relative Offset smaller than the Relative Offset specified in the SRR in order to be aligned on an appropriate boundary in the Target)". This issue was debated and the group determined the Target shall use the specified Relative Offset in the SRR only (and use 0 modulo 4).

Response:

Accepted.

Action:

Corrected in draft of revision 5.

8.113: StoreTek Comment # 113 (Editorial)

PDF Page # 112 Paper Page # 96 Section # Annex D Figure # D.8

Problem: The last sentence of the Error Recovery text in the figure body "(or a Relative...)" is incorrect.

Solution: Remove "(or a Relative Offset smaller than the Relative Offset specified in the SRR in order to be aligned on an appropriate boundary in the Target)". This issue was debated and the group determined the Target shall use the specified Relative Offset in the SRR only (and use 0 modulo 4).

Response:

Accepted.

Action:

Corrected in draft of revision 5.

8.114: StoreTek Comment # 114 (Editorial)

PDF Page # 122 Paper Page # 106 Section # E.3.2 Paragraph # 2

Problem: The 3rd sentence states through the "tenth" block, which is incorrect.

Solution: Replace "tenth" with "twelfth".

Response:

Accepted.

Installation:

Installed as requested.

8.115: StoreTek Comment # 115 (Editorial)

PDF Page # 122 Paper Page # 106 Section # E.3.2 Paragraph # 2 Problem:

The 4th sentence states the FCP_RSP "will also be retransmitted" is incorrect.

Solution: Replace "will also be retransmitted" with "will be transmitted".

Response:

Accepted.

Installation:

Depending on the timing, it may be either. That change was made.

8.116: StoreTek Comment # 116 (Editorial)

PDF Page # 125 Paper Page # 109 Section # F Paragraph #

Problem: Update to match later document.

Solution: Update the text to match document T11/99-340v3 on the web site (it's actually v4 as indicated in the document text). I (DAP) will be updating this document as a result of recent FC-GS-3 work. The new document number will be 00-039v0.

Response:

Accepted.

Installation:

I hope my rewrite caught all the problems, because 00-039v0 is not available on the web at the moment.

8.117: StoreTek Comment # 117 (Technical)

PDF Page # 126 Paper Page # 110 Section # F.2 Paragraph # 5

Problem: In item 4 there is reference to ADISC, should PDISC also be included?

Solution: Add PDISC to the text as necessary.

Response:

This is informative. No change is required. This response was approved by the May 15, 2000 meeting of the FCP-2 working group.

Installation:

No change was required.

8.118: StoreTek Comment # 118 (Technical)

PDF Page # 133 Paper Page # 117 Section # I.1 Paragraph #

Problem: Should multi-initiator Reserve/Release be mentioned here?

Solution: This looks like a good spot for some text regarding Reserve/Release in a multi-initiator environment and I (DAP) am willing to do the work.

Response:

Proposal required. What would be said that is not already a standard somewhere else?

The committee, in their May 15, 2000 meeting, suggested that I.1 should be changed to require the requirements of the target reset definitions and related changes. In addition, it was proposed to add text referencing SPC-2, recommending persistent reservation and perhaps normal reservations as desirable for multi-initiator behavior.

This resolution was accepted in the June 7, 2000 working group meeting, although the results must be verified carefully.

Installation:

See SPC-2, clause 5.5.3.1. No change was made. Annex I remains deleted.

8.119: StoreTek Comment # 119 (Editorial)

PDF Page # 135 Paper Page # 119 Section # J Paragraph #

Problem: Requirements for other standards should be in the other standards.

Solution: Remove Annex J after submitting proposals against future versions of the affected standards. If this is not done, at least edit Annex J to remove phrases like "I believe".

Response:

Accepted.

Installation:

Annex J is deleted.

8.120: StoreTek Comment # 120 (Editorial)

PDF Page # 137 Paper Page # cxxix Section # ? Paragraph # ? Problem: This list of figures has been duplicated.

Solution: Remove the list of figures and verify the document ending page number.

Response:

Accepted.

Installation:

Installed as requested.

9 Sun Microsystems

The following comments were received from Bob Snively of Sun Microsystems

9.1 Sun 1 Document references

Editorial

All sections. Document references are inconsistent or not helpful. Most people cannot hold the numbers of the various standards in their head, yet NCITS/ANSI prefers that the numbers of the referenced standards be used as the method for designating documents. Examples include:

3.4 last sentence: document cited as “FC-FS”

4.1 first paragraph: document cited as “ANSI X3.230”

6.2.7.2 first paragraph: document cited as “ANSI X3.297”

Assuming this is acceptable to the editors, I would prefer to use either the document name exclusively, or both the document name and the document number together. As examples: “FC-FS” or “FC-PH, X3.230”

Response:

Accepted: See 4.29.

Installation:

Installed as requested by 4.29.

9.2 Sun 2 Use of word FCP

Editorial

All sections. The word “FCP” is used as a noun, in the context “The FCP...” while referring to the protocol. This looks like terrible English and reads very badly.

I would like to see the words “Fibre Channel protocol” used when speaking of the protocol, and the words “FCP standard” when referring to the document. See in particular:

Section 5.5, page 19: “The FCP” s/b “Fibre Channel Protocol”

Annex A.1, page 71. “The FCP-2” s/b “This standard”

Response:

Accepted. See related comments by other commentors.

Installation:

Installed as requested. FCP and FCP-2 continue to be used as adjectives.

9.3 Sun 3 Correct hexadecimal references

Editorial

All sections. The conventions for hexadecimal notation (AB1Ch) are not followed consistently. Corrections need to be installed everywhere, particularly sections 6.1 (p22), 9.1 (p36), 11.3 (p60),

Response:

Accepted.

Installation:

Installed as requested in clauses 6, 9, 11, B, D, and E.

9.4 Sun 4 Update contacts

Editorial

page ii. The E-mail addresses for the X3T10 chair and the T10 reflector must be updated. The SCSI BBC information must be updated. The references to X3 must be changed to NCITS.

Response:

Accepted.

Installation:

Installed as requested.

9.5 Sun 5 Remove document revision history

Editorial

page iii. The document revision history should be removed.

Response:

Accepted.

Installation:

Installed as requested.

9.6 Sun 6 Combine annexes into primary table of contents

Editorial

page viii. The annex table of contents should be moved from page x and appended to the normal table of contents on page viii.

Response:

Accepted.

Installation:

Installed as requested.

9.7 Sun 7 Correct document description

Editorial

Section "Introduction", page xv.

Clause 7 should be inserted in the document description with text that says: "Clause 7 describes the FC-4 specific name server object for FCP."

Annex E should be inserted with text that says "Annex E is an informative annex providing examples of error recovery procedures."

Annex G should be inserted with text that says "Annex G is an informative annex showing examples of ELS formats required for proper FCP-2 recovery operations."

The text describing removal of annexes should clarify that the referenced document is the old standard.

Text for annexes H, I, and J should be inserted.

Response:

Accepted.

Installation:

Installed as requested. Much of the offending text was deleted.

9.8 Sun 8 Remove redundant sentence

Editorial

Page 2, Clause 2.3, first paragraph, last sentence is redundant and should be deleted.

Response:

Accepted.

Installation:

Installed as requested.

9.9 Sun 9 Clarify definition of base address

Editorial

Page 2, clause 3.1.5, the definition should be replaced with “base address: The virtual address of the byte having the lowest address among the bytes to be transferred to or from an application client buffer.”

Response:

Accepted.

Installation:

An alternate definition was used.

9.10 Sun 10 Data overlay definition restriction

Editorial

Page 3, clause 3.1.13, the definition of data overlay should be corrected to exclude link recovery. “data overlay: Data overlay occurs when data is transferred to or from the same offset of the SCSI application client buffer more than once during the same command, except for the recovery of link transmission failures.”

Response:

Accepted.

Installation:

A new definition based on improvements in SAM-2 was selected instead.

9.11 Sun 11 Circular definition of MCM

Editorial

Page 3, 3.1.27, the definition of MCM should have the word “MCM” removed in the defining text in two locations. A reference to FC-AL-3 should be provided.

Response:

MCM is removed from the standard.

Installation:

Installed as requested.

9.12 Sun 12 typo

Editorial

Page 5, section 3.3.8. “standards” s/b “standard”.

Response:

Accepted.

Installation:

Installed as requested.

9.13 Sun 13 typo

Editorial

Page 6, section 3.4. second line s/b "...defined in the glossary or in the text..."

Response:

Accepted.

Installation:

Installed as requested.

9.14 Sun 14 Clarify number of sequences

Editorial

Page 8, section 4.1, next to the last sentence s/b "The maximum number of active sequences that can simultaneously be open between an initiator FCP_Port and a target FCP_Port is restricted by the allowable range of values of the Sequence ID to 256, as defined in FC-PH."

Response:

Accepted.

Installation:

Installed as requested.

9.15 Sun 15 Use of "the FCP"

Editorial

Page 8, section 4.2, first paragraph. The word "FCP" in this sentence should be replaced with "FCP host adapter" in three places.

Response:

Accepted.

Installation:

Installed as requested.

9.16 Sun 16 typo

Editorial

Page 8, section 4.2, 4th paragraph. "... command, has..." s/b "...command, and has..."

Response:

Accepted.

Installation:

Installed as requested.

9.17 Sun 17 typo

Page 8, Correct fonts in section 4.2, 5th paragraph.

Response:

Accepted.

Installation:

Installed as requested.

9.18 Sun 18 table typo

Page 11, section 4.6, Remove extra line in table 2.

Response:

Accepted.

Installation:

Installed as requested.

9.19 Sun 19 Clarify task management completion

Editorial

Page 12, section 4.7, second paragraph. Change “A task management function ends with an FCP_RSP IU that indicates whether it was correctly accepted.” to “A task management function ends with an FCP_RSP IU that indicates the completion status of the function.”

Response:

Accepted.

Installation:

Installed as requested.

9.20 Sun 20 Clearing effects of PRLI/PRLO

Technical

Page 13, table 4. In the column that indicates the clearing action for PRLI/PRLO, all the “Y” entries actually only apply for the affected image pair. This must either be indicated in a note or have a separate entry for that case in each relevant row.

Response:

Since Process Associators have been removed from FCP-2, there is now only one case to be considered. No change is required for this, but editorial improvements are still desirable, separating the table into “link clearing actions” and “protocol/SCSI clearing actions”. The response was approved by the FCP-2 working group meeting on May 15, 2000.

Installation:

Installed as requested.

9.21 Sun 21 Clearing effects on buffered data

Technical

This was presented by George Penokie on Jan 26, 2000. He suggests that reserved XOR data be cleared if there is a target power cycle, a reset LIP, a logout of all initiators, TPRLO, SCSI target reset, or a Logical Unit Reset. All other cases would preserve the data.

Response:

Accepted. The comment was extended to include Copy data and Extended Copy data. TPRLO could be a problem, since it is required for the necessary communications to occur. Further study will be done on this area and an action item assigned.

Extended Copy needs a specified behavior for targets, probably specified in the Receive Copy Results service action. I need to specify a behavior for each of the events with respect to buffered data, then refer to SAM-2 and SPC-2 to define the proper behavior.

This resolution was accepted in the June 7, 2000 working group meeting.

Installation:

FCP-2 SCSI Target Object	FCP-2 SCSI initiator action clears object									
	Target Power Cycle	Reset LIP(y,x) ³	LOGO ¹³ , PLOGI	PRLI ^{8,13} , PRLO	TPRLO ⁵	SCSI TARGET RESET	SCSI LOGICAL UNIT RESET ^{4,9}	Clear Task Set ⁴	Abort Task Set ⁴	ABTS w/Last Seq.
Buffered data for XOR, EXTENDED COPY, COPY For all SCSI initiator ports Only for SCSI initiator port initiating action	Y	Y	N Y	N Y	Y -	Y -	Y -	Y -	N -Y	N N

9.22 Sun 22 Clarification of mode page management

Editorial

Page 14, table 5, column 4. The column should indicate that this is the state after the PRLI/PRLO has been executed.

Response:

Accepted.

Installation:

Installed as requested.

9.23 Sun 23 typo

Editorial

Page 15, section 4.9, title. The title should indicate that this references only Process Login/Logout.

Response:

Accepted.

Installation:

Installed as requested.

9.24 Sun 24 Process Login image definition

Technical

Page 16, section 5.1, second paragraph. In this paragraph, it is clearly stated that the process associator does not take place in the identification of the initiator or target. However, in the third sentence, there is a left-over sentence that indicates that more than one logical initiator or logical target image may be defined by the process associator. The sentence "More than one logical initiator or logical target image may be defined..." should be deleted.

Response:

Process Associator is now removed from FCP-2. This text and any other text associated with Process Associators should be edited or removed. The response was approved by the FCP-2 working group meeting on May 15, 2000.

Installation:

Installed as requested.

9.25 Sun 25 Process Associator for FCP_Port addressability

Technical

Page 16, section 5.2. This section defines a process associator value for third-party referencing of FCP addresses. Since the Process Associator does not take part in the initiator or target definition, it is not

necessary to include the Process Associator in the definition. Table 7 should have the PA_VAL bit changed to reserved and the Process Associator field changed to reserved. Section 5.2.1 and 5.2.3 should be deleted.

Response:

Accepted. See 7.4. The response was approved by the FCP-2 working group meeting on May 15, 2000.

Installation:

Installed as requested.

9.26 Sun 26 Incorrect definition of Data Out IU T7

Editorial

Page 18, section 5.4, table 8. This is an editorial error that was not caught in the original FCP document. The T7 Data Out action IU can only occur when there are two consecutive write data sequences. With the final definition of Disable Write Data Transfer, all FCP_DATA IUs are separated by a XFER_RDY IU, making T7 an unused IU. T7 should be removed from the table and notes of table 8.

Response:

Accepted.

Installation:

Installed as requested.

9.27 Sun 27 Remnant of I2 IU needs to be removed

Editorial

Page 19, table 9, notes. The I2 data IU has been removed from the table. The third note should also have it removed.

Response:

Accepted.

Installation:

Installed as requested.

9.28 Sun 28 Clarify definition of tag

Technical?

Page 21, section 5.6.9. The third sentence indicates that the OX_ID is the tag defined by SAM. That is not strictly true, because the OX_ID exists for all exchanges, even those that have no tag definition. The sentence should be. "The value of the OX_ID is used to identify an FCP I/O Operation the same way that the tag value identifies I/O Operations in ANSI X3.270."

Response:

Accepted. The response was approved by the FCP-2 working group meeting on May 15, 2000.

Installation:

Installed as requested with minor corrections.

9.29 Sun 29 Correct RO requirements

Technical *****

Page 21, section 5.6.11, last sentence. The sentence indicates that RLTV_OFF is not required if both FCP_Ports can unambiguously reassemble the transmitted IUs. This creates severe interoperability

problems for those ports that may be attached that cannot perform this magic. This interoperability issue is not negotiated in any login parameters. The correct solution is to require the presence of the RO, then allow the recipient of the data to use the RO or other FC-PH mechanisms to reassemble the data.

Response:

Accepted. The response was approved by the FCP-2 working group meeting on May 15, 2000.

Installation:

Installed as requested.

9.30 Sun 30 Make Process Associator obsolete for FCP

Technical *****

Process Associators create a complex functionality that cannot successfully distinguish separate images in the initiator or the target. In the target, separate images (including both initiator and target enforced protection) are created using the logical unit. In the initiator, no separate images are explicitly defined, but they can be emulated by using more than one port address identifier for the initiator port. Since the function originally conceived of (but never practically implemented) by Process Associators in FCP can be done practically by other mechanisms more natural to both FC and SCSI, Process Associators should be made obsolete for FCP. Process Login should still be used to negotiate capabilities and to identify target/initiator pairs.

Response:

Accepted. The response was approved by the FCP-2 working group meeting on May 15, 2000.

Installation:

Installation required corrections to 5.1, 5.2.1, 6.2, major corrections to 6.3.2, 6.4,

Most of sub-clauses 5.2.2, 5.2.4, 6.3.3 and 6.3.4 were deleted.

9.31 Sun 31 Distinguish image pair and initiator/target pair

Technical *****

Section 6, all sections. In many places, image pair is referenced. However in some cases it is implicitly a relationship between initiator and target, and in other cases it is a relationship between initiator process image and target process image. The two cases should be distinguished by using the word “image pair” for those that use a process image and “initiator/target pair” for those that do not use a process image.

Response:

Accepted in principle. Since Process Associators are no longer used in FCP-2, image pair only defines initiator/target pairs now. This will be corrected by changes related to 9.30 Sun 30. The response was approved by the FCP-2 working group meeting on May 15, 2000.

Installation:

This was corrected by the response to 9.30 Sun 30.

9.32 Sun 32 typo

Editorial

Page 22, section 6, first paragraph. “extended link services in ANSI” s/b “extended link services defined in ANSI”

Response:

Accepted.

Installation:

Corrected by solution of a previous comment.

9.33 Sun 33 Correct login requirement

Editorial

Page 22, section 6, second paragraph, last sentence: is “Devices introduced into a configuration or modifications in the addressing or routing of the configuration may require new login procedures.”, should be “Devices introduced into a configuration or modifications in the addressing or routing of the configuration may require the login and discovery procedures to be executed again.”

Response:

Accepted.

Installation:

Installed as requested. Note that this improves a previous response.

9.34 Sun 34 Problem with process associators

Technical

Page 23, section 6.2.2: Refer to Sun 30. The originator for all FCP communications is the initiator. The mechanisms to manage multiple images behind a single initiator port are incomplete. Section 6.2, third paragraph is one example of this attempt to create an unsupported function. Similar problems exist in the corresponding paragraph of 6.2.1 and 6.2.3.

Response:

Accepted in principle. This will be corrected by the changes required to resolve comment 9.30 Sun 30. The response was approved by the FCP-2 working group meeting on May 15, 2000.

Installation:

These paragraphs were deleted or rewritten as part of the correction of 9.30 Sun 30.

9.35 Sun 35 Problem with clearing PRLI image pairs

Editorial

Page 24, section 6.2.5, first paragraph. The third sentence of this paragraph indicates how outstanding exchanges are affected by a PRLI. This is actually referenced in table 4, but incorrectly. See Sun 20. The correct solution is eliminate Process Associators. Failing that, a reference should be used here and the definition of the clearing effects should be placed in table 4.

Response:

Accepted.

Installation:

Changed as part of the solution to 9.30 Sun 30.

9.36 Sun 36 Correct behavior of new PRLI

Editorial

Page 24, second paragraph, reads in part:

Immediately after the execution of the first PRLI, both members of all image pairs shall have the same state as they would have after a hard reset or a power on with respect to each other. No tasks, reservations or status shall be present in either SCSI device. The MODE SELECT parameters will assume their default or saved states for all image pair. Tasks, reservations, status, and MODE SE-

LECT parameters for other initiators are not affected. A Unit Attention condition (Sense Key = 6) with an Additional Sense Code of Reset Occurred (ASC = 29, ASCQ = 00) shall be presented upon the first attempt to communicate between the N_Ports using FCP when a new PRLI has been performed. A target port shall not generate a unit attention condition for initiators which are already logged in. Subsequent PRLI operations shall have no effect on FCP operation between two devices except where new requirements are negotiated between the devices.

The text should be corrected as follows:

Immediately after the execution of ~~the first~~ any PRLI, both members of all new image pairs shall have the same state as they would have after a hard reset or a power on with respect to each other. No tasks, non-persistent reservations or status shall be present in either SCSI device. The MODE SELECT parameters will assume their default or saved states for ~~all~~ the new image pairs. Tasks, reservations, status, and MODE SELECT parameters for other ~~initiators~~ image pairs are not affected. A Unit Attention condition (Sense Key = 6) with an Additional Sense Code of Reset Occurred (ASC = 29, ASCQ = 00) shall be presented upon the first attempt to communicate between the N_Ports using FCP when a new PRLI image pair has been ~~performed~~ created. A target port shall not generate a unit attention condition for ~~initiators~~ initiator members of image pairs which are already logged in. Subsequent PRLI operations shall have no effect on FCP operation between two devices except where new requirements are negotiated between the devices.

This is another example of the problems associated with Process Associators.

Response:

Accepted. In the September 11, 2000 working group, it was pointed out that reference to the tables of clearing actions (Table 4) would be useful here.

Installation:

This was corrected as part of the rewrite associated with 9.30 Sun 30.

9.37 Sun 37 Correction to PRLI request

Technical

Page 25, section 6.2.6.4. If process associators are removed for FCP, the value for the Establish Image Pair field shall be 0.

Response:

Process associators are removed. Image pairs are still required. The response was approved by the FCP-2 working group meeting on May 15, 2000.

Installation:

No change was necessary.

9.38 Sun 38 Definition of process suspect

Editorial

Page 26, section 6.2.6.7, first paragraph. The word “process” in the first sentence should probably be replaced with the words “member of the image pair”, or alternatively, the words initiator and target should be used.

Response:

Accepted.

Installation:

Installed as requested.

9.39 Sun 39 Incorrect use of word “image pair”

Editorial

Page 26, section 6.2.6.7, third paragraph. The paragraph presently reads:

An image pair shall use the retransmission capability only if the RETRY bit is set in both the request payload and in the accept payload. If the RETRY bit is set to 0 in either the request payload or the accept payload, the SRR shall not be performed by the initiator. If the SRR is received by the target, the SRR shall be rejected with LS_RJT.

The text should read:

An ~~image pair~~ initiator and target port pair shall use the retransmission capability only if the RETRY bit is set in both the request payload and in the accept payload. If the RETRY bit is set to 0 in either the request payload or the accept payload, the SRR shall not be performed by the initiator. If ~~the an~~ SRR ~~ELS~~ is received by ~~the a~~ target ~~that has set the RETRY bit to 0~~, the SRR shall be rejected with LS_RJT.

Response:

Accepted.

Installation:

Installed as requested.

9.40 Sun 40 Correct Write XFER_RDY Disabled definition

Technical

Page 27, section 6.2.6.13, first two sentences should be rewritten as follows:

When this bit is set to 0, FCP_XFER_RDY IUs shall ~~be used~~ be transmitted by the target to request each of the SCSI write FCP_DATA IUs from the initiator. for SCSI write operations. When this bit is set to 1, FCP_XFER_RDY IUs ~~may be not~~ shall not be used before the first FCP_DATA IU to be transferred in the write operation.

Response:

Accepted. The response was modified and approved by the FCP-2 working group meeting on May 15, 2000.

Installation:

Installed as requested.

9.41 Sun 41 Complete Image Pair Established definition

Technical

Page 28, section 6.2.7.1, first paragraph should be rewritten as follows:

IMAGE PAIR ESTABLISHED is valid only if bit 13 was set to 1 on the corresponding Service Parameter page of the PRLI request and if the image pair was correctly established.

Response:

Accepted. Process associators are removed. Image pairs are still required. The response was approved by the FCP-2 working group meeting on May 15, 2000.

This resolution was accepted in the June 7, 2000 working group meeting.

Installation:

Another comment improved upon this resolution by referencing instead FC-FS.

9.42 Sun 42 Correct PRLO text

Technical *****

Page 29, section 6.3, first paragraph, should have the same corrections applied as those defined in Sun 36. In addition, it should be clarified that tasks are reset for all image pairs that have been “unpaired” and destroyed by the PRLO, but not for other image pairs.

Response:

Since Process Associators are removed, only one image pair exists between an initiator and target, so no distinction is required and all tasks are destroyed. The response was approved by the FCP-2 working group meeting on May 15, 2000.

Installation:

Installed as approved.

9.43 Sun 43 State after PRLO

Technical

Page 29, section 6.3, paragraph 3, second sentence. The second sentence should be modified to read:

After PRLO, no further FCP communication is possible between those two N_Ports.

Response:

Accepted. The response was approved by the FCP-2 working group meeting on May 15, 2000.

Installation:

Installed as approved.

9.44 Sun 44 State of image pairs after PRLO

Technical

Page 29, section 6.3, 4th paragraph. The paragraph leaves some uncertainty about the proper response to the PRLO and the proper state of image pairs if some are discontinued, some are not discontinued, and some do not exist (or never existed). I believe that the PRLO should respond as if the image pairs that do not exist are successfully discontinued just as if they existed.

Response:

Since Process Associators are removed, only one image pair exists between an initiator and target, so no distinction is required and the image pair is destroyed by PRLO. The response was approved by the FCP-2 working group meeting on May 15, 2000.

Installation:

Installed as approved.

9.45 Sun 45 Clarify table 13

Editorial

Page 30, section 7.1, table 13. The table should be restructured in bit/byte format to make the definitions clearer. The fields should be identified and described by field name.

Response:

Accepted.

Installation:

Rewritten by response to 8.52

9.46 Sun 46 Verify FCP specific object format

Editorial

Page 30, section 7.2. This section was written before FC-GS-3 was available. It should be examined for consistency with FC-GS-3 and any corrections installed.

Response:

Accepted.

Installation:

Rewritten by response to 8.52

9.47 Sun 47 Install references

Editorial

Page 31, section 8, table 15. The references for FCP_ACC and FC__RJT need to be installed.

Response:

Accepted.

Installation:

Installed as requested.

9.48 Sun 48 Clarify table 16

Editorial

Page 32, section 8.1, table 16. The table should be restructured in bit/byte format to make the definitions clearer. The fields should be identified and described by field name.

Response:

Accepted.

Installation:

Installed as requested.

9.49 Sun 49 SRR inconsistent error reporting

Technical

Page 31, section 8.1. The seventh paragraph indicates that an SRR that cannot be accepted is treated as an “Initiator Detected Error.” The third paragraph of the “payload” description on the next page indicates that such an error will be indicated with an FCP_RJT. These two statements need to be reconciled. I expect that there are really two cases. One could be treated as an Initiator Detected Error (failed link recovery), while the other could be treated as an FCP_RJT (invalid payload contents).

Response:

In the May 15, 2000 meeting, Carl Zeitler pointed out that these also conflict with the proposal to abandon error recovery when the first level recovery fails. There was a consensus that any reject of SRR, including either an error or a lack of data should be treated as an initiator detected error.

In addition, on pdf page 31, it is not clear what happens in the last paragraph. The word accept does not clearly define whether this means SRR receives an ACC.

This section must be reviewed again.

This resolution was accepted in the June 7, 2000 working group meeting.

Installation:

This was already slightly modified, but the parts relevant to this comment received the following additional modifications. The intent was to separate this case from those involving failures in SRR transmission.

The S_ID field designates the initiator requesting the information retransmission. The D_ID field designates the target that is to receive the request. In the event that the target responds to the SRR with an FCP FC-4 Link Service Reject ~~cannot accept the SRR request~~, the target shall return CHECK CONDI-

TION status with the sense key set to HARDWARE ERROR and an additional sense code of INITIATOR DETECTED ERROR MESSAGE RECEIVED. A target that has agreed during PRLI to support retransmission should ~~not reject~~ ~~accept~~ requests for retransmission of the requested frames unless unusual conditions make the retransmission impossible. ~~Retransmission may not be supported for some logical units on a target.~~ SRR requests for exchanges involving logical units that do not support retransmission on a target that supports retransmission for other logical units shall be rejected with an FCP FC-4 Link Service Reject containing a reason code of "unable to support command request" and a reason code explanation of "unable to supply requested data".

9.50 Sun 50 Describe payload for FCP_RJT

Editorial

On page 33, section 8.3, the paragraphs describing payload, the description is complicated enough to warrant the creation of a table that describes the complete payload.

Response:

Accepted.

Installation:

Installed as requested.

9.51 Sun 51 FCP_LUN format

Technical

On page 36, section 9.1.1.1. FCP-2 revision 4 shows the FCP_LUN field in the FCP_CMND IU as an 8 byte field. It states: "The FCP logical unit number (FCP_LUN) is the address of the desired logical unit in the attached subsystem. The FCP_LUN field is specified by ANSI X3.230 for all IUs of Category 6."

The last sentence implies one can find detail on the contents of the LUN field in X3.230, but that document is FC-PH, and FC-PH simply defines the field as "Entity Address (FC-4 dependent)". So the references point at each other.

Was the intent in FCP-2 to let the LUN field be defined by the appropriate SCSI standard document(s)? FCP mentioned the SCSI Device Model. Or was more specific guidance to a specific format of the LUN field intended in FCP-2? FCP Annex C gave a SCSI Controller Command LUN field usage example.

The proper documentation is probably in SAM-2.

Response:

The proper reference is to SAM-2, where the address field is specified in 4.11.2. The response was approved by the FCP-2 working group meeting on May 15, 2000.

Installation:

This was further simplified when FC-FS removed the definition information and made this all protocol specific. The offending sentence was deleted.

9.52 Sun 52 FCP_CMND IU sub-section titles

Editorial

The titles for sections 9.1.1.x starting on page 37 should not have the byte number included in the title.

Response:

Accepted.

Installation:

Installed as requested.

9.53 Sun 53 Clarification of ordered queueing

Technical

Page 37, section 9.1.1.3, the text of paragraph 4 should be rewritten as follows:

ORDERED_Q requests that the task be managed according to the rules for an ORDERED task attribute. With a class 2 fabric, special care ~~must be~~ should be taken ~~exercised~~ to guarantee successful ordering. ~~Sequential~~ In order delivery ~~must~~ should be requested at login to ensure correct ordering among tasks. ~~FCP_CMND IUs must be acknowledged before new FCP_CMND IUs are issued to avoid inadvertent reordering of commands during retries of F_BSY.~~ Acknowledgements should be received before new FCP_CMND IUs are issued to avoid inadvertent reordering of commands during delays in the fabric, including retries of F_BSY. Ordering can also be accomplished by waiting for the completion of those commands requiring ordering before transmitting the FCP_CMND for the next FCP I/O operation, or by using the precise delivery mechanism.

Response:

After consideration by the May 15, 2000 working group meeting, the following resolutions were agreed upon.

This should actually be three separate paragraphs. The first paragraph should provide a definition. The second paragraph should define the requirements for class 2 behavior. The third should address the operation for all classes.

Note that a definition of in-order delivery must be provided. Two alternatives are available. The definition may either be included in the model and glossary or the definition may be included in annex D. The in-order definition must be tighter and more complete than that in FC-FS. In-order delivery may be damaged by fabric busy states. FC-FLA should be examined for additional information about in-order delivery. It is likely that FC-MI will need to be corrected and that FC-FS and other standards may also be affected. Dave Peterson will address any FC-MI problems and I will address any other problems identified.

This resolution was agreed upon in the June 7, 2000 working group meeting.

Installation:

This was modified by a different comment that suggested eliminating the in-order case and simply placing the two models using synchronized command execution and CRN as the only two in-order cases. The corrected text was moved to the model section.

9.54 Sun 54 Clarification of task management flags

Editorial

Page 38, section 9.1.1.4, the words "Task Management function" s/b "Task Management request".

Response:

Accepted.

Installation:

SAM-2 uses the words Task Management function. This was verified in the text.

9.55 Sun 55 ACA clarification

Technical

Page 38, section 9.1.1.4, Clear ACA. It is unclear what the proper behavior is if there is no ACA present when a Clear ACA is transmitted. References to SAM should be provided to clarify this.

Response:

Accepted in principle. The reference should actually be to SAM-2. The response was approved by the FCP-2 working group meeting on May 15, 2000.

Installation:

SAM-2 is a bit vague about this, only indicating that the CLEAR ACA will be simply accepted and acknowledged as complete if a CA condition is present. The editor assumes that this will also be the case for other cases where no ACA condition is present. The text is updated accordingly.

9.56 Sun 56 Complete Clear ACA description

Technical

Page 38, section 9.1.1.4, Clear ACA, 4th paragraph, the incomplete sentence should be completed as:

Depending on the MODE SELECT parameters that have been established, additional FCP I/O operations may have to be aborted by the recovery abort as part of the process of clearing the automatic contingent allegiance.

Response:

Accepted. The response was approved by the FCP-2 working group meeting on May 15, 2000.

Installation:

Installed as requested.

9.57 Sun 57 Clarify Target Reset

Editorial

Page 38, section 9.1.1.4, Target Reset. The first paragraph should be rewritten as a list (see Logical Unit Reset text as an example) to make it easier to read.

Response:

Accepted.

Installation:

This problem was resolved by using references to the clearing effects tables.

9.58 Sun 58 Correction of note about SAM-2

Editorial

On page 39 and 40, section 9.1.1.4, the text of the notes about SAM-2 should be corrected by changing the words “by this mechanism” to “with this completion status”. There are 4 such notes to be corrected.

Response:

Accepted.

Installation:

Clarified by other rewrites.

9.59 Sun 59 Clarify dependant logical unit

Editorial

Page 39, section 9.1.1.4, Logical Unit Reset, item 6. The definition of dependent logical units is a little vague. It is not included in the glossary and the reference 4.11 does not exist. The definition should be extracted from SAM-2, placed in the glossary, and referenced here.

Response:

Accepted.

Installation:

SAM-2 is clearly referenced as the source of this definition.

9.60 Sun 60 Clarify logical unit reset

Editorial

Page 39, 9.1.1.4, logical unit reset, second paragraph after list. The first sentence should be re-ordered to say: “shall be terminated using a recovery abort by whichever port”.

Response:

Accepted.

Installation:

Clarified by rewrite.

9.61 Sun 61 Clarify logical unit reset

Editorial

Page 39, 9.1.1.4, logical unit reset, last paragraph. The Logical Unit Reset does not address targets, but rather logical units. The ambiguity should be addressed in terms of those exchanges ambiguous with respect to the logical unit, not those ambiguous with respect to the target.

Response:

Accepted.

Installation:

Installed as requested.

9.62 Sun 62 Clarify Clear Task Set

Editorial

Page 40, 9.1.1.4, Clear Task Set. This section has the same problems as the logical unit reset, except that the focus of the logical unit reset should be logical unit and the focus of clear task set should be task sets. See Sun 60 and Sun 61.

Response:

Accepted.

Installation:

Corrected by rewrite.

9.63 Sun 63 Clarify Additional FCP_CDB length

Technical

Page 40, 9.1.1.5. Add a sentence to this section. “The Additional FCP_CDB Length field shall be zero for task management requests.”

Response:

Accepted. The response was approved by the FCP-2 working group meeting on May 15, 2000.

Installation:

Installed with editorial corrections.

9.64 Sun 64 Clarify Additional FCP_CDB

Technical

Page 41, 9.1.1.9. The text of the second sentence should be changed as shown: “The ADDITIONAL_FCP_CDB shall not be present ~~is not valid and is ignored~~ if any task management flag is set to 1.

Response:

Accepted. The response was approved by the FCP-2 working group meeting on May 15, 2000.

Installation:

Installed as requested.

9.65 Sun 65 Use of word FC-PH

Editorial

Page 41, 9.1.2.2, second paragraph. The text “The FC-PH allows...” s/b “The FC-PH standard allows...”

Response:

Accepted.

Installation:

Removed by rewrite and moving of recovery abort definition.

9.66 Sun 66 Verify proper execution of recovery abort

Technical?

Page 41, 9.1.2.2, fourth paragraph. The text “A target ... specified RX_ID.” needs to be clarified. In particular, it is not clear what the detailed values of the recovery qualifier are with respect to RX_ID.

Response:

I believe that the original intent of this was:

A target shall always accept an ABTS using the unassigned RX_ID value of FFFFh and establish a Recovery_Qualifier ~~with~~ without a specified RX_ID.

Accepted. The response was approved by the FCP-2 working group meeting on May 15, 2000.

Installation:

Corrected by rewrite in 12.3.

9.67 Sun 67 Clarify FCP_XFER_RDY

Editorial

Page 42, section 9.2, first paragraph. The text “... to perform ...” s/b “... to receive ...”.

Response:

Accepted.

Installation:

Installed as requested.

9.68 Sun 68 Clarify FCP_XFER_RDY when disabled

Editorial

Page 42, section 9.2, second paragraph. An additional sentence should be added at the end of the paragraph as follows: “The first FCP_DATA IU is transmitted without a preceding FCP_XFER_RDY.”

Response:

Accepted.

Installation:

Installed as requested.

9.69 Sun 69 Clarify obligation of initiator

Editorial

Page 42, section 9.2, third paragraph. The last sentence should be changed to read: “The initiator shall be ready to transmit any part or all of the ~~the entire~~ FCP_DL bytes of data.”

Response:

Accepted.

Installation:

Corrected in first paragraph.

9.70 Sun 70 Clarify Data_RO

Editorial

Page 42, 9.2.1. The first sentence should change the words “the next FCP_DATA” to “the requested FCP_DATA”. In addition, a reference should be put in place for the SCSI-3 application client buffer offset, probably in SAM-2.

Response:

Accepted.

Installation:

Installed as requested.

9.71 Sun 71 Clarify Burst_LEN

Editorial

Page 42, 9.2.2, first paragraph should be changed as follows: “~~For data transfers from the SCSI initiator to the target,~~ The BURST_LEN field indicates the amount of buffer space prepared for the next FCP_DATA IU and requests the transfer of an IU from the initiator of that exact length. This value is the same as the SCSI data delivery request byte count. See SAM-2.”

Response:

Accepted.

Installation:

Installed as requested.

9.72 Sun 72 Clarify maximum burst length

Technical

Page 42, 9.2.2, third paragraph. The following text should be added to the third paragraph: “A BURST_LEN greater than FCP_DL or longer than the maximum burst length specified by the disconnect/reconnect mode page is not valid.”

Response:

Accepted. The response was approved by the FCP-2 working group meeting on May 15, 2000.

Installation:

Installed as requested, with editorial modifications.

9.73 Sun 73 Clarify FCP_DATA IU

Editorial

Page 43, 9.3, first paragraph. The first paragraph should be changed as follows: “The data associated with a particular FCP I/O Operation is transmitted in the same exchange that sent the FCP_CMND requesting the transfer. ~~identified by the FQXID.~~”

Response:

Accepted.

Installation:

Installed as requested.

9.74 Sun 74 Simplify Mode Sense/Select reference

Editorial

Page 43, section 9.3, second paragraph. Delete the last sentence and replace it with a reference to 10.1.1.6.

Response:

Accepted.

Installation:

A superior editorial revision was accepted.

9.75 Sun 75 Improve text

Editorial

Page 43, section 9.3, fourth paragraph. Since there is only one Data Out IU, the parenthetic (T6 or T7) should be deleted. The last sentence needs to be corrected to indicate “first” rather than “corresponding”.

Response:

Accepted.

Installation:

Installed as requested. Also corrected in other paragraphs of clause 9 and in clause 12.

9.76 Sun 76 Improve text

Editorial

Page 43, section 9.3, fifth paragraph. Since there is only one Data Out IU, the parenthetic T6 and T7 should be removed. The last sentence needs to be corrected to read: “The command is completed normally except that data beyond the FCP DL count shall not be transferred and that the appropriate overrun condition is presented. ~~for presentation of the overrun condition.~~ See 9.4.1.”

Response:

Accepted.

Installation:

Installed as requested.

9.77 Sun 77 Clarify data is contiguous

Editorial

Page 43, section 9.3, 8th paragraph. The third sentence “The target shall not request that sets of data in the middle of a transfer not be transferred.” should be deleted. The second sentence covers this.

Response:

Accepted.

Installation:

Installed as requested.

9.78 Sun 78 Stylistic improvement

Editorial

Page 44, section 9.3, last paragraph. The wording of the following sentence, “ANSI X3.230 specifies the mechanisms by which an IU shall be transferred.” should be changed to “ANSI X3.230 specifies how an IU shall be transferred.”

Response:

Accepted.

Installation:

Installed as requested with editorial improvements.

9.79 Sun 79 Improve description of linking

Editorial

Page 44, section 9.4, third paragraph. The wording of the last sentence should be changed to: “~~There is no FCP-2 function equivalent to the~~ The LINKED COMMAND COMPLETE or LINKED COMMAND COMPLETE (WITH FLAG) function defined by SAM and SAM-2 is implicit in the presentation of the proper status in the FCP_RSP.”

Response:

Accepted.

Installation:

Installed as requested.

9.80 Sun 80 Include task management in FCP_RSP_INFO

Technical

Page 47, section 9.4.10. The FCP_RSP_INFO description should contain an explicit requirement that FCP_RSP_INFO is always present in a task management response.

Response:

Accepted. The response was approved by the FCP-2 working group meeting on May 15, 2000.

Installation:

The first paragraph was modified to read:

The FCP_RSP IU provides completion information for FCP I/O operations. The information includes SCSI status, protocol verification, and any applicable autosense data. The FCP_RSP IU shall return the completion status of all task management functions using the FCP_RSP_INFO field.

9.81 Sun 81 Improve table format

Editorial

Page 48, section 9.4.10, table 27. The table should be reformatted to clearly define the bits and bytes used.

Response:

Accepted.

Installation:

Installed as requested.

9.82 Sun 82 Correct task management completion

Technical

Page 48, section 9.4.10, last paragraph. The first sentence should be changed as follows: ~~The task management function may or may not have been performed by the target if RSP_CODE is returned or if no FCP_RSP is returned before the Exchange is aborted.~~ The completion status of the task management

function is indicated by the RSP CODE. If the Exchange is aborted before the FCP RSP is returned, the completion status is unknown.

Response:

Accepted. The response was approved by the FCP-2 working group meeting on May 15, 2000.

Installation:

Installed as requested.

9.83 Sun 83 Capitalize error codes

Editorial

Page 48, section 9.4.10, table 28. SPI-3 has elected to place the packetized failure codes in upper case. They recommend that the corresponding response codes of table 28 all be upper case.

Response:

Accepted.

Installation:

After reviewing the appearance of the document, this proposal was not installed.

9.84 Sun 84 Verify task management completion

Technical

There was a statement at one meeting that the FCP-2 document is not consistent with the SAM-2 document with respect to the task management function completion codes. This must be verified.

Response:

After review, the task management completions are:

- 1) Function complete
- 2) Function not supported
- 3) Function failed

These are the same in definition in both FCP-2 and SAM-2, although different wording is used for them. The wording in FCP-2 will be adjusted to more closely parallel the SAM-2 wording.

Accepted. The response was approved by the FCP-2 working group meeting on May 15, 2000.

Installation:

Installed as requested.

9.85 Sun 85 Correct description of SCSI mode parameters

Editorial

Page 50, section 10.1, first sentence: The sentence should be changed to read: "This clause describes the block descriptors and the pages used with MODE SELECT and MODE SENSE commands that ~~influence~~ control and report the parameters that influence the behavior of FCP.

Response:

Accepted.

Installation:

Installed without the added text, which is not required.

9.86 Sun 86 Clarify requirements for parameters

Editorial

Page 50, section 10.1.1, last sentence: The sentence should be changed to read: "If a parameter that is not ~~appropriate for the an~~ standard for FCP-2 SCSI-3 device is set nonzero, the device server shall return CHECK CONDITION status. The sense key shall be set to ILLEGAL REQUEST and the additional sense code set to ILLEGAL FIELD IN PARAMETER LIST.

Response:

Accepted.

Installation:

Installed using the word supported in response to a previous comment.

9.87 Sun 87 Add recommendation to Bus Inactivity Limit

Technical

Page 52, section 10.1.1.3: The following note should be added after the last paragraph:

Note: Because of the low overheads associated with initiating and closing bus tenancy on Fibre Channel links, device servers should end tenancies immediately upon completing the required transfers.

Response:

Accepted. The response was approved by the FCP-2 working group meeting on May 15, 2000.

Installation:

Installed as requested.

9.88 Sun 88 Note that FC Port Control page violates standards

Editorial

Page 54/55, section 10.1.3: The following note should be added before Table 32:

Note: Some of the bits defined by the Fibre Channel Port Control page require the port to violate one or more of the fibre channel standards. The non-standard behaviors have been identified as useful for certain specialized operating environments.

Response:

Accepted.

Installation:

Installed as requested.

9.89 Sun 89 typo

Editorial

Page 55, section 10.1.3.2:

Initiated s/b Initiated
sequences s/b sequence

Response:

Accepted.

Installation:

Installed as requested.

9.90 Sun 90 Correct DTIPE bit = 0 description

Technical

Page 55/56, section 10.1.3.2: At present, if DTIPE is set to zero, vendor specific initialization is expected. The proper behavior should be to follow the initialization method specified by FC-AL-2.

Response:

Accepted. The response was approved by the FCP-2 working group meeting on May 15, 2000.

Installation:

Installed as requested.

9.91 Sun 91 Improve RHA readability

Editorial

Page 56, section 10.1.3.4: The second paragraph should be divided into two paragraphs separated between "... get its hard address." and "If the hard address ...".

Response:

Accepted.

Installation:

After review of the text, no change was made.

9.92 Sun 92 Clarify RR_TOV default

Technical

Page 57, section 10.1.3.9: The next to the last sentence should be changed to read: If no timer is specified, the RR_TOV value in byte 7 shall be ignored by the device server and a vendor specific default value shall be used.

Response:

Accepted. The response was approved by the FCP-2 working group meeting on May 15, 2000.

Installation:

Installed as approved, with an additional modification.

9.93 Sun 93 typo

Editorial

Page 60, section 11.2. "... with the aborted Sequence." s/b "... with an aborted Sequence."

Response:

Accepted.

Installation:

Installed as requested.

9.94 Sun 94 Concern about organization of error recovery section

Editorial

Page 62, section 12. It appears that a descriptive paragraph or model would be appropriate either here or in section 4.0. The overall structure of 12 depends on two types of error detection, one that works for all classes of service and an additional one that works for acknowledged classes of service. Once an error is detected, there appears to be two types of error recovery that can be performed, one that does exchange level recovery, and the other that does sequence level recovery. This is a bit difficult to pick out of the document.

Response:

Accepted.

Installation:

Installed as in 9.103 Sun 103.

9.95 Sun 95 Remove redundant sentence

Editorial

Page 62, section 12.1.1. The sentence “An FCP-2 ... defined below.” should be deleted. It is left over from a previous revision of the document.

Response:

Accepted.

Installation:

Corrected during re-write of those paragraphs.

9.96 Sun 96 Emphasize optional error recovery

Editorial

Page 62, section 12.1.2. The first sentence should be rewritten as: “SCSI devices may use the mechanisms described in this chapter to detect the presence of link errors, then perform optional retransmission procedures that ~~will~~ allow the commands to be completed without requiring ~~complex~~ higher level recovery algorithms.” The extra line space above the paragraph should be deleted.

Response:

Accepted.

Installation:

Corrected during re-write.

9.97 Sun 97 typo

Editorial

Page 62, 12.1.2, third paragraph. Correct font.

Response:

Accepted.

Installation:

Corrected as requested.

9.98 Sun 98 Clarify error detection

Editorial

Page 62, section 12.2.1, first paragraph. The sentence should be rewritten as: “The Exchange originator (SCSI Initiator) may detect the following errors. It may optionally further identify and recover the error as described in 12.3. ~~shall initiate error detection and recovery described in 12.3 for the following:~~”

In addition, in line item 3, “an Sequence” s/b “a Sequence”.

The same rewrite should be done for the paragraph associated with the Exchange responder.

Response:

Accepted.

Installation:

Changed as requested, with minor editorial modifications in 12.2.1, two places.

Following the lead of 9.100 Sun 100, the text was also changed to “shall”.

After discussion at the September 11, 2000 working group meeting, it was identified that the list needs to be split. The first two items are really only indications of a potential problem, while the others are actual errors. The first two will be moved into a second category in a separately explained list.

After further review, I believe that those two cases need simply be deleted, since they are covered by 12.4.1.1 and 12.4.1.2. The corresponding text below is also corrected.

9.99 Sun 99 Clarify sequence error detection

Editorial

Page 63, sections 12.2.1 and 12.2.2. Item 4 of the target list of section 12.2.2 really applies to all classes and should be deleted from 12.2.2. In 12.2.1, the wording for sequence errors should be changed to match the text deleted from 12.2.2. Reference to section 12.3.9 for the recovery process should be made.

Response:

Accepted.

Installation:

Changed as requested.

9.100 Sun 100 Clarify error detection

Editorial

Page 62, section 12.2.2, first paragraph. The second sentence should be rewritten as: "The Exchange originator (SCSI Initiator) may detect the following errors. It may optionally further identify and recover the error as described in 12.3. ~~shall initiate error detection and recovery described in 12.3 for the following:~~"

The same rewrite should be done for the paragraph associated with the Exchange responder.

Response:

Accepted in principle. In the May 5, 2000 meeting of the FCP-2 working group, the proposed response was modified to indicate that all errors in the respective lists "shall" be detected. Other errors may be detected by other mechanisms.

Installation:

With minor editorial changes, the requested change was made in two places.

9.101 Sun 101 Clarify exchange level error recovery

Editorial *****

Section 12.1.1 outlines how exchange level error recovery works. The only place it is actually described in detail is in 12.3.8, 12.3.9, 12.4, and 12.5 actually describe different portions of the exchange level error recovery. However, 12.3.8 and 12.3.9 in large measure duplicate the detection discussion of 12.2.1 and 12.2.2. Section 12.4 overlaps with the recovery information in 12.5.2. I believe that 12.3.8 and 12.3.9 should be selectively deleted where the information is duplicated by 12.2.1 and 12.2.2. I believe that section 12.4 should be carried into section 12.5.2, with which it is almost totally redundant.

Response:

Accepted.

Installation:

Changed as requested.

9.102 Sun 102 Clarify exchange level error recovery

Editorial

Page 63, Section 12.2.2 The last two paragraphs describe recovery mechanisms, not detection mechanisms. These belong in another section, possibly 12.5.

Response:

Accepted.

Installation:

Changed as requested.

9.103 Sun 103 Overall formatting of recovery suggestion

Editorial

The relationship among recovery algorithms and detection algorithms is not as clear as it should be. I would suggest the following organization:

12.1 Overview

12.1.1 Overview of exchange level recovery

12.1.2 Overview of sequence level recovery

12.2 Initial FCP error detection

12.2.1 Error detection for all classes of service

Initiator

Target

12.2.2 Additional error detection for acknowledged classes

Initiator

Target

12.3 Exchange level error recovery (largely the same as old 12.5)

12.3.1 SCSI initiator abort of exchange (largely the same as old 12.5.1)

12.3.2 SCSI target abort of exchange (largely the same as old 12.5.2, combined with 12.4)

12.4 FCP-2 specific error recovery (this is distinguished by special use of REC and time-outs.)

This contains all the sections from 12.3.1 to 12.3.7. Note that 12.3.8 and 12.3.9 are included already in 12.2.1.

12.5 Second level error recovery (This contains all the sections from 12.6.1 through 12.6.3)

12.6 Responses to FCP-level frames before PLOGI or PRLI (This contains all of 12.7)

See also 11.8

Response:

Accepted.

Changed as requested.

9.104 Sun 104 Clarify REC polling

Editorial

Page 64, section 12.3.1. The overall model of polling using REC is never defined. Parts of it are included in the REC_TOV definition, some implicit time-out conditions in 12.2.1, and parts in 12.3.1. Since we are not covering the overall error recovery in section 4, it seems appropriate to spend a paragraph indicating how polling is performed in 12.3.1.

Response:

Accepted.

Installation:

Corrected as requested, although the correction was placed in a new paragraph before the old 12.3.1.

9.105 Sun 105 Clarify REC response if no OX_ID

Technical

Page 64, section 12.3.2. The definition of the reason code for the LS_RJT is incomplete. The definition should be: "... for the REC with a reason code of Logical Error and a reason code explanation of Invalid OX_ID-RX_ID combination (0317h))."

Response:

Accepted. The response was approved by the FCP-2 working group meeting on May 15, 2000.

Installation:

The reason code and reason code explanations were all reviewed and corrected and placed in the correct format as required by 4.559.

9.106 Sun 106 Correct error recovery reason

Editorial

Page 64, section 12.3.2. The sentence "This is to ensure that no reply Sequences have been lost." is really not correct. It will eventually become apparent that they were lost. This is really to find out more quickly that the sequences have been lost.

Response:

Accepted.

Installation:

The text was changed to read:

At a minimum interval of REC_TOV, the REC shall be retransmitted to more quickly determine if a reply Sequence has been lost.

9.107 Sun 107 Clarify REC response if no OX_ID

Technical

Page 66, section 12.3.7. The definition of the reason code for the LS_RJT is incomplete. The definition should be: "... to the REC from the target will be a LS_RJT with a reason code of Logical Error and a reason code explanation of Invalid OX_ID-RX_ID combination (0317h)."

Response:

Accepted. The response was approved by the FCP-2 working group meeting on May 15, 2000.

Installation:

The reason code and reason code explanations were all reviewed and corrected and placed in the correct format as required by 4.559.

9.108 Sun 108 Exchange bashing options

Technical

Page 66, section 12.3.8. The initiator may also abort the exchange with any task management function or with the ABORT TASK function, which uses the recovery abort protocol, which uses ABTS. It is my impression that ULP_TOV will use one of the higher level functions, probably ABORT TASK, to invoke the ABTS.

Response:

Accepted in principle. The resolution requires careful phrasing. The response was approved by the FCP-2 working group meeting on May 15, 2000.

Installation:

The text was changed to read:

If ULP_TOV times out and the Exchange is not complete, the application client shall clear the exchange resources using the ABORT TASK task management request or the initiator shall clear the exchange resources using the recovery abort protocol. (See 9.1.3.)

9.109 Sun 109 Redundant sections

Technical

Page 67, section 12.4 appears to be largely redundant with 12.5.2 and should be combined with it.

Response:

Accepted. The response was approved by the FCP-2 working group meeting on May 15, 2000.

Installation:

Installed as requested.

9.110 Sun 110 Exchange bashing options again

Editorial

Page 67, 12.5.1, paragraphs 4, 5, and 7. The words “ABTS protocol” should be replaced with “recovery abort”

Response:

Accepted.

Installation:

Corrected in clause 12

9.111 Sun 111 Stylistic correction

Editorial

Page 69, section 12.6.1. The phrase “If the SCSI target is not on a remote loop,” s/b “If the SCSI target is on the local loop or if the loop is private,”.

Response:

Accepted.

Installation:

Corrected by the correction of 1.47.

9.112 Sun 112 Clear resources after second level error recovery of REC

Technical

Page 69, section 12.6.2, next to last paragraph. The paragraph should be modified to read: “The REC shall be retried at a rate not to exceed once per the time-out period for at least 3 times. If none of the RECs receive a response, the Initiator shall report an error condition to the ULP, clear resources associated with the exchange, and perform an implicit logout with the target.”

Response:

Accepted in principle. See 1.47. After careful consideration at the May 15, 2000 meeting of the FCP-2 study group, the response was accepted in principle. Carl Zeitler has suggested that multiple retries of the retry process are not meaningful and that the exchange should be terminated with an ABTS-LS after 0 or 1 retries of the recovery process.

Installation:

Corrected as requested.

9.113 Sun 113 Clear resources after second level error recovery of SRR

Technical

Page 69, section 12.6.2, next to last paragraph. The paragraph should be modified to read: "The SRR shall be retried at a rate not to exceed once per the time-out period for at least 3 times. If none of the SRRs receive a response, the Initiator shall report an error condition to the ULP, clear resources associated with the exchange, and perform an implicit logout with the target.

Response:

Accepted in principle. See 1.47.

In the May 15, 2000 meeting of the FCP-2 working group, Carl Zeitler's suggestion to simplify the retry of multiple errors was accepted. Carl proposed that ABTS-LS be used to perform a clean up after 1 failed try on SRR and after one failed retry of REC (for R_A_TOV).

The possible approaches for retry of an ABTS-LS were to

- a) perform an implicit logout, or
- b) perform a selective or link reset

This probably requires a bit more thought.

In the June 7, 2000 working group meeting, the decision was to perform an implicit logout and recover the resources. This would interfere with other on-going activities.

Installation:

This was resolved by a series of other comments. See 12.6 and 12.7.

9.114 Sun 114 Clarify sending of logout

Technical

Page 69, section 12.7. The first paragraph should be rewritten as follows: "If a SCSI Target receives an FCP_CMND from ~~an NL_Port~~ a port with which it has not successfully completed N_Port Login (PLOGI), it shall discard the FCP_CMND and in a new exchange, send LOGO to that ~~NL_Port port~~. No Exchange is created in the SCSI Target for the discarded request, and the originator of the discarded request terminates the Exchange associated with the discarded request and any other open Exchanges for the SCSI Target sending the LOGO. ~~The LOGO is not part of the Exchange associated with the discarded request.~~

Response:

Accepted. The response was approved by the FCP-2 working group meeting on May 15, 2000.

Installation:

Corrected as requested, with additional improvements from other comments.

9.115 Sun 115 Allow implicit login

Technical

Page 69, section 12.7. The successful completion of a login should include an implicit login. A new paragraph should be added at the end that says: "FCP-2 devices that have used implicit PLOGI and/or implicit PRLI to establish their parameters and relationships may accept all FCP-2 IUs exactly as if they had completed an explicit PLOGI and/or PRLI.

Response:

Accepted. The response was approved by the FCP-2 working group meeting on May 15, 2000.

Installation:

This was corrected in the primary paragraphs by the response to 1.48.

9.116 Sun 116 Remove placeholder

Technical

Page 69, section 12.7. Delete the last sentence of the section, which had been reserved as a placeholder for any other frames of interest.

Response:

Accepted. The response was approved by the FCP-2 working group meeting on May 15, 2000.

Installation:

Deleted as requested.

9.117 Sun 117 Remove editor's note

Editorial

Page 71, section A.1. The editor's note should be removed.

Response:

Accepted.

Installation:

Installed as requested.

9.118 Sun 118 Remove SCSI Parallel Interface

Editorial

Beginning page 74, sections of A.5. These sections were originally taken from a parallel SCSI document. The words "SCSI parallel interface services" s/b "Fibre Channel Protocol for SCSI services".

Response:

Accepted.

Installation:

Installed as requested.

9.119 Sun 119 Resetting FCP

Editorial

Page 75, section A.5.1.1. The words "ABORT TASK message" s/b "ABORT TASK function".

Response:

Accepted.

Installation:

These sections were deleted and defined by reference.

9.120 Sun 120 Create change document for FC-FS

Editorial

Page 77, section B.1. The words "a future version of FC-PH" should be "FC-FS".

The document requesting these changes for FC-FS must be prepared by the editor.

Response:

Accepted.

Installation:

Annex B is deleted.

9.121 Sun 121 Clarify Basic Link Services requirements

Editorial

Page 77, section B.2. The word “exceptions” s/b “additional functions”.

Response:

Accepted.

Installation:

Annex B is deleted.

9.122 Sun 122 Clarify ABTS description

Editorial

Page 77, section B.2.1, second paragraph should be rewritten to say: “~~FC-PH does not specify a mechanism to determine which behavior an ABTS should create. While using~~ To meet the requirements of the FCP-2 standard protocol, the default value of bit 0 in the ABTS request parameter field shall be interpreted as requiring the aborting of the exchange, as described in section 9.1.2.2 on page 41 of this standard. ~~While using the FCP-2 protocol, a~~ A value of 1 in bit 0 of the parameter field requires that the sequence be aborted as described in FC-FS FC-PH, clause 21.2.2.1 and as described in section 12.4 on page 67 of this standard.”

Response:

Accepted.

Installation:

This is now installed in FC-FS. Annex B is deleted.

9.123 Sun 123 Reference update

Editorial

Page 77, section B.3. “FC-PH” s/b “FC-FS”.

Response:

Accepted.

Installation:

Annex B is deleted.

9.124 Sun 124 Clarify REC description

Editorial

Page 78, section B.3.1, first paragraph. The text “If the RX_ID is unspecified in the request” s/b “If the RX_ID is specified as undetermined in the request”.

Response:

Accepted.

Installation:

Installed with small editorial changes.

9.125 Sun 125 Reference update

Editorial

Page 78, section b.3.1, “FC-PH” s/b “FC-FS”.

Response:

Accepted.

Installation:

Annex B is deleted.

9.126 Sun 126 Clarify REC Accept payload

Editorial

Page 79, section b.3.1, table B.4 and text underneath:

- a) Table B.4 should be modified to show the byte/bit layouts
- b) The first sentence under the table, “E_STAT ...” under the table should be deleted. The full byte definitions of the E_STAT value should be incorporated in table B.4.
- c) The third paragraph under the table should be changed from “set the” to “set to the”.

Response:

Accepted.

Installation:

Installed as requested.

9.127 Sun 127 typo

Editorial

Page 81, section C.1: “initiators and targets” s/b “initiators or targets”.

Response:

Accepted.

Installation:

Installed as requested.

9.128 Sun 128 document format improvement

Editorial

Page 84, C.2, The text should be moved to join Figure C.1.

Response:

Accepted.

Installation:

Installed as requested.

9.129 Sun 129 Consider T11/99-722v2

Technical

Carl Zeitler of Compaq has offered document T11/99-722v2 for consideration with respect to error recovery examples including those in Annex D. If these considerations are not included in his formal comments, they are included in this formal comment.

Response:

Accepted in principle. The work has gone through several iterations. The final iteration will be used. The response was approved by the FCP-2 working group meeting on May 15, 2000.

Installation:

Installed as requested.

9.130 Sun 130 Correct error recovery procedure

Technical

Page 95 and 96, Figure D.7 and D.8. The last sentence in figure D.7 should be rewritten to read: “The Target retransmits the FCP_XFER_RDY using the specified Relative Offset ~~(or a Relative Offset smaller than the Relative Offset specified in the SRR in order to be aligned on an appropriate boundary in the Target).~~”

In addition, the label for the last data transfer arrow should be: “FCP_DATA (seq=2, cnt=1)”.

Response:

Accepted. The response was approved by the FCP-2 working group meeting on May 15, 2000.

Action:

Corrected in draft of revision 5.

9.131 Sun 131 typo

Editorial

Page 97 and 98, Figure D.9 and D.10. The label for the last data transfer arrow should be “FCP_DATA (seq=2, cnt=1)”.

Response:

Accepted.

Action:

Corrected in draft of revision 5. Note that this was just a matter of spacing the labels to more closely identify the arrows.

9.132 Sun 132 typo

Editorial

Page 100, Figure D.12. The last two sentences need to be separated by a blank space.

Response:

Accepted.

Action:

Corrected in draft of revision 5.

9.133 Sun 133 Acknowledged classes

Editorial

Page 103, Table E.1. The words “Class 2 or Class 3 Frame” s/b “Acknowledged or unacknowledged frame”. The words “Class 2 only frame” s/b “Acknowledgement frame”.

Response:

Accepted.

Installation:

Installed as requested.

9.134 Sun 134 Clarify text of E.2

Editorial

Page 103, section E.2 (all). The example weaves together queued and unqueued cases. As a result, it is harder than necessary to interpret these pages. The section should separate the queued and unqueued cases into two separate examples.

Response:

Accepted.

Installation:

This is one of many flaws in this annex. The annex is deleted.

9.135 Sun 135 Implicit confirm?

Technical

Page 104, Section E.2.2. The third sentence of the second paragraph is not correct. There is no concept of an implicit confirmation with respect to a target-initiator nexus in SCSI or FCP. The best solution is probably to delete the sentence.

Response:

Accepted. This requires further review. The basic problem may be incomplete assumptions.

This resolution was accepted in the June 7, 2000 working group meeting.

Installation:

Installed as requested.

9.136 Sun 136 Is example desirable?

Editorial

Page 105, Figure E.1. After some review, this picture looks just like D.9 and D.10. If this section is redundant, it should be removed.

Response:

Accepted.

Installation:

Annex is deleted.

9.137 Sun 137 Clarify discovery is for initiator

Editorial

Page 109, F1. The sections in F.1 are involved only in discovery of SCSI peripheral devices by the initiators. The text and titles should be modified to address this.

Response:

Accepted.

Installation:

Installed as requested.

9.138 Sun 138 Simplify list

Editorial

Page 109, section F.1.1, item 7. This item should be divided into two items, like the corresponding items of the list in F.1.2

Response:

Accepted.

Installation:

Installed as requested.

9.139 Sun 139 typo

Editorial

Page 109, section F.2, first line. delete “that”

Response:

Accepted.

Installation:

Installed as requested.

9.140 Sun 140 Clarify fabric and device authentication

Editorial

Page 110, section F.2. The list of items 1-4, is actually two lists, items 1 and 2 addressing the fabric logins and items 3 and 4 addressing the port logins. The text should be separated into two parts. Items 2 and 4 need to be rewritten to clarify the “if-then-else” sense of the sentences. The last part of each sentence (what to do if a configuration change has occurred) needs to be separated out of the respective paragraph and presented as a separate line item or as a separate conclusion.

Response:

Accepted.

Installation:

The text was clarified. It did not finally appear necessary to separate the items into two groups.

9.141 Sun 141 Logical Unit Authentication

Technical *****

At present, this specifies two device identification page items, port name and node name. This is incorrect. It should be LUN WWN (which may or may not be derived from node name) and optional port name using the association bit.

Response:

Accepted. The response was approved by the FCP-2 working group meeting on May 15, 2000.

Installation:

Installed as requested.

9.142 Sun 142 Improve informative text

Editorial

Page 111, section G.1. The first sentence, “The required formats for recovery ELSs are described below” s/b “Examples of the formats for recovery ELSs are described below.”

Response:

Accepted.

Installation:

Installed as requested.

9.143 Sun 143 Complete informative text

Editorial

Page 113, Section G.?. Should additional examples be provided for REC and SRR?

Response:

Accepted.

Installation:

Not installed. These should be clear from the descriptions in the document.

9.144 Sun 144 Re-distribute contents of Annex H

Editorial

Annex H should be deleted, and its contents distributed into the body of the document.

Paragraph 1 should be distributed to section 9.4

Paragraph 2 should be distributed to section 9.4

Paragraph 3 should be distributed to section 4.2 or 9.1.

Paragraph 4 should be distributed to a location just before section 4.9.

Response:

Accepted.

Installation:

Paragraph 1 should be distributed to section 9.4 (done, with editorial modifications)

Paragraph 2 should be distributed to section 9.4 (done, with editorial modifications)

Paragraph 3 should be distributed to section 4.2 or 9.1. (done, with editorial modifications, in 4.2)

Paragraph 4 should be distributed to a location just before section 4.9. (done, by creating a new sub-clause)

Annex H is deleted.

9.145 Sun 145 Re-distribute contents of Annex I

Editorial

Annex I, with the following modifications, should be moved to section 4.8.

“If a SCSI Target Reset, Logical Unit Reset, or Clear Task Set management function is received by a SCSI Target that has multiple SCSI Initiators logged in with it, then the SCSI Target ~~should~~ shall:

a) create a Unit Attention Condition for all other SCSI Initiators ~~(an FCP_RSP may have been transmitted but not received by the SCSI Initiator, or the SCSI Initiator may have transmitted a command that has not yet been received by the SCSI Target) (refer to SAM and SAM-2);~~

b) clear all resources associated with the cleared Exchanges, ~~per SCSI Architectural Model~~ (refer to SAM and SAM-2);

~~c) return FCP_RSP upon completion of (a) and (b). The payload shall be zeroes with the exception of the FCP_RSP_LEN_VALID bit, FCP_RSP_LEN (which shall be set equal to 8), and the FCP_RSP_INFO (refer to FCP-2). [This is normal behavior already defined for task management, and need not be repeated here].~~

~~Upon discovery of the Unit Attention Condition set in a), SCSI Initiators should issue ABTS for all commands that are outstanding for the appropriate LUN or LUNs at that SCSI Target as described in 12.5.1. From a SCSI Initiator perspective, this is all commands for which FCP_RSP has not been received.” [This is normal behavior, already covered in other sections.]~~

Response:

Accepted.

Installation:

Note that the original text of Annex I is suspect. The text requires the initiator detecting a Unit Attention Condition to crack the FCP_RSP and determine that a Unit Attention Condition is present, then perform an ABTS (not an ABORT TASK which invokes recovery abort) for a set of commands that cannot be identified because there is no information about how many LUNs are affected, and for which

the initiator has not been keeping track of the LUNs anyway. As a result, the only realistic option is to time them out using the ULP timer, have the target terminate them with recovery abort or an as yet undefined RSP_CODE, or use the TASK ABORTED status defined for future revisions of SAM. Two and 1/2 of these options are already native to FCP-2 and the other 1/2 has not been proposed, so I believe the last paragraph of I should be dropped.

The remainder is about the proper behavior of the FCP_RSP timing with respect to task management functions and should go in the model under Task Management functions, not clearing the task management functions as was originally proposed. Note that this is largely obviated by the statement in 9.4.11 which says correctly:

Operations started by a task management function may continue after the FCP_RSP for the task management has been delivered.

By the time this was all considered, there were no changes other than those resolving other comments to clause 4.8 that were worth making before removing Annex I.

Annex I is deleted.

9.146 Sun 146 Remove Annex J

Editorial

These changes to FC-PH-2 and FC-FS should already be in progress and should not need to be covered here.

Response:

Accepted.

Installation:

Review my comments please.

J.1.1 Typographic error in FC-PH-2

This is now complete in FC-FS.

J.1.2 Incorrect process associator association with node values.

A letter has been posted to address this issue.

J.1.3 Invalid indication for PRLI responses

This is now complete in FC-FS.

J.1.4 No reject code for Process Login required

The process login required reject code is not yet installed. At present, FCP-2 skates by with “type not supported”, but there should be a special reject code. This is included in the letter posted.

J.1.5 Proper behavior when no PRLI is present

This has been cleaned up pretty well and should be okay now.

J.2.1 DTDC field in disconnect-reconnect mode page

FC-PLDA makes DTDC and DImm fields valid, while FCP-2 makes them zero. There is no reason to try to change FC-PLDA, since FCP-2 updates that stuff.

10 Comments from Texas Instruments

The following comments accompanied the ballot from Texas Instruments, prepared by Paul D. Aloisi.

10.1: TI Comment 1 (Editorial)

2.2 Last Paragraph - NCITS documents should be reference not just X3T10

Response:

Accepted.

Installation:

Installed as requested.

10.2: TI Comment 2 (Editorial)

General - The references to SCSI-3, I thought we had changed to just SCSI without the -3

Response:

Accepted.

Installation:

Installed as requested in abbreviations.

10.3: TI Comment 4 (Editorial)

X3T10 should be just T10 - several places in the document. 2.2 example

Response:

Accepted.

Installation:

Installed as requested.

10.4: TI Comment 5 (Editorial)

Web site and reflectors are www.t10.org & T10.org

Response:

Accepted.

Installation:

Installed as requested.

10.5: TI Comment 6 (Editorial)

John Lohmeyer mail is lohmeys@t10.org

Response:

Accepted.

Installation:

Installed as requested.

10.6: TI Comment 7 (Editorial)

We don't use the SCSI Bulletin board any more.

Response:

Accepted.

Installation:

Deleted as requested.

11 Comments from Compaq

The following comments were provided by Carl Zeitler of Compaq Computer Corporation.

11.1 Compaq CommentID:1 (Editorial)

PDFPage: 46 Document Page: 30 ClauseSubclause:7.1 Paragraph number: 1 Line: 2

Comment: Remove the "a" , first word on line 2.

Response:

Accepted.

Installation:

Rewritten by response to 8.52

11.2 Compaq CommentID:2 (Technical)

PDFPage: Document Page: 31 ClauseSubclause:8.1 Paragraph number: last Line:

Comment: Restarting Sequence Count is fine for Class 3. It doesn't work for Class 2 since any frame with a Sequence Count value within the range of the Recovery Qualifier will be discarded. So reword:

For Class 3, the Sequence Count..... For Class 2, The Sequence Count must be one greater than the last Sequence Count used in the Exchange.

Response:

Accepted. The response was approved by the FCP-2 working group meeting on May 15, 2000.

This comment elicited extensive discussions at the June 7, 2000 working group meeting. It was noted that the requirement to reset sequence count to 0 with SRR is inconsistent with continuously increasing sequence count. Relevant sections include Clause 8.1, paragraph 6 and clause 11.2.

Class 3 behavior sets it back to 0 as a reset and is compliant with FC-FS clause 12.9. However that conflicts with clause 17.6.3.3 in FC-FS. Class 3 did not use ABTS, but the handshake of SRR terminates the sequence. Protocol specific termination of a sequence is not defined in FC-FS.

At present, the best solution is to not use continuously increasing sequence count in class 3, although it appears to be desirable in class 2.

At present, the "discard single" discard policy is required and the "discard multiple" discard policy is allowed. The FCP-2 recovery structure appears to require the discard single policy. FC-FS must also be changed. The SRR function punctuates the stream of sequences as effectively as ACK, ABTS or a sequence initiative change. A new FC-FS correction document must be created to:

- a) include the sequence id as a component of the recovery qualifier.
- b) allow the reset of sequence count in class 3 if the recovery qualifier is not used.

Installation:

The change in 8.1 was made as approved. I did not see any required change in clause 11.2. The FC-FS change in the change in a) above was not accepted. I have no record of the installation of b) in FC-FS, but it is now covered in SRR in FCP-2, which should do the job.

11.3 Compaq CommentID:3 (Editorial)

PDFPage: Document Page: 31 ClauseSubclause:8.1 Paragraph number: Last on the page Line: Last on the page Comment

Comment: Is the period missing on the last sentence or is text missing?

Response:

Accepted.

Installation:
Installed as requested.

11.4 Compaq CommentID:4 (Technical)

PDFPage: Document Page: 37 ClauseSubclause:9.1.1.3 ORDERED_Q Paragraph number:
Comment: Sequential delivery by the fabric does not insure task order in either Class 2 or 3 if a frame gets busied off and resent or if the frame is discarded in Class 3. There are 2 solutions that I can see. One is CRN, so everything is in order or can be put back in order. If CRN is not used, then waiting for some response for each previous command or a GOOD response to a REC on each command preceding the command requiring ordering should suffice. The "ordered" command must also get a response or good response back on its REC, before issuing the next command, to insure that no frames pass it by for the out-of-order case.

Response:

Accepted in principle. The wording may require refinement. The response was approved by the FCP-2 working group meeting on May 15, 2000.

Installation:

Ordering was moved to the model and the use of in-order delivery by the fabric was removed as an option.

11.5 Compaq CommentID:5 (Technical)

PDFPage:75 Document Page:59 ClauseSubclause: 11 Paragraph number: Table 35 Line:

Title: R_A_TOV/2 support for out-of order

Comment: R_A_TOV/2 is required for out-of-order recovery.

In Table 35, qualify current Default Value for REC_TOV for in-order-delivery. Add a new line, for REC_TOV, qualified by out-of-order delivery where Default Value is R_A_TOV/2.

Response:

At the May 15, 2000 meeting of the FCP-2 working group, the choice was to reference document T11/00-145. R_A_TOV/w is the value defined for REC_TOV for out of order behavior. The comment was accepted.

Installation:

Changes as a result of T11/00-145 include:

- a) 12.5.2: 2 times R_A_TOV changed to R_A_TOV
- b) Placed a note in 8.3 indicating that failure of SRR caused the original Exchange to be aborted.

All other changes were included by other comments and documents.

11.6 Compaq CommentID:6 (Technical)

PDFPage:78 Document Page:62 ClauseSubclause:12.1.2 Paragraph number: 3 Line:

Title: Remove paragraph

Comment: For out of order, the error detection and recovery procedures are different. Even for in-order, recovery is different-i.e., reuse/non-reuse of SEQ_CNT for Classes 3 and 2 respectively for data.

Response:

This requires further study. If true, this requirement is undesirable, and would be sufficient to reinstate the prohibition on out-of-order delivery.

Carl Zeitler has prepared a series of ladder diagrams, presented in 173r3 and subsequent revisions, that tell how FCP-2 recovery operates with out-of-order delivery. In the discussion on May 15, 2000, the committee agreed that the diagrams should be carried as an informative annex. A note should be included in the text that indicates that FCP-2 requires in-order delivery to use the documented recovery mechanisms. However, with the assumption that continually increasing sequence count and fully implemented recovery qualifier behavior are both available, the recovery mechanisms indicated in the annex created by Carl may optionally be performed whether the transfer is in order or out of order.

Additional work will be done in future revisions of FCP to formalize the definition of out-of-order recovery.

Carl's proposal to respond to multiple failures and failures of the retry process with an ABTS-LS was accepted.

There was a consensus that the recovery process should be the same for out-of-order and in-order cases. Detection may be improved and made more timely by exploiting the acknowledged classes of service.

Installation:

This was resolved by a series of other comments. See 12.6 and 12.7.

In addition, the following text replaced the restriction on out-of-order transfer:

This clause defines the error detection and recovery mechanisms for fabrics that guarantee in-order frame delivery. However, if continuously increasing sequence count is used and if support for recovery qualifiers is fully implemented as defined in FC-FS, the same recovery mechanisms can be used for fabrics that do not guarantee in-order frame delivery, as shown in the examples in Annex C.

11.7 Compaq CommentID:7 (Technical)

PDFPage:78 Document Page:62 ClauseSubclause: 12.1.2 Paragraph number:4 Line:

Title: Remove

Comment: Remove to cover out-of-order.

Response:

Accepted. The response was approved by the FCP-2 working group meeting on May 15, 2000.

Installation:

See 11.6.

11.8 Compaq CommentID: 8 (Technical)

PDFPage:80 Document Page:64 ClauseSubclause:12.3.1 Paragraph number: Line:

CommentType: T

Title: Don't understand intent of paragraph

Comment: Need ladder diagram to help explain the text.

Response:

The intent of the paragraph is to explain three concepts:

- 1) Sequence errors should be indicated with a request for ABTS before performing an REC. Unfortunately, it is not explained how this can occur if the REC comes from the sequence originator.
- 2) If an REC is rejected as non-supported, use exchange level recovery.
- 3) If an REC receives no response, perform second level recovery.

Item 1 should probably be deleted from the paragraph. Items 2 and 3 are duplicated several other places. This should be fixed by the editorial changes proposed in 9.103 Sun 103.

The response was approved by the FCP-2 working group meeting on May 15, 2000.

Installation:

At the September 11, 2000 working group, Carl Zeitler was given an action item to verify that this was correctly fixed.

11.9 Compaq CommentID: 9 (Technical)

PDFPage:80 Document Page:64 ClauseSubclause: 12.3.3 Paragraph number: 2 Line: 6

Title: Addition for Class 2

Comment: Recovery Qualifier is established. The Target needs to use the next higher SEQ_CNT value, one greater than used in ABTS.

Add qualifying sentence just prior to the last sentence in the paragraph: For Class 2, the Sequence count used in the new Sequence, shall be one greater than that used to transmit the ABTS.

Response:

Accepted in principle. This must be applied to all acknowledged classes, not just class 2.

Note that this is a dumb requirement of FC-FS, which could be corrected by including SEQ_ID in the recovery_qualifier range.

The response was approved by the FCP-2 working group meeting on May 15, 2000.

Installation:

If this is actually required to be stated, it really belongs in section 12.2.2. I have inserted a reminder in that section as follows:

FC-FS requires that an ABTS(Sequence) be transmitted by a Sequence Initiator detecting a missing ACK. A recovery qualifier may be required and adjustment of subsequent sequence counts may be required as specified by FC-FS.

This resolution was approved in the September 11, 2000 working group.

11.10 Compaq CommentID: 10 (Technical)

PDFPage:80 Document Page:64 ClauseSubclause: 12.3.4 Paragraph number: 3 Line: 3

CommentType: T

Title: Qualifier for Class 2

Comment: Add sentence to end of paragraph: For Class 2, the Sequence count used in the new Sequence, shall be one greater than that used to transmit the ABTS.

Response:

Accepted in principle. This must be applied to all acknowledged classes, not just class 2.

Note that this is a dumb requirement of FC-FS, which could be corrected by including SEQ_ID in the recovery_qualifier range.

The response was approved by the FCP-2 working group meeting on May 15, 2000.

Installation:

See 11.10.

This resolution was approved in the September 11, 2000 working group.

11.11 Compaq CommentID:11 (Technical)

PDFPage: 81 Document Page: 65 ClauseSubclause:12.3.5 Paragraph number: 2 Line: Last sentence. CommentType: T

Title: Add in a new Sequence

Comment: Change the sentence to read: After transmitting the ACC for the SRR, the Target transmits an FCP_XFER_RDY, in a new Sequence, with the Relative Offset...

Response:

Accepted. The response was approved by the FCP-2 working group meeting on May 15, 2000.

Installation:

Changed as requested.

11.12 Compaq CommentID: 12 (Technical)

PDFPage: 81 Document Page:65 ClauseSubclause: 12.3.5 Paragraph number: 3 Line: 1

Title: Qualifier for Class 2

Comment: Add new Sequence and Class 2 qualifier for Sequence count. Suggested change for paragraph 3:

FCP_DATA shall be retransmitted in a new Sequence. For Class 3, the Sequence count shall start at zero, even if continuously increasing sequence count is used. For Class 2, the Sequence count shall be one greater than that used to transmit the ABTS.

Response:

Accepted in principle. The terms should be “unacknowledged classes” and “acknowledged classes”. I would suggest that for unacknowledged classes, the word “may” should be used, since I do not believe there is any requirement that they start at zero. The response was approved by the FCP-2 working group meeting on May 15, 2000.

Installation:

Changed as requested by response.

11.13 Compaq CommentID:13 (Technical)

PDFPage: 81 Document Page:65 ClauseSubclause:12.3.6 Paragraph number: 3 Line: 1

Title: Qualifier for Class 2

Comment: Add Class 3 qualifier to sentence: The Sequence count for retransmitted FCP_DATA, in class 3, shall start..... Add additional sentence: For Class 2, the starting Sequence count shall be one greater than that used to transmit the ABTS.

Response:

Accepted in principle. This must be applied to all acknowledged classes, not just class 2. The response was approved by the FCP-2 working group meeting on May 15, 2000.

Installation:

Changed as requested by response of 11.12.

11.14 Compaq CommentID:14 (Technical)

PDFPage: 82 ClauseSubclause:12.3.7 Document Page:66 Paragraph number: Line:

Title: Separate recovery procedures for Classes 2 and 3

Comment:

Trying to mimic Class 3 for this case doesn't work.

Solution: Put text currently in 12.3.7 into 12.3.7.1 FCP-CONF Recovery for Class 3.

Replace 2nd paragraph with: After the transmission of FCP_RESP and no FCP_CONF is received within R_A_TOV, the Target shall issue REC.

At end of subclause add: See D.? for an example.

Add 12.3.7.2 FCP_CONF Recovery for Class 2

If E_D_TOV expires prior to receiving the ACK to FCP_CONF, the Initiator issues ABTS. Receipt of BA_RJT indicates that FCP_CONF was received, and no recovery is necessary. If BA_ACC indicates that FCP_CONF was not received, then it is retransmitted in a new Sequence with a Sequence count one greater than used in ABTS.

Upon expiration of R_A_TOV following the receipt of BA_ACC or BA_RJT, the Initiator issues RRQ to free up the Recovery Qualifier and associated resources in the Target, if necessary. See D.?? and D.??? for examples.

Response:

This violates our basic assumption that, while the detection may be enhanced, the recovery remains unchanged. REC should be used as the recovery process. No change will be made.

In the May 15, 2000 meeting of the FCP study group, only one real problem case has been identified, involving FCP_CONF. A solution would be to constrain the use of FCP_CONF as previously proposed. Dave Peterson has some pending work on this.

This response was accepted in the June 7, 2000 meeting.

Installation:

No change was made, pending the Dave Baldwin proposal's acceptance.

11.15 Compaq CommentID:15 (Technical)

PDFPage: 83 ClauseSubclause:12.4 Document Page:67 Paragraph number: 2 Line: C)

Title: Remove option b) and c).

Comment: These options are inconsistent with the rest of the error procedures for Class 2. The a) option is all that is required.

Response:

However, the other two options will also accomplish the goal. No change is required.

After further study in the May 15, 2000 working group, the conclusion was that case c had to be removed, but that cases a and b should remain.

Installation:

Changed as resolved.

11.16 Compaq CommentID:16 (Technical)

PDFPage: 83 ClauseSubclause:12.4 Document Page:67 Paragraph number: 3 Line:

Title: Abort Perform ABTS doesn't work for out of order

Comment: Delete the paragraph. Error detection is done by the Sequence initiator.

Response:

This simplification is outside the FC-FS standard. No change is required.

After further study in the May 15, 2000 working group, the conclusion was that the target port may send ABTS-LS. My notes indicate that this depends on a time-out. The text will be reviewed.

Installation:

Section 12.4 presently applies to sequence level recovery, not exchange level recovery. For exchange level recovery, the corresponding requirement violates FC-PLDA, but could be placed in 12.1.1.

The September 11, 2000 working group agreed that there was no change required.

11.17 Compaq CommentID:17 (Editorial)

PDFPage: 83 ClauseSubclause:12.4 Document Page: 67 Paragraph number: last Line:

Title: Change text

Comment: Examples of recovery for acknowledged services are shown throughout Appendix D. for acknowledged service.

Change paragraph to:

Examples of recovery for acknowledged services are shown in Appendix D.

Response:

Accepted. (The comment was changed to editorial). The response was approved by the FCP-2 working group meeting on May 15, 2000.

Installation:

Changed as requested.

11.18 Compaq CommentID:18 (Technical)

PDFPage: 85 ClauseSubclause:12.6.2 Document Page:69 Paragraph number: 1 Line: a)

Title: Change ABTS to ABTS (LS)

Comment: To be more precise, change ABTS to ABTS (LS)

Same is also true for 16.6.3 SRR in the same respective place.

(Note that in the Ladder diagrams, D.13 and D.14, I changed E_D_TOV to 2 * R_A_TOV to agree with your text in these sections.)

Response:

Accepted. The response was approved by the FCP-2 working group meeting on May 15, 2000.

Installation:

Changed as requested.

11.19 Compaq CommentID:19 (Editorial)

PDFPage: 85 ClauseSubclause:12.7 Document Page:69 Paragraph number: last Line:

Title: Needs to be removed

Comment: Add text if applicable.

Response:

Accepted.

Installation:

Changed as requested.

11.20 Compaq CommentID:20 (Editorial)

PDFPage:87 ClauseSubclause:A.1 Document Page:71 Paragraph number: 4 Line: last

Title: Change though to through in line c)

Comment:

Response:

Accepted.

Installation:

Installed as requested.

11.21 Compaq Comment from FCP-2 editor (Technical)

Many of the comments from Compaq are further explained by the ladder diagrams contained in T10 document T10/00-137r0.pdf.

Response:

Include conclusions of latest revision of relevant documents.

Installation:

The document used was Carl Zeitler's document T10/00-137r5. All changes were installed with the following exceptions.

Carl's diagrams D13 and D13a contain essentially the same information as the corresponding diagrams in the figure in annex D "REC or REC Response Lost, Unacknowledged Classes".

The text is updated to include the additional information Carl provided, but the diagrams are not separated into two diagrams.

Carl's diagrams D.5? and D.5?? were not installed. They are two of several thousand possible examples of exchange ambiguities and multiple errors. The text and intent from the diagrams will be expressed in chapter 12. The intent to make that update is captured in 12.8.

12 Additional comments identified during ballot resolution process

12.1 FC-MI multi-initiator resolution (Technical)

Section TBD:

Some devices attempting to participate in a multi-initiator reject PRLIs if both the initiator and target bits are set. This is wrong. Some devices may also reject the presence of any other initiator.

This needs to be checked in FCP-2. The particular issue is whether or not FCP-2 has been explicit in the requirements for supporting multi-initiator operation and temporary initiator operation.

FCP-2 will discuss it further, and, if any changes are required to FCP-2 or to FC-MI, a proposal will be presented.

Response:

Section 6.2.6.11 explicitly requires the setting of both bits 4 and 5 to be allowed. This was also true in FCP, clause 6.2.6.9. The devices not meeting this requirement are not compliant with FCP-2.

After further discussion, Bill Martin in an E-mail dated 5/25/00 indicates that the real problem is that FCP-2 is not explicit about the expected behavior when both bits are set. FCP-2 will be reviewed to be sure that it is indicated that an FCP-2 device that would set both the initiator and the target bit shall accept any combination of the bits (except both set to zero) when returned by a device being logged in.

The present revision of FC-MI does not address this question. There does not appear to be any test in SANMark that specifically verifies this capability or justifies this failure. Dave Peterson will bring a proposal to the FC-MI working group.

No change is required. The response was approved by the FCP-2 working group meeting on May 15, 2000.

Installation:

No change was required.

12.2 Concern about the re-definitions of fields defined in SPC-2 (Editorial)

Section 10.1, all sub-clauses.

Gary Stephens has called attention to the definitions of protocol dependent fields in SPC-2 and FCP-2. He believes that FCP-2 should not redefine fields described in SPC-2. Ralph Weber indicates that FCP-2 presently describes the use of protocol dependent fields in a manner consistent with the text of SPC-2 and feels that there is no problem. This will be cross-checked in FCP-2, but there is not expected to be any problem.

Response:

The comment is accepted in principle. At present, no required changes have been identified, but this will be reviewed.

Installation:

No changes were made.

12.3 Mode Page 19 returned to short format

Section 10.1.3.

The MCM function has been removed from FC-AL-3.

Response:

All references to MCM are removed. In particular, clauses 10.1.3.10 through 10.1.3.13 are removed. The Mode Page 19 is shortened to its original length of 8 bytes.

Installation:

Installed as requested.

12.4 FCP support of SPC-2 fields

Section 5.2 specifies a format for fields used in SPC-2, but defined in a protocol specific manner. During the review of SPC-2, it became obvious that this format had to be modified and extended to be compliant with 7.3.4 of SPC-2.

Response:

Define “Target Identifier” and “Logical Unit Number” required by 7.3.4 of SPC-2. This information is implicitly obvious, but needs to be made explicit.

Installation:

After reviewing the SPC-2 document, it became clear that there remained only one undefined parameter, the third-party function for the RESERVE commands. All other cases are explicitly defined by SPC-2 using SAM and/or FCP conventions. The COPY command information was removed.

12.5 Correction of timing during retry

Carl Zeitler’s ladder diagrams make a text change in 12.6.2. He indicates that the time-out for ACC after a REC should be R_A_TOV instead of E_D_TOV.

Response:

Accepted.

Installation:

The text presently indicates 2 times R_A_TOV.

12.6 Correction of retry in the presence of nested failures

Carl Zeitler’s ladder diagrams make a text change in 12.6.2. He indicates that a sentence should be provided specifying that if two RECs fail, the original Exchange is aborted, regardless of class.

He further expects that any ABTS or RRQ failure should also cause the original Exchange to be aborted, but has not specified a location for such a cautionary statement.

Response:

Accepted.

Installation:

The text is changed to read:

If a response to an REC is not received within 2 times R_A_TOVELS, the SCSI initiator shall:

- 1) send an ABTS for the REC followed by an RRQ if a BA_ACC is received for the ABTS; and
- 2) send another REC in a new Exchange.

If the response to the second REC is not received within 2 times R_A_TOVELS, the SCSI initiator should ~~may~~:

- 1) send an ABTS for the REC followed by an RRQ if a BA_ACC is received for the ABTS;
- ~~2) perform a recovery abort for all outstanding exchanges for that target; and~~
- ~~3) perform an implicit logout for that target.~~

Other retry mechanisms after the second REC fails shall comply with FC-FS, but are otherwise vendor specific.

~~The REC shall be retried at a rate not to exceed once per the timeout period for at least 3 times. If none of the RECs receive a response, the initiator shall report an error condition to the ULP.~~

This also addresses problems 5.22, 9.113 Sun 113, and 11.6.

In the September 11, 2000 working group, the following additional improvements were made:

In the first “red” sentence, “may” was changed to “should”. Cases 2 and 3 in red should be removed, since they are covered by FC-FS behaviors. The text should be clarified to show that, if other retry mechanisms are used, the Exchange must still be cleared.

12.7 Correction of SRR recovery

Carl Zeidler’s ladder diagrams make a text change in 12.6.3. He indicates that a sentence should be provided specifying that for class 3, an SRR failure causes the original exchange to be aborted. In class 2, failures of SRR cause the original exchange to be aborted. In addition, the time-out value of E_D_TOV in section 12.6.3 should be changed to 2 times R_A_TOV to agree with the text in 12.6.3.

Response:

Accepted.

Installation:

The text is changed to read:

If a response to an SRR is not received within 2 times R_A_TOVELS, the SCSI initiator shall:

- 1) send an ABTS for the SRR followed by an RRQ if a BA_ACC is received for the ABTS;
- 2) may perform a recovery abort for the original exchange;
- 3) may perform a recovery abort for all other exchanges to the same target; and
- 4) may perform an implicit logout for that target

Other retry mechanisms after the SRR fails shall comply with FC-FS, but are otherwise vendor specific.

See D.30, D.31, D.32, and D.33.

This also addresses problems 5.22, 9.113 Sun 113, and 11.6.

In the September 11, 2000 working group, it was suggested that this be reformatted in the style of 12.6. That was installed. Note that the request to provide shall for both the first and second line items makes any other retry mechanisms illegal, so that option is removed from the text.

12.8 Handling of multiple errors and ambiguities

Carl Zeitler's ladder diagrams D.5? and D.5?? map two of several thousand possible ambiguities and multiple error examples. The intent of the text will be placed in chapter 12 of FCP-2 if it is not already clear there. At present, the key items of the text include:

Reuse of Exchange IDs can produce ambiguities. In the event of multiple errors, the current Exchange [I believe that should indicate all affected Exchanges] shall be aborted. The initiator shall not act on the ABTS until either the ACK to FCP_CMND is received or E_D_TOV expires.

Error recovery shall not be attempted if multiple errors, or the appearance of multiple errors, have occurred in an Exchange. One such example is the loss of both the ACK to an FCP_CMND IU and the loss of the corresponding FCP_RSP. A multiple error arises when a Recovery Qualifier has been established and then either an ABTS is received or the recovery action indicates the need to send an ABTS. The Exchange shall be aborted by issuing ABTS(Abort Sequence) if called for in the recovery process or by setting the Last_Sequence bit to one in BA_ACC with a payload of SEQ_ID invalid, Low SEQ_CNT = 0, High SEQ_CNT = FFFFh, or both.

Response:

Accepted. The intent of the text was approved in the September 11, 2000 working group meeting.

12.9 Correct LS_RJT codes

In section 12.3.2, the text "(i.e., the Initiator receives an LS_RJT for the REC with a reason code indicating the OX_ID is unknown)" should be "(i.e., the Initiator receives an LS_RJT for the REC with a reason code of Logical Error and a Reason Explanation of Invalid OX_ID-RX_ID combination, indicating the OX_ID is unknown)".

Response:

Accepted.

Installation:

Corrected in other comments.

12.10 Starting point is different for out-of-order, in-order recovery

In section 12 and in Annex D, the detection of an error requires the completion of all steps associated with the detection if certain prerequisites are not met. If delivery is guaranteed in order, the same prerequisites must be met, but the necessary waiting times are eliminated.

The prerequisites for ~~starting at the earliest possible time~~ out-of-order recovery are:

a) Continuously increasing sequence count is used.

~~b) SRR has a new bit defined that distinguishes between a desire to reset the sequence count to 0 and the desire to use the next continuously increasing sequence count.~~

~~The SRR must additionally be modified to contain the required bit.~~

Response:

In the September 11, 2000 working group, it was decided that out of order recovery requires these prerequisites. E-mail is to be published to discuss this item. I have proposed the above marked changes in the requirement in the e-mail.

12.11 Redundant description of recovery abort

The recovery abort is described with one set of words in section 12.5.2 and with a different set of words in section 9.1.2.2.

Response:

The recovery abort should be covered only one place. The proper place is 12.5.2, referenced by 9.1.2.2.

Installation:

Part of this was installed as part of the resolution of 4.547 and related comments about section 12.5. Many sections of clause 12 were affected, since we had used different terminology before this.

The referring text was installed in 9.1.2.2.

Annex D was reviewed to verify that there were no error cases where a target performed a recovery abort. All Annex D abort operations were identified as ABTS (Sequence) or ABTS(Exchange) operations.

An additional example showing recovery abort was created for Annex D.

12.12 Correction of ambiguous case for recovery

Dave Baldwin has provided a solution documented in T10/00-260r1 for a particular ambiguous recovery case. This correction was accepted by a vote of 7 in favor, 5 opposed as the least objectionable of the proposed solutions. This will be included in revision 5. It is possible that revision 6 will pick up a simplified error recovery procedure proposed by Matt Wakeley.

Response:

Accepted:

Installation:

A new section is provided in the model to describe task retry identification. Table 2 in section 4.7 is modified to reference task retry identification. (Approved, September 11, 2000)

The parameter field for commands will optionally contain a unique 32-bit handle for the command. Installed in 5.6, table 10; 5.6.11; (Approved, September 11, 2000)

REC will be brought over from FC-FS as an FC-4 Link Service. Installed in 8.1 and 8.2. (Approved, September 11, 2000).

A target or initiator transmitting REC will use the unique 32-bit handle when inquiring about a command. Installed in 8.1 and 8.2.

Requires correction of outside ruling in table 15 in 8.1 (Approved, September 11, 2000)

A note in the payload section for REC and SRR was suggested to remind people that the parameter field may need a special value. (Approved, September 11, 2000) Since this is included only two paragraphs earlier in the explicit introduction to each of the payloads, I have not installed this change.

SRR will contain the unique 32-bit handle when requesting retry of a command. Installed in 8.3.

Resources will be cleared by the target after RR_TOV, having a maximum value of 30 seconds, in order to prevent wrapping of the handle. Installed in 11.3. I changed this instead to require that the task retry identifier not be re-used within RR_TOV because of a comment raised in the September 11, 2000 working group). At the September 11 working group it was requested to allow the recovery of resources earlier than RR_TOV. After review of the text, I believe that is presently allowed. Those parts referring to recovery of FCP_RSP and associated resources were moved to 12.4.1.5.

The PRLI bit in word 3, bit 9 will be used to indicate that the handles will be used in retry. Installed in 6.2.6, table 11; 6.2.6.7; and 6.2.7, table 12. The wording was slightly improved and approved in the September 11, 2000 working group.

Re-use of an OX_ID value constitutes implicit acknowledgement that the command has been completed and that target resources associated with the previous command having the same OX_ID value can be recovered. Installed in 11.3.

During study of the installation of this, some additional corrections in 12.4.1.5 were identified.

RR_TOV should be used for case c in non-tagged and case b in the tagged description.

Case c for the tagged case should be deleted.

A special case from 11.5 was to be moved to 12.4.1.5, but I cannot identify the relevant case, so no change was made.

An additional request was made to include acknowledged classes as a special case of FCP_CONF recovery. I did not see any change that needed to be made and so made none.

12.13 Require Relative Offset in FCP_DATA IUs

As part of the correction of 5.6.11 to meet the requirements of 12.12, the use of relative offset for FCP_DATA IUs was reviewed. The relative offset should be mandatory so that either segmentation/reassembly mechanism can be exploited by any target or initiator.

Response:

Approved.

Installation:

Installed in 5.6.11. Approved in the September 11, 2000 working group meeting.

12.14 Update references

The following reference documents will be used instead of their obsolete counterparts. Text changes will result from this. Documents to be used are FC-FS (instead of FC-PH series), SAM-2 (instead of SAM), and SPC-2 (instead of SPC).

Response:

Approved.

Installation:

Global search and correction for all cases of the obsolete documents.

Removed flag bit obsolete warning in 4.2. This was approved in the September 11, 2000 working group meeting.

12.15 Remove Annex B

Because the ABTS information has been moved to FC-FS and the REC information has been moved into FCP as an FCP FC-4 Link Service, there remains no information in annex B.

The annex should be removed.

Response:

Installation:

Installed as requested. This simultaneously resolves most of the other comments on Annex B, but they will still be considered as possible improvements to the text that has been transferred.