- * Specification revision: sas1r09b
- * Page Number: 279, 534
- * Section: 7.14.4.3.1, Table K.4
- * Layer: SL CC1

* Issue Description: In the description of SL_CC1 there is no mention of how to handle received OPEN_REJECT(STP RESOURCES BUSY) which indicates that it should be ignored. We believe that there should be an additional paragraph as follows:

If this state receives an OPEN_REJECT Received (STP Resources Busy) message after transmitting the OPEN address frame, this state shall send an Open Failed (STP Resources Busy) confirmation to the port layer.

If this is accepted, then Table K.4 should add Open Failed (STP Resources Busy)

- *. Specification revision: sas1r09b
- *. Page Number: 533
- *. Section: Annex K
- *. Layer: SP

*. Issue Description: "Dword Received" confirmation from SP to Link Layer state machine receivers is not listed in Table K.2 - see 6.9.2 page 209.

- *. Specification revision: sas1r09b
- *. Page Number: 304
- *. Section: 7.16.7.1
- *. Layer: SSP Link Layer

*. Issue Description: The DONE Timeout confirmation to PL was removed in revision 08; however, figure 152 still shows the confirmation. This message should be change to "Request Break", as this is what the text says to do in this situation.