

To: Members of T10

From: Erich Oetting, SMC Technical Editor

Re: Known defects in SMC (T10/999D Revision 10a)

1. In Table 2, the Operation code for RELEASE ELEMENT (10) should be 57h instead of 56h.
2. In Table 2, the Operation Code for RELEASE ELEMENT (6) should be 17h instead of 16h.
3. In Table 2, the REZERO UNIT command is obsolete and should be removed.