

August 10, 1989

John B. Lohmeyer
Chairman X3T9.2
NCR
3718 North Rock Road
Wichita, KS 67226

Subject: ESDI SYNCHRONOUS SPINDLE CONFIGURATION PARAMETER

Dear John;

After reviewing the ESDI Working Draft rev. 3A Dated 6/23/89, I noticed some deviation from the agreement at the January SCSI/ESDI Working Committee in Costa Mesa.


There is a minor discrepancy in the "Set Configuration Parameter Bits" for "Synchronous Spindle" on page 57 Table 30.

The correction should read the following:

TABLE 30: SET CONFIGURATION SOFT SWITCH PARAMETER BITS

15 - 14	11 - 8	7 6 5 4 3 2 1 0 P
CMD FUNC	SW NO	Switch Parameter
1 1 1 0	0 0 0 0 to 0 x x x 1 0 0 0 to 1 0 1 1 1 1 0 0	Vendor Unique Reserved = 0 Set Synchronized Drive x x x x x x 0 0 = Slave x x x x x x 0 1 = Master x x x x x x 1 0 = Un synchronize
	1 1 0 1 1 1 1 0 1 1 1 1 0 0 0 1	Notched Drive Zone Number Synchronized Sector Offset Reserved = 0 x x x x x x 0 1 = Set Soft Sct x x x x x x 1 0 = Set Hard Sct

Best Regards,


Kiyotake Kumazawa
Hitachi America Ltd
Assistant Engineering Manager
617-890-0804