Date: March 29, 2007

To: T10 Committee (SCSI)

From: George Penokie (IBM)

Subject: SES-2: New element status code

1 Overview

There are cases where a SES device has elements that it can only tell certain initiator ports about. One example of this would be when elements are in different zones. This proposal adds an element status code that may be used to indicate that an initiator port does not have access to an element

2 SES-2 additions

Add into table Table 61 — ELEMENT STATUS CODE field a new row that contains the following:

Table 1 — ELEMENT STATUS CODE **field**

Code	Name	Condition	Mandatory or optional
xh	No Access Allowed	No status available because the initiator port the command was received from does not have access to this element	Optional