## SCSI-2 CAM Changes Proposal

From: Scott Smyers
   Apple Computer, Inc.
   Cupertino, CA

To: John Lohmeyer X3T9.2 Committee Chairman

Date: October 8, 1991

Subject: Proposed change in time units for Timeout Value field in CAM

The Timeout Value field in the CCB for the Execute IO function is presently defined to be a one second granularity. We anticipate some of our CAM-clients will require an even smaller timeout value than the one second minimum. We therefore propose that the time unit for this field be changed to 100 microSeconds from seconds. . Below is the revised text.

## 9.1.25  Timeout Value

This field contains the maximum period in units of 100uSec that a request can remain outstanding. If this value is exceeded then the CAM Status shall report the timeout condition. A value of 00h in the CCB means the peripheral driver accepts the SIM default timeout. A value of F...Fh in the CCB specifies an infinite period.

SCSI-2 CAM Change Proposal     1     Apple Computer, Inc.

4/7