

## 2005 T10 Mailing #2

<u>Announce</u>	<u>Description</u>	<u>File Type and Size</u>
jbl0502	Memorandum from the Chairman	<a href="#">PDF</a> (29263)
sy0502	Table of Contents	<a href="#">PDF</a> (n/a)
ann-m067	Meeting Notice: May 2-6, 2005 Oklahoma City, OK	<a href="#">PDF</a> (52646)
ann-m068	Meeting Notice: Jul 11-15, 2005 Colorado Springs, CO	<a href="#">PDF</a> (130814)
map-m067	Meeting Map: May 2-6, 2004 Oklahoma City, OK	<a href="#">PDF</a> (39082)

<u>Document Number</u>	<u>Description</u>	<u>Author</u>	<u>File Type and Size</u>
04-198r5	Background Media Scan	Gerald Houlder	<a href="#">PDF</a> (342000)
04-222r3	SAS-2 More phy test patterns	Rob Elliott	<a href="#">PDF</a> (41532)
04-262r8	ATA Command Pass-Through	Curtis Stevens	<a href="#">PDF</a> (60729)
04-333r1	SAS-1.1: PHY VACANT SMP Function Response	Robert Sheffield	<a href="#">PDF</a> (75038)
04-355r4	Response to T10 Letter Ballot comments on SPC-3	Ralph O. Weber	<a href="#">PDF</a> (2033974)
04-355r5	Response to T10 Letter Ballot comments on SPC-3	Ralph O. Weber	<a href="#">PDF</a> (2042659)
04-355r6	Response to T10 Letter Ballot comments on SPC-3	Ralph O. Weber	<a href="#">PDF</a> (2055664)
04-355r7	Response to T10 Letter Ballot comments on SPC-3	Ralph O. Weber	<a href="#">PDF</a> (2068633)
04-364r2	Add a new ADT Link Service IU - Device Reset IU	Matthew Bondurant	<a href="#">PDF</a> (19680)
04-370r3	SAS-1.1 Merge IT and IR with XT and XR	Rob Elliott	<a href="#">PDF</a> (507423)
04-378r2	SAS-1.1 Clarification of SATA Signaling Level Specification	Barry Olawsky	<a href="#">PDF</a> (2845671)
04-389r1	SPC-4: Log Page-Subpages	Kevin Butt	<a href="#">PDF</a> (76064)
04-389r2	SPC-4: Log Page-Subpages	Kevin Butt	<a href="#">PDF</a> (88034)
04-389r3	SPC-4: Log Page-Subpages	Kevin Butt	<a href="#">PDF</a> (89206)
04-397r1	SAT ATA Control Mode SubPage Proposal	Mark A Overby	<a href="#">PDF</a> (57103)
04-397r2	SAT Control Mode Page Proposal	Mark Overby	<a href="#">PDF</a> (96309)
04-397r3	SAT Control Mode Page Proposal	Mark Overby	<a href="#">PDF</a> (83828)
05-002r3	SSC-3: Sequential-Access Device log page	Kevin Butt	<a href="#">PDF</a> (19184)
05-002r4	SSC-3: Sequential-Access Device log page	Kevin Butt	<a href="#">PDF</a> (21344)
05-005r2	SES-2: Audible Alarm Element Addition	Kevin Marks	<a href="#">PDF</a> (20162)
05-010r1	SAS 1.1 External Connector Interoperability	Steven Fairchild	<a href="#">PDF</a> (162533)
05-010r2	SAS 1.1 External Connector Interoperability	Steven Fairchild	<a href="#">PDF</a> (228421)
05-010r3	SAS 1.1 External Connector Interoperability	Steven Fairchild	<a href="#">PDF</a> (226156)
05-015r2	SPC-4, SMC-3 and ADC-2: add new ADC-2 command to set Volume Identifier	Paul Entzel	<a href="#">PDF</a> (32645)
05-023r1	SAS-1.1 Connector figures	Jerry Kachlic and Rob Elliott	<a href="#">PDF</a> (951485)
05-030r1	Minutes: ADI Meeting (17 January 2005)	Michael Banther	<a href="#">PDF</a> (48943)
05-036r1	Minutes of T10 Plenary Meeting #65 - Jan 20, 2005	Weber & Lohmeyer	<a href="#">PDF</a> (236159)
05-036r2	Minutes of T10 Plenary Meeting #65 - Jan 20, 2005	Weber & Lohmeyer	<a href="#">PDF</a> (235964)
05-044r1	FCP-3 SPC-3 return check condition when FCP_DL too small	David Peterson	<a href="#">PDF</a> (41041)
05-044r2	FCP-3 SPC-3 return check condition when FCP_DL too small	David Peterson	<a href="#">PDF</a> (40321)
05-045r1	Minutes of FCP-3 Working Group - Jan 18, 2005	Bob Nixon	<a href="#">PDF</a> (19387)
05-049r0	SSC-3 Physical Device Model	Paul Suhler	<a href="#">PDF</a> (127164)
05-049r1	SSC-3 Physical Device Model	Paul Suhler	<a href="#">PDF</a> (122907)
05-052r1	Agenda for T10 Meeting #66 (March 2005)	John Lohmeyer	<a href="#">PDF</a> (67320)
05-055r0	SAS-1.1 SMP Enclosure WWN and Connector information	Steve Johnson	<a href="#">PDF</a> (27975)
05-055r1	SAS-1.1 SMP Enclosure WWN and Connector information	Steve Johnson	<a href="#">PDF</a> (28152)
05-056r0	Minutes: 19 January 2005 MMC WG Meeting Minutes	William P. McFerrin	<a href="#">PDF</a> (20109)
05-058r0	SAS-1.1 - COMWAKE Received clarification	Robert Sheffield	<a href="#">PDF</a> (79521)
05-058r1	SAS-1.1 - COMWAKE Received clarification	Robert Sheffield	<a href="#">PDF</a> (79833)
05-059r0	05-023r0 SAS-1.1 Connector figures	Dal Allan	<a href="#">PDF</a> (51699)
05-059r1	05-023r0 SAS-1.1 Connector figures	Dal Allan	<a href="#">PDF</a> (17730)
05-060r0	Project proposal for Serial Attached SCSI 2 (SAS-2)	Rob Elliott	<a href="#">PDF</a> (22233)
05-061r0	Minutes SAS-1.1 PHY WG teleconference February 3, 2005	Alvin Cox	<a href="#">PDF</a> (19956)

05-062r0	SAS 1.1 Signal Performance Measurements Annex	George O. Penokie	<a href="#">PDF</a> (125768)
05-062r1	SAS 1.1 Signal Performance Measurements Annex	George O. Penokie	<a href="#">PDF</a> (132556)
05-062r2	SAS 1.1 Signal Performance Measurements Annex	George O. Penokie	<a href="#">PDF</a> (126236)
05-063r0	SMC-3 Prioritized feature list	Susan Gray	<a href="#">PDF</a> (25714)
05-064r0	SES-2 Additional Element Status diagnostic page Valid bit	Rob Elliott	<a href="#">PDF</a> (44006)
05-064r1	SES-2 Additional Element Status diagnostic page Valid bit	Rob Elliott	<a href="#">PDF</a> (54116)
05-065r0	Minutes SAS-1.1 PHY WG teleconference February 10, 2005	Alvin Cox	<a href="#">PDF</a> (23990)
05-066r0	SSC-3: Obsolete GAP SIZE field	David Peterson	<a href="#">PDF</a> (6768)
05-067r0	SSC-3: Obsolete RSMK and setmarks	David Peterson	<a href="#">PDF</a> (6661)
05-068r0	SSC-3: Mode page support	David Peterson	<a href="#">PDF</a> (13707)
05-069r0	SAS-1.1 Transient during OOB	Alvin Cox	<a href="#">PDF</a> (19324)
05-070r0	SMC-3 Open/Close element command	Noud Snelder	<a href="#">PDF</a> (19298)
05-071r0	ISO/IEC SCSI Part Number Score Card	Ralph O. Weber	<a href="#">PDF</a> (23328)
05-072r0	SPC-3 Subclause 5.2 (Mandatory Commands) Rewrite	Ralph O. Weber	<a href="#">PDF</a> (34369)
05-072r1	SPC-3 Subclause 5.2 (Mandatory Commands) Rewrite	Ralph O. Weber	<a href="#">PDF</a> (30940)
05-072r2	SPC-3 Subclause 5.2 (Mandatory Commands) Rewrite	Ralph O. Weber	<a href="#">PDF</a> (34917)
05-073r0	SPC-3 Report target port group transitioning support	Rob Elliott	<a href="#">PDF</a> (15795)
05-073r1	SPC-3 Report target port group transitioning support	Rob Elliott	<a href="#">PDF</a> (17384)
05-074r0	SPC-3 SPC-4 SES-2 SMC-3 Command requirements	Rob Elliott	<a href="#">PDF</a> (37107)
05-074r1	SPC-3 SPC-4 SES-2 SMC-3 Command requirements	Rob Elliott	<a href="#">PDF</a> (57937)
05-075r0	SAS-1.1 OOB Signal Transmitter Requirements	Neil Wanamaker	<a href="#">PDF</a> (11607)
05-076r0	Minutes SAS-1.1 PHY WG teleconference February 17, 2005	Alvin Cox	<a href="#">PDF</a> (28139)
05-077r0	Summary of current SAS-SATA OOB Algorithm	Bill Bissonette	<a href="#">PDF</a> (171594)
05-077r1	Summary of current SAS-SATA OOB Algorithm	Bill Bissonette	<a href="#">PDF</a> (336555)
05-078r0	SMC-3 Extended device capabilities	Noud Snelder	<a href="#">PDF</a> (39094)
05-079r0	Minimum XR/IR Receiver Signal Level for 3Gb SATA Mode	Barry Olawsky	<a href="#">PDF</a> (42573)
05-079r1	Minimum XR/IR Receiver Signal Level for 3Gb SATA Mode	Barry Olawsky	<a href="#">PDF</a> (42851)
05-079r2	Minimum XR/IR Receiver Signal Level for 3Gb SATA Mode	Barry Olawsky	<a href="#">PDF</a> (118482)
05-079r3	Minimum XR/IR Receiver Signal Level for 3Gb SATA Mode	Barry Olawsky	<a href="#">PDF</a> (121232)
05-080r0	FCP-3: Use of fill bytes in FCP_DATA IUs	Gerald Houlder	<a href="#">PDF</a> (71712)
05-080r1	FCP-3: Use of fill bytes in FCP_DATA IUs	Gerald Houlder	<a href="#">PDF</a> (73647)
05-081r0	SAM-4 task management function lifetime	Rob Elliott	<a href="#">PDF</a> (18164)
05-081r1	SAM-4 task management function lifetime	Rob Elliott	<a href="#">PDF</a> (18426)
05-082r0	2005 Five-Year Maintenance Review of INCITS Standards	Parthenia Purnell	<a href="#">PDF</a> (73750)
05-083r0	SAS-1.1 PHY transmitter and receiver electrical table updates	Alvin Cox	<a href="#">PDF</a> (82056)
05-083r1	SAS-1.1 PHY transmitter and receiver electrical table updates	Alvin Cox	<a href="#">PDF</a> (125380)
05-083r2	SAS-1.1 PHY transmitter and receiver electrical table updates	Alvin Cox	<a href="#">PDF</a> (126711)
05-084r0	SAS 1-1 Compact Connectors (Internal and External)	Jay Neer	<a href="#">PDF</a> (1224333)
05-084r1	SAS 1-1 Compact Connectors (Internal and External)	Jay Neer	<a href="#">PDF</a> (961971)
05-084r2	SAS 1-1 Compact Connectors (Internal and External)	Jay Neer	<a href="#">PDF</a> (898205)
05-085r0	Style Guide	George O. Penokie	<a href="#">PDF</a> (545883)
05-085r1	Style Guide	George O. Penokie	<a href="#">PDF</a> (545591)
05-086r0	SAS-1.1 Link layer timeout race conditions	Rob Elliott	<a href="#">PDF</a> (564208)
05-087r0	Minutes SAS-1.1 PHY WG teleconference February 24, 2005	Alvin Cox	<a href="#">PDF</a> (24408)
05-088r0	Minutes of SAT Working Group - Feb 24-25, 2005	Mark Evans	<a href="#">PDF</a> (143742)
05-089r0	SAS-1.1: Discovery Process Missing Route Table Rules	Steve Johnson	<a href="#">PDF</a> (28906)
05-089r1	SAS-1.1: Discovery Process Missing Route Table Rules	Steve Johnson	<a href="#">PDF</a> (29640)
05-090r0	T11 Liaison Report, Feb, 2005	Robert Snively	<a href="#">PDF</a> (10722)
05-091r0	ADT-2: update to SAM-3, SPC-3, and ADC-2	Paul Entzel	<a href="#">PDF</a> (20491)
05-092r0	ISO Status Report March 2005	Gary S. Robinson	<a href="#">PDF</a> (55421)
05-092r1	ISO Status Report March 2005	Gary S. Robinson	<a href="#">PDF</a> (64224)
05-093r0	SAS-1.1, Responding to an OPEN address frame while in the BreakWait state	Mark Evans	<a href="#">PDF</a> (76952)
05-093r1	SAS-1.1, Responding to an OPEN address frame while in the BreakWait state	Mark Evans	<a href="#">PDF</a> (85567)
05-094r0	Minutes of SAS Protocol Working Group - Mar 7, 2005	Weber & Lohmeyer	<a href="#">PDF</a> (59716)
05-095r0	Minutes of SAT Working Group - Mar 8, 2005	Mark Evans	<a href="#">PDF</a> (101981)
05-096r0	Minutes of CAP Working Group - Mar 8-9, 2005	Weber & Lohmeyer	<a href="#">PDF</a> (69431)
05-097r0	Minutes of T10 Plenary Meeting #66 - Mar 10, 2005	Weber & Lohmeyer	<a href="#">PDF</a> (268138)

05-098r0	SAS-1.1 External cable intra-pair skew	Rob Elliott	<a href="#">PDF</a> (15234)
05-099r0	Minutes SAS-1.1 PHY WG teleconference March 3, 2005	Alvin Cox	<a href="#">PDF</a> (21046)
05-100r0	SAS-1.1 Compact connector sideband usage	Rob Elliott	<a href="#">PDF</a> (24170)
05-101r0	SBC-2 Validation of Protection Information	William Martin	<a href="#">PDF</a> (10464)
05-101r1	SBC-2 Validation of Protection Information	William Martin	<a href="#">PDF</a> (11820)
05-102r0	SAS-1.1 Annex J Missing Confirmations	William Martin	<a href="#">PDF</a> (11640)
05-103r0	SAS-1.1 State Transition Ambiguity	William Martin	<a href="#">PDF</a> (10589)
05-104r0	FCP-3: Working Group Agenda (3/8/05)	David Peterson	<a href="#">PDF</a> (9634)
05-105r0	SSC-3 Working Group Agenda (3/9/05)	David Peterson	<a href="#">PDF</a> (10208)
05-106r0	SAS 1.1 - Link and Port layer state machine fixes	George O. Penokie	<a href="#">PDF</a> (163791)
05-106r1	SAS 1.1 - Link and Port layer state machine fixes	George O. Penokie	<a href="#">PDF</a> (206935)
05-107r0	SAS-1.1 SAM-4 Overlapped tag handling	Rob Elliott	<a href="#">PDF</a> (233581)
05-107r1	SAS-1.1 SAM-4 Overlapped tag handling	Rob Elliott	<a href="#">PDF</a> (233339)
05-109r0	SAT REQUEST SENSE Correction Proposal	Mark Overby	<a href="#">PDF</a> (21206)
05-110r0	Minutes of SAS Phy Working Group - Mar 8, 2005	Alvin Cox	<a href="#">PDF</a> (48229)
05-110r1	Minutes of SAS Phy Working Group - Mar 8, 2005	Alvin Cox	<a href="#">PDF</a> (48862)
05-111r0	Minutes: SSC-3 (Mar 9, 2005)	Kevin Butt	<a href="#">PDF</a> (41714)
05-112r0	Minutes of ADI Meeting (7 March 2005)	Michael Banther	<a href="#">PDF</a> (60934)
05-113r0	Minutes of FCP-3 Protocol Working Group - Mar 7, 2005	Bob Nixon	<a href="#">PDF</a> (21838)
05-114r0	SAS Updates to Discover example	Steven Fairchild	<a href="#">PDF</a> (177091)
05-115r0	ADC-2 TapeAlert Response Parameter TSD Bit	Michael Banther	<a href="#">PDF</a> (73342)
05-117r0	SNIA Liaison Report to T10	Roger Cummings	<a href="#">PDF</a> (22038)
05-118r0	Minutes: SMC-3 March 7, 2005	Susan Gray	<a href="#">PDF</a> (28632)
05-119r0	STA T10 Update - March 10, 2005	Marty Czekalski	<a href="#">PDF</a> (128189)
05-121r0	Agenda for T10 Meeting #67 (May 2005)	John Lohmeyer	<a href="#">PDF</a> (67401)
05-122r0	T10 Project Summary - March 2005	John Lohmeyer	<a href="#">PDF</a> (53835)
05-123r0	Jeopardy Letter for May 2005 meeting	John Lohmeyer	<a href="#">PDF</a> (100140)
05-124r0	ADT-2 Remove Restriction When Max ACK Offset Equals Zero	Michael Banther	<a href="#">PDF</a> (62349)
05-125r0	Letter Ballot on forwarding SAS-1.1 to first public review	John Lohmeyer	<a href="#">PDF</a> (115781)
05-129r0	ADC-2 NOTIFY DTD UA Creation Denied	Michael Banther	<a href="#">PDF</a> (53057)

<u>Description</u>	<u>Rev PL / Editor</u>	<u>File Size</u>
Automation/Drive Interface - Commands - 2 (ADC-2)	00 Suhler / Entzel	<a href="#">PDF</a> (469167)
Automation/Drive Interface - Transport Protocol - 2 (ADT-2)	00 Suhler / Entzel	<a href="#">PDF</a> (1108495)
Fibre Channel Protocol - 3 (FCP-3)	03e David Peterson	<a href="#">PDF</a> (929313)
MultiMedia Command Set - 5 (MMC-5)	01b Bill McFerrin	<a href="#">PDF</a> (3812489)
SCSI / ATA Translation	02 Bob Sheffield	<a href="#">PDF</a> (1142025)
SCSI Architecture Model - 4 (SAM-4)	02 George Penokie	<a href="#">PDF</a> (1011494)
SCSI Enclosure Services - 2 (SES-2)	10 Rob Elliott	<a href="#">PDF</a> (809054)
SCSI Enclosure Services - 2 (SES-2)	11 Rob Elliott	<a href="#">PDF</a> (761102)
SCSI Primary Commands - 3 (SPC-3)	21d Ralph Weber	<a href="#">PDF</a> (3046546)
SCSI Primary Commands - 3 (SPC-3)	21e Ralph Weber	<a href="#">PDF</a> (3053516)
SCSI Primary Commands - 3 (SPC-3)	22 Ralph Weber	<a href="#">PDF</a> (3046396)
SCSI Stream Commands - 3 (SSC-3)	01c Dave Peterson	<a href="#">PDF</a> (906791)
Serial Attached SCSI - 1.1 (SAS-1.1)	08 Rob Elliott	<a href="#">PDF</a> (5711595)
Serial Attached SCSI - 1.1 (SAS-1.1)	09 Rob Elliott	<a href="#">PDF</a> (6092111)
Serial Attached SCSI Driver Interface (SDI)	00 Rob Elliott	<a href="#">PDF</a> (461201)