

Outstanding Standards Contributions regarding ISO/IEC JTC 1/SC 25/WG 4					Gary S Robinson 2/22/2002
				03/06/02	
Project No.	Short Title	Project #	last doc. published	Date	GSR Comments from/for T1n
	FDDI				
1.25.13.01.03	FDDI PHY		IS 9314-1:1989		
1.25.13.01.04	FDDI MAC		IS 9314-2:1989		
1.25.13.01.05	FDDI PMD		IS 9314-3:1990	10/19/01	We do not need to revise (replace EIA ref with IEC ref) N575, FAP12
1.25.13.01.06	FDDI SMF-PMD		IS 9314-4:1999		
1.25.13.01.07	FDDI HRC		IS 9314-5:1995	07/01/01	5yr review confirmed 25n727
1.25.13.01.08	FDDI SMT		IS 9314-6:1998		
1.25.13.01.09	FDDI LCF-PMD		IS 9314-9:2000		
1.25.13.01.10	FDDI TP-PMD		FCD 9314-10 (in 01/00)	10/19/01	Need FDIS text, FAP13, Ask NCITS if there is any need for this project
1.25.13.01.11	FDDI MAC-2		IS 9318-8:1998		
1.25.13.01.12	FDDI PHY-2		IS 9314-6:1998		
1.25.13.01.15	FDDI CT-PICS		IS 9314-13:1998		
1.25.13.01.20	FDDI PMD-ATS		IS 9314-20:2001		
1.25.13.01.21	FDDI PHY-ATS		IS 9314-21:2000		
1.25.13.01.25	FDDI SMT-ATS		IS 9314-25:1998		
1.25.13.01.26	FDDI MAC-ATS		IS 9314-26:2001		
	IPI				
1.25.13.10.09	IPI-3 Tape	505-m, X3.290:1997	IS 9318-4:1990 -- DIS 18353 as revision (in 02/99)	02/04/02	In publication process, Questions from ISO to RC on delta between revisions answered
1.25.13.10.18	Responsive Link		none		waiting for NWIP from Japan
	SCSI				
1.25.13.10.13, 1.25.13.11.01	SCSI-2	0375-m	IS 9316:1995	07/01/01	5yr review confirmed, 25n727
1.25.13.11.02	SCSI-2 CAM		IS 9316-2:2000		
1.25.13.11.03	SCSI-3 SPC	0995-m	CD 14776-311 (in 11/97)	08/31/01	Auto withdrawal in JTC1, US to drop, T10 motion 092001
1.25.13.11.08	SCSI-3 SAM	0994-m	IS 14776-411:1999	09/11/01	Editorial error being corrected by WVP for next review cycle
1.25.13.11.10	SCSI-3 SBC	0996-m	FCD 14776-321 (in 09/00)	02/04/02	DoC n712A, FDIS ballot, standard is n631, aproved via T10 LB T10-259r0/01-260r0, FDIS approved, GSR needs to send final text
1.25.13.11.11	SCSI-3 SSC	0997-d	FCD 14776-331 (in 6/01)	01/09/02	DoC n709a, nxst FCD n717, need FDIS text and DoC (709a ?), T10 motion 092001, FDIS ballot begun, n761, sent to ITTF for publishing
1.25.13.11.nm	SCSI-3 SSC2	1434-d			
1.25.13.11.13	SCSI-3 SMC	0999-m	CD 14776-351 (in 04/98)	02/22/02	N799, Sent FCD text, DoC is N582 Erich Oetting, WVP fixed text, made .DOC, sent to EO for review
1.25.13.11.15	SCSI-3 SCC		IS 14776-341:2000	09/11/01	published, should be withdrawn next review cycle
1.25.13.11.16	SCSI OMC		IS 14776-381:2000	10/11/01	published, US comments by RW too late, not included, I have comment
1.25.13.11.17	SCSI MMC-2	1228-d	FCD 14776-362 (in 11/00)	02/07/02	Approved NP N706, and CD 4/2001, voting of CD in N610, sent DoC to WVP, RoC n718, FDIS sent to ITTF, T10 motion 092001to disapprove with comments, vote sent, FDIS over, GSR sent sample text to RR for him to generate final text with correction.
1.25.13.11.18	SCSI FCP-2	1144-d	NCITS 350	02/22/02	waiting for NP and document, in PR resolving comments, BS, T10 motion 092001 for NP, GSR did NWIP
1.25.13.11.19	SCSI SAM-2	1157-d	none	09/11/01	In development
1.25.13.11.20	SCSI SBP-2	1155-m	DIS 14776-232 (in 03/00)	01/04/02	FT, DIS n677,xst IS, et sent to GVA & WVP, PJ editor, waiting for publication, Status from Jurgen
1.25.13.11.21	SCSI SPI-2	1142-m	FCD 14776-112 (in 03/01)	02/04/02	G P Editor, sent to GVA for final processing, FDIS approved, need revised patent letter, waiting for RE patent letter
1.25.13.11.22	SCSI-3 SES	1212-m	CD 14776-371 (in 04/98)	02/04/02	waiting for FCD text DoC, N529, need status, BS, FAP3, JBL to send RS source
1.25.13.11.23	SCSI SCC-2	1225-m	IS 14776-342:2000	08/31/01	published

1.25.13.11.25	SCSI RBC	1240-d	FCD 14776-326 (in 6/01)	01/04/02	CoC n684 CD, nxst FDIS, Sent et & DoC WVP, DoC 714, FCD n715 ballot, RW, T10 motion 092001 to disaprove with comments, need to update text and send to WVP for FDIS ballot, should be out for FDIS ballot, status where is ballot GSR ???
1.25.13.11.26	SCSI SPI-3	1302-d	FCD 14776-113 (in 08/00)	02/13/02	Editor GP, FCD Approved, CoC SC 25 N 683, sent to GP for DoC and updating, DoC finished, text updated, send to WVP, T10 motion 092001, FAP4, FDIS ballot has AFNOR NO comment about connector reference
1.25.13.11.27	SCSI SPC-2	1236-d	none	02/13/02	waiting for NP and document, , T10 motion 092001 for NP, NWIP done and sent to DD, Need vote at NCITS, document ready in ISO style
1.25.13.11.28	SCSI SPI-4	1365d	none	02/22/02	in development GSR did NWIP
1.25.13.11.29	SCSI MMC-3	1363-d	none	09/11/01	need NP motion in Nov 2001
1.25.13.11.30	SCSI RMC	1364-d	none	31/08/01	cancelled
1.25.13.11.31	SCSI SBC-2	1417-d	none	09/11/01	in development
1.25.13.11.32	SCSI SST	1380-d	none	09/11/01	in development
1.25.13.11.33	SCSI SPC-3	1416-d	none	09/11/01	starting development
1.25.13.11.34	SCSI SRP	1415-d	none	09/11/01	in development
	OSD	1355-d			
	SDV	1378-DT			
	SMC-2	1383-D			
	PIP	1439-D			
	SSM	1414-DT			
	MMC	1048-M			
	SBP-2	1467-D			
	HIPPI				
1.25.13.12.01	HIPPI-PH	667-m, X3.183:19 91	IS 11518-1:1995	07/01/01	5yr review reaffirmed, 25n727
1.25.13.12.02	HIPPI-FP		IS 11518-2:2000		
1.25.13.12.03	HIPPI-LE	825-M, NCITS 218:2000	IS 11518-3:1996	08/01/01	5yr review reaffirmed
1.25.13.12.06	HIPPI-SC	818-M, NCITS 222:1997	IS 11518-6:2000		
1.25.13.12.08	HIPPI-ATM	1026-D, X3.299:19 97	IS 11518-8:1999		
1.25.13.12.09	HIPPI-Serial	1117-D, X3.300	IS 11518-9:1999		
1.25.13.12.10	HIPPI-6400-PH	1213-M, NCITS 323:1998	IS 11518-10:2001	03/21/01	Published
1.25.13.12.11	HIPPI-6400-SC	1231-M, NCITS 324:1999	none	10/19/01	waiting for text for FT, cancel international project, FAP6
1.25.13.12.12	HIPPI-6400-OPT	1249-D, NCITS 338:	none	10/19/01	waiting for text for FT, cancel international project, FAP6
	FC				
1.25.13.13.01	FC-PH	x3.230:19 94	DIS 14165-111 (in 05/98)	08/31/01	Document not available, request withdrawal in future, to be replaced by PI and FS
1.25.13.13.02	SCSI-3 FCP	0993-m	CD 14776-221 (in 04/98)	02/04/02	need FCD text and DoC, FAP7, should be replaced by FCP-2, RS, requested WG4 via email to JM 26 Oct to replace, approved, replaced by FCP-2
1.25.13.13.04	FC-FP		IS 14165- 211:1999		
1.25.13.13.05	FC-FG	958-M, X3.289:19 96	IS 14165- 141:2001	08/31/01	published
1.25.13.13.06	FC-AL-2	1133-M, NCITS 332:1999	FCD 14165-122 (in 11/00)	02/04/02	CoC N705, FCD DoC generated, HT making changes to .WP file, nxst FDIS ballot, need to send DoC and text to WVP, US may make comments at FDIS ballot, make motion for NO vote after text is sent, reminded HT 11/30/01, STATUS

1.25.13.13.11	FC-SB-2	1357-D, NCITS 349:	NWIP approved (in 02/96)	02/06/02	<i>NWIP approved, GSR needs to send FCD text with ISO changes, motion to forward doc and resind FT T11 10/01, text needs to be converted to ISO in .FM, I sent Sample to RD</i>
1.25.13.13.12	FC-SW	959-D, NCITS 321:1998	IS 14165- 131:2000	08/31/01	<i>published</i>
1.25.13.13.14	FC-PH-2	901-D, x3.297:19 97	CD 14165-112 (in 10/96)	08/31/01	<i>to be dropped, see 1.25.13.13.01</i>
1.25.13.13.15	FC-GS-2	1134-M, NCITS 288:1999	NWIP approved (in 02/96)	02/04/02	<i>14165-412, JTC1 N5881/N6025, waiting for FCD text, FAP8, should be replaced by GS-3, requested WG4 via email to JM 26 Oct to replace, Approved, to be replaced by GS-3</i>
1.25.13.13.16	FC-PH-3	1119-M, X3.303:19 98	CD 14165-113 (in 10/96)	08/31/01	<i>to be dropped, see 1.25.13.13.01</i>
1.25.13.13.18	FC-AV	1237-D, NCITS 356:	14165-321	02/22/02	<i>waiting for NP, FAP9, GSR did NWIP</i>
1.25.13.13.NN	FC-AV-2	1504-D	14165-321	02/07/02	<i>waiting for NP, in development, but may be cancelled for lack of interest</i>
1.25.13.13.20	FC-BB	1238-D, NCITS 342:	14165-241	02/06/02	<i>SC25 issued NWIP, MR editor, completed public review, may add BB-2, need FCD text, FAP10, T11 motion to approve NP in Oct 2001, Text should be available 8/2002</i>
1.25.13.13.21	FC-100-TP	not USA	NP14165-114	02/04/02	<i>Draft available, TC wants US to vote NO, need motion at 2/2002 meeting</i>
1.25.13.13.22	FC-FS	1331-D	Res14165-251	10/19/01	<i>JTC! N5813, need NP, in development</i>
1.25.13.13.23	FC-GS-3	1356-M, NCITS 348:2001	Res14165-413	02/04/02	<i>need NP, use GS-2 project, GSR to do</i>
1.25.13.13.24	FC-PI	1306-D, NCITS 352:	Res14165-115	08/31/01	<i>need NP, need status</i>
1.25.13.13.25	FC-SW-2	1305-D, NCITS 355:	Res14165-132	08/31/01	<i>need NP, need status</i>
1.25.13.13.26	FC-VI	1332-D, NCITS 357:	Res14165-331	02/22/02	<i>GSR did NWIP</i>
1.25.13.13.NN	FC-BB-2	1466-D			
	ST				
1.25.13.14.01	ST		none	10/19/01	<i>in development, FAP11</i>
1.25.13.14.02	ST-API	1333-D	none	10/19/01	<i>in development, FAP11</i>
1.25.13.14.nn	ST-RTP	1418-M, NCITS 343:2001	none	04/12/01	<i>Motion to withdraw failed @ T11 4/01 meeting,</i>
	HPSB				
1.25.13.15.01	HPSB, 1394		none	02/04/02	<i>NP in ballot in US, T10 approved NWIP motion 092001, document still being prepared, NPIW ready for ballot, IEEE completed copyright letter</i>
1.25.13.15.02	HPSB, 1394.1		none		
1.25.13.15.03	PPDT, 1394.3		none		
	former SC26 projects: Microprocessor Architecture				
1.25.26.01.01	Bin Flpt Arithm	754	IEC 60559:1989	08/31/01	<i>Reaffirm, Pritchard wants to revise, do we revise or reaffirm ?</i>
1.25.26.01.02	MUFOM		IEC 60975:1989	08/31/01	<i>withdrawn</i>
1.25.26.01.03	CSR		IS 13213:1994	08/31/01	<i>confirmed 5yr</i>
	former SC26 projects: Bus Architecture				
1.25.26.02.01	Multibus I - Part 1		IEC 60796- 1:1990		
1.25.26.02.02	Multibus I - Part 2		IEC 60796- 2:1990		

1.25.26.02.03	Multibus I - Part 3		IEC 60796-3:1990		
1.25.26.02.04	VMEbus		IEC 60821:1991, IEC 60821-am1:1999	08/31/01	<i>confirm</i>
1.25.26.02.05	VSB, VMEbus parallel		IEC 60822:1988	08/31/01	<i>confirm</i>
1.25.26.02.06	VSSbus, VMEbus serial		IEC 60823:1990	08/31/01	<i>drop</i>
1.25.26.02.07	Futurebus+		IS 10857:1994	08/31/01	<i>drop</i>
1.25.26.02.08	STEBus		IS 10859:1997		
1.25.26.02.09	Multibus II		IS 10861:1994		
1.25.26.02.10	VICbus		IS 11458:1993, IS 11458-am1:2000	08/31/01	<i>published</i>
1.25.26.02.11	SCI		IS 13961:2000	08/31/01	<i>published</i>
1.25.26.02.12	Futurebus+ Profile M		IS 14536:1995	08/31/01	<i>need status</i>
1.25.26.02.13	HIC		IS 14575:2000	08/31/01	<i>published</i>
1.25.26.02.14	STbus		IS 14576:1999	08/31/01	<i>published</i>
1.25.26.02.15	Sbus		IS 15205:2000	08/31/01	<i>published</i>
1.25.26.02.16	VME64		IS 15776:200X	01/09/02	<i>published</i>
1.25.26.03.01	Terminology		IEC 60824:1988		
1.25.26.03.02	Pin allocations		IEC 60828:1988		
Note(s):					