# Summary of Comments on Serial Attached SCSI Standard

# Author: ADPT

Date: 1/31/2003 4:17:43 PM

Page: i Sequence number: 4 Date: 1/30/2003 5:55:52 PM Type: Note ACCEPT - DONE (adopted Mark Evans' proposed terminology changes) 1.0 References to ATA through-out the draft need to be reviewed and changed to SATA where necessary. The interface protocol that SAS implements is SATA. SATA specification in turn references ATA as the upper layer protocol. Page: 8 Sequence number: 14 Date: 1/30/2003 5:58:38 PM Type: Note REJECT (only one use of that term at this time this comment was reviewed, in the port introduction; changed it to use "identification sequence") 2.0 The term "initialization" is used in 3 places. It should be added to the definitions sub-clause. Page: 8 Sequence number: 15 Date: 1/30/2003 6:01:22 PM Type: Note **REFER PROTOCOL WG** 3.0 The term "idle" used through-out the draft has conflicting meanings. Sometimes it refers to "idle time" and other times to "no activity". We should use "idle time" or "idle dwords" or "no activity". Page: 24 Sequence number: 9 Date: 1/22/2003 3:32:17 PM Type: Note REJECT (initiator could support SATA to talk to a SATA-only target port, but STP won't help)(whole section being deleted anyway) 4.0 P24, 4.1.6 2nd para - Last sentence reads "included in SAS domains if the expander device". S/B "included in SAS domains if the Initiator or expander device" Page: 30 Sequence number: 12 Date: 1/23/2003 5:04:38 PM Type: Note ACCEPT - DONE 5.0 P30, 5th para - "physical links that make up to pathway", S/B "physical links that make up the pathway". Page: 66 Sequence number: 4 Date: 1/31/2003 4:01:23 PM Type: Note ACCEPT - DONE (per SAS PHY WG Accept. Update all cable and backplane figures to reflect power and port capabilities) 6.0 P66, Figure 33 Internal backplane environment - It is unclear where power for the target device is derieved. Page: 68 Sequence number: 6

Type: Note ACCEPT - DONE (per SAS PHY WG Change AR+/-, AT+/-, BR+/-, and BT+/- to RP+/-, TP+/-, RS+/-, and TS+/- respectively. Resolves both Adaptec comments without adding a SATA column to table 30.) 7.0 P68, Table 30 - For clarification, a SATA column S/B added that clearly shows that the connections are the same. Page: 68 Sequence number: 7 Date: 1/31/2003 4:17:50 PM Type: Note ACCEPT - DONE (per SAS PHY WG Change AR+/-, AT+/-, BR+/-, and BT+/- to RP+/-, TP+/-, RS+/-, and TS+/- respectively. Resolves both Adaptec comments without adding a SATA column to table 30.) 8.0 P68, Table 30 - Name Column - Names should match SATA to resolve confusion. Refer to figure 6 in SATA 1.0. Use the same terminology used in Table 31 for Rx and Tx signals. Page: 71 Sequence number: 21 Date: 1/31/2003 4:44:13 PM Type: Note REJECT (per phy WG - Active is not determined by the cable assembly.) 9.0 P71, 5.4.2 2nd para - S/B "one, two, three, or four active physical links". Page: 72 Sequence number: 10 Date: 1/31/2003 4:47:16 PM Type: Note ACCEPT - DONE (with "defined by this standard". Per phy WG: Resolve ADPT comment by changing "characteristic tables to: characteristics within this standard) 10.0 P72, 5.7.1 1st para - Is "transmitter and reciever characteristic tables, See Tables 35 & 36, only". Page: 73 Sequence number: 2 Date: 2/9/2003 11:23:37 AM Type: Note ACCEPT - DONE (Accept connector designation, reject distance. Figures will be updated.) 11.0 P73, Figure 35 & 36 - distance from connector pin to loads S/B specified. The connector should also be identified. Page: 74 Sequence number: 6 Date: 1/31/2003 4:55:26 PM Type: Note ACCEPT - DONE 12.0 P74, Table 34 - note b - refer to the SATA 1.0 specification Page: 77 Sequence number: 7 Date: 1/20/2003 5:14:04 PM Type: Note REJECT (per phy WG: Not needed with incorporation of OOB characteristics in Table 35.) 13.0 P77, Top of page - add a new sub-clause 5.7.4.1 Page: 82 Sequence number: 11 Date: 1/31/2003 5:50:23 PM Type: Note **REFER PHY WG** 14.0 P82, 5.7.11, 3rd para - Is "specification of the external, initiator, expander .....device transmitter". S/B "specification of the initiator, expander .....device transmitter". What is an external device transmitter? Page: 94 Sequence number: 1 Date: 1/20/2003 5:40:32 PM Type: Note REJECT (per SAS phy WG, Reject. The text is not in error.)

15.0 P94, 6.5 1st para - "signals are low-speed signal patterns detected". S/B "signals are low-speed envelope patterns detected".

Page: 97 Sequence number: 9 Date: 1/8/2003 2:09:38 PM Type: Note REJECT (for OOB signal detection, all rates up to the highest speed must be supported) 16.0 P97, 3rd para - e.g. should read "a SAS reciever shall support its current speed and one generation less. A 3.0Gbps reciever shall support 1.5Gbps, a 6.0Gbps reciever need only support 3.0Gbps. The transmitter and reciever portion of the PHY shall support the same rate. Page: 98 Sequence number: 4 Date: 1/8/2003 2:28:41 PM Type: Note ACCEPT - DONE (added receiving but not primitive, since it's a primitive sequence) 17.0 P98, 6.6.1, last sentence - "After a HARD RESET a device" S/B "After reciept of a HARD RESET primitive a device". Page: 104 Sequence number: 8 Date: 1/9/2003 3:33:55 PM Type: Note REJECT (but will remove the whole sentence) 18.0 P104, Table 49 -RCD - comments- reads "Used by transmitter and receiver to calculate the speed negotiation window time." S/B "Used by transmitter and reciever to indicate the speed negotiation window is beginning." Page: 104 Sequence number: 9 Date: 1/24/2003 3:07:10 PM Type: Note REJECT (but the receiver times are being deleted) 19.0 P104, Table 49 3rd row - "(SNTT for reciever)" S/B "(SNTR for reciever)" Page: 104 Sequence number: 10 Date: 1/24/2003 3:07:04 PM Type: Note REJECT (but the receiver times are being deleted) 20.0 P104, Table 49 6th row - "(SNLT for reciever)" S/B "(SNLR for reciever)" Page: 105 Sequence number: 3 Date: 1/9/2003 4:11:03 PM Type: Note ACCEPT - DONE (just remove "receiving") 21.0 P105, 1st sentence- "If the recieved phy supports the physical link rate...." S/B "If the phy supports the recieved physical link rate...." Page: 106 Sequence number: 5 Date: 1/9/2003 4:26:07 PM Type: Note ACCEPT - DONE (added "sequence" here and in prev paragraph) 22.0 P106, 1st sentence - "...SAS phy fails speed negotiation, it shall....." S/B "...SAS phy fails speed negotiation at all supported rates, it shall ..... " Page: 138 Sequence number: 15 Date: 1/8/2003 1:02:38 PM Type: Note ACCEPT - DONE 23.0 P138, 7.1.4.9, 4th para - TBD?

Sequence number: 11 Date: 1/8/2003 1:18:00 PM Type: Note ACCEPT - DONE 24.0 P143, 7.1.6.5, delete "used as" Page: 151 Sequence number: 5 Date: 1/24/2003 7:15:16 PM Type: Note ACCEPT - DONE (changed all "device" to "port" and made sure all are defined in ch3) 25.0 P151, clarify what is a SMP target/initiator? Page: 161 Sequence number: 8 Date: 1/22/2003 5:27:09 PM Type: Note REJECT (whole section deleted)(comment is correct; if left in, need to show gating off the output and input) 26.0 P161, Figure 68 - the figure does not match the verbage on the previous page - sub-clause 7.10. Page: 229 Sequence number: 25 Date: 1/6/2003 6:15:51 PM Type: Note ACCEPT - DONE (it was called TIMEOUT in the table) 27.0 P229, the RETRANSMIT bit shall. Where is the bit shown in the SSP Frame format table 88 or table 96? Page: 240 Sequence number: 13 Date: 2/2/2003 2:01:55 PM Type: Note ACCEPT - DONE 28.0 P240, remove the editors note

# Author: DELL

Page: 65 Sequence number: 4 Date: 1/20/2003 4:03:10 PM Type: Note REJECT (SAS PHY WG majority vote to REJECT as the WG looked at this item prior to choosing no key.) Dell #1 Request investigation of keying feature for SAS 4X external connection to allow future compatibility with SATA 4X JBODs. The current cable selection (non-keyed) is not compatible with any keyed cable. Proposal could anticipate a keyed SAS connector for controllers and JBODs, and a keyed SAS/SATA connector for controllers only. Page: 65 Sequence number: 5 Date: 1/22/2003 10:04:52 AM Type: Note REJECT (per phy WG) Dell #2 Request investigation of the HDD connector keying feature to prevent SAS drives from plugging into SATA backplanes. Most drive slots use bays and carriers with integrated levers for increased seating force. The drive carrier lever engages with the front panel just prior to the connection engagement, which means activating the lever to seat the drive will cause damage to the drive and midplane connectors due to the increased (10x) forces involved.

# Author: DSS

Page: 21 Sequence number: 12 Date: 1/23/2003 3:13:53 PM Type: Note ACCEPT - DONE (reworded; see new text) 1. (T) Section 4.1.3, second paragraph (unordered list). It is unclear in the standard, but I don't think Phys don't have SAS addresses. This wording needs improvement to indicate exactly what the SAS Address in question is assigned to. Page: 32 Sequence number: 6 Date: 2/9/2003 4:20:47 PM Type: Note ACCEPT - DONE (No. Chapter 10 says "The target device shall use different identifiers for each logical unit name, each target port identifier, and the target device name." To help clarify that in this section, added "The selected SAS address shall be used for no other name or identifier." to the device name and port identifier sections.) 2. (T) Section 4.2.1, first paragraph. In FCP-2, the device (node) is allowed to share the same name as LUN 0. Is that true for SAS also? Page: 34 Sequence number: 5 Date: 1/23/2003 6:15:46 PM Type: Note ACCEPT - DONE (remove the bit mention) 3. (T) Section 4.2.6, first paragraph. Should be "6-bit". Page: 35 Sequence number: 3 Date: 1/7/2003 6:18:00 PM Type: Note REJECT - state machines are a key documentation technique to try to reduce interpretation differences about what is legal. 4. (T) Section 4.3, entire section. These state machines do not belong in this standard as normalized text. The standard should be specifying observable behavior, not implementation such as this. Page: 41 Sequence number: 1 Date: 1/6/2003 3:46:39 PM Type: Note ACCEPT - DONE 5. (E) Table 12, there are 2 cases of missing ")". Page: 43 Sequence number: 11 Date: 1/6/2003 3:47:04 PM Type: Note ACCEPT - DONE 6. (E) Table 15, there are 2 cases of missing ")". Page: 49 Sequence number: 15 Date: 1/11/2003 5:07:34 PM Type: Note ACCEPT - DONE (changed to "SCSI BUS RESET OCCURRED" since the new names proposed in 02-232 were rejected) 7. (T) Section 4.4.2, last paragraph. The additional sense code "HARD RESET OCCURRED" does not exist. Page: 49 Sequence number: 16 Date: 1/6/2003 3:12:08 PM Type: Note 8. (T) Section 4.6.1, first paragraph unordered list, item c. This sounds like it forbids an expander from supporting only wide ports with multiple phys per port.

Page: 50 Sequence number: 6 Date: 1/7/2003 4:15:12 PM Type: Note 9. (E) Section 4.6.2, third paragraph. Change the second sentence to "If an expander device contains more than one internal SMP port, more than one internal SSP port, or more than one internal STP port, the additional ports shall include SAS addresses different from that of the expander device. Page: 138 Sequence number: 14 Date: 1/6/2003 3:13:32 PM Type: Note ACCEPT - DONE 10. (E) Section 7.1.4.6, second paragraph. Reference is wrong - should be 7.7. Page: 141 Sequence number: 5 Date: 1/6/2003 3:13:56 PM Type: Note ACCEPT - DONE 11. (E) Section 7.1.4.12, second paragraph. Reference is wrong - should be 7.7. Page: 151 Sequence number: 4 Date: 1/8/2003 1:32:39 PM Type: Note ACCEPT - DONE 12. (T) Section 7.7.2, seventh paragraph after table 73. Shouldn't this be "the SAS Address of the port transmitting the IDENTIFY address frame"? Page: 154 Sequence number: 6 Date: 1/24/2003 7:21:34 PM Type: Note ACCEPT - DONE (changed other text indicating the address is for the device. It's for the port.) 13. (T) Section 7.8.1, forth paragraph. In section 7.7.2, the SAS ADDRESS field is defined as belonging to the device, not the port. Here it looks like the port's SAS Address. If it is not the port's SAS address, but is in fact the devices SAS Address, this statement is incorrect and it is not possible to detect that multiple Phys are attached to the same port using the SAS Address. If instead a Phy is supposed to report the SAS Address of the port it is attached to, then expander devices will need to assign a unique SAS Address to each port. Page: 157 Sequence number: 13 Date: 1/6/2003 3:15:56 PM Type: Note 14. (E) Section 7.8.6. Hanging paragraphs, add a level 3 subclause heading. Page: 157 Sequence number: 14 Date: 1/6/2003 3:16:13 PM Type: Note 15. (E) Section 7.8.6, last paragraph. The wording of the second sentence is unclear, and it occurs at least twice in the document. I think it is trying to limit the frame length for the purpose of ignoring primitives to cover the case where the EOAF is missed. Better wording is: "For the purpose of ignoring primitives, IDENTIFY frames consist of a SOAF followed by a maximum of 8 dwords and an EOAF. Page: 157 Sequence number: 15 Date: 1/11/2003 5:02:20 PM Type: Note

REFER PROTOCOL WG (I agree) 16. (T) Section 7.8.6.1.2.1. States can't take action. The state machine can take action while in a state or when entering or leaving a state. Even better, the port can take an action when the state machine is in a state, or when it (the state machine) transitions into or out of a state. This issue is prevalent in these state machine descriptions. Page: 162 Sequence number: 9 Date: 1/6/2003 3:17:05 PM Type: Note 17. (E) Section 7.12.1, second paragraph. What about XFER\_RDY? Page: 162 Sequence number: 10 Date: 1/6/2003 3:17:30 PM Type: Note 18. (E) Section 7.12.2.1, third paragraph. The term "connection response" is used in this paragraph without definition. The term "connection request response" is defined in the next subclause. Are these the same? Page: 162 Sequence number: 11 Date: 1/6/2003 3:17:47 PM Type: Note 19. (E) Section 7.12.2.1, third paragraph. The method of performing timeouts is vendor specific and should not be specified this way. Fix the wording so that timeout periods are used rather than timers. Page: 162 Sequence number: 12 Date: 1/6/2003 3:18:49 PM Type: Note 20. (E) Section 7.12.2.1, forth paragraph. There is a double negative in the second sentence that confuses the meaning. Page: 162 Sequence number: 13 Date: 1/17/2003 1:20:25 PM Type: Note 21. (E) Section 7.12.2.1, forth paragraph, last sentence. Change "Rate matching is used on any ... " to "Rate matching shall be used on any ... " Page: 163 Sequence number: 28 Date: 1/6/2003 3:19:35 PM Type: Note 22. (T) Section 7.12.2.2, last paragraph. The first paragraph in subclause 7.16.1 describes another reason for sending an OPEN\_REJECT. Page: 170 Sequence number: 5 Date: 1/6/2003 3:20:01 PM Type: Note 23. (T) Section 7.13 and 7.14. The state machines described in subclauses 7.13 and 7.14 are implementation details that are vendor specific and should not be included as normative text within a T10 standard. This standard should be limited to specifying observable behavior and refrain from specifying implementation. Page: 191

Sequence number: 9 Date: 1/6/2003 3:20:37 PM Type: Note 24. (T) Section 7.16.5, the paragraph before figure 79. The term "back channel" and "backchannel" is used here without definition. Page: 193 Sequence number: 5 Date: 1/6/2003 3:21:04 PM Type: Note 25. (E) Section 7.16.6, unordered list. "unbalanced", "imbalanced", "nonbalanced" and "not balanced" are all terms that are used throughout the document. Should look for one consistent, defined term. Page: 193 Sequence number: 6 Date: 2/9/2003 3:39:17 PM Type: Note REJECT 26. (T) Subclause 7.16.7 describes an implementation of subclauses 7.16.1 through 7.16.6. This is inappropriate for normative text and should be removed. Page: 207 Sequence number: 6 Date: 1/6/2003 3:22:20 PM Type: Note 27. (T) Section 7.18.1, first paragraph. Several of the management functions may require software or firmware intervention. No provision is included to break the connection and free the resource while this intervention takes place. This could lead to serious performance degradation in SAS networks. Page: 207 Sequence number: 7 Date: 1/6/2003 3:22:38 PM Type: Note 28. (T) Section 7.18.1, last paragraph. What is the action for frames with less than 8 bytes and good CRC? Page: 207 Sequence number: 8 Date: 1/6/2003 3:23:04 PM Type: Note 29. (T) Section 7.18.2, second sentence. What should the source expect to receive if it transmits more than 1 request? Page: 208 Sequence number: 10 Date: 1/11/2003 5:01:05 PM Type: Note REJECT 30. (T) Subclause 7.18.4 describes an implementation of subclauses 7.18.1 through 7.18.3. This is inappropriate for normative text and should be removed. Page: 227 Sequence number: 2 Date: 2/2/2003 11:05:08 AM Type: Note REJECT (it receives them before they are ACKed, thus the "going to". Changed to "to be" per Intel comment.) 31. (E) Section 9.1. Change "...that are going to be ACKed..." to "that are ACKed..." Page: 228 Sequence number: 6

Date: 1/6/2003 3:24:12 PM

Type: Note ACCEPT - DONE 32. (T) Table 88. TIMEOUT bit should be RETRANSMIT bit. Page: 229 Sequence number: 22 Date: 1/6/2003 3:24:35 PM Type: Note ACCEPT - DONE 33. (T) Table 89. Data frames are 1 to 1 024 bytes (can't have zero length data frame). Page: 229 Sequence number: 23 Date: 2/2/2003 11:14:56 AM Type: Note ACCEPT - DONE (changed to "failed in its previous attempt" without mentioning specific reasons) 34. (T) Section 9.1, fourth paragraph after table 89. The frame can be retransmitted after receiving a NAK also. Page: 229 Sequence number: 24 Date: 2/2/2003 11:08:58 AM Type: Note ACCEPT - DONE (added an e.g. to try to clarify) 35. (E) Section 9.1, seventh paragraph after table 89. I don't understand the last sentence in this paragraph. "The tag space used in the tag fields is shared across COMMAND and TASK frames." Page: 230 Sequence number: 12 Date: 1/6/2003 3:25:42 PM Type: Note ACCEPT - DONE 36. (E) Section 9.2.2.1, first paragraph after table 90. The rules for handling commands sent to logical units that do not exist are defined in SAM-2, not SPC-2. Page: 231 Sequence number: 4 Date: 1/13/2003 6:20:43 PM Type: Note REJECT (Jan WG - SAM-3 will mention that CHECK CONDITION/ILLEGAL MESSAGE will be returned for any invalid task attributes. It's not a SAS-specific issue.) 37. (T) Section 9.2.2.1. What is the correct response to a COMMAND frame with a TASK ATTRIBUTE field value that is not supported by the logical unit? Page: 231 Sequence number: 5 Date: 2/2/2003 11:30:42 AM Type: Note **REVIEW PROTOCOL WG** REJECT (this is how SPI-5, FCP-2, and SRP handle such bytes.) 38. (T) Section 9.2.2.1, second paragraph after table 91. Defining fields to be reserved generally means they must be tested for zero. Change the second sentence from "Any bytes between the end of the CDB and the end of the two fields are reserved" to "Any bytes between the end of the CDB and the end of these two field shall be ignored". Change the last sentence to "...the remaining ten bytes shall be ignored and the ... " Page: 232 Sequence number: 6 Date: 2/2/2003 12:03:33 PM Type: Note REFER PROTOCOL WG (SAM-3 should describe this case. Posted to T10 reflector.) 39. (T) Section 9.2.2.2, paragraph preceding table 93. I could find no rules for handling task management functions addressed to logical units that do not exist in either SPC-2 or SAM-2.

Sequence number: 7 Date: 2/2/2003 3:00:06 PM Type: Note ACCEPT - DONE (added footnote that TARGET RESET is not supported on this row. FCP uses 20h for that function.) 40. (E) Table 93. Why is 20h spelled out here with the "all others" below indicating "reserved"? Page: 232 Sequence number: 8 Date: 2/2/2003 11:37:56 AM Type: Note ACCEPT - DONE (added "unsupported") 41. (T) Section 9.2.2.2, first paragraph after table 93. What if a valid TMF is not supported? Page: 232 Sequence number: 9 Date: 2/2/2003 11:36:55 AM Type: Note **REVIEW PROTOCOL WG** ACCEPT - DONE (no need to define all the tmf behaviors - SAM-3 does that. This paragraph and the QUERY TASK paragraph should be deleted.) 42. (T) Section 9.2.2.2, third paragraph after table 93. What is returned if the task with TAG OF TASK TO BE MANAGED is in the task set? Page: 233 Sequence number: 17 Date: 1/22/2003 6:22:09 PM Type: Note REJECT (but renamed Relative Offset here to Requested Offset and the header one to Data Offset) 43. (T) Section 9.2.2.3, first paragraph after table 94. This is confusing to have RELATIVE OFFSET field in the payload of the frame and a field with exactly the same name in the header of the frame. Recommend that this field be removed and the RELATIVE OFFSET field in the frame header be used for this purpose. Page: 233 Sequence number: 18 Date: 1/22/2003 6:23:01 PM Type: Note ACCEPT - DONE 45. (T) Section 9.2.2.3, second paragraph after table 94. The last sentence in this paragraph should be "...the target port shall set the WRITE DATA LENGTH field to less than or equal to the value in the MAXIMUM BURST SIZE field times 512 (see 10.1.6.14)." Page: 233 Sequence number: 19 Date: 1/22/2003 6:24:42 PM Type: Note REVIEW PROTOCOL WG (changed to "to the value indicated by". Don't think we want to specify the 512 here; the mode page owns that) 46. (T) Section 9.2.2.3, forth paragraph after table 94. Change the first sentence in this paragraph to: "...set the relative offset to 512 times the value of the FIRST BURST SIZE field in the Disconnect-Reconnect mode page (see 10.1.1.1.5). Fix the link to the section. Page: 234 Sequence number: 4 Date: 1/6/2003 3:48:20 PM Type: Note ACCEPT - DONE 47. (E) Section 9.2.2.4, first paragraph after note 23. This paragraph is redundant with the first 2 paragraphs on this page. We get it already. Page: 236 Sequence number: 4 Date: 2/2/2003 12:46:12 PM

Type: Note TODO **REVIEW PROTOCOL WG** REJECT (Jan WG - that's for SAM-3 to worry about. Feb: sure we shouldn't specify a RESPONSE\_DATA bad frame response?) 52. (T) Section 9.2.5.1, fifth paragraph. What is to be done with a COMMAND frame with an unsupported TASK ATTRIBUTE value? Page: 237 Sequence number: 8 Date: 2/2/2003 1:08:21 PM Type: Note ACCEPT - DONE (added footnote explaining that code 00h is only used with responding to a TASK frame) 48. (T) Table 99. A command frame that does not have an invalid field value will not return a RESPONSE IU with RESPONSE\_DATA format, but will instead use the SENSE\_DATA format. This means that option 'a' under Code 0 is not required. It would also be helpful to add a paragraph explaining this behavior to the subclause. Page: 237 Sequence number: 9 Date: 2/2/2003 1:06:36 PM Type: Note REFER PROTOCOL WG (currently, the sense data list length is required to be x4, so the padding is inside the sense data field itself. The frame header number of fill bytes is not used (only DATA frames use that). This does differ from other protocols so might be worth changing.) 49. (T) Section 9.2.2.5.4, forth paragraph. Add statement that the NUMBER OF FILL BYTES field in the frame header shall indicate the number of fill bytes added. Page: 239 Sequence number: 8 Date: 1/11/2003 4:55:31 PM Type: Note REFER PROTOCOL WG 50. (T) Section 9.2.4.3, second paragraph. The lack of an ability to recover from these types of errors at the link level will preclude the use of this interface on devices other than disk drives. When this shortcoming is solved in the next generation of SAS, it will create interoperability issues that will hinder the acceptance of this interface. Quantum has produced a proposal (02-487) that will solve this problem that should be included before forwarding SAS. Page: 240 Sequence number: 12 Date: 2/2/2003 2:02:48 PM Type: Note REJECT (same comment made on prev page - only one needed for tracking) REFER PROTOCOL WG 51. (T) Section 9.2.4.4, first paragraph. The lack of an ability to recover from these types of errors at the link level will preclude the use of this interface on devices other than disk drives. When this shortcoming is solved in the next generation of SAS, it will create interoperability issues that will hinder the acceptance of this interface. Quantum has produced a proposal (02-487) that will solve this problem that should be included before forwarding SAS. Page: 241 Sequence number: 4 Date: 2/2/2003 3:09:19 PM Type: Note ACCEPT - DONE (per Jan WG; all changed to just "initiator shall abort" except 10.1.3, which gives an "e.g. sending ABORT TASK")) 53. (E) Section 9.2.5.2, third paragraph. An initiator always has the option of sending a TASK frame with an ABORT TASK or ABORT TASK SET task management function. Perhaps it would be better to remove the recurring statements and add a paragraph that states that an initiator may use this means to abort the task when an error is detected with it. Page: 242 Sequence number: 20 Date: 1/11/2003 4:52:24 PM Type: Note REJECT

54. (T) Subclause 9.2.6 describes an implementation of subclauses 9.2.1

through 9.2.5. This is inappropriate for normative text and should be removed. Page: 260 Sequence number: 9 Date: 1/11/2003 4:52:11 PM Type: Note ACCEPT - DONE (reference to 10.3.1 added) 55. (T) Section 9.4.2, second paragraph after table 102. Where is FUNCTION described? Page: 260 Sequence number: 10 Date: 1/11/2003 4:50:42 PM Type: Note ACCEPT - DONE (1023 fixed to 1024) 56. (T) Section 9.4.2, third paragraph after table 102. Should be 1 024 bytes based on description of max size frame? Page: 261 Sequence number: 10 Date: 1/30/2003 4:42:07 PM Type: Note ACCEPT - DONE (changed 1023 to 1024) 57. (T) Section 9.4.3, first paragraph after table 104. Should be 1 024 bytes based on description of max size frame? Page: 262 Sequence number: 5 Date: 1/11/2003 4:48:15 PM Type: Note REJECT 58. (T) Subclause 9.4.4 describes an implementation of subclauses 9.4.1 through 9.4.3. This is inappropriate for normative text and should be removed. Page: 269 Sequence number: 4 Date: 1/11/2003 4:48:04 PM Type: Note **REVIEW PROTOCOL WG** ACCEPT - DONE (reworded with DATAPRES) 59. (T) Table 108. There is no RSPVALID field in the RESPONSE frame. Page: 270 Sequence number: 4 Date: 1/11/2003 4:47:59 PM Type: Note **REVIEW PROTOCOL WG** ACCEPT - DONE (reworded with DATAPRES) 60. (T) Table 109. There is no RSPVALID field in the RESPONSE frame. Page: 274 Sequence number: 4 Date: 1/11/2003 4:47:54 PM Type: Note **REVIEW PROTOCOL WG** ACCEPT - DONE (reworded with DATAPRES) 61. (T) Table 116. There are no RSPVALID or SNSVALID fields in the RESPONSE frame. Page: 275 Sequence number: 3 Date: 1/30/2003 2:33:33 PM Type: Note ACCEPT - DONE (reworded with DATAPRES) 62. (T) Table 117. There are no RSPVALID or SNSVALID fields in the RESPONSE frame.

Page: 276 Sequence number: 4 Date: 1/30/2003 2:31:26 PM Type: Note REJECT (but downgraded the list to a set of examples, since there are other ways to determine the tag is free for reuse. The layer crossing is conceptually solved by passing the DONEs, etc. upstream - I'd rather just refer to them directly in the examples). 63. (T) Section 10.1.3, last paragraph and unordered list. This paragraph is placing a requirement on an application client that involves knowledge of activities not seen at that level. Page: 277 Sequence number: 4 Date: 1/11/2003 4:37:24 PM Type: Note REJECT (the OPEN used to open the connection communicated the full SAS address of the opener and destination. That is used for persistent reservations as the "initiator port address".) 64. (T) Section 10.1.5. Without a port login, the only method available to associate persistent reservation to an initiator port is to use the hashed source address. A statement to clarify this should be added in this subclause. What action should be taken in cases where a conflict exists? Page: 277 Sequence number: 5 Date: 1/13/2003 8:48:23 PM Type: Note REJECT (can use OPEN\_REJECT (RETRY) to prevent additional initiator-based opens) 65. (T) Section 10.1.5. Similar to SPI, there is no port login function that can be used by a device to manage each I T nexus. Unlike SPI, SAS networks can be configured with hundreds of initiators. How does a device report an error caused by receipt of a command from an initiator when no more resources are available to manage a new I T nexus? Page: 277 Sequence number: 6 Date: 1/14/2003 11:06:14 AM Type: Note REJECT 66. (T) Section 10.1.6.1.1. Unfortunately, there is precedence for this. However, mode pages are a bad way to configure the transport layer. It requires too much information be shared between layers and between logical units, which should not be sharing information. A much better method of configuring the transport layer was introduced when port logins were added, and that is exactly where the parameters included in this page belong. Unfortunately again, this transport layer does not include the concept of a port login, a shortcoming that will undoubtedly be corrected in future versions causing great interoperability issues for years to come. Page: 279 Sequence number: 6 Date: 1/30/2003 1:56:05 PM Type: Note ACCEPT - DONE (requires moving the 512-byte definition up above this sentence) 67. (E) Section 10.1.6.1.5, first paragraph. The wording of the last sentence is confusing. Try replacing "... where the transfer length is specified in the WRITE DATA LENGTH field" with "where the WRITE DATA LENGTH field is equal to 512 times the FIRST BURST SIZE." Page: 279 Sequence number: 7 Date: 1/30/2003 1:49:52 PM Type: Highlight ACCEPT - DONE ("the same connection in which the command is transferred" 68. (T) Section 10.1.6.1.5, fourth paragraph. The last sentence in this paragraph should be removed or the term "this connection" should be clarified. Page: 281 Sequence number: 8

Date: 1/11/2003 4:29:17 PM

Type: Note ACCEPT - DONE (corrected page layout) 69. (T) Table 122. What happened to byte 2 and 3? Page: 281 Sequence number: 9 Date: 2/8/2003 12:18:37 PM Type: Note ACCEPT - DONE (but it's plus 4 not plus 2, once the byte numbers for this page are corrected). [comment moved to 10.1.6.2.3 from 6.2.2] 70. (T) Section 10.1.6.2.3. A description for the PAGE LENGTH field should be added that states the PAGE LENGTH shall be equal to the (NUMBER OF PHYS value times the SAS phy mode descriptor length) plus 2 and is not adjusted for truncation. Page: 296 Sequence number: 9 Date: 1/6/2003 3:39:26 PM Type: Note ACCEPT - DONE 71. (E) Section 10.3.1.2, paragraph immediately preceding table 131. This paragraph should not be numbered. Page: 302 Sequence number: 12 Date: 1/29/2003 3:48:16 PM Type: Note ACCEPT - DONE (clarified that it might be the SAS address of a SAS port, expander device, or address provided for a SATA device port. Also added expander device to SAS device in next a)b) list.) 72. (T) Section 10.3.1.4, the paragraphs below table 139 that describe the SAS ADDRESS field. According to the definition of SAS Address in 3.1.99, Phys don't have SAS Addresses. These must be either the SAS address of the Port or the device. Page: 308 Sequence number: 3 Date: 1/6/2003 3:41:12 PM Type: Note ACCEPT - DONE 73. (E) Section 10.3.1.7, third paragraph below table 147. Reference numbers need to be fixed. Page: 312 Sequence number: 6 Date: 1/6/2003 3:41:03 PM Type: Note ACCEPT - DONE 74. (E) Section 10.3.1.8, third paragraph after table 150. Reference numbers need to be fixed. Page: 330 Sequence number: 4 Date: 1/17/2003 11:33:47 AM Type: Note REJECT (but added "to help" in 4.2.3) 75. (T) Annex D. This annex indicates that hashed address collisions should be very infrequent, but they will still happen. What action is taken when a collision is detected?

### Author: ENDL

Page: v Sequence number: 1 Date: 2/6/2003 11:42:03 AM Type: Note ACCEPT - DONE (track with another comment) Remove revision history before delivering the dpANS to Public Review. Page: 6 Sequence number: 1 Date: 2/7/2003 6:34:18 PM Type: Highlight TODO (Cris Simpson will think up some wording) 3.1.17 confirmation Is a confirmation really just a single parameter passed from a lower layer to a higher layer? Or, is a confirmation a passing of parameters and other state information from a lower layer to a higher layer? Page: 6 Sequence number: 2 Date: 1/22/2003 3:36:13 PM Type: Highlight ACCEPT - DONE (deleted "device". It was intended to indicate that there is no special SAS meaning for the term on its own.) 3.1.25 device The definition of device should include some relationship to SAS. As currently defined, a "device" may be a pencil, a house, a spaceship, or the moon. Page: 6 Sequence number: 3 Date: 1/22/2003 10:34:16 AM Type: Highlight REJECT (per Jan Editor's meeting: acronym suffices) 3.1.27 direct current Provide a definition for A.C. Page: 6 Sequence number: 4 Date: 1/7/2003 2:21:38 PM Type: Highlight **REFER PHYSICAL WG** 3.1.27 direct current Provide a definition for "signal". Relying on the standard English definition for "signal" allows a Stop sign to be a "signal". Page: 7 Sequence number: 1 Date: 1/22/2003 10:36:05 AM Type: Highlight **REFER PROTOCOL and PHYSICAL WG** 3.1.39 expander connection router Global The reason why "signal" is not a defined term is becoming clear, i.e. "signal" has no consistent usage in SAS. The term "signal" as used in the ER definition almost certainly means something very different than the term "signal" as used in the D.C. definition. Otherwise, a SAS expander operates by switching raw waveforms from one phy to another, which seems unlikely to be the case. The inconsistent usage of 'signal' is far and away the most egregious problem ENDL discovered in its limited Letter Ballot review. Page: 7 Sequence number: 2 Date: 1/25/2003 11:19:31 AM Type: Highlight ACCEPT - DONE (deleted sentence) 3.1.43 expander port Please provide a subject for this 'sentence': "Contains one or more phys." Page: 7 Sequence number: 3 Date: 1/7/2003 2:27:42 PM Type: Highlight ACCEPT - DONE ("set of values") 3.1.55 hash function Since "domain" is equivalent to "SAS domain" (see 3.1.31), a hash function can be applied only to a SAS domain, whatever that means. Perhaps "domain" can be replaced with "value range" twice in the 3.1.55 definition.

Page: 8 Sequence number: 1 Date: 2/7/2003 6:33:57 PM Type: Highlight TODO (Cris Simpson will think up some wording) 3.1.62 indication Is an indication really just a single parameter passed from a lower layer to a higher layer? Or, is an indication a passing of parameters and other state information from a lower layer to a higher layer? Page: 8 Sequence number: 2 Date: 1/7/2003 2:29:36 PM Type: Highlight ACCEPT - DONE 3.1.63 information unit "Portion" s/b "The portion" Page: 8 Sequence number: 3 Date: 2/7/2003 6:33:03 PM Type: Highlight REJECT (but deleted link altogether) 3.1.70 link "A physical link." s/b "Synonymous with physical link (see 3.1.86)." Page: 9 Sequence number: 1 Date: 2/7/2003 6:46:42 PM Type: Highlight REJECT (but deleted the "part of" sentence) 3.1.80 OOB sequence "OOB signals. Part of" s/b "OOB signals, part of" Page: 9 Sequence number: 2 Date: 2/7/2003 6:36:57 PM Type: Highlight TODO (Cris Simpson working on wording) 3.1.96 request Is a request really just a single parameter passed from a higher layer to a lower layer? Or, is a request a passing of parameters and other state information from a higher layer to a lower layer? Page: 9 Sequence number: 3 Date: 2/7/2003 6:36:48 PM Type: Highlight TODO (Cris Simpson working on wording) 3.1.97 response Is a response really just a single parameter passed from a higher layer to a lower layer? Or, is a response a passing of parameters and other state information from a higher layer to a lower layer? Page: 10 Sequence number: 1 Date: 1/30/2003 6:04:16 PM Type: Line REJECT (but deleted "SAS primitive" since that term is never used. SATA primitive is only used twice. Once replaced by "Primitives defined by SATA". The other is in a title of scrambling types.) 3.1.xx Since SAS primitive has a definition, should SATA primitive have a definition? Page: 10 Sequence number: 2 Date: 2/7/2003 6:51:10 PM Type: Highlight REFER EDITORS WG (is it the device (singular) that "originates" or the app clients and initiator ports (plural) that "originate" 3.1.115 SCSI initiator device "originate device service" s/b "originates device service" Page: 11 Sequence number: 1

Date: 1/30/2003 6:07:20 PM

Type: Highlight

ACCEPT - DONE (added "to an expander device". Also added to subtractive routing method definition.)

3.1.137 table routing method

It is not clear from the definitions whether a table routing method could result in a routing to an end device. If that is possible, both table routing and direct routing may do the same thing. If that is not possible, then "route connection requests" should be "route connection requests to devices other than end devices".

Page: 15 Sequence number: 1 Date: 1/7/2003 3:06:59 PM Type: Highlight ACCEPT - DONE 3.4 Editorial conventions "Fields containing only one bit are usually referred to as the name bit instead of the name field." is a repeat of the second sentence in the third paragraph in this subclause. Remove this paragraph because the earlier sentence uses small caps more correctly. Page: 19 Sequence number: 1 Date: 1/7/2003 5:28:27 PM Type: Highlight REJECT (this is not a subset of SAS ports) 4.1.1 Architecture overview 'which' s/b 'that' [twice] Page: 22 Sequence number: 1 Date: 1/7/2003 5:34:29 PM Type: Circle ACCEPT - DONE 4.1.3 Ports Figure 6 Ports Based on the title of the subclause, the title of the figure, and the text preceding the figure, the ports attached to the narrow link should belabeled 'Narrow Port', 'Port'. Page: 23 Sequence number: 1 Date: 1/7/2003 5:37:17 PM Type: Circle ACCEPT - DONE 4.1.4 SAS devices figure 7 If figure 6 is changed to use 'Narrow Port' perhaps figure 7 should be changed too. Page: 23 Sequence number: 2 Date: 1/22/2003 3:31:03 PM Type: Highlight ACCEPT - DONE (added "in this standard") 4.1.4 SAS devices last 2 in subclause The phrase 'In figures that show ports but no phys ...' makes not sense in the context of this subclause. Perhaps 'In figures in this standard that show ports but no phys ...'. Page: 26 Sequence number: 1 Date: 2/8/2003 11:35:48 AM Type: Circle ACCEPT - DONE (kept the internal port given the new virtual phy approach for internal SAS devices. It's important to clarify that those internal expander ports have direct routing attributes. Changed "target port" to "SAS port" so it represents both initiators and targets and added a SAS device around it.. Labeled the expander port as "internal". Made each use the "more than one is possible" style.) 4.1.8.2 Edge expander device set, figure 11 I think this figure would more clearly represent the routing possibilities in an edge expander device set if the optional target port joined the optional initiator port in being absent from the figure. If necessary, add a sentence before or after the figure indicating that optional initiator and target ports have been omitted for clarity.

Page: 26 Sequence number: 2 Date: 1/23/2003 4:07:38 PM

#### Type: Note

ACCEPT - TODO (moved the edge expander and configurable expander device sections after the Domain. 4.1.1 introduces a hierarchy of objects; 4.1.2 details the lowest level (phy) and leads up to this section on domains. Subsequent sections on expander topologies, connections, and pathways may follow in 4.1.xx or move up to 4.x level.

Counterargument: expander topologies are really defining the service delivery subsystem object, so should remain before domains.)

4.1.9 Domains

The presence of a subclause describing domains separating two subclauses discussing expanders and expander topologies is more than a little confusing. My gut level preference would be to put the domains subclause between 4.1.1 and 4.1.2. However, it appears that the general order of topic introduction in 4.1 is from the bottom of the architectural pyrimid up, leading to the conclusion that the discussion of domains should appear last among the subclauses in 4.1.

Page: 28

Sequence number: 1 Date: 1/23/2003 4:45:51 PM

Type: Strikeout

ACCEPT - DONE (replaced with an intro saying something like "a service delivery subsystem may contain expanders") 4.1.10 Expander device topologies

Delete the first sentence of this subclause. It grows tiresome with repetition. Surely, the reader has grapsed the concept by this point in 4.1.

Page: 28

Sequence number: 2

Date: 1/22/2003 3:35:11 PM

Type: Highlight

4.1.10 Expander device topologies

Regarding, 'The number of edge expander devices and the phy route attributes of edge expander devices within an edge expander device set shall be established when the edge expander device set is configured.' Since it is said else where that application clients do something to edge expander device sets in the configuration process, does the cited sentence mean that application clients can control the number of exander devices in an edge expander device set?

Page: 30

Sequence number: 2 Date: 1/23/2003 5:07:42 PM Type: Highlight ACCEPT - DONE (overcome by rewrite) 4.1.11 Connections items a) and c) in the first unordered list identify the protocol in use, while item b) omits this information. Include or do not include the protocol information equally in all list entries. Page: 30 Sequence number: 3 Date: 1/23/2003 5:02:39 PM Type: Highlight ACCEPT - DONE (Reworded) 4.1.11 Connections Regarding, '...the number of connections shall not exceed the number of phys within the wide port (i.e., only one connection per phy is allowed) ... '. It would seem that this requirement applies equally well to both wide and narrow ports. Furthermore, I cannot find a statement that specifically limits a narrow port to one connection per phy (i.e., one connection). It might be useful to 1) remove the word 'however', and 2) change 'wide port' to 'port' or if that is deemed too vague change 'wide port' to 'port, either wide or narrow,'. Page: 30 Sequence number: 4 Date: 1/23/2003 5:03:29 PM Type: Highlight ACCEPT - DONE 4.1.11 Connections Move the qualifying phrase 'if multiple pathways exist between the initiator port(s) and the target port(s)' to the beginning of the sentence so that the word following directly introduces the list. Page: 31 Sequence number: 1 Date: 1/22/2003 3:34:18 PM Type: Circle 4.1.11 Connections

Do not anchor figure 17 to list entry d) so that list entry d) is not orphaned from the rest of the list by a quarter page of white space.

Page: 31
Sequence number: 2
Date: 1/22/2003 3:34:24 PM
Type: Circle

4.1.11 Connections
It is most curious how connection E has succeeded in avoiding the requirement to pass through any phy on one of the expanders and in the target port.

Page: 32
Sequence number: 1
Date: 1/22/2003 3:34:41 PM
Type: Circle

4.1.11 Connections

Since figure 18 appears to make no attempt to unambiguously relate pathways to physical links (e.g., one of the magenta pathways passes through four phys in the expander device) perhaps it would be best to remove the physical links and expander device phys from the figure.

#### Author: FUJ

Page: ix Sequence number: 4 Date: 1/7/2003 11:13:52 AM Type: Note ACCEPT - DONE FUJITSU-1 PDF page : ix Section : 1.19 Revision sas-r02c Figure/Table Paragraph/sentense/row/colum Comment: 1.19 Revision sas-03 Page: 6 Sequence number: 16 Date: 1/22/2003 10:05:45 AM Type: Highlight ACCEPT - DONE (delete the 2nd sentence) FUJITSU-2 PDF page: 6 Section: 3.1.18 connection Figure/Table Paragraph/sentense/row/colum Comment : It defines only SSP(SCSI) case. SMP/STP case should be added since "3.1.78 nexus:" explains only SCSI and "see SAM-3" Page: 109 Sequence number: 16 Date: 1/9/2003 4:48:12 PM Type: Note ACCEPT - DONE (removed "Phy layer" and changed "phy" to "phy layer") FUJITSU-3 PDF page : 109 Section : 6.8.2 OOB sequence status Figure/Table : Figure 56 Paragraph/sentense/row/colum : line 3 Comment : "Phy layer SAS phy (SP) state machine" / "SAS phy (SP) state machine" unification of the term as "SAS phy layer (SP) state machine" Page: 139 Sequence number: 4 Date: 1/22/2003 10:06:45 AM Type: Highlight ACCEPT - DONE (change "response" to "the result of") FUJITSU-4 PDF page : 139 Section: 7.1.4.11 OPEN\_REJECT

Figure/Table : Paragraph/sentense/row/colum line 2 Comment : "The response to some OPEN\_REJECTs is to abandon the connection request and the response to other OPEN\_REJECTs is to retry the connection request." This "response" makes confusion as RESPONSE to the originator of OPEN\_REJECT. An "action" seems better to understanding. Page: 139 Sequence number: 5 Date: 1/17/2003 6:23:27 PM Type: Highlight ACCEPT - TODO (change "Any device" to "any phy" (check other tables nearby). This does not only apply to expanders. The last sentence in the description describes the direct-connect situation which does not include an expander.) FUJITSU-5 PDF page : 139 Section: 7.1.4.11 OPEN\_REJECT Figure/Table :Table 61 Paragraph/sentense/row/colum: 2nd row Comment : OPEN\_REJECT (CONNECTION RATE NOT SUPPORTED) by "Any device". No Expander case, this is a mistake of OOB speed matching sequence. But how to communicate using different speed? So, this is the case of only Expander. Page: 139 Sequence number: 6 Date: 1/17/2003 6:10:30 PM Type: Note **REJECT** (no change requested) FUJITSU-6 PDF page : 139 Section: 7.1.4.11 OPEN\_REJECT Figure/Table : Table 61 Paragraph/sentense/row/colum : 1st, last row Comment : In case of BAD/WRONG destination, Initiator can report to Upper Application, but device can do nothing except to terminate the command. This kind of logical error should be reported on appropriate method. Page: 163 Sequence number: 26 Date: 1/17/2003 6:15:57 PM Type: Highlight ACCEPT - TODO (point to where arbitration fairness selects the winner when OPENs cross) FUJITSU-7 PDF page : 163 Section: 7.12.2.2 Connection request responses Figure/Table : Table 78 Paragraph/sentense/row/colum : 4th row Comment : "OPEN address frame" "indicates two connection requests crossing on the physical link." In no expander case, the action should be defined to avoid racing condition or ping-pong condition. For instance, Initiator implicitly abandon the connection request, and Target proceeds operation. Page: 163 Sequence number: 27 Date: 1/17/2003 6:15:48 PM Type: Note REJECT (the device sending OPEN is not the only one that could send a BREAK. The other side could send it first.) FUJITSU-8 PDF page : 163 Section: 7.12.2.2 Connection request response Figure/Table : Table 78 Paragraph/sentense/row/colum : row 5 BREAK Comment : According to 7.12.5 and 7.12.6, BREAK is used by originator at first. If BREAK is responded for Connection (OPEN address

frame), this is a protocol error. So, "The destination port or expander port may reply with BREAK indicating the connection is not being established." is not correct. BREAK is the response of the BREAK of open requester not correct response of Connection request (OPEN address frame). Page: 167 Sequence number: 11 Date: 1/17/2003 6:22:57 PM Type: Highlight ACCEPT - TODO (see MXO comment; switching to ignore) FUJITSU-9 PDF page : 167 Section: 7.12.5 Abandoning a connection request Figure/Table : Table 81 Paragraph/sentense/row/colum : row 3 No response and timer expires Comment : In case of response time out of BREAK, there should be clear action definition. Since BREAK is used for AIP timeout, the response timeout of BREAK is double timeout condition. Link Initialization or something to recover or terminate queue action should be taken. (Then, the other path action should be taken on multiple port devices in future.)

#### Author: HP relliott

Page: ix Sequence number: 1 Date: 12/30/2002 10:43:31 AM Type: Highlight ACCEPT - DONE 1.19 Revision sas-r02d This should be sas-r03 not sas-r02d. Page: 30 Sequence number: 1 Date: 12/30/2002 10:06:58 AM Type: Note 4.1.11 Connections This general intro needs to make it clear that frames related to one command (ATA or SCSI) may be transferred in different connections. A connection need not stay open for the duration of the command. Page: 59 Sequence number: 1 Date: 12/30/2002 11:14:56 AM Type: Highlight ACCEPT - DONE 4.6.11.3 Expander route table Change "expander" to "expander device" before (i.e., self-reference) Page: 61 Sequence number: 1 Date: 1/24/2003 10:58:30 AM Type: Highlight ACCEPT - DONE 4.6.11.4 Expander route index order Table 26 - Expander route table levels Change "SAS address of the device" to "SAS address of the port" for each entry Page: 114 Sequence number: 1 Date: 12/30/2002 10:06:58 AM Type: Highlight 6.8.3 SP state machine Implement Editor's Note 1 about the interaction between SP and SP DWS.

Page: 137 Sequence number: 1 Date: 1/13/2003 4:51:17 PM Type: Note **REJECT (Jan WG)** 7.1.4.4 BROADCAST Make one of the BROADCAST primitives BROADCAST (VENDOR SPECIFIC). Page: 137 Sequence number: 2 Date: 1/22/2003 10:17:23 AM Type: Note ACCEPT - DONE (per Jan WG go ahead and use 8 broadcast codes. Keep existing encodings; pull next four from annex H for the new ones.) 7.1.4.4 BROADCAST Increase the total number of broadcast primitives to 8. There are 4 more D04.7 codes available. broadcast (change) broadcast (rsvd change 0) (end devices treat as change) broadcast (rsvd change 1) broadcast (rsvd 0) broadcast (rsvd 1) broadcast (rsvd 2) broadcast (rsvd 3) broadcast (rsvd 4) Page: 142 Sequence number: 1 Date: 12/30/2002 11:24:04 AM Type: Strikeout ACCEPT - DONE 7.1.5.6 RRDY (Receiver ready) Remove: "RRDY (RESERVED 2) Reserved. Processed the same as RRDY (NORMAL)." There is no primitive code assigned for this. Page: 143 Sequence number: 1 Date: 1/6/2003 1:45:56 PM Type: Note ACCEPT - DONE 7.2 Clock skew management Remove blank line after second paragraph Page: 151 Sequence number: 1 Date: 2/9/2003 4:29:43 PM Type: Highlight ACCEPT - DONE (clarified that for SAS ports, it's a port identifier. For expander devices, it's a device name.) 7.7.2 IDENTIFY address frame "The SAS ADDRESS field indicates the SAS address of the device transmitting the IDENTIFY address frame." It's really the SAS address of the port, not the device. Page: 160 Sequence number: 1 Date: 12/30/2002 10:06:58 AM Type: Highlight 7.9 Power management Change "If the primitives arrives" to "If the primitive arrives" Page: 162 Sequence number: 1 Date: 12/30/2002 10:06:58 AM Type: Highlight 7.12.2.1 Connection request "If none of the prospective intermediate physical links does not support the requested connection rate," should be "If one of the ..."

Page: 163 Sequence number: 1 Date: 12/30/2002 10:06:58 AM Type: Highlight 7.12.2.2 Connection request responses BREAK is effectively referenced twice by table 81 since it shows up here, and this table shows up in table 81 Need to differentiate between originated and received BREAKs (the latter need responses) too Page: 165 Sequence number: 1 Date: 12/30/2002 10:06:58 AM Type: Note 7.12.3.1.4 Pathway Recovery This comparison should also include the connection rate as the lowest priority bits, so two requests from a wide port (which have the same source address) resolve consistently This parallels the normal arbitration fields specified in 7.12.3.1.1 (which uses AWT, source address, connection rate) Page: 207 Sequence number: 1 Date: 12/30/2002 10:06:58 AM Type: Highlight 7.17.3 Preparing to close an STP connection Add "or" before the last option in the list: "detected, [or] after" Page: 216 Sequence number: 1 Date: 12/30/2002 1:53:27 PM Type: Highlight ACCEPT - DONE 8.3.2 Port layer remove duplicate header numbers Page: 224 Sequence number: 1 Date: 12/30/2002 10:06:58 AM Type: Highlight 8.4.3.1.2 PL\_PM I\_T nexus loss timer Second list: a) Open Failed (Connection Rate Not Supported) is unnecessary since targets are required to try 1.5 Gbps and that will never get this error (at least for target side) Page: 228 Sequence number: 1 Date: 12/30/2002 1:54:27 PM Type: Highlight ACCEPT - DONE 9.2.1 SSP frame format Table 88 - SSP frame format Change TIMEOUT bit to RETRANSMIT Page: 240 Sequence number: 1 Date: 2/2/2003 2:36:19 PM Type: Highlight ACCEPT - DONE (for too short for LUN field, too short for CDB, and additional cdb mismatch, generate a RESPONSE IU with a RESPONSE CODE indicating INVALID FRAME. In ch10 protocol services, this means a service delivery subsystem failure.) 9.2.5.1 Target port error handling and 9.2.6.3.9 in the state machine "the target port shall return a CHECK CONDITION status with a sense key of ILLEGAL REQUEST and an additional sense code of INFORMATION UNIT TOO SHORT (see 9.2.6.3.9)." Instead, return a RESPONSE frame with a RESPONSE CODE indicating this problem. Don't involve the application layer. Page: 240

Sequence number: 2 Date: 2/2/2003 2:36:51 PM Type: Highlight ACCEPT - DONE (for too short for LUN field, too short for CDB, and additional cdb mismatch, generate a RESPONSE IU with a RESPONSE CODE indicating INVALID FRAME. In ch10 protocol services, this means a service delivery subsystem failure.) 9.2.5.1 Target port error handling "the target port shall return a CHECK CONDITION status with a sense key of ILLEGAL REQUEST and an additional sense code of INFORMATION UNIT TOO LONG (see 9.2.6.3.9)." Instead, return a RESPONSE frame with a RESPONSE CODE and don't bother the application layer. Page: 258 Sequence number: 1 Date: 2/2/2003 4:44:18 PM Type: Highlight ACCEPT - DONE 9.2.6.3.9.1 State description (for ST\_TTS7) Editor's Note 3 - add service response argument to SCSI Command Received () and Task Management Function Request () This note should be rejected. Errors in command frame reception should generate RESPONSE frames with RESPONSE CODE errors, not CHECK CONDITIONs. Page: 258 Sequence number: 2 Date: 2/2/2003 4:44:38 PM Type: Highlight TODO (probably not) 9.2.6.3.9.1 State description (ST\_TTS7) Editor's Note 4 - add local Service Response to Send Command Complete () and Task Management Function Executed () Implement only if a SAM-3 proposal is accepted in the letter ballot resolution timeframe. Page: 259 Sequence number: 1 Date: 1/6/2003 1:06:38 PM Type: Highlight ACCEPT - DONE 9.3.1 Initial FIS Change "the SMP REPORT SATA PORT function" to "the SMP REPORT PHY SATA function" Page: 259 Sequence number: 2 Date: 12/30/2002 1:54:12 PM Type: Highlight ACCEPT - DONE 9.3.2 SATA tunneling for multiple STP initiator ports Change "CLOSE CLEAR AFFILIATION" to "CLOSE (CLEAR AFFILIATION)" Page: 292 Sequence number: 1 Date: 2/3/2003 3:02:20 PM Type: Highlight TODO (depends on CAP WG handling of 02-419) 10.1.9 SCSI vital product data Table 128 - Device Identification VPD page required identification descriptors The target device name should follow the common string format being proposed in 02-419 (if that is accepted by CAP). Only SAS-only devices should be required to use the "naa." format name for a target device name. Similarly, only SAS-only devices should be required to use the NAA binary formats for logical unit names. Page: 294 Sequence number: 1 Date: 1/30/2003 12:32:27 PM Type: Note ACCEPT - DONE (1/21 call voted to accept 03-034r4 which doesn't contain a GENERAL CONTROL function any longer. Instead, a virtual internal phy concept is used.) 10.3.1 SMP functions Add a GENERAL CONTROL function 80h. See 03-034. It has bits to reset internal targets of each protocol clear affiliation of an internal STP target Page: 296 Sequence number: 1 Date: 12/30/2002 3:25:49 PM Type: Highlight

ACCEPT - DONE 10.3.1.2 REPORT GENERAL function EXPANDER ROUTE INDEXES paragraph ...route indexes PER PHY also note that some phys may not reach this limit Page: 296 Sequence number: 2 Date: 12/30/2002 3:24:21 PM Type: Highlight ACCEPT - DONE 10.3.1.2 REPORT GENERAL function Table 131 - REPORT GENERAL response The row labeled byte 28 should be labeled byte 11. Page: 296 Sequence number: 3 Date: 12/30/2002 3:24:14 PM Type: Highlight ACCEPT - DONE 10.3.1.2 REPORT GENERAL function Table 131 - REPORT GENERAL response The first row labeled byte 31 should be labeled byte 27. Page: 302 Sequence number: 1 Date: 1/29/2003 3:53:10 PM Type: Highlight ACCEPT - DONE (Reworded) 10.3.1.4 DISCOVER function "The ATTACHED SAS ADDRESS field contains the SAS address of the attached phy." It's really the SAS address of the attached port or erxpander device, as reported by the attached phy. Page: 302 Sequence number: 2 Date: 1/29/2003 3:50:47 PM Type: Highlight ACCEPT - DONE (mention "transmitted during initialization sequence". Also mention SAS port and expander device as the owner of the SAS address.) "The SAS ADDRESS field contains the SAS address of this phy." It's really the address reported by this phy, not the address of this phy. Page: 382 Sequence number: 1 Date: 2/3/2003 2:56:17 PM Type: Highlight ACCEPT - TODO (waiting on copyright release from SCSI Trade Association) Annex J SAS logo Figure J.1 — SAS logo The SCSI Trade Association has a new logo for SAS to replace this one.

# Author: IBM

Page: ii Sequence number: 1 Date: 1/6/2003 6:16:00 PM Type: Highlight ACCEPT - DONE Points of Contact George Penokie's email address is gop@us.ibm.com

Page: iii Sequence number: 2 Date: 1/7/2003 11:08:43 AM Type: Highlight REVIEW ALL WG ACCEPT - DONE (contents merged with LSI comment) Abstract

Sequence number: 1

This abstract is inaccurate and should be rewritten to the following:

This standard defines mechanical, electrical, timing requirements, command, and task management delivery protocol requirements to transfer commands and data between SCSI devices attached to a SCSI

serial interface. This standard is intended to be used in conjunction with the SCSI command sets. The resulting interface facilitates the interconnection of computers and intelligent peripherals and thus provides a common interface standard for both system integrators and suppliers of intelligent peripherals.

Page: v Sequence number: 2 Date: 2/6/2003 11:42:09 AM Type: Highlight ACCEPT - TODO **Revision Information** This needs to be removed before public review. Page: x Sequence number: 2 Date: 2/8/2003 11:11:31 AM Type: Circle REFER EDITORS WG TODO (some of the headers are so long that even no ident still causes wrap problems. If the header ends right at the end, the page number goes to the next line alone. If the header ends further right, the tab wraps too. Probably need to just shorten or lengthen some of the problematic state names.) Contents Indents only go one deep. So, for example, everything under clause 4 should be intended to the same level no matter how many sub-sections there are. This will happen at either ANSI or ISO any way. Also, when the indents are more that four deep there is a readability issue with long section titles. Page: x Sequence number: 3 Date: 1/6/2003 6:16:00 PM Type: Highlight ACCEPT - DONE Contents The term 'Page' needs to be move so the 'e' aligns with the LSD of the page number. Page: xxxiii Sequence number: 2 Date: 1/6/2003 6:16:00 PM Type: Note ACCEPT - DONE Foreword The INCITS leadership should be adding here as follows: Karen Higginbottom, Chair David Michael, Vice-chair Monica Vago, Secretary Page: xxxiii Sequence number: 3 Date: 1/6/2003 6:16:00 PM Type: Note ACCEPT - DONE Foreword The t10 leadership should be adding here as follows: John B. Lohmeyer, Chair George O. Penokie, Vice-Chair Ralph O. Weber, Secretary Page: xxxiii Sequence number: 4 Date: 2/6/2003 11:43:43 AM Type: Note ACCEPT - TODO Foreword The list of t10 members should be added here. A good format is to place the list in three columns (see SPI-5) Page: 1

Date: 1/7/2003 1:53:36 PM Type: Highlight **REJECT** - this standard is better Figure 1 The statement << this standard >> should in this case be replaced with SAS. Page: 1 Sequence number: 2 Date: 1/7/2003 1:53:30 PM Type: Highlight **REJECT** - this standard is better Figure 2 The statement << this standard >> should in this case be replaced with SAS. Page: 4 Sequence number: 1 Date: 1/11/2003 5:31:27 PM Type: Highlight ACCEPT - DONE (global format fix for notes) 2.3 References under development Global The format of the notes should be << NOTE 1 - >> the dash is missing. Page: 4 Sequence number: 2 Date: 1/7/2003 1:55:41 PM Type: Square **REVIEW EDITORS WG** REJECT - there are SATA references throughout this standard. (might want to make it clear that a "SATA" reference means all of these, not just the 8/29/01 document) 2.4 Other references As far as I can tell there are no references to these documents within this standard. So why are they listed as norminative? They should be removed or appropriate references added. Page: 5 Sequence number: 3 Date: 1/7/2003 2:14:28 PM Type: Highlight ACCEPT - DONE 3.1.13 broadcast primitive processor The statement << The portion of an ... >> should be changed to << An object within an ... >>. Page: 5 Sequence number: 4 Date: 2/6/2003 1:46:07 PM Type: Note ACCEPT - DONE 3.1 Definitions The ATA definitions should be replaced with document 03-022. Page: 6 Sequence number: 10 Date: 2/6/2003 11:52:00 AM Type: Strikeout ACCEPT - DONE (changed most "domain" references to "SAS domain". Kept this definiton but changed to "A SAS domain, SCSI domain, or ATA domain." (since we have a section called "Domains" which has pictures of ATA domains. I don't want to rename that section "SAS domains and ATA domains".)) 3.1.31 domain: Get rid of this by using << SAS domain >> in all cases. Page: 6 Sequence number: 11 Date: 1/7/2003 2:20:41 PM Type: Strikeout ACCEPT - DONE 3.1.32 downstream phy: The term << primary>> should be deleted as it provide no additional information to the definition.

Sequence number: 12 Date: 1/7/2003 2:15:27 PM Type: Highlight REJECT - upward signals are not always a response to anything 3.1.17 confirmation A confirmation is not a parameter that is passed rather it is the a response returned from a lower layer indicating completion of a request from a higher layer. Page: 7 Sequence number: 8 Date: 1/7/2003 2:24:10 PM Type: Highlight ACCEPT - DONE 3.1.39 expander connection router (ER): The statement << The portion of an ...>> should be changed to << An object within an ... >>. Page: 7 Sequence number: 9 Date: 1/7/2003 2:25:07 PM Type: Highlight ACCEPT - DONE 3.1.41 expander function: The statement << The portion of an ... >> should be changed to << An object within an ... >>. Page: 7 Sequence number: 10 Date: 2/7/2003 11:19:48 AM Type: Highlight ACCEPT - DONE (changed to "A routed SAS address" among other changes) 3.1.44 expander route entry: So what is << A single destination SAS address >>? Do not all SAS addresses belong to an individual device? If so then all are single destination SAS addresses. Page: 7 Sequence number: 11 Date: 1/7/2003 2:28:33 PM Type: Highlight ACCEPT - DONE 3.1.55 hash function: Change the statement << into a hashed value >> to << into a shorter hashed value >>. Page: 8 Sequence number: 10 Date: 1/6/2003 6:16:00 PM Type: Highlight 3.1.62 indication: An indication is not a parameter that is passed rather it is a transaction from a lower layer that conveys a request to a higher layer. Page: 8 Sequence number: 11 Date: 2/7/2003 6:46:14 PM Type: Strikeout REJECT - this links the term to other defined terms also in the glossary. Did add some xrefs. 3.1.72 link reset sequence: This is way to detailed and is a duplicate of what is in 4.4. Delete << an identification sequence, or a phy reset sequence followed by a hard reset sequence, another phy reset sequence, and an identification sequence>> and replace with << one or more other sequences (see 4.4).>> Page: 9 Sequence number: 10 Date: 2/7/2003 6:36:43 PM Type: Highlight TODO (Cris Simpson working on wording) 3.1.96 request: A request is not a parameter that is passed rather it is a transaction request from a higher layer that invokes a service from a lower layer.

Page: 9 Sequence number: 11 Date: 2/7/2003 6:36:38 PM Type: Highlight TODO (Cris Simpson working on wording) 3.1.98 response: A response is not a parameter that is passed rather it is a transaction from a higher layer that conveys the result of a request to a lower layer. Page: 9 Sequence number: 12 Date: 1/7/2003 2:49:36 PM Type: Strikeout ACCEPT - DONE 3.1.91 programmed maximum physical link rate: The definition is no place to be defining the default value. Delete << defaults to the hardware maximum physical link rate.>> Page: 9 Sequence number: 13 Date: 1/7/2003 2:49:43 PM Type: Strikeout ACCEPT - DONE 3.1.92 programmed minimum physical link rate: The definition is no place to be defining the default value. Delete << defaults to the hardware maximum physical link rate.>> Page: 10 Sequence number: 6 Date: 1/7/2003 2:55:28 PM Type: Highlight REFER PROTOCOL WG (depends on if it's referring to the "request-response" model in SAM-3 4.2 and 4.3, or the 4-step model in the transport protocol services) 3.1.116 SCSI initiator port: The statement <<reguests and responses are routed>> should be <<reguests and confirmations are routed>>. Note this is also wrong in SAM-3. Page: 10 Sequence number: 7 Date: 1/7/2003 2:55:39 PM Type: Highlight REFER PROTOCOL WG (see prev comment) 3.1.119 SCSI target port: The statement << requests and responses are routed>> should be <<indications and responses are routed>>. Note this is also wrong in SAM-3. Page: 11 Sequence number: 8 Date: 1/20/2003 4:01:47 PM Type: Strikeout REJECT (per PHY WG, but delete "(SSC)" abbreviation and keep a definition since the term is used within the specification.) 3.1.129 spread spectrum clocking (SSC): This should be deleted as the term is not used anywhere else in this standard. Page: 11 Sequence number: 9 Date: 1/7/2003 2:59:26 PM Type: Highlight ACCEPT - DONE ("set of protocols and the interconnect") 3.1.124 Serial Attached SCSI (SAS): The term <<pre>cprotocol>> should be <<pre>cprotocols>> as there are at least two protocols defined (i.e., SMP and SSP) Page: 12 Sequence number: 2 Date: 2/8/2003 10:39:04 AM Type: Square TODO (Cris Simpson working on wording) 3.1.146 transport protocol service confirmation: 3.1.147 transport protocol service indication: . 3.1.148 transport protocol service request: 3.1.149 transport protocol service response: I don't think these should even be in the glossary. But if they remain they need to change in the same manner suggested in the confirmation, indication, request, and response definitions.

Page: 12 Sequence number: 3 Date: 2/8/2003 10:38:14 AM Type: Strikeout ACCEPT - DONE 3.1.151 upstream phy: The term << primary >> should be deleted as it provide no additional information to the definition. Page: 12 Sequence number: 4 Date: 2/8/2003 10:37:45 AM Type: Strikeout REJECT (since we don't say "primitive" after each one in the text, the reader might not realize some obscure string of capital letters is a primitive name.) 3.2 Symbols and abbreviations Primitives should not be listed in the abbreviations list. Remove all primitives from the list. Page: 13 Sequence number: 3 Date: 2/8/2003 10:39:56 AM Type: Strikeout **REJECT** (see same comment earlier) 3.2 Symbols and abbreviations Primitives should not be listed in the abbreviations list. Remove all primitives from the list. Page: 13 Sequence number: 4 Date: 2/8/2003 10:39:53 AM Type: Strikeout REJECT (see same comment earlier) 3.2 Symbols and abbreviations Primitives should not be listed in the abbreviations list. Remove all primitives from the list. Page: 14 Sequence number: 2 Date: 1/6/2003 6:16:00 PM Type: Highlight ACCEPT - DONE 3.3.6 need not:: Remove one of the :s Page: 16 Sequence number: 3 Date: 1/7/2003 2:37:45 PM Type: Circle ACCEPT - DONE Figure 3 The indication goes from lower layers to higher layers. This should be response name. Page: 16 Sequence number: 4 Date: 1/7/2003 2:37:54 PM Type: Circle ACCEPT - DONE Figure 3 The indication goes from lower layers to higher layers. This should be response name. Page: 16 Sequence number: 5 Date: 1/7/2003 2:38:06 PM Type: Circle ACCEPT - DONE Figure 3 The Response goes from higher layers to lower layers. This should be indication name. Page: 16

Sequence number: 6 Date: 1/7/2003 2:37:59 PM Type: Circle ACCEPT - DONE Figure 3 The Response goes from higher layers to lower layers. This should be indication name Page: 17 Sequence number: 5 Date: 1/7/2003 5:23:46 PM Type: Highlight REFER EDITORS WG (why not use quotes? Not using them just makes it more confusing. This also occurs in some table column header references in the annexes.) 3.5.3 Parameters, requests, indications, confirmations, and responses Loss the """" around the <<"(to all states)">>. Page: 17 Sequence number: 6 Date: 1/7/2003 5:21:23 PM Type: Highlight REJECT (I like to spell out the first use in the text then use the acronym thereafter - who studies the acronym list before reading the document? Also, MSB and LSB could easily be read as ms/ls BYTE not BIT.) 3.6 Bit and byte ordering There is not need to redefine the LSB and MSB acronym as it has already been defined in the abbreviations list. Change << least significant bit (LSB) is shown on the right and the most significant bit (MSB)>> to <<LSB is shown on the right and the MSB>>. Page: 19 Sequence number: 2 Date: 1/7/2003 5:27:59 PM Type: Highlight REJECT - not referring to a subset of ports; all SAS ports do this 4.1.1 Architecture overview This which should be a that. Page: 19 Sequence number: 3 Date: 1/6/2003 6:16:00 PM Type: Highlight REJECT - not referring to a subset of ports 4.1.1 Architecture overview This which should be a that. Page: 20 Sequence number: 1 Date: 1/7/2003 5:24:47 PM Type: Highlight REJECT (what's wrong with semicolons for related sentences?) 4.1.2 Physical links and phys The statement <<A phy is a transceiver; it is the object in a ...>> should be changed to <<A phy is a transceiver and it is the object in a ...>> Page: 21 Sequence number: 8 Date: 1/7/2003 5:25:30 PM Type: Highlight ACCEPT - DONE (but with "which" rather than "that" - it's not a subset) 4.1.2 Physical links and phys The statement <<unique phy identifier (see 4.2.6) within the device.>> should be changed to <<p>compared to <</p> unique within the device>>. Page: 21 Sequence number: 9 Date: 1/29/2003 12:35:34 PM Type: Strikeout ACCEPT - DONE (this is here so ch4 the model chapter introduces the concept of link rates and dwords, which are used throughout subsequent chapters. Changed from naming 1.5 and 3.0 to "rates defined in 5.7" to address this comment. Later on in the connections section we have to add the concept of connection rate to address another comment.) 4.1.2 Physical links and phys This should be deleted as it only contains information that is defined elsewhere. It adds nothing to the standard and could easily be forgotten about and not updated in the next version of the standard. Delete << Phys transmit and receive bits at physical link rates of 1,5 Gbps or 3,0 Gbps (see 5.7). The bits are part of

Page: 24 Sequence number: 6 Date: 1/22/2003 3:06:09 PM Type: Highlight REJECT (whole section being deleted anyway) 4.1.6 Target devices The idea that a target would support both SCSI and ATA is too weird to conceive. I would like the idea deleted. The effect is that some of the and/ors change to or and figure 9 looses the middle set of boxes. Page: 25 Sequence number: 4 Date: 2/8/2003 11:17:04 AM Type: Highlight REJECT (that's not true) Figure 10 The term <<(optional)>> should be deleted as everything is optional unless stated otherwise. Page: 25 Sequence number: 5 Date: 1/6/2003 6:16:00 PM Type: Highlight 4.1.8.2 Edge expander device set The statement << grouped into edge expander device sets.>> should be changed to << grouped into an edge expander device set>> Page: 25 Sequence number: 6 Date: 1/6/2003 6:16:00 PM Type: Highlight 4.1.8.2 Edge expander device set The statement <<The edge expander device sets are>> should be <<An edge expander device set is>> Page: 25 Sequence number: 7 Date: 1/6/2003 6:16:00 PM Type: Highlight 4.1.8.2 Edge expander device set The statement <<Edge expander device sets are>> should be <<An edge expander device set is>>. Page: 26 Sequence number: 4 Date: 2/8/2003 11:18:07 AM Type: Highlight REJECT (but deleted this anyway) Figure 11 The term <<(optional)>> should be deleted as everything is optional unless stated otherwise. Page: 28 Sequence number: 3 Date: 1/6/2003 6:16:00 PM Type: Circle 4.1.10 Expander device topologies After the sentence that ends in <<is configured.>> add in the following sentence <<The method used to configure edge expander device sets is outside the scope of this standard.>> Page: 28 Sequence number: 4 Date: 1/6/2003 6:16:00 PM Type: Circle Figure 14 The bracket that is labeled <<64 edge expander device sets>> should be rotated 90 degrees and be stretched to bracket the two edge expander device sets. Page: 29 Sequence number: 2 Date: 1/6/2003 6:16:00 PM

Date: 1/6/2003 6:16: Type: Circle Figure 15

Type: Highlight

ACCEPT - DONE (and removed the 8-bit part too)

The bracket that is labeled <<64 attached devices or edge expander device sets>> should be rotated 90 degrees and be stretched to bracket the edge expander device set, the initiator or target devices, and the ...s.

Page: 29 Sequence number: 3 Date: 1/6/2003 6:16:00 PM Type: Circle Figure 16 The bracket that is labeled <<64 physical links per edge expander device set>> should be rotated 90 degrees and be stretched to bracket the initiator or target devices. Page: 29 Sequence number: 4 Date: 1/6/2003 6:16:00 PM Type: Circle Figure 16 The bracket that is labeled <<2 edge expander device sets>> should be rotated 90 degrees and be stretched to bracket the 2 edge expander device sets. Page: 30 Sequence number: 9 Date: 1/23/2003 5:00:40 PM Type: Highlight REJECT (yes more than one I\_T can be connected at a time in the domain. It's only on a physical link that they are one at a time.) 4.1.11 Connections The statement <<b) SCSI initiator port(s) to expander port(s) to SCSI target port(s); and>> is not correct. You cannot establish a connection between more that one initiator port and target port at a time. The statement should be changed to << b) SCSI initiator port to expander port(s) to SCSI target port; and>>. The same is probably true for item c. Page: 30 Sequence number: 10 Date: 1/23/2003 5:06:20 PM Type: Note TODO (this adds excess white space in many places. re-evaluate near end of editing. Maybe a 1 point line could be snuck in?) 4.1.11 Connections Global Having the anchored frame tag at the end of a paragraph can cause paragraphs, lines, and even individual words to be separated be large amounts of white space. This can made it difficult to read. The solution to this is to place the anchor in it's own paragraph. I recommend this be done. throughout this standard. Page: 32 Sequence number: 5 Date: 1/6/2003 6:16:00 PM Type: Circle Figure 18 The text in the key list is not lined up. Page: 33 Sequence number: 1 Date: 1/23/2003 5:52:17 PM Type: Highlight ACCEPT - DONE 4.2.2 SAS addresses The statement <<names in this>> in note 7 should be <<names defined by this standard.>> Page: 34 Sequence number: 2 Date: 1/23/2003 5:51:57 PM Type: Highlight REJECT - this convention is already described in section 3.4 after table 2 for binary and hex numbers 4.2.2 SAS addresses The \_ notation needs to be added to the notations section. Page: 34 Sequence number: 3 Date: 1/23/2003 6:16:05 PM

4.2.6 Phy identifier

Sequence number: 1 Date: 2/9/2003 5:21:30 PM

The statement <<a unique 8-bit identifier within the device.>> should be change to <<an 8-bit identifier that is unique within the device.>>.

Page: 35 Sequence number: 2 Date: 1/7/2003 6:16:47 PM Type: Highlight ACCEPT - DONE 4.3.1 State machine overview The statement <<and target devices and their relationships to each other and to the SAS device,>> should be changed to <<and target devices, their relationships to each other, and to the SAS device,>> Page: 36 Sequence number: 2 Date: 1/7/2003 6:19:57 PM Type: Circle REJECT (f a state machine has an associated transmitter, that controls both data and control of the MUX. SP, SP\_IR, and SL are this way) Figure 20 The blue dotted line on the last thing on the right is not connected to the correct text box. On closer inspection it looks like there two other blue dotted lines that look like they are going to the wrong place and there are two boxes with no lines coming out. Page: 39 Sequence number: 5 Date: 1/23/2003 6:34:34 PM Type: Note REJECT (some of these have special meaning for STP) Figure 23 In general this is too detailed for a SAS standard. Reduce the details. At a minimum reduce or eliminate the SATA primitives. All that is needed are some << SATA primitives >> labels. Page: 39 Sequence number: 6 Date: 1/24/2003 9:32:45 AM Type: Note 4.3.3 Signals Tables 9 through 22 There needs to be a better notation for the direction indication. the --> and <-- looks hookey. Page: 39 Sequence number: 7 Date: 1/24/2003 9:32:38 AM Type: Note 4.3.3 Signals Tables 9 through 22 In these tables the acronyms for the state machines are used but not all of them have been defined at this point in the standard. One solution would be to make a list or table of all the state machines with there acronyms before table 9. Another way would be to add in keys to every table with the acronym followed by the long name. Page: 39 Sequence number: 8 Date: 2/9/2003 5:05:23 PM Type: Note ACCEPT - DONE (tracking with Mark Evans' comment) 4.3.3 Signals between state machines This section needs to be replaced with proposal 03-023. Page: 40 Sequence number: 1 Date: 1/24/2003 9:32:54 AM Type: Circle 4.3.3 Signals Tables 11 through 15 Where ever there are multiple blank rows they should be combined to make a single blank area. Page: 45

Type: Circle

REJECT (it's not. Table 10 also has signals to the expander function.)

Table 18

Why is this the only table that has something called an << Expander function>> in the layers column? It seems out of place. At the minimum some kind if explanation is needed as to what it is and why it is here.

Page: 49 Sequence number: 6 Date: 1/24/2003 9:45:07 AM Type: Highlight ACCEPT - DONE (changed this to "a hard reset") 4.4.2 Hard reset In the statement <<If the port is part of a SCSI device, this causes a Transport Reset>> it is not clear what the <<th>statement to. This needs to be corrected. Page: 49 Sequence number: 7 Date: 1/24/2003 9:40:31 AM Type: Note ACCEPT - DONE (but only here, the first additional sense code mentioned; not adding an SPC-3 crossref to every use of additional sense code because there is often already a crossref after such) 4.4.2 Hard reset There should be a reference to SPC-3 at the end of the last paragraph of this section. Page: 49 Sequence number: 8 Date: 2/9/2003 5:22:28 PM Type: Highlight ACCEPT - DONE 4.5 I T nexus loss The statement <<an open connection time out in response>> should be changed to <<an open connection time out occurs in response>> Page: 49 Sequence number: 9 Date: 1/24/2003 9:35:56 AM Type: Highlight **REJECT** (timers expire) 4.5 I T nexus loss The term <<expires>> is not a word that should be used (look up the definition). It could easily be translated into dies. A quick fix would be to use <<times out>>. But I am open to other suggestions. Page: 49 Sequence number: 10 Date: 2/9/2003 5:24:10 PM Type: Circle REJECT (the editorial conventions say "lists sequenced by letters" which covers upper and lower case. There is no need to explain caps vs. lowercase; it's obvious.) 4.6.1 Expander device model overview We have not used the A,B,C convention in any t10 standards yet. We have been just using the a,b,c even in second level lists. If we are going to start using this then we need to define in the conventions section how we will indicate up to four(?) levels for both ordered and unordered lists. I don't think that is necessary and that changing this to a,b,c would not cause any confusion. Page: 49 Sequence number: 11 Date: 2/9/2003 5:25:18 PM Type: Strikeout **REVIEW PROTOCOL WG** REJECT (we indicate the minimum number here as 2. This sentence indicates there is a maximum as well.) 4.6.1 Expander device model overview I see no benefit from the statement << For the maximum number of phys, see 4.1.8>>. If should be deleted or at a minimum reduced to <<(see 4.1.8)>>. Page: 49 Sequence number: 12 Date: 1/6/2003 6:16:00 PM Type: Highlight 4.5 I T nexus loss The statement << it shall retry the connection request until: >> appears to be in conflict with Table 61 — OPEN\_REJECT abandon

primitives. That table includes OPEN\_REJECT (CONNECTION RATE NOT SUPPORTED). So who can it be retried and abandoned at the same time . This needs to be fixed.

Page: 50 Sequence number: 3 Date: 1/6/2003 6:16:00 PM Type: Highlight Figure 25 What is the statement <<Narrow or wide port>> have to do with this figure? It seems like it is saying there is a port that connects the expander function to the external SAS port. I believe it should be deleted. Page: 50 Sequence number: 4 Date: 1/6/2003 6:16:00 PM Type: Highlight 4.6.1 Expander device model overview In figure 25 it appears the <<external expander port>> is called an <<external SAS port>> also the same figure lists <<IR>> while the text lists <<SL\_IR>>. This inconsistent terminology needs to be resolved. Page: 50 Sequence number: 5 Date: 1/6/2003 6:16:00 PM Type: Circle 4.6.1 Expander device model overview There are several cases of inconsistent terminology between this section and figure 25. These all need to be resolved to one set of terms. Page: 51 Sequence number: 1 Date: 1/24/2003 9:50:43 AM Type: Highlight ACCEPT - DONE 4.6.6 Expander device interface The statement <<The interaction between an XL state machine and the expander function is called the expander device interface, and uses signals called requests, confirmations, indications, and responses.>> should be changed to <<The interaction between the XL state machine and the expander function consists of requests, confirmations, indications, and responses. This interaction is called the expander device interface.>> Page: 52 Sequence number: 1 Date: 2/9/2003 5:27:26 PM Type: Circle REJECT (Jan editors meeting said accept, but that's incorrect) Figure 26 The outputs from the broadcast primitive processor should be called confirmation not indication. The indication only occurs when there are interim steps between the request and the confirmation. Page: 53 Sequence number: 1 Date: 2/9/2003 5:27:36 PM Type: Circle REJECT (Jan editors meeting said accept, but that's incorrect) Figure 27 The outputs from the broadcast primitive processor should be called confirmations not indications. The indication only occurs when there are interim steps between the request and the confirmation. Page: 55 Sequence number: 1 Date: 1/24/2003 10:21:49 AM Type: Circle REJECT - the input indications are very important (the phy has got two signals named Transmit Open - the request going out and the indication coming in). Table 24 Global All the request/indication terms should be changed to just request. There is no need to state the indication part of the procedure. Page: 55 Sequence number: 2 Date: 1/24/2003 10:22:30 AM

Type: Circle REJECT - the input confirmations are very important (the phy has got two signals named Arb Status (Normal) - the respose going out and the confirmation coming in). Table 24 Global All the confirmation/response terms should be changed to just confirmation. There is no need to state the response part of the procedure. This change should also be made in the globally. Page: 55 Sequence number: 3 Date: 1/6/2003 6:16:00 PM Type: Highlight 4.6.9 Expander connection router interface The term <<signals>> is not correct here. I'm not sure what it should be maybe <<dwords>> or <<pre>correct Page: 59 Sequence number: 2 Date: 2/9/2003 5:29:22 PM Type: Strikeout REJECT (the example is of a sequence of unknown length not a 3 level sequence) 4.6.9 Expander connection router interface The <<, etc.>> should be deleted because the e.g. implies an etc. at the end of the list. Page: 59 Sequence number: 3 Date: 2/9/2003 5:30:39 PM Type: Highlight REJECT (unordered list makes the conditions stand out better) 4.6.9 Expander connection router interface The following <<For each of the level 2 devices that: a) is an edge expander device with M phys; and b) is attached to a phy in the level 1 edge expander device with the table routing attribute, the next M entries shall be the SAS addresses of the devices (level 3) attached to that level 2 edge expander device.>> should be changed to << For each of the level 2 devices that is an edge expander device with M phys and is attached to a phy in the level 1 edge expander device with the table routing attribute, the next M entries shall be the SAS addresses of the devices (level 3) attached to that level 2 edge expander device.>> Page: 65 Sequence number: 3 Date: 1/31/2003 3:48:54 PM Type: Highlight **REJECT** (per SAS PHY WG Reject IBM comment: Adds to the normative explanation of the SAS connection scheme by showing similarities.) 5.1 SATA cables and connectors (informative) This section should be placed in a annex that describes any SATA specific functions. Page: 66 Sequence number: 3 Date: 1/31/2003 3:56:32 PM Type: Highlight ACCEPT - DONE (per SAS PHY WG with "pins" too) 5.2 SAS cables and connectors Figure 32 The statement <<Tx to Rx on each>> should be changed to <<the Tx signal to the Rx signal on each>> Page: 67 Sequence number: 9 Date: 1/31/2003 4:05:44 PM Type: Highlight ACCEPT - DONE (per PHY WG Accept text change but leave as text rather than changing to a footnote.) 5.2 SAS cables and connectors

The following paragraph should be a footnote in table 29 and should be modified as shown <<The SATA device plug connector (e.g., used by a <<SATA>> disk drive) may be attached to a SAS backplane receptacle connector or a SAS internal cable receptacle connector, connecting the primary signal pairs and leaving the second signal pairs unconnected.

Sequence number: 10 Date: 1/31/2003 4:06:48 PM Type: Strikeout ACCEPT - DONE 5.2 SAS cables and connectors The term <<drive>> should be deleted as the form factors apply to a size of a device not the type of device. Page: 67 Sequence number: 11 Date: 1/31/2003 4:11:33 PM Type: Highlight ACCEPT - DONE (per SAS PHY WG Delete (xxx)s to resolve IBM comment. Use is obvious by the name.) 5.3.2.1 SAS plug connector overview The statement <<(for SAS cables) and SAS backplane receptacle connectors (for SAS backplanes).>> should be <<for SAS cables and SAS backplane receptacle connectors for SAS backplanes>> Page: 67 Sequence number: 12 Date: 1/31/2003 4:13:21 PM Type: Highlight ACCEPT - DONE (per PHY WG) 5.3.3 SAS internal cable receptacle connector The statement <<li>k, pins S8 through S14, is>> should be <<li>k (i.e., pins S8 through S14) is>>. Page: 68 Sequence number: 2 Date: 1/31/2003 4:41:20 PM Type: Highlight ACCEPT - DONE (per PHY WG) Table 30 So when I hook up all the voltage and precharge pins together and blow-up the drive and the possibly the power supply who is going to be responsible. This should change to << The precharge pin and each corresponding voltage pin shall be connected together (e.g., the V5 precharge pin is connected to the two V5 pins).>>. Page: 68 Sequence number: 3 Date: 1/31/2003 5:08:59 PM Type: Highlight ACCEPT - DONE (with "pin" per phy WG) 5.3.5 SAS internal connector pin assignments The statement << AT+ of connector 1 shall connect to AR+ >> should be << AT+ signal of connector 1 shall connect to AR+ signal >>. Page: 68 Sequence number: 4 Date: 1/20/2003 4:12:52 PM Type: Highlight ACCEPT - DONE 5.3.6 SAS external cable plug connector It the statement << It attaches >> what is the << it >> supposed to be be? I'm not sure. This needs to be fixed. Page: 68 Sequence number: 5 Date: 1/20/2003 4:10:02 PM Type: Highlight ACCEPT - DONE 5.3.5 SAS internal connector pin assignments The statement <<Table 30 shows>> should be <<Table 30 defines>>. Page: 69 Sequence number: 3 Date: 1/20/2003 4:12:42 PM Type: Highlight ACCEPT - DONE

5.3.7 SAS external receptacle connector It the statement << It attaches >> what is the << it >> supposed to be be? I'm not sure. This needs to be fixed.

Page: 69 Sequence number: 4 Date: 1/20/2003 4:13:28 PM Type: Highlight ACCEPT - DONE 5.3.8 SAS external connector pin assignments The statement <<Table 31 shows>> should be <<Table 31 defines>>. Page: 70 Sequence number: 6 Date: 1/31/2003 4:27:40 PM Type: Highlight ACCEPT - DONE (per PHY WG) 5.4.1 SAS internal cables The statement << SATA-style cable receptacle on the initiator device >> should be << SATA-style cable receptacle (see SATA) on the initiator device >>. Page: 70 Sequence number: 7 Date: 1/31/2003 4:29:14 PM Type: Highlight ACCEPT - DONE (per PHY WG, with "same as that defined for") 5.4.1 SAS internal cables The following << A SAS initiator device shall use a SATA-style host plug connector for connection to the SAS internal cable. The SATA host plug connector is defined in SATA. The signal assignment for the SAS initiator device or expander device with this connector shall be the same as defined for a SATA host in SATA. >> should be changed to << A SAS initiator device shall use a SATA-style host plug connector (see STAT) for connection to the SAS internal cable. The signal assignment for the SAS initiator device or expander device with this connector shall be the same as a SATA host (see SATA). >> Page: 71 Sequence number: 14 Date: 1/31/2003 4:43:31 PM Type: Highlight ACCEPT - DONE (per phy WG; include rather than carry) 5.4.2 SAS external cables The statement << not carry power>> should be changed to << not contain power >>. Page: 71 Sequence number: 15 Date: 1/20/2003 4:29:36 PM Type: Highlight ACCEPT - DONE 5.6 READY LED pin The statement << READY LED signal is raised, >> should be << READY LED signal is asserted, >> Page: 71 Sequence number: 16 Date: 1/20/2003 4:33:44 PM Type: Strikeout ACCEPT (deleted whole sentence) 5.6 READY LED pin The following should be deleted << since this pin may be connected by a system directly to power supply GROUND. >>. The standard does not need to justify a requirement. Page: 71 Sequence number: 17 Date: 1/20/2003 4:43:20 PM Type: Highlight ACCEPT - DONE 5.6 READY LED pin global Whenever a signal name is used it needs to be followed by the term << signal >>. Several places in this section READY LED is used without the term << signal >>. It should have been written as << READY LED signal >> in all cases.

Page: 71 Sequence number: 18 Date: 1/20/2003 4:26:34 PM Type: Highlight ACCEPT - DONE 5.6 READY LED pin The title of this section is not correct. It should be << READY LED signal >>. Page: 71 Sequence number: 19 Date: 1/20/2003 4:43:06 PM Type: Highlight ACCEPT - DONE 5.6 READY LED pin global There should be a reference to where the <<standby or stopped power condition state,>> are defined. Page: 71 Sequence number: 20 Date: 1/20/2003 4:43:12 PM Type: Highlight ACCEPT - DONE 5.6 READY LED pin global There should be a reference to where the <<. active or idle power condition state,>> are defined. Page: 72 Sequence number: 7 Date: 1/20/2003 4:49:28 PM Type: Highlight ACCEPT - DONE 5.6 READY LED pin The references to the a,b,c list items should have a cross-reference link. Page: 72 Sequence number: 8 Date: 2/9/2003 11:22:37 AM Type: Strikeout REJECT (from minutes of Joint WG in Jan: George Penokie led a discussion of the importance or unimportance of BER (Bit Error Rate) in SAS. Bill Ham, Alvin Cox and several others attempted (without success) to convince George that all BER information in SAS is very necessary. Eventually, it was agreed that every occurrence of BER in SAS be inspected and agreement reached by the group to keep them, remove them, or reword them to emphasize a preference for the use of better BERs than those stated in SAS.) 5.7.2 General interface specification All references to a BER should be removed from this standard. The value as specific is not low enough and specifying a lower number is not practical. Any SAS design that only meets the current specified BER will fail any qualification being used today. Page: 72 Sequence number: 9 Date: 1/20/2003 5:00:10 PM Type: Highlight ACCEPT - DONE (per SAS phy WG, changed to "These signal specifications are consistent with using good quality cable assemblies constructed with shielded twinex cable with 24 gauge solid wire up to eight meters in length without using any form of equalization (e.g., transmitter pre-emphasis, receiver adaptive equalization, or passive cable equalization).") 5.7.2 General interface specification The following statement indicates there are cable lengths specified in this standard but there are none. I believe that with out guidance from this standard as to what reasonable lengths are for cables this group is doing a disservice to the using community. I proposal cable lengths be specified in the same manner as they are in SPI-5. << TxRx connections operating at the maximum specified distances may require some form of equalization (e.g., transmitter pre-emphasis, receiver adaptive equalization, or passive cable equalization) to enable the signal requirements to be met. >> Page: 74 Sequence number: 3 Date: 1/20/2003 5:02:30 PM

Type: Circle ACCEPT - DONE Table 34 The entries in the characteristics column should be left justified. Page: 74 Sequence number: 4 Date: 1/31/2003 4:55:57 PM Type: Strikeout ACCEPT - DONE (per phy WG) Table 34 The term << or odd mode, >> is not used anywhere else in this standard and should be deleted. Page: 74 Sequence number: 5 Date: 1/31/2003 4:56:35 PM Type: Highlight ACCEPT - DONE Table 34 The statement << rate (both up and down). >> should be << rate for both power on and power off conditions. >> Page: 75 Sequence number: 1 Date: 1/20/2003 5:06:28 PM Type: Highlight ACCEPT - DONE 5.7.3.2 Delivered (receive) eye mask at IR, CR, and XR The term << delivered (receive) >> should be changed to << receive >> Page: 76 Sequence number: 1 Date: 1/20/2003 5:12:15 PM Type: Highlight ACCEPT - DONE 5.7.3.3 Jitter tolerance masks In the statement starting with << However, the leading >> the << however >> seems odd. It's not clear as to where the << however >> is referring to. Either the sentence needs to move or the << however >> should be deleted. I think deletion is the right answer. Page: 76 Sequence number: 2 Date: 1/31/2003 4:58:48 PM Type: Highlight ACCEPT - DONE (per phy WG) 5.7.4 Transmitted signal characteristics After the first usage of the statement << SATA 1.0 signal levels >> there needs to be a the << (see SATA) >> reference added. Page: 77 Sequence number: 4 Date: 1/25/2003 11:22:27 AM Type: Highlight ACCEPT - DONE (xref to 5.7.8) 5.7.5 Received signal characteristics Table 35 There need to be a reference to were the << CJTPAT test pattern >> is. Page: 77 Sequence number: 5 Date: 1/31/2003 4:59:26 PM Type: Highlight REJECT (per phy WG reject IBM comment to split tables.) 5.7.5 Received signal characteristics Table 36 This table should be broken into three tables with titles of: << Delivered signal characteristic at IR compliance points >>, << Delivered signal characteristic at CR compliance points >>, and << Delivered signal characteristic at XR compliance points >>. Then the first column can be deleted and the table will not flow across multiple pages.

Date: 1/31/2003 5:00:19 PM Type: Highlight REFER PHY WG (OOB to be discussed next call. proposal by Russ Brown to include note c rewording) 5.7.5 Received signal characteristics Table 36 The term << guaranteed >> should be deleted in all cases. Standards in general do not give guarantees. I do not believe anything would be lost if it is deleted. Page: 80 Sequence number: 1 Date: 1/31/2003 5:01:51 PM Type: Highlight ACCEPT - DONE (Accept IBM comment. make the following changes: Change section title to: Compliant jitter test pattern (CJTPAT) Change first sentence to: The CJTPAT within a compliant protocol frame shall be used for all jitter testing unless otherwise specified.) 5.7.8 Jitter compliance test pattern (CJTPAT) What the heck does CJPAT stand for: Jitter compliance test pattern or compliant protocol frame? It appears to be defined as both here. This needs to be resolved. Page: 81 Sequence number: 1 Date: 2/9/2003 11:24:15 AM Type: Highlight ACCEPT - TODO (inspect all tables at last edit) 5.7.9 Impedance specifications Table 39 The formatting of table 39 needs work. The super-script is running into the double lines. Page: 81 Sequence number: 2 Date: 1/31/2003 5:04:32 PM Type: Highlight ACCEPT - DONE 5.7.9 Impedance specifications Table 39 The last sentence of the footnotes does not have a period. Page: 81 Sequence number: 3 Date: 1/31/2003 5:04:09 PM Type: Highlight ACCEPT - DONE (per phy WG, with tweaks. Add the following definition: Media: A term referring to particular elements comprising the interconnect including copper cables, pc boards, or other transmission line materials.) 5.7.9 Impedance specifications Table 39 The term << media >> is not defined. This needs to be added to the glossary. Page: 82 Sequence number: 5 Date: 1/20/2003 5:31:05 PM Type: Highlight ACCEPT - DONE 5.7.11 Transmitter characteristics global The term << A. C. >> needs to be changed to <<A.C.>> in all cases. Page: 82 Sequence number: 6 Date: 1/31/2003 5:35:47 PM Type: Highlight ACCEPT - DONE 5.7.11 Transmitter characteristics alobal The term << D. C. >> needs to be changed to <<D.C.>> in all cases.

Sequence number: 7 Date: 1/31/2003 5:35:20 PM Type: Highlight ACCEPT - DONE 5.7.11 Transmitter characteristics global There should be no << etc. >> at the end of an e.g. list. The ect is implied in all e.g. lists and is therefore not needed. Page: 82 Sequence number: 8 Date: 1/20/2003 5:35:34 PM Type: Highlight ACCEPT - DONE (f is the signal frequency in hertz.) 5.7.11 Transmitter characteristics In the equation for S21 it in not clear what << f >> is. There needs to be a << Where: >> after the equation that describes << f >>. Page: 82 Sequence number: 9 Date: 1/20/2003 5:38:27 PM Type: Highlight REJECT (per phy WG, "a" intentionally left out as inclusion of it implies a single measurement. Multiple measurements) 5.7.11 Transmitter characteristics The statement << determined by measurement made >> seems to be missing a word. I think it should be << determined by a measurement made >>. Page: 86 Sequence number: 10 Date: 2/6/2003 11:16:16 AM Type: Highlight REJECT (but moved column to the right. Shows the differences between SAS and SATA primitives.) 6.2.1 Encoding overview Table 40 The << Usage in SATA >> column should be deleted. As most there could be a footnote stating << For the SATA usage of K28.3 and K28.5 characters see SATA. >> Page: 88 Sequence number: 2 Date: 1/24/2003 12:15:55 PM Type: Highlight ACCEPT - DONE (deleted parens altogether) 6.3.2 Transmission order The statement << (SOF delimiter) >> is not complete in SAS because we use other delimiters. It should be change to << (e.g., SOF delimiter) >>. Page: 88 Sequence number: 3 Date: 1/24/2003 12:15:49 PM Type: Highlight ACCEPT - DONE (deleted parens altogether) 6.3.2 Transmission order The statement << (EOF delimiter) >> is not complete in SAS because we use other delimiters. It should be change to << (e.g., EOF delimiter) >>. Page: 88 Sequence number: 4 Date: 1/24/2003 12:10:58 PM Type: Highlight REJECT - this seems like a truly parenthetical expression to me. It's not crucial to the sentence but is pointing out that the characters might be the same. 6.3.3.1 Definitions The statement << two (not necessarily different) transmission >> should be change to << two, not necessarily different, transmission >>. Page: 88 Sequence number: 5 Date: 1/24/2003 12:12:08 PM Type: Highlight ACCEPT - DONE 6.3.3.1 Definitions

The term << Current RD >> should not be capitalized. Change to << current RD >>.

Page: 88 Sequence number: 6 Date: 1/24/2003 12:11:40 PM Type: Highlight ACCEPT - DONE 6.3.3.1 Definitions The term << Current RD >> should not be capitalized. Change to << current RD >>. Page: 92 Sequence number: 1 Date: 1/24/2003 12:19:18 PM Type: Highlight ACCEPT - DONE (table 43 or table 44) 6.3.3.2 Generating transmission characters In the statement << the table shall be found >> what table is being referred to? I don't know and this needs to be fixed. Page: 93 Sequence number: 2 Date: 1/24/2003 12:19:40 PM Type: Circle ACCEPT - DONE 6.4 Bit order Figure 44 The << 16 >> at the top needs to be fixed. Page: 95 Sequence number: 1 Date: 1/8/2003 1:53:56 PM Type: Highlight ACCEPT - DONE 6.5 Out of band (OOB) signals \*\*\*\* The term << UI >> is used throughout this section with a different meaning than in all section up to this point. In this section it is assumed to be a fixed value while in all other sections it assumed to be a value the is related to the data rate of the bus. This inconsistency cannot be allowed. The thing that is called UI in this section needs to be renamed. I like OOBI. Out Of Band Interval. This would then be defined as the G1 UI. Page: 95 Sequence number: 2 Date: 1/8/2003 1:56:15 PM Type: Strikeout REJECT (now that we're not using the SATA UI(OOB) term, this note serves to relate OOBI to UI(OOB) in SATA.) Table 46 This statement << UI(OOB) is different than that defined in SATA; SAS has tighter clock tolerance. >> is meaningless in this standard as there are lots of differences between SAS and SATA. Page: 97 Sequence number: 5 Date: 1/8/2003 2:08:17 PM Type: Highlight ACCEPT - DONE 6.5 Out of band (OOB) signals The statement << Figure 47 describes SAS OOB signal detection by the SP receiver. >> needs a cross-reference to the SP receiver section which 6.7. Page: 97 Sequence number: 6 Date: 2/9/2003 5:36:42 PM Type: Note ACCEPT - DONE (track with Mark Evans' comment) 6.5 Out of band (OOB) signals Here's another one of those chopped sentences that occur because of the anchor placement. Page: 97 Sequence number: 7 Date: 2/9/2003 5:36:04 PM Type: Note

ACCEPT - TODO (review all tables in last edit) Tables Global

Many of the table have spacing between the double line borders and the text that is too close. This needs to be fixed on all tables.

Page: 99 Sequence number: 1 Date: 1/8/2003 2:29:16 PM Type: Highlight **REVIEW PROTOCOL WG** REJECT (it is most useful in context, which is here.) 6.6.2 SATA phy reset sequence (informative) This entire section should be deleted as it only described SATA functionality that is a duplicate of what is defined in the SATA document. If not deleted then it should be moved to a informative annex. Page: 99 Sequence number: 2 Date: 1/8/2003 2:55:35 PM Type: Highlight ACCEPT - DONE 6.6.3 SAS to SATA phy reset sequence The statement << in response to a COMINT, >> should be << in response to receiving a COMINIT, >>. Page: 100 Sequence number: 5 Date: 1/8/2003 3:02:42 PM Type: Circle ACCEPT - DONE Figure 50 The << Time z >> and it's definition are not lined up. Page: 102 Sequence number: 4 Date: 1/8/2003 5:42:21 PM Type: Highlight ACCEPT - DONE 6.6.4.1 SAS OOB sequence The statement <<phy A starting the SAS OOB sequence before, after, or at the same time as SAS phy. >> should be << phy A starting the SAS OOB sequence before, after, or at the same time as SAS phy B. >>. Page: 103 Sequence number: 1 Date: 1/8/2003 5:52:15 PM Type: Strikeout **REVIEW PROTOCOL WG REJECT** (highlights an important difference) 6.6.4.2 SAS speed negotiation sequence The statement << like the SATA speed negotiation sequence. >> is not relevant to this standard and should be deleted. Page: 103 Sequence number: 2 Date: 1/8/2003 5:52:36 PM Type: Strikeout ACCEPT - DONE 6.6.4.2 SAS speed negotiation sequence The SNLT is defined elsewhere so there is not need for the statement << a subset of the SNTT used by the receiver. >> which is more confusing than helpful. Delete it. Page: 104 Sequence number: 4 Date: 1/24/2003 2:46:14 PM Type: Highlight ACCEPT - DONE (who cares if an initiator takes longer? An attached device unless it tries. There should be a requirement on expanders. We might place a requirement on targets. Even then, the initiator's own polls will find a hot-plugged target quickly as it deserves. This value is here just to indicate that some attempt should be made again if nothing is detected. Changing to: initiator max - no (initiator can wait as long as it wants) initiator min - yes (for EMI) expander max - yes (so initiators are assured of seeing targets quickly)

expander min - yes (for EMI) target max - no target min - yes (for EMI) drop nominal time only applies to enabled phys (see SMP PHY CONTROL) (original comment:) Table 49 The hot-plug time out should be a requirement not a option. The <<should>> should be changed to a << shall >> Page: 104 Sequence number: 5 Date: 1/8/2003 1:57:22 PM Type: Strikeout ACCEPT - DONE (deleted note a as it is not used) Table 49 This statement << UI(OOB) is different than that defined in SATA; SAS has tighter clock tolerance. >> is meaningless in this standard as there are lots of differences between SAS and SATA. Page: 104 Sequence number: 6 Date: 1/14/2003 8:52:33 PM Type: Note REJECT (the WG repeatedly requested overall text rules here so the state machine doesn't have to be thought-simulated to figure out the resulting rules. That's what this section does.) 6.6.4.2 SAS speed negotiation sequence \*\*\*\* Much of the information in this section after table 49 is an exact duplicate of the information provided in the SAS speed negotiation states sections. It is not a good idea to have the same thing defined in two places in the standard. I suggest that the duplicate information in this section be placed in annex B. Page: 105 Sequence number: 1 Date: 1/8/2003 6:10:42 PM Type: Highlight ACCEPT - DONE (it's not an "in other words" sentence. However, an ordered list works much better. Also tossed the "valid" and "invalid" wording. Also changed annex B examples like this.) 6.6.4.2 SAS speed negotiation sequence The statement << (supported by phy A but not by phy B, so invalid), >> should be << (i.e., supported by phy A but not by phy B, so invalid), >> Page: 105 Sequence number: 2 Date: 1/8/2003 6:12:32 PM Type: Highlight ACCEPT - DONE (it's not an "in other words" sentence. However, an ordered list works much better. Also tossed the "valid" and "invalid" wording. Also changed annex B examples like this.) 6.6.4.2 SAS speed negotiation sequence The statement << (supported by phy A but not by phy B, so invalid), >> should be << (i.e., supported by phy A but not by phy B, so invalid), >> Page: 106 Sequence number: 4 Date: 1/24/2003 3:50:22 PM Type: Highlight REJECT (only required for expander phys) 6.6.5 Phy reset sequence after device is attached The transmission of COMINIT should be a requirement not a option. The <<should>> should be changed to a << shall >> Page: 108 Sequence number: 1 Date: 1/24/2003 6:18:28 PM Type: Highlight REJECT (SATA used Await. English rules would replace Await with WaitFor, not just Wait) 6.8 SAS phy (SP) state machine (global) All the states that have << Await >> in the title should be change to << Wait >>. Page: 108

Sequence number: 2 Date: 1/8/2003 6:30:19 PM Type: Strikeout

REJECT (allow that rule to be violated in introductions... note this one even has an e.g. about the source)

6.8.1 Overview

The statement << from the management layer >> should be deleted as the general rule is that we do not state where things come from in state diagrams.

Page: 109 Sequence number: 5 Date: 1/10/2003 2:36:41 PM Type: Highlight ACCEPT - DONE 6.8.2.1.1 State description The statement << This state shall send a Transmit COMINIT parameter to the SP transmitter and wait for COMINIT to be transmitted and/or received.>> should be << Upon entry into this state, this state shall: a) request a COMINIT be transmitted by sending a Transmit COMINIT parameter to the SP transmitter then wait for the receipt of a COMINIT Transmitted parameter and/or a COMINIT Detected parameter; and b) send a PhyNotReady parameter to the SP\_DWS state machine. >> Page: 109 Sequence number: 6 Date: 1/10/2003 11:20:56 AM Type: Highlight ACCEPT - DONE (it doesn't wait at all; changed "and does not receive" to "and has not received" so it doesn't imply waiting might occur) 6.8.2.1 SP1:OOB\_COMINIT state There is a problem with this state in that there is not indication as to the timing relationship between the receipt of COMINIT Transmitted and COMINIT Detected. This does not allow one to pick out which one of the three transitions to make. For example a COMINIT transmitted is received so how long does the state wait before determining that no COMINIT detected is going to occur? Or the reverse? This needs to be fixed. Page: 109 Sequence number: 7 Date: 1/6/2003 6:16:00 PM Type: Circle Figure 56 The statement << (to all states in the SP state machine causing transition to SP1:OOB\_COMMINIT) >> should be changed to << causes all states to transition to SP1:OOB\_COMMINIT) >> Page: 109 Sequence number: 8 Date: 1/24/2003 6:19:59 PM Type: Circle **REJECT** (per Jan WG) Figure 56 The labels on the state transitions should be deleted and they don't necessarily give the complete reason for the transition. Page: 110 Sequence number: 3 Date: 2/9/2003 5:43:26 PM Type: Strikeout REJECT (useful as an overview here) 6.8.2.3.1 State description The statement << This state is entered when a COMINIT sequence has been detected but the COMINIT initiated in SP1:OOB\_COMINIT has not been completely transmitted. >> should be deleted as we do not describe entry conditions only exit conditions. Page: 110 Sequence number: 4 Date: 2/9/2003 5:43:42 PM Type: Strikeout REJECT (useful as an overview here) 6.8.2.4.1 State description The statement << This state is reached when a COMINIT has been transmitted and detected.>> should be deleted as we do not describe entry conditions only exit conditions. Page: 110

Sequence number: 5 Date: 1/10/2003 2:42:27 PM Type: Highlight

ACCEPT - DONE 6.8.2.4.1 State description The statement << This state shall send a Transmit COMSAS parameter to the SP transmitter and wait for COMSAS to be transmitted and/or detected..>> should be << Upon entry into this state, this state shall request a COMSAS be transmitted by sending a Transmit COMSAS parameter to the SP transmitter then wait for the receipt of a COMSAS Transmitted parameter and/or a COMSAS Detected parameter. >> Page: 110 Sequence number: 6 Date: 1/10/2003 5:09:58 PM Type: Highlight ACCEPT - DONE (changed "does not receive" to "has not received" to avoid any implication of waiting) 6.8.2.4 SP4:OOB\_COMSAS state There is a problem with this state in that there is not indication as to the timing relationship between the receipt of COMSAS Transmitted and COMSAS Detected. This does not allow one to pick out which one of the three transitions to make. For example a COMSAS Detected is received so how long does the state wait before determining that no COMSAS Transmitted is going to occur? The reverse? This needs to be fixed. Page: 110 Sequence number: 7 Date: 1/10/2003 2:37:38 PM Type: Highlight ACCEPT - DONE 6.8.2.3.1 State description The statement << This state waits for COMINIT to be transmitted. >> should be << This state waits for receipt of a COMINIT Transmitted parameter. >> Page: 111 Sequence number: 2 Date: 2/9/2003 5:44:32 PM Type: Strikeout REJECT (useful as an overview) 6.8.2.6.1 State description The statement << This state is entered when a COMSAS sequence has been both transmitted and detected. >> should be deleted as we do not describe entry conditions only exit conditions. Page: 111 Sequence number: 3 Date: 2/4/2003 7:10:25 PM Type: Highlight REJECT (but changed to "initialized and started") 6.8.2.7.1 State description The statement << time out timer shall be initialized and enabled. >> should be << time out timer shall be set to it's initial value and enabled. >> Page: 111 Sequence number: 4 Date: 1/24/2003 6:24:52 PM Type: Highlight ACCEPT - DONE (moved the NOTE into an i.e.; split item d) into two) 6.8.2.7.2 Transition SP7:OOB\_AwaitCOMSAS to SP1:OOB\_COMINIT The statements << If all of these conditions are true: ... this state shall send a Broadcast Event Notify (SATA Spinup Hold) confirmation to the expander function and perform this transition. NOTE 11 In other words, SMP PHY CONTROL-based requests to reset the phy bypass spinup hold; all other resets honor it. >> should be changed to <<This state shall send a Broadcast Event Notify (SATA Spinup Hold) confirmation to the expander function if: .... >> This deletes the note. Page: 113 Sequence number: 3 Date: 1/10/2003 5:15:33 PM Type: Highlight ACCEPT - DONE Figure 57 The term << window >> in 2 places should be << rate >>. Page: 113 Sequence number: 4 Date: 1/10/2003 5:15:01 PM

Type: Highlight ACCEPT - DONE (made a little shorter) Figure 57 The << ALIGN1 Detected >> going into SP11 looks like it is coming from SP10. Page: 113 Sequence number: 5 Date: 1/24/2003 6:30:17 PM Type: Circle REJECT (per Jan WG) Figure 57 The labels on the state transitions should be deleted and they don't necessarily give the complete reason for the transition. Page: 114 Sequence number: 4 Date: 1/6/2003 6:16:00 PM Type: Strikeout 6.8.3.1.1 State description The following statement should be deleted as the information stated is already stated elsewhere << This allows time required for a transmitter to switch to either the next higher or next lower supported speed. >> Page: 114 Sequence number: 5 Date: 1/6/2003 6:16:00 PM Type: Highlight 6.8.3.1.1 State description The following statement << This state marks the beginning of the SAS speed negotiation process. >> should be << This is the initial state of the SAS speed negotiation >>. Page: 114 Sequence number: 6 Date: 1/6/2003 6:16:00 PM Type: Strikeout 6.8.3.1.1 State description The following statement should be deleted as the same information is duplicated in the last sentence of this section << It is used to transmit idle in between SAS speed negotiation windows. >>. Page: 114 Sequence number: 7 Date: 2/4/2003 7:11:25 PM Type: Highlight REJECT (this is the selected timer terminology) 6.8.3.1.1 State description The statement <<... RCD timer shall be initialized and >> should be << ... RCD timer shall be set to it's initial value and enabled..>>. Page: 114 Sequence number: 8 Date: 1/10/2003 10:44:47 AM Type: Highlight ACCEPT - DONE 6.8.3.1.2 Transition SP8:SAS\_Start to SP10:SAS\_AwaitALIGN The statement << speed negotiation window is supported. >> should be << speed negotiation rate is supported. >> It's not the window that's supported or not supported but the link rate for that window. Page: 114 Sequence number: 9 Date: 1/10/2003 10:44:53 AM Type: Highlight ACCEPT - DONE 6.8.3.1.3 Transition SP8:SAS\_Start to SP9:SAS\_RateNotSupported The statement << speed negotiation window is not supported. >> should be << speed negotiation rate is not supported. >> It's not the window that's supported or not supported but the link rate for that window. Page: 114 Sequence number: 10 Date: 1/6/2003 6:16:00 PM Type: Square 6.8.3.1.1 State description

This should be an a.b.c list like this: Upon entering this state, this state shall: a) set the RCD timer to it's initial value; b) enable the RCD timer; and c) send the Set Rate parameter to the SP transmitter to select the next negotiated rate. Page: 114 Sequence number: 11 Date: 1/6/2003 6:16:00 PM Type: Highlight 6.8.3.1.1 State description The statement << During this state idle shall be transmitted. >> should be changed to << This state shall request idle dwords be transmitted by repeatedly sending a Transmit Idle Dword parameter to the SP transmitter (see 7.3). >> Page: 114 Sequence number: 12 Date: 1/6/2003 6:16:00 PM Type: Highlight 6.8.3.2.1 State description The statement << During this state idle shall be transmitted. >> should be changed to << This state shall request idle dwords be transmitted by repeatedly sending a Transmit Idle Dword parameter to the SP transmitter (see 7.3). >> Page: 114 Sequence number: 13 Date: 2/4/2003 7:10:58 PM Type: Highlight REJECT (but changed to "initialized and started") The statement << SNTT timer shall be initialized and enabled. >> should be << SNTT timer shall be set to it's initial value and enabled. >> Page: 114 Sequence number: 14 Date: 1/25/2003 4:44:32 PM Type: Strikeout ACCEPT - DONE 6.8.3.2.1 State description This statement adds nothing but confusion and should be deleted << The state machine exits from this state after the SNTT expires.>> Page: 114 Sequence number: 15 Date: 1/10/2003 10:44:05 AM Type: Highlight ACCEPT - DONE (after ..expires if...) 6.8.3.1.2 Transition SP8:SAS Start to SP10:SAS AwaitALIGN The statement << occur if the RCD timer expires and the current >> should be << occur after the RCD timer expires if the current >>. The timer will always time out. Page: 114 Sequence number: 16 Date: 1/10/2003 10:44:10 AM Type: Highlight ACCEPT - DONE (after ..expires if...) 6.8.3.1.3 Transition SP8:SAS\_Start to SP9:SAS\_RateNotSupported The statement << occur if the RCD timer expires and the current >> should be << occur after the RCD timer expires if the current >>. The timer will always time out. Page: 114 Sequence number: 17 Date: 1/10/2003 10:45:58 AM Type: Highlight ACCEPT - DONE 6.8.3.2.2 Transition SP9:SAS\_RateNotSupported to SP14:SAS\_Fail The statement << if the >> should be <<after the >> as the timer will always time out.

Page: 114 Sequence number: 18 Date: 1/6/2003 6:16:00 PM Type: Square 6.8.3.3.1 State description The following should be made into an a,b,c list << The state machine shall start transmitting ALIGN (0) primitives at the current rate (G1, G2, G3...). Upon entering this state, the SNTT timer and SNLT timer shall be initialized and enabled. >> as follows: << Upon entering this state, this state shall: a) request ALIGN (0) be transmitted at the current rate (e.g., G1, G2, G3) by repeatedly sending a Transmit ALIGN0 parameter to the SP transmitter: and b) the SNTT timer and SNLT timer shall be set to their initial value and enabled. >>. Page: 114 Sequence number: 19 Date: 1/6/2003 6:16:00 PM Type: Highlight 6.8.3.3.1 State description The statement << synchronization occurs before >> should be changed to << synchronization (i.e., ALIGN0 Detected parameter or ALIGN1 Detected parameter received) occurs before >>. Page: 114 Sequence number: 20 Date: 1/6/2003 6:16:00 PM Type: Highlight 6.8.3.1.1 State description The statement << speed negotiation window received as an argument.>> should be changed to << SAS Speed Negotiation Window Rate argument. >> Page: 115 Sequence number: 6 Date: 1/6/2003 6:16:00 PM Type: Strikeout 6.8.3.4.1 State description The statement << This state is reached after ALIGN (0) has been both transmitted and received. >> should be deleted as we do not describe entry conditions only exit conditions. Page: 115 Sequence number: 7 Date: 1/6/2003 6:16:00 PM Type: Highlight 6.8.3.4.1 State description The following statement << This state shall repeatedly send a Transmit ALIGN0 parameter to the SP transmitter.>> should be <<This state shall request ALIGN (0) be transmitted at the current rate (e.g., G1, G2, G3) by repeatedly sending a Transmit ALIGN0 parameter to the SP transmitter. >> Page: 115 Sequence number: 8 Date: 1/25/2003 4:47:57 PM Type: Highlight REJECT (rewording implies an ominiscent state. This state can only based decisions on its inputs.) 6.8.3.4.2 Transition SP11:SAS\_AwaitALIGN1 to SP14:SAS\_Fail The following statement << This transition shall occur if the SNTT timer expires. This indicates that the other phy has not been able to lock at the current rate. >> should be <<This transition shall occur if the other phy has not locked at the current rate and the SNTT timer times-out. >> Page: 115 Sequence number: 9 Date: 1/25/2003 4:46:51 PM Type: Highlight REJECT (this state can only respond to its input signals, not to the state of some other phy.) 6.8.3.4.3 Transition SP11:SAS\_AwaitALIGN1 to SP14:SAS\_ AwaitSNW The statement <<This transition shall occur if this state receives an ALIGN1 Detected parameter before the SNTT timer expires. This indicates that the other phy has been able to lock at the current rate. >> should be changed to << This transition shall occur if the other phy has locked (i.e., ALIGN1 Detected parameter received before the SNTT timer expires). >> Page: 115 Sequence number: 10 Date: 1/6/2003 6:16:00 PM Type: Strikeout

6.8.3.5.1 State description

The statement << This state is reached after ALIGN (1) has been both transmitted and received. >> should be deleted as we do not describe entry conditions only exit conditions.

Page: 115 Sequence number: 11 Date: 1/6/2003 6:16:00 PM Type: Highlight 6.8.3.5.1 State description The following statement << This state shall repeatedly send a Transmit ALIGN1 parameter to the SP transmitter.>> should be <<This state shall request ALIGN (1) be transmitted at the current rate (e.g., G1, G2, G3) by repeatedly sending a Transmit ALIGN1 parameter to the SP transmitter.>>. Page: 115 Sequence number: 12 Date: 1/10/2003 10:46:42 AM Type: Highlight ACCEPT - DONE 6.8.3.5.2 Transition SP12:SAS\_AwaitALIGN1 to SP13:SAS\_Pass The statement << if the >> should be << after the >>. Page: 115 Sequence number: 13 Date: 1/6/2003 6:16:00 PM Type: Highlight 6.8.3.6.2 Transition SP13:SAS\_Pass to SP8:SAS\_Start The statement << which is sent as an argument to the SN\_start state>> should be moved to the end of the section and restated as <<This transition shall pass a SAS Speed Negotiation Window Rate argument to the SN start state. >>. Page: 116 Sequence number: 2 Date: 1/6/2003 6:16:00 PM Type: Highlight 6.8.3.7.3 Transition SP14:SAS\_Fail to SP8:SAS\_Start The statement << Which speed negotiation window to use is sent as an argument with this transition. >> should be changed to <<This transition shall pass which speed negotiation window to use in the SAS Speed Negotiation Window Rate argument to the SN\_start state. >>. Page: 116 Sequence number: 3 Date: 1/6/2003 6:16:00 PM Type: Strikeout 6.8.3.8.1 State description The following << to provide rule checking for dword synchronization and determination of link failure. >> should be deleted as the information is already in the DWS section. A reference to DWS would be OK. Page: 116 Sequence number: 4 Date: 1/6/2003 6:16:00 PM Type: Highlight 6.8.3.8.1 State description The statement << the receipt of a COMINIT; >> should be << the receipt of a COMINIT Detected parameter >>. Page: 116 Sequence number: 5 Date: 1/6/2003 6:16:00 PM Type: Strikeout 6.8.3.8.1 State description The statement << While in this state, dwords from the link layer are transmitted at the negotiated physical link rate >> should be deleted as it is stated 2 times in this section. Page: 116 Sequence number: 6 Date: 1/6/2003 6:16:00 PM Type: Strikeout 6.8.3.8.1 State description The statement << from the link layer >> should be deleted as the general rule is that we do not state where things come from in state diagrams.

Page: 117 Sequence number: 1 Date: 1/10/2003 10:55:14 AM Type: Highlight REJECT (but changed it to "if ...this state receives" to match other text) 6.8.3.8.2 Transition SP15:SAS\_PHY\_Ready to SP1:OOB\_COMINIT The statement << occur if: >> should be << occur after >>. Page: 117 Sequence number: 2 Date: 2/5/2003 10:03:07 AM Type: Highlight ACCEPT - DONE 6.8.4 SATA host emulation states The statement << the SAS device (an initiator device or expander device) has >> should be << a SAS initiator device or an expander device has >>. Page: 117 Sequence number: 3 Date: 1/6/2003 6:16:00 PM Type: Strikeout 6.8.4 SATA host emulation states The statement << During SATA host emulation, the SAS device transmits a COMWAKE sequence and then waits to receive a COMWAKE. Once the COMWAKE sequence is detected, the SAS device follows the speed negotiation sequence defined in SATA. >> should be deleted as the information in this statement is duplicate information. Page: 118 Sequence number: 5 Date: 2/4/2003 6:46:17 PM Type: Circle ACCEPT - DONE Figure 58 The COMWAKE Transmitted parameter is missing as a input to SP16. Page: 118 Sequence number: 6 Date: 2/4/2003 6:49:18 PM Type: Circle ACCEPT - DONE Figure 58 The COMWAKE Detected parameter is missing as a input to SP17. Page: 118 Sequence number: 7 Date: 2/4/2003 6:49:25 PM Type: Circle ACCEPT - DONE Figure 58 The COMWAKE Completed parameter is missing as a input to SP18. Page: 118 Sequence number: 8 Date: 1/24/2003 6:31:38 PM Type: Circle **REJECT** (per Jan WG) Figure 58 The labels on the state transitions should be deleted and they don't necessarily give the complete reason for the transition. Page: 119 Sequence number: 3 Date: 1/6/2003 6:16:00 PM Type: Highlight 6.8.4.2.2 Transition SP17:SATA\_AwaitCOMWAKE to SP18:SATA\_AawitNoCOMWAKE There is a type in the SP18 state name. It should SATA\_AwaitNoCOMWAKE. Page: 119

Sequence number: 4 Date: 1/6/2003 6:16:00 PM Type: Highlight 6.8.4.1.1 State description The statement << wait for COMWAKE to be transmitted. >> should be changed to << wait for a COMWAKE Completed parameter to be received. >>. Page: 119 Sequence number: 5 Date: 1/6/2003 6:16:00 PM Type: Highlight 6.8.4.3.1 State description The statement << This state waits for COMWAKE to be fully received. >> should be << This state waits for a COMWAKE Completed parameter to be received. >> Page: 119 Sequence number: 6 Date: 1/6/2003 6:16:00 PM Type: Highlight 6.8.4.4.1 State description The statement << repeatedly send a Transmit D10.2 parameter to the SP transmitter; >> should be << request D10.2s be transmitted by repeatedly sending a Transmit D10.2 parameter to the SP transmitter. >> Page: 119 Sequence number: 7 Date: 2/4/2003 7:14:01 PM Type: Highlight REJECT (but changed to "initialized and start") 6.8.4.4.1 State description The statement << start the ALIGN detect time out timer; >> should be << set the ALIGN detect timer to it's initial value and enabled it; >> Page: 119 Sequence number: 8 Date: 1/6/2003 6:16:00 PM Type: Highlight 6.8.4.4.1 State description The statement <<ALIGN to be received or an ALIGN detect time out. >> should be << ALIGN0 Received parameter to be received or an ALIGN detect time out to occur. >> Page: 119 Sequence number: 9 Date: 2/4/2003 7:14:52 PM Type: Strikeout TODO (is it based on receiving COMWAKE or transmitting it?) 6.8.4.4.1 State description The statement << The SAS device shall start transmitting D10.2 characters no later than 20 G1 dwords (i.e., 533 ns) after COMWAKE was deasserted. >> should be deleted as it makes no sense here. It appears to be more of a transmitter requirement rather than a requirement of this state. Also COMWAKE is not something that can be deasserted it is a sequence of signals. Page: 119 Sequence number: 10 Date: 1/6/2003 6:16:00 PM Type: Strikeout 6.8.4.4.2 Transition SP19:SATA\_AwaitALIGN to SP20:SATA\_AdjustSpeed The statement << at any of its supported physical link rates. >> should be deleted as it makes no sense here. Page: 119 Sequence number: 11 Date: 2/4/2003 7:15:18 PM Type: Highlight REJECT (unnececessarily verbose) 6.8.4.5.1 State description The statement << This state shall repeatedly send Transmit D10.2 parameters to the SP transmitter >> should be << This state shall request D10.2s be transmitted by repeatedly sending a Transmit D10.2 parameter to the SP transmitter >> Page: 120 Sequence number: 7 Date: 1/10/2003 10:50:49 AM Type: Highlight ACCEPT - DONE (but left in "this state")

6.8.4.5.2 Transition SP20:SATA\_AdjustSpeed to SP21:SATA\_TransmitALIGN This statement << when this state receives a Transmitter Ready parameter. >> should be <<after receiving a Transmitter Ready parameter. >>. Page: 120 Sequence number: 8 Date: 1/6/2003 6:16:00 PM Type: Highlight 6.8.4.6.1 State description The statement << This state shall repeatedly send the Transmit ALIGN0s parameter to the SP transmitter. >> should be << This state shall request ALIGN0s be transmitted by repeatedly sending a Transmit ALIGN0 parameter to the SP transmitter. >> Page: 120 Sequence number: 9 Date: 1/6/2003 6:16:00 PM Type: Strikeout 6.8.4.6.1 State description The statement << When the SP receiver detects three back-to-back non-ALIGNs, the state machine transitions to state SP22:SATA\_PHY\_Ready. >> should be deleted as all the information is in the transition description. Page: 120 Sequence number: 10 Date: 1/10/2003 10:55:44 AM

## Type: Highlight

Page: 120

REJECT (that doesn't follow the convention)

6.8.4.7.4 Transition SP22:SATA\_PHY\_Ready to SP23:SATA\_PM\_Slumber

The statement << if this state receives an Enter Slumber request. >> should be << if an Enter Slumber request is received.>>.

Sequence number: 11 Date: 1/10/2003 10:55:38 AM Type: Highlight REJECT (that doesn't follow the convention) 6.8.4.7.4 Transition SP22:SATA\_PHY\_Ready to SP23:SATA\_PM\_Slumber The statement << if this state receives an Enter Partial request. >> should be << if an Enter Partial request is received.>> Page: 120 Sequence number: 12 Date: 2/4/2003 7:05:45 PM Type: Highlight ACCEPT - DONE (changed to OOB\_COMINIT proper state number) 6.8.4.7.2 Transition SP22:SATA\_PHY\_Ready to SP1:Reset In figure 58 this transition goes to SP1:OOB\_COMINIT but here it goes to SP1:Reset . Only one is correct. This needs to be fixed.

Page: 120

Sequence number: 13

Date: 1/6/2003 6:16:00 PM

Type: Highlight

6.8.4.7.2 Transition SP22:SATA\_PHY\_Ready to SP1:Reset The statement << This transition shall occur if this state receives a COMINIT Received parameter or a DWS Reset parameter. >> makes no sense as there is not COMINIT Received or DWS Reset in figure 58. So it is not clear what causes this transition.

Page: 120 Sequence number: 14 Date: 1/6/2003 6:16:00 PM Type: Highlight

6.8.4.7.1 State description

The statement << This state shall send a PhyReady (SATA) parameter to the SP\_DWS state machine. >> should be Upon entering this state, this state shall send a PhyReady (SATA) parameter to the SP\_DWS state machine. >>.

Page: 120 Sequence number: 15 Date: 1/6/2003 6:16:00 PM Type: Highlight 6.8.4.7.1 State description The statement << In this state, the SP state machine hands control over dword transmission to the SP\_DWS state machine. The SP receiver monitors the input dword stream looking for COMINIT. >> should be << This state sends RhyReady (SATA) parameter to the SP\_DWS state machine to enable it. >> If this state needs to take some action if a COMINIT detected or complete happens then there needs to be a parameter input and a description as to what happens when the parameter is received.

Page: 120 Sequence number: 16 Date: 1/10/2003 10:55:53 AM Type: Highlight REJECT (that doesn't follow the convention) 6.8.4.8.2 Transition SP23:SATA\_PM\_Partial to SP16:SATA\_COMWAKE The statement << if this state receives a Exit Partial request. >> should be << if an Exit Partial request is received. >> Page: 120 Sequence number: 17 Date: 1/10/2003 10:56:00 AM Type: Highlight REJECT (that doesn't follow the convention) 6.8.4.8.3 Transition SP23:SATA\_PM\_Partial to SP18:SATA\_AwaitNoCOMWAKE The statement << if this state receives a COMWAKE Detected parameter. >> should be << if a COMWAKE Detected parameter is received. >>. Page: 120 Sequence number: 18 Date: 1/6/2003 6:16:00 PM Type: Highlight 6.8.4.8.1 State description The statement << Exit from this state is driven from receipt of COMWAKE or by request of the link layer. >> should be << This state waits for a COMWAKE Detected parameter or a Exit Partial parameter to be received. >> Page: 120 Sequence number: 19 Date: 1/6/2003 6:16:00 PM Type: Highlight 6.8.4.9.1 State description The statement << Exit from this state is driven from receipt of COMWAKE or by request of the link layer. >> should be << This state waits for a COMWAKE Detected parameter or a Exit Slumber parameter to be received. >>. Page: 120 Sequence number: 20 Date: 1/10/2003 10:56:04 AM Type: Highlight REJECT (that doesn't follow the convention) 6.8.4.9.2 Transition SP24:SATA\_PM\_Slumber to SP16:SATA\_COMWAKE The statement << if this state receives a Exit Slumber request. >> should be << if an Exit Slumber request is received. >> Page: 121 Sequence number: 2 Date: 2/4/2003 6:59:47 PM Type: Highlight REJECT (may be a better convention, but not predominant for SAS-1) 6.8.4.9.3 Transition SP24:SATA\_PM\_Slumber to SP18:SATA\_AwaitNoCOMWAKE The statement << if this state receives a COMWAKE Detected parameter. >> should be << if a COMWAKE Detected parameter is received. >>. Page: 121 Sequence number: 3 Date: 1/9/2003 9:23:21 AM Type: Highlight REJECT (they're sent/pushed here for action. received implies "pulled") 6.9.1 Overview The statement << are sent to the SP\_DWS machine >> should be << are received by the SP\_DWS state machine >>. Page: 121 Sequence number: 4 Date: 1/10/2003 10:58:52 AM Type: Circle ACCEPT (item c) above should have been "receiving Phy Not Ready" not PhyReady - that causes the state machine to start in DWS0) 6.9.1 Overview There should be text here that states what happens when a PhyNotReady parameter is received.

Sequence number: 5 Date: 1/11/2003 4:09:47 PM Type: Note REFER PROTOCOL WG 6.9.1 Overview It seems like there should a Dword Received parameter from the receiver that goes to all the states within this state machine. As a result there should be a green open arrow pointing to the edge of the SP\_DWS state machine. The following text should be added here: All the states within the SP\_DWS receive the Dword Receive parameter from the SP receiver. Page: 121 Sequence number: 6 Date: 1/10/2003 10:59:22 AM Type: Strikeout REJECT (that rule is not for introductions) 6.9.1 Overview The statement << from the SP state machine. >> should be deleted as the general rule is that we do not state where things come from in state diagrams. Page: 121 Sequence number: 7 Date: 1/10/2003 10:59:27 AM Type: Strikeout REJECT (that rule is not for introductions) 6.9.1 Overview The statement << from the SP state machine: >> should be deleted as the general rule is that we do not state where things come from in state diagrams. Page: 122 Sequence number: 1 Date: 1/6/2003 6:16:00 PM Type: Circle Figure 59 There needs to be a cut-out so the PhyNotReady arrow points to the SP\_DWS state machine. Also the text need not state that the parameter goes to all states. That is implied. The statement << (This parameter causes a transition to SP\_DW0:AcquireSync) >>. Page: 122 Sequence number: 2 Date: 1/24/2003 6:31:59 PM Type: Circle **REJECT** (per Jan WG) Figure 59 The labels on the state transitions should be deleted and they don't necessarily give the complete reason for the transition. Page: 123 Sequence number: 5 Date: 1/6/2003 6:16:00 PM Type: Strikeout 6.9.2.1 State description The statement << This state is entered upon power on loss or previous dword synchronization. >> should be deleted as we do not define entry conditions. Page: 123 Sequence number: 6 Date: 1/6/2003 6:16:00 PM Type: Highlight 6.9.2.1 State description The statement << In this state, the receiver monitors the input data stream >> should be << This state monitors the Dwords received in the Dword Received parameter >>. Page: 123 Sequence number: 7 Date: 1/6/2003 6:16:00 PM Type: Highlight 6.9.2.1 State description The statement << character it detects into the >> should be << character detected into the >>. Page: 123 Sequence number: 8

Date: 1/6/2003 6:16:00 PM

Type: Highlight 6.9.2.2 Transition SP\_DWS0:AcquireSync to SP\_DWS1:Valid1 The statement << is detected. >> should be << is received >>. Page: 123 Sequence number: 9 Date: 1/10/2003 11:01:17 AM Type: Strikeout REJECT (it explains the state name and is not a set of entry equations) 6.9.3.1 State description The statement << This state is reached after one valid primitive has been detected. >> should be deleted as we do not describe entry conditions. Page: 123 Sequence number: 10 Date: 1/10/2003 11:01:23 AM Type: Strikeout REJECT (it explains the state name and is not a set of entry equations) 6.9.4.1 State description The statement << This state is reached after the receiver has detected two valid primitives. >> should be deleted as we do not describe entry conditions. Page: 123 Sequence number: 11 Date: 1/10/2003 11:01:30 AM Type: Strikeout REJECT (it explains the state name and is not a set of entry equations) 6.9.5.1 State description The statement << This state is reached when the receiver has detected three valid primitives without adjusting the dword synchronization. >> should be deleted as we do not describe entry conditions. Page: 123 Sequence number: 12 Date: 1/6/2003 6:16:00 PM Type: Highlight 6.9.3.1 State description The statement << In this state, the receiver shall monitor the input data stream looking >> should be << This state shall monitor the Dwords received in the Dword Received parameter looking >> Page: 123 Sequence number: 13 Date: 1/6/2003 6:16:00 PM Type: Highlight 6.9.4.1 State description The statement << In this state, the receiver shall monitor the input data stream looking >> should be << This state shall monitor the Dwords received in the Dword Received parameter looking >> Page: 123 Sequence number: 14 Date: 1/6/2003 6:16:00 PM Type: Highlight 6.9.5.1 State description The statement << In this state, the receiver shall monitor the incoming data stream looking >> should be << This state shall monitor the Dwords received in the Dword Received parameter looking >> Page: 123 Sequence number: 15 Date: 1/6/2003 6:16:00 PM Type: Highlight 6.9.3.2 Transition SP\_DWS1:Valid1 to SP\_DWS2:Valid2 The statement << This transition shall occur when a valid primitive is detected. >> should be << This transition shall occur after receiving a Dword Received parameter that contains a valid primitive. >> Page: 123 Sequence number: 16 Date: 1/6/2003 6:16:00 PM Type: Highlight

6.9.4.2 Transition SP\_DWS2:Valid2 to SP\_DWS3:SyncAcquired

The statement << This transition shall occur when a valid primitive is detected. >>

should be << This transition shall occur after receiving a Dword Received parameter that contains a valid primitive. >>

Page: 123 Sequence number: 17 Date: 1/6/2003 6:16:00 PM Type: Highlight 6.9.4.3 Transition SP\_DWS2:Valid2 to SP\_DWS0:AcquireSync The statement << This transition shall occur when a invalid dword is detected. >> should be << This transition shall occur after receiving a Dword Received parameter that contains an invalid Dword.>> Page: 123 Sequence number: 18 Date: 1/6/2003 6:16:00 PM Type: Highlight 6.9.5.2 Transition SP\_DWS3:SyncAcquired to SP\_DWS4:Lost1 The statement << This transition shall occur when an invalid dword (i.e., the first invalid dword) is detected.>> should be << This transition shall occur after receiving a Dword Received parameter that contains an invalid Dword (i.e., the first invalid dword).>> Page: 123 Sequence number: 19 Date: 1/11/2003 4:07:53 PM Type: Highlight REFER PROTOCOL WG (we once had a tiny section after the XP state machine, easily overlooked. We decided to keep the rules here and delete that section.) 6.9.5.2 Transition SP\_DWS3:SyncAcquired to SP\_DWS4:Lost1 The statement << An expander forwarding the dword to another phy shall replace the invalid dword with ERROR for a SAS physical link or SATA ERROR for a SATA physical link. >> seems out of place here. This should be defined in the expander information that describes the insertion of error primitives. As most there should be a reference to that information << For expander rules on invalid Dwords replacement see x.x.x. >> Page: 124 Sequence number: 2 Date: 1/6/2003 6:16:00 PM Type: Strikeout 6.9.6.1 State description The statement << This state is reached when one invalid dword has been received and not nullified. >> should be deleted as we do not describe entry conditions. Page: 124 Sequence number: 3 Date: 1/10/2003 11:01:41 AM Type: Strikeout REJECT (it explains the state name and is not a set of entry equations) 6.9.7.1 State description The statement << This state is reached when a valid dword has been received, and another valid dword will nullify the previous invalid dword. >> should be deleted as we do not describe entry conditions. Page: 124 Sequence number: 4 Date: 1/10/2003 11:01:49 AM Type: Strikeout REJECT (it explains the state name and is not a set of entry equations) 6.9.8.1 State description The statement << This state is reached when two invalid dwords has been received and not nullified. >> should be deleted as we do not describe entry conditions. Page: 124 Sequence number: 5 Date: 1/10/2003 11:01:54 AM Type: Strikeout REJECT (it explains the state name and is not a set of entry equations) 6.9.9.1 State description The statement << This state is reached when a valid dword has been received, and another valid dword will nullify the previous invalid dword. >> should be deleted as we do not describe entry conditions.

Sequence number: 6 Date: 1/10/2003 11:01:35 AM Type: Highlight REJECT (it explains the state name and is not a set of entry equations) 6.9.6.1 State description The statement << In this state, the receiver shall monitor the incoming data stream looking >> should be << This state shall monitor the Dwords received in the Dword Received parameter looking >> Page: 124 Sequence number: 7 Date: 1/6/2003 6:16:00 PM Type: Highlight 6.9.7.1 State description The statement << In this state, the receiver shall monitor the incoming data stream looking >> should be << This state shall monitor the Dwords received in the Dword Received parameter looking >> Page: 124 Sequence number: 8 Date: 1/6/2003 6:16:00 PM Type: Highlight 6.9.8.1 State description The statement << In this state, the receiver shall monitor the incoming data stream looking >> should be << This state shall monitor the Dwords received in the Dword Received parameter looking >> Page: 124 Sequence number: 9 Date: 1/6/2003 6:16:00 PM Type: Highlight 6.9.9.1 State description The statement << In this state, the receiver shall monitor the incoming data stream looking >> should be << This state shall monitor the Dwords received in the Dword Received parameter looking >> Page: 124 Sequence number: 10 Date: 1/6/2003 6:16:00 PM Type: Highlight 6.9.6.2 Transition SP\_DWS4:Lost1 to SP\_DWS5:Lost1Recovered The statement << This transition shall occur when a valid dword is detected. >> should be << This transition shall occur after receiving a Dword Received parameter that contains an valid Dword.>> Page: 124 Sequence number: 11 Date: 1/6/2003 6:16:00 PM Type: Highlight 6.9.7.2 Transition SP\_DWS5:Lost1Recovered to SP\_DWS3:SyncAcquired The statement << This transition shall occur when a valid dword is detected. >> should be << This transition shall occur after receiving a Dword Received parameter that contains an valid Dword.>> Page: 124 Sequence number: 12 Date: 1/6/2003 6:16:00 PM Type: Highlight 6.9.8.2 Transition SP\_DWS6:Lost2 to SP\_DWS7:Lost2Recovered The statement << This transition shall occur when a valid dword is detected. >> should be << This transition shall occur after receiving a Dword Received parameter that contains an valid Dword.>> Page: 124 Sequence number: 13 Date: 1/6/2003 6:16:00 PM Type: Highlight 6.9.6.3 Transition SP\_DWS4:Lost1 to SP\_DWS6:Lost2 The statement << This transition shall occur when an invalid dword is detected.>> should be << This transition shall occur after receiving a Dword Received parameter that contains an invalid Dword.>>

Sequence number: 14 Date: 1/6/2003 6:16:00 PM Type: Highlight 6.9.7.3 Transition SP\_DWS5:Lost1Recovered to SP\_DWS6:Lost2 The statement << This transition shall occur when an invalid dword is detected.>> should be << This transition shall occur after receiving a Dword Received parameter that contains an invalid Dword.>> Page: 124 Sequence number: 15 Date: 1/6/2003 6:16:00 PM Type: Highlight 6.9.8.3 Transition SP DWS6:Lost2 to SP DWS8:Lost3 The statement << This transition shall occur when an invalid dword is detected.>> should be << This transition shall occur after receiving a Dword Received parameter that contains an invalid Dword.>> Page: 124 Sequence number: 16 Date: 1/6/2003 6:16:00 PM Type: Highlight 6.9.6.3 Transition SP\_DWS4:Lost1 to SP\_DWS6:Lost2 The statement << An expander forwarding the dword to another phy shall replace the invalid dword with ERROR for a SAS physical link or SATA\_ERROR for a SATA physical link. >> seems out of place here. This should be defined in the expander information that describes the insertion of error primitives. As most there should be a reference to that information << For expander rules on invalid Dwords replacement see x.x.x. >> Page: 124 Sequence number: 17 Date: 1/6/2003 6:16:00 PM Type: Highlight 6.9.7.3 Transition SP DWS5:Lost1Recovered to SP DWS6:Lost2 The statement << An expander forwarding the dword to another phy shall replace the invalid dword with ERROR for a SAS physical link or SATA\_ERROR for a SATA physical link. >> seems out of place here. This should be defined in the expander information that describes the insertion of error primitives. As most there should be a reference to that information << For expander rules on invalid Dwords replacement see x.x.x. >> Page: 124 Sequence number: 18 Date: 1/6/2003 6:16:00 PM Type: Highlight 6.9.8.3 Transition SP\_DWS6:Lost2 to SP\_DWS8:Lost3 The statement << An expander forwarding the dword to another phy shall replace the invalid dword with ERROR for a SAS physical link or SATA ERROR for a SATA physical link. >> seems out of place here. This should be defined in the expander information that describes the insertion of error primitives. As most there should be a reference to that information << For expander rules on invalid Dwords replacement see x.x.x. >> Page: 125 Sequence number: 1 Date: 1/10/2003 11:02:02 AM Type: Strikeout REJECT (it explains the state name and is not a set of entry equations) 6.9.10.1 State description The statement << This state is reached when three invalid dwords has been received and not nullified. >> should be deleted as we do not describe entry conditions. Page: 125 Sequence number: 2 Date: 1/10/2003 11:02:21 AM Type: Strikeout REJECT (it explains the state name and is not a set of entry equations) 6.9.11.1 State description The statement << This state is reached when a valid dword has been received, and another valid dword will nullify the previous invalid dword. >> should be deleted as we do not describe entry conditions. Page: 125

Sequence number: 3 Date: 1/6/2003 6:16:00 PM Type: Highlight 6.9.10.1 State description The statement << In this state, the receiver shall monitor the incoming data stream looking >> should be << This state shall monitor the Dwords received in the Dword Received parameter looking >> Page: 125 Sequence number: 4 Date: 1/6/2003 6:16:00 PM Type: Highlight 6.9.11.1 State description The statement << In this state, the receiver shall monitor the incoming data stream looking >> should be << This state shall monitor the Dwords received in the Dword Received parameter looking >> Page: 125 Sequence number: 5 Date: 1/6/2003 6:16:00 PM Type: Highlight 6.9.9.2 Transition SP\_DWS7:Lost2Recovered to SP\_DWS4:Lost1 The statement << This transition shall occur when a valid dword is detected. >> should be << This transition shall occur after receiving a Dword Received parameter that contains an valid Dword.>> Page: 125 Sequence number: 6 Date: 1/6/2003 6:16:00 PM Type: Highlight 6.9.10.2 Transition SP\_DWS8:Lost3 to SP\_DWS9:Lost3Recovered The statement << This transition shall occur when a valid dword is detected. >> should be << This transition shall occur after receiving a Dword Received parameter that contains an valid Dword.>> Page: 125 Sequence number: 7 Date: 1/6/2003 6:16:00 PM Type: Highlight 6.9.11.2 Transition SP\_DWS9:Lost3Recovered to SP\_DWS6:Lost2 The statement << This transition shall occur when a valid dword is detected. >> should be << This transition shall occur after receiving a Dword Received parameter that contains an valid Dword.>> Page: 125 Sequence number: 8 Date: 1/6/2003 6:16:00 PM Type: Highlight 6.9.9.3 Transition SP DWS7:Lost2Recovered to SP DWS8:Lost3 The statement << This transition shall occur when an invalid dword is detected.>> should be << This transition shall occur after receiving a Dword Received parameter that contains an invalid Dword.>> Page: 125 Sequence number: 9 Date: 1/6/2003 6:16:00 PM Type: Highlight 6.9.10.3 Transition SP\_DWS8:Lost3 to SP\_DWS0:AcquireSync The statement << If an invalid dword (i.e., the fourth non-nullified invalid dword) is detected, this state shall send a DWS Reset parameter to the SP state machine and this transition shall occur. >> should be << This transition shall occur after receiving a Dword Received parameter that contains an invalid Dword (i.e., the fourth non-nullified invalid dword) and after sending a DWS Reset parameter to the SP state machine.>> Page: 125 Sequence number: 10 Date: 1/6/2003 6:16:00 PM Type: Highlight 6.9.11.3 Transition SP DWS9:Lost3Recovered to SP DWS0:AcquireSync The statement << If an invalid dword (i.e., the fourth non-nullified invalid dword) is detected, this state shall send a DWS Reset parameter to the SP state machine and this transition shall occur. >> should be << This transition shall occur after receiving a Dword Received parameter that contains an invalid Dword (i.e., the fourth non-nullified invalid dword) and after sending a DWS Reset parameter to the SP state machine.>>

Date: 1/6/2003 6:16:00 PM

Type: Highlight

6.9.9.3 Transition SP\_DWS7:Lost2Recovered to SP\_DWS8:Lost3

The statement << An expander forwarding the dword to another phy shall replace the invalid dword with ERROR for a SAS physical link or

SATA\_ERROR for a SATA physical link. >> seems out of place here. This should be defined in the expander information that describes the insertion of error primitives. As most there should be a reference to that information << For expander rules on invalid Dwords replacement see x.x.x. >>

Page: 125 Sequence number: 12 Date: 1/25/2003 11:24:27 AM Type: Strikeout ACCEPT - DONE 6.10 Spin-up The statement << NOTE 12 A SATA target device with rotating media spins up: a) automatically after power on (allowed by SATA); b) after its phy is enabled (allowed by SATA); c) after the reset sequence has completed (recommended by SATA); or d) after the Power Up in Standby flag is cleared by an application (if the ATA Power Up in Standby feature is implemented). The ATA Power Up in Standby feature is not widely implemented, since it requires the target device to include a nonvolatile memory to remember the state of the Power Up in Standby flag. Desktop-class disk drives do not typically have nonvolatile memory storage. >> has no value to this standard and should be deleted. Page: 127 Sequence number: 2 Date: 1/25/2003 11:24:39 AM Type: Highlight REJECT Table 51 The footnotes have to be on each split of the table not just the last one. Page: 135 Sequence number: 1 Date: 1/16/2003 5:58:35 PM Type: Strikeout ACCEPT - TODO (keep these 3 sentences here. Put a short reference in each of the \_4\_ sections below back to here - "ALIGNs may be sent inside primitive sequences as described in 7.1.3.1.") 7.1.3.1 Primitive sequence overview The statement << ALIGNs may be sent inside primitive sequences without affecting the count or breaking the consecutiveness requirements. >> should be deleted as it is repeated in each of the next three sections. The other option would be to delete the text in all three sections and leave it here. Page: 135 Sequence number: 2 Date: 1/16/2003 6:18:31 PM Type: Highlight ACCEPT - TODO (delete everything after "consecutively") 7.1.3.4 Triple primitive sequence The statement << consecutively and followed by idle dwords until a response is received. >> should be <<consecutively followed by idle dwords. >> The statement << until a response is received >> is incomplete because it does not describe what the response is that is received. Either that has to be defined or the statement deleted. Page: 135 Sequence number: 3 Date: 1/6/2003 6:16:00 PM Type: Strikeout 7.1.3.3 Repeated primitive sequence The statement << until a response is received >> is incomplete because it does not describe what the response is that is received. Either that has to be defined or the statement deleted. Page: 135 Sequence number: 4 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.1.3.4 Triple primitive sequence The statement << detect a triple primitive sequence by receiving the identical primitive in three consecutive dwords. >> should be << detect a triple primitive sequence after the identical primitive is received in three consecutive dwords. >>

Page: 135 Sequence number: 5 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.1.3.5 Redundant primitive sequence The statement << shall be sent six times consecutively. >> should be << shall be sent six times consecutively followed by idle dwords Page: 135 Sequence number: 6 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.1.3.5 Redundant primitive sequence The statement << detect redundant primitive sequences by receiving an identical primitive for three consecutive dwords. >> should be << detect a redundant primitive sequence after the identical primitive is received in three consecutive dwords. >> Page: 135 Sequence number: 7 Date: 1/16/2003 6:05:16 PM Type: Highlight ACCEPT - TODO (Change to "After receiving a triple primitive sequence, a receiver shall not detect a second instance of the same triple primitive sequence until") Apply everywhere. 7.1.3.4 Triple primitive sequence \*\*\* In the statement << receiver shall not detect primitive sequences a second time until it >> it is not clear if the primitive sequence that shall not be detected is this primitive sequence or any primitive sequence or any triple primitive sequence. This needs to be made clear. Page: 135 Sequence number: 8 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.1.3.5 Redundant primitive sequence In the statement << receiver shall not detect primitive sequences a second time until it >> it is not clear if the primitive sequence that shall not be detected is this primitive sequence or any primitive sequence or any redundant primitive sequence. This needs to be made clear. Page: 136 Sequence number: 1 Date: 1/6/2003 6:16:00 PM Type: Strikeout ACCEPT - DONE 7.1.4.2 ALIGN The statement << are used for >> should be deleted as it is duplicated in the sentence. Page: 136 Sequence number: 2 Date: 1/6/2003 6:16:00 PM Type: Strikeout **REVIEW PROTOCOL WG REJECT** - highlights a difference with SATA 7.1.4.2 ALIGN The statement << NOTE 14 SATA devices are allowed to decode every dword starting with a K28.5 as an ALIGN, since ALIGN is the only primitive defined starting with K28.5. >> as it contains no information that is relevant to this standard. Page: 137 Sequence number: 5 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.1.4.4 BROADCAST Change << BROADCAST indications >> to << BROADCASTs >>. Page: 137 Sequence number: 6 Date: 1/6/2003 6:16:00 PM Type: Highlight

7.1.4.4 BROADCAST Change << BROADCAST indication >> to << BROADCAST >>. Page: 137 Sequence number: 7 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.1.4.4 BROADCAST Change << second indication >> to << second BROADCAST >>. Page: 137 Sequence number: 8 Date: 1/6/2003 6:16:00 PM Type: Highlight Table 60 The term << initiator affiliation. >> is not used anywhere else in this standard. So I have no idea as to what it is. It needs to be defined or changed to a term that is defined. Page: 137 Sequence number: 10 Date: 1/13/2003 10:37:47 AM Type: Highlight ACCEPT - TODO (Jan WG treat like CLOSE (NORMAL) when received in SSP or SMP connection) 7.1.4.5 CLOSE There is no indication as to what a device should do if it does not support STP and receives a CLOSE (CLEAR AFFILIATION). I suggest the description should be changed to << Close an open STP connection and clear the initiator affiliation. If a device does not support STP it shall process the CLOSE (CLEAR AFFILIATION) the same as CLOSE (NORMAL). >> Page: 138 Sequence number: 8 Date: 1/6/2003 6:16:00 PM Type: Highlight ACCEPT - DONE 7.1.4.9 NOTIFY The TBD needs to be replaced with a reference. Page: 138 Sequence number: 9 Date: 1/6/2003 6:16:00 PM Type: Note REFER EDITORS WG - it says "is only valid" during that time, is it necessary to say ignored otherwise? 7.1.4.8 HARD RESET There should be a statement that states that the HARD\_RESET shall be ignored if received at any time other than after a phy reset sequence and before the identification sequence. Page: 138 Sequence number: 10 Date: 1/8/2003 1:04:01 PM Type: Highlight ACCEPT - DONE 7.1.4.9 NOTIFY The statement << devices shall transmit NOTIFY (ENABLE\_SPINUP) >> should changed to << devices shall use NOTIFY (ENABLE\_SPINUP) >>. The rules for usage do follow in this paragraph but the use of the word << transmit >> in this sentence makes the sentence seem incomplete. Page: 138 Sequence number: 11 Date: 1/16/2003 6:32:32 PM Type: Note REJECT - TODO (Either ALIGN or NOTIFY fulfills the 2048 dwords.) 7.1.4.9 NOTIFY The way this is now it is possible that the receiver may not get an ALIGN within the 2048 dwords if a NOTIFY replaces an ALIGN. There needs to be a rule that when sending NOTIFYs the transmitter is still required to send ALIGNs at least once every 2048 dwords.

Page: 139 Sequence number: 3 Date: 1/6/2003 6:16:00 PM Type: Highlight Table 61 The term << affiliation >> needs to be defined. Page: 140 Sequence number: 3 Date: 1/6/2003 6:16:00 PM Type: Circle ACCEPT - DONE Table 62 There needs to be a double line between the body and footer. Page: 141 Sequence number: 3 Date: 1/17/2003 1:28:01 PM Type: Square ACCEPT - TODO Table 63 The statement << Timed out waiting for an ACK or NAK. The ACK/NAK count does not match the frame count. Transmitter is going to transmit BREAK in 1 ms unless DONE is received prior to that. >> should be << The SSP state machine timed out waiting for an ACK or NAK (see 7.16.7.2) and the transmitter is going to transmit BREAK unless a DONE is received within 1 ms of transmitting the DONE (ACK/NAK TIMEOUT). Page: 143 Sequence number: 6 Date: 1/6/2003 6:16:00 PM Type: Highlight ACCEPT - DONE (joined two sentences with and) 7.2 Clock skew management The statement << This is used when transmitting data >> should be << The internal clock is used when transmitting data >>. Page: 143 Sequence number: 7 Date: 1/6/2003 6:16:00 PM Type: Highlight REFER PROTOCOL WG - it's really concerned with bits, not dwords here. Data is a good generic term. 7.2 Clock skew management The statement << data needs to be latched based >> should be << dwords need to be latched based >>. Page: 143 Sequence number: 8 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.2 Clock skew management The statement << receive data and not be able to >> should be << receive dwords and not be able to Page: 143 Sequence number: 9 Date: 1/16/2003 6:36:03 PM Type: Highlight ACCEPT - TODO (change all these "data" to "dwords". In the figure, "clock derived from serial bitstream") 7.2 Clock skew management The statement << have data when needed >> should be << have dwords when needed >>. Page: 143 Sequence number: 10 Date: 1/8/2003 1:18:12 PM Type: Highlight **REVIEW EDITORS WG** REJECT (this is a valid use of "will") 7.1.6.3 SATA\_HOLD and SATA\_HOLDA (Hold and hold acknowledge) The statement << SATA\_HOLDA will arrive within >> should be << SATA\_HOLDA arrives within >>.

Date: 1/6/2003 6:16:00 PM Type: Square ACCEPT - DONE Table 66 Make the information << Original source of data SSP initiator phy or target phy in SSP connection, SMP initiator phy or SMP target phy in SMP connection, Any phy outside connections, or STP target phy in an STP connection >> into a left aligned a,b,c list. Page: 144 Sequence number: 5 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.2 Clock skew management The term << amongst >> should << through >> Page: 144 Sequence number: 6 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.3 Idle links ACCEPT - DONE (slightly different) The statement << While no connection is open and a physical link is idle, or while an SSP or SMP connection is open and the physical link is idle, SAS phys shall transmit idle dwords. >> should be << SAS phys shall transmit idle words if: a) no connection is open and a physical link is idle; b) an SSP connection is open and the physical link is idle; or c) an SMP connection is open and the physical link is idle. >> Page: 145 Sequence number: 3 Date: 1/6/2003 6:16:00 PM Type: Highlight REJECT - there's no overlap between lines, and the suggested setting adds awkward look extra space to some of the lines but not all Table 67 The paragraphs within the definitions should have the paragraph designer, basic, line spacing, fixed box unchecked. This will remove the superscripts running into the line above. Page: 146 Sequence number: 3 Date: 1/6/2003 6:16:00 PM Type: Highlight ACCEPT - DONE 7.4.2 CRC generation The statement << order - the bits within each byte of the data dword are transposed to match the implicit transposition in the 8b10b encoding process. >> should be << order (i.e., the bits within each byte of the data dword are transposed to match the implicit transposition in the 8b10b encoding process). >>. Page: 147 Sequence number: 13 Date: 1/17/2003 11:28:23 AM Type: Highlight REJECT (but sentence being deleted) 7.5 Scrambling The statement << Table 69 shows when the scrambling logic shall treat data as big-endian and when it shall treat data as little-endian. >> should be << Table 69 shows when the scrambling logic shall handle data as big-endian and when it shall handle data as little-endian. >> . Page: 147 Sequence number: 14 Date: 1/17/2003 11:05:07 AM Type: Highlight ACCEPT - TODO (delete second sentence) 7.5 Scrambling The statement << These patterns can cause issues in the physical >> should be << These patterns may cause issues in the physical >>. Page: 149

Sequence number: 1

Date: 1/6/2003 6:16:00 PM Type: Strikeout ACCEPT - DONE 7.7.1 Address frames overview The statement << Primitives may be inserted in the address frame. >> is no longer valid and needs to be deleted. Page: 150 Sequence number: 2 Date: 1/24/2003 7:13:10 PM Type: Strikeout ACCEPT - DONE 7.7.2 IDENTIFY address frame The statement << The recipient shall ignore reserved and ignored fields in the IDENTIFY address frame. >> should be deleted as the information is already stated in the keywords definitions. Page: 152 Sequence number: 3 Date: 1/16/2003 7:28:57 PM Type: Strikeout ACCEPT - TODO (Move all the reasons for OPEN REJECT into the OPEN REJECT table in 7.7.early.) 7.7.3 OPEN address frame The statement << The destination device shall reject the connection request with OPEN\_REJECT (PROTOCOL NOT SUPPORTED) if the PROTOCOL field is set to a value it does not support. >> should be deleted as this information is already stated in the state machines. Page: 153 Sequence number: 2 Date: 1/21/2003 1:05:31 PM Type: Strikeout (move to 7.15) 7.7.3 OPEN address frame The statement << Every phy shall support the 1,5 Gbps connection rate at every physical link rate. >> should be deleted as this is not the place to put link speed requirements. Page: 153 Sequence number: 3 Date: 1/24/2003 7:18:31 PM Type: Strikeout ACCEPT - DONE (changing Reserved to Compatible Features; shall set to zero, receivers shall not check. This is NOT the normal definition of reserved.) The statement << The destination device shall ignore the contents of reserved fields in the OPEN address frame. >> should be deleted as it is already stated in the keywords definitions section. Page: 153 Sequence number: 4 Date: 1/24/2003 7:17:57 PM Type: Strikeout REFER PROTOCOL WG 7.7.3 OPEN address frame The statement << The INITIATOR CONNECTION TAG field is used for SSP and STP connection requests to provide an initiator port an easier context lookup when the target port originates a connection request. >> states no requires or options and should be deleted. Page: 154 Sequence number: 4 Date: 1/24/2003 7:24:19 PM Type: Highlight **REFER PROTOCOL WG** REJECT (shall expect is a rule, which we are trying to establish here) 7.8.1 Overview The statement << Each phy shall also expect to receive an >> should be << Each phy receives an >>. Page: 154 Sequence number: 5 Date: 1/24/2003 7:23:13 PM Type: Highlight ACCEPT - DONE (this IS the definition of it. Nevertheless, pointed to 4.4.1 the reset overview) 7.8.1 Overview

The statement << link reset sequence. >> should be << link reset sequence (see x.x.x.) >>.

Page: 155 Sequence number: 8 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.8.2 Initiator device specific rules The statement << When this is done after a link reset sequence, this allows the application client within an initiator device to discover all the devices in the SAS domain. When this is done after a BROADCAST (CHANGE), this allows the application client within an initiator device to determine what has changed in the SAS domain. >> should be << If an application client initiates the discover process after a link reset sequence then on completion of the discovery that application client has discovered all the devices within the SAS domain. If the application client initiates the discovery process after a BROADCAST (CHANGE) then on completion of the discovery that application client has discovered any devices that have been removed or inserted into the SAS domain. >> Page: 155 Sequence number: 9 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.8.2 Initiator device specific rules The statement << a routing loop. It shall disable routing >> should be << a routing loop then the application client shall disable routing >> . Page: 155 Sequence number: 10 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.8.2 Initiator device specific rules The statement << function request is used to disable the expander port of an expander device. >> should be << function request shall be used to disable the expander port of an expander device. >> Page: 155 Sequence number: 11 Date: 1/6/2003 6:16:00 PM Type: Square 7.8.5.1 Overview The statements << The SL\_IR state machine sends the following parameters to the SL\_IR transmitter: a) Transmit IDENTIFY; and b) Transmit HARD RESET. The SL\_IR state machine receives the following parameters: a) SOAF Received; b) Data Dword Received; c) EOAF Received; and d) HARD\_RESET Received. >> should be placed in section 7.8.6 as that is where the transmitter and receiver information is defined. That way it is all in one place. Page: 155 Sequence number: 12 Date: 1/24/2003 7:39:31 PM Type: Note ACCEPT - DONE 7.8.5.1 Overview There needs to be an item << c) Transmit Idle Dword >> added to the SL\_IR transmitter list. Page: 155 Sequence number: 13 Date: 1/24/2003 7:38:46 PM Type: Note ACCEPT - DONE 7.8.5.1 Overview There needs to be an items << e) IDENTIFY Transmitted f) HARD\_RESET Transmitted >> add to the SL\_IR receiver list. Page: 156 Sequence number: 8 Date: 1/6/2003 6:16:00 PM Type: Circle Figure 67 Figure 67

The << Enable Disable Link Layer (Disable) >> confirmation needs to point into each of the 3 state machines. The statement << (to all states in all state machines, causing transition to Idle state) >> should be changed to << ((This parameter causes a transition to SL\_IR\_xxx1:Idle) >> replace xxx with TIR, RIF, and IRC on the appropriate arrow.

Page: 156 Sequence number: 9 Date: 1/6/2003 6:16:00 PM Type: Circle Figure 67 Several of the green arrows look like they are originating from other states. They should be shortened to avoid confusion. Page: 156 Sequence number: 10 Date: 1/24/2003 7:41:52 PM Type: Circle ACCEPT - DONE Figure 67 The << Enable Disable SAS Link (Enable) >> should indicate it goes to SL or XL. Page: 157 Sequence number: 5 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.8.6 SL\_IR transmitter and receiver The statement << SOAF/IDENTIFY address frame/EOAF; >> has a problem in that the name of the parameter that causes the transmission is called << Transmit IDENTIFY >>. Those two names are enough different so it is not obvious one is a result of the other. One solution would be to add << (i.e., Transmit IDENTIFY parameter) >> to item b). Page: 157 Sequence number: 6 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.8.6 SL\_IR transmitter and receiver The statement << The SL\_IR receiver shall ignore any primitive received inside an IDENTIFY address frame. In this case, a data dword shall be considered inside a frame when it is received after an SOAF and before an EOAF if the primitive is received after the 8th data dword following the SOAF. >> seems to be confusing. Changing it to the following may help << The SL\_IR receiver shall ignore any primitive received inside an IDENTIFY address frame. In this case, a primitive shall be considered inside a frame when it is received within the first eight data dwords after an SOAF. >> Page: 157 Sequence number: 7 Date: 1/6/2003 6:16:00 PM Type: Note 7.8.6 SL IR transmitter and receiver There needs to be a new paragraph that describes what the SL\_IR receiver receives. Something like << When the SL\_IR receiver receives a dword the SL IR receiver notifies the SL IR state machine of the receipt of those dwords. The following are the only received dwords that the SL IR transmitter shall send notifications on: a) SOAF; b) Data Dword; c) EOAF; or d) HARD\_RESET. >>. Page: 157 Sequence number: 8 Date: 1/6/2003 6:16:00 PM Type: Strikeout 7.8.6.1.1 Overview The statement << This is the only state machine in the SL\_IR state machines that transmits dwords on the physical link. >> Is obvious and not necessary. Page: 157 Sequence number: 9 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.8.6.1.2.1 State description The statement << This state shall repeatedly send Transmit Idle Dword to the SL\_IR transmitter. >> should be << This state shall request idle dwords be transmitted by repeatedly sending a Transmit Idle Dword parameter to the SL\_IR transmitter (see 7.3). >>

Page: 157 Sequence number: 10 Date: 1/24/2003 7:45:48 PM Type: Highlight ACCEPT - DONE 7.8.6.1.2.2 Transition SL\_IR\_TIR1:Idle to SL\_IR\_TIR2:Transmit\_Identify The statement << when both: >> should be changed to << after >>. Page: 157 Sequence number: 11 Date: 1/24/2003 7:45:54 PM Type: Highlight ACCEPT - DONE 7.8.6.1.2.3 Transition SL\_IR\_TIR1:Idle to SL\_IR\_TIR3:Transmit\_Hard\_Reset The statement << when both: >> should be changed to << after >>. Page: 157 Sequence number: 12 Date: 1/24/2003 7:45:09 PM Type: Highlight ACCEPT - DONE 7.8.6.1.3.1 State description The statement << This state shall send a Transmit IDENTIFY parameter to the SL\_IR transmitter. >> should be << Upon entry into this state, this state shall send a Transmit IDENTIFY parameter to the SL\_IR transmitter. >> Page: 158 Sequence number: 2 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.8.6.1.3.2 Transition SL\_IR\_TIR2: Transmit\_Identify to SL\_IR\_TIR4: Completed The statement << This transition shall occur after this state has sent an Identify Transmitted parameter. >> should be << This transition shall occur after: a) receiving a IDENTIFY Transmitted parameter; and b) sending an Identify Transmitted parameter to the IRC state machine. >>. Page: 158 Sequence number: 3 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.8.6.1.3.1 State description The statement << When this state receives >> should be << After this state receives >>. Page: 158 Sequence number: 4 Date: 1/24/2003 7:46:49 PM Type: Highlight ACCEPT - DONE 7.8.6.1.4.1 State description The statement << This state shall send a >> should be << Upon entry into this state, this state shall send a >>. Page: 158 Sequence number: 5 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.8.6.1.4.1 State description The statement << When this state receives >> should be << After this state receives >>. Page: 158 Sequence number: 6 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.8.6.1.4.2 Transition SL\_IR\_TIR3:Transmit\_Hard\_Reset to SL\_IR\_TIR3:Completed The statement << This transition shall occur after sending a HARD\_RESET Transmitted confirmation. >> should be << This transition shall occur after: a) receiving a HARD\_RESET Transmitted parameter; and b) sending a HARD\_RESET Transmitted confirmation to the management application layer. >>.

Date: 1/6/2003 6:16:00 PM Type: Highlight 7.8.6.1.5 SL\_IR\_TIR4:Completed state The statement << This state shall repeatedly send the Transmit Idle Dword parameter to the SL\_IR transmitter. >> should be << This state shall request idle dwords be transmitted by repeatedly sending a Transmit Idle Dword parameter to the SL\_IR transmitter (see 7.3). >> Page: 158 Sequence number: 8 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.8.6.2.2.1 State description The statement << This state waits for an SOAF to be received from the physical link, indicating an address frame is arriving. >> should be << This state waits for an address frame to be received. >> Page: 158 Sequence number: 9 Date: 1/24/2003 7:47:20 PM Type: Highlight ACCEPT - DONE 7.8.6.2.2.2 Transition SL\_IR\_RIF1:Idle to SL\_IR\_RIF2:Receive\_Identify\_Frame The statement << when both: >> should be changed to << after >>. Page: 158 Sequence number: 10 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.8.6.2.3.1 State description The statement << After receiving the frame, it shall check if it is a correct IDENTIFY address frame. >> should be << After receiving the address frame, this state shall check if it is a valid IDENTIFY address frame. >> Page: 158 Sequence number: 11 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.8.6.2.1 Overview The statement << an IDENTIFY address frame from the physical link and checks the IDENTIFY address >> should be << an IDENTIFY address frame and checks that IDENTIFY address >>. Page: 159 Sequence number: 3 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.8.6.2.3.2 Transition SL\_IR\_RIF2:Receive\_Identify\_Frame to SL\_IR\_RIF3:Completed The statement << This transition shall occur after receiving an EOAF and sending the Identify Received parameter or Address Frame Failed confirmation. >> should be << This transition shall occur after: a) receiving an EOAF Received parameter; and b) sending the Identify Received parameter or Address Frame Failed confirmation. >> Page: 159 Sequence number: 4 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.8.6.2.4 SL\_IR\_RIF3:Completed state The statement << This state does nothing except wait for >> should be << This state waits for >>. Page: 159 Sequence number: 5 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.8.6.3.1 Overview The statement << state machines function is to ensure IDENTIFY address >> should be << state machine ensures IDENTIFY address >>. Page: 159 Sequence number: 6 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.8.6.3.2.1 State description

The statement << This state shall >> should be << Upon entry into this state, this state shall: >>

Page: 159 Sequence number: 7 Date: 1/6/2003 6:16:00 PM Type: Note 7.8.6.3.2.1 State description There is not description of when the << Identify Time out >> confirmation is send out. That confirmation is in figure 67 as an output from the SL\_IR\_IRC1 state. This needs to fixed. Page: 160 Sequence number: 7 Date: 1/24/2003 7:48:07 PM Type: Highlight ACCEPT - DONE (removed) 7.10 Near-end analog loopback test This section should be deleted as it causes implantation problems and is of little or no use in real life. Page: 160 Sequence number: 8 Date: 1/6/2003 6:16:00 PM Type: Strikeout 7.8.6.3.3.1 State description The statement << from the Transmit IDENTIFY or HARD\_RESET state machine, >> should be deleted as we do not state were things come from. Page: 160 Sequence number: 9 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.8.6.3.3.1 State description The statement << initialize a receive identify time out >> should be << initialize the receive identify time out >> . Page: 160 Sequence number: 10 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.8.6.3.3.1 State description The statement << time out timer is exceeded, this state shall: >> should be << time out timer times out, this state shall >>. Page: 160 Sequence number: 11 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.8.6.3.3.1 State description The << Identify Sequence Complete >> confirmation is not shown in figure 67. This needs to be fixed. Page: 160 Sequence number: 12 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.8.6.3.3.1 State description The << HARD\_RESET Received >> confirmation is not shown in figure 67. This needs to be fixed. Page: 160 Sequence number: 13 Date: 1/6/2003 6:16:00 PM Type: Highlight The statement << time out timer is exceeded before >> should be << time out timer times out before >> . Page: 160 Sequence number: 14 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.8.6.3.3.2 Transition SL\_IR\_IRC2:Wait to SL\_IR\_IRC3:Completed The statement << This transition shall occur after sending a HARD\_RESET Received confirmation, Identify Timeout confirmation, or Identify Sequence Complete confirmation to the management application layer. >> should be << This transition

shall occur:

a) if an Identify Received parameter and an Identify Transmitter parameter are received, and after sending:

A) an Identify Sequence Complete confirmation to the management application layer;

B) in an expander device, a Broadcast Event Notify (Identification Sequence Complete) confirmation to the expander function; C) a Phy Enabled confirmation to the port layer and the management application layer; and

D) an Enable Disable SAS Link (Enable) parameter to the SL state machine (see 7.13) in initiator devices and target devices or the XL state machine (see 7.14) in expander devices;

b) if a HARD\_RESET Received parameter is received and after sending a HARD\_RESET Received confirmation to the management application layer; or

c) if the identify timer times out and after sending an Identify Timeout confirmation to the management application layer.>>

Page: 160 Sequence number: 15 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.8.6.3.4 SL\_IR\_IRC3:Completed state The statement << This state does nothing except wait for >> should be << This state waits for >>. Page: 160 Sequence number: 16 Date: 1/6/2003 6:16:00 PM Type: Strikeout The statement << SATA interface power management is not supported in SAS. >> should be deleted. For something that is not supported there seems to be a lot of discussion in this section. Page: 160 Sequence number: 17 Date: 1/6/2003 6:16:00 PM Type: Strikeout 7.8.6.3.3.1 State description The statement << from the Receive IDENTIFY Address Frame state machine >> should be deleted as the general rule is that we do not state where things come from in state diagrams. Page: 161 Sequence number: 7 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.11 Domain changes The statement << domain with a discover process (see 4.6.11.5) >> should be << domain using the discover process (see 4.6.11.5) >> Page: 162 Sequence number: 6 Date: 1/6/2003 6:16:00 PM Type: Highlight The statement << communication can begin. >> should be << any communication begins >>. Page: 162 Sequence number: 7 Date: 1/25/2003 4:48:54 PM Type: Highlight 7.12.2.1 Connection request The statement << After transmitting an OPEN address frame, the source phy shall initialize an open time out timer to 1 ms and start the timer. Whenever an AIP is received, the source phy shall reinitialize and restart the timer. Source phys are not required to enforce a limit on the number of AIPs received before abandoning the connection request, but they may do so. When any connection response is received, the source phy shall reinitialize the timer. If the timer expires before a connection response is received, the source phy may assume the destination port does not exist and shall transmit BREAK to abandon the connection request. >> is a duplicate of the information that is in the state machines and should be deleted. Page: 163 Sequence number: 18 Date: 1/25/2003 11:38:31 AM Type: Highlight REJECT (the OPEN address frame is mentioned in the first sentence in this paragraph) 7.12.3 Arbitration fairness The statement << the SCALE bit to one; >> should be << the SCALE bit in the OPEN address frame to one; >>.

Sequence number: 19 Date: 1/25/2003 11:40:24 AM Type: Highlight ACCEPT - DONE (deleted retry delay so this is moot; responses would have been 1) this IS the definition of retry delay 2) it was supposed to be a shall; 3) agree it should be a minimum) 7.12.2.2 Connection request responses The text << the source port shall wait a retry delay of 15 µs before >> has more than one problem. One is that the term retry delay should be defined as a specific time (i.e., retry delay = 15usec) the 15 usec would then be dropped from the text. Or the the statement needs to change to << the source port shall wait 15 µs before >>. The next problem is that this is a shall when it should be a should. The last problem is that there is no tolerance on the value. It should be stated as << shall (should) wait a minimum of 15 us before >>. Page: 163 Sequence number: 20 Date: 1/6/2003 6:16:00 PM Type: Strikeout 7.12.2.2 Connection request responses The term << possible >> should be deleted. Page: 163 Sequence number: 21 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.12.2.2 Connection request responses global The statement << I\_T\_L\_Q >> should be << I\_T\_L\_Q nexus >>. In all cases I\_T, I\_T\_L, and I\_T\_L\_Q should be I\_T nexus, I\_T\_L nexus, and I T L Q nexus. Page: 163 Sequence number: 22 Date: 1/25/2003 11:30:02 AM Type: Highlight ACCEPT - DONE (with which rather than that; it's not a subset) 7.12.3 Arbitration fairness The statement << wait timer counting the >> should be << wait timer that counts the >>. Page: 163 Sequence number: 23 Date: 1/25/2003 11:33:17 AM Type: Highlight ACCEPT - DONE 7.12.3 Arbitration fairness The statement << may be unfair, setting the >> should be << may be unfair by setting the >>. Page: 163 Sequence number: 24 Date: 1/25/2003 11:40:35 AM Type: Highlight ACCEPT - TODO 7.12.3 Arbitration fairness The term <<li>livelocks.>> needs to be added to the glossary. Page: 163 Sequence number: 25 Date: 1/25/2003 11:34:47 AM Type: Strikeout REJECT (a hint that livelocks exist if the AWT is rendered ineffective seems appropriate here) 7.12.3 Arbitration fairness The statement << and helps prevent livelocks. >> should be deleted. Page: 163 Sequence number: 32 Date: 1/25/2003 11:36:12 AM Type: Highlight ACCEPT - DONE (Jan WG remove totally; also removed the single reference to retry delay in the port layer) 7.12.2.2 Connection request responses

The requirement << After receiving an OPEN\_REJECT that indicates a retry may be performed (see table 62), the source port shall wait a retry delay of 15 µs before issuing another connection request to the same destination port. >> should be removed as it only adds needless complexity to targets and initiators. It's also not clear the reason for this requirement as the open/reject functionally will most likely be contained totally in hardware.

Page: 164 Sequence number: 8 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.12.3 Arbitration fairness Note 22 states << of the time a device must wait after receiving OPEN\_REJECT (PATHWAY BLOCKED) >> which has two problems one is the word must is used. If that is changed to a shall which seems logical then problem two occurs in that now you have a requirement in a note which is not allowed. This needs to be fixed. Page: 164 Sequence number: 9 Date: 1/25/2003 11:41:35 AM Type: Highlight REJECT - "by" implies there might be other ways to win arbitration 7.12.3 Arbitration fairness The statement << wins arbitration, receiving either >> should be << wins arbitration by receiving either >>. Page: 164 Sequence number: 10 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.12.3 Arbitration fairness The statement << arbitration request, receiving an OPEN address frame from the destination port with matching PROTOCOL and CONNECTION RATE fields. >> should be << arbitration request if an OPEN address frame from the destination port with matching PROTOCOL and CONNECTION RATE fields was received. >> Page: 164 Sequence number: 11 Date: 1/25/2003 11:42:36 AM Type: Highlight ACCEPT - DONE 7.12.3 Arbitration fairness The statement << values in this order: >> should be << values in the following order: >>. Page: 164 Sequence number: 12 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.12.3.1.1 Arbitration overview The statement << values in this order: >> should be << values in the following order: >>. Page: 165 Sequence number: 3 Date: 1/25/2003 11:44:48 AM Type: Highlight REJECT (SAM has a status called CONDITION MET; what's wrong with that term?) 7.12.3.1.1 Arbitration overview The statement << conditions are met: >> should be << conditions occur >>. Page: 165 Sequence number: 4 Date: 1/25/2003 11:44:40 AM Type: Highlight REJECT (SAM has a status called CONDITION MET; what's wrong with that term?) 7.12.3.1.1 Arbitration overview The statement << conditions are met: >> should be << conditions occur >>. Page: 165 Sequence number: 5 Date: 1/25/2003 11:44:36 AM Type: Highlight REJECT (SAM has a status called CONDITION MET; what's wrong with that term?) 7.12.3.1.1 Arbitration overview

The statement << conditions are met: >> should be << conditions occur >>.

Page: 165 Sequence number: 6 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.12.3.1.1 Arbitration overview The statement << port which contains >> should be << port that contains >>. Page: 165 Sequence number: 7 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.12.3.1.1 Arbitration overview The statement << destination (this case occurs >> should be << destination (i.e., occurs >> Page: 165 Sequence number: 8 Date: 1/25/2003 11:45:04 AM Type: Highlight REJECT (SAM has a status called CONDITION MET; what's wrong with that term?) 7.12.3.1.3 Partial Pathway Timer The statement << conditions are met: >> should be << conditions occur >>. Page: 165 Sequence number: 9 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.12.3.1.3 Partial Pathway Timer The statement << above are not met, the >> should be << above do not occur, the >>. Page: 165 Sequence number: 10 Date: 1/6/2003 6:16:00 PM Type: Strikeout 7.12.3.1.3 Partial Pathway Timer Delete the statement << until reaching zero, >> and place the following statement in this section << The expander connection manager shall stop decrementing the PPT timer when it reaches zero. >>. Page: 165 Sequence number: 11 Date: 1/6/2003 6:16:00 PM Type: Highlight The statement << manager shall hold the PPT timer at an initial value set to the partial pathway time out value. >> does not make sense. This needs to be fixed. Page: 165 Sequence number: 12 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.12.3.1.4 Pathway Recovery The statement << requests in order to prevent deadlock using Pathway Recovery Priority comparisons. >> should be << requests using Pathway Recovery Priority comparisons. >>. Page: 165 Sequence number: 13 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.12.3.1.4 Pathway Recovery The statement << fields within the OPEN >> should be << fields from the OPEN >>. Page: 165 Sequence number: 14 Date: 1/6/2003 6:16:00 PM Type: Strikeout 7.12.3.1.4 Pathway Recovery The statement << as follows: >> should be deleted as there is no list that follows.

Sequence number: 1 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.12.4.1 All expander devices The statement << frame will win >> should be << frame shall will >> or << frame wins >>. Page: 166 Sequence number: 2 Date: 1/6/2003 6:16:00 PM Type: Strikeout 7.12.3.1.4 Pathway Recovery The term << effectively >> should be deleted as it adds nothing. Page: 166 Sequence number: 3 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.12.3.1.4 Pathway Recovery The statement << only with the SOURCE SAS >> should be << only on the SOURCE SAS >>. Page: 166 Sequence number: 4 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.12.4.1 All expander devices In the statement << frame unless it has higher >> it is not clear what the it is referring to. This needs to be fixed. Page: 166 Sequence number: 5 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.12.4.1 All expander devices The statement << three AIPs consecutively >> should be << three consecutive AIPs >>. Page: 166 Sequence number: 6 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.12.4.1 All expander devices The term << immediately >> does not give enough information as to how soon immediately is. This needs to be fixed. Page: 166 Sequence number: 7 Date: 1/17/2003 1:10:00 PM Type: Strikeout ACCEPT - TODO 7.12.4.2 Edge expander devices The statement << this means >> should be deleted. Page: 166 Sequence number: 8 Date: 1/17/2003 1:09:36 PM Type: Highlight ACCEPT - TODO 7.12.4.2 Edge expander devices The statement << When two edge expander >> should be << If two edge expander >>. Page: 166 Sequence number: 9 Date: 1/17/2003 1:09:48 PM Type: Highlight ACCEPT - TODO 7.12.4.2 Edge expander devices The statement << When a fanout expander >> should be << If a fanout expander >>. Page: 167 Sequence number: 4 Date: 1/6/2003 6:16:00 PM

Type: Highlight

7.12.4.3 Fanout expander devices The statement << phys which are >> should be << phys that are >>.

Type: Highlight

Page: 167 Sequence number: 5 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.12.4.3 Fanout expander devices In the statement << it shall compare >> it is not clear what the it is. This needs to be fixed. Page: 167 Sequence number: 6 Date: 1/6/2003 6:16:00 PM Type: Note 7.12.4.3 Fanout expander devices There are a whole bunch of << it >> s in this section where it is not clear what the it is. This needs to be fixed. Page: 167 Sequence number: 7 Date: 1/6/2003 6:16:00 PM Type: Strikeout 7.12.5 Abandoning a connection request The statement << After transmitting BREAK, the source port shall initialize a break time out timer to 1 ms and start the timer. If the timer expires before a break response is received, the source port may assume the physical link is unusable. >> should be deleted as it is duplicated in the state machine descriptions. Page: 167 Sequence number: 8 Date: 1/17/2003 6:22:41 PM Type: Circle ACCEPT - TODO (see MXO comment - switching to ignore) This confirms that the connection request has been abandoned. Table 81 The statement << The BREAK was too late and an open response arrived late. The originator shall honor this as a response to the open request it was attempting to abandon. >> is not clear and the reference to 7.12.2 does not help in understanding this. This needs to be fixed. Page: 167 Sequence number: 9 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.12.5 Abandoning a connection request The statement << the target port. >> should be << the destination port >> as a BREAK can be sent from both targets and initiators . Page: 167 Sequence number: 10 Date: 1/6/2003 6:16:00 PM Type: Strikeout 7.12.5 Abandoning a connection request The term << possible >> should be deleted. Page: 168 Sequence number: 2 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.12.5 Abandoning a connection request The statement << that an open response will not occur. >> should be << that an open response shall not occur >>. Page: 168 Sequence number: 3 Date: 1/6/2003 6:16:00 PM Type: Note Figure 69 The order of the BREAKs in this figure is not clear. They should be numbered in the time order they will occur. Page: 169 Sequence number: 1 Date: 1/25/2003 11:46:04 AM

REJECT - the title is "breaking a connection" 7.12.5 Abandoning a connection request The statement << BREAK to break the connection. >> should be << BREAK to end the connection >>. Page: 169

Sequence number: 2 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.12.6 Breaking a connection The statement << to break a connection, >> should be << to end a connection, >>. Page: 169 Sequence number: 3 Date: 1/6/2003 6:16:00 PM Type: Strikeout 7.12.6 Breaking a connection The term << possible >> should be deleted. Page: 169 Sequence number: 4 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.12.6 Breaking a connection The statement << may be broken as the >> should be ended as the >> Page: 169 Sequence number: 5 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.12.6 Breaking a connection The statement << to a broken connection: >> should be << to a connection that has ended do to a BREAK: >>. Page: 169 Sequence number: 6 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.12.6 Breaking a connection The statement << the broken connection; >> should be << to a connection that has ended do to a BREAK: >>. Page: 169 Sequence number: 7 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.12.6 Breaking a connection The statement << a broken connection >> should be << a connection that has ended do to a BREAK >>. Page: 169 Sequence number: 8 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.12.6 Breaking a connection The statement << a broken connection >> should be << a connection that has ended do to a BREAK >>. Page: 170 Sequence number: 2 Date: 1/6/2003 6:16:00 PM Type: Strikeout 7.12.7 Closing a connection The statement << when the connection was opened. >> does not seem necessary and is unclear. It should be deleted. Page: 170 Sequence number: 3 Date: 1/25/2003 11:46:22 AM Type: Highlight 7.12.7 Closing a connection The statement << If an expander that supports attachment of a SATA target >> should start a new paragraph. [also expander should be expander device]

Sequence number: 4 Date: 1/6/2003 6:16:00 PM Type: Circle Figure 71 It is not at all clear what the purpose of the ACK and RRDY indications from the transmitter is all about. This needs to be fixed. Page: 171 Sequence number: 1 Date: 1/6/2003 6:16:00 PM Type: Strikeout 7.13.1 Overview The statement << from the SL IR state machines >> should be deleted as the general rule is that we do not state where things come from in state diagrams. Page: 171 Sequence number: 2 Date: 1/6/2003 6:16:00 PM Type: Strikeout 7.13.1 Overview The statement << from the SSP, STP, and SMP link layer state machines: >> should be deleted as the general rule is that we do not state where things come from in state diagrams. Page: 171 Sequence number: 3 Date: 1/6/2003 6:16:00 PM Type: Strikeout 7.13.1 Overview The statement << from the SL IR state machines >> should be deleted as the general rule is that we do not state where things come from in state diagrams. Page: 172 Sequence number: 1 Date: 1/6/2003 6:16:00 PM Type: Circle Figure 72 The << Enable Disable Link Layer (Disable) >> confirmation needs to touch the edge of the state machine box. The statement << (to all states in all state machines, causing transition to SL0:Idle) >> should be changed to << (This parameter causes a transition to SL0:Idle) >>. Page: 173 Sequence number: 1 Date: 1/6/2003 6:16:00 PM Type: Note 7.13.2 SL transmitter and receiver There should be a list of inputs and outputs from the SL transmitter listed in this section. Something like this should be added. << The SL state machine sends the following parameters to the SL transmitter: a, b, c list of outputs The SL state machine receives the following parameters from the SL receiver: a, b, c list of inputs Page: 174 Sequence number: 7 Date: 1/17/2003 12:58:35 PM Type: Highlight 7.13.2 SL transmitter and receiver The statement << The SL receiver shall ignore any primitive received inside an OPEN address frame. In this case, a dword shall be considered inside a frame when it is received after an SOAF and before an EOAF if the primitive is received after the 8th data dword following the SOAF. >> seems to be confusing. Changing it to the following may help << The SL receiver shall ignore any primitive received inside an OPEN address frame. In this case, a primitive shall be considered inside a frame when it is received within the first eight data dwords after an SOAF. >> Page: 174 Sequence number: 8 Date: 2/3/2003 3:32:54 PM Type: Highlight ACCEPT - DONE (but paragraph deleted) 7.13.3.1 State description

The statement << SSP Link (Enable) confirmation is received >> should be << SSP Link (Enable) parameter is received >>

Page: 174 Sequence number: 9 Date: 2/3/2003 3:27:33 PM Type: Highlight ACCEPT - DONE (modeled after XL0 wording; dropped "activated" concept) 7.13.3.1 State description The statement << that is used when the SL state machine is activated and there is no active connection >> should be << that is used when the SL state machine is activated and there is no pending or active connection >>. This should be the same wording that is used in the XL0 state description in 7.14.2.1. Page: 174 Sequence number: 10 Date: 2/3/2003 3:34:05 PM Type: Highlight ACCEPT - DONE 7.13.3.1 State description The statement << The SL0:Idle state is the >> should be << This state is the >>. Page: 175 Sequence number: 1 Date: 1/11/2003 5:25:44 PM Type: Highlight ACCEPT - DONE 7.13.4.1 State description The statement << c) If the frame is discarded then no further action is taken by this state relating to the invalid address frame. >> should not have a c). It should just be a sentence. Page: 177 Sequence number: 6 Date: 2/3/2003 3:20:00 PM Type: Highlight ACCEPT - DONE (recast into paragraph rather than a) b) list so "this transition shall occur after" is contiguous) 7.13.5.2 Transition SL2:Selected to SL0:Idle The statement in 1, 2, 3, and 4 << then after this >> should be changed to << and after this >> . This change should make the statements more clear that they are currently. Page: 179 Sequence number: 1 Date: 1/24/2003 7:50:55 PM Type: Highlight REJECT (mentioning both the parent and the two children are important here) 7.14.1 Overview The statement << facilitated by the expander function - specifically the expander connection manager and expander connection router. >> should be << facilitated by the expander connection manager and the expander connection router. >> Page: 180 Sequence number: 3 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.14.1 Overview The statement << The XL state machine shall be activated after the completion of the phy reset sequence by receiving an after receiving an Enable Disable SAS Link (Disable) parameter from the SL\_IR state machines (see 7.8.5). >> should be changed to << The state machine shall start in the XL0:Idle state. The state machine shall transition to the XL0:Idle state from any other state after receiving an Enable Disable SAS Link (Disable) parameter from the SL\_IR state machines (see 7.8.5). >> Page: 180 Sequence number: 4 Date: 1/6/2003 6:16:00 PM Type: Strikeout 7.14.1 Overview The statement << from the expander connection manager: >> should be deleted as the general rule is that we do not state where things come from in state diagrams. Page: 180 Sequence number: 5 Date: 1/6/2003 6:16:00 PM Type: Strikeout 7.14.1 Overview

The statement << from the broadcast primitive processor: >> should be deleted as the general rule is that we do not state where things come from in state diagrams.

Page: 180 Sequence number: 6 Date: 1/6/2003 6:16:00 PM Type: Strikeout 7.14.1 Overview The statement << from the SL\_IR state machine: >> should be deleted as the general rule is that we do not state where things come from in state diagrams. Page: 181 Sequence number: 1 Date: 1/6/2003 6:16:00 PM Type: Circle Figure 74 The << Enable Disable Link Layer (Disable) >> confirmation needs a cut out from the XL state machine and it needs to touch the edge of the state machine box. The statement << (to all states in all state machines, causing transition to XL0:Idle) >> should be changed to << (This parameter causes a transition to XL0:Idle) >>. Page: 182 Sequence number: 1 Date: 1/6/2003 6:16:00 PM Type: Circle Figure 75 The << Enable Disable Link Layer (Disable) >> confirmation needs a cut out from the XL state machine and it needs to touch the edge of the state machine box. The statement << (to all states in all state machines, causing transition to XL0:Idle) >> should be changed to << (This parameter causes a transition to XL0:Idle) >>. Page: 183 Sequence number: 1 Date: 1/6/2003 6:16:00 PM Type: Circle Figure 76 The << Enable Disable Link Layer (Disable) >> confirmation needs a cut out from the XL state machine and it needs to touch the edge of the state machine box. The statement << (to all states in all state machines, causing transition to XL0:Idle) >> should be changed to << (This parameter causes a transition to XL0:Idle) >>. Page: 183 Sequence number: 2 Date: 1/6/2003 6:16:00 PM Type: Note 7.14.2 XL0:Idle state (before this section) There needs to be a section added here they gives the XL transmitter and XL receiver information (i.e., the green arrows). This section would be very similar to 7.13.2 SL transmitter and receiver. Page: 184 Sequence number: 4 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.14.2.1 State description The statement << Otherwise, this state shall repeatedly send a Transmit Idle Dword parameter to the XL transmitter. >> should be << This state shall request idle dwords be transmitted by repeatedly sending a Transmit Idle Dword parameter to the XL transmitter (see 7.3). >> and should be it's own paragraph. Page: 184 Sequence number: 5 Date: 2/3/2003 3:27:12 PM Type: Highlight ACCEPT - DONE (kept as is here) 7.14.2.1 State description The statement << that occurs when there is no pending or active connection >> should be << that is used when the XL state machine is activated and there is no pending or active connection >>. This should be the same wording that is used in the SL0 state description in 7.13.3.1. Page: 184 Sequence number: 6

Date: 1/6/2003 6:16:00 PM Type: Highlight 7.14.2.1 State description The statement << Transmit Broadcast Primitive parameter >> should be << Transmit Broadcast Primitive request >> .

Page: 184 Sequence number: 7 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.14.2.1 State description The statement << this state shall send a Transmit BROADCAST parameter to the XL transmitter. >> should be << this state shall request a BROADCAST be transmitted by sending a Transmit BROADCAST parameter to the XL transmitter. >> Page: 184 Sequence number: 8 Date: 1/6/2003 6:16:00 PM Type: Note 7.14.2 XL0:Idle state There is not description of what occurs when the Enable Disable SAS Link (Enable) parameter is received. This needs to be fixed. Page: 184 Sequence number: 9 Date: 1/6/2003 6:16:00 PM Type: Note 7.14.2 XL0:Idle state There is not description of what causes an Open Address Frame parameter to be sent to the XL5 state. This needs to be fixed. Page: 184 Sequence number: 10 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.14.2.2 Transition XL0:Idle to XL1:Request Path The statement << shall occur when the following conditions are met: >> should be << shall occur if: >>. Page: 184 Sequence number: 11 Date: 1/6/2003 6:16:00 PM Type: Circle 7.14.2.2 Transition XL0:Idle to XL1:Request\_Path The is nothing in figure 74 that shows a Transmit Open or a Transmit Break. This needs to be fixed. Page: 184 Sequence number: 12 Date: 1/6/2003 6:16:00 PM Type: Strikeout 7.14.2.2 Transition XL0:Idle to XL1:Request Path The following should be deleted << from another phy via the expander connection router >> as the general rule is that we do not state where things come from in state diagrams. Page: 184 Sequence number: 13 Date: 1/6/2003 6:16:00 PM Type: Strikeout 7.14.2.2 Transition XL0:Idle to XL1:Request\_Path The following should be deleted << from another phy via the expander connection router >> as the general rule is that we do not state where things come from in state diagrams. Several of the deletions I am suggesting in 7.14 look like they should reference a section that describes the interaction between expander objects Page: 184 Sequence number: 14 Date: 1/6/2003 6:16:00 PM Type: Strikeout 7.14.2.3 Transition XL0:Idle to XL5:Forward Open The following should be deleted << from another phy via the expander connection router >> as the general rule is that we do not state where things come from in state diagrams. Page: 184 Sequence number: 15

Date: 1/6/2003 6:16:00 PM Type: Strikeout 7.14.2.3 Transition XL0:Idle to XL5:Forward\_Open

The following should be deleted << from another XL state machine via the expander connection router >> as the general rule is that we do not state where things come from in state diagrams.

Page: 184 Sequence number: 16 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.14.2.3 Transition XL0:Idle to XL5:Forward\_Open The statement << shall occur when the following conditions are met: >> should be << shall occur if: >>. Page: 184 Sequence number: 17 Date: 1/24/2003 7:52:22 PM Type: Highlight ACCEPT - DONE 7.14.2.4 Transition XL0:Idle to XL9:Break The statement << shall occur when a BREAK Received parameter is received. >> should be << shall occur after receiving a BREAK Received parameter. >> Page: 184 Sequence number: 18 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.14.2.5 Transition XL0:Idle to XL10:Break\_Wait The statement << shall occur when a Transmit Break indication is received from another XL state machine via the expander connection router. >> should be << shall occur after receiving a Transmit Break indication. >>. Page: 184 Sequence number: 19 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.14.3.1 State description The statements << This state shall send the following parameters to the XL transmitter: a) Transmit AIP (WAITING ON PARTIAL) when an Arbitrating (Waiting On Partial) confirmation is received from the expander connection manager; b) Transmit AIP (WAITING ON PARTIAL) when an Arbitrating (Blocked On Partial) confirmation is received from the expander connection manager; c) Transmit AIP (WAITING ON CONNECTION) when an Arbitrating (Waiting On Connection) confirmation is received from the expander connection manager; or d) Transmit AIP (NORMAL). >> should be << This state shall request: a) an AIP (WAITING ON PARTIAL) be transmitted by sending a Transmit AIP (WAITING ON PARTIAL) parameter to the XL transmitter if an Arbitrating (Waiting On Partial) confirmation is received: b)an AIP (WAITING ON PARTIAL) be transmitted by sending a Transmit AIP (WAITING ON PARTIAL) parameter to the XL transmitter if an Arbitrating (WBlocked On Partial) confirmation is received: c)an AIP (WAITING ON CONNECTION) be transmitted by sending a Transmit AIP (WAITING ON CONNECTION) parameter to the XL transmitter if an Arbitrating (Waiting On Connection) confirmation is received; d)an AIP (NORMAL) be transmitted by sending a Transmit AIP(NORMAL) if an ????? is received; Page: 184 Sequence number: 20 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.14.3.1 State description The statement << Request Path request >> should be << Request Path confirmation >>. Page: 185 Sequence number: 3 Date: 1/6/2003 6:16:00 PM Type: Note 7.14.3 XL1:Request\_Path state The way Arbitrating (Block On Partial) is used is not consistent with the way confirmations and parameters are used in the rest of this standard. It is acting more like a signal is this description. This needs to be fixed. There needs to be two arguments; one for Blocked On Partial and another called something like Partial Cleared. The descriptions would then say that the timer starts on Arbitration (Blocked On Partial) and if no Arbitrating (Partial Cleared) is received before the timer timers out then xyz happens.

Page: 185 Sequence number: 4 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.14.3.1 State description The statement << status is conveyed to the expander >> should be << status is sent to the expander >>. Page: 185 Sequence number: 5 Date: 1/6/2003 6:16:00 PM Type: Note 7.14.3 XL1:Request Path state There was no description of the Arb Reject parameter shown in figure 74 in this section. Page: 185 Sequence number: 6 Date: 1/24/2003 7:54:17 PM Type: Strikeout ACCEPT - DONE 7.14.3.2 Transition XL1:Request\_Path to XL2:Request\_Open The following should be deleted << from the expander connection manager. >> should be deleted as the general rule is that we do not state where things come from in state diagrams. Page: 185 Sequence number: 7 Date: 1/24/2003 7:54:22 PM Type: Strikeout ACCEPT - DONE 7.14.3.2 Transition XL1:Request\_Path to XL2:Request\_Open The following should be deleted << from the expander connection manager. >> should be deleted as the general rule is that we do not state where things come from in state diagrams. Page: 185 Sequence number: 8 Date: 1/24/2003 7:54:27 PM Type: Strikeout ACCEPT - DONE 7.14.3.2 Transition XL1:Request\_Path to XL2:Request\_Open The following should be deleted << from the expander connection manager. >> should be deleted as the general rule is that we do not state where things come from in state diagrams. Page: 185 Sequence number: 9 Date: 1/24/2003 7:53:00 PM Type: Circle ACCEPT - DONE 7.14.3.2 Transition XL1:Request\_Path to XL2:Request\_Open 7.14.3.3 Transition XL1:Request Path to XL4:Open Reject 7.14.3.4 Transition XL1:Request Path to XL0:Idle 7.14.3.5 Transition XL1:Request\_Path to XL9:Break The term < when >> should be << after >>. Page: 185 Sequence number: 10 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.14.4.1 State description The statement << This state shall repeatedly send a Transmit Idle Dword parameter to the XL transmitter. >> should be << This state shall request idle dwords be transmitted by repeatedly sending a Transmit Idle Dword parameter to the XL transmitter (see 7.3). >>. Page: 185 Sequence number: 11 Date: 1/6/2003 6:16:00 PM Type: Note 7.14.4 XL2:Request\_Open state The Transmit Idle Dword parameter, the Transmit Open request (?), and Transmit Open indication (?) are missing from figure 75. This needs to be fixed.

Page: 185 Sequence number: 12 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.14.4.1 State description The statement << This state shall send a Transmit >> give no indication as to when this is supposed to happen. I am guessing the statement should be << Upon entry into this state, this state shall send a Transmit >>. Page: 185 Sequence number: 13 Date: 1/6/2003 6:16:00 PM Type: Strikeout 7.14.4.1 State description The statement << received by the destination phy as a Transmit Open indication. >> should be deleted. Page: 185 Sequence number: 14 Date: 1/6/2003 6:16:00 PM Type: Strikeout 7.14.4 XL2:Request\_Open state The statement << Transmit Open request/indication >> should be << Transmit Open request >>. Page: 185 Sequence number: 15 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.14.4.2 Transition XL2:Request\_Open to XL3:Open\_Confirm\_Wait The statement << This transition shall occur after the OPEN address frame has been forwarded to a destination phy. >> should be << This transition shall occur after sending an OPEN address frame transmitted by sending a Transmit OPEN Address Frame parameter to the XL transmitter of a destination phy. >> Page: 185 Sequence number: 16 Date: 1/6/2003 6:16:00 PM Type: Strikeout 7.14.3.1 State description The statement << from the expander connection manager. >> should be deleted as the general rule is that we do not state where things come from in state diagrams. Page: 186 Sequence number: 2 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.14.5.3 Transition XL3:Open\_Confirm\_Wait to XL7:Connected There is no << OPEN\_ACCEPT Transmitted >> parameter in figure 75. Page: 186 Sequence number: 3 Date: 1/6/2003 6:16:00 PM Type: Square 7.14.5.1 State description Most of what is in the following statements should be placed in the section that describe the transitions as the receipt of the various confirmation (if they really are configurations) and parameter cause the state transitions It also needs to be reworded to match the wording used in the other state diagram sections << This state shall send the following parameters to the XL transmitter: a) Transmit AIP (NORMAL) when an Arb Status (Normal) confirmation is received; b) Transmit AIP (WAITING ON PARTIAL) when an Arb Status (Waiting On Partial) confirmation is received; c) Transmit AIP (WAITING ON CONNECTION) when an Arb Status (Waiting On Connection) confirmation is received; d) Transmit AIP (WAITING ON DEVICE) when an Arb Status (Waiting On Device) confirmation is received; e) Transmit OPEN\_ACCEPT when an Open Accept confirmation is received; f) Transmit OPEN\_REJECT when an Open Reject confirmation is received; or g) Transmit Idle Dword when none of the previous conditions are present. This state shall send a Transmit Break request to a destination phy when a BREAK Received parameter is received. >> Page: 186 Sequence number: 4 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.14.5.1 State description The statement << q) Transmit Idle Dword when none of the previous conditions are present. >> should be << This state shall request idle dwords be transmitted by repeatedly sending a Transmit Idle Dword parameter to the XL transmitter (see 7.3). >>.

Page: 186 Sequence number: 5 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.14.5.1 State description The statement << Arb Status (Waiting on Partial) is received, >> should be << Arb Status (Waiting on Partial) request is received, >> Page: 186 Sequence number: 6 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.14.5.1 State description The statement << Otherwise, this state shall send a Phy Status (Partial Pathway) confirmation to the expander connection manager. >> Is not precise in that it gives no information as to when the Phy Status (Partial Pathway) confirmation is to be sent. Page: 186 Sequence number: 7 Date: 1/6/2003 6:16:00 PM Type: Strikeout 7.14.5.2 Transition XL3:Open\_Confirm\_Wait to XL0:Idle The statement << from a destination phy, >> should be deleted. Page: 186 Sequence number: 8 Date: 1/6/2003 6:16:00 PM Type: Strikeout 7.14.5.2 Transition XL3:Open Confirm Wait to XL0:Idle The statement << from a destination phy, >> should be deleted. Page: 186 Sequence number: 9 Date: 1/6/2003 6:16:00 PM Type: Strikeout 7.14.5.2 Transition XL3:Open\_Confirm\_Wait to XL0:Idle The statement << from a destination phy, >> should be deleted. Page: 186 Sequence number: 10 Date: 1/6/2003 6:16:00 PM Type: Strikeout 77.14.5.3 Transition XL3:Open\_Confirm\_Wait to XL7:Connected The statement << from a destination phy, >> should be deleted. Page: 186 Sequence number: 11 Date: 1/6/2003 6:16:00 PM Type: Strikeout 7.14.5.5 Transition XL3:Open\_Confirm\_Wait to XL10:Break\_Wait The statement << from a destination phy, >> should be deleted. Page: 186 Sequence number: 12 Date: 1/6/2003 6:16:00 PM Type: Circle 7.14.5.2 Transition XL3:Open\_Confirm\_Wait to XL0:Idle 7.14.5.3 Transition XL3:Open\_Confirm\_Wait to XL7:Connected According to Figure 75 the term << confirmation >> in these sections should be << request >>. Page: 186 Sequence number: 13 Date: 1/6/2003 6:16:00 PM Type: Circle 7.14.5.2 Transition XL3:Open\_Confirm\_Wait to XL0:Idle There is no parameter in figure 75 that shows anything about << path resources >> being released. This needs to be fixed.

Page: 186 Sequence number: 14 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.14.5.4 Transition XL3:Open\_Confirm\_Wait to XL9:Break The statement << after a BREAK Received parameter is received and a Transmit Break request has been sent to a destination phy. >> should be << after receiving BREAK Received parameter and requesting a BREAK be transmitted by sending a Transmit BREAK parameter to the XL transmitter of a destination phy. >> Page: 186 Sequence number: 15 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.14.5.5 Transition XL3:Open Confirm Wait to XL10:Break Wait The statement << occur when a Transmit Break indication is received >> should be << occur after receiving a Transmit Break request. >>. Page: 186 Sequence number: 16 Date: 1/6/2003 6:16:00 PM Type: Note 7.14.6.1 State description There is no Arb Reject confirmation in figure 74. There is an Arb Reject parameter passed from the XL1 state. But that is not described in the XL1 state. This needs to be fixed. Page: 186 Sequence number: 17 Date: 1/6/2003 6:16:00 PM Type: Note 7.14.6.1 State description Most of what is in the following statements should be placed in the section that describe the transitions as the receipt of the various confirmation (if they really are configurations) and parameter cause the state transitions It also needs to be reworded to match the wording used in the other state diagram sections << This state shall send the following parameters to the XL transmitter: a) Transmit OPEN\_REJECT (NO DESTINATION) when an Arb Reject (No Destination) confirmation is received from the expander connection manager; b) Transmit OPEN\_REJECT (BAD DESTINATION) when an Arb Reject (Bad Destination) confirmation is received from the expander connection manager; c) Transmit OPEN\_REJECT (CONNECTION RATE NOT SUPPORTED) when an Arb Reject (Bad Connection Rate) confirmation is received from the expander connection manager; d) Transmit OPEN\_REJECT (PATHWAY BLOCKED) when an Arb Reject (Pathway Blocked) confirmation is received from the expander connection manager. >> Page: 186 Sequence number: 18 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.14.6.1 State description The statement << This state shall >> should be << This state shall >> Page: 186 Sequence number: 19 Date: 1/6/2003 6:16:00 PM Type: Strikeout 7.14.6.1 State description The statement << from the expander connection manager;>> should be deleted as the general rule is that we do not state where things come from in state diagrams. Page: 186 Sequence number: 20 Date: 1/6/2003 6:16:00 PM Type: Strikeout 7.14.6.1 State description The statement << from the expander connection manager; >> should be deleted as the general rule is that we do not state where things come from in state diagrams. Page: 187 Sequence number: 2 Date: 1/6/2003 6:16:00 PM Type: Note

The is an << Open Address Frame >> parameter and a << Transmit Idle Dword >> parameter in figure 75 for this state that are not

7.14.7 XL5:Forward\_Open state

Page: 187 Sequence number: 3 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.14.7.1 State description The statement << frame indicated by the Transmit Open indication received from a source phy >> does not make any sense. I'm not sure how to fix it but it must be fixed. Page: 187 Sequence number: 4 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.14.7.1 State description There is no << Transmit Open indication >> shown in figure 75. This needs to be fixed. Page: 187 Sequence number: 5 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.14.7.1 State description The statement << This state shall send a Transmit OPEN Address Frame parameter to the XL transmitter with the fields set to the values specified by the >> has some problems. There is no indication as to where or what event causes what is stated to occur. This needs be fixed. Then it needs to be reworded to something like << After (trigger event) this state shall request an OPEN address frame be transmitted by sending a Transmit OPEN Address Frame parameter to the XL transmitter. The Transmit OPEN Address Frame arguments shall be set to the values specified by the Transmit Open indication. >> Page: 187 Sequence number: 6 Date: 1/6/2003 6:16:00 PM Type: Highlight How does this state know when an << OPEN address frame has been transmitted. >> when there are no Open Address Frame Transmitted parameters as inputs? This needs to be fixed. Page: 187 Sequence number: 7 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.14.8.1 State description The statement << This state shall transmit idle dwords. >> >> should be << This state shall request idle dwords be transmitted by repeatedly sending a Transmit Idle Dword parameter to the XL transmitter (see 7.3). >>. Page: 187 Sequence number: 8 Date: 1/6/2003 6:16:00 PM Type: Circle 7.14.8.1 State description There is no OPEN\_ACCEPT or OPEN\_REJECT parameters shown in figure 75. This needs to be corrected. Page: 187 Sequence number: 9 Date: 1/6/2003 6:16:00 PM Type: Square 7.14.8.1 State description Most of what is in the following statements should be placed in the section that describe the transitions as the receipt of the various confirmation (if they really are configurations) and parameter cause the state transitions It also needs to be reworded to match the wording used in the other state diagram sections << This state shall send the following responses through the expander connection router to a source phy, received by the source phy as confirmations: a) Open Accept when OPEN\_ACCEPT is received; b) Open Reject when OPEN\_REJECT is received; c) Backoff Retry when a higher priority OPEN address frame is received (see 7.12.3) and the source SAS address and connection rate of the received OPEN address frame are not equal to the destination SAS address and connection rate of the transmitted OPEN address frame; or d) Backoff Reverse Path when a higher priority OPEN address frame is received (see 7.12.3) and the source SAS address and connection rate of the received OPEN address frame are equal to the destination SAS address and connection rate of the transmitted OPEN address frame.

Page: 187

Sequence number: 10

Date: 1/6/2003 6:16:00 PM

Type: Highlight

7.14.8.1 State description

The statement << This state shall send the following arbitration responses through the expander connection router to a source phy, received by the source phy as confirmations:

a) Arb Status (Waiting On Device) when an AIP Received parameter has not been received;

b) Arb Status (Normal) when an AIP (NORMAL) Received parameter is received;

c) Arb Status (Waiting On Partial) when an AIP (WAITING ON PARTIAL) Received parameter is received;

d) Arb Status (Waiting On Connection) when an AIP (WAITING ON CONNECTION) Received parameter is received; and

e) Arb Status (Waiting On Device) when an AIP (WAITING ON DEVICE) Received parameter is received.

>> should be << This state shall request:

a) an Arb Status (Waiting On Device) be transmitted by sending an Arb Status (Waiting On Device) parameter to the XL transmitter if an AIP Received parameter is not received; >>This gives no indication as to when the parameter that is not received is checked or under what conditions it is considered not received <<

b)an Arb Status (Normal) be transmitted by sending an Arb Status (Normal) parameter to the XL transmitter if an AIP (NORMAL) Received parameter is received;

c)an Arb Status (Waiting On Partial) be transmitted by sending an Arb Status (Waiting On Partial) parameter to the XL transmitter if an AIP (WAITING ON PARTIAL) Received parameter is received;

d)an Arb Status (Waiting On Connection) be transmitted by sending an Arb Status (Waiting On Connection) if an AIP (WAITING ON CONNECTION) Received parameter is received; and

e)an Arb Status (Waiting On Device) be transmitted by sending an Arb Status (Waiting On Device) if an AIP (WAITING ON DEVICE) Received parameter is received. >>.

Page: 187

Sequence number: 11

Date: 1/6/2003 6:16:00 PM

Type: Strikeout

7.14.6.1 State description

The statement << from the expander connection manager; >> should be deleted as the general rule is that we do not state where things come from in state diagrams.

Page: 187

Sequence number: 12

Date: 1/6/2003 6:16:00 PM

Type: Strikeout

7.14.6.1 State description

The statement << from the expander connection manager; >> should be deleted as the general rule is that we do not state where things come from in state diagrams.

Page: 188

Sequence number: 4

Date: 1/6/2003 6:16:00 PM

Type: Highlight

7.14.8.1 State description

The statement << Otherwise, this state shall send a Phy Status (Partial Pathway) confirmation to the expander connection manager. >> Is not precise in that it gives no information as to when the Phy Status (Partial Pathway) confirmation is to be sent.

Page: 188 Sequence number: 5 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.14.8.1 State description The statement << Arb Status (Waiting on Partial) is received, >> should be << Arb Status (Waiting on Partial) request is received, >>

Page: 188 Sequence number: 6 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.14.8.1 State description The statement << This stat

The statement << This state shall send a Transmit Break request to a source phy when a BREAK Received parameter is received. >> needs to be moved into the relevant state transition. And reworded to the standard wording.

Page: 188 Sequence number: 7 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.14.8.2 Transition XL6:Open\_Response\_Wait to XL0:Idle The statement << The XL7:XL0 transition shall occur after one of the following conditions are met: >> should be << This transition shall occur after: >>. Page: 188 Sequence number: 8 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.14.8.2 Transition XL6:Open\_Response\_Wait to XL0:Idle The statement << OPEN REJECT is received. Open Reject response has been sent to a source phy. and path resources have been released: >> should be << an OPEN REJECT is received, and after requesting an Open Reject be transmitted by sending an Open Reject response to the XL transmitter of a source phy and after path resources have been released >> Also, there is nothing in figure 75 that would indicate what parameter is used to determine that << resources have been released >>. Page: 188 Sequence number: 9 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.14.8.2 Transition XL6:Open\_Response\_Wait to XL0:Idle The statement << received OPEN address frame >> should be << received OPEN Address Frame Received parameter >> Page: 188 Sequence number: 10 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.14.8.2 Transition XL6:Open Response Wait to XL0:Idle The statement << a Backoff Retry response has been sent to a source phy, and path resources have been released. >> should be << and after requesting an Backoff Retry be transmitted by sending a Backoff Retry response to the XL transmitter of a source phy and after path resources have been released >> Also, there is nothing in figure 75 that would indicate what parameter is used to determine that << resources have been released >>. Page: 188 Sequence number: 11 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.14.8.3 Transition XL6:Open\_Response\_Wait to XL2:Request\_Open The statement << received OPEN address frame >> should be << received OPEN Address Frame Received parameter >> Page: 188 Sequence number: 12 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.14.8.3 Transition XL6:Open Response Wait to XL2:Request Open The statement << and Backoff Reverse Path response has been sent to a source phy.>> should be << and after requesting a Backoff Reverse Path be transmitted by sending a Backoff Reverse Path response to the XL transmitter of a source phy >> Page: 188 Sequence number: 13 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.14.8.5 Transition XL6:Open\_Response\_ The statement << occur after a BREAK is received and Transmit Break response is sent to a source phy. >> should be << after receiving BREAK Received parameter and requesting a BREAK be transmitted by sending a Transmit BREAK parameter to the XL transmitter of a source phy. >> Page: 188 Sequence number: 14 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.14.8.6 Transition XL6:Open\_Response\_Wait to XL10:Break\_Wait The statement << occur when a Transmit Break indication is received >> should be << occur after receiving a Transmit Break request. >>. Page: 188

Sequence number: 15 Date: 1/6/2003 6:16:00 PM Type: Strikeout

7.14.8.6 Transition XL6:Open\_Response\_Wait to XL10:Break\_Wait The statement << from a source phy. >> should be deleted.

Page: 188 Sequence number: 16 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.14.9.1 State description The statement << This state shall send a Transmit Break request to a connected phy when a BREAK Received parameter is received.. >> needs to be moved into the relevant state transition. And reworded to the standard wording. Page: 188 Sequence number: 17 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.14.9.1 State description The statement << This state shall send a Transmit Close request to a connected phy when a CLOSE Received parameter is received >> needs to be moved into the relevant state transition. And reworded to the standard wording. Page: 188 Sequence number: 18 Date: 1/6/2003 6:16:00 PM Type: Square 7.14.9.1 State description The statements << This state shall transmit all dwords received by the Transmit Dword indication from a connected phy via the expander connection router. This state shall send all valid dwords received by the SAS phy through the expander connection router to a connected phy using the Transmit Dword request with the exception of BREAK and CLOSEes. >> are very confusing. The indications, responses, and parameters need to be more clearly defined as to which cause what action. This needs to be fixed. Page: 188 Sequence number: 19 Date: 1/6/2003 6:16:00 PM Type: Strikeout 7.14.9.2 Transition XL7:Connected to XL8:Close\_Wait The statement << from a connected phy via the expander connection router. >> needs to be deleted. Page: 188 Sequence number: 20 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.14.9.1 State description The statement << Tis transition shall occur when a Transmit Close indication is received >> should be This transition shall occur after receiving a Transmit Close indication and after requesting a Transmit Close be transmitted by sending a Transmit Close parameter to the XL transmitter of a connected phy. >> Page: 188 Sequence number: 21 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.14.9.1 State description The statement << This state shall send a Phy Status (Connected) confirmation to the expander connection manager. >> gives no indication as to what event triggers the confirmation being sent. This needs to be fixed. Page: 189 Sequence number: 1 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.14.9.3 Transition XL7:Connected to XL9:Break The statement << occur when a BREAK Received parameter is received. >> should be << after receiving BREAK Received parameter and requesting a BREAK be transmitted by sending a Transmit BREAK parameter to the XL transmitter. >> Page: 189 Sequence number: 2 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.14.9.4 Transition XL7:Connected to XL10:Break\_Wait The statement << occur when a Transmit Break indication is received >> should be << occur after receiving a Transmit Break

Page: 189 Sequence number: 3 Date: 1/6/2003 6:16:00 PM Type: Strikeout 7.14.9.4 Transition XL7:Connected to XL10:Break\_Wait The statement << from a connected phy via the expander connection router. >> should be deleted. Page: 189 Sequence number: 4 Date: 1/6/2003 6:16:00 PM Type: Strikeout 7.14.10.4 Transition XL8:Close\_Wait to XL10:Break\_Wait The statement << from a connected phy via the expander connection router. >> should be deleted. Page: 189 Sequence number: 5 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.14.10.4 Transition XL8:Close\_Wait to XL10:Break\_Wait The statement << occur when a Transmit Break indication is received >> should be << occur after receiving a Transmit Break request. >> Page: 189 Sequence number: 6 Date: 1/24/2003 7:57:04 PM Type: Highlight ACCEPT - DONE (but it's a Transmit Break request to the internals, not a Transmit Break to the XL transmitter) 7.14.10.3 Transition XL8:Close\_Wait to XL9:Break The statement << occur when a BREAK Received parameter is received. >> should be << after receiving BREAK Received parameter and requesting a BREAK be transmitted by sending a Transmit BREAK parameter to the XL transmitter. >> Page: 189 Sequence number: 7 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.14.10.2 Transition XL8:Close\_Wait to XL0:Idle The statement << after a CLOSE has been both transmitted and received and after path resources have been released for this connection. >> should be << after receiving a Close Received parameter, after requesting a CLOSE be transmitted by sending a Transmit Close to the XL transmitter of a connected phy, and after sending a Transmit Close request to the ???? . The expander device shall transmit the same CLOSE primitive that was received (e.g. CLOSE (NORMAL) forwarded as CLOSE (NORMAL)). >>. Page: 189 Sequence number: 8 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.14.10.1 State description The statement << This state shall send a Transmit Break request to a connected phy when a BREAK Received parameter is received. >> needs to be moved into the relevant state transition. And reworded to the standard wording. Page: 189 Sequence number: 9 Date: 1/6/2003 6:16:00 PM Type: Highlight The statement << This state shall send a Transmit Close request to a connected phy when a CLOSE Received parameter is received. The expander device shall transmit the same CLOSE primitive that was received (e.g. CLOSE (NORMAL) forwarded as CLOSE (NORMAL)). >> needs to be moved into the relevant state transition. And reworded to the standard wording. Page: 189 Sequence number: 10 Date: 1/6/2003 6:16:00 PM Type: Highlight The statement << This state shall send a Transmit >> gives no indication as to when this is supposed to occur. This needs to be fixed.

request. >>.

Page: 189 Sequence number: 11 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.14.10.1 State description The statement << then shall repeatedly send a Transmit Idle Dword parameter to the XL transmitter. >> should be << then this state shall request idle dwords be transmitted by repeatedly sending a Transmit Idle Dword parameter to the XL transmitter (see 7.3). >>. Page: 189 Sequence number: 12 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.14.10.1 State description The statement << This state shall send a Phy Status (Connected) confirmation to the expander connection manager. >> gives no indication as to what event triggers the confirmation being sent. This needs to be fixed. Page: 189 Sequence number: 13 Date: 1/6/2003 6:16:00 PM Type: Square 7.14.10.1 State description The statements << This state shall send all valid dwords received by the SAS phy through the expander connection router to a connected phy using the Transmit Dword request with the exception of BREAK and CLOSEes. >> are very confusing. The indications, responses, and parameters need to be more clearly defined as to which cause what action. This needs to be fixed. Page: 189 Sequence number: 14 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.14.11.1 State description How does this happen? << releases any path resources. >> Page: 189 Sequence number: 15 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.14.11.1 State description The statement << This state shall send a Transmit BREAK parameter to the XL transmitter. >> needs to be moved into the relevant state transition. And reworded to the standard wording. Page: 189 Sequence number: 16 Date: 1/6/2003 6:16:00 PM Type: Highlight The statement << This transition shall occur after transmitting a BREAK. >> should be << This transition shall occur after requesting a BREAK be transmitted by sending a Transmit BREAK parameter to the XL transmitter. >> Page: 189 Sequence number: 17 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.14.12.1 State description How does this happen? << releases any path resources. >> Page: 189 Sequence number: 18 Date: 1/6/2003 6:16:00 PM Type: Highlight The statement << send a Transmit BREAK parameter to the XL transmitter. >> should be << request a BREAK be transmitted by sending a Transmit BREAK parameter to the XL transmitter. Page: 190 Sequence number: 3 Date: 1/25/2003 4:12:38 PM Type: Strikeout ACCEPT - DONE

7.14.12.2 Transition XL10:Break\_Wait to XL0:Idle The statement << whichever occurs first. >> should be deleted.

Page: 190 Sequence number: 4 Date: 2/4/2003 6:23:46 PM Type: Highlight REJECT (paragraph being deleted per Brian Day comment) 7.15 Rate matching The statement << on any potential intermediate physical link. >> should be << on any physical link that makes up any potential pathway >>. Page: 190 Sequence number: 5 Date: 1/6/2003 6:16:00 PM Type: Strikeout 7.15 Rate matching The statement << to reduce EMI. >> should be deleted. As that information is not needed. Page: 190 Sequence number: 6 Date: 2/4/2003 6:31:42 PM Type: Circle REJECT (but redrew figure show the phys are shown left-to-right and the timelines are labeled) Figure 77 This figure would be clearer if the phy-expander-phy boxes where removed and the arrows from the text point to the correct blobs. Page: 190 Sequence number: 7 Date: 2/4/2003 6:28:00 PM Type: Strikeout ACCEPT - DONE 7.15 Rate matching The term << immediately >> should be deleted. Page: 190 Sequence number: 8 Date: 2/4/2003 6:28:31 PM Type: Highlight ACCEPT - DONE (changed to "forwarding") The statement << after seeing an OPEN\_ACCEPT. >> should be << after transmitting (receiving ??) an OPEN\_ACCEPT >>. I'm not sure which is correct but I don't think expanders are going to have eyes that will see things. Page: 190 Sequence number: 9 Date: 2/4/2003 6:30:53 PM Type: Note REVIEW PROTOCOL WG (the OPEN is allowed to have ALIGNs - should we prohibit that?) ACCEPT - DONE (require the first dword after the OPEN address frame be one of the rate matching ALIGNs.) 7.15 Rate matching There is no description about when the source is supposed to start transmitting at the link rate sent in the OPEN. This needs to be specified here. Page: 191 Sequence number: 2 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.16.2 Full duplex The statement << so the DONE (NORMAL) may be followed by RRDYs, ACKs, and NAKs. >> should be << allowing RRDYs, ACKs, and NAK to follow a DONE (NORMAL). >> Page: 191 Sequence number: 3 Date: 1/6/2003 6:16:00 PM Type: Strikeout 7.16.3 SSP frame transmission The statement << The link layer shall check that the number of data dwords between the SOF and EOF is at least 28 bytes and that the CRC is

valid. >> should be deleted as the requirement is contains in the state descriptions.

Page: 191 Sequence number: 4 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.16.4 SSP flow control The statement << An SSP target port or an SSP target/initiator port acting in its target role may refuse to provide credit for any reason, including because it needs to transmit a frame itself. This prevents deadlocks where both ports are waiting on the other to provide credit. >> should be << To prevent deadlocks where both an SSP target port and an SSP initiator port are waiting on the other to provide credit an SSP target port or an SSP target/initiator port acting in its target role may refuse to provide credit for any reason, including because it needs to transmit a frame itself. >> Page: 191 Sequence number: 5 Date: 1/24/2003 7:57:58 PM Type: Highlight ACCEPT - DONE 7.16.4 SSP flow control The statement << be interlocked. >> should be << be interlocked and which shall be non-interlocked >>. Page: 193 Sequence number: 2 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.16.6 Preparing to close an SSP connection The statement << 1 ms; the ACK/NAK count >> should be << 1 ms and as a result the ACK/NAK count >>. Page: 193 Sequence number: 3 Date: 1/22/2003 9:56:19 AM Type: Highlight ACCEPT - DONE 7.16.6 Preparing to close an SSP connection The is a space missing at the end if this sentence << channel.Once a port >>. Page: 193 Sequence number: 4 Date: 1/24/2003 8:04:35 PM Type: Highlight ACCEPT - DONE 7.16.6 Preparing to close an SSP connection I believe the may in the statement << it may close the connection by transmitting the CLOSE >> should be a shall. Page: 194 Sequence number: 6 Date: 1/6/2003 6:16:00 PM Type: Strikeout 7.16.7.1 Overview The statement << from the SL state machine >> should be deleted as the general rule is that we do not state where things come from in state diagrams. Page: 194 Sequence number: 7 Date: 1/6/2003 6:16:00 PM Type: Strikeout 7.16.7.1 Overview The statement << from the SL state machine >> should be deleted as the general rule is that we do not state where things come from in state diagrams. Page: 194 Sequence number: 8 Date: 1/6/2003 6:16:00 PM Type: Strikeout 7.16.7.1 Overview The statement << from the SSP\_D1:DONE\_Wait state >> as the general rule is that we do not state where things come from in state diagrams.

Page: 194 Sequence number: 9 Date: 1/6/2003 6:16:00 PM Type: Strikeout 7.16.7.1 Overview The statement << from the SSP\_D1:DONE\_Wait state >> should be deleted as the general rule is that we do not state where things come from in state diagrams. Page: 197 Sequence number: 3 Date: 2/9/2003 3:39:53 PM Type: Note ACCEPT - TODO 7.16.7 SSP link layer (SSP) state machines There needs to be a section added after figure 84 and before 7.16.7.2 to describe the SSP transmitter and SSP receiver. Something like this needs to be here . << The SSP state machine sends the following parameters to the SSP transmitter: a, b, c list of outputs The SSP state machine receives the following parameters from the SSP receiver: a, b, c list of inputs >> in addition there should be wording like that in section 7.13.2. Page: 199 Sequence number: 6 Date: 1/6/2003 6:16:00 PM Type: Strikeout 7.16.7.5.1 State description The statement << from the port layer >> should be deleted as the general rule is that we do not state where things come from in state diagrams. Page: 199 Sequence number: 7 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.16.7.4.1 State description The statement << A DONE (ACK/NAK TIMEOUT) confirmation informs >> should be << A DONE Received (ACK/NAK TIMEOUT) >>. Page: 200 Sequence number: 8 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.16.7.7.1 State description The statement << that the frame has been >> should be << that the SOF/frame/EOF have been >>. Page: 202 Sequence number: 6 Date: 1/31/2003 6:06:43 PM Type: Strikeout ACCEPT - DONE 7.16.7.11 SSP\_RIM1:Rcv\_Interlock\_Monitor state The statement << from the SSP\_TAN1: Idle state >> should be deleted as the general rule is that we do not state where things come from in state diagrams. Page: 202 Sequence number: 7 Date: 1/31/2003 6:07:05 PM Type: Strikeout ACCEPT - DONE 7.16.7.11 SSP\_RIM1:Rcv\_Interlock\_Monitor state The statement << from the SSP\_RF1:Rcv\_Frame state >> should be deleted as the general rule is that we do not state where things come from in state diagrams. Page: 203 Sequence number: 1 Date: 1/31/2003 6:07:40 PM Type: Strikeout ACCEPT - DONE 7.16.7.14.1 State description The statement << from the SSP\_RF1:Rcv\_Frame state. >> should be deleted as the general rule is that we do not state where

things come from in state diagrams.

Page: 204 Sequence number: 3 Date: 1/10/2003 11:26:48 AM Type: Highlight REJECT (no "translation" is occurring) 7.17.1 STP frame transmission The statement << Table 84 shows a target port transmitting a SATA frame to an expander port. >> should be << Table 84 shows the expander port or STP initiator port translation of a SATA frame or primitive to an STP frame or primitive when the STP frame or primitive is received from a SATA target >>. Page: 204 Sequence number: 4 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.17.1 STP frame transmission The statement << on the path to the STP initiator port solely for the frame. >> should be << on the pathway to the STP initiator port. >>. I don't understand what << solely for the frame >> means. It doesn't seems to imply that every frame requires an open to be transmitted which should not be correct. Page: 204 Sequence number: 5 Date: 1/31/2003 6:05:50 PM Type: Highlight 7.17.1 STP frame transmission The statement << Table 85 shows an STP initiator port transmitting a frame, with the expander device attached to the SATA target port opening a connection solely for the frame. >> should be << Table 85 shows the expander port translation of a STP frame or primitive to an SATA frame or primitive when the STP frame</p> or primitive is received from an STP initiator port or expander port. The STP initiator port opens a connection to an expander port on a pathway to the expander. >> I don't understand what << solely for the frame >> means. It doesn't seems to imply that every frame requires an open to be transmitted which should not be correct. Page: 205 Sequence number: 2 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.17.2 STP flow control The statement << number of dwords it must store in an internal buffer if it can do so without exceeding >> should be << number of dwords it is required to store in an internal buffer if it does so without exceeding >>. Page: 205 Sequence number: 3 Date: 1/6/2003 6:16:00 PM Type: Highlight 7.17.2 STP flow control The statement << during which each expander device must accept incoming data dwords into a buffer. >> should be << during which each expander device shall accept incoming data dwords into a buffer. >>. Page: 205 Sequence number: 4 Date: 1/31/2003 6:05:06 PM Type: Highlight ACCEPT - DONE 7.17.1 STP frame transmission The statement << CLOSE on the expander >> should be << CLOSE at the expander >>. Page: 205 Sequence number: 5 Date: 1/31/2003 6:05:10 PM Type: Highlight ACCEPT - DONE 7.17.1 STP frame transmission The statement << CLOSE on the expander >> should be << CLOSE at the expander >>. Page: 205

Sequence number: 6 Date: 1/31/2003 6:05:36 PM Type: Highlight

ACCEPT - DONE 7.17.1 STP frame transmission The statement << While the connection is open, the expander device is not involved. >> should be << While the connection is open, the expander device passes through all dwords without modification. >> Page: 207 Sequence number: 4 Date: 1/25/2003 11:49:08 AM Type: Highlight REJECT (whole paragraph deleted anyway)(could add a see SATA xref) 7.17.3 Preparing to close an STP connection The term << command-tag queuing >> is not used anywhere else in this document. Either it needs to be defined or deleted. Page: 207 Sequence number: 5 Date: 1/25/2003 11:49:26 AM Type: Highlight REJECT (whole paragraph deleted) 7.17.3 Preparing to close an STP connection The statement << An expander device may issue CLOSE at the end of each frame, after a time out waiting for another frame, after every n frames, after a certain time period, after a SATA\_CONT is detected, after a SATA\_HOLD is detected. >> should be an a,b,c list and needs an << or >> between the last two cases. Page: 208 Sequence number: 3 Date: 2/1/2003 4:34:21 PM Type: Strikeout REJECT (SL to SMP communication froms allowed) 7.18.4.1 Overview The statement << from the SL state machine >> should be deleted as the general rule is that we do not state where things come from in state diagrams. Page: 208 Sequence number: 4 Date: 2/1/2003 4:34:27 PM Type: Strikeout REJECT (SL to SMP communication froms allowed) 7.18.4.1 Overview The statement << from the SL state machine >> should be deleted as the general rule is that we do not state where things come from in state diagrams. Page: 208 Sequence number: 5 Date: 2/1/2003 4:34:34 PM Type: Strikeout REJECT (SL to SMP communication froms allowed) 7.18.4.1 Overview The statement << from the SL state machine >> should be deleted as the general rule is that we do not state where things come from in state diagrams. Page: 208 Sequence number: 6 Date: 1/25/2003 11:54:53 AM Type: Strikeout ACCEPT - DONE 7.18.4.1 Overview The statement << from the SMP\_IL3:Rcv\_response\_Frame state >> should be deleted as the general rule is that we do not state where things come from in state diagrams. Page: 208 Sequence number: 7 Date: 1/25/2003 11:54:57 AM Type: Strikeout ACCEPT - DONE 7.18.4.1 Overview The statement << from the SMP\_IL3:Rcv\_response\_Frame state >> should be deleted as the general rule is that we do not state where things come from in state diagrams.

Page: 208 Sequence number: 8 Date: 1/25/2003 11:55:07 AM Type: Strikeout ACCEPT - DONE 7.18.4.1 Overview The statement << from the SMP\_TL2:Wait\_transmit\_frame state >> should be deleted as the general rule is that we do not state where things come from in state diagrams. Page: 208 Sequence number: 9 Date: 1/25/2003 11:55:02 AM Type: Strikeout ACCEPT - DONE 7.18.4.1 Overview The statement << from the SMP\_TL1:Wait\_originate\_frame state >> should be deleted as the general rule is that we do not state where things come from in state diagrams. Page: 210 Sequence number: 2 Date: 2/1/2003 4:36:17 PM Type: Note ACCEPT - TODO 7.18.4 SMP link layer (SMP) state machines There needs to be a section added after figure 84 and before 7.16.7.2 to describe the SMP transmitter and SMP receiver. Something like this needs to be here . << The SMP state machine sends the following parameters to the SMP transmitter: a. b. c list of outputs The SMP state machine receives the following parameters from the SMP receiver: a, b, c list of inputs >> in addition there should be wording like that in section 7.13.2 Page: 211 Sequence number: 3 Date: 1/25/2003 11:57:35 AM Type: Strikeout ACCEPT - DONE 7.18.4.2.3.1 State description The statement << from the port layer >> should be deleted as the general rule is that we do not state where things come from in state diagrams. Page: 213 Sequence number: 2 Date: 1/6/2003 6:16:00 PM Type: Highlight 8 Port layer This section should be entirely replaced with document 03-024 plus figures. Page: 215 Sequence number: 5 Date: 1/6/2003 6:16:00 PM Type: Highlight 8.3.1 Overview global In some places within this document AWT is used and in other places << arbitration wait timer >> is used. This needs to be made consistent. I vote for fewer acronyms. Page: 216 Sequence number: 11 Date: 1/6/2003 6:16:00 PM Type: Note Figure 91 Some of the text on the arrows needs to be positioned better. For example: the << Phy Enabled >> text entering into PL\_OC1 covers most of the arrow, it is not clear which transition the << (requests to each phy) from the PL\_OC2 is attached to, and the name of the state machine should be across the top as in all the other state diagrams. Page: 217 Sequence number: 4 Date: 1/6/2003 6:16:00 PM Type: Note 8.3.3.1.1 State description overview

I thought all arguments had the first letter of each word capitalized. None of these do. This should be made consistent.

Page: 228 Sequence number: 5 Date: 1/6/2003 6:16:00 PM Type: Highlight ACCEPT - DONE (it's the retransmit bit) Table 88 There is no description of the << TIMEOUT >> bit, This needs to be fixed. Page: 229 Sequence number: 6 Date: 1/6/2003 6:16:00 PM Type: Highlight ACCEPT - DONE Table 89 I thought we outlawed 0 length data frames. I think the IU size for DATA should be 1 to 1 024. Page: 229 Sequence number: 7 Date: 2/2/2003 11:13:54 AM Type: Highlight ACCEPT - DONE (removed sentence; changed Name column to Name of frame; added "frame" after each) 9.2.1 SSP frame format Why not put this information into table 89 << An SSP frame containing a COMMAND information unit (IU) is called a COMMAND frame; an SSP frame containing a TASK IU is called a TASK frame; etc. >> or make it an a,b,c list. But in any case list them all. Page: 229 Sequence number: 8 Date: 1/6/2003 6:16:00 PM Type: Highlight ACCEPT - DONE (the TIMEOUT bit in the table should be this bit) 9.2.1 SSP frame format I don't see any bit named this in table 88. It needs to be added or this paragraph needs to be deleted << The RETRANSMIT bit may be set to one for RESPONSE frames and shall be set to zero for all other frame types. This field indicates the frame is a retransmission after the target port timed out waiting for the ACK or NAK for its previous attempt to transmit the frame. >>. If it stays then the term << field >> in the second sentence needs to be changed to << bit >>. Page: 229 Sequence number: 9 Date: 2/2/2003 11:10:32 AM Type: Highlight **REJECT** (no improvement) 9.2.1 SSP frame format The statement << The TAG field allows the initiator port to establish a context for commands and task management functions. >> should be << The TAG field is an value assigned by the application client and sent to the initiator port in the SCSI command information unit and the task management information unit. The tag is used to establish a context between different commands and different task management functions. >> Page: 229 Sequence number: 10 Date: 1/22/2003 6:07:54 PM Type: Highlight ACCEPT - DONE ("established by the connection".) 9.2.1 SSP frame format The statement << that is unique for the I\_T nexus. >> should be << that is unique for the I\_T nexus defined by the source SAS address and the destination SAS address. >>. Page: 229 Sequence number: 11 Date: 2/2/2003 11:08:31 AM Type: Highlight REJECT (semicolons join related sentences) 9.2.1 SSP frame format The statement << SAM-3; the TAG field >> should be <<SAM-3. The TAG field >>.

Page: 229 Sequence number: 12 Date: 1/6/2003 6:16:00 PM Type: Strikeout ACCEPT - DONE (changed to "more easily". The field is not strictly necessary to establish a context, it's just an assist.) 9.2.1 SSP frame format Delete the term << quickly >> as the is no time reference as to how quick quick is. Page: 229 Sequence number: 13 Date: 1/22/2003 6:05:54 PM Type: Highlight ACCEPT - DONE (overcome by rewrite) 9.2.1 SSP frame format The statement << that need this field >> should be << that use this field >>. Page: 229 Sequence number: 14 Date: 1/6/2003 6:16:00 PM Type: Highlight ACCEPT - DONE 9.2.1 SSP frame format The statement << set a value that is unique for the I\_T nexus. >> should be << set it to a value that is unique for each I\_T nexus. >> Page: 229 Sequence number: 15 Date: 1/22/2003 6:05:41 PM Type: Highlight ACCEPT - DONE (overcome by a rewrite of this paragraph) 9.2.1 SSP frame format The statement << need this field >> should be << use this field >>. Page: 229 Sequence number: 16 Date: 1/6/2003 6:16:00 PM Type: Highlight REJECT - this is the only case; it's not an example, so e.g. is not appropriate. 9.2.1 SSP frame format The statement << frame (due to a >> should be << frame (e.g., due to >>. Page: 229 Sequence number: 27 Date: 1/13/2003 10:23:32 AM Type: Highlight ACCEPT - TODO (per Jan WG: let both initiator and target set it arbitrarily except for XFER\_RDY -> DATA. Use recepient shall ignore wording. No need to say a target not needing it shall use FFFFh - any value is fine.) 9.2.1 SSP frame format The statement <<The target port shall set this field to FFFFh for all frames other than XFER\_RDY frames. >> should be deleted. The tag should have meaning to the target only. The current requirement suggests that the initiator may expect and verify that the tag is FFFFh for non-XFER\_RDY frames. This should not happen. Some targets implementations would prefer to use target port transfer tag to keep track of frames. That makes it easy to associate a frame in an analyzer trace (read data, response, etc.) with a particular command. Page: 230 Sequence number: 5 Date: 1/22/2003 6:16:33 PM Type: Strikeout REJECT (this emphasizes that this layer, the transport layer, is not using the CRC field, even though it shows up in the transport layer data structures.) 9.2.1 SSP frame format The statement << not the transport layer. >> is redundant and should be deleted. Page: 230 Sequence number: 6 Date: 1/6/2003 6:16:00 PM Type: Highlight ACCEPT - DONE 9.2.2.1 COMMAND information unit

The term << performed >> should be << processed >>.

ACCEPT - DONE

Page: 230 Sequence number: 7 Date: 1/6/2003 6:16:00 PM Type: Strikeout REJECT - mirrors wording in SPC-3 9.2.2.1 COMMAND information unit The term << SCSI >> should be deleted as it is redundant with SPC-2. Page: 230 Sequence number: 8 Date: 1/6/2003 6:16:00 PM Type: Highlight ACCEPT - DONE 9.2.2.1 COMMAND information unit The term << specifies >> should be << contains >>. Page: 231 Sequence number: 1 Date: 1/6/2003 6:16:00 PM Type: Highlight ACCEPT - DONE The statement << For example, a six-byte CDB occupies the first six bytes of the CDB field; the remaining ten bytes are reserved and the ADDITIONAL CDB BYTES field is not present. >> should be << (e.g., a six-byte CDB occupies the first six bytes of the CDB field; the remaining ten bytes are reserved and the ADDITIONAL CDB BYTES field is not present). >> Page: 231 Sequence number: 2 Date: 1/6/2003 6:16:00 PM Type: Highlight ACCEPT - DONE 9.2.2.2 TASK information unit The << performed >> should be << processed >>. Page: 232 Sequence number: 1 Date: 1/6/2003 6:16:00 PM Type: Highlight ACCEPT - DONE 9.2.2.2 TASK information unit The term << specifies >> should be << contains >>. Page: 232 Sequence number: 2 Date: 1/6/2003 6:16:00 PM Type: Strikeout REJECT - the reference should be SAM-3 not SPC-2, and the SCSI wording is copied from SPC-2/3. 9.2.2.2 TASK information unit The term << SCSI >> should be deleted as it is redundant with SPC-2. Page: 232 Sequence number: 3 Date: 1/22/2003 6:20:05 PM Type: Highlight ACCEPT - DONE (changed to "set to the value of the [xyz] field") Table 93 global In the description column there are several cases where small caps is used when they should not be. Small caps should only be used when referencing the name of a field not the contains of the field. For example << The task manager shall perform the ABORT TASK SET task management function with L set to LOGICAL UNIT NUMBER >>> should be << The task manager shall perform the ABORT TASK SET task management function with L set to logical unit number >> . Page: 232 Sequence number: 4 Date: 1/6/2003 6:16:00 PM Type: Highlight

9.2.2.2 TASK information unit The statement << The TARGET RESET task management function defined in SAM-3 is not supported. >> should be a footnote in table 91.

Page: 233 Sequence number: 6 Date: 2/2/2003 12:11:10 PM Type: Highlight ACCEPT - DONE 9.2.2.3 XFER\_RDY information unit The term << indicates >> should be << contains >>. Page: 233 Sequence number: 7 Date: 2/2/2003 12:41:27 PM Type: Highlight **REVIEW EDITORS WG** ACCEPT - DONE (changed to "contains...app client buffer offset of the segment of write data") 9.2.2.3 XFER\_RDY information unit The statement << initial application client buffer offset of the write data >> implies that all XFER\_RDYs for a given I\_T\_L\_Q nexus will have the same value. That does not seem right. Is it? Page: 233 Sequence number: 8 Date: 1/6/2003 6:16:00 PM Type: Strikeout REJECT - don't want it to sound like data is just transferred, either. There is not an e.g. here implying DATA frames are one possible option. 9.2.2.3 XFER RDY information unit The statement << (using DATA frames). >> seems redundant and could be interpreted to means that there is another way to to move data besides DATA frames. Page: 233 Sequence number: 9 Date: 1/6/2003 6:16:00 PM Type: Highlight ACCEPT - DONE (changed "indicates how many" to "contains the number of") 9.2.2.3 XFER\_RDY information unit The term << indicates >> should be << contains >>. Page: 233 Sequence number: 10 Date: 1/6/2003 6:16:00 PM Type: Strikeout **REJECT** - see nearby same comment 9.2.2.3 XFER RDY information unit The statement << (using DATA frames). >> seems redundant and could be interpreted to means that there is another way to to move data besides DATA frames. Page: 233 Sequence number: 11 Date: 1/22/2003 6:21:25 PM Type: Highlight ACCEPT - DONE 9.2.2.3 XFER\_RDY information unit The paragraph << The initial XFER\_RDY frame for a given command shall set the relative offset to the value of the FIRST BURST SIZE field in the Disconnect-Reconnect mode page (see 10.1.1.1.5). If any additional XFER\_RDY frames are required, the RELATIVE OFFSET field shall be set to the value of the previous XFER RDY frames relative offset plus the previous XFER RDY frames write data length. >> need to move up under the relative offset field paragraph. Page: 233 Sequence number: 12 Date: 1/22/2003 6:20:30 PM Type: Highlight ACCEPT - DONE (Requested Offset) Table 94

The field name << RELATIVE OFFSET >> is a problem because when this table is combined with the header information (in table 88) you then have two fields with exactly the same name. So things get confusing real fast. I recommend changing the name of the

Page: 234 Sequence number: 2 Date: 1/6/2003 6:16:00 PM Type: Highlight **REVIEW EDITORS WG** ACCEPT - DONE (they're synonyms - what's wrong with constrained?) 9.2.2.4 DATA information unit The statement << constrained by >> should be << limited to >>. Page: 234 Sequence number: 3 Date: 1/6/2003 6:16:00 PM Type: Highlight REJECT - this makes it sound like just the value is important, when the association to a specific XFER\_RDY frame is the key point 9.2.2.4 DATA information unit The statement << The DATA frame shall only contain write data for a single XFER\_RDY frame. >> should be << The DATA frame shall contain no more write data than was indicated in the WRITE DATA LENGTH field of a single XFER\_RDY frame. >>. Page: 235 Sequence number: 1 Date: 1/6/2003 6:16:00 PM Type: Strikeout REJECT - but replaced with field names (see Intel comment) 9.2.2.5.1 RESPONSE information unit overview This should be deleted << which defines the format and content of the response IU. >> as this information is in the table. Page: 235 Sequence number: 2 Date: 1/6/2003 6:16:00 PM Type: Highlight ACCEPT - DONE 9.2.2.5.1 RESPONSE information unit overview The statement << and if an error occurs >> should be << and in response to any errors that occur >>. Page: 236 Sequence number: 2 Date: 1/6/2003 6:16:00 PM Type: Strikeout ACCEPT - DONE 9.2.2.5.3 RESPONSE information unit RESPONSE\_DATA format The term << certain >> should be deleted as it add a level in uncertainty to the standard. Page: 237 Sequence number: 1 Date: 1/14/2003 11:19:02 AM Type: Highlight ACCEPT - DONE (Jan WG: The sense data list length field shall not be larger than 1000 (see table 89).) 9.2.2.5.4 RESPONSE information unit SENSE\_DATA format This seems like a strange value to pick << than 1 000 and shall >> why not 1024? Unless there is some reason it should be changed to 1 024. Page: 237 Sequence number: 2 Date: 1/6/2003 6:16:00 PM Type: Highlight ACCEPT - DONE 9.2.3 Frame sequences The statement << sequence. The transport protocol services (see 10.1.1) invoked by the application layer are also shown. >> should be << sequence and the transport protocol services (see 10.1.1) invoked by the application layer. >>. Page: 237 Sequence number: 3 Date: 1/16/2003 7:48:31 PM Type: Note ACCEPT - DONE (with frame rather than IU) Figures 94 - 97 Put the term << IU >> after all the IU names (e.g., TASK IU, RESPONSE IU).

Page: 237 Sequence number: 4 Date: 1/22/2003 6:39:08 PM Type: Note ACCEPT - DONE (also mention that connections may come and go at any time) 9.2.3 Frame sequences Somewhere in this section there should be a paragraph that states the following : - that commands can be sent any time. - When commands are queued data may be transferred for any command at any time. - Responses may be returned in any order. Page: 238 Sequence number: 1 Date: 1/6/2003 6:16:00 PM Type: Highlight ACCEPT - DONE 9.2.3 Frame sequences The statement << sequence. The transport protocol services (see 10.1.1) invoked by the application layer are also shown. >> should be << sequence and the transport protocol services (see 10.1.1) invoked by the application layer. >>. Page: 238 Sequence number: 2 Date: 1/6/2003 6:16:00 PM Type: Highlight ACCEPT - DONE 9.2.3 Frame sequences The statement << sequence. The transport protocol services (see 10.1.1) invoked by the application layer are also shown. >> should be << sequence and the transport protocol services (see 10.1.1) invoked by the application layer. >>. Page: 239 Sequence number: 2 Date: 1/6/2003 6:16:00 PM Type: Highlight ACCEPT - DONE 9.2.3 Frame sequences The statement << sequence. The transport protocol services (see 10.1.1) invoked by the application layer are also shown. >> should be << sequence and the transport protocol services (see 10.1.1) invoked by the application layer. >>. Page: 239 Sequence number: 3 Date: 1/6/2003 6:16:00 PM Type: Highlight ACCEPT - DONE (changed to 'times out waiting for") 9.2.4.3 XFER RDY frame The statement << and does not receive an ACK or NAK, it shall close >> should be << and times out waiting for ACK or NAK it shall close >>. Page: 240 Sequence number: 3 Date: 1/6/2003 6:16:00 PM Type: Highlight ACCEPT - DONE (changed to 'times out waiting for") 9.2.4.4 DATA frame The statement << and does not receive an ACK or NAK, it shall close >> should be << and times out waiting for ACK or NAK it shall close >>. Page: 240 Sequence number: 4 Date: 1/6/2003 6:16:00 PM Type: Highlight ACCEPT - DONE (changed to 'times out waiting for") 9.2.4.4 DATA frame The statement << and does not receive an ACK or NAK, it shall abort >> should be << and times out waiting for ACK or NAK it shall abort >> Page: 240

Sequence number: 5

Date: 1/6/2003 6:16:00 PM Type: Highlight ACCEPT - DONE 9.2.4.5 RESPONSE frame There is no bit named << RETRANSMIT bit >> in the SSP frame. This needs to be fixed. Page: 240 Sequence number: 6 Date: 1/6/2003 6:16:00 PM Type: Highlight ACCEPT - DONE 9.2.4.5 RESPONSE frame The statement << RETRANSMIT bit of one, and it >> should be << RETRANSMIT bit set to one, and it >> Page: 241 Sequence number: 1 Date: 1/6/2003 6:16:00 PM Type: Highlight ACCEPT - DONE 9.2.5.2 Initiator port error handling The statement << is not twelve bytes long, >> should be << is not 12 bytes long, >>. Page: 241 Sequence number: 2 Date: 1/16/2003 8:03:14 PM Type: Note REJECT - remain silent (initiator handling of bizarre errors need not be specified) 9.2.5.2 Initiator port error handling The last three paragraphs all need a statement about what the initiator does if it does receive a RESPONSE. I believe << discard it >> is the right answer but it needs to be stated. Page: 242 Sequence number: 1 Date: 1/6/2003 6:16:00 PM Type: Highlight ACCEPT - DONE 9.2.6.1 Overview The statement << SSP transport layer contains state >> should be << SSP transport layer (ST) contains state >>. Page: 242 Sequence number: 2 Date: 1/6/2003 6:16:00 PM Type: Highlight REJECT The statement << perform the following functions: >> should be << run in parallel to: >>. Page: 242 Sequence number: 3 Date: 1/6/2003 6:16:00 PM Type: Strikeout REJECT 9.2.6.2.1 Overview The statement << (initiator send frame) >> should be deleted. Page: 242 Sequence number: 4 Date: 1/6/2003 6:16:00 PM Type: Strikeout REJECT 9.2.6.2.1 Overview The statement << (initiator process response) >> should be deleted. Page: 242 Sequence number: 5 Date: 2/8/2003 2:09:52 PM Type: Strikeout ACCEPT - DONE 9.2.6.2.1 Overview The statement << (initiator process response) >> should be deleted.

Page: 242 Sequence number: 6 Date: 2/8/2003 2:12:47 PM Type: Strikeout ACCEPT - DONE 9.2.6.2.1 Overview The statement << (initiator send frame) >> should be deleted. Page: 242 Sequence number: 7 Date: 1/6/2003 6:16:00 PM Type: Strikeout ACCEPT - DONE 9.2.6.2.1 Overview The statement << (initiator send frame) >> should be deleted. Page: 242 Sequence number: 8 Date: 2/8/2003 2:12:38 PM Type: Strikeout REJECT 9.2.6.2.1 Overview The statement << (initiator receive data) >> should be deleted. Page: 242 Sequence number: 9 Date: 2/8/2003 2:12:09 PM Type: Strikeout ACCEPT - DONE 9.2.6.2.1 Overview The statement << (initiator frame router) >> should be deleted. Page: 242 Sequence number: 10 Date: 2/8/2003 2:12:01 PM Type: Strikeout ACCEPT - DONE 9.2.6.2.1 Overview The statement << (initiator frame router) >> should be deleted. Page: 242 Sequence number: 11 Date: 2/8/2003 2:11:29 PM Type: Strikeout ACCEPT - DONE 9.2.6.2.1 Overview The statement << (initiator frame router) >> should be deleted. Page: 242 Sequence number: 12 Date: 1/6/2003 6:16:00 PM Type: Strikeout REJECT 9.2.6.2.1 Overview The statement << (initiator frame router) >> should be deleted. Page: 242 Sequence number: 13 Date: 2/8/2003 2:09:21 PM Type: Strikeout REJECT 9.2.6.2.1 Overview The statement << from the SCSI initiator devices application layer, >> should be deleted as we do not indicate where things come from only where they go to. Page: 242

Sequence number: 14 Date: 2/8/2003 2:09:37 PM Type: Strikeout REJECT 9.2.6.2.1 Overview The statement << from the ST\_IFR (initiator frame router) state machine >> should be deleted as we do not indicate where things come from only where they go to. Page: 242 Sequence number: 15 Date: 2/8/2003 2:10:30 PM Type: Strikeout REJECT 9.2.6.2.1 Overview The statement << from the ST\_IFR (initiator frame router) state machine >> should be deleted as we do not indicate where things come from only where they go to. Page: 242 Sequence number: 16 Date: 2/8/2003 2:10:38 PM Type: Strikeout REJECT 9.2.6.2.1 Overview The statement << from the ST\_IFR (initiator frame router) state machine >> should be deleted as we do not indicate where things come from only where they go to. Page: 242 Sequence number: 17 Date: 2/8/2003 2:10:45 PM Type: Strikeout REJECT 9.2.6.2.1 Overview The statement << from the ST ISF (initiator send frame) state machine. >> should be deleted as we do not indicate where things come from only where they go to. Page: 242 Sequence number: 18 Date: 2/8/2003 2:11:17 PM Type: Strikeout REJECT (but dropped "state machine") 9.2.6.2.1 Overview The statement << from the port layer state machine >> should be deleted as we do not indicate where things come from only where they go to. Page: 242 Sequence number: 19 Date: 2/8/2003 12:36:20 PM Type: Highlight ACCEPT - DONE 9.2.6 SSP transport layer state machines global in 9.2.6 The term << port layer state machines >> should in most if not all cases be << port layer >>. Page: 243 Sequence number: 2 Date: 1/6/2003 6:16:00 PM Type: Strikeout ACCEPT - DONE 9.2.6.2.1 Overview The statement << (initiator process response) >> should be deleted. Page: 243 Sequence number: 3 Date: 1/6/2003 6:16:00 PM Type: Strikeout ACCEPT - DONE 9.2.6.2.1 Overview The statement << (initiator receive data) >> should be deleted.

Page: 243 Sequence number: 4 Date: 2/8/2003 2:16:53 PM Type: Strikeout **REJECT** (but deleted state machine) 9.2.6.2.1 Overview The statement << from the port layer state machine. >> should be deleted as we do not indicate where things come from only where they go to. Page: 243 Sequence number: 5 Date: 2/8/2003 2:15:07 PM Type: Strikeout REJECT 9.2.6.2.1 Overview The statement << from the SCSI initiator device's application layer >> should be deleted as we do not indicate where things come from only where they go to. Page: 244 Sequence number: 8 Date: 1/6/2003 6:16:00 PM Type: Highlight ACCEPT - DONE 9.2.6.2.1 Overview The term << describes >> should be << shows >>. Page: 244 Sequence number: 9 Date: 2/8/2003 2:18:47 PM Type: Square REJECT (that's what SAM-3 calls it, and Ralph rejected suggestions to rename the protocol services) Figure 98 The term << Request >> should be deleted from the << Send Task Management Request >> Page: 245 Sequence number: 2 Date: 2/9/2003 12:29:53 PM Type: Strikeout REJECT (paragraph deleted) 9.2.6.2.2.1 State description The statement << from the SCSI initiator device's application layer >> should be deleted. Page: 245 Sequence number: 3 Date: 2/9/2003 12:29:38 PM Type: Strikeout **REJECT** (paragraph deleted) 9.2.6.2.2.1 State description The statement << from the ST IFR (initiator frame router) state machine. >> should be deleted. Page: 245 Sequence number: 4 Date: 2/9/2003 12:29:14 PM Type: Strikeout REJECT (kept something similar as paragraph moved to ST\_ISF overview section) 9.2.6.2.2.1 State description The statement << from the ST\_ISF2:Prepare\_Command\_Request state, >> should be deleted. Page: 245 Sequence number: 5 Date: 2/9/2003 12:29:22 PM Type: Strikeout REJECT (kept something similar as paragraph moved to ST\_ISF overview section) 9.2.6.2.2.1 State description The statement << from the ST\_ISF3:Prepare\_Send\_Data\_Out state. >> should be deleted. Page: 245 Sequence number: 6 Date: 2/8/2003 2:48:52 PM

Type: Square

TODO ACCEPT - DONE (movement done; TODO on activate wording) 9.2.6.2.2.1 State description The paragraph <<The ST\_ISF state machine shall be initiated when a Send SCSI Command or a Send Task Management Request transport protocol service request is received from the SCSI initiator device's application layer or when an XFER\_RDY Arrived parameter is received from the ST\_IFR (initiator frame router) state machine. >> does not belong here. It should be part of the overview for the state machine. This is only supposed to be information about the state not the state machine. And should be changed to << The ST\_ISF state machine shall be activated when a Send SCSI Command or a Send Task Management Request transport protocol service request is received or when an XFER\_RDY Arrived parameter is received. >> Page: 245 Sequence number: 7 Date: 2/9/2003 12:28:39 PM Type: Square ACCEPT - DONE 9.2.6.2.2.1 State description The paragraph <<This state shall be entered when either a COMMAND or TASK frame is received from theST\_ISF2:Prepare\_Command\_Request state, or when a DATA frame is received from the ST\_ISF3:Prepare\_Send\_Data\_Out state. >> should be << This state is the initial state and is the state that is used after the ST\_ISF state machine has been activated. >> Page: 245 Sequence number: 8 Date: 2/8/2003 2:59:17 PM Type: Highlight ACCEPT - DONE 9.2.6.2.2.1 State description The statement << A Send SCSI Command or a Send Task Management Request transport protocol service request includes the following to be used >> should be << A Send SCSI Command transport protocol service request or a Send Task Management protocol service request includes the following to be used >> Page: 245 Sequence number: 9 Date: 2/3/2003 3:04:53 PM Type: Highlight REJECT (whole sentence being deleted) 9.2.6.2.2.1 State description The statement << The request may >> should be << The transport protocol service request may >>. Page: 245 Sequence number: 10 Date: 2/8/2003 2:59:38 PM Type: Highlight REJECT 9.2.6.2.2.1 State description It looks like the term << request: >> should be << transport protocol service request >> in all cases in this section. This needs to be fixed. Page: 245 Sequence number: 11 Date: 2/9/2003 12:26:53 PM Type: Highlight ACCEPT - DONE (already in transition, so just deleted this) 9.2.6.2.2.1 State description The statement << If the ST\_ISF state machine was initiated as the result of receiving a transport protocol service request, then this state shall transition to the ST\_ISF2:Prepare\_Command\_Request state.>> belongs in the transition description not here.

Page: 245 Sequence number: 12 Date: 2/9/2003 12:25:08 PM Type: Note REJECT 9.2.6.2.2.1 State description The term << initiated >> should be << activated >> in this section.

Page: 245 Sequence number: 13 Date: 1/13/2003 6:56:59 PM Type: Note ACCEPT - TODO (upgrade to a shall to match 10.1.3 and 9.2.5.2) 9.2.6.2.2.1 State description I don't like the mays in item a) and item b). Why is this a may instead of a shall? Page: 246 Sequence number: 2 Date: 2/2/2003 3:34:26 PM Type: Strikeout ACCEPT - DONE 9.2.6.2.2.1 State description The statement << from the port layer state machine. >> should be deleted. Page: 246 Sequence number: 3 Date: 2/9/2003 12:32:18 PM Type: Square ACCEPT - DONE (merged 12 byte check and wriet data length check into transition) 9.2.6.2.2.1 State description The statement << e) If the length of the XFER\_RDY frame is 12 bytes, the write data length is correct, and an ACK Transmitted confirmation has been received, then this state shall transition to theST\_ISF3:Prepare\_Send\_Data\_Out state. >> belongs in the transition description. It should be moved there. Page: 246 Sequence number: 4 Date: 2/9/2003 12:32:53 PM Type: Highlight REJECT 9.2.6.2.2.1 State description The statement << If this state is entered from the ST ISF2:Prepare Command Request state, then this state shall send a Transmit Frame (Interlocked) request to the port layer state machine. >> should be << Upon entry into this state from the ST\_ISF2:Prepare\_Command\_Request state, this state shall send a Transmit Frame (Interlocked) request to the port layer state machine. >> Page: 246 Sequence number: 5 Date: 2/9/2003 12:32:59 PM Type: Highlight REJECT 9.2.6.2.2.1 State description The statement << If this state is entered from the ST\_ISF3:Prepare\_Send\_Data\_Out state, then this state shall send a Transmit Frame (Non-interlocked) request to the port layer state machine. >> should be << Upon entry into this state from the ST\_ISF3:Prepare\_Send\_Data\_Out state, this state shall send a Transmit Frame (Non-Interlocked) request to the port layer state machine. >> Page: 246 Sequence number: 6 Date: 2/9/2003 12:33:23 PM Type: Strikeout ACCEPT - DONE 9.2.6.2.2.1 State description The statement << from this state >> should be deleted. Page: 246 Sequence number: 7 Date: 2/9/2003 12:33:38 PM Type: Strikeout ACCEPT - DONE 9.2.6.2.2.1 State description The statement << (initiator process response) >> should be deleted. Page: 246 Sequence number: 8 Date: 2/9/2003 12:34:27 PM Type: Highlight ACCEPT - DONE 9.2.6.2.2.1 State description The statement << After sending a Transmit Frame request this state shall wait for a Transmission Status confirmation. If the

confirmation is not Transmission Status (Frame Transmitted), >> should be << After sending a Transmit Frame request to the port layer this state shall wait for a Transmission Status confirmation. If the confirmation is not Transmission Status (Frame Transmitted) confirmation, >>

Page: 246 Sequence number: 9 Date: 2/9/2003 12:34:55 PM Type: Square REJECT (terminate is fine. Putting it here is fine; it's something that happens in this state.) 9.2.6.2.2.1 State description The statement << After sending a Delivery Failure parameter to the ST IPR state machine, the ST ISF state machine shall terminate. >> does not belong here. It should be part of the overview for the state machine. This is only supposed to be information about the state not the state machine. It should also be reword to remove the << terminate >> term. Maybe stopped or removed or deactivated. Page: 246 Sequence number: 10 Date: 2/9/2003 12:35:58 PM Type: Highlight ACCEPT - DONE (changed to shall... if there is more data to transfer. Vague but accurate.) 9.2.6.2.2.1 State description The may in the statement << If the transmitted frame was a DATA frame, then this state may transition to the >> seems like there should be more description. The transition either occurs or it does not occur. Also this whole paragraph should be down in the transition section. This needs to be fixed. Page: 246 Sequence number: 11 Date: 2/9/2003 12:37:25 PM Type: Square ACCEPT (deleted the first one. The text kind of implies termination for different reasons, but we'll assume that sequencing is unimportant for these rules) 9.2.6.2.2.1 State description The statement << After sending a Delivery Failure parameter to the ST\_IPR state machine, the ST\_ISF state machine shall terminate. >> is a duplicate of what is stated just above and does not belong here. It should be in the state machine overview. Page: 246 Sequence number: 12 Date: 2/9/2003 12:38:15 PM Type: Highlight REJECT (it's up to this layer to decide to cancel a request for whatever reason. SAM doesn't describe timeouts (yet) in its Execute Command model.) 9.2.6.2.2.1 State description The may in the statement <<This state may also send a Cancel request to the port layer state >> seems like there should be more description. The transition either occurs or it does not occur. Page: 246 Sequence number: 13 Date: 2/9/2003 12:38:30 PM Type: Highlight REJECT (only happens in this state) 9.2.6.2.2.1 State description The statement << The ST\_ISF state machine shall terminate upon receipt of a Cancel Acknowledge confirmation. >> does not belong here. It should be in the state machine overview. Page: 246 Sequence number: 14 Date: 2/9/2003 12:39:01 PM Type: Highlight ACCEPT - DONE 9.2.6.2.2.2 Transition ST ISF1:Send Frame to ST ISF2:Prepare Command Request The statement << occur after a Send SCSI Command or Send Task Management Request transport protocol service request has been received. >> should be << occur after receiving a Send SCSI Command or Send Task Management Request transport protocol service request. >>. Page: 247

Sequence number: 7 Date: 2/9/2003 11:04:33 AM Type: Highlight ACCEPT - DONE (changed some ands to ifs too) 9.2.6.2.2.3 Transition ST\_ISF1:Send\_Frame to ST\_ISF3:Prepare\_Send\_Data\_Out The statement << a) an ACK Received confirmation has been received for a COMMAND frame for a data-out operation and the first burst size is not zero; b) an XFER\_RDY Arrived parameter has been received, all required values are present and correct, and an ACK Transmitted confirmation has been received; or c) a Transmission Status (Frame Transmitted) confirmation for a Transmit Frame (Non-interlocked) request has been received and the number of data bytes that has been transmitted for the request is less than the first burst size or the write data length. >> should be << a) receiving an ACK Received confirmation for a COMMAND frame for a data-out operation if the first burst size is not zero:</p> b) receiving an XFER\_RDY Arrived parameter with all required values present and correct, and after receiving an ACK Transmitted confirmation; or c) receiving a Transmission Status (Frame Transmitted) confirmation for a Transmit Frame (Non-interlocked) request if the number of data bytes that has been transmitted for the Transmit Frame (Non-interlocked) request is less than the first burst size or the write data length. >> Page: 247 Sequence number: 8 Date: 2/9/2003 11:05:03 AM Type: Strikeout REJECT (important to say where the values came from) 9.2.6.2.3.1 State description The statement << received from the SCSI initiator device's application layer >> should be deleted. Page: 247 Sequence number: 9 Date: 2/9/2003 11:05:17 AM Type: Strikeout REJECT (important to say where they came from) 9.2.6.2.3.1 State description The statement << received from the SCSI initiator device's application layer >> should be deleted. Page: 247 Sequence number: 10 Date: 1/30/2003 4:23:27 PM Type: Highlight ACCEPT - DONE ("after constructing") 9.2.6.2.3.2 Transition ST\_ISF2:Prepare\_Command\_Request to ST\_ISF1:Send\_Frame The statement << after the ST\_ISF2:Prepare\_Command\_Request state >> should be <<after this state >>. Page: 247 Sequence number: 11 Date: 2/9/2003 11:05:59 AM Type: Strikeout REJECT (but changed parens to comma) 9.2.6.2.4.1 State description The statement << (these were received either from the SCSI initiator device's application layer or included in an XFER\_RDY Arrived parameter): >> should be deleted. Page: 248 Sequence number: 2 Date: 2/9/2003 10:57:47 AM Type: Highlight ACCEPT - DONE (deleted whole paragraph and added data to the first a)b)c) list. Saying it shall generate fill bytes should be enough here. The definitions of those fields need to be referenced to understand them anyway.) 9.2.6.2.4.1 State description In what case would the following statement not be true? << If all of the data for the request is not included in the frame, the number of data bytes in the frame shall be a multiple of four, and the number of fill bytes shall be zero. >> If it is always true or is described somewhere else then it should be deleted. Page: 248 Sequence number: 3 Date: 1/30/2003 4:23:51 PM Type: Highlight ACCEPT - DONE ("after constructing") 9.2.6.2.4.2 Transition ST\_ISF3:Prepare\_Send\_Data\_Out to ST\_ISF1:Send\_Frame

The statement << after the ST\_ISF3:Prepare\_Send\_Data\_Out state has >> should be << after this state has >>.

Page: 248 Sequence number: 4 Date: 2/8/2003 2:49:20 PM Type: Square ACCEPT - DONE 9.2.6.2.5.1 State description The statement << The ST\_IRD state machine shall be initiated when a Data-In Arrived parameter is received. >> should be in the state machine overview not here. Page: 248 Sequence number: 5 Date: 2/8/2003 2:55:43 PM Type: Square REJECT (it happens after this state does something) 9.2.6.2.5.1 State description The statement << This state machine shall terminate after sending the parameter. >> should be in the state machine overview not here. Page: 248 Sequence number: 6 Date: 2/8/2003 2:57:24 PM Type: Highlight ACCEPT - DONE 9.2.6.2.5.2 Transition ST IRD1:Receive Data In to ST IRD2:Process Received Data In The statement << by the ST\_IRD1:Receive\_Data\_In has been >> should be << by this state has been >>. Page: 248 Sequence number: 7 Date: 2/8/2003 2:55:35 PM Type: Square REJECT (it happens after this state does something) 9.2.6.2.6 ST\_IRD2:Process\_Received\_Data\_In state The statement << The ST\_IRD state machine shall terminate after the data-in data is processed. >> should be in the state machine overview not here. Page: 248 Sequence number: 8 Date: 2/8/2003 2:50:17 PM Type: Square REJECT (this is the overview, there being only one state) 9.2.6.2.7 ST\_IPR1:Process\_Received\_Response state The statement << The ST\_IPR state machine shall be initiated when a Response Arrived parameter is received or a Delivery Failure parameter is received. >> should be in the state machine overview not here. Page: 249 Sequence number: 3 Date: 2/8/2003 2:55:55 PM Type: Square REJECT (it happens after this state does something) 9.2.6.2.7 ST\_IPR1:Process\_Received\_Response state The statement << The ST\_IPR state machine shall terminate after sending a confirmation.>> should be in the state machine overview not here. Page: 249 Sequence number: 4 Date: 2/9/2003 10:52:06 AM Type: Highlight ACCEPT - DONE (bit was incorrectly called TIMEOUT in the frame header table; RETRANSMIT is the correct name) 9.2.6.2.7 ST\_IPR1:Process\_Received\_Response state The statement << of the RETRANSMIT bit. >> is a problem because there is no RETRANSMIT bit. This needs to be fixed. Page: 249 Sequence number: 5 Date: 2/8/2003 2:50:40 PM Type: Square REJECT (this is the overview, there being only one state) 9.2.6.2.8 ST\_IFR1:Initiator\_Frame\_Router state The statement << The ST\_IFR state machine shall be initiated when:

 a) an Accept\_Reject OPENs request is received; b) a Frame Received confirmation is received; c) a DONE Received confirmation is received; or d) a hard reset occurs. >> should be in the state machine overview not here. Page: 249 Sequence number: 6 Date: 2/9/2003 10:52:19 AM Type: Highlight REJECT 9.2.6.2.8 ST\_IFR1:Initiator\_Frame\_Router state The statement << If the ST\_IFR state machine was initiated as the result of receiving >> should be << If this state initially received >>. Page: 249 Sequence number: 7 Date: 2/9/2003 10:52:52 AM Type: Highlight REJECT (this is a one-state state machine so this IS the overview) 9.2.6.2.8 ST\_IFR1:Initiator\_Frame\_Router state The statement << The ST\_IFR state machine shall terminate after sending an Accept\_Reject OPENs request to the port layer state machine. >> should be in the state machine overview not here. Page: 250 Sequence number: 11 Date: 2/2/2003 3:39:31 PM Type: Strikeout **REJECT** (helpful for overview) 9.2.6.3.1 Overview The statement << from the port layer state machine >> should be deleted. Page: 250 Sequence number: 12 Date: 2/2/2003 3:41:43 PM Type: Strikeout **REJECT** (fine for overview) 9.2.6.3.1 Overview The statement << from the SCSI target device's application layer >> should be deleted. Page: 250 Sequence number: 13 Date: 2/2/2003 3:42:26 PM Type: Strikeout **REJECT** (fine for overview) 9.2.6.3.1 Overview The statement << from the SCSI target device's application layer; >> should be deleted. Page: 250 Sequence number: 14 Date: 2/9/2003 10:45:07 AM Type: Highlight REJECT 9.2.6.2.8 ST\_IFR1:Initiator\_Frame\_Router state The statement << If the ST\_IFR state machine was initiated as the result of receiving >> should be << If this state initially received >>. Page: 250 Sequence number: 15 Date: 2/8/2003 2:25:36 PM Type: Highlight REJECT (deleting entire paragraph) 9.2.6.2.8 ST\_IFR1:Initiator\_Frame\_Router state The statement << If the ST\_IFR state machine was initiated as the result of receiving >> should be << If this state initially received >>.

Date: 2/9/2003 10:45:16 AM Type: Highlight REJECT 9.2.6.2.8 ST\_IFR1:Initiator\_Frame\_Router state The statement << If the ST\_IFR state machine was initiated as the result of a >> should be << If this state initially received a >>. Page: 250 Sequence number: 17 Date: 2/9/2003 10:45:33 AM Type: Highlight REJECT (this is a one-state state machine, so this IS the overview) 9.2.6.2.8 ST\_IFR1:Initiator\_Frame\_Router state All these << terminate >>s are a problem because the state machine comings and goings should be specified in the state machines overview. Page: 250 Sequence number: 18 Date: 1/13/2003 6:58:58 PM Type: Highlight REJECT TODO (maybe change to "valid state machine) 9.2.6.2.8 ST\_IFR1:Initiator\_Frame\_Router state The statement << specify an existing state machine, >> should be << specify an active state machine >>. Page: 250 Sequence number: 19 Date: 2/8/2003 2:56:02 PM Type: Square REJECT (it happens after this state does something) 9.2.6.2.8 ST IFR1:Initiator Frame Router state The statement << The ST IFR state machine shall terminate after sending a parameter to another state machine. >> should be in the state machine overview not here. Page: 250 Sequence number: 20 Date: 2/9/2003 10:45:47 AM Type: Strikeout REJECT 9.2.6.3.1 Overview The statement << (target frame router) >> should be deleted. Page: 250 Sequence number: 21 Date: 2/9/2003 10:46:02 AM Type: Strikeout ACCEPT - DONE 9.2.6.3.1 Overview The statement << (target transport server) >> should be deleted. Page: 250 Sequence number: 22 Date: 2/9/2003 10:46:42 AM Type: Strikeout REJECT (when moved to the correct section it's an appropriate use) 9.2.6.3.1 Overview The statement << (target transport server) >> should be deleted. Page: 250 Sequence number: 23 Date: 2/2/2003 3:42:34 PM Type: Strikeout ACCEPT - DONE 9.2.6.3.1 Overview The term << several >> should be deleted. in item d) Page: 251 Sequence number: 4 Date: 2/2/2003 3:44:07 PM Type: Highlight ACCEPT - DONE

9.2.6.3.1 Overview The term << describes >> should be << shows >>. Page: 251 Sequence number: 5 Date: 2/2/2003 3:50:00 PM Type: Circle ACCEPT - DONE (used correct connector style so arcs appear) Figure 99 Either all the crossing lines need hops or none should have them. For this figure it looks like none would be OK. Page: 251 Sequence number: 6 Date: 2/9/2003 10:30:40 AM Type: Highlight REJECT (this is the SAM-3 name) Figure 99 The term << Request >> in the << task Management Request Received >> should be deleted. Page: 252 Sequence number: 6 Date: 2/2/2003 3:57:57 PM Type: Strikeout ACCEPT - DONE 9.2.6.3.2 ST\_TFR1:Target\_Frame\_Router state The statement << from the SCSI target device's application layer, >> should be deleted. Page: 252 Sequence number: 7 Date: 2/2/2003 3:31:52 PM Type: Strikeout ACCEPT - DONE 9.2.6.3.2 ST\_TFR1:Target\_Frame\_Router state The statement << from the port layer state machine, >> should be deleted. Page: 252 Sequence number: 8 Date: 2/2/2003 3:29:28 PM Type: Square REJECT - this IS the overview (it's a one state state machine. Added "machine" to the header. 9.2.6.3.2 ST\_TFR1:Target\_Frame\_Router state The statement << The ST\_TFR state machine shall be initiated when: a) an Accept\_Reject OPENs request is received; b) a Frame Received confirmation is received; or c) a hard reset occurs. >> should be in the state machine overview not here. Page: 252 Sequence number: 9 Date: 2/2/2003 3:57:27 PM Type: Square REJECT (this IS the overview) 9.2.6.3.2 ST\_TFR1:Target\_Frame\_Router state The statement << Each indication or parameter shall contain the content of the SAS frame. The ST\_TFR state machine shall terminate after sending a Data-Out Arrived parameter or transport protocol service indication. >> should be in the state machine overview not here. Page: 252 Sequence number: 10 Date: 2/2/2003 3:26:28 PM Type: Highlight ACCEPT - DONE ("this state" accepted, "but key "initiated as the result of") 9.2.6.3.2 ST\_TFR1:Target\_Frame\_Router state The statement << If the ST\_TFR state machine was initiated as the result of receiving >> should be << If this state initially received >>. Page: 252

Sequence number: 11 Date: 2/2/2003 3:26:31 PM Type: Highlight

ACCEPT - DONE ("this state" accepted, "but key "initiated as the result of") 9.2.6.3.2 ST\_TFR1:Target\_Frame\_Router state The statement << If the ST\_TFR state machine was initiated as the result of receiving >> should be << If this state initially received >>. Page: 252 Sequence number: 12 Date: 2/2/2003 3:26:36 PM Type: Highlight ACCEPT - DONE ("this state" accepted, "but key "initiated as the result of") 9.2.6.3.2 ST\_TFR1:Target\_Frame\_Router state The statement << If the ST\_TFR state machine was initiated as the result of receiving >> should be << If this state initially received >>. Page: 252 Sequence number: 13 Date: 2/2/2003 3:57:03 PM Type: Highlight REJECT (this IS the overview) 9.2.6.3.2 ST\_TFR1:Target\_Frame\_Router state All these << terminate >>s are a problem because the state machine comings and goings should be specified in the state machines overview. Page: 252 Sequence number: 14 Date: 2/2/2003 3:56:47 PM Type: Highlight ACCEPT - DONE ("as send a corresponding Accept Reject OPENs) 9.2.6.3.2 ST TFR1:Target Frame Router state The statement << with the received attribute to the port layer state machine. >> should be << with the attribute received with the Accept Reject OPEN to the port layer state machine. >> Page: 252 Sequence number: 15 Date: 2/2/2003 3:55:43 PM Type: Highlight ACCEPT - DONE 9.2.6.3.2 ST\_TFR1:Target\_Frame\_Router state The statement << the length of the information unit is [28 + (4 x additional CDB length)] bytes. >> should be << the length of the information unit (see 9.2.5.1) >>. All the length rules are specified elsewhere and should not be here. Page: 252 Sequence number: 16 Date: 2/2/2003 3:55:01 PM Type: Highlight ACCEPT - DONE 9.2.6.3.2 ST\_TFR1:Target\_Frame\_Router state The statement << the length of the information unit is 28 bytes. >> should be << the length of the information unit (see 9.2.5.1) >>. All the length rules are specified elsewhere and should not be here. Page: 252 Sequence number: 17 Date: 2/2/2003 3:53:35 PM Type: Highlight ACCEPT - DONE 9.2.6.3.2 ST\_TFR1:Target\_Frame\_Router state The statement << information unit is not 28 bytes, >> should be << information unit is not correct, >> Page: 252 Sequence number: 18 Date: 2/2/2003 3:55:53 PM Type: Highlight ACCEPT - DONE 9.2.6.3.2 ST\_TFR1:Target\_Frame\_Router state The statement << If it conflicts, this state may send a Response >> should be << If the tag is checked and it conflicts this state shall send a >>. There should no requirement for checking but if checked and there is a error then the response should be a shall.

Sequence number: 19 Date: 2/2/2003 3:52:10 PM Type: Highlight REJECT - hard reset is more than a signal 9.2.6.3.2 ST\_TFR1:Target\_Frame\_Router state The statement << hard reset, then the ST\_TFR state >> should be << HARD\_RESET Received confirmation , then the ST\_TFR state >> Page: 252 Sequence number: 20 Date: 2/2/2003 3:51:35 PM Type: Highlight REJECT (only the ones named in SAM are "transport protocol service requests". Everything else follow's SAS's plain request terminology.) 9.2.6.3.2 ST\_TFR1:Target\_Frame\_Router state Global It looks like the term << request: >> when used in relation to requests from the application layer should be << transport protocol service request >> in all cases in this section. This needs to be fixed. Page: 252 Sequence number: 21 Date: 2/2/2003 3:26:44 PM Type: Highlight ACCEPT - DONE 9.2.6.3.2 ST\_TFR1:Target\_Frame\_Router state The statement << then the ST\_TFR state machine shall discard >> should be << then this state machine shall discard >>. Page: 252 Sequence number: 22 Date: 2/2/2003 3:26:51 PM Type: Highlight ACCEPT - DONE 9.2.6.3.2 ST\_TFR1:Target\_Frame\_Router state The statement << then the ST\_TFR state machine shall discard >> should be << then this state machine shall discard >>. Page: 253 Sequence number: 1 Date: 1/30/2003 4:09:06 PM Type: Strikeout ACCEPT - DONE 9.2.6.3.3.2 Transition ST\_TTS1:Target\_Request\_Response\_Router to ST\_TTS2:Send\_Frame The statement << from the SCSI target device's application layer. >> should be deleted. Page: 253 Sequence number: 2 Date: 1/30/2003 4:08:37 PM Type: Strikeout ACCEPT - DONE 9.2.6.3.3.3 Transition ST\_TTS1:Target\_Request\_Response\_Router to ST\_TTS4:Receive\_Data\_Out The statement << from the SCSI target device's application layer. >> should be deleted. Page: 253 Sequence number: 3 Date: 1/30/2003 4:08:27 PM Type: Strikeout ACCEPT - DONE 9.2.6.3.3.4 Transition ST\_TTS1:Target\_Request\_Response\_Router to ST\_TTS7:Prepare\_Response The statement << from the SCSI target device's application layer. >> should be deleted. Page: 253 Sequence number: 4 Date: 2/2/2003 4:18:27 PM Type: Strikeout ACCEPT - DONE 9.2.6.3.4.1 State description The statement << This state is entered when a DATA frame is received from the ST\_TTS3:Prepare\_Send\_Data\_In state, when an XFER\_RDY frame is received from the ST\_TTS4:Receive\_Data\_Out state, when a RESPONSE frame is received from the ST\_TTS7:Prepare\_Response state, or after the ST\_TTS7:Prepare\_Response state has determined that the vendor-specific number of retries for a RESPONSE frame has been exceeded. >> should be deleted as we do not describe entry conditions.

Page: 253 Sequence number: 5 Date: 1/30/2003 4:11:00 PM Type: Strikeout ACCEPT - DONE 9.2.6.3.3.1 State description The statement << from the SCSI target device's application layer: >> should be deleted. Page: 253 Sequence number: 6 Date: 2/2/2003 4:17:25 PM Type: Square ACCEPT - DONE (Created an overview for it) 9.2.6.3.3.1 State description The statement << The ST\_TTS state machine shall be initiated when one of the following is received from the SCSI target device's application layer: a) a Send Data-In transport protocol service request; b) a Receive Data-Out transport protocol service request; c) a Task Management Function Executed transport protocol service response; or d) a Send Command Complete transport protocol service response. >> should be in the state machine overview not here. Page: 253 Sequence number: 7 Date: 1/30/2003 4:10:42 PM Type: Highlight REJECT (it's already overly redundant to even mention these fields.) 9.2.6.3.3.1 State description The list  $\langle a \rangle$  connection rate; b) initiator connection tag: c) destination SAS address; and d) source SAS address. >>should be moved into the lists for each of the protocol services. I know this will create the same entries in each but it would be clearer. Page: 253 Sequence number: 8 Date: 1/30/2003 4:09:53 PM Type: Strikeout REJECT (these add on to the initial a)b)c) list just above) 9.2.6.3.3.1 State description Delete << also >> and add in the complete list. Page: 253 Sequence number: 9 Date: 1/30/2003 4:09:59 PM Type: Strikeout REJECT (these add on to the initial a)b)c) list just above) 9.2.6.3.3.1 State description Delete << also >> and add in the complete list. Page: 253 Sequence number: 10 Date: 1/30/2003 4:10:05 PM Type: Strikeout REJECT (these add on to the initial a)b)c) list just above) 9.2.6.3.3.1 State description Delete << also >> and add in the complete list. Page: 253 Sequence number: 11 Date: 1/30/2003 4:07:19 PM Type: Highlight ACCEPT - DONE 9.2.6.3.3.2 Transition ST\_TTS1:Target\_Request\_Response\_Router to ST\_TTS2:Send\_Frame The statement << after the ST\_TTS1:Target\_Request\_Response\_Router state has received a Send Data-In transport protocol service request >> should be << after receiving a Send Data-In transport protocol service request. >>

Sequence number: 12 Date: 1/30/2003 4:07:40 PM Type: Highlight ACCEPT - DONE 9.2.6.3.3.3 Transition ST\_TTS1:Target\_Request\_Response\_Router to ST\_TTS4:Receive\_Data\_Out The statement << after the ST\_TTS1:Target\_Request\_Response\_Router state has received a Receive Data-Out transport protocol service request >> should be << after receiving a Receive Data-Out transport protocol service request. >> Page: 253 Sequence number: 13 Date: 1/30/2003 4:07:48 PM Type: Highlight ACCEPT - DONE 9.2.6.3.3.4 Transition ST\_TTS1:Target\_Request\_Response\_Router to ST\_TTS7:Prepare\_Response The statement << after the ST\_TTS1:Target\_Request\_Response\_Router state has received a Task Management >> should be << after receiving a Task Management >>. Page: 254 Sequence number: 6 Date: 2/2/2003 3:34:44 PM Type: Strikeout ACCEPT - DONE 9.2.6.3.4.1 State description The statement << from the port layer state machine. >> should be deleted. Page: 254 Sequence number: 7 Date: 2/2/2003 3:34:52 PM Type: Strikeout ACCEPT - DONE 9.2.6.3.4.1 State description The statement << from the port layer state machine. >> should be deleted. Page: 254 Sequence number: 8 Date: 2/2/2003 4:23:24 PM Type: Square REJECT 9.2.6.3.4.1 State description If the TTS state machine was initiated as the result of this state receiving a Send Data-In transport protocol service request, the specified values are included with the request, and this state has received an ACK Transmitted confirmation, then this state shall transition to the ST TTS3:Prepare Send Data In state. >> should be in the state machine overview not here. Page: 254 Sequence number: 9 Date: 2/9/2003 10:26:46 AM Type: Highlight ACCEPT - DONE 9.2.6.3.4.1 State description The statement << state shall receive >> should be << state shall wait for receipt >>. Page: 254 Sequence number: 10 Date: 1/6/2003 6:16:00 PM Type: Highlight 9.2.6.3.4.1 State description The statement << If the frame transmitted was a DATA frame, then this state may transition to the ST\_TTS3:Prepare\_Send\_Data\_In state after receiving a Transmission Status (Frame Transmitted) confirmation. >> should be moved to the relevant state transition description. Page: 254 Sequence number: 11 Date: 1/6/2003 6:16:00 PM Type: Highlight 9.2.6.3.4.1 State description

The statement << If the confirmation is ACK Received and the transmitted frame was an XFER\_RDY frame, then this state shall transition to the ST\_TTS4:Receive\_Data\_Out state. >> should be moved to the relevant state transition description.

Page: 254 Sequence number: 12 Date: 1/6/2003 6:16:00 PM Type: Highlight 9.2.6.3.4.1 State description The statement << If the frame transmitted was an XFER\_RDY frame or a RESPONSE frame, then this state shall wait to receive an ACK Received, NAK Received, or Connection Failed confirmation before transitioning from this state. >> should be moved to the relevant state transition description. Page: 254 Sequence number: 13 Date: 2/9/2003 10:30:03 AM Type: Highlight ACCEPT - DONE (reworded quite a bit to get rid of "confirmation transmission status parameter") 9.2.6.3.4.1 State description The statement << one of the following: >> should be << one of the following occurs >>. Page: 255 Sequence number: 1 Date: 2/2/2003 3:35:06 PM Type: Strikeout ACCEPT - DONE 9.2.6.3.4.1 State description The statement << from the port layer state machine. >> should be deleted. Page: 255 Sequence number: 2 Date: 2/2/2003 3:35:16 PM Type: Strikeout ACCEPT - DONE 9.2.6.3.4.4 Transition ST\_TTS2:Send\_Frame to ST\_TTS7:Prepare\_Response The statement << from the port layer state machine: >> should be deleted. Page: 255 Sequence number: 3 Date: 2/2/2003 4:31:38 PM Type: Square REJECT (it only happens in this state) 9.2.6.3.4.1 State description The statement << The ST\_TTS state machine shall terminate after sending the Data-In Delivered confirmation. >> should be in the state machine overview not here. Page: 255 Sequence number: 4 Date: 2/2/2003 4:31:49 PM Type: Highlight REJECT (it only happens in this state) 9.2.6.3.4.1 State description The statement << The ST\_TTS state machine terminates upon receipt of a Cancel Acknowledge confirmation >> should be in the state machine overview not here. Page: 255 Sequence number: 5 Date: 2/9/2003 10:18:02 AM Type: Highlight ACCEPT - DONE 9.2.6.3.4.2 Transition ST\_TTS2:Send\_Frame to ST\_TTS3:Prepare\_Send\_Data\_In The statement << this state receives >> should be << receiving >> Page: 255 Sequence number: 6 Date: 2/9/2003 10:17:55 AM Type: Highlight ACCEPT - DONE 9.2.6.3.4.2 Transition ST\_TTS2:Send\_Frame to ST\_TTS3:Prepare\_Send\_Data\_In The statement << this state receives >> should be << receiving >>

Page: 255 Sequence number: 7 Date: 1/30/2003 4:24:35 PM Type: Highlight ACCEPT - DONE 9.2.6.3.4.3 Transition ST\_TTS2:Send\_Frame to ST\_TTS4:Receive\_Data\_Out The statement << this state has received >> should be << receiving >> Page: 255 Sequence number: 8 Date: 2/8/2003 5:00:10 PM Type: Highlight ACCEPT - DONE (changed to "received from the application layer") 9.2.6.3.5.1 State description The statement << the tag received from the ST\_TTS2:Send\_Frame state to construct the frame. >> should be << the received tag to construct the frame. >>. Page: 255 Sequence number: 9 Date: 1/30/2003 4:24:59 PM Type: Highlight ACCEPT - DONE ("after constructing") 9.2.6.3.5.2 Transition ST\_TTS3:Prepare\_Send\_Data\_In to ST\_TTS2:Send\_Frame The statement << after the ST\_TTS3:Prepare\_Send\_Data\_In state has >> should be << after this state has >>. Page: 256 Sequence number: 4 Date: 2/9/2003 10:16:52 AM Type: Strikeout ACCEPT - DONE 9.2.6.3.6.1 State description The statement << This state is entered after one of the following occurs: a) a Receive Data-Out service request is received from the ST\_TS1:Request\_Response\_Router state; b) a DATA frame is received from the ST\_TFR (target frame router) state machine; c) an ACK Received confirmation for an XFER\_RDY frame was received from the ST\_TTS2:Send\_Frame state; d) an XFER\_RDY frame has been constructed by the ST\_TTS5:Prepare\_XFER\_RDY state; or e) data-out data has been processed by the ST\_TTS6:Process\_Received\_Data\_Out state. >> should be deleted as we do not describe entry conditions. Page: 256 Sequence number: 5 Date: 2/2/2003 3:35:25 PM Type: Strikeout ACCEPT - DONE 9.2.6.3.6.1 State description The statement << from the port layer state machine >> should be deleted. Page: 256 Sequence number: 6 Date: 2/2/2003 3:35:33 PM Type: Strikeout ACCEPT - DONE 9.2.6.3.6.1 State description The statement << from the ST\_TFR state machine. >> should be deleted. Page: 256 Sequence number: 7 Date: 2/2/2003 4:13:51 PM Type: Strikeout ACCEPT - DONE 9.2.6.3.6.1 State description The statement << from the ST\_TFR1:Target\_Frame\_Router state. >> should be deleted. Page: 256 Sequence number: 8 Date: 2/9/2003 10:01:13 AM

Type: Highlight

ACCEPT - DONE (and included first burst handling text too) 9.2.6.3.6.1 State description The statement << If this state was entered as the result of receiving a Receive Data-Out service request from the ST\_TS1:Request\_Response\_Router state then this state shall transition to the ST\_TTS5:Prepare\_XFER\_RDY state. >> should be moved to the relevant state transition description. Page: 256 Sequence number: 9 Date: 1/30/2003 4:19:06 PM Type: Highlight REJECT (it terminates after this state does that) 9.2.6.3.6.1 State description The statement << The ST\_TTS state machine shall terminate after sending the confirmation. >> should be in the state machine overview not here. Page: 256 Sequence number: 10 Date: 1/30/2003 4:18:59 PM Type: Highlight REJECT (it terminates after this state does that) 9.2.6.3.6.1 State description The statement << The ST\_TTS state machine shall terminate after sending the confirmation. >> should be in the state machine overview not here. Page: 256 Sequence number: 11 Date: 1/30/2003 4:18:53 PM Type: Highlight REJECT (it terminates after this state does that) 9.2.6.3.6.1 State description The statement << The ST\_TTS state machine shall terminate after sending the confirmation. >> should be in the state machine overview not here. Page: 256 Sequence number: 12 Date: 1/30/2003 4:18:47 PM Type: Highlight REJECT (it terminates after this state does that) 9.2.6.3.6.1 State description The statement << The ST\_TTS state machine shall terminate after sending the confirmation. >> should be in the state machine overview not here. Page: 256 Sequence number: 13 Date: 2/9/2003 10:16:24 AM Type: Highlight ACCEPT - DONE 9.2.6.3.6.1 State description The statement << If the target transport tag value matches the value sent with the corresponding XFER\_RDY frame, and the length of the data does not exceed that specified by the XFER\_RDY frame that requested the data, then this state shall transition to the ST\_TTS6:Process\_Received\_Data\_Out state. >> should be moved to the relevant state transition description. Page: 256 Sequence number: 14 Date: 2/9/2003 10:16:10 AM Type: Highlight ACCEPT - DONE (deleted this arc entirely; let TTS5 go directly to TTS2) 9.2.6.3.6.1 State description The statement << If this state is entered from the ST\_TTS5:Prepare\_XFER\_RDY state, then this state shall transition to the ST\_TTS2:Send\_Frame state. >> should be moved to the relevant state transition description. Page: 256 Sequence number: 15 Date: 1/30/2003 4:19:28 PM Type: Highlight REJECT (it terminates after this state does that) 9.2.6.3.6.1 State description The statement << The ST\_TTS

state machine shall terminate after sending the confirmation. >> should be in the state machine overview not here.

Page: 257 Sequence number: 1 Date: 2/2/2003 4:32:50 PM Type: Strikeout ACCEPT - DONE 9.2.6.3.6.4 Transition ST\_TTS4:Receive\_Data\_Out to ST\_TTS6:Process\_Received\_Data\_Out The statement << from the ST\_TFR (target frame router) state machine. >> should be deleted. Page: 257 Sequence number: 2 Date: 2/2/2003 4:26:02 PM Type: Strikeout ACCEPT - DONE 9.2.6.3.9.1 State description The statement << by this state from the ST\_TFR state machine. >> should be deleted. Page: 257 Sequence number: 3 Date: 2/8/2003 3:46:06 PM Type: Strikeout ACCEPT - DONE 9.2.6.3.9.1 State description The statement << This state is entered after one of the following occurs: a) a Response Data parameter is received by this state from the ST\_TFR state machine; b) a Task Management Function Executed transport protocol service response was received by the ST TTS1:Target Request Response Router state from the SCSI target device's application layer; c) a Send Command Complete transport protocol service response was received by the ST TTS1:Target Request Response Router state from the SCSI target device's application layer; or d) the ST TTS2:Send Frame state receives something other than a Transmission Status (Frame Transmitted) confirmation followed by an ACK Received confirmation for a RESPONSE frame from the port layer state machine (i.e., the frame transmission was unsuccessful). >> should be deleted as we do not describe entry conditions. Page: 257 Sequence number: 4 Date: 2/2/2003 4:26:26 PM Type: Square ACCEPT - DONE (moved to new overview section) 9.2.6.3.9.1 State description The statement << If not already running, the ST\_TTS state machine shall be initiated when a Response Data parameter is received. >> should be in the state machine overview not here. Page: 257 Sequence number: 5 Date: 1/30/2003 4:13:06 PM Type: Highlight ACCEPT - DONE 9.2.6.3.6.2 Transition ST\_TTS4:Receive\_Data\_Out to ST\_TTS2:Send\_Frame The statement << This transition shall occur after this state has received an XFER\_RDY frame from the ST\_TTS5:Prepare\_XFER\_RDY state. >> should be << This transition shall occur if this state is entered from the ST\_TTS5:Prepare\_XFER\_RDY state. >> Page: 257 Sequence number: 6 Date: 1/30/2003 4:13:57 PM Type: Highlight ACCEPT - DONE 9.2.6.3.6.4 Transition ST\_TTS4:Receive\_Data\_Out to ST\_TTS6:Process\_Received\_Data\_Out The statement << after the ST\_TTS4:Receive\_Data\_Out state receives a Data-Out Arrived parameter >> should be << after receiving a Data-Out Arrived parameter >> Page: 257 Sequence number: 7 Date: 1/30/2003 4:13:32 PM Type: Highlight ACCEPT - DONE The statement << This transition shall occur after a Receive Data-Out transport protocol service request has been received by the

ST\_TTS4:Receive\_Data\_Out state from the ST\_TTS1:Request\_Response\_Router state. >> should be << This transition shall

Page: 257 Sequence number: 8 Date: 1/30/2003 4:14:36 PM Type: Highlight ACCEPT - DONE (changed to "after constructing") 9.2.6.3.7.2 Transition ST\_TTS5:Prepare\_XFER\_RDY to ST\_TTS4:Receive\_Data\_Out The statement << after the ST\_TTS5:Prepare\_XFER\_RDY state has >> should be << after this state has >>. Page: 258 Sequence number: 3 Date: 2/8/2003 4:18:21 PM Type: Strikeout ACCEPT - DONE (this is actually one of those odd "receiving stuff with a transition" scenarios. Reworded to say "if this state machine receives" which avoids the transition-with-contents issue.") 9.2.6.3.9.1 State description The statement << from the ST\_TTS1:Target\_Request\_Response\_Router state, >> should be deleted. Page: 258 Sequence number: 4 Date: 2/2/2003 3:36:27 PM Type: Strikeout ACCEPT - DONE 9.2.6.3.9.1 State description The statement << from the port layer state machine >> should be deleted. Page: 258 Sequence number: 5 Date: 2/8/2003 3:47:37 PM Type: Strikeout ACCEPT - DONE 9.2.6.3.9.1 State description The statement << from the ST\_TFR state machine, >> should be deleted. Page: 258 Sequence number: 6 Date: 2/8/2003 3:47:47 PM Type: Strikeout ACCEPT - DONE 9.2.6.3.9.1 State description The statement << from the ST\_TFR state machine, >> should be deleted. Page: 258 Sequence number: 7 Date: 2/8/2003 4:55:30 PM Type: Highlight REJECT (convention seems to be to use lowercase here... see list above. It's not a field reference, it's the name of a single bit value) 9.2.6.3.9.1 State description The term << retransmit >> as in retransmit bit should be in small caps. Page: 259 Sequence number: 4 Date: 1/30/2003 4:26:49 PM Type: Strikeout **REJECT - why?** 9.3.2 SATA tunneling for multiple STP initiator ports The statement << from an STP initiator port, >> should be deleted. Page: 259 Sequence number: 5 Date: 1/30/2003 4:22:46 PM Type: Highlight ACCEPT - DONE ("after constructing") 9.2.6.3.9.2 Transition ST\_TTS7:Prepare\_Response to ST\_TTS2:Send\_Frame

The statement << after the ST\_TTS7:Prepare\_Response state has >> should be << after this state has >>.

Page: 259 Sequence number: 6 Date: 1/6/2003 6:16:00 PM Type: Highlight 9.3.2 SATA tunneling for multiple STP initiator ports Why is the term << PHY OPERATION >> in small caps? I don't think it should be. Page: 259 Sequence number: 7 Date: 1/6/2003 6:16:00 PM Type: Highlight ACCEPT - DONE 9.3.2 SATA tunneling for multiple STP initiator ports The statement << In this state, >> should be << Under these conditions, >>. Page: 259 Sequence number: 8 Date: 1/6/2003 6:16:00 PM Type: Highlight 9.3.2 SATA tunneling for multiple STP initiator ports Why is the term << PHY OPERATION >> in small caps? I don't think it should be. Page: 259 Sequence number: 9 Date: 1/6/2003 6:16:00 PM Type: Highlight REFER EDITORS WG (sends is not good) 9.3.2 SATA tunneling for multiple STP initiator ports This statement << STP initiator port issues an >> should be << STP initiator port sends an >> Page: 259 Sequence number: 10 Date: 1/6/2003 6:16:00 PM Type: Highlight 9.3.2 SATA tunneling for multiple STP initiator ports Why is the term << PHY OPERATION >> in small caps? I don't think it should be. Page: 259 Sequence number: 11 Date: 1/6/2003 6:16:00 PM Type: Highlight 9.3.2 SATA tunneling for multiple STP initiator ports Why is the term << PHY OPERATION >> in small caps? I don't think it should be. Page: 259 Sequence number: 12 Date: 1/6/2003 6:16:00 PM Type: Highlight **REFER EDITORS WG** (that's the name of the SATA frame - perhaps add to acronym list) 9.3.3 BIST Activate FIS The acronym << BIST >> is not in the acronyms list. It needs to be added or removed from here. Page: 260 Sequence number: 4 Date: 1/30/2003 4:28:59 PM Type: Highlight REJECT (but reworded whole paragraph in terms of SMP target ports) 9.4.1 SMP overview The statement << Other target ports >> should be << Target ports >>. Page: 260 Sequence number: 5 Date: 1/22/2003 5:38:38 PM Type: Highlight ACCEPT - DONE (globally changed target port to SMP target port or SSP target port or STP target port, and initiator port to SMP

initiator port or SSP initiator port or STP initiator port)

Figure 100 The label << Target port >> should be << Expander port or Target port >>. Page: 260 Sequence number: 6 Date: 1/30/2003 4:28:10 PM Type: Highlight REJECT - "determined by" is too active a verb for this - sounds like the function is going to do something to figure it out. "based on" works better. 9.4.2 SMP REQUEST frame The statement << length is based on the function >> should be << length is based on the function >> length is determined by the selected function >>. Page: 260 Sequence number: 7 Date: 1/30/2003 5:01:10 PM Type: Note ACCEPT - DONE Table 102 There needs to be a row labeled << Fill bytes if Needed >> added to this table. Page: 261 Sequence number: 5 Date: 1/30/2003 5:03:18 PM Type: Highlight ACCEPT - DONE ("by the SMP target port") 9.4.3 SMP\_RESPONSE frame global for SMP The statement << the target port >> should be << the target port or expander port >> or << destination port >> Page: 261 Sequence number: 6 Date: 1/6/2003 6:16:00 PM Type: Note ACCEPT - DONE Table 103 There needs to be a row labeled << Fill bytes if Needed >> added to this table. Page: 261 Sequence number: 7 Date: 1/6/2003 6:16:00 PM Type: Note ACCEPT - DONE 9.4.3 SMP RESPONSE frame There is no description of what the << FUNCTION >> field is. This needs to be fixed. Page: 261 Sequence number: 8 Date: 1/6/2003 6:16:00 PM Type: Highlight ACCEPT - DONE (with no xref) 9.4.3 SMP\_RESPONSE frame The statement << requested, and are described in the model section. >> should be << requested (see x.x.x.). >> Page: 262 Sequence number: 1 Date: 1/30/2003 5:24:21 PM Type: Highlight REJECT (request in the generic state machine sense) 9.4.4.1 Overview The statement << that process requests from the management application layer and >> should be << that process management requests and >> . Page: 262 Sequence number: 2 Date: 1/30/2003 5:24:25 PM Type: Highlight REJECT (request in the generic state machine sense)

9.4.4.2.1 Overview

The statement << processes requests from the management application layer. >> should be << processes management requests. >>.

Page: 262 Sequence number: 3 Date: 1/30/2003 5:23:20 PM Type: Highlight ACCEPT - DONE 9.4.4.2.1 Overview The term << communicated >> should be << sent >>. Page: 262 Sequence number: 4 Date: 1/30/2003 5:23:49 PM Type: Highlight ACCEPT - DONE 9.4.4.2.1 Overview The statement << in a return confirmation. >> should be <<as a confirmation. >>. Page: 263 Sequence number: 4 Date: 1/30/2003 5:24:53 PM Type: Strikeout ACCEPT - DONE 9.4.4.2.2.1 State description The statement << from the management application layer. >> should be deleted. Page: 263 Sequence number: 5 Date: 1/6/2003 6:16:00 PM Type: Highlight 9.4.4.2.2.1 State description The statement << of values to be used in the CONNECTION RATE, INITIATOR CONNECTION TAG, DESTINATION SAS ADDRESS, and SOURCE SAS ADDRESS fields in the OPEN address frame, and the FUNCTION and ADDITIONAL REQUEST BYTES fields in the SMP\_REQUEST frame. >> should list the actual values, not the fields they go into, in an a,b,c list like the ones in the several of the other ST state descriptions. Page: 264 Sequence number: 5 Date: 1/6/2003 6:16:00 PM Type: Strikeout 9.4.4.2.4.1 State description The statement << from the port layer >> should be deleted. Page: 264 Sequence number: 6 Date: 1/30/2003 5:38:03 PM Type: Highlight ACCEPT - DONE 9.4.4.3.1 Overview The statement << is communicated from the port layer and that confirmation is sent to the management application layer. >> should be << is sent to the management application layer. >>. Page: 264 Sequence number: 7 Date: 1/30/2003 5:46:31 PM Type: Strikeout REFER PROTOCOL WG (it's not obvious when transitions "carry" values since they don't show up in the figures) 9.4.4.2.3.1 State description The statement << received in the MT\_ID1:Idle to MT\_ID2:Send transition, >> should be deleted. Page: 264 Sequence number: 8 Date: 1/6/2003 6:16:00 PM Type: Highlight 9.4.4.2.3.1 State description The statement << frame using the function and additional request bytes arguments >> should be << frame using the received

function and additional request bytes arguments >>

Page: 264 Sequence number: 9 Date: 1/6/2003 6:16:00 PM Type: Highlight 9.4.4.2.3.1 State description The statement << used for the CONNECTION RATE, INITIATOR CONNECTION TAG, DESTINATION SAS ADDRESS, and SOURCE SAS ADDRESS fields in the OPEN address frame >> should list the actual values, not the fields they go into, in an a,b,c list like the ones in the several of the other ST state descriptions. Page: 264 Sequence number: 10 Date: 1/30/2003 5:36:19 PM Type: Highlight ACCEPT - DONE The statement << after a Transmission Status (SMP Frame Transmitted) confirmation is received. >> should be << after receiving a Transmission Status (SMP Frame Transmitted) confirmation. >>. Page: 264 Sequence number: 11 Date: 1/6/2003 6:16:00 PM Type: Highlight 9.4.4.2.4.1 State description The statement << This state shall initialize a SMP frame receive time out timer to a vendor-specific time and start the timer upon entry into this state. >> should be << Upon entry into this state, this state shall initialize a SMP frame receive time out timer to a vendor-specific time and start the timer. >> Page: 264 Sequence number: 12 Date: 1/21/2003 12:12:21 PM Type: Highlight 9.4.4.2.4.2 Transition MT\_ID3:Receive to MT\_ID1:Idle The statement << a) an Frame Received (SMP) confirmation is received, and, as a result, this state has sent an SMP Frame Pair Sent/Received confirmation to the management application layer; b) a Connection Closed or Frame Received (SMP Failure) confirmation is received, and, as a result, this state has sent an SMP Frame Tx/Rcv Failure confirmation to the management application layer; or c) the SMP frame receive time out timer is exceeded before a SMP Frame Pair Sent/Received confirmation is received, and, as a result, this state has sent an SMP Frame Receive Time out confirmation to the management application layer and has sent an SMP Transmit Break request to the port layer. >> should be << a) receiving a Frame Received (SMP) confirmation and after sending an SMP Frame Pair Sent/Received confirmation to the management application laver: b) receiving a Connection Closed or Frame Received (SMP Failure) confirmation and after sending an SMP Frame Tx/Rcv Failure confirmation to the management application layer; or c) the SMP frame receive time out timer times out before a SMP Frame Pair Sent/Received confirmation is received and after this state has sent an SMP Frame Receive Timeout confirmation to the management application layer and has sent an SMP Transmit Break request to the port layer. >> Page: 264 Sequence number: 13 Date: 1/6/2003 6:16:00 PM Type: Highlight 9.4.4.3.1 Overview The term << forwards >> should be << sends >>. Page: 265 Sequence number: 3 Date: 1/30/2003 5:38:35 PM Type: Strikeout ACCEPT - DONE 9.4.4.3.2.1 State description The statement << from the port layer. >> should be deleted. Page: 265 Sequence number: 4 Date: 1/30/2003 5:43:39 PM Type: Strikeout ACCEPT - DONE

9.4.4.3.3.1 State description The statement << from the management application layer. >> should be deleted.

Page: 265 Sequence number: 5 Date: 1/30/2003 5:40:16 PM Type: Highlight ACCEPT - DONE (added shall send to the state description, and based this just on after sending) 9.4.4.3.2.2 Transition MT\_TD1:Idle to MT\_TD2:Respond The statement << occur after an Frame Received (SMP) confirmation is received, and, as a result, this state has sent an SMP Frame Received confirmation to the >> should be << occur after receiving a Frame Received (SMP) confirmation and after sending an SMP Frame Received confirmation to the >> Page: 265 Sequence number: 6 Date: 1/30/2003 5:41:05 PM Type: Highlight ACCEPT - DONE (slightly different) 9.4.4.3.3.1 State description The statement << Upon receipt, this state shall send a Transmit Frame (SMP) request to the port layer. >> should be a new paragraph and changed to << This state shall send a Transmit Frame (SMP) request to the port layer after receiving a Tx SMP Frame request. >>. Page: 265 Sequence number: 7 Date: 1/6/2003 6:16:00 PM Type: Highlight 9.4.4.3.3.2 Transition MT\_TD2:Respond to MT\_TD1:Idle The statement << a) a Transmission Status (SMP Frame Transmitted) confirmation is received; or b) a Connection Closed confirmation is received, and, as a result, this state has sent an SMP Connection Closed confirmation to the management application layer. >> should be << a) receiving a Transmission Status (SMP Frame Transmitted) confirmation ; or b) receiving a Connection Closed confirmation and after sending an SMP Connection Closed confirmation to the management application layer. >>. Page: 267 Sequence number: 1 Date: 1/6/2003 6:16:00 PM Type: Highlight ACCEPT - DONE 10.1.1.1 Transport protocol services overview The statement << and how each transport protocol service is implemented in SSP. >> should be << and the SSP implementation of each transport protocol service. >>. Page: 267 Sequence number: 2 Date: 1/6/2003 6:16:00 PM Type: Strikeout REJECT - requests and confirmations are only used by state machines. This is not referencing a specific state machine. 10.1.1.1 Transport protocol services overview The terms << state machines >> should be deleted as we don't normally refer to state machines only layers. Page: 267 Sequence number: 3 Date: 2/1/2003 1:58:33 PM Type: Highlight ACCEPT - DONE 10.1.1.2 Send SCSI Command transport protocol service The statement << protocol service request to have an initiator port >> should be << protocol service request to request an initiator port >> Page: 268 Sequence number: 1 Date: 1/6/2003 6:16:00 PM Type: Highlight **REJECT** - no improvement 10.1.1.2 Send SCSI Command transport protocol service

The statement << shows how the arguments to the Send SCSI Command transport protocol service are used. >> should be << shows the usage of the Send SCSI Command transport protocol service arguments. >>.

Page: 268 Sequence number: 2 Date: 1/6/2003 6:16:00 PM Type: Highlight **REJECT** - no improvement 10.1.1.3 SCSI Command Received transport protocol service The statement << shows how the arguments to the SCSI Command Received transport protocol service are determined. >> should be << shows the usage of the SCSI Command Received transport protocol service arguments >> Page: 268 Sequence number: 3 Date: 1/6/2003 6:16:00 PM Type: Strikeout REJECT - the only other place is 9.2.5.1 which is a summary of error handling with cross references to the home of each rule. This is the "normative" location for this rule (bridging to SAM-3) and is pointed to by 9.2.4.5 and elsewhere. 10.1.1.3 SCSI Command Received transport protocol service The statement << If a target port calls SCSI Command Received () with a TAG already in use (i.e., an overlapped command), the device server responses are defined in SAM-3. >> should be deleted as the tag checking rules are defined elsewhere in this document. Page: 269 Sequence number: 2 Date: 1/6/2003 6:16:00 PM Type: Highlight **REJECT** - no improvement 10.1.1.4 Send Command Complete transport protocol service The statement << shows how the arguments to the Send Command Complete transport protocol service are used. >> should be << shows the usage of the Send Command Complete transport protocol service arguments. >>. Page: 269 Sequence number: 3 Date: 2/1/2003 1:58:45 PM Type: Highlight ACCEPT - DONE 10.1.1.4 Send Command Complete transport protocol service The statement << have a target port transmit >> should be << request a target port transmit >>. Page: 270 Sequence number: 1 Date: 1/6/2003 6:16:00 PM Type: Highlight **REJECT** - no improvement 10.1.1.5 Command Complete Received transport protocol service The statement << shows how the arguments to the Command Complete Received transport protocol service are determined. >> should be << shows the usage of the Command Complete Received transport protocol service arguments. >>. Page: 270 Sequence number: 2 Date: 1/6/2003 6:16:00 PM Type: Highlight ACCEPT - DONE (globally) 10.1.1.6 Send Data-In transport protocol service The term << I\_T\_L\_Q >> should be << I\_T\_L\_Q nexus >> in all cases. Page: 270 Sequence number: 3 Date: 2/1/2003 1:59:16 PM Type: Highlight ACCEPT - DONE 10.1.1.6 Send Data-In transport protocol service The statement << have a target port transmit >> should be << request a target port transmit >>. Page: 271 Sequence number: 1 Date: 1/6/2003 6:16:00 PM

Type: Highlight

**REJECT** - no improvement 10.1.1.6 Send Data-In transport protocol service The statement << shows how the arguments to the Send Data-In transport protocol service are used. >> should be << shows the usage of the Send Data-In transport protocol service arguments. >>. Page: 271 Sequence number: 2 Date: 1/6/2003 6:16:00 PM Type: Highlight **REJECT** - no improvement 10.1.1.7 Data-In Delivered transport protocol service The statement << shows how the arguments to the Data-In Delivered transport protocol service are determined. >> should be << shows the usage of the Data-In Delivered transport protocol service arguments. >>. Page: 271 Sequence number: 3 Date: 1/6/2003 6:16:00 PM Type: Highlight ACCEPT - DONE (globally) 10.1.1.8 Receive Data-Out transport protocol service The term << I\_T\_L\_Q >> should be << I\_T\_L\_Q nexus >> in all cases. Page: 271 Sequence number: 4 Date: 1/6/2003 6:16:00 PM Type: Square ACCEPT - DONE (changed "returned" to "completed successfully" - this means the device server is waiting for the function call to be invoked by the target port.) 10.1.1.8 Receive Data-Out transport protocol service The statement << A device server shall not call Receive Data Out () for a given I T L Q until Data Out Received () has returned for the previous Receive Data Out () call (i.e., no XFER RDY until all write DATA frames for the previous XFER RDY frame, if any, and has provided link layer acknowledgement for all of the previous write DATA frames for that I\_T\_L\_Q). >> does not parse I think it should be << A device server shall not call Receive Data Out () for a given I\_T\_L\_Q nexus until Data Out Received () has been returned for the previous Receive Data Out () call (i.e., no XFER\_RDY sent until all write DATA frames for the previous XFER\_RDY frame, if any, and have been provided by link layer acknowledgements for all of the previous write DATA frames for that I\_T\_L\_Q nexus). >> Page: 271 Sequence number: 5 Date: 2/1/2003 1:59:25 PM Type: Highlight ACCEPT - DONE 10.1.1.7 Data-In Delivered transport protocol service The statement << have a target port transmit >> should be << request a target port transmit >>. Page: 272 Sequence number: 2 Date: 1/6/2003 6:16:00 PM Type: Highlight **REJECT** - no improvement 10.1.1.8 Receive Data-Out transport protocol service The statement << shows how the arguments to the Receive Data-Out transport protocol service are used. >> should be << shows the usage of the Receive Data-Out transport protocol service arguments. >>. Page: 272 Sequence number: 3 Date: 1/6/2003 6:16:00 PM Type: Highlight **REJECT - no improvement** 10.1.1.9 Data-Out Received transport protocol service The statement << shows how the arguments to the Data-Out Received transport protocol service are determined. >> should be << shows the usage of the Data-Out Received transport protocol service arguments. >>. Page: 272 Sequence number: 4 Date: 2/1/2003 1:59:50 PM Type: Highlight ACCEPT - DONE 10.1.1.10 Send Task Management Request transport protocol service

The statement << have an initiator port transmit >> should be << request an initiator port transmit >>.

Page: 273 Sequence number: 2 Date: 2/1/2003 2:00:24 PM Type: Highlight ACCEPT - DONE 10.1.1.12 Task Management Function Executed transport protocol service The statement << have a target port transmit >> should be << request a target port transmit >>. Page: 273 Sequence number: 3 Date: 1/6/2003 6:16:00 PM Type: Highlight **REJECT** - no improvement 10.1.1.10 Send Task Management Request transport protocol service shows how the arguments to the Send Task Management Request transport protocol service are used. >> should be << shows the usage of the Send Task Management Request transport protocol service arguments. >>. Page: 273 Sequence number: 4 Date: 1/6/2003 6:16:00 PM Type: Highlight **REJECT** - no improvement 10.1.1.11 Task Management Request Received transport protocol service The statement << shows how the arguments to the Task Management Request Received transport protocol service are determined. >> should be << shows the usage of the Task Management Request Received transport protocol service arguments. >>. Page: 273 Sequence number: 5 Date: 1/30/2003 2:39:36 PM Type: Strikeout ACCEPT - DONE (delete this paragraph. There are no such rules in either SAM-3.) 10.1.1.11 Task Management Request Received transport protocol service The statement << If a target port calls Task Management Request Received () with a TAG already in use, the device server responses are defined in SAM-3. >> should be deleted as the tag checking rules are defined elsewhere in this document. Page: 274 Sequence number: 3 Date: 1/6/2003 6:16:00 PM Type: Highlight **REJECT** - no improvement 10.1.1.12 Task Management Function Executed transport protocol service The statement << shows how the arguments to the Task Management Function Executed transport protocol service are used. >> should be << shows the usage of the Task Management Function Executed transport protocol service arguments. >>. Page: 275 Sequence number: 1 Date: 1/6/2003 6:16:00 PM Type: Highlight **REJECT** - no improvement 10.1.1.13 Received Task Management Function-Executed transport protocol service The statement << shows how the arguments to the Received Task Management Function-Executed transport protocol service are determined. >> should be << shows the usage of the Received Task Management Function-Executed transport protocol service arguments. >>. Page: 275 Sequence number: 2 Date: 1/6/2003 6:16:00 PM Type: Note ACCEPT - DONE 10.1.2 Device server error handling The information in this section could be placed in a single table. This should make the presentation of the error information easier to determine. << If a device server calls Receive Data-Out () and receives a Delivery Result that indicate a deliver failure the device server shall respond as shown in table xx. Table xx - Response to Delivery Result DELIVERY FAILURE Columns would be: Delivery Result : Status : Sense Key : Additional sense code: >>

Page: 276 Sequence number: 2 Date: 1/30/2003 2:27:49 PM Type: Strikeout ACCEPT - DONE (per Jan WG - keep the list but as an example) 10.1.3 Application client error handling The statement << it determines the ACK for the RESPONSE frame was seen by the target port. This is indicated by: >> should be deleted. The workings of the lower layers is not needed here. JanWG: Change to: shall not use the tag until it determines the tag is no longer in use by the logical unit (e.g., the ACK for the RESPONSE frame was seen by the target port). Examples of ways the app client may determine when a tag may be reused are: a) b) c) Page: 276 Sequence number: 3 Date: 2/1/2003 2:06:24 PM Type: Square **REVIEW PROTOCOL WG** ACCEPT - DONE ( A table doesn't help; changed the wording a bit.) The statement << If an application client calls Send SCSI Command () and an initiator port calls Command Complete Received () and delivers a Service Response of Service Delivery of Target Failure - ACK/NAK Timeout, the application client shall send a QUERY TASK task management function with Send Task Management Request () to determine whether the command was received successfully. If Received Task Management Function Executed () returns a Service Response of FUNCTION SUCCEEDED, the application client shall assume the command was delivered successfully. If it returns a Service Response of FUNCTION COMPLETE, and Command Complete Received () has not yet been called a second time for the command in guestion, the application client shall assume the command was not delivered successfully and may reuse the tag. >> is very awkward. There must be a better way to present this information. May by some kind of table like the one suggested in the target error handling suggested in the above comment. Page: 277 Sequence number: 2 Date: 1/6/2003 6:16:00 PM Type: Highlight ACCEPT - DONE (data that shall be returned is described) 10.1.5.1 INQUIRY command The statement << is modified as described >> should be << by a SAS device is described >>. Page: 277 Sequence number: 3 Date: 1/6/2003 6:16:00 PM Type: Highlight ACCEPT - DONE 10.1.5.4 START STOP UNIT command The statement << are modified as described >> should be << by a SAS device is described >>. Page: 279 Sequence number: 1 Date: 1/6/2003 6:16:00 PM Type: Highlight ACCEPT - DONE 10.1.6.1.3 MAXIMUM CONNECT TIME LIMIT field The statement << (i.e., a value of one in this field specifies that the time shall be less than or equal to 100 µs, a value of two in this field specifies that the time shall be less than or equal to 200 µs, etc.). >> should be << (e.g., a value of one in this field specifies that the time shall be less than or equal to 100 µs, a value of two in this field specifies that the time shall be less than or equal to 200 µs). >> Page: 279 Sequence number: 2 Date: 1/6/2003 6:16:00 PM Type: Highlight ACCEPT - DONE 10.1.6.1.4 MAXIMUM BURST SIZE field The statement << (i.e., a value of one in this field specifies that the number of bytes transferred to the initiator port for the nexus shall be less than or equal to 512, a value of two in this field specifies that the number of bytes transferred to the initiator port for the nexus shall be less than or equal to 1 024, etc.). >> should be << (e.g., a value of one in this field specifies that the number

of bytes transferred to the initiator port for the nexus shall be less than or equal to 512, a value of two in this field specifies that the number of bytes transferred to the initiator port for the nexus shall be less than or equal to 1 024). >>

Page: 279 Sequence number: 3 Date: 1/6/2003 6:16:00 PM Type: Highlight ACCEPT - DONE (added "frame" after XFER\_RDY wherever it was not already followed by "information unit" or used in a signal name) 10.1.6.1.5 FIRST BURST SIZE field The term << XFER\_RDY frame >> is << XFER\_RDY >> in many other places in the standard. This needs to be stated one way. I believe just << XFER\_RDY >> is used everywhere else. Page: 279 Sequence number: 4 Date: 1/6/2003 6:16:00 PM Type: Highlight ACCEPT - DONE 10.1.6.1.5 FIRST BURST SIZE field The statement << (i.e., a value of one in this field specifies that the number of bytes transferred by the initiator port shall be less than or equal to 512, a value of two in this field specifies that the number of bytes transferred by the initiator port shall be less than or equal to 1 024, etc.). >> should be << (e.g., a value of one in this field specifies that the number of bytes transferred by the initiator port shall be less than or equal to 512, a value of two in this field specifies that the number of bytes transferred by the initiator port shall be less than or equal to 1 024). >> Page: 279 Sequence number: 5 Date: 1/6/2003 6:16:00 PM Type: Highlight ACCEPT - DONE 10.1.6.1.5 FIRST BURST SIZE field The statement << size, i.e., an initiator port shall transmit no data frames to the target port before receiving an XFER\_RDY frame. >> should be << size (i.e., an initiator port shall transmit no data frames to the target port before receiving an XFER\_RDY frame). >> Page: 281 Sequence number: 3 Date: 1/30/2003 1:45:04 PM Type: Highlight ACCEPT - DONE ("create" doesn't work. Changed to "recognizing") 10.1.6.2.2 Protocol-Specific Port mode page - short format The statement << connection time outs before treating it as an I\_T nexus loss >> should be << connection time outs before creating an I\_T nexus loss >> Page: 281 Sequence number: 4 Date: 1/14/2003 11:14:51 AM Type: Highlight ACCEPT - DONE 10.1.6.2.2 Protocol-Specific Port mode page - short format The statement << If the mode page is implemented, the default setting shall be 2 000 ms. >> is a problem. We have never specified a default value for a more page value. Why are we going it here? I don't believe we should start now. We could possibly recommend the value in a note. Reword to << Note xx: If this mode page is implemented a non-zero default value should be specified. It is recommend that this value be 2 000 ms. >> Page: 281 Sequence number: 5 Date: 1/30/2003 1:46:51 PM Type: Highlight REJECT (but changed to "never recognize an I\_T nexus loss". Details about specific OPEN\_REJECTs belong in the port layer.) 10.1.6.2.2 Protocol-Specific Port mode page - short format The statement << indicates the target port shall never consider rejections an I\_T nexus loss. >> should be << indicates the target port shall not stop retrying OPEN\_REJECT (NO DESTINATION), OPEN\_REJECT (CONNECTION RATE NOT SUPPORTED) connection requests. Page: 281

Date: 2/8/2003 12:18:52 PM Type: Strikeout REJECT - there is an SMP table with a field like number of phys that are not followed by descriptors. Why not make it clear? If the field were called "number of phy mode descriptors" I would agree (but I don't want to rename it to that) 10.1.6.2.3 Protocol-Specific Port mode page - Phy Control And Discover subpage The statement << and indicates the number of SAS phy mode descriptors that follow. >> is obvious and should be deleted. Page: 282 Sequence number: 1 Date: 1/6/2003 6:16:00 PM Type: Highlight REJECT - listing all the fields will take 1/4 of a page while conveying little useful information. These paragraphs just say they're defined elsewhere. 10.1.6.2.3 Protocol-Specific Port mode page - Phy Control And Discover subpage The statement << The PHY IDENTIFIER field, ATTACHED DEVICE TYPE field, NEGOTIATED PHYSICAL LINK RATE field, ATTACHED SSP INITIATOR bit, ATTACHED STP INITIATOR bit, ATTACHED SMP INITIATOR bit, ATTACHED SSP TARGET bit, ATTACHED STP TARGET bit, ATTACHED SMP TARGET bit, ATTACHED SAS ADDRESS field, SAS ADDRESS field, HARDWARE MINIMUM PHYSICAL LINK RATE field, and HARDWARE MAXIMUM PHYSICAL LINK RATE field are defined in the SMP DISCOVER function (see 10.3.1.4). >> needs to made into an a,b,c list. Page: 283 Sequence number: 1 Date: 1/30/2003 1:37:33 PM Type: Highlight REJECT (the list would take as much space as the table; it's just a redirection to another section anyway) 10.1.6.2.3 Protocol-Specific Port mode page - Phy Control And Discover subpage The statement << The PHY OPERATION field, PROGRAMMED MINIMUM PHYSICAL LINK RATE field, and PROGRAMMED MAXIMUM PHYSICAL LINK RATE field are defined in the SMP PHY CONTROL function >> . >> needs to made into an a.b.c list. Page: 283 Sequence number: 2 Date: 1/6/2003 6:16:00 PM Type: Highlight REJECT - this terminology works better for multiprotocol devices Table 124 The term << Protocol-specific log parameter >> should be changed to << SAS log parameter >> in all cases. Page: 284 Sequence number: 1 Date: 1/6/2003 6:16:00 PM Type: Highlight REJECT Table 125 The term << Protocol-specific log parameter >> should be changed to << SAS log parameter >> in all cases. Page: 285 Sequence number: 1 Date: 1/6/2003 6:16:00 PM Type: Highlight ACCEPT - DONE Table 126 Left justify all the entries in the << Description >> column. Page: 286 Sequence number: 1 Date: 1/6/2003 6:16:00 PM Type: Highlight REJECT 10.1.7.1 Protocol-Specific log page for SAS The statement << The PHY IDENTIFIER field, ATTACHED DEVICE TYPE field, NEGOTIATED PHYSICAL LINK RATE field, ATTACHED SSP INITIATOR bit, ATTACHED STP INITIATOR bit, ATTACHED SMP INITIATOR bit, ATTACHED SSP TARGET bit, ATTACHED STP TARGET bit, ATTACHED SMP TARGET bit, ATTACHED SAS ADDRESS field, and SAS ADDRESS field are defined in the SMP DISCOVER function (see 10.3.1.4). >> needs to made into an a,b,c list.

Date: 1/6/2003 6:16:00 PM Type: Highlight REJECT 10.1.7.1 Protocol-Specific log page for SAS The statement << The INVALID DWORD COUNT field, DISPARITY ERROR COUNT field, LOSS OF DWORD SYNCHRONIZATION field, and PHY RESET PROBLEM COUNT field are each defined in the SMP REPORT PHY ERROR LOG response data (see 10.3.1.5). >> needs to made into an a,b,c list. Page: 287 Sequence number: 7 Date: 2/3/2003 2:14:31 PM Type: Square ACCEPT - DONE (this was intended to be a brief overview of the spinup concept. Changed to: The logical unit uses NOTIFY (ENABLE SPINUP) to: a) automatically spin-up after power on; and b) delay spin-ups requested by START STOP UNIT commands. ) 10.1.8 SCSI power condition states The statement << a) after power on, if the target device has not received a START STOP UNIT command with the START bit set to zero, transition to the active power condition state after receiving NOTIFY (ENABLE\_SPINUP). The target device automatically transitions after power on without waiting for the application client; and b) after power on, if the target device has previously received a START STOP UNIT command with the START bit set to zero when it receives a START STOP UNIT command with the START bit set to one, spin-up after receiving the next NOTIFY (ENABLE\_SPINUP). The application client's request is effectively delayed until NOTIFY (ENABLE\_SPINUP) arrives. >> makes no sense in the context of this section. Something is wrong here and I have no idea what is going on here. This needs to be fixed. Page: 287 Sequence number: 8 Date: 1/6/2003 6:16:00 PM Type: Strikeout REJECT - the fact that it is a superset is important 10.1.8 SCSI power condition states The statement << The SA\_PC state machine is an enhanced version of the logical unit power condition state machines described in SPC-3, SBC-2, and RBC. >> doesn't add anything to SAS and should be deleted. Page: 287 Sequence number: 9 Date: 1/6/2003 6:16:00 PM Type: Highlight ACCEPT - DONE 10.1.8 SCSI power condition states The list of state machines needs cross-references and an indication of the initial state. Page: 288 Sequence number: 3 Date: 1/6/2003 6:16:00 PM Type: Note ACCEPT - DONE Figure 103 This drawing needs the orange background and the state machine title in it like all the other state machine drawings in this document. Page: 288 Sequence number: 4 Date: 1/6/2003 6:16:00 PM Type: Highlight REJECT - states are not always zero time, transitions are. The whole idea of a state is that it is "maintaining state" for some period of time 10.1.8.1.1 State description The statement << This state shall be entered upon power on. This state consumes zero time. >> should be << Upon power on this state shall be entered. >> All states are zero time so there is no need to state it here. Page: 289 Sequence number: 8 Date: 1/25/2003 4:51:27 PM Type: Highlight REJECT

10.1.8.2.2 Transition SA\_PC\_1:Active to SA\_PC\_2:Idle

The term << expires.>> should be << timed out >>.

Page: 289 Sequence number: 9 Date: 1/25/2003 4:51:16 PM Type: Highlight REJECT 10.1.8.2.3 Transition SA\_PC\_1:Active to SA\_PC\_3:Standby The term << expires.>> should be << timed out >> Page: 289 Sequence number: 10 Date: 1/25/2003 4:51:07 PM Type: Highlight REJECT 10.1.8.3.3 Transition SA\_PC\_2:Idle to SA\_PC\_3:Standby The term << expires.>> should be << timed out >>. Page: 290 Sequence number: 3 Date: 1/6/2003 6:16:00 PM Type: Highlight REJECT - that requirement is for SBC-2 to state, not this standard. 10.1.8.5.1 State description The statement << This state is only implemented >> should be << This state shall only implemented >> Page: 291 Sequence number: 10 Date: 1/6/2003 6:16:00 PM Type: Highlight ACCEPT - DONE 10.1.8.6.1 State description The statement << This state is only implemented >> should be << This state shall only implemented >>. Page: 291 Sequence number: 11 Date: 2/1/2003 2:08:53 PM Type: Highlight **REVIEW PROTOCOL WG** REJECT (It is indeed the transition or perhaps the entry into the state that causes excess power, not the fact of being in the new state itself (idle might use 1 W, idle->active might use 50 W for a brief period, then active might drop to 15 W.) 10.1.8.6.2 Transition SA\_PC\_5:Active\_Wait to SA\_PC\_1:Active \*\*\*\* The statement << the device does not temporarily consume additional power during the transition to SA\_PC\_1:Active. >> should be << the device does not temporarily consume additional power as a result of a transition to SA PC 1:Active. >> but I don't understand what this is all about. The statement itself tells me nothing. This needs to be fixed. Page: 291 Sequence number: 12 Date: 1/25/2003 4:51:53 PM Type: Highlight REJECT 10.1.8.6.3 Transition SA\_PC\_5:Active\_Wait to SA\_PC\_3:Standby The term << expires.>> should be << timed out >> Page: 291 Sequence number: 13 Date: 1/25/2003 4:52:02 PM Type: Highlight REJECT 10.1.8.6.5 Transition SA\_PC\_5:Active\_Wait to SA\_PC\_6:Idle\_Wait The term << expires.>> should be << timed out >>. Page: 291 Sequence number: 14 Date: 1/6/2003 6:16:00 PM Type: Highlight ACCEPT - DONE 10.1.8.7.1 State description

The statement << This state is only implemented >> should be << This state shall only implemented >>

Page: 291 Sequence number: 15 Date: 1/22/2003 5:40:16 PM Type: Highlight REJECT (going with expires everywhere) 10.1.8.7.3 Transition SA\_PC\_6:Idle\_Wait to SA\_PC\_3:Standby The term << expires.>> should be << timed out >> Page: 292 Sequence number: 2 Date: 1/6/2003 6:16:00 PM Type: Highlight ACCEPT - DONE (but added VPD to the acronym list and "(VPD)" to the 1.1.9 section header, its first use) 10.1.9 SCSI vital product data The statement << the Device Identification vital product data (VPD) page (83h) >> should be << the Device Identification VPD page (83h) >> Page: 292 Sequence number: 3 Date: 1/6/2003 6:16:00 PM Type: Highlight ACCEPT - DONE (twice) Table 128 The statement << The IDENTIFIER field contains the SAS address of the target port being used to run the INQUIRY command. >> should be << The IDENTIFIER field contains the SAS address of the target port though which the INQUIRY command was received. >> Page: 294 Sequence number: 2 Date: 2/1/2003 2:22:49 PM Type: Strikeout REJECT (this explains why the CRC field, owned by the link layer, is shown in this application layer section. Added xref to SMP link layer; added similar sentence for SMP FRAME TYPE and transport layer.) 10.3.1.1 Function overview The statement << The CRC field is included in each frame, although that field is parsed by the link layer. >> should be deleted as it is information that is stated else where and should not be here. Page: 296 Sequence number: 6 Date: 1/6/2003 6:16:00 PM Type: Highlight ACCEPT - DONE 10.3.1.2 REPORT GENERAL function The statement << 1) Table 131 defines the response format. >> should not have a << 1) >> in it. This needs to be fixed. Page: 296 Sequence number: 7 Date: 1/6/2003 6:16:00 PM Type: Highlight ACCEPT - DONE 10.3.1.2 REPORT GENERAL function The statement << for either of the following reasons: >> should be << for the following reasons: >> Page: 296 Sequence number: 8 Date: 1/6/2003 6:16:00 PM Type: Note ACCEPT - DONE 10.3.1.2 REPORT GENERAL function The << EXPANDER ROUTE INDEXES field >> and the << CONFIGURABLE ROUTE TABLE>> need some cross references to where the expander route table is defined and the configurable route table is defined. Page: 297 Sequence number: 4 Date: 1/6/2003 6:16:00 PM Type: Highlight ACCEPT - DONE

10.3.1.2 REPORT GENERAL function << table that shall be configured. >> should be << table that is required to be configured. >> Page: 298 Sequence number: 4 Date: 1/22/2003 9:35:00 AM Type: Highlight ACCEPT - DONE (Jan WG; with mods per 03-060; George will propose that SPC-3 use "shall" here too) 10.3.1.3 REPORT MANUFACTURER INFORMATION function \*\*\*\* The statement << The vendor identification string should be one defined >> should be << The vendor identification string shall be as defined >> Page: 299 Sequence number: 3 Date: 1/6/2003 6:16:00 PM Type: Highlight ACCEPT - DONE 10.3.1.4 DISCOVER function The statement << by the phy, as well as the routing attribute supported >> should be << by the phy and the routing attribute supported >> Page: 299 Sequence number: 4 Date: 2/3/2003 2:20:04 PM Type: Highlight ACCEPT - TODO (this is hard to search for) 10.3.1.4 DISCOVER function Global The usage of small caps should be limited to field names only. The use when talking about the value is not correct (e.g., NUMBER OF PHYS and FUNCTION RESULT) here. This needs to be fixed. Page: 301 Sequence number: 3 Date: 1/6/2003 6:16:00 PM Type: Highlight ACCEPT - DONE 10.3.1.4 DISCOVER function The statement << complete (when a SAS device is attached) or after the initial Register - Device to Host FIS has been received (when a SATA device is attached). >> should be << complete if a SAS device is attached or after the initial Register - Device to Host FIS has been received if a SATA device is attached. >> Page: 301 Sequence number: 4 Date: 1/21/2003 7:10:12 PM Type: Highlight ACCEPT - DONE (see Vixel comment: second sentence removed, "method" added into descriptions in table) 10.3.1.4 DISCOVER function The statement << The ROUTING ATTRIBUTE field shall not change based on the attached device type. The routing method used by the expander connection manager shall change based on the attached device type as described in table 137. >> If not clear as to the point that is trying to be made. This needs to be fixed or deleted. Page: 302 Sequence number: 6 Date: 1/6/2003 6:16:00 PM Type: Highlight ACCEPT - DONE (see Maxtor resolution) 10.3.1.4 DISCOVER function In the statement << link rate if they have been >> what it the << they >> referring to. This needs to be fixed. Page: 302 Sequence number: 7 Date: 2/8/2003 12:20:44 PM Type: Strikeout REJECT (without that phrase the whole note is meaningless, and the group at least at one time felt the note was worth maintaining) Table 139 The statement << in its local data structures >> should be deleted as that kind of data structure is not defined anywhere.

Page: 302 Sequence number: 8 Date: 1/6/2003 6:16:00 PM Type: Note REJECT - these sentences just refer to the other bits for their meaning. Will add cross references to the IDENTIFY address frame. 10.3.1.4 DISCOVER function All the << The xxx bit indicates the xxx value received during the link reset sequence. >> should be for example<< An ATTACHED SSP INITIATOR bit set to one indicates an SSP initiator is attached. An ATTACHED SSP INITIATOR bit set to zero indicates an SSP initiator is not attached. >> Page: 302 Sequence number: 9 Date: 1/6/2003 6:16:00 PM Type: Highlight ACCEPT - DONE 10.3.1.4 DISCOVER function The statement << completes, when a SAS device is attached; >> should be << completes if a SAS device is attached; >> Page: 302 Sequence number: 10 Date: 1/6/2003 6:16:00 PM Type: Highlight ACCEPT - DONE 10.3.1.4 DISCOVER function The statement << completes, when a SATA device is attached; >> should be << completes if a SATA device is attached; >> Page: 303 Sequence number: 4 Date: 1/29/2003 12:44:29 PM Type: Highlight ACCEPT - DONE (Jan WG Note added for a recommended default) 10.3.1.4 DISCOVER function The statement << The default value for PARTIAL PATHWAY TIMEOUT VALUE shall be 7 µs. >> is a problem. We have never specified a default value for a mode page value. Why are we going it here? I don't believe we should start now. We could possibly recommend the value in a note. Reword to << Note xx: If this function is implemented a it is recommend that this value be 7 µs. >> Page: 305 Sequence number: 5 Date: 1/6/2003 6:16:00 PM Type: Highlight ACCEPT - DONE 10.3.1.5 REPORT PHY ERROR LOG function The statement << have been received (outside of phy reset sequences). >> should be << have been received outside of phy reset sequences. >> Page: 305 Sequence number: 6 Date: 1/6/2003 6:16:00 PM Type: Highlight ACCEPT - DONE 10.3.1.5 REPORT PHY ERROR LOG function The statement << have been received (outside of phy reset sequences). >> should be << have been received outside of phy reset sequences. >> Page: 305 Sequence number: 7 Date: 1/6/2003 6:16:00 PM Type: Highlight ACCEPT - DONE 10.3.1.5 REPORT PHY ERROR LOG function The statement << has been lost (outside of phy reset sequences). >> should be << has been lost outside of phy reset sequences. >>. Page: 307 Sequence number: 3 Date: 1/6/2003 6:16:00 PM Type: Highlight ACCEPT - DONE (with "may be used")

The statement << This function is used primarily as a diagnostic tool to resolve topology issues. >> should be << This function is used to resolve topology issues. >> Page: 308 Sequence number: 2 Date: 1/6/2003 6:16:00 PM Type: Highlight ACCEPT - DONE 10.3.1.7 REPORT ROUTE INFORMATION function The statement << the table routing attribute (see 4.x.x.x) the >> needs a real cross reference. Page: 312 Sequence number: 4 Date: 1/6/2003 6:16:00 PM Type: Highlight ACCEPT - DONE 10.3.1.8 CONFIGURE ROUTE INFORMATION function The statement << the table routing attribute (see 4.x.x.x) the >> needs a real cross reference. Page: 312 Sequence number: 5 Date: 1/29/2003 6:30:50 PM Type: Note REJECT - in this response there is no such data to worry about - just the CRC (moot with combined table) Table 152 What happened to the << rest of data is invalid. >> statement in the two descriptions. It should be stated here also. Page: 314 Sequence number: 1 Date: 1/21/2003 4:41:38 PM Type: Highlight ACCEPT - DONE 10.3.1.9 PHY CONTROL function The << PROGRAMMED MINIMUM PHYSICAL LINK RATE field >> and << PROGRAMMED MAXIMUM PHYSICAL LINK RATE field >> need to be described in separate paragraphs. Page: 314 Sequence number: 2 Date: 1/6/2003 6:16:00 PM Type: Highlight REJECT (but raises a bigger issue filed as a PostLB comment) 10.3.1.9 PHY CONTROL function The statement << may be set beforehand >> should be << may be sent in an operation other than a LINK RESET operation before a LINK RESET is sent. >> Page: 316 Sequence number: 1 Date: 1/6/2003 6:16:00 PM Type: Note ACCEPT - DONE (this response frame doesn't have any "rest of data" to worry about, so removed it from 10h. This comment prompted adding it to one of the REPORT PHY SATA results). Table 157 What happened to the << rest of data is invalid. >> statement in the two descriptions. It should be stated here also. Page: 319 Sequence number: 1 Date: 1/6/2003 6:16:00 PM Type: Note ACCEPT - DONE A.1 Compliant jitter test pattern (CJTPAT) The statements << The second column (8b data dword) lists the >> and << The third column (Scrambler output dword) lists >> and << The fourth column (Scrambled 8b data dword) shows >> need to reference the table to which they are referencing. Page: 326 Sequence number: 1 Date: 1/6/2003 6:16:00 PM Type: Highlight ACCEPT - DONE (deleted the whole paragraph)

10.3.1.7 REPORT ROUTE INFORMATION function

C.1 CRC generator and checker implementation examples

I.2 Header file

The statement << 1, 2, and 3 below are included to provide a validation >> needs a more precise. The reference to <<below >> needs to be more accurate.

Page: 330 Sequence number: 1 Date: 1/6/2003 6:16:00 PM Type: Highlight ACCEPT - DONE D.1 Hashing overview The statement << 4.2.2 describes hashed SAS addresses >> should be << See 4.2.2 for a description of the hashed SAS addresses >> Page: 330 Sequence number: 2 Date: 1/20/2003 6:12:26 PM Type: Note REJECT (all the decimal points are lined up, which makes these bizarre ISO formatted numbers more readable) Table D.1 Center all the cells. Page: 331 Sequence number: 1 Date: 1/6/2003 6:16:00 PM Type: Highlight ACCEPT - DONE also changed the may later in the sentence D.3 Hash generation The statement << length can be treated as >> should be << length is treated as >>. Page: 332 Sequence number: 1 Date: 1/6/2003 6:16:00 PM Type: Highlight ACCEPT - DONE D.5 Hash implementation with XORs The statement << 24-bit HASHED SAS ADDRESS field for the SSP frame >> should be << 24-bit hashed SAS address for the SSP frame >> . Page: 336 Sequence number: 1 Date: 1/6/2003 6:16:00 PM Type: Strikeout ACCEPT - DONE E.1 Scrambler implementation in C The term << specified >> should be deleted. Page: 340 Sequence number: 1 Date: 1/6/2003 6:16:00 PM Type: Highlight REJECT - why use 11 characters when 4 suffice? F.3 Byte and bit ordering The statement << Thus, the first byte contains the least >> should be << As a result the first byte contains the least >> Page: 360 Sequence number: 1 Date: 1/6/2003 6:16:00 PM Type: Highlight ACCEPT - DONE H.1 Overview The statement << Hamming distance (the number of bits different in two patterns) of at least >> should be << Hamming distance (i.e., the number of bits different in two patterns) of at least >>. Page: 366 Sequence number: 1 Date: 1/25/2003 4:56:59 PM Type: Highlight ACCEPT - DONE ("initialize before use")

The statement << SMP Request, must be initialized >> should be << SMP Request, is initialized >>.

Page: 369 Sequence number: 1 Date: 1/25/2003 4:57:33 PM Type: Highlight ACCEPT - DONE ("initialize before use") 1.2 Header file The statement << SMP Response, must be initialized >> should be << SMP Response, is initialized >> Page: 370 Sequence number: 1 Date: 1/25/2003 4:58:21 PM Type: Highlight ACCEPT - DONE I.2 Header file The statement << file will perform the >> should be << file performs the >>. Page: 371 Sequence number: 2 Date: 1/30/2003 11:00:33 AM Type: Highlight ACCEPT - DONE 1.3 Source file The statement << change primitives will initiate >> should be << change primitives initiate >>. Page: 371 Sequence number: 3 Date: 1/25/2003 5:04:32 PM Type: Highlight ACCEPT - DONE 1.3 Source file The statement << discover information will end up >> should be << discover information ends up >>. Page: 372 Sequence number: 1 Date: 1/25/2003 5:05:06 PM Type: Highlight ACCEPT - DONE I.2 Header file The statement << expander in the chain must be configured >> should be << expander in the chain is configured >>. Page: 373 Sequence number: 1 Date: 1/25/2003 5:07:15 PM Type: Highlight ACCEPT - DONE (removed warning) 1.2 Header file The statement << production code must handle >> should be << production code handles >>. Requirements cannot be in an informative annex. Page: 373 Sequence number: 2 Date: 1/25/2003 5:06:29 PM Type: Highlight ACCEPT - DONE (this isn't a requirement it's a warning that the code isn't complete here. Removed, however.) 1.2 Header file The statement << production code must handle >> should be << production code handles >>. Requirements cannot be in informative annex. Page: 374 Sequence number: 1 Date: 1/25/2003 5:08:01 PM Type: Highlight ACCEPT - DONE 1.3 Source file The statement << this routine will add a SAS Address >> should be << this routine adds a SAS Address >>.

Sequence number: 2 Date: 1/25/2003 5:08:04 PM Type: Highlight ACCEPT - DONE I.3 Source file The statement << this routine will add a SASAddress >> should be << this routine adds a SASAddress >>. Page: 374 Sequence number: 3 Date: 1/25/2003 5:08:07 PM Type: Highlight ACCEPT - DONE 1.3 Source file The statement << this routine will reset the ChainEntry >> should be << this routine resets the ChainEntry >>. Page: 375 Sequence number: 1 Date: 1/25/2003 5:08:12 PM Type: Highlight ACCEPT - DONE I.3 Source file The statement << this routine will get the route index >> should be << this routine gets the route index >>. Page: 375 Sequence number: 2 Date: 1/25/2003 5:08:15 PM Type: Highlight ACCEPT - DONE I.3 Source file The statement << this routine will get the >> should be << this routine gets the >>. Page: 379 Sequence number: 1 Date: 1/25/2003 5:09:13 PM Type: Highlight ACCEPT - DONE I.3 Source file The statement << this routine will append >> should be << this routine appends >>. Page: 380 Sequence number: 1 Date: 1/25/2003 5:09:23 PM Type: Highlight ACCEPT - DONE 1.3 Source file The statement << DiscoverProcess will get >> should be << DiscoverProcess gets >>. Page: 380 Sequence number: 2 Date: 1/25/2003 5:09:51 PM Type: Highlight ACCEPT - DONE I.3 Source file The statement << we find will naturally move >> should be << we find naturally moves >>. Page: 382 Sequence number: 4 Date: 1/6/2003 6:16:00 PM Type: Note REJECT - I see no such header with Acrobat 5.0.5 Annex J There seems to a bogus frame title at the end of the document. It shows up as an << untitled >> entry in the bookmarks list in Acrobat which seems to be hyper linked to something on page 172.

## Author: INTC

Page: ii Sequence number: 2 Date: 12/30/2002 10:44:33 AM Type: Highlight ACCEPT - DONE Front matter HIS s/b IHS Page: iii Sequence number: 3 Date: 1/7/2003 11:09:04 AM Type: Highlight ACCEPT - DONE (see IBM and LSI comments) Abstract "Serial ATA compatible physical layer": partly true, but overly limited. Implies that SATA is used as-is, across the board. Expand/clarify. Page: iv Sequence number: 1 Date: 1/7/2003 11:13:31 AM Type: Highlight ACCEPT - DONE (changed to 2003) ANSI stuff 2002 s/b 2003 or 200x Page: xxxi Sequence number: 1 Date: 1/7/2003 1:52:38 PM Type: Highlight ACCEPT - DONE (spaces after figure number) TOC Fix para formatting for Annex TOC entries Page: xxxiii Sequence number: 5 Date: 1/7/2003 1:52:56 PM Type: Highlight ACCEPT - DONE (removed "of "instead to match other standards) Foreword Fix 'of it' or reword for clarification from "At the time of it approved this standard, INCITS had the following members:" to "At the time of standard approval, INCITS had the following members:" Page: 5 Sequence number: 5 Date: 2/6/2003 11:45:47 AM Type: Highlight ACCEPT - DONE (new ATA terminology per Mark Evans proposal. George won't allow us to use quotes around referenced terms.) 3.1.3 ATA device NOTE 4 "uses the term device": place single quotes around words when the word itself is referenced: the term 'device', the term 'target device' Page: 5 Sequence number: 6 Date: 2/6/2003 11:45:07 AM Type: Highlight ACCEPT - DONE (new ATA terminology per Mark Evans proposal) 3.1.4 ATA domain "(ATA) service delivery subsystem": Clarify whether this has the same defn as the SCSI SDS Page: 5 Sequence number: 7 Date: 2/6/2003 11:44:45 AM

Type: Highlight ACCEPT - DONE (new ATA terminology per Mark Evans proposal) 3.1.6 ATA initiator port "Equivalent to a host adapter": 'initiator port' is an abstraction, 'host adapter' is, at least in one sense, a piece of hardware. Clarify model, and that reference to 'HA' is to the term 'HA', not a thing. (FRAG) Page: 5 Sequence number: 8 Date: 1/7/2003 2:12:59 PM Type: Highlight ACCEPT - DONE 3.1.3 ATA device NOTE 4 GLOBAL "ATA/ATAPI V1": Be consistent w/ 2.4, which uses ATAPI-7 (GLOBAL) Page: 5 Sequence number: 9 Date: 2/6/2003 11:44:38 AM Type: Highlight ACCEPT - DONE (new ATA terminology per Mark Evans proposal) 3.1.9 ATA target port "task router" does not appear in ATAPI7. Use correct ATA terminology. Page: 5 Sequence number: 10 Date: 2/6/2003 1:58:55 PM Type: Highlight ACCEPT - DONE 3.1.14 byte 8 s/b 'eight' Page: 5 Sequence number: 11 Date: 2/6/2003 1:59:01 PM Type: Highlight ACCEPT - DONE 3.1.15 character 10 s/b 'ten' Page: 6 Sequence number: 13 Date: 2/7/2003 5:24:40 PM Type: Highlight ACCEPT - DONE (application client runs the discover process - fixed globally) 3.1.30 discover process management application client: Clarify whether 'process' means 'algorithm' or some executing code. Page: 6 Sequence number: 14 Date: 1/22/2003 9:49:51 AM Type: Highlight ACCEPT - DONE (delete it. That will mean no special meaning) 3.1.25 device 'A physical entity' seems quite vague. Clarify whether that is the intent. Page: 6 Sequence number: 15 Date: 1/7/2003 2:18:28 PM Type: Highlight ACCEPT - DONE 3.1.34 (Page 6) dword synchronization Add '(see 6.9)' Page: 7 Sequence number: 12 Date: 12/30/2002 1:45:08 PM

Type: Highlight ACCEPT - DONE 3.1.45 expander route index Fix typo -- change "a" to "an" Page: 7 Sequence number: 13 Date: 2/7/2003 5:56:11 PM Type: Highlight ACCEPT - TODO (make "with" the most common usage throughout)(still broken) 3.1.47 fanout expander device 'no phys with subtractive' - ambiguous. Change 'with' to 'having' Page: 7 Sequence number: 14 Date: 2/6/2003 3:47:57 PM Type: Highlight ACCEPT - DONE 3.1.40 (Page 7) expander device Make defn more generic - It provides connectivity by routing frames. Page: 7 Sequence number: 15 Date: 2/7/2003 11:01:50 AM Type: Highlight ACCEPT - DONE (new generic definition) 3.1.43 (Page 7) expander port "A SAS expander device object that routes SSP, SMP, and STP frames to and from physical links or to internal initiator ports and/or target ports. Contains one or more phys." Either add: 'routes primitives, primitive sequences and other frames too.' or make more generic by not listing every function. Page: 8 Sequence number: 12 Date: 2/7/2003 6:34:07 PM Type: Highlight TODO (Cris Simpson will think up some wording) 3.1.62 indication indication: Defn is same as for 'confirmation'. Clarify whether they are identical. Page: 9 Sequence number: 14 Date: 1/20/2003 6:08:39 PM Type: Highlight ACCEPT - DONE (changed to lowercase p-like) 3.1.95 reflection coefficient This is the upper-case greek letter "gamma". It normally represents a complex number indicating phase as well as magnitude. Later, the char 'rho' is used, representing abs val. Page: 9 Sequence number: 15 Date: 2/7/2003 6:49:25 PM Type: Highlight ACCEPT - DONE (reworded to match new object hierarchy) 3.1.84 phv "interfaces to a service delivery subsystem" Please confirm intent that phy is outside the SDS. Page: 9 Sequence number: 16 Date: 2/7/2003 6:47:51 PM Type: Highlight TODO (Cris Simpson working on wording) 3.1.98 response response: Confirm intent that this be interchangable with 'request'

Page: 9 Sequence number: 17 Date: 1/17/2003 5:47:34 PM Type: Highlight ACCEPT - TODO (see other comment) 3.1.83 (Page 9) pathway "A set of physical links between a SAS initiator port and a SAS target port" Use defn from 4.1.12: "A pathway is the physical route of a connection." Page: 9 Sequence number: 18 Date: 1/7/2003 2:45:33 PM Type: Highlight REJECT - consecutive may mislead because of interspersed ALIGNs. The cross reference defines it in detail. 3.1.91 (Page 9) primitive sequence "A set of primitives" change to "A set of one or more consecutive primitives" Page: 9 Sequence number: 19 Date: 2/7/2003 6:36:24 PM Type: Highlight TODO (Cris Simpson working on wording) 3.1.96 (Page 9) request: "request" has the same definition as "response" Clarify the differenence between the two. Page: 9 Sequence number: 20 Date: 2/7/2003 6:48:29 PM Type: Highlight REJECT 3.1.100 (Page 9) SAS device "an ATA device" - Change 'device' to 'object' Page: 10 Sequence number: 8 Date: 2/7/2003 6:50:56 PM Type: Highlight REJECT (SAS port and expander port kept separate in new model) 3.1.104 SAS port an expander port is also a SAS port, although it doesn't have a SAS address. Add 'expander port'. Page: 10 Sequence number: 9 Date: 2/7/2003 6:50:34 PM Type: Highlight ACCEPT - DONE (new ATA wording rewrote this) 3.1.102 (Page 10) SAS initiator device: a SMP initiator device is also a SAS initiator device Page: 10 Sequence number: 10 Date: 2/7/2003 6:50:28 PM Type: Highlight ACCEPT - DONE (new ATA wording rewrote this) 3.1.106 (Page 10) SAS target device: Add SSP, SMP, STP target devices, and initiators. Page: 11 Sequence number: 10 Date: 1/17/2003 4:58:42 PM Type: Highlight ACCEPT - TODO (phy definition fixed) 3.1.127 service delivery subsystem 'service requests' SDS defn appears to be at odds with that

Page: 11 Sequence number: 11 Date: 1/20/2003 4:02:16 PM Type: Highlight ACCEPT (definition rewritten by PHY WG) 3.1.129 spread spectrum clocking increase -> widen Page: 11 Sequence number: 12 Date: 1/20/2003 4:02:19 PM Type: Highlight ACCEPT (definition rewritten by PHY WG) 3.1.129 spread spectrum clocking peaks -> peak amplitude Page: 11 Sequence number: 13 Date: 1/7/2003 3:03:12 PM Type: Highlight REJECT - we don't do anything to break linked command usage 3.1.141 task "linked commands" - remove if linked cmds not supported Page: 11 Sequence number: 14 Date: 1/22/2003 10:40:30 AM Type: Highlight ACCEPT - DONE 3.1.128 (Page 11) speed negotiation sequence "determine the highest common supported physical link rate" change to "negotiate the operational physical link rate" Page: 11 Sequence number: 15 Date: 1/7/2003 3:00:39 PM Type: Highlight ACCEPT - DONE 3.1.128 speed negotiation sequence 'where' s/b 'by which' Page: 13 Sequence number: 5 Date: 1/20/2003 6:08:08 PM Type: Highlight ACCEPT - DONE 3.2 symbols and abbreviations The lower-case greek letter "rho" is normally used to represent the "absolute" reflection coefficient (real ratio of incident to reflected voltage). It looks like an italics lower-case roman letter 'p'. Page: 17 Sequence number: 7 Date: 1/17/2003 12:29:43 PM Type: Highlight TODO (Cris will investigate an alternate term that is not message or signal) 3.5.3 Parameters, requests, indications, confirmations, and responses "Parameters": Incorrect use of the term 'parameter' to mean 'signal', 'notification', or 'indication' (in the generic sense). Replace with one of these or an appropriate term that better reflects what's really being passed. If nothing else, call it a 'message' or an 'object', so that it can carry multiple parameters, as is the actual case.

Page: 19 Sequence number: 4 Date: 1/23/2003 2:36:07 PM Type: Highlight REJECT (expander device is not a SAS device, but contains one. Changed to match new glossary definition.) 4.1.1 (Page19) Architecture overview "A SAS device (see 4.1.4) is an ATA device or SCSI device with ports in a SAS domain:" Expander device is also a SAS device as defined on page 9, 3.1.100 SAS device. Page: 19 Sequence number: 5 Date: 1/23/2003 2:36:45 PM Type: Highlight REJECT (yes they are; fixed the phy definition, which should help reduce confusion) 4.1.1 (Page 19) Architecture overview "The service delivery subsystem in a SAS domain may include expander devices" Expander devices are not part of the "service delivery subsystem. Expander device interfaces to the SAS service delivery subsystem. This is also shown in Figure 4 on page 20. Page: 21 Sequence number: 10 Date: 1/23/2003 3:15:11 PM Type: Highlight ACCEPT - DONE 4.1.3 (Page 21) Ports (narrow ports and wide ports) "A port may contain one or more phys." should be A port contains one or more phys. Page: 21 Sequence number: 11 Date: 1/23/2003 3:14:47 PM Type: Highlight ACCEPT - DONE (rewritten) 4.1.3 Ports (narrow ports and wide ports) Clarify whether the SAS address of the port or the device. Page: 23 Sequence number: 3 Date: 1/22/2003 3:04:46 PM Type: Highlight REJECT (but the SP state machine supports both modes, and this is a common question)(whole section deleted anyway) 4.1.5 Initiator devices "Initiator ports may support SSP and/or STP and/or SATA." SAS initiator does not support native SATA as stated below -"Initiator ports supporting SATA are outside the scope of this standard." Page: 24 Sequence number: 7 Date: 1/22/2003 3:06:24 PM Type: Highlight REJECT (whole section being deleted) 4.1.6 Target devices Figure 9 Target device: Figure doesn't match text. Figure should show SATA target device/port, perhaps as a separate block attached to the Service delivery subsystem. Page: 24 Sequence number: 8 Date: 1/22/2003 3:06:39 PM Type: Highlight REJECT (whole section being deleted) 4.1.6 Target devices SAS target device does not support SATA, it can support ATA target. Confusing.

Page: 25 Sequence number: 8 Date: 12/30/2002 10:07:22 AM Type: Highlight 4.1.8.2 Edge expander device set This sentence needs to be clarified in terms of the phys of other edge expander devices that the phys that support table routing can be attached to (eg., direct routing, subtractive routing, table routing, or all of the above) Figure 11 implies that it would only attach to a subtractive port. Page: 25 Sequence number: 9 Date: 1/17/2003 4:55:15 PM Type: Highlight ACCEPT - TODO (fixed phy definition) 4.1.8.1 Expander device overview "Expander devices are part of the service delivery subsystem" appears to be in conflict with glossary defn for phy. Clarify SDS model. Page: 25 Sequence number: 10 Date: 2/8/2003 11:14:41 AM Type: Highlight ACCEPT - DONE (changed glossary to "may contain subtractive routing attributes") 4.1.8.1 Expander device overview subtractive routing attribute defined in Clause 3 and general concept is clear; however, the delineation between edge/fanout due to subtractive routing is unclear. Conflicts with defn for 'edge expander device'. Please clarify. glossary is: An expander device containing phys with subtractive routing attributes (see 4.1.8.1). Page: 25 Sequence number: 11 Date: 1/17/2003 4:49:12 PM Type: Highlight REJECT (this is true) 4.1.8 (Page 25) Expander device overview "Expander devices are part of the service delivery subsystem." - expander is not part of the service delivery subsystem as shown in Fig. 4 on page 20. Expander interface to the service delivery subsystem. Page: 25 Sequence number: 12 Date: 1/17/2003 4:38:26 PM Type: Highlight ACCEPT - TODO (SAS initiator ports, SAS or SATA target ports, or expander ports) 4.1.8.1 Expander device overview Fig 10 (Pae 25) Expander device Expander only interface to SATA target. The diagram is not clear that it seems it also allows the expander device interface to SATA initiators, SATA expander ports. Page: 25 Sequence number: 13 Date: 1/17/2003 4:33:15 PM Type: Highlight REJECT (we once tried to call that an edge router, but the WG preferred to keep it in the edge expander device class) 4.1.8.1 Expander device overview "There are two types of expander devices differentiated by the routing attributes of their phys, edge expander devices and fanout expander devices." The expander device which is not the leaf edge expander within the edge expander set behaves differently than an edge expander and fanout expander. It has the routing capability as the fanout expander but it also has a subtractive port which fanout expander does not have. Thus, there are THREE types.

Page: 25 Sequence number: 14 Date: 12/30/2002 10:07:22 AM Type: Highlight 4.1.8.2 (Page 25) Edge expander device set "attached to the phys supporting subtractive routing on another edge expander device set;" change to "attached to the phys supporting subtractive routing on another edge expander or edge expander device set;" to make it clear even an edge expander is a subset of edge expander set Page: 26 Sequence number: 5 Date: 1/17/2003 4:27:02 PM Type: Highlight ACCEPT - TODO (a self-configuring expander really contains a mgmt app client and initiator port to do the work...) 4.1.8.3 (Page 26) Configurable expander device "Expander devices with a configurable route table [MAY] depend on the application client within one or more initiator devices to use the discover process (see 4.6.11.5) to configure the expander route table." The edge expander set can self-initialize itself. Page: 27 Sequence number: 2 Date: 1/23/2003 4:26:47 PM Type: Highlight ACCEPT - DONE 4.1.9 Domains Figure 12 Add 'STP' targ port. Page: 27 Sequence number: 3 Date: 1/23/2003 4:24:29 PM Type: Highlight ACCEPT - DONE (add some SMP boxes and add note that normally SMP targets are inside the cloud) 4.1.9 Domains Figure 12 Also need to show SMP connections in the SAS domain. Page: 27 Sequence number: 4 Date: 1/23/2003 4:27:40 PM Type: Highlight REJECT (the "other expander ports" phrase covers STP passthru)(but whole paragraph deleted anyway) 4.1.9 (Page 27) Domains "The expander port attached to a SATA target port translates STP to SATA;" It should also mention the case where the expander attached to a STP target port where the expander only need to pass thru STP traffic. Page: 28 Sequence number: 5 Date: 1/23/2003 4:30:02 PM Type: Highlight REJECT (An edge expander device set is not an edge expander device. An edge expander device set is not a SAS device. An edge expander device is not a SAS device (although it contains one). Each edge expander device has its own SAS address. Thus, an edge expander device set has lots of SAS addresses.) 4.1.10 (Page 28) Expander device topologies Clarify: Is edge expander device set a \_single\_ SAS device? Probably not because edge expander device set has one or more device name? Page: 29 Sequence number: 5 Date: 1/23/2003 4:47:51 PM Type: Highlight ACCEPT - DONE (add "temporary." Pull in second sentence from the glossary too (not necessarily as the 2nd sentence here; wording changes may be appropriate))

4.1.11 (Page 29) Connections "A connection is an association between an initiator port and a target port." A "connection" is a physical path that is logically established and has the right to pass information between the initiator and the target as only as the logical establishment is maintained. Clarify. 3.1.x has "A temporary association between an initiator port and a target port (see 7.12). During a connection all transmitted dwords are associated with the I\_T nexus formed by that initiator port and target port." Page: 30 Sequence number: 11 Date: 1/23/2003 5:04:53 PM Type: Highlight ACCEPT - DONE 4.1.11 Connections "to pathway" changed to "the pathway" Page: 31 Sequence number: 5 Date: 1/17/2003 2:36:52 PM Type: Highlight ACCEPT - TODO (pull the 4.1.12 definition into 3.1.83, but change "required" to "used" in both places) 4.1.12 Pathways "the pathway consists of all the physical links required to route dwords between the initiator phy and the target phy" Definition is not quite the same as defined in 3.1.83 on page 9 which says: A set of physical links between a SAS initiator port and a SAS target port (see 4.1.12). Page: 31 Sequence number: 6 Date: 1/17/2003 2:31:28 PM Type: Highlight ACCEPT - TODO (see other comments; more clarification/examples obviously needed) 4.1.10 Expander device topologies Figure 17 - Multiple connections on wide ports Initiator \*\*\* This Initiator shows two ports. The Expander device has two corresponding Expander ports. CLARIFY how the expander can determine there are two ports if the initiator reports the same "device" SAS address in the Identify address frame on all 6 phys? Need an overview of multi-ported devices and usage of device & port SAS addresses. Page: 33 Sequence number: 2 Date: 2/9/2003 4:20:01 PM Type: Highlight ACCEPT - DONE (add Device name section 4.2.x and make sure it points to the VPD page for targets. Removed this paragraph; put the appropriate shalls in the Device name and Port identifier sections. Moved Note 7 into the Device names section.) 4.2.2 SAS addresses Specify which one is reported when device has multple ports in the same domain. Page: 34 Sequence number: 4 Date: 2/9/2003 4:29:06 PM Type: Highlight ACCEPT - DONE (Add ref to IDENTIFY and OPEN address frames where port identifiers are used. In the new Device name section, reference IDENTIFY where the device name is used.) 4.2.5 Port identifiers Clarify whether this is the SAS address reported in the Identify message, or is it the "device" SAS address? Page: 49 Sequence number: 13 Date: 1/7/2003 6:24:28 PM

Type: Highlight ACCEPT - DONE (broadcast primitive processor) 4.6.1 Expander device model overview bullet a).C) Is this the "Broadcast" Primitive Processor? If so, I think the original "Broadcast" was clearer. If not, then the "BPP" acronym doesn't match. Other places including the Acronym glossary in section 3.2, and section 4.6.5, "BPP" continues to be referred to as the "Broadcast Primitive Processor". Page: 49 Sequence number: 14 Date: 1/24/2003 9:35:02 AM Type: Highlight TODO (maybe an informative annex of examples or add addresses to other pictures) 4.6.1 Expander device model overview (c): Clarify how the expander determines how to group phys under ports. If it's based on the SAS address reported in the Identify address frame, all phys attached to the same "device" must form a single port? Page: 51 Sequence number: 2 Date: 1/24/2003 9:49:58 AM Type: Highlight ACCEPT - DONE (change SL\_IR to Broadcast) 4.6.5 Broadcast primitive processor (BPP): I don't believe "SL\_IR primitive requests" has been defined anywhere. Does it include RESET? ALIGN? BROADCAST primitives? If there is a subset of all the primitives that applies that's different from the BROADCAST primitives defined in section 7.1, they ought to be so designated as SL IR primitive requests in section 7.1. If "SL\_IR primitive requests" are the same thing as "Broadcast Primitives", then the text here should use the same term. Page: 55 Sequence number: 4 Date: 1/24/2003 10:07:23 AM Type: Highlight ACCEPT - DONE 4.6.9 Expander connection router interface Table 24 Transmit Close Replace "an CLOSE" with "a CLOSE" Page: 57 Sequence number: 1 Date: 1/17/2003 2:26:12 PM Type: Note ACCEPT - TODO (make sure the expander model section defines self-initializing expanders and clarifies that they have some sort of application client internally running.) 4.6.11.1 Define a method for identifying/reporting this case for self-initialized. Page: 59 Sequence number: 4 Date: 12/30/2002 11:15:46 AM Type: Highlight ACCEPT - DONE 4.6.11.4 Expander route index order change "has" to "have" Page: 61 Sequence number: 2 Date: 1/24/2003 11:04:02 AM Type: Highlight ACCEPT - DONE 4.6.11.4 Expander route index order "U" should be changed to "V" \*\*\*

Page: 76 Sequence number: 3 Date: 1/20/2003 5:12:27 PM Type: Highlight **REJECT** (per PHY WG) 5.7.3.3 Jitter Tolerance Masks change "Z1" to "Z1tol" Page: 77 Sequence number: 6 Date: 1/20/2003 5:44:09 PM Type: Highlight ACCEPT - DONE 5.7.4 Transmitted Signal Characteristics General comment: A 3Gb PHY hitting maximum specs for compliance point CT will not be able to pass both bit rate r/f times. Reduce min r/f time for 1,5 from 133 to 67ps. Page: 81 Sequence number: 4 Date: 1/31/2003 5:32:34 PM Type: Highlight ACCEPT - DONE 5.7.9 Impedence specifications Table 39 - Impedance requirements footnote f: The text uses an upper-case greek letter "gamma" that normally represents a complex number. To represent the "magnitude" of the reflection coefficient, use the lower-case greek letter "rho". Page: 81 Sequence number: 5 Date: 1/20/2003 6:09:01 PM Type: Highlight ACCEPT - DONE 5.7.9 Impedance specifications Table 39 - Impedance requirements footnote f: The text uses an upper-case greek letter "gamma" that normally represents a complex number. To represent the "magnitude" of the reflection coefficient, use the lower-case greek letter "rho". Page: 82 Sequence number: 10 Date: 1/20/2003 5:38:34 PM Type: Note REJECT (per phy WG) 5.7.11 Transmitter characteristics Clarify whether both cases must pass, or whether one or the other is sufficient. Page: 104 Sequence number: 7 Date: 1/9/2003 4:08:54 PM Type: Note ACCEPT - DONE (deleted) 6.6.4.2 table 49 Footnoote The reference doesn't appear to be applied to anything. In any case the comment doesn't belong with this table as it is defined as the SAS speed negotiation. Correct ref or delete. Page: 108 Sequence number: 3 Date: 1/8/2003 6:38:57 PM Type: Highlight ACCEPT - DONE (it's really OOB\_COMINIT) 6.8.1 Overview "SP0:SAS\_PowerOn state" is not defined anywhere within the document. Define this state.

Page: 108 Sequence number: 4 Date: 1/17/2003 2:21:49 PM Type: Note REJECT (but added cross ref after SP\_DWS reference) 6.8.1 Overview Define 'DWS' in clause 3 Page: 109 Sequence number: 9 Date: 1/9/2003 6:03:44 PM Type: Highlight REJECT (we're not trying to list all entry actions like timer controls...just signals to other state machines that may be generated) 6.8.2 OOB sequence states Fig 56 Entry action is not listed as described in 6.8.2.2.1 on page 110. Page: 109 Sequence number: 10 Date: 1/8/2003 6:41:58 PM Type: Highlight REJECT (The state description below says "send this and wait..) 6.8.2 OOB sequence states Fig 56 "Transmit COMSAS" When should this action be executed? Clarify. Page: 109 Sequence number: 11 Date: 1/9/2003 6:04:08 PM Type: Highlight REJECT (we're not trying to list all entry actions like timer controls...just signals to other state machines that may be generated) 6.8.2 OOB sequence states Fig 56 SP7:OOB\_AwaitCOMSAS entry action is not listed as described in 6.8.2.7.1 on page 111 Page: 109 Sequence number: 12 Date: 1/9/2003 4:51:08 PM Type: Highlight REJECT (state description describes when... this just shows the signals that might come out of the states) 6.8.2 OOB sequence states Fig 56 The "Broadcast Event Notify" transition looks like an unconditional jump in the state diagram, but it actually only transit if all the conditions list in 6.8.2.7.2 are true. It is very misleading as shown in the state diagram. Page: 109 Sequence number: 13 Date: 1/9/2003 6:06:01 PM Type: Highlight REJECT (we used to have Verilog style equations and output definitions, and the complaint was they were too informative. Now we have minimal text descriptions and get complaints from some that they're still too much and others that they're not enough.) 6.8.2 OOB sequence states Fig 56 SAS phy (SP) state machine - OOB sequence states With all the missing transition conditions and entry action conditions, it makes this state diagram practically useless. Add complete details or remove so as not to cause confusion. Page: 109 Sequence number: 14 Date: 1/8/2003 6:41:10 PM Type: Highlight REJECT (yes. The state description below says "send this and wait. That means send it one time upon entry.) 6.8.2 OOB sequence states

Fig 56 "Transmit COMINIT" When should this action be executed? When entering SP1? Page: 109 Sequence number: 15 Date: 1/9/2003 4:50:36 PM Type: Highlight REJECT (state description describes when these are sent) 6.8.2 OOB sequence states Fia 56 "PhvNotReadv" When should this action be executed? When entering SP1? Page: 110 Sequence number: 8 Date: 1/9/2003 6:09:03 PM Type: Highlight REJECT (when we had full equations this was specified. The text describes how multiple arcs are chosen when more than one is possible.) 6.8.2.1.2 Transition SP1:OOB\_COMINIT to SP2:OOB\_AwaitCOMX "a COMINIT Transmitted parameter and does not receive a COMINIT Detected parameter." In Fig 56 on page 109, the transition condition only listed "COMINIT Transmitted"parameter" Page: 110 Sequence number: 9 Date: 1/9/2003 6:09:11 PM Type: Highlight REJECT (when we had full equations this was specified. The text describes how multiple arcs are chosen when more than one is possible.) 6.8.2.1.3 "a COMINIT Detected parameter and does not receive a COMINIT Transmitted parameter" In Fig 56 on page 109, the transition condition only listed " COMINIT Detected" Page: 110 Sequence number: 10 Date: 1/10/2003 2:38:28 PM Type: Highlight ACCEPT - DONE 6.8.2.2.1 State description Ambiguous: COMINIT and COMSAS could be read as modifiers for 'timeout'. Add 'detect' after each. Page: 110 Sequence number: 11 Date: 1/17/2003 2:18:32 PM Type: Highlight REJECT (figures don't show rules) 6.8.2.3.1 State description "but the COMINIT initiated in SP1:OOB\_COMINIT has not been completely transmitted." This condition is not shown in state diagram Fig 56 on page 109. Page: 110 Sequence number: 12 Date: 1/10/2003 2:43:04 PM Type: Highlight REJECT (when we had full equations this was specified. The text describes how multiple arcs are chosen when more than one is possible. However, did change "does not " to "has not".) 6.8.2.4.2 Transition SP4:OOB\_COMSAS to SP5:OOB\_AwaitCOMSAS\_Sent "and does not receive a COMSAS Transmitted parameter." This condition is not listed in the transition in Fig. 56 on 109, which may cause race condition in SM.

Page: 111 Sequence number: 5 Date: 1/10/2003 2:43:11 PM Type: Highlight REJECT (when we had full equations this was specified. The text describes how multiple arcs are chosen when more than one is possible. However, did change "does not " to "has not") 6.8.2.4.4 "and does not receive a COMSAS Detected parameter." This transition condition is not listed in Fig 56 on page 109 Page: 111 Sequence number: 6 Date: 1/10/2003 2:26:58 PM Type: Highlight REJECT (this is the only one like this, and this sentence provides that warning) 6.8.2.6.2 (Page 111) "The COMSAS Completed parameter may be received before this state is entered.' How long does this COMSAS Completed or other completed/transmitted/detected) signal stay valid after the event? Since this is the only place in this state machine description where receiving "before" the state is OK. Does it mean that all other detection/transmitted/etc. paramters are required to be valid only after the corresponding state has been entered? Page: 111 Sequence number: 7 Date: 1/24/2003 6:25:45 PM Type: Highlight ACCEPT - DONE (reworded as "receipt of a COMSAS Detected parameter") 6.8.2.7.1 State description In Fig 56 on page 109, it states "COMSAS detected", is "received" the same as "detected? Page: 112 Sequence number: 3 Date: 1/24/2003 6:27:06 PM Type: Highlight ACCEPT - DONE (now transitions to a new state based on other comments) 6.8.2.7.5 Transition SP7:OOB\_AwaitCOMSAS to SAS\_AwaitNoCOMX Change "SAS\_AwaitNoCOMX" to "SP2:SAS\_AwaitCOMX" Page: 113 Sequence number: 6 Date: 1/11/2003 3:57:57 PM Type: Highlight REJECT (diagram just shows what signals come from what states, not when) Figure 57 (Page 113) When should "Transmit ALIGN1" should be sent? The text in 6.8.3.4.1 says "repeatedly send", but this is not reflected in this state diagram. Page: 113 Sequence number: 7 Date: 1/17/2003 2:18:03 PM Type: Highlight ACCEPT - TODO (something that means "Failure with no recourse") 6.8.3 SAS speed negotiation states Figure 57 "No more rates" is not even close to what is described in 6.8.3.7.2 on page 116. Clarify. Page: 114 Sequence number: 21 Date: 1/17/2003 2:15:35 PM Type: Highlight REJECT (See other idle comment) 6.8.3.1.1 (Page 114)

"During this state idle shall be transmitted." This requirement is not listed in the state diagram state SP8 in Fig 57 on page 113 Page: 114 Sequence number: 22 Date: 1/17/2003 2:15:23 PM Type: Highlight ACCEPT - TODO 6.8.3.2.1 (Page 114) Clarify: Is "enabled" the same as "started"? Page: 114 Sequence number: 23 Date: 1/17/2003 2:15:14 PM Type: Highlight REJECT (see other idle comment) 6.8.3.2.1 "During this state idle shall be transmitted." This requirement is not listed in the state diagram state SP8 in Fig 57 on page 113 Page: 114 Sequence number: 24 Date: 2/4/2003 7:11:49 PM Type: Highlight ACCEPT - DONE (have timers start not enable globally) 6.8.3.3.1 (Page 114) Need clarification: Is "enabled" the same as "started"? Page: 114 Sequence number: 25 Date: 1/25/2003 4:45:02 PM Type: Highlight ACCEPT - DONE (delete whole sentence) 6.8.3.3.1 (Page 114) State description "if synchronization occurs before the SNLT expires." Need to clarify what "synchronization" means, I think it is trying to say either "ALIGN0 Detected" or "ALIGN1 Detected". Usually the word "synchronizatin" means something else. This sentence can be deleted because the same action is clearly described in 6.8.3.3.2 and 6.8.3.3.3 . Also, missing transition if only SNLT expires and no "synchronization" in this state? Page: 115 Sequence number: 14 Date: 1/17/2003 2:12:22 PM Type: Highlight ACCEPT - TODO 6.8.3.4.1 "This state is exited when the SNTT expires or when ALIGN (1) primitives are received before the SNLT timer expires." This same information is repeated at 6.8.3.4.2 Page: 115 Sequence number: 15 Date: 1/17/2003 2:06:53 PM Type: Highlight 6.8.3.5.1 (Page 115) "This state is reached after ALIGN (1) has been both transmitted and received." This sentence is not describing the same behavior as shown in the state diagram - Fig 57 on page 113. Change to: "This state is reached after ALIGN(1) has been recovered before the SNLT timer expires" Page: 116 Sequence number: 7 Date: 1/17/2003 2:01:51 PM Type: Highlight ACCEPT - TODO ("at the rate established in the previous speed negotiation window.") 6.8.3.8.1 "While in this state dwords from the link layer are transmitted at the negotiated physical link rate." Who (in what state/state machine) is responsible to tell the PHY what the negotiated link rate is? Clarify. Page: 118 Sequence number: 9 Date: 2/4/2003 6:50:17 PM Type: Highlight ACCEPT - DONE 6.8.4 SATA host emulation states Figure 58 SP16:SATA\_COMWAKE Missing input parameter "COMWAKE Transmitted" with dotted line unfilled arrow into SP16. Page: 118 Sequence number: 10 Date: 2/4/2003 6:50:00 PM Type: Highlight REJECT (text describes the order requirements) 6.8.4 SATA host emulation states Figure 58 - SAS phy (SP) state machine - SATA host emulation states SP20: SATA AdjustSpeed dotted unfilled arrow with parameter (Transmit D10.2) and dotted unfilled arrow with parameter (Set Rate) It seems it may have to send "Set Rate" parameter before "Transmit D10.2", please clarify. Page: 119 Sequence number: 12 Date: 1/10/2003 10:49:18 AM Type: Highlight REJECT (figure just shows the possible signals not the details. That's what this text is for) 6.8.4.4.1 State description "a) repeatedly send a Transmit D10.2 parameter to the SP transmitter" "repeatedly send" is not shown in the state diagram in Fig 58 as a condition required for transmitting D10.2 Page: 119 Sequence number: 13 Date: 1/17/2003 1:52:27 PM Type: Highlight REJECT (but will make timers stand out better in the text and may add timer arcs to figures in SAS-2) 6.8.4.4.1 State description GLOBAL "b) start the ALIGN detect timeout timer" It looks like this is a state entry action and it is not listed in the state diagram in Fig 58 THIS IS one of a pattern of incomplete definitions due to the assumption of hidden, underlying state machines. Need to explicitly identify these implicit state machines and the signals/messages they exchange with other SMs. Page: 119 Sequence number: 14 Date: 1/17/2003 1:53:04 PM Type: Highlight ACCEPT/REJECT - TODO (split the comment) 6.5.4.4.1 State description

"The SAS device shall start transmitting D10.2 characters no later than 20 G1 dwords (i.e. 533 ns) after COMWAKE was deasserted" Use of COMWAKE is confusing - sometimes parms are received, sometimes CW is 'deasserted' - what is it? [agree] This seems as a state entry action and it does not show the relation of transmitting D10.2 characters no later than 20 G1 dwords after COMWAKE was deasserted in the state diagram in Fig 58. [reject] Since not all SAS implementation required to support G1 speed, this state should not specify requirement in "G1 dwords", instead it should just specify time - 533 ns. [accept; check what SATA intends] Page: 119 Sequence number: 15 Date: 1/22/2003 9:41:55 AM Type: Highlight ACCEPT - DONE (made into an ordered list) must set the rate before transmitting the 10.2s Page: 137 Sequence number: 9 Date: 1/22/2003 9:48:47 AM Type: Highlight ACCEPT - DONE (change "init sequence" to "link reset sequence". This is not concerned with the higher level software.) 7.1.4.4 BROADCAST If an expander's routing tables are configured by initiators, how does an expander know the initialization sequence has completed? Clarify. Page: 138 Sequence number: 12 Date: 1/6/2003 1:31:04 PM Type: Highlight ACCEPT - DONE 7.1.4.9 NOTIFY NOTIFY (ENABLE\_SPINUP) Add correct reference for TBD. Page: 138 Sequence number: 13 Date: 1/22/2003 9:48:13 AM Type: Highlight ACCEPT - DONE (change "accept" to "honor" and "all target ports equivalently") 7.1.4.9 Notify Meaning of 'accept' here requires clarification. Page: 141 Sequence number: 4 Date: 1/17/2003 1:46:21 PM Type: Highlight ACCEPT - TODO (see IBM comment) 7.1.5.3 DONE Table 63 Ack/NAK TIMEOUT "is going to" Sentence s/b xref to where the behavior is defined Page: 142 Sequence number: 6 Date: 1/6/2003 1:42:19 PM Type: Highlight ACCEPT - DONE 7.1.6.3 SATA\_HOLD and SATA\_HOLDA "...transmitting a SATA\_HOLD." should be changed to "...receiving an SATA\_HOLD" Page: 162 Sequence number: 8 Date: 1/22/2003 9:47:11 AM Type: Highlight ACCEPT - DONE ("If any of the prospective... does not support")

7.12.2.1 Connection Request
 "If none of the prospective intermediate physical links [does not]
 support the requested connection rate, ..."
 Remove "does not"

Page: 166 Sequence number: 10 Date: 1/17/2003 1:19:04 PM Type: Highlight ACCEPT - TODO (requests to devices not in the fanout expander routing tables cause the fanout expander to returns NO DEST, and requests to devices in the fanout tables but not currently attached to an edge expander return BAD DEST) 7.12.4.2 Edge Expander Devices Par. 5, last sentence "When a fanout expander device is in the domain, an OPEN\_REJECT (NO DESTINATION) is returned." "is returned" - who returns? Page: 166 Sequence number: 11 Date: 1/17/2003 1:07:38 PM Type: Highlight ACCEPT - TODO (delete this table. Chapter 4 has much more details on the model for routing tables. Add cross reference to Ch 4. Check all the paragraphs here looking for out of date text.) 7.12.4.2 Edge expander devices The simple edge expander device routing table described in table 80 needs to be reconciled with the expander routing table described in "4.6.11.3 Expander route table." Text needs to describe when it's appropriate to use the simpler table vs. the more complex table and what the restrictions are if a simpler approach is used. Page: 174 Sequence number: 11 Date: 1/17/2003 1:04:23 PM Type: Highlight REJECT (missing SOAFs just mean the frame data looks like idle dwords. The EOAF is then ignored.) 7.13.3.1 State Description par. 7 . (i.e) Explanation missing regarding what should be done about data dwords transmitted between consecutive EOAFs. SOAFs is clear. (Multiple occurrences) Page: 191 Sequence number: 6 Date: 1/22/2003 9:46:13 AM Type: Highlight ACCEPT - DONE ("Receiving ports shall acknowledge frames within 1 ms if not discarded as described in 7.x.x.x with either ...") 7.16.3 SSP frame transmission "Every frame shall be acknowledged" By whom? Place the requirement on something. Page: 191 Sequence number: 7 Date: 1/22/2003 9:44:10 AM Type: Highlight ACCEPT - DONE (rename section "transmission and reception". Also done in SMP and STP sections.) 7.16.3 SSP frame transmission Create new subclause for frame reception. Page: 191 Sequence number: 8 Date: 1/17/2003 12:56:09 PM Type: Highlight ACCEPT - TODO ("Every frame not discarded as described in 7.16.7.9". See other comment) 7.16.3 SSP frame transmission "Every frame shall be acknowledged" conflicts with 7.16.7.9, which describes some frames that are dropped. Qualify with 'valid' or something.

Page: 198 Sequence number: 2 Date: 12/30/2002 10:07:22 AM Type: Highlight 7.16.7.2 SSP\_TIM1:Tx\_Interlock\_Monitor state 'When the number of EOF Transmitted parameters received' - These are signals, indications, something. They are not parameters. Use an appropriate term, see ANSI IT Dictionary. Page: 213 Sequence number: 3 Date: 1/6/2003 1:17:15 PM Type: Highlight ACCEPT - DONE 8.1 Overview "PC\_OC" s/b replaced with "PL\_OC" Page: 213 Sequence number: 4 Date: 12/30/2002 10:07:22 AM Type: Highlight 8.1 Overview 'establish port connections and disconnections' - Sounds awk to establish a disconn. Reword. Page: 213 Sequence number: 5 Date: 12/30/2002 10:07:22 AM Type: Highlight 8.2 Overview 'pass transmit data, receive data' AWK - reword. Suggest 'data for transmission, received data' Page: 213 Sequence number: 6 Date: 12/30/2002 10:07:22 AM Type: Highlight 8.1 Overview '...form the port layer' AWK. Rearrange sentence. Suggest 'The port layer consists of ...' Page: 214 Sequence number: 7 Date: 12/30/2002 10:07:22 AM Type: Highlight 8.2.2 Bus inactivity time limit timer ALL OTHER TIMERS 'The timer shall count down' - specify when (or include xref to spec, here, 8.4.4.1)it starts. (For this and all other defined timers) Page: 217 Sequence number: 5 Date: 12/30/2002 1:30:39 PM Type: Highlight ACCEPT - DONE 8.3.2.2 Transition PL\_OC1:Idle to PC\_OC2:Overall\_Control In this heading, the heading number is duplicated and PC\_OC2 should be changed to PL\_OC2 Page: 217 Sequence number: 6 Date: 1/8/2003 9:36:04 AM Type: Highlight ACCEPT - DONE 8.3.3.1.1 State Description Overview PM\_PM should change to PL\_PM

Sequence number: 7 Date: 12/30/2002 10:07:22 AM Type: Highlight 8.3.3.1.1 State description overview The Tx Frame parameter "following arguments: Balance Required or Balance Not Required" BR and BNR are not arguments, they are possible values of an argument that should be called 'Balance Requirement' or something similar. Correct. Page: 217 Sequence number: 8 Date: 12/30/2002 10:07:22 AM Type: Highlight 8.3.3.1.1 State description overview GLOBAL "parameter" s/b 'request' as per 4.3.3.2 . Page: 217 Sequence number: 9 Date: 12/30/2002 10:07:22 AM Type: Highlight 8.3.3.1.2 Keep track of connections/frame requests "Keep track of connections/frame requests" is the first time I've seen an imperative used as a subclause title. Replace with "Connection frame/request tracking" Page: 217 Sequence number: 10 Date: 12/30/2002 10:07:22 AM Type: Highlight 8.3.3.1.2 Keep track of connections/frame requests "A phy is available if it is not processing a Tx Frame" What if it has lost sync, etc? Add defn for 'available' or qualify. Clarify. Page: 217 Sequence number: 11 Date: 12/30/2002 10:07:22 AM Type: Highlight 8.3.3.1.1 State description overview GLOBAL The information ("parameters/arguments" to/from various state machines and layers) discussed throughout this clause needs to be defined as per 3.7. Very confusing: for example, "parameter shall include as arguments:" Page: 218 Sequence number: 6 Date: 12/30/2002 10:07:22 AM Type: Highlight 8.3.3.1.4 SSP wide port rules Multiple in subclause "An initiator port shall not transmit ...for which...transmitting a frame []" Add "on another phy". Page: 218 Sequence number: 7 Date: 12/30/2002 10:07:22 AM Type: Highlight 8.3.3.1.3 Select a request to process and the phy on which to process it GLOBAL "Tx Frame request" Elsewhere, Tx Frame is called a parameter. Change all occurences to 'request'. Page: 218

Sequence number: 8 Date: 12/30/2002 10:07:22 AM Type: Highlight

8.3.3.1.3 Select a request to process and the phy on which to process it 1) Is 'Tx Frame request' the same as 'Transmit Frame request' above? If so, be consistent in usage, if not, add some modifier to one to make the distinction clear. Page: 218 Sequence number: 9 Date: 12/30/2002 10:07:22 AM Type: Highlight 8.3.3.1.3 Select a request to process and the phy on which to process it "A destination is considered the same" - AWK suggest: "Destinations are considered to be identical if they have the same protocol and SAS address." Page: 218 Sequence number: 10 Date: 12/30/2002 10:07:22 AM Type: Highlight 8.3.3.1.2 Keep track of connections/frame requests "This state shall consider a phy as having an active connection" Drop "shall consider" and define it: "A phy has an active connection when ... " Page: 219 Sequence number: 3 Date: 12/30/2002 10:07:22 AM Type: Highlight 8.3.3.1.5 Filling in the Tx Frame arguments 3d para "Balanced" Remove 'd' Page: 219 Sequence number: 4 Date: 12/30/2002 10:07:22 AM Type: Highlight 8.3.3.1.5 Filling in the Tx Frame arguments 3d para "argument" -> 'value' (This appears to be redundant to 8.3.3.1.1) Confusing use of 'argument' and 'parameter' Page: 219 Sequence number: 5 Date: 12/30/2002 10:07:22 AM Type: Highlight 8.3.3.1.5 Filling in the Tx Frame arguments "are transferred to the selected PL\_PM's AWT timer and PBC counter" By whom? The PL\_PM, or the PL\_OC2? Clarify. Page: 219 Sequence number: 6 Date: 12/30/2002 10:07:22 AM Type: Highlight 8.3.3.1.5 Filling in the Tx Frame arguments "are not received" Place reqmt on sender that it not send, or clarify that these are not present within TxFrame, or are ignored on receipt. Page: 219 Sequence number: 7 Date: 12/30/2002 10:07:22 AM Type: Highlight 8.3.3.1.5 Filling in the Tx Frame arguments "are received as arguments" s/b "are present in "

Page: 219 Sequence number: 8 Date: 12/30/2002 10:07:22 AM Type: Highlight 8.3.3.1.5 Filling in the Tx Frame arguments "a corresponding PL\_OC Retry Frame AWT timer" Provide separate text listing all architectural timers and their functions. Page: 219 Sequence number: 9 Date: 12/30/2002 10:07:22 AM Type: Highlight 8.3.3.1.5 Filling in the Tx Frame arguments The I\_T nexus loss "The selected PL\_PM timer shall be set" Express in active voice (who shall?). Page: 219 Sequence number: 10 Date: 12/30/2002 10:07:22 AM Type: Highlight 8.3.3.1.5 Filling in the Tx Frame arguments "state (i.e, either stopped," Clarify that you are defining the possible states or ref where defined. "i.e." is a bit too casual. Page: 219 Sequence number: 11 Date: 12/30/2002 10:07:22 AM Type: Highlight 8.3.3.1.5 Filling in the Tx Frame arguments 'are read from' Use active voice. Page: 219 Sequence number: 12 Date: 12/30/2002 10:07:22 AM Type: Highlight 8.3.3.1.5 Filling in the Tx Frame arguments "is updated" Use active voice. Page: 220 Sequence number: 1 Date: 12/30/2002 10:07:22 AM Type: Highlight 8.3.3.1.6 Confirmations "to finish servicing each Transmit Frame request." Unclear is this how THIS state completes the request, or does it tells the Transport layer to do so? Clarify. Page: 220 Sequence number: 2 Date: 12/30/2002 10:07:22 AM Type: Highlight 8.3.3.1.6 Confirmations "Since the transport layer responses ... are instantaneous" 'are returned immediately' seems better if the intent is (response returned as soon as request received). Clarify. Page: 220 Sequence number: 3 Date: 12/30/2002 10:07:22 AM Type: Highlight 8.3.3.1.6 Confirmations Need comma after e.g. "to continue" may be clearer.

Page: 220 Sequence number: 4 Date: 12/30/2002 10:07:22 AM Type: Highlight 8.3.3.1.6 Confirmations "parameter" -> "confirmation"? Page: 220 Sequence number: 5 Date: 12/30/2002 10:07:22 AM Type: Highlight 8.3.3.1.6 Confirmations Table 86 header "parameter" s/b 'value' or 'code' Page: 221 Sequence number: 4 Date: 12/30/2002 10:07:22 AM Type: Highlight 8.3.3.1.7 Handling Cancel requests "Cancel request for a specific Transmit Frame request" There is no listing I could find of the arguments to a Cancel request. Add xref to that defn. Clarify the means by which a specific TF request is identified. Page: 221 Sequence number: 5 Date: 12/30/2002 10:07:22 AM Type: Highlight 8.3.3.1.7 Handling Cancel requests "send a Cancel Acknowledge...and terminate" Either change order to (terminate, ack), or add prohibition on beginning TF processing. Page: 221 Sequence number: 6 Date: 12/30/2002 10:07:22 AM Type: Highlight 8.3.3.1.7 Handling Cancel requests "layer, this frame is currently" Ambig. s/b " layer and the specified frame "? Clarify. Page: 221 Sequence number: 7 Date: 12/30/2002 10:07:22 AM Type: Highlight 8.3.3.1.7 Handling Cancel requests "layer, this frame is currently" AMBIG s/b " layer and the specified frame "? Clarify. Page: 225 Sequence number: 5 Date: 12/30/2002 10:07:22 AM Type: Highlight 8.4.3.1.4 Open Failed handling "parameter" - confirmation? Page: 227 Sequence number: 1 Date: 12/30/2002 11:28:40 AM Type: Highlight ACCEPT - DONE 9.1 Transport layer overview clarify: "only receives from the link layer those frames that are to be ACKed." Page: 229 Sequence number: 17 Date: 1/6/2003 10:39:04 AM Type: Highlight ACCEPT - DONE (added xref to 9.2.4.5 RESPONSE error handling)

9.2.1 SSP frame format RETRANSMIT "may be set to one" Add xref or "shall be set to one" when a RESP frame is a retrans. Page: 229 Sequence number: 18 Date: 1/6/2003 10:37:11 AM Type: Highlight ACCEPT - DONE 9.2.1 SSP frame format For DATA "to that" s/b "to the tag" Page: 229 Sequence number: 19 Date: 1/17/2003 12:14:12 PM Type: Highlight REJECT (paragraph being redone, targets always allowed to use the field) 9.2.1 SSP frame format **TP** Xfer Tag "need" s/b "use" (We don't care if they NEED it, just whether they use it) Page: 229 Sequence number: 20 Date: 1/17/2003 12:13:44 PM Type: Highlight REJECT (the whole paragraph is being redone, and targets are allowed to set the field any time) 9.2.1 SSP frame format **TPXfer Tag** "do not need this field" Clarify whether TP can use it sometime, but not other times. or say "use" Page: 229 Sequence number: 21 Date: 1/17/2003 12:01:25 PM Type: Highlight REJECT (Jan WG disk drives don't need) 9.2.1 SSP frame format Table 89 - FRAME TYPE field Max data frame size of 1024 is inefficient for block-sizes greater than 512 bytes. This is a serious problem for systems that use data-integrity guards on a block-by-block basis. Recommend the max DATA IU payload accommodate two blocks with a generously-sized block-guard (16-bytes). Change (1 024) to (1 056). Page: 230 Sequence number: 9 Date: 1/6/2003 10:44:53 AM Type: Highlight ACCEPT - DONE ("...shall transfer data beginning on a dword boundary...". Kept the i.e.) 9.2.1 SSP frame format DATA frames "each DATA frame shall begin on a dword boundary" It's the TRANSFER, frame. Drop (i.e.) Page: 230 Sequence number: 10 Date: 12/30/2002 2:04:44 PM Type: Highlight ACCEPT - DONE (a SAM-3 reference was meant) 9.2.1.1 COMMAND information unit "SPC-2" if referencing SAM-3, why not SPC-3, especially when ref'd on next page. Be consistent. Suggest SPC-3. Page: 230 Sequence number: 11

Date: 12/30/2002 1:37:57 PM Type: Highlight ACCEPT - DONE (globally for all occurrences of [0-9]<space>[0-9] except in the 8b10b tables) 9.2.1 SSP frame format The INFORMATION UNIT field 024 - Make space non-breaking (ctrl-space) Page: 231 Sequence number: 3 Date: 1/6/2003 10:50:05 AM Type: Highlight ACCEPT - DONE (also in 9.2.2.1) 9.2.2.2 TASK information unit "request a" s/b "request that a" Page: 233 Sequence number: 13 Date: 1/6/2003 10:57:47 AM Type: Highlight REJECT (but changed "begin" wording a bit) 9.2.2.3 XFER\_RDY information unit "each DATA frame shall begin on a dword boundary" Remove (ie) Page: 233 Sequence number: 14 Date: 1/6/2003 10:57:05 AM Type: Highlight REJECT (but changed "aligned" to "multiple") 9.2.2.3 XFER RDY information unit "non-dword aligned write data length" A length does not have alignment. Remove the paren statement. Page: 233 Sequence number: 15 Date: 1/6/2003 10:56:26 AM Type: Highlight ACCEPT - DONE (target port) 9.2.2.3 XFER\_RDY information unit GLOBAL "frame for a given command shall set" Frames don't set themselves. Place the regmt on some port. Page: 235 Sequence number: 3 Date: 1/6/2003 11:22:07 AM Type: Highlight ACCEPT - DONE (added all the field names in the intro to the DATAPRES field. The descriptions are in subsequent sections) 9.2.2.5.1 RESPONSE information unit overview Table 96 - RESPONSE information unit STATUS - Following text does not give ref to where STATUS values defined. (make sure for all fields) Page: 236 Sequence number: 3 Date: 1/6/2003 12:25:01 PM Type: Highlight ACCEPT - DONE (for all 3 sections, used a)b)c) lists to highlight that they're based on DATAPRES) 9.2.2.5.3 RESPONSE information unit RESPONSE\_DATA format "The SENSE DATA field shall not be present." Make clear that this and related regmts are conditional on the DATAPRES == RESP\_DATA, and not global. Suggest unordered list under "If the DATAPRES..." Page: 237 Sequence number: 5

Date: 1/13/2003 6:02:38 PM

Type: Highlight ACCEPT - DONE (removed it) Table 99 9.2.2.5.3 RESPONSE information unit RESPONSE\_DATA format "NO FAILURE, when responding to a COMMAND frame" Response data would not be returned if there was no error. Remove this. Page: 237 Sequence number: 6 Date: 1/6/2003 12:26:27 PM Type: Highlight ACCEPT - DONE (a)b)c) list format) 9.2.2.5.4 RESPONSE information unit SENSE\_DATA format "The RESPONSE DATA LIST LENGTH field shall be set to zero" Make clear that thes regmts are conditional on DATAPRES value. Page: 239 Sequence number: 4 Date: 1/6/2003 12:48:57 PM Type: Highlight ACCEPT - DONE 9.2.4.1 COMMAND frame "whether ... received or not" 'Whether' is sufficient to cover both cases. Drop "or not". Page: 239 Sequence number: 5 Date: 1/6/2003 12:48:39 PM Type: Highlight ACCEPT - DONE 9.2.4.1 COMMAND frame "command [] was ACKed" add "frame" Page: 239 Sequence number: 6 Date: 1/6/2003 12:48:12 PM Type: Highlight REJECT - (no unit attention, just a CHECK CONDITION for the command involved. "Returning CHECK CONDITION status" is higher level than returning a RESPONSE frame with CHECK CONDITION status and avoids needing to mention opening a new connection and other details.) 9.2.4.3 XFER\_RDY frame "close the connection ..return a [] CHECK CONDITION status" Does this mean "generate a UA"? Add "a RESPONSE FRAME with" (MULTIPLE places) Does it establish a new connection to send the RESPONSE? Clarify. Page: 239 Sequence number: 7 Date: 1/6/2003 12:42:29 PM Type: Highlight ACCEPT - DONE (changed to 'times out waiting for") 9.2.4.3 XFER\_RDY frame "does not receive an ACK or NAK" Over what time period? Clarify. Page: 240 Sequence number: 7 Date: 2/2/2003 2:36:35 PM Type: Highlight ACCEPT - DONE (for too short for LUN field, too short for CDB, and additional cdb mismatch, generate a RESPONSE IU with a RESPONSE CODE indicating INVALID FRAME. In ch10 protocol services, this means a service delivery subsystem failure.) 9.2.5.1 Target port error handling "too short to contain a LUN field" Be explicit - state number of bytes. Page: 240

Sequence number: 8 Date: 2/2/2003 2:36:26 PM Type: Highlight

ACCEPT - DONE (for too short for LUN field, too short for CDB, and additional cdb mismatch, generate a RESPONSE IU with a RESPONSE CODE indicating INVALID FRAME. In ch10 protocol services, this means a service delivery subsystem failure.) 9.2.5.1 Target port error handling "contains a LUN field but is too small to contain a CDB" If frame is malformed, how could you say it has LUN but not CDB? Replace this with a list of sizes, in bytes, and the appropriate responses. Page: 240 Sequence number: 9 Date: 1/6/2003 12:55:38 PM Type: Highlight REJECT - the crossreference has that rule 9.2.5.1 Target port error handling "OVERLAPPED COMMANDS DETECTED" State (non) requirements on checking. Page: 240 Sequence number: 10 Date: 1/6/2003 12:52:31 PM Type: Highlight ACCEPT - DONE (changed several others in this section) 9.2.5.1 Target port error handling 'TAG that is already in use' - Should be small caps only if referring to the field, but not to the value. Correct. Page: 241 Sequence number: 3 Date: 2/8/2003 12:34:46 PM Type: Highlight ACCEPT - TODO (per Jan WG; 03-088 makes this request) 9.2.5.1 Target port error handling ILLEGAL TARGET PORT TRANSFER TAG - Although the tag may be invalid, there's no indication that it's illegal. Rename ASC - use INVALID.

## Author: KnowledgeTek

Page: 8 Sequence number: 13 Date: 1/7/2003 2:39:21 PM Type: Highlight ACCEPT - DONE (figure 3 is backwards) 3.1.62 indication: The definition says < passed from lower layer... > 3.5.1 State machine convetions overview, Figure 3 shows < indication from upper layer... > Page: 9 Sequence number: 21 Date: 1/7/2003 2:42:14 PM Type: Highlight ACCEPT - DONE (figure is wrong) 3.1.98 response: definition says < passed from a higher layer...> 3.5.1 State machine conventions overview, figure3 says < to upper layer ... > Page: 53 Sequence number: 2 Date: 12/31/2002 1:35:11 PM Type: Highlight ACCEPT - DONE (phy status) 4.6.7 Expander device interface detail Figure 27 'Link Status' sb 'Phy Status' or Table 23 needs to change its entries to 'Link Status'

Page: 53 Sequence number: 3 Date: 12/31/2002 1:34:05 PM Type: Highlight ACCEPT - DONE 4.6.7 Expander device interface detail Figure 27 All of the requests and indications using "Send" sb "Transmit" or Table 24 should change its entries to "Send". There are eight occurences of "Send" in this figure that should change to "Transmit" Page: 53 Sequence number: 4 Date: 1/11/2003 5:16:49 PM Type: Highlight ACCEPT - DONE Send Page: 53 Sequence number: 5 Date: 12/31/2002 1:34:25 PM Type: Highlight ACCEPT - DONE Send Page: 53 Sequence number: 6 Date: 12/31/2002 1:34:28 PM Type: Highlight ACCEPT - DONE Send Page: 53 Sequence number: 7 Date: 12/31/2002 1:34:32 PM Type: Highlight ACCEPT - DONE Send Page: 53 Sequence number: 8 Date: 12/31/2002 1:34:09 PM Type: Highlight ACCEPT - DONE Send Page: 53 Sequence number: 9 Date: 12/31/2002 1:34:14 PM Type: Highlight ACCEPT - DONE Send Page: 53 Sequence number: 10 Date: 1/11/2003 5:16:45 PM Type: Highlight ACCEPT - DONE Send Page: 57 Sequence number: 2 Date: 12/28/2002 1:31:59 PM Type: Highlight 4.6.11.1 Routing attributes and methods 4th paragraph The following paragraph implies that the routing will be either table OR direct, not both: "A phy that has the table routing attribute allows the expander connection manager to use one of the following methods to route connection requests: a) the table routing method if attached to an expander device; or

b) the direct routing method if attached to an end device."

4.6.11.2 Expander device connection request routing

2nd paragraph

This paragraph says that if the "DISABLE ROUTE ENTRY bit" is set the entry is ignored (I assume that means the connection request will get an OPEN\_REJECT response???):

"If the destination SAS address of a connection request matches the attached SAS address of an expander route entry and the DISABLE ROUTE ENTRY bit is set to one in the expander route entry, then the expander connection manager shall ignore the expander route entry."

4.6.11.3 Expander route table

10th paragraph

This paragraph states that the "attached" expander's entry is disabled (I assume this means directly attached and not cascaded expanders beyond the one directly attached???):

"If the discover process detects an expander route table entry that references the SAS address of an attached edge expander device, it shall set the DISABLE ROUTE ENTRY bit to one in the expander route table entry." Given the above, how can access to internal devices (i.e., SMP Target function) that share the expanders SAS address be accomplished?

Page: 61

Sequence number: 3

Date: 2/9/2003 5:30:57 PM

Type: Highlight

REJECT - TODO (the directly attached SAS address is NOT part of the route table. This needs to be made clear however) 4.6.11.4 Expander route index order

Table 26 - Expander route table levels.

The first entry in the table for level one should be the expander SAS address of expander N. Level two entries should begin with the device SAS addresses attached to phy0 of expander N. etc.... There is only one Level 1 entry per phy. I believe the whole table is wrong...

(I'm assuming the text is correct in paragraph 2, including numbered list, of the same clause???).

That text follows here:

For purposes of configuring the expander route table, the edge expander devices attached to the phy are assigned levels:

1) the attached edge expander device is considered level 1;

2) devices attached to it are considered level 2;

3) devices attached to level 2 edge expander devices are considered level 3; and

4) etc.

Page: 63 Sequence number: 1 Date: 12/28/2002 2:49:20 PM Type: Highlight 4.6.11.4 Table 27 - Expander route table entries for edge expander E0 phy 0 see comments for table 26 The level 1 entries should be the devices attached to the E0 phy 0, that is edge expander E1. Level 2 entries are the devices attached to edge expander E1 (i.e., D1,1... D1,Y) I'm assuming the text is correct in the 2nd paragraph, including numbered list, of the same clause. Page: 63 Sequence number: 2 Date: 12/15/2002 11:57:10 PM Type: Highlight 4.6.11.4 Table 28 - Expander route table entries for fanout expander device F phy 0 See comment on table 27, same type of errors apply to this table. Page: 64 Sequence number: 1 Date: 2/9/2003 5:33:24 PM Type: Highlight REJECT (all application clients running the discover process have to fill in the tables the same way, or multiple initiators would confuse each other. The level-order traversal has each initiator gingerly probe the domain closest-to-furthest) 4.6.11.5 Discover process 1st paragraph "The order of traversal shall be to discover: 1) the expander device to which the initiator port is attached; 2) every device attached to that expander device; and 3) as each expander device is found, every device attached to that expander device." The above requires traversal to go down each phy to end before moving to the next phy. This seems to complicate the process of building the routing table entries since the order is based on level. Why the requirement as stated???

Page: 99 Sequence number: 3 Date: 1/8/2003 2:52:16 PM Type: Highlight ACCEPT - DONE (removed the times altogether. Also reformatted the picture a bit to show locking on the nth rate not the 2nd rate) 6.6.2.2 SATA speed negotiation sequence (informative) Figure 49 Time reference is incorrect. 533 ns sb 53,3 ns Page: 108 Sequence number: 5 Date: 1/8/2003 6:29:33 PM Type: Highlight ACCEPT - DONE (should be SP1:OOB\_COMINIT) 6.8.1 Overview A reference is made to "SP0:SAS\_PowerOn state" in the thrid paragraph. This state does not appear in the state figures nor is there a state description of function or how it transistions to other states. Nor is it listed in the preceeding paragraph of SP states. Page: 110 Sequence number: 13 Date: 1/22/2003 10:19:41 AM Type: Highlight REJECT (yes that is the intent for the first two; once a Transmit COMxxx is sent, COMxxx Transmitted ought to show up. The last one is waiting on COMSAS Completed after COMSAS Detected. If this hangs forever, it means the bus is hung sending ALIGN bursts. I think reset as the only out is acceptable.) 6.8.2.3 SP3:OOB\_AwaitCOMINIT\_Sent state 6.8.2.5 SP5:OOB\_AwaitCOMSAS\_Sent state 6.8.2.6 SP6:OOB AwaitNoCOMSAS state The above states have only one way out. If that event doesn't occur it appears the only way out is reset. Is that the intent??? Page: 114 Sequence number: 27 Date: 12/28/2002 8:04:38 PM Type: Highlight 6.8.3.1.1 State description 4th paragraph, item b) states: "to the value of the speed negotiation window received as an argument." This "argument" is not shown in the state diagram figure 57 nor is there an indication of where it comes from. Page: 115 Sequence number: 16 Date: 12/31/2002 1:31:34 PM Type: Highlight ACCEPT - DONE 6.8.3.6.2 Transition SP13:SAS Pass to SP8:SAS Start 1st paragraph, item a) SN\_start state sb SP8:SAS\_Start state. Page: 117 Sequence number: 4 Date: 2/5/2003 10:04:28 AM Type: Highlight REJECT (yes, SAS initiators can attach directly to SATA drives. That becomes outside the scope of this standard. However, the SP state machine is integrated and handles both (for both initiators and expanders), since there is nothing in SATA that we can clearly "join in progress" to handle the rest of the link reset sequence.) 6.8.4 SATA host emulation states 1st paragragh states: ...(an initiator device... Is this allowed???? Page: 215 Sequence number: 6 Date: 12/31/2002 1:30:29 PM Type: Underline ACCEPT - DONE 8.3.10verview

Paragragph 3 Sentence 2 PL\_PM1:Idle sb PL\_OC1:Idle Page: 216 Sequence number: 12 Date: 12/31/2002 1:29:46 PM Type: Highlight ACCEPT - DONE Clause 8.3.2.1 & 8.3.2.2 8.3.2.1 & 8.3.2.2 is repeated in the clause heading Page: 216 Sequence number: 13 Date: 12/31/2002 1:29:49 PM Type: Highlight ACCEPT - DONE 8.3.2 repeated Page: 217 Sequence number: 12 Date: 12/31/2002 1:29:53 PM Type: Highlight ACCEPT - DONE Clause 8.3.2.1 & 8.3.2.2 8.3.2.1 & 8.3.2.2 is repeated in the clause heading Page: 217 Sequence number: 13 Date: 12/31/2002 1:29:41 PM Type: Highlight ACCEPT - DONE 8.3.3.1.1 State description overview 1st paragraph PM\_PM sb PL\_PM Page: 233 Sequence number: 16 Date: 12/31/2002 1:29:13 PM Type: Highlight ACCEPT - DONE 9.2.2.4 DATA information unit 2nd paragraph, last sentence states: "The minimum size of the data IU is one byte." 9.2.1 SSP frame format Table 89 states: "0 - 1024 bytes" under infomation unit size. Assumming text takes precedence over tables and the text is correct, Table 89 needs to be fixed. Page: 260 Sequence number: 8 Date: 12/31/2002 1:29:00 PM Type: Highlight ACCEPT - DONE 9.4.2 SMP\_Request Frame 1 023 bytes sb 1 024 bytes. Page: 261 Sequence number: 9 Date: 12/31/2002 1:21:55 PM Type: Highlight ACCEPT - DONE 9.4.3 SMP\_RESOPONSE Frame 1 023 bytes sb 1 024 bytes Page: 298 Sequence number: 5 Date: 12/31/2002 1:28:51 PM Type: Highlight

ACCEPT - DONE (removed paragraph) 10.3.1.3 REPORT MANUFACTURER INFORMATION function. This paragraph does not apply and should be deleted or the field does apply and needs to be added to table 133. The ADDITIONAL LENGTH field indicates the length in bytes of the parameters, including the ADDITIONAL LENGTH field. If the ADDITIONAL REQUEST BYTES of the SMP\_REQUEST is too small to transfer all of the parameters, the ADDITIONAL LENGTH shall not be adjusted to reflect the truncation. Page: 305

Sequence number: 8 Date: 12/31/2002 1:28:25 PM Type: Highlight ACCEPT - DONE (they stop at the maximum and do not wrap) 10.3.1.5 REPORT PHY ERROR LOG function None of the following fields indicates if the field wraps or freezes at max count. INVALID DWORD COUNT DISPARITY ERROR COUNT LOSS OF DWORD SYNCHRONIZATION COUNT PHY RESET PROBLEM COUNT

Page: 315 Sequence number: 2 Date: 1/9/2003 5:56:09 PM Type: Highlight ACCEPT - DONE (it is updated regardless) 10.3.1.9 PHY CONTROL function PARTIAL PATHWAY TIMEOUT VALUE description does not state if this value is always update or not regardless of phy operation requested.

## Author: LSI Brian Day

Page: 30 Sequence number: 13 Date: 1/23/2003 5:04:46 PM Type: Note ACCEPT - DONE 4.1.11 Connections page 30 In second paragraph from end, should read "...links that make up the pathway..." (change "to" to "the") Page: 138 Sequence number: 17 Date: 1/8/2003 9:43:33 AM Type: Note ACCEPT - DONE (should ALIGN have a table too?) 7.1.4.9 NOTIFY page 138. The NOTIFY does not have a table as the other primitives, and should be added. Page: 142 Sequence number: 8 Date: 1/8/2003 1:16:52 PM Type: Note REFER PROTOCOL WG (Added "When transmitting a frame," to head the sentence and fixed transmitting to receiving. Also may need to describe "when receiving a frame" but don't want to restate the SATA standard. ) 7.1.6.3 SATA\_HOLD and SATA\_HOLDA page 142 The first sentence is incorrect. Replace sentence with "An expander device running SATA protocol shall transmit a SATA\_HOLDA within 20 dwords of receiving a SATA\_HOLD when it is the source of the data dwords of the frame." Page: 143 Sequence number: 12 Date: 1/22/2003 9:51:51 AM Type: Note ACCEPT - DONE (change to "shall not transmit SATA\_X\_RDY or SATA\_R\_RDY on the SATA physical link until...") 7.1.6.4 SATA\_R\_RDY and SATA\_X\_RDY page 143

Last sentence should start "Expander or initiator devices..."

Page: 149 Sequence number: 2 Date: 1/8/2003 1:31:47 PM Type: Note ACCEPT - DONE (per other comment, just removed that sentence.) 7.7.1 Address frame overview page 149. Only ALIGNS should be allowed inside address frames. Change third sentence to "Except for ALIGN, primitives may not be inserted in the address frame." Page: 153 Sequence number: 5 Date: 1/13/2003 5:57:47 PM Type: Note REJECT (but deleted the conflicting paragraph in 7.15) REFER PROTOCOL WG (I think 7.15 should be fixed and this paragraph is correct. If there is one possible 3 Gbps path, the initiator should be allowed to request it, even if 1.5 Gbps paths might be available along the way. It may request 1.5 if it cares more about connecting that getting a certain rate.) 7.7.3 OPEN address frame page 153. Middle of page, sentence starting "When requesting a connection to a target port..." conflicts with section 7.15. Change sentence to "When requesting a connection to a target port, an initiator port shall set the CONNECTION RATE field to the slowest negotiated physical link rate on any potential intermediate physical link." Page: 157 Sequence number: 16 Date: 1/21/2003 11:28:12 AM Type: Note TODO (globally check "any primitive". Only mention that ALIGNs/NOTIFYs are ignored in the clock skew mgmt/rate matching/ALIGN prim/NOTIFY prim/XYZ receiver sections. Make sure each link layer state machine has a receiver section to include such a rule.) 7.8.6 SL\_IR transmitter and receiver page 157 ALIGNs are allowed inside of address frames. Change wording in second paragraph to "... a primitive other than ALIGN is requested ...". Change wording in third paragraph to "... shall ignore any primitive other than ALIGN received inside ..." Page: 163 Sequence number: 29 Date: 1/22/2003 9:54:13 AM Type: Note ACCEPT - DONE (Jan WG agreed AWT should be mandatory) 7.12.3 Arbitration fairness page 163 AWT is mandatory. Change start of second paragraph to "Each initiator port, target port, and expander port shall include an arbitration wait timer ..." Change start of third paragraph to "Initiator ports and target ports shall implement arbitration wait timers. They shall set the timer ..." Page: 174 Sequence number: 12 Date: 1/21/2003 11:29:27 AM Type: Note TODO (see other comment) 7.13.2 SL transmitter and receiver page 174 ALIGNs are allowed inside of address frames. Change wording in second paragraph to "... a primitive other than ALIGN is requested ...". Change wording in third paragraph to "... shall ignore any primitive other than ALIGN received inside ..." Page: 175 Sequence number: 2 Date: 1/11/2003 5:25:36 PM Type: Note ACCEPT - DONE 7.13.4.1 State description page 175

Last paragraph has a misformatted sentence with c).

Page: 190 Sequence number: 11 Date: 1/22/2003 9:55:00 AM Type: Note ACCEPT - DONE (globally fixed "an SATA" to "a SATA") 7.15 Rate matching page 190 Last paragraph should read "... port discovers a SATA target ..." (change "an" to "a") Page: 193 Sequence number: 7 Date: 1/22/2003 9:55:56 AM Type: Note ACCEPT - DONE 7.16.6 Preparing to close an SSP connection page 193 Last paragraph needs to include CREDIT\_BLOCKED. Change wording to "... may transmit ACK, NAK, RRDY, and CREDIT\_BLOCKED ..." Page: 194 Sequence number: 10 Date: 1/22/2003 10:00:07 AM Type: Note ACCEPT - DONE 7.16.7.1 Overview page 194 Sentence starting with "The SSP\_RF state machine ... " should read "... if those frames were successfully or unsucessfully received." (Add "ly") Page: 201 Sequence number: 4 Date: 1/22/2003 10:00:45 AM Type: Note ACCEPT - DONE 7.16.7.8 SSP\_TF4:Indicate\_Done\_Tx state page 201. Item c) should start "Wait For DONE (Credit Timeout) ...". Page: 202 Sequence number: 8 Date: 1/22/2003 10:01:45 AM Type: Note ACCEPT - DONE 7.16.7.12.2 Transition SSP\_TC1:Idle to SSP\_TC2:Indicate\_Credit\_Tx page 202 Add another sentence "This transition shall pass a CREDIT\_BLOCKED argument to the Indicate\_Credit\_Tx state if a Rx Credit Status (Blocked) parameter was received." Page: 207 Sequence number: 9 Date: 1/22/2003 10:04:13 AM Type: Note ACCEPT - DONE (but change "manages the STP connection requests" to "manages affiliations") 7.17.3 Preparing to close an STP connection page 207 In second paragraph, expander behavior regarding multi initiator ports is incorrect or misleading. Replace entire paragraph with: "In a SCSI domain with a single initiator port, when a SATA target port transmits an SATA\_X\_RDY, the expander device may use the time between SATA\_X\_RDY and SATA\_R\_RDY to insert an OPEN address frame to open a connection to the initiator port. In a SAS domain with multiple initiator ports, the expander device manages the STP connection requests (see 9.3.2). Only data FISes are subject to flow control, so the expander device shall be capable of accepting a whole register FIS frame." Page: 207 Sequence number: 10 Date: 1/22/2003 10:02:15 AM Type: Note

DE: NOTE ACCEPT - DONE 7.17.3 Preparing to close an STP connection page 207

Third paragraph starting "An expander device may issue CLOSE ..." conflicts with first paragraph. Remove entire paragraph.

Page: 214 Sequence number: 8 Date: 1/8/2003 9:34:52 AM Type: Note 8.2.1 Timers and counters overview page 214 Parentheses in item c) conflicts with section 4.5. Remove words in parentheses. Page: 215 Sequence number: 7 Date: 1/17/2003 12:33:18 PM Type: Note 8.2.5 Arbitration wait time (AWT) timer page 215 Add sentence at end "The AWT timer shall not be incremented past 7FFFh." Page: 216 Sequence number: 14 Date: 1/11/2003 5:24:51 PM Type: Note ACCEPT - DONE (it was pointing down not right) Figure 91 page 216 Arrowhead missing between PL\_OC1 and PL\_OC2 Page: 217 Sequence number: 14 Date: 1/8/2003 9:36:14 AM Type: Note ACCEPT - DONE 8.3.3.1.1 State description overview page 217 Replace "PM\_PM" with "PL\_PM". Page: 218 Sequence number: 11 Date: 1/8/2003 9:34:52 AM Type: Note 8.3.3.1.3 Select a request to process and the phy on which to process it page 218 Second paragraph, should also take the initiator bit into account. Change sentence to "A destination is considered the same if it has the same SAS address, initiator bit, and protocol." Page: 221 Sequence number: 8 Date: 1/11/2003 5:23:49 PM Type: Note ACCEPT - DONE 8.4.1 Overview page 221. Last sentence on page. Change "PL\_PM1" to "PL\_PM1:Idle". Page: 226 Sequence number: 13 Date: 1/8/2003 9:34:52 AM Type: Note 8.4.4.1 State Description page 226. Fifth paragraph on page is incorrectly issuing Disable Tx Frames for any DONE Received. Correct condition is already covered in fourth paragraph. Remove entire paragraph. Page: 228 Sequence number: 7 Date: 1/8/2003 9:36:35 AM Type: Note ACCEPT - DONE

9.2.1 SSP Frame Format page 228 Replace "TIMEOUT" with "RETRANSMIT" in table 88. Page: 229 Sequence number: 26 Date: 1/11/2003 4:13:41 PM Type: Note ACCEPT - DONE 9.2.1 SSP Frame Format page 229 Change Information unit size in table 89 for DATA from "0 to 1024" to "1 to 1024" Page: 246 Sequence number: 15 Date: 1/21/2003 12:01:03 PM Type: Note ACCEPT - TODO (Mark Evans will provide rewritten 2 paragraphs supporting data frame pipelining) 9.2.6.2.2.1 State Description page 246 Seventh paragraph (starting with "After receiving ...") and eighth paragraph (starting with "If the transmitted frame ...") are redundant, and transport should wait for port layer confirmation regardless of whether it is data-out or data-in operation. Change 7th paragraph to read as "After receiving a Transmission Status (Frame Transmitted) confirmation for a COMMAND or TASK frame, this state shall then wait for one of the following confirmations from the port layer state machine before transitioning from this state:" Remove eighth paragraph. Page: 250 Sequence number: 24 Date: 2/9/2003 10:49:30 AM Type: Note ACCEPT - DONE (ending with "based on the connection" rather than "for the connection") Page 250 9.2.6.2.8 ST\_IFR1:Initiator\_Frame\_Router state, sixth paragraph Reword first sentence: If the frame type is correct relative to the confirmation, then this state may check that the hashed source SAS address and the hashed destination SAS address in the frame match the source SAS address of the port transmitting the frame and the destination SAS address of the port receiving the frame for the current connection. Page: 252 Sequence number: 23 Date: 1/21/2003 12:03:20 PM Type: Note ACCEPT - TODO (also do a global search for other cases) Page 252 9.2.6.3.2 ST\_TFR1:Target\_Frame\_Router state, sixth paragraph Reword first sentence: If the frame type is correct relative to the confirmation, then this state may check that the hashed source SAS address and the hashed destination SAS address in the frame match the source SAS address of the port transmitting the frame and the destination SAS address of the port receiving the frame for the current connection. Page: 264 Sequence number: 14 Date: 2/5/2003 10:05:25 AM Type: Note ACCEPT - DONE (and mention that it shall be set to one) 9.4.4.2.3.1 State description page 264 Add INITIATOR field into sentence, to read "... CONNECTION RATE, INITIATOR, INITIATOR CONNECTION TAG, ..." Page: 264 Sequence number: 15 Date: 1/21/2003 12:12:57 PM Type: Note ACCEPT - TODO (also see IBM comment; check globally for past tense in transitions) 9.4.4.2.4.2 Transition MT\_ID3:Receive to MT\_ID1:Idle page 264 Change all occurances of "has sent" to "shall send" in items a), b), and c).

Page: 264 Sequence number: 16 Date: 1/11/2003 5:22:51 PM Type: Note ACCEPT - DONE 9.4.4.3.1 Overview page 264 Change item b) from "MT\_TD2:Send" to "MT\_TD2:Respond" Page: 276 Sequence number: 5 Date: 1/30/2003 2:30:11 PM Type: Note ACCEPT - DONE (the list downgraded to a list of examples) 10.1.3 Application client error handling page 276 Last paragraph implies a specific implementation, and does not cover the cases when the connection is broken. Recommend to remove last paragraph. Alternately say that the method the application client uses to reuse tags is outside the scope of this standard. Page: 324 Sequence number: 7 Date: 1/21/2003 4:15:08 PM Type: Note ACCEPT - DONE (all 3 parts) Annex B page 324 Replace references to figures A.1 and A.2 to B.1 and B.2 respectively. (DONE) In Figure B.1, sequence for Phy A Tx/ Phy B Rx should say "Not supported by phy A". (DONE) For consistency, swap the sequences so that Figures B.1 and B.2 are consistent as far as which Rx/Tx is shown on top. (In B.1, Phy A Rx is shown on top, where in B.2 Phy A Tx is shown on top). (DONE)

## Author: LSI jenkins

Page: 72 Sequence number: 1 Date: 1/20/2003 4:52:30 PM Type: Highlight ACCEPT - DONE (thanks) 5.7 Driver and receiver electrical characteristics For what it's worth, an acquaintance of mine who was not involved with the drafting of the SAS spec reviewed this document on behalf of another company. He offered the unsolicited comment that this was a quite well written specification. ...Just thought I'd pass that along.

Page: 77 Sequence number: 1 Date: 2/4/2003 7:09:11 PM Type: Highlight ACCEPT - DONE 5.7.4 Transmitted signal characteristics Table 35 — Transmitted signal characteristics at Tx compliance points 133 ps (0.2 UI) provides no overlap with required 3Gbps max rise time. I believe the initial intent was to track SATA. However, the SATA min risetime at 1.5Gbps is being changed to 100 ps (0.15 UI). I propose that SAS change this value to 67 ps (0.1 UI) at 1.5 Gbps, allowing extra room for higher performance devices. I also propose that the minimum rise/fall time of 67 ps (0.2 UI) at 3 Gbps be changed to 50 ps (0.15 UI) for similar reasons. Page: 78 Sequence number: 1 Date: 1/31/2003 5:00:08 PM Type: Highlight REFER PHY WG (OOB to be discussed next call. proposal by Russ Brown to include note c rewording) 5.7.4 Transmitted signal characteristics Table 36 — Delivered signal characteristic at Rx compliance points (part 2 of 2) "OOB detect guaranteed on (eye opening) ... OOB detect guaranteed off signal level " It is unclear to me a) how to interpret these values, and b) how they are meant to line up (if at all) with the SATA spec values. The signal characteristic names suggest that the first spec is the eye opening of a minimum valid signal, while the second spec is the

absolute peak-peak voltage of noise which must be ignored. This is fine, but it is unclear how this relates to footnote c which seems to be describing something different.

Regarding lining up with SATA, that document specifies "squelch detector threshold" with a min/max of 50/200 mVp-p. Apologies for having no clear recommended change, but it seems that a 120 mV required noise tolerance does not compare well with SATA's threshold range of 50 to 200 mV.

## Author: LSI John Lohmeyer

Page: iii Sequence number: 1 Date: 1/7/2003 11:08:51 AM Type: Note **REVIEW ALL WG** ACCEPT - DONE (contents merged with IBM comment) Abstract The abstract is incomplete. SAS also defines a physical layer and a management protocol (SMP). Consider replacing the existing abstract with: This standard specifies the functional requirements for the Serial Attached SCSI (SAS) physical interconnect, which is compatible with the Serial ATA physical interconnect. It also specifies three transport protocols, one to transport SCSI commands, another to transport Serial ATA commands to multiple target devices, and a third to support interface management. Page: ix Sequence number: 2 Date: 12/30/2002 10:43:24 AM Type: Highlight ACCEPT - DONE 1.19 Revision Information sas-r02c in 1.19 should be sas-r03, but all of the revision history needs to be removed for public review anyway. Page: xxxiii Sequence number: 1 Date: 12/30/2002 10:58:25 AM Type: Note ACCEPT - DONE Foreword I think it is appropriate to give a credit to the Serial Attached SCSI Working Group, which did the initial SAS proposal. This credit should go after the T10 member list. Possible wording: The Serial Attached SCSI Working Group provided the initial proposal for this standard. This Working Group consisted of the following member companies: <<<This list needs to be reviewed for accuracy>>> Adaptec Corp. Amphenol **BREA** Technologies Compaq Computer Corp. Crossroads Systems, Inc. Cypress Semiconductor Data Transit Corp. Dell **Eurologic Systems Limited** FCI Fujitsu Limited Hewlett Packard Co. Hitachi America, Ltd. IBM Corp. I-TECH Corp. KnowledgeTek, Inc. LSI Logic Corp. Marvell Technology Group Ltd. Maxtor Corp. Molex Inc. **NEC Electronics** QLogic Corp. Seagate Technology Serverworks Sierra Logic Silicon Image

Page: 5 Sequence number: 1 Date: 2/6/2003 11:46:53 AM Type: Highlight ACCEPT - DONE (new ATA terminology per Mark Evans proposal) 3.1.8 ATA target device and 3.1.9 ATA target port See previous comment. Page: 5 Sequence number: 2 Date: 2/6/2003 11:46:43 AM Type: Highlight ACCEPT - DONE (new ATA terminology per Mark Evans proposal. ATA target device only has one ATA target port, so they ARE both equivalent.) 3.1.8 ATA target device and 3.1.9 ATA target port Since both ATA target device and ATA target port are equivalent to a device in ATA, does this mean that ATA target devices and ATA target ports are equivalent? If not, then one of these things is not equivalent to an ATA device. Page: 6 Sequence number: 5 Date: 1/7/2003 2:22:57 PM Type: Highlight ACCEPT - DONE 3.1.32 downstream phy Replace "direction frame transmission" with "direction of frame transmission" Page: 6 Sequence number: 6 Date: 2/6/2003 1:44:10 PM Type: Highlight **REVIEW PROTOCOL WG** REJECT - TODO (but general issue addressed with internal phy/internal SAS device concept. SAS devices are the generic term, which may be in end devices or expander devices.) 3.1.37 end device Delete "that is not contained within an expander device". This is the first of several comments on "internal devices" and "internal ports". The current working draft does not use this terminology consistently and needs a number of changes no matter how the problem is solved. I prefer a solution that acknowledges that internal devices are just like external devices except for their lack of phys and does not attempt to merge internal devices into the expander device definition. Places I addressed in my comments: 3.1.37 end device 3.1.40 expander device 3.1.43 expander port 3.1.66+ internal device 3.1.70 link 3.1.73+ logical link 3.1.82 partial pathway 3.1.83 pathway 4.1.3 Ports (narrow ports and wide ports) 4.6.1 Expander device model overview 4.1.8.1 Expander device overview 4.1.8.2 Edge expander device set: 3rd paragraph. Is 64 the maximum number of phys or devices? 4.1.8.2 Edge expander device set, Figure 11 - Edge expander device set 4.1.12 Pathways 4.4.2 Hard reset - fifth paragraph 5.3.2.1 SAS plug connector overview Places possibly needing additional changes: 4.1.8.2 Edge expander device set: 1st paragraph; 2nd sentence. Address internal devices? 4.1.8.3 Configurable expander device: 1st paragraph; last sentence. Does the ECM route requests to non-phys? 4.1.9 Domains, Figure 12 - Domains and connections. Should internal devices be shown? 4.1.10 Expander device topologies: 3rd paragraph.

4.1.10 Expander device topologies, Figures 14-16 Should internal devices be shown?

4.1.11 Connections, Figure 17 Should internal devices be shown? 7.7.2 IDENTIFY address frame, Table 73 - Device types and paragraph above the table 7.12.4.2 Edge expander devices, Table 80 10.3.1 SMP functions. We may need to revise or add functions to properly support internal devices. 10.3.1.2 REPORT GENERAL response (in particular, the NUMBER OF PHYS field may need clarification and we may need to add a field for the number of internal ports). 10.3.1.4 DISCOVER function, Table 138 may need a clarification Page: 7 Sequence number: 4 Date: 1/7/2003 2:28:19 PM Type: Highlight ACCEPT - DONE 3.1.55 hash function Replace "and that reduces" with "reducing" Page: 7 Sequence number: 5 Date: 2/6/2003 3:26:45 PM Type: Highlight REJECT (but rewritten) 3.1.40 expander device Replace the last sentence with: "An expander device supports SMP via an internal SMP target device. However, this internal device is logically considered outside the expander device. Other internal devices (e.g., a SCSI device supporting enclosure services) may also be packaged with expander devices, however these devices are also logically considered outside the expander device. Page: 7 Sequence number: 6 Date: 2/7/2003 11:02:34 AM Type: Highlight REJECT (but rewritten based on other comments) 3.1.43 expander port Replace "physical links or to internal initiator ports and/or target ports. Contains one or more phys." with "links. Contains zero or more phys." Page: 8 Sequence number: 4 Date: 12/30/2002 10:07:04 AM Type: Note After 3.1.66 Add a new definition: "3.1.66+ internal device: An end device that is physically packaged with an expander device and uses a logical link." Page: 8 Sequence number: 5 Date: 2/7/2003 6:32:45 PM Type: Highlight REJECT (but deleted "link" altogether. Changed some remaining uses to "physical link" throughout the document.) 3.1.70 link Replace "physical link" with "physical or logical link". Page: 8 Sequence number: 6 Date: 2/7/2003 6:35:32 PM Type: Note REJECT (we don't need to name that link since there are no specs on it and no references to it. We just say an internal phy attaches to an internal SAS port.) After 3.1.73 Add a new definition: "3.1.73+ logical link: For internal devices, the virtual link from the expander port to the internal device port. Contains no phys." Page: 9 Sequence number: 4

Sequence number: 4 Date: 1/30/2003 3:20:43 PM Type: Highlight

REJECT (just leaving OOB here alone in both 3.1.80 and 3.1.81) 3.1.81 OOB signal Replace "out-of-band (OOB)" with "OOB". Page: 9 Sequence number: 5 Date: 1/30/2003 3:20:37 PM Type: Highlight REJECT (just leaving OOB here alone in both 3.1.80 and 3.1.81) 3.1.80 OOB sequence Replace "OOB" with "out-of-band (OOB)". Page: 9 Sequence number: 6 Date: 1/22/2003 10:38:11 AM Type: Strikeout REJECT - we don't use link alone 3.1.82 partial pathway Delete "physical". Page: 9 Sequence number: 7 Date: 1/22/2003 10:38:01 AM Type: Strikeout REJECT - we don't use link alone 3.1.83 pathway Delete "physical". Page: 10 Sequence number: 3 Date: 2/4/2003 7:01:11 PM Type: Highlight REJECT (why expand each and/or into lots of text more prone to errors?) 3.1.101 SAS domain Global Replace "an ATA domain and/or a SCSI domain" with an ATA domain, a SCSI domain, or both domains". This comment applies to all occurrences of and/or. Page: 10 Sequence number: 4 Date: 1/7/2003 2:56:47 PM Type: Note ACCEPT - DONE 3.1.122 Serial ATA (SATA) Add "(see 2.4)" to the end of the definition. Page: 11 Sequence number: 2 Date: 1/7/2003 2:59:18 PM Type: Note REJECT - use "set of protocols and the interconnect" 3.1.124 Serial Attached SCSI (SAS) This definition is confusing in that this standard defines three protocols (SSP, STP, and SMP) plus a physical transport. It may be easiest just to delete this definition. Page: 12 Sequence number: 1 Date: 12/30/2002 11:06:06 AM Type: Note ACCEPT - DONE 3.2 Symbols and abbreviations Add: EMI electromagnetic interference EMI is referenced in 7.15. Page: 15 Sequence number: 2 Date: 1/7/2003 3:06:41 PM Type: Highlight

ACCEPT - DONE (removed second sentence; small caps is correct) 3.4 Editorial conventions The first sentence after Table 2 is redundant with the last sentence of the third paragraph. Delete one of these sentences. Why does one have NAME in small caps and the other is lower-case? Page: 17 Sequence number: 1 Date: 1/7/2003 3:13:28 PM Type: Highlight ACCEPT - DONE 3.5.2 Transitions In the last paragraph of this subclause, replace "valid in entry" with "valid upon entry". Page: 17 Sequence number: 2 Date: 1/7/2003 5:19:38 PM Type: Highlight ACCEPT - DONE 3.5.3 Parameters, requests, etc. In the last paragraph of this subclause, replace "onto" with "to". Page: 17 Sequence number: 3 Date: 1/7/2003 5:22:20 PM Type: Highlight ACCEPT - DONE 3.6 Bit and byte ordering In the fourth paragraph, replace "non-monotonically" with "non-sequentially". Page: 18 Sequence number: 1 Date: 12/30/2002 11:09:17 AM Type: Note ACCEPT - DONE 3.7 Notation for procedures and functions In the first procedure (Procedure Name), the parenthesis do not match. If the Search example below is correct, then there is an extra right parenthesis after input-2. Page: 21 Sequence number: 1 Date: 1/7/2003 5:31:03 PM Type: Highlight ACCEPT - DONE 4.1.3 Ports (narrow ports and wide ports) In the third paragraph, replace "with one phy" with "with only one phy". Page: 21 Sequence number: 2 Date: 12/30/2002 10:07:04 AM Type: Note 4.1.3 Ports (narrow ports and wide ports) Rename this subclause: 4.1.3 Ports (narrow ports, wide ports, and internal ports) Add the following paragraph: "An internal port in an expander device does not contain a phy and is used to connect to an internal device." Page: 24 Sequence number: 1 Date: 1/22/2003 3:07:34 PM Type: Highlight REJECT (STP target ports are allowed)(whole section being deleted anyway) 4.1.6 Target devices Figure 9 - Target device The text "STP and SMP" is too close to the line. Page: 24 Sequence number: 2 Date: 1/22/2003 3:07:48 PM Type: Note

REJECT (STP target ports are allowed)(whole section being deleted anyway) 4.1.6 Target devices Figure 9 - Target device Don't most ATA targets use SATA protocol instead of STP protocol? Also, see the related comment at 4.1.11 Connections. Page: 25 Sequence number: 1 Date: 2/8/2003 11:16:41 AM Type: Note ACCEPT - DONE 4.1.8.1 Expander device overview Figure 10 - Expander Device Modify the figure to show the required SMP target port. The internal expander ports should be included in the Expander device (shaded box) while the target and initiator internal ports should be outside the shaded box. Page: 25 Sequence number: 2 Date: 12/30/2002 10:07:04 AM Type: Highlight 4.1.8.1 Expander device overview Replace the second sentence of the first paragraph with: "Expander devices include one or more internal expander ports connected to internal devices. These internal ports use a logical link that does not contain phys. All expander devices have one internal expander port connected to an internal SMP target port. They may have additional internal expander ports connected to internal initiator ports or internal target ports (e.g., a SCSI enclosure services target device)." Page: 25 Sequence number: 3 Date: 12/30/2002 10:07:04 AM Type: Highlight 4.1.8.2 Edge expander device set Third paragraph. Should this maximum be the number of devices or phys? Page: 26 Sequence number: 3 Date: 2/8/2003 11:18:20 AM Type: Note REJECT (but deleted this anyway) 4.1.8.2 Edge expander device set Figure 11 - Edge expander device set Show the internal target port outside the Edge expander device set box. Page: 30 Sequence number: 5 Date: 1/23/2003 4:58:58 PM Type: Note ACCEPT - DONE (list removed in favor of generic SSP, STP, and SMP references. We can't say ATA initiator any more.) 4.1.11 Connections In the first list, it appears that a connection type has been omitted: d) ATA initiator port(s) using STP to ATA target port(s) using STP. If this connection type is not intended to be supported, then delete STP target ports from the second paragraph in 4.1.6 and from Figure 9 Page: 31 Sequence number: 3 Date: 12/30/2002 10:07:04 AM Type: Highlight 4.1.11 Connections In the third list, why does item d) appear on the next page? There is plenty of room to place it on the same page with the first three list items. Page: 31 Sequence number: 4 Date: 12/30/2002 10:07:04 AM Type: Highlight 4.1.12 Pathways Is there a pathway to an internal target device? If so, then the first paragraph needs some changes to accommodate targets without phys. I suggest re-wording the second paragraph of this paragraph as follows:

"In the case where there are expander devices between an initiator and a target, the pathway consists of all the links required to route dwords between the initiator and the target."

Page: 32 Sequence number: 2 Date: 12/30/2002 10:07:04 AM Type: Note 4.1.12 Pathways Figure 18 - Pathways The pathway lines and arcs obscure the physical link lines. Consider moving them a bit above or below the physical link lines. Page: 32 Sequence number: 3 Date: 12/30/2002 10:07:04 AM Type: Highlight 4.1.12 Pathways Add a forward reference from the e.g. in the first paragraph under Figure 18 to the subclause on connections: (see 7.12). Page: 32 Sequence number: 4 Date: 12/30/2002 10:07:04 AM Type: Strikeout 4.1.12 Pathways Delete "physical" from the paragraph after figure 18. Page: 49 Sequence number: 1 Date: 1/24/2003 9:47:09 AM Type: Note REFER PROTOCOL WG 4.4.2 Hard Reset The second paragraph, first sentence is ambiguous. What exactly does "stop transmitting" mean? Is this the Tx Off Voltage in table 35? If so, add a forward reference. What are the timing requirements to stop transmitting? Page: 49 Sequence number: 2 Date: 12/30/2002 10:07:04 AM Type: Highlight 4.4.2 Hard Reset Delete the second sentence of the fifth paragraph and add the following two paragraphs after the fifth paragraph: "If the port is an internal port within an expander device and the internal port is connected to an internal SCSI device, this causes a Transport Reset event notification to the SCSI application layer (see 10.1.4); the SCSI device shall perform the actions defined for hard reset in SAM-3. If the port is an internal port within an expander device and the internal port is connected to an internal ATA device, the ATA device shall perform the actions defined for power-on or hardware reset in ATA." Page: 49 Sequence number: 3 Date: 12/30/2002 10:07:04 AM Type: Highlight 4.6.1 Expander device model overview First list, item d). Replace "internal" with "internal expander port providing a connection for an internal SMP target port." Page: 50 Sequence number: 1 Date: 2/9/2003 5:26:49 PM Type: Note ACCEPT - TODO (the "port" boxes should all have "more than one" constructs. Also, the external phy "more than one" boxes should be on the bottom right to match other such figures) 4.6.1 Expander device model overview Figure 25 Is there some reason that only one SATA port is shown? Don't ports automatically configure to the protocol of the attached device? Page: 50 Sequence number: 2 Date: 12/30/2002 10:07:04 AM Type: Highlight 4.6.1 Expander device model overview Replace "the following:" with "additional internal expander ports providing connections for:"

Page: 66 Sequence number: 1 Date: 1/31/2003 5:16:12 PM Type: Note ACCEPT - DONE (Reject size, accept color suggestion. Size will vary depending on needs of the figure rather than size consistancy from figure to figure.) 5.2 SAS cables and connectors Figure 33 Where SAS uses the same connector as in SATA, the color and size should match the corresponding connector in figure 31. Thus the SATA-style host plug connector should be dark green and be the same size as the dark green signal host plug connector in figure 31. The signal portions of the SAS internal cable connectors need to be shown in pink (just like the SATA internal cable) and the end that plugs into the target device needs to be the same width as the SAS plug connector. Page: 67 Sequence number: 1 Date: 1/31/2003 4:04:23 PM Type: Note ACCEPT - DONE (per PHY WG. Accept. Type of connector: SAS internal cable SATA-style signal cable receptacle, Reference: SATA, Attaches to: SATA-style host plug, Reference SATA.) 5.2 SAS cables and connectors Table 29 - Connectors Add rows for the SATA-style host plug connector and the SATA-style signal cable receptacle. References should be to SATA for the connector drawings and to 5.4.1 for pin assignments. Page: 67 Sequence number: 2 Date: 1/31/2003 4:06:16 PM Type: Highlight ACCEPT - DONE 5.2 SAS cables and connectors Penultimate paragraph. Replace "second" with "secondary". Page: 67 Sequence number: 3 Date: 1/31/2003 4:10:28 PM Type: Highlight ACCEPT - DONE (per SAS PHY WG Change text to: "SAS target devices supporting internal interconnection of physical link(s) and power...") 5.3.2.1 SAS plug connector overview This subclause uses "internal ports" for a different concept than used elsewhere in the standard. I recommend replacing "internal ports" with "internal connections". Page: 67 Sequence number: 4 Date: 1/31/2003 4:38:43 PM Type: Strikeout ACCEPT - DONE 5.3.3 SAS internal cable receptacle connector In list item b, delete "only". Page: 67 Sequence number: 5 Date: 1/31/2003 4:38:35 PM Type: Strikeout ACCEPT - DONE 5.3.4 SAS backplane receptacle connector In list item b, delete "only". Page: 67 Sequence number: 6 Date: 1/20/2003 4:07:16 PM Type: Highlight ACCEPT - DONE 5.3.2.1 SAS plug connector overview Since 5.3.2.1 is the only subclause under 5.3.2, promote this subclause.

Date: 2/9/2003 5:35:08 PM Type: Note REJECT (per PHY WG. You are correct that the signals do not cross, but they do not cross because the pin signal assignments are different for an initiator and a target. Unlike SATA, with SAS there is a target connector and an initiator connector. We did not see the merit of the comment and did not understand why it was made except for possible confusion with the original SAS pinout when the initiator and target pin assignments were different.)) 5.3.5 SAS internal connector pin assignments In the first paragraph under table 30, the second sentence is either not true or misleading. The Rx and Tx signals are not crossed in the SAS internal cable assembly using the SATA-style signal cable receptacle on one end and the SAS internal cable receptacle on the other end (see figure 34). Page: 69 Sequence number: 1 Date: 1/31/2003 4:24:21 PM Type: Highlight ACCEPT - DONE (per PHY WG but as should rather than It is recommended. Accept Add sentence: It is recommended that external cables be labeled to indicate how many physical links are included (e.g., X1, X2, X3, and X4 on each connector's housing).) 5.3.8 SAS external connector pin assignments We should recommend that external cables be labeled to indicate how many physical links are included (e.g., X1, X2, X3, and X4 on each connector's overmolding). Page: 71 Sequence number: 1 Date: 1/20/2003 4:31:26 PM Type: Highlight ACCEPT - DONE (per phy WG, removed whole secod half of sentence including all color references) 5.6 READY LED pin Replace "shall" with "should". The visual output color is not important to the operation of the interface. Page: 71 Sequence number: 2 Date: 1/31/2003 5:30:44 PM Type: Highlight ACCEPT - DONE (although compond adjectives may use extra hyphens, they don't have to. Nevertheless, removed everywhere not used preceding a noun.) 5.6 READY LED pin Global List item d), last sentence. Replace "vendor-specific" with "vendor specific". Global comment: There is no hyphen if these words are not used as an adjective modifying a noun. There are also many places in the document where the hyphen needs to be added because vendor-specific is used as an adjective modifying a noun. Page: 86 Sequence number: 1 Date: 1/24/2003 12:01:04 PM Type: Highlight ACCEPT - DONE (globally) 6.2.1 Encoding overview Global Replace "10 bit" with "10-bit" whenever this phrase is used as an adjective to modify characters or bytes. This comment also applies to the occurrences of "8 bit", which should be changed to "8-bit". Page: 100 Sequence number: 1 Date: 1/8/2003 2:59:51 PM Type: Highlight ACCEPT - DONE 6.6.3 SAS to SATA phy reset sequence The text (two paragraphs above Figure 50 - SAS to SATA OOB sequence) says that the SAS phy responds with COMRESET. However figure 50 shows a COMWAKE at this point. Page: 100 Sequence number: 2 Date: 1/24/2003 2:48:18 PM

Type: Highlight

Sequence number: 1

ACCEPT - DONE (hot-plug timeout is currently in the speed negotiation sequence timing table. It is really related to the phy reset sequence, not just the speed negotiation sequence. I think a new phy reset sequence timing table should be created in 6.6.1 that

includes the hot-plug timeout. Then, this is no longer a forward reference. Tom agrees) 6.6.4.1 SAS OOB sequence Add forward reference in first paragraph: "hot-plug timeout (see table 49)".

Page: 101 Sequence number: 1 Date: 1/24/2003 2:51:35 PM Type: Highlight ACCEPT - DONE (reworded if phrases to the front of each of a) and b)) 6.6.4.1 SAS OOB sequence In the first list, shouldn't item a) be: "... has not yet transmitted a COMINIT, followed by a COMSAS; or" Page: 104 Sequence number: 1 Date: 1/24/2003 3:46:36 PM Type: Highlight ACCEPT - DONE (create a timing table in 6.6.2 for this. SATA unfortunately doesn't refer to this time by name - the 880 is embedded in the state machine description. We don't want to do that.) 6.6.4.2 SAS speed negotiation sequence Table 49 - SAS speed negotiation sequence timing specs (last row) What is a SATA speed negotiation parameter doing in a SAS speed negotiation table? Either put this parameter in a different table or name of this table appropriately (e.g., delete "SAS"). Page: 109 Sequence number: 1 Date: 1/10/2003 5:02:47 PM Type: Highlight ACCEPT - DONE 6.8.2 OOB sequence states Figure 56 - SAS phy (SP) state machine - OOB sequence states The "COMSAS Transmitted" parameter into the SP3:OOB AwaitCOMINIT Sent should be "COMINIT Transmitted". Page: 111 Sequence number: 1 Date: 1/10/2003 10:42:21 AM Type: Highlight ACCEPT - DONE 6.8.2.7.2 Transition SP7:OOB\_AwaitCOMSAS to SP1:OOB\_COMINIT List item a) is missing the verb "is". It should read: "a) this device is in..." Page: 112 Sequence number: 1 Date: 1/10/2003 5:13:35 PM Type: Highlight ACCEPT - DONE (changed to the new SP2 state) 6.8.2.7.5 Transition SP7:OOB AwaitCOMSAS to SAS AwaitNoCOMX Where does this transition really go? The subclause title is missing the state descriptor. Figure 56 shows this transition going to SP2:OOB\_AwaitCOMx. Page: 114 Sequence number: 2 Date: 12/30/2002 10:07:04 AM Type: Note Editor's Notes Global Obviously, the four editor's notes need to be resolved and removed. Page: 115 Sequence number: 1 Date: 2/4/2003 6:44:46 PM Type: Highlight ACCEPT - DONE 6.8.3.4.1 State description Second paragraph should read: "This state shall repeatedly send a Transmit ALIGN1 parameter..." Page: 115 Sequence number: 2 Date: 12/30/2002 10:07:04 AM Type: Highlight

6.8.3.4.3 Transition SP11:SAS\_AwaitALIGN1 to SP14:SAS\_AwaitSNW Replace "SNTT" with "SNLT". Should we add a note to clarify that this transition is not taken if ALIGN1 is detected after SNLT expires and before SNTT expires? Page: 115 Sequence number: 3 Date: 12/30/2002 10:07:04 AM Type: Highlight 6.8.3.5.2 Transition SP12:SAS\_AwaitALIGN1 to SP13:SAS\_Pass Replace "if" with "after". Page: 115 Sequence number: 4 Date: 12/30/2002 10:07:04 AM Type: Highlight 6.8.3.6.2 Transition SP13:SAS\_Pass to SP8:SAS\_Start The term "fallen back" is not defined. Should it be defined as an SP14 to SP2 transition? "Fallen back" also appears in 6.8.3.6.3. Page: 116 Sequence number: 1 Date: 2/4/2003 6:43:47 PM Type: Highlight ACCEPT - DONE (deleted duplicate sentence) 6.8.3.8.1 State description The last sentence of the last paragraph is redundant with the previous paragraph. Page: 118 Sequence number: 1 Date: 1/8/2003 6:51:06 PM Type: Highlight ACCEPT - DONE 6.8.4 SATA host emulation states

Third paragraph: Replace "specification" with "standard".

Page: 118 Sequence number: 2 Date: 2/4/2003 6:46:23 PM Type: Note 6.8.4 SATA host emulation states ACCEPT - DONE Figure 58 - SAS phy (SP) state machine - SATA host emulation states State SP16 needs a COMWAKE Transmitted input parameter (see 6.8.4.1.2). Page: 118 Sequence number: 3 Date: 2/4/2003 6:49:34 PM Type: Note ACCEPT - DONE 6.8.4 SATA host emulation states Figure 58 - SAS phy (SP) state machine - SATA host emulation states State SP17 needs a COMWAKE Detected input parameter (see 6.8.4.2.2). Page: 118

Sequence number: 4 Date: 2/4/2003 6:49:41 PM Type: Note ACCEPT - DONE 6.8.4 SATA host emulation states Figure 58 - SAS phy (SP) state machine - SATA host emulation states State SP18 needs a COMWAKE Completed input parameter (see 6.8.4.3.2). Page: 119

Sequence number: 1 Date: 1/11/2003 4:06:41 PM Type: Highlight 6.8.4.4.1 State description In list item c, replace "ALIGN" with "ALIGN0". Page: 119 Sequence number: 2 Date: 2/4/2003 7:02:32 PM Type: Highlight ACCEPT - DONE ("after entry into this state.") 6.8.4.4.1 State description Should the last word of this subclause be "completed"? If not, define "deasserted". Page: 120 Sequence number: 1 Date: 2/4/2003 6:50:50 PM Type: Highlight ACCEPT - DONE 6.8.4.6.1 State description Replace "ALIGN0s" with "ALIGN0". Page: 120 Sequence number: 2 Date: 2/4/2003 7:04:03 PM Type: Highlight ACCEPT - DONE 6.8.4.7.3 Transition SP22:SATA\_PHY\_Ready to SP24:SATA\_PM\_Partial Change this subclause name to "Transition SP22:SATA\_PHY\_Ready to SP23:SATA\_PM\_Partial" (i.e., SP24 should be SP23). Page: 120 Sequence number: 3 Date: 2/4/2003 7:03:57 PM Type: Highlight ACCEPT - DONE 6.8.4.7.4 Transition SP22:SATA PHY Ready to SP23:SATA PM Slumber Change this subclause name to "Transition SP22:SATA PHY Ready to SP24:SATA PM Slumber" (i.e., SP23 should be SP24). Page: 120 Sequence number: 4 Date: 2/4/2003 7:05:56 PM Type: Highlight ACCEPT - DONE 6.8.4.7.2 Transition SP22:SATA\_PHY\_Ready to SP1:Reset Change this subclause name to "Transition SP22:SATA\_PHY\_Ready to SP1:OOB\_COMINIT" (i.e., Reset should be OOB COMINIT). Page: 120 Sequence number: 5 Date: 2/4/2003 6:55:05 PM Type: Highlight REJECT (but corrected picture to match this text) 6.8.4.8.2 Transition SP23:SATA PM Partial to SP16:SATA COMWAKE Change the name of this subclause to "Transition SP23:SATA\_PM\_Partial to SP17:SATA\_AwaitCOMWAKE". Page: 120 Sequence number: 6 Date: 12/30/2002 10:07:04 AM Type: Highlight 6.8.4.8.1 State description 6.8.4.9.1 State description Replace "Exit from this state is driven from" with "This state is exited upon". Page: 123 Sequence number: 1 Date: 1/11/2003 4:08:39 PM Type: Highlight ACCEPT - DONE 6.9.2.1 State description Replace "upon power on loss or previous dword synchronization" with "upon power on or loss of previous dword synchronization." Page: 123 Sequence number: 2 Date: 1/24/2003 6:35:43 PM Type: Note

ACCEPT - DONE 6.9.3 SP1\_DWS1:Valid1 state This transition needs to be added to the text: 6.9.3.3 Transition SP\_DWS1:Valid1 to SP\_DWS0:AcquireSync "This transition shall occur when an invalid dword is detected." Page: 123 Sequence number: 3 Date: 12/30/2002 10:07:04 AM Type: Highlight 6.9.5.1 State description The text refers to a PhyReady (SAS) parameter and to a PhyReady (SATA) parameter as being inputs to this state. However, neither is shown in figure 59. These parameters should be added to the figure. Page: 124 Sequence number: 1 Date: 12/30/2002 10:07:04 AM Type: Highlight 6.9.7.1 State description 6.9.9.1 State description 6.9.11.1 State description Replace the first sentence with: "This state is reached if a valid dword is received while in the previous state. Receiving another valid dword in this state nullifies the previous invalid dword. " Page: 128 Sequence number: 1 Date: 1/6/2003 1:22:34 PM Type: Highlight ACCEPT - DONE 7.1.2 Primitive summary Table 51 Table 52 Table 53 Note c in the three primitive tables omits single primitive from the list of primitive types. Add "as a single primitive," to the list in note c for each table. Page: 137 Sequence number: 3 Date: 1/6/2003 1:29:35 PM Type: Highlight ACCEPT - DONE (reworded as "Processed the same ... by end devices" to match other tables) 7.1.4.4 BROADCAST Table 59 - BROADCAST primitives Replace "process the same" with "process this primitive the same". Page: 138 Sequence number: 1 Date: 1/6/2003 1:31:46 PM Type: Highlight ACCEPT - DONE 7.1.4.6 EOAF (End of address frame) The link to 7.4 is wrong. Replace it with a link to 7.7. Page: 138 Sequence number: 2 Date: 1/6/2003 1:34:55 PM Type: Strikeout ACCEPT - DONE 7.1.4.9 NOTIFY Last sentence of third paragraph. Delete "as described in TBD" or fill in a valid TBD. Page: 138 Sequence number: 3 Date: 1/6/2003 1:34:45 PM Type: Highlight REJECT - there's no real prohibition against sending it to other types of SAS devices. Only SSP targets require it. 7.1.4.9 NOTIFY In the fourth paragraph, replace "while" with "only while".

Page: 140 Sequence number: 1 Date: 1/16/2003 6:42:44 PM Type: Highlight ACCEPT - TODO (Either: a) no such destination device; or b) the SAS address is valid for a SATA target device attached to an expander device, but the initial Register FIS has not been successfully received. 7.1.4.11 OPEN\_REJECT Table 62 - OPEN\_REJECT retry primitives The wording in the description of OPEN\_REJECT (NO DESTINATION) is confusing. I think you should replace "devices" with "device" in the third line, but perhaps there is a better change. Page: 141 Sequence number: 1 Date: 1/6/2003 1:40:57 PM Type: Highlight ACCEPT - DONE 7.1.4.12 SOAF (Start of address frame) The link to 7.4 is wrong. Replace it with a link to 7.7. Page: 142 Sequence number: 2 Date: 2/7/2003 6:12:39 PM Type: Highlight REJECT (no, normal ERROR is used in that case) 7.1.6.1 SATA ERROR In the first paragraph, isn't SATA\_ERROR also sent when forwarding dwords from a SATA link to a SAS link and an invalid dword is received? Page: 142 Sequence number: 3 Date: 1/6/2003 1:52:16 PM Type: Highlight ACCEPT - DONE 7.1.6.2 SATA\_PMACK, SATA\_PMNAK, SATA\_PMREQ\_P, and SATA\_PMREQ\_S (Power management acknowledgements and requests) The link to 7.4 is not correct. I think 7.9 is the correct link. Page: 143 Sequence number: 2 Date: 1/6/2003 1:46:08 PM Type: Highlight ACCEPT - DONE 7.2 Clock skew management In the second paragraph, replace "To solve this," with "To solve this problem,". Page: 143 Sequence number: 3 Date: 2/4/2003 6:40:38 PM Type: Highlight ACCEPT - DONE 7.2 Clock skew management In the second paragraph, replace "strip it out" with "strip them out". Page: 143 Sequence number: 4 Date: 12/30/2002 10:07:04 AM Type: Highlight 7.2 Clock skew management In the second paragraph, replace "make it to" with "are placed into". Page: 144 Sequence number: 1 Date: 1/6/2003 1:55:38 PM Type: Strikeout ACCEPT - DONE (added "a phy" before "that is" so it doesn't look like i.e. is being replicated) 7.2 Clock skew management

Date: 12/30/2002 10:07:04 AM

Page: 146 Sequence number: 1 Date: 1/6/2003 2:00:19 PM Type: Highlight ACCEPT - DONE 7.4.2 CRC generation In the sentence above 7.4.3, the link to 6.5 is wrong. I think it should be to 7.6, Bit order of CRC and Scrambler. Page: 147 Sequence number: 1 Date: 1/6/2003 2:02:12 PM Type: Highlight ACCEPT - DONE 7.4.3 CRC checking In the penultimate paragraph, the link to 6.5 is wrong. I think it should be to 7.6, Bit order of CRC and Scrambler. Page: 147 Sequence number: 2 Date: 1/6/2003 2:02:01 PM Type: Highlight ACCEPT - DONE (removed paragraph) 7.4.3 CRC checking In the last paragraph, the link to Annex B is wrong. I think it should be to Annex C, CRC. Page: 147 Sequence number: 3 Date: 1/8/2003 1:29:50 PM Type: Highlight ACCEPT - DONE 7.5 Scrambling In the paragraph above table 69, the reference to 6.5 is wrong. I think it should be to 7.6, Bit order of CRC and Scrambler. Page: 147 Sequence number: 4 Date: 1/8/2003 1:29:39 PM Type: Highlight ACCEPT - DONE 7.5 Scrambling In the first paragraph, second sentence, replace "issues" with "EMI issues". Page: 150 Sequence number: 1 Date: 1/8/2003 1:32:07 PM Type: Highlight REJECT (if we put the range here it's bound to change) 7.7.1 Address frames overview In the paragraph below table 71, replace "entire address frame" with "address frame (bytes 0 through 27)". Page: 152 Sequence number: 1 Date: 12/30/2002 3:48:56 PM Type: Note ACCEPT - DONE 7.7.3 OPEN address frame The descriptions of the fields in table 74 should be re-ordered to match the order of the fields in the table. Page: 154 Sequence number: 1 Date: 1/6/2003 2:12:42 PM Type: Highlight ACCEPT - DONE 7.8.1 Overview In the penultimate paragraph, replace "it" with "the additional IDENTFY address frame". Page: 154 Sequence number: 2

Type: Strikeout 7.8.2 Initiator device specific rules 7.8.3 Fanout expander device specific rules 7.8.4 Edge expander device specific rules Delete "specific" from each of these subclause titles. Page: 155 Sequence number: 1 Date: 12/30/2002 10:07:04 AM Type: Highlight 7.8.2 Initiator device specific rules Replace the second paragraph with "When the discover process is done after a link reset sequence, the application client within an initiator device discovers all the devices in the SAS domain. When the discover process is done after a BROADCAST (CHANGE), the application client within an initiator device determines what has changed in the SAS domain.". Page: 155 Sequence number: 2 Date: 12/30/2002 10:07:04 AM Type: Strikeout 7.8.4 Edge expander device specific rules Assuming my previous comment on the 7.8.2 title is accepted, delete "specific" in the second paragraph of this subclause. Page: 155 Sequence number: 3 Date: 1/24/2003 7:40:57 PM Type: Strikeout ACCEPT - DONE 7.8.5.1 Overview Delete reference to 7.8; we are already in subclause 7.8. Page: 157 Sequence number: 1 Date: 12/30/2002 10:07:04 AM Type: Highlight 7.8.6 SL\_IR transmitter and receiver In the paragraph below the list, what should the SL\_IR transmitter do if a primitive is requested to be transmitted while sending an IDENTIFY address frame? Discard the primitive or store it until the EOAF? Page: 157 Sequence number: 2 Date: 12/30/2002 10:07:04 AM Type: Highlight 7.8.6 SL\_IR transmitter and receiver The last sentence of the last paragraph is not clear. We need to explain what is magical about the 8th data dword. Page: 158 Sequence number: 1 Date: 12/30/2002 10:07:04 AM Type: Highlight 7.8.6.1.4.2 Transition SL IR TIR3:Transmit Hard Reset to SL IR TIR3:Completed Replace "SL\_IR\_TIR3:Completed" with "SL\_IR\_TIR4:Completed" in the title of this subclause. Page: 159 Sequence number: 1 Date: 12/30/2002 10:07:04 AM Type: Highlight 7.8.6.2.3.1 State description In the last paragraph, replace "illegal" with "invalid". Page: 159 Sequence number: 2 Date: 12/30/2002 10:07:04 AM Type: Highlight 7.8.6.3.2 SL\_IR\_IRC1:Idle state The state diagram (figure 67) shows an identify 'Timeout' parameter confirmation leaving this state, but it is not described. I think it was moved to the SL\_IR\_IRC2 state and should be deleted from this state in the state diagram. Page: 160

Sequence number: 2

Date: 12/30/2002 10:07:04 AM Type: Highlight 7.8.6.3.3.1 State description The first list item talks about an "Identify Sequence Complete confirmation". However this confirmation does not appear in figure 67. Please add it to the figure. Page: 160 Sequence number: 3 Date: 12/30/2002 10:07:04 AM Type: Highlight 7.8.6.3.3.1 State description The penultimate paragraph talks about an "Identify Received parameter". However this parameter does not appear in figure 67. Please add it to the figure. Page: 160 Sequence number: 4 Date: 12/30/2002 10:07:04 AM Type: Highlight 7.8.6.3.3.1 State description The penultimate paragraph talks about an "HARD\_RESET Received confirmation". However this confirmation appears under the SL\_IR\_IRC1:Idle state in figure 67. Please move it to the SL\_IR\_IRC2:Wait state in the figure. Page: 160 Sequence number: 5 Date: 1/25/2003 11:26:08 AM Type: Highlight ACCEPT - DONE 7.9 Power management Replace the last sentence of the third paragraph with "If one of these primitives arrives while an STP connection is open, it may forward the primitive to the STP initiator port.". Page: 161 Sequence number: 1 Date: 12/30/2002 10:07:04 AM Type: Strikeout 7.11 Domain changes Assuming my previous comment regarding the title of subclause 7.8.2 is accepted, delete "specific" from the 5th paragraph. Page: 161 Sequence number: 2 Date: 12/30/2002 10:07:04 AM Type: Strikeout 7.11 Domain changes Assuming my previous comment regarding the title of subclause 7.8.3 is accepted, delete "specific" from the 6th paragraph. Page: 161 Sequence number: 3 Date: 12/30/2002 10:07:04 AM Type: Strikeout 7.11 Domain changes Assuming my previous comment regarding the title of subclause 7.8.4 is accepted, delete "specific" from the 7th paragraph. Page: 162 Sequence number: 2 Date: 12/30/2002 10:07:04 AM Type: Highlight 7.12.2.1 Connection request In the last paragraph, second sentence, replace "does not support" with "supports". Page: 163 Sequence number: 2 Date: 12/30/2002 10:07:04 AM Type: Highlight 7.12.2.2 Connection request responses Table 78 - Connection request responses In the description of AIP, the sentence beginning with "While the expander..." is not worded correctly. The number of expander devices (plural) does not match it (singular). Replace "it returns an AIP" with "they return AIPs".

Sequence number: 3 Date: 12/30/2002 10:07:04 AM Type: Note 7.12.2.2 Connection request responses Is there an order of precedence to the list future connection rates in the penultimate paragraph? Page: 163 Sequence number: 4 Date: 12/30/2002 10:07:04 AM Type: Note 7.12.2.2 Connection request responses Last paragraph. Shouldn't the list of reasons to transmit OPEN\_ACCEPT include that the INITIATOR bit is in an acceptable state as documented in 7.7.3? Page: 163 Sequence number: 5 Date: 1/25/2003 11:37:38 AM Type: Highlight ACCEPT - TODO (add definitions of deadlock and livelock to ch3) 7.12.3 Arbitration fairness Fourth paragraph, last word. The term "livelocks" should either be eliminated (it is only used here) or a definition should be included. Page: 163 Sequence number: 30 Date: 1/25/2003 11:28:41 AM Type: Note ACCEPT - DONE (made subsequent section at the same level) 7.12.3 Arbitration fairness page 163 Hanging paragraph. Page: 164 Sequence number: 1 Date: 12/30/2002 10:07:04 AM Type: Highlight 7.12.3 Arbitration fairness Paragraph 6. Do we also need to specify that the INITIATOR field is compatible with the role we were requesting? Page: 168 Sequence number: 1 Date: 12/30/2002 10:07:04 AM Type: Highlight 7.12.5 Abandoning a connection request The paragraph just below table 81 and above figure 69 breaks unnaturally across a page boundary, with the last two lines on the next page even though there is plenty of space on the previous page. Page: 174 Sequence number: 1 Date: 12/30/2002 10:07:04 AM Type: Note 7.13.2 SL transmitter and receiver The last two paragraphs of this subclause are nearly identical to the last two paragraphs in 7.8.6 and thus have the same issues identified there. These paragraphs need similar changes. Page: 174 Sequence number: 2 Date: 2/3/2003 3:34:34 PM Type: Highlight REJECT (this sentence deleted instead) 7.13.3.1 State description In the third paragraph, neither of the confirmations listed are shown in figure 72. Please add them to the figure. Page: 177 Sequence number: 1 Date: 2/3/2003 3:17:36 PM Type: Highlight ACCEPT - DONE (by is bye bye) 7.13.5.1 State description

Replace "by by" by "by" in the second paragraph.

Page: 177 Sequence number: 2 Date: 12/30/2002 10:07:04 AM Type: Highlight 7.13.5.2 Transition SL2:Selected to SL0:Idle Each of the 4 conditions has an English problem with the phrase ", then after". The problem can be corrected by replacing ", then" with " and" in four places. Page: 178 Sequence number: 1 Date: 1/24/2003 7:50:06 PM Type: Highlight ACCEPT - DONE 7.13.6.1 State description Add either "(see SATA)" or "(see 7.17.4)" at the end of the fourth paragraph. Page: 180 Sequence number: 1 Date: 12/30/2002 10:07:04 AM Type: Strikeout 7.14.1 Overview In the paragraph after the first list, delete "an after receiving". Page: 184 Sequence number: 1 Date: 12/30/2002 10:07:04 AM Type: Highlight 7.14.2.2 Transition XL0:Idle to XL1:Request Path Item b) references a Transmit Break indication, but the indication does not appear as an input to the XL0:Idle state in figure 74. Please add it. Page: 184 Sequence number: 2 Date: 12/30/2002 10:07:04 AM Type: Highlight 7.14.2.2 Transition XL0:Idle to XL1:Request\_Path Item a) references a Transmit Open indication, but the indication does not appear as an input to the XL0:Idle state in figure 74. Please add it. Page: 184 Sequence number: 3 Date: 12/30/2002 10:07:04 AM Type: Highlight 7.14.3.1 State description Should the second list include the INITIATOR bit? Page: 185 Sequence number: 1 Date: 12/30/2002 10:07:04 AM Type: Highlight 7.14.4.1 State description In the second paragraph, the Transmit Idle Dword parameter is referenced, but it does not appear for this state in figure 75. Please add it to the figure. Page: 185 Sequence number: 2 Date: 12/30/2002 10:07:04 AM Type: Highlight 7.14.4.1 State description In the third paragraph, the Transmit Open request is referenced, but it does not appear for this state in figure 75. Please add it to the figure. Page: 187 Sequence number: 1 Date: 12/30/2002 10:07:04 AM Type: Highlight 7.14.7.1 State description

In the first paragraph, the Transmit Open indication is referenced, but it does not appear in figure 75 for this state. Please add it to the figure.

Page: 188 Sequence number: 1 Date: 12/30/2002 10:07:04 AM Type: Highlight 7.14.8.2 Transition XL6:Open\_Response\_Wait to XL0:Idle The link (see 7.12.3) does not work. Page: 188 Sequence number: 2 Date: 12/30/2002 10:07:04 AM Type: Highlight 7.14.8.3 Transition XL6:Open\_Response\_Wait to XL2:Request\_Open The link (see 7.12.3) does not work. Page: 188 Sequence number: 3 Date: 1/14/2003 8:40:46 PM Type: Highlight TODO (this really needs to point to the DWS state machine) 7.14.9.1 State description In the fourth paragraph, replace "section 7.12.4" with "subclause 7.12.4." Also, make the link work. Page: 193 Sequence number: 1 Date: 12/30/2002 10:07:04 AM Type: Highlight 7.16.6 Preparing to close an SSP connection The last two sentences of the last paragraph are run together. Add a space. Page: 194 Sequence number: 1 Date: 12/30/2002 10:07:04 AM Type: Highlight 7.16.7.1 Overview In the paragraph beginning with "The SSP\_TF state machine's...", replace "it" with "is". Page: 194 Sequence number: 2 Date: 12/30/2002 10:07:04 AM Type: Highlight 7.16.7.1 Overview In the paragraph beginning with "The SSP\_RF state machine's...", replace "successful or unsuccessful received." with "successfully or unsuccessfully received.". Page: 195 Sequence number: 1 Date: 12/30/2002 10:07:04 AM Type: Highlight 7.16.7.1 Overview Figure 82 (and Global) The SSP\_TF3 state is split between two figures (not even consecutive figures). This is very confusing because there is no visual clue in the figure that the state is continued elsewhere. We should add some clue that it is continued somewhere else (perhaps the horizontal bar under the state name or the vertical bar should be dashed). Page: 202 Sequence number: 1 Date: 12/30/2002 10:07:04 AM Type: Highlight 7.16.7.11 SSP\_RIM1:Rcv\_Interlock\_Monitor state In the fourth paragraph, replace "Received Frames" with "Frame Received". Page: 204 Sequence number: 1 Date: 1/10/2003 11:25:15 AM Type: Highlight

ACCEPT - DONE 7.17.1 STP frame transmission Table 84 - SATA target port transmitting a frame It the title of the second column, replace "or STP" with "or to STP". Page: 204 Sequence number: 2 Date: 1/10/2003 11:26:16 AM Type: Highlight ACCEPT - DONE (throughout tables 84 and 85) 7.17.1 STP frame transmission Table 84 - SATA target port transmitting a frame Table 85 - STP initiator port transmitting a frame "<repeats>" needs a better definition. If it means that the SATA\_X\_RDY primitive repeats, then replace it with "<SATA\_X\_RDY repeats>". Page: 205 Sequence number: 1 Date: 12/30/2002 10:07:04 AM Type: Highlight 7.17.1 STP frame transmission Last paragraph, third sentence. Replace "...involved." with "...involved (except to repeat dwords)." Page: 207 Sequence number: 2 Date: 1/25/2003 11:48:23 AM Type: Highlight ACCEPT - DONE 7.17.3 Preparing to close an STP connection Second paragraph. Replace "SCSI domain" with SAS domain". Page: 211 Sequence number: 1 Date: 1/25/2003 11:57:03 AM Type: Highlight ACCEPT - DONE (data dwords) 7.18.4.3.1.1 State description Third paragraph. Replace "dword" with "dwords". Page: 211 Sequence number: 2 Date: 1/25/2003 11:56:36 AM Type: Highlight ACCEPT - DONE 7.18.4.3.1.2 Transition SMP TL1: Wait originate frame to SMP TL2: Wait transmit frame The first sentence of the first paragraph would be clearer if another "after" were included after the "and" as follows: "...after a valid SMP request frame is received and after sending ... " Page: 214 Sequence number: 1 Date: 12/30/2002 10:07:04 AM Type: Highlight 8.2.4 I\_T nexus loss timer In list item a), replace "counting and assigned an expired status;" with "counting and shall be assigned an expired status;" Page: 214 Sequence number: 2 Date: 12/30/2002 10:07:04 AM Type: Highlight 8.2.4 I\_T nexus loss timer In list item b), replace "and assigned" with "and shall be assigned". Page: 214 Sequence number: 3 Date: 12/30/2002 10:07:04 AM Type: Highlight 8.2.4 I\_T nexus loss timer

First paragraph, first sentence. Replace "is" with "shall be" or "may be", depending on whether this timer is mandatory or optional. Depending on this choice, the second sentence of this paragraph should start with "It shall be:" or "If implemented, it is:".

Page: 215 Sequence number: 1 Date: 12/30/2002 10:07:04 AM Type: Note 8.3.1 Overview In the second list (of states), add references to 8.3.2 for the PL\_OC1:Idle state and to 8.3.3 for the PL\_OC2:Overall\_Control state. Page: 215 Sequence number: 2 Date: 12/30/2002 10:07:04 AM Type: Highlight 8.3.1 Overview In the last paragraph, last sentence. How can the Overall\_Control state machine transition to the PL\_PM1:Idle state, which is in another state machine? Should this sentence read, "The state machine shall transition to the PL\_OC2:Overall\_Control state after receiving a Phy Enabled confirmation from any phy assigned to the port."? Page: 216 Sequence number: 2 Date: 12/30/2002 1:30:21 PM Type: Strikeout ACCEPT - DONE 8.3.2 8.3.2 PL\_OC1:Idle state Delete redundant subclause number. Page: 216 Sequence number: 3 Date: 12/30/2002 1:30:27 PM Type: Strikeout ACCEPT - DONE 8.3.2.1 8.3.2.1 State description Delete redundant subclause number. Page: 217 Sequence number: 1 Date: 12/30/2002 10:07:04 AM Type: Highlight 8.3.3.1.1 State description overview The example in the first line is an exhaustive list. Replace "e.g.," with "i.e.,". Page: 217 Sequence number: 2 Date: 12/30/2002 10:07:04 AM Type: Strikeout 8.3.2.2 8.3.2.2 Transition PL OC1:Idle to PC OC2:Overall Control Delete redundant subclause number. Page: 218 Sequence number: 1 Date: 12/30/2002 10:07:04 AM Type: Highlight 8.3.3.1.4 SSP wide port rules First paragraph. Add forward reference to COMMAND frames subclause after "COMMAND frames". That is, "(see 9.2.4.1)". Page: 218 Sequence number: 2 Date: 12/30/2002 10:07:04 AM Type: Highlight 8.3.3.1.4 SSP wide port rules Second paragraph. Add forward reference to TASK frame subclause after "TASK frame". That is, "(see 9.2.4.2)". Page: 218 Sequence number: 3 Date: 12/30/2002 10:07:04 AM Type: Highlight 8.3.3.1.4 SSP wide port rules Fifth paragraph. Add forward reference to DATA frame subclause after "DATA frame". That is, "(see 9.2.4.4)".

Page: 218 Sequence number: 4 Date: 12/30/2002 10:07:04 AM Type: Highlight 8.3.3.1.4 SSP wide port rules Sixth paragraph. Add forward reference to RESPONSE frame subclause after "RESPONSE frame". That is, "(see 9.2.4.5)". Page: 219 Sequence number: 1 Date: 12/30/2002 10:07:04 AM Type: Highlight 8.3.3.1.5 Filling in the Tx Frame arguments In list item a), shouldn't "should" be "shall"? Page: 221 Sequence number: 1 Date: 12/30/2002 10:07:04 AM Type: Highlight 8.3.3.1.6 Confirmations Global In the last paragraph of this subclause, replace "running" with "running,". Global: While English allows the last comma before an "and" or "or" to be omitted, it is less ambiguous to include the comma. This is especially true for lists within lists. This comment may apply elsewhere. Page: 221 Sequence number: 2 Date: 12/30/2002 10:07:04 AM Type: Note 8.4.1 Overview In the second list (of states), add references: a) PL\_PM1:Idle (see 8.4.2); b) PL\_PM2:ReqWait (see 8.4.3); c) PL\_PM3:Connected (see 8.4.4); and d) PL\_PM4:Wait\_For\_Close (see 8.4.5). Page: 224 Sequence number: 2 Date: 12/30/2002 10:07:04 AM Type: Highlight 8.4.3.1.2 PL\_PM I\_T nexus loss timer First paragraph. This paragraph deals with SSP ports. Why is item d), which is an STP confirmation, in the list? Page: 225 Sequence number: 1 Date: 12/30/2002 10:07:04 AM Type: Highlight 8.4.3.1.4 Open Failed handling In the first paragraph, fourth line, replace "Open Failure confirmation" with "Open Failed confirmation". Page: 225 Sequence number: 2 Date: 12/30/2002 10:07:04 AM Type: Highlight 8.4.3.1.4 Open Failed handling Table 87 - Retry Frame conditions In Table 87, is it obvious what is done if the I\_T nexus loss timer has expired and an Open Failed (Pathway Blocked) confirmation is received? If not, add a row to this table describing this case. Page: 226 Sequence number: 1 Date: 12/30/2002 10:07:04 AM Type: Highlight 8.4.4.1 State description The eighth paragraph refers to a DONE (ACK/NAK TIMEOUT) Received confirmation, which does not appear in figures 92 nor 93. Should the "DONE Transmitted" confirmation in figure 93 be "DONE Received"? If so, fix figure 93 and change the confirmation in this paragraph to be "DONE Received (ACK/NAK TIMEOUT) confirmation".

Sequence number: 2 Date: 12/30/2002 10:07:04 AM Type: Highlight 8.4.4.1 State description Ninth paragraph. This paragraph refers to a DONE Received confirmation going to the application layer and to a DONE Received confirmation coming from the link layer. Neither appears in figures 92 and 93. Page: 226 Sequence number: 3 Date: 12/30/2002 10:07:04 AM Type: Highlight 8.4.4.1 State description Tenth paragraph. The "Close Connection request" in the third sentence does not appear in figures 92 nor 93. Page: 226 Sequence number: 4 Date: 12/30/2002 10:07:04 AM Type: Highlight 8.4.4.1 State description Last paragraph. The "Close Connection request" in the second sentence does not appear in figures 92 nor 93. Page: 228 Sequence number: 2 Date: 12/30/2002 1:55:24 PM Type: Highlight ACCEPT - DONE (it's the retransmit bit) 9.2.1 SSP frame format Table 88 - SSP frame format Byte 10 includes a TIMEOUT bit that is not described. Page: 229 Sequence number: 1 Date: 12/30/2002 2:09:36 PM Type: Highlight ACCEPT - DONE (the TIMEOUT bit should have been RETRANSMIT) 9.2.1 SSP frame format The fourth paragraph below Table 89 refers to a RETRANSMIT bit, but this bit does not appear in Table 88. Where does it go? Page: 230 Sequence number: 1 Date: 1/6/2003 10:49:09 AM Type: Highlight ACCEPT - DONE 9.2.1 SSP frame format Penultimate paragraph. Find some way to prevent the 1 024 from wrapping from one line to the next line. Page: 233 Sequence number: 1 Date: 1/6/2003 11:08:27 AM Type: Highlight ACCEPT - DONE 9.2.2.3 XFER\_RDY information unit First paragraph under table 94. The reference to 10.1.1.1.5 is wrong and the link does not work. I think this reference should be to 10.1.6.1.5. Page: 233 Sequence number: 2 Date: 1/6/2003 11:08:16 AM Type: Highlight ACCEPT - DONE 9.2.2.3 XFER RDY information unit Last paragraph. The reference to 10.1.1.1.5 is wrong and the link does not work. I think this reference should be to 10.1.6.1.5. Page: 244 Sequence number: 1 Date: 2/8/2003 2:34:22 PM Type: Highlight ACCEPT - DONE (the UnOrderList0Reset paragraph tag was marked to "Keep with next" which is unnecessary) 9.2.6.2.1 Overview

The penultimate paragraph wraps unnaturally to the top of a new page when there is plenty of room for it on the previous page.

Page: 244 Sequence number: 2 Date: 2/8/2003 2:31:25 PM Type: Highlight ACCEPT - DONE (but then decided to remove it entirely) 9.2.6.2.1 Overview Figure 98 - SSP transport layer (ST) state machines - initiator device Replace "DONE (ACK/NAK TIMEOUT) Received" with "DONE Received (ACK/NAK TIMEOUT)". Page: 246 Sequence number: 1 Date: 2/9/2003 11:07:19 AM Type: Highlight REJECT (this is making sure the ACK went out for the XFER\_RDY) 9.2.6.2.2.1 State description In item e) describing the XFER\_RDY Arrived parameter, replace "ACK Transmitted" with "ACK Received". Page: 247 Sequence number: 1 Date: 2/9/2003 11:01:11 AM Type: Highlight REJECT (this is waiting to ensure the ACK is sent out for the XFER\_RDY before starting to send data frames) 9.2.6.2.2.3 Transition ST\_ISF1:Send\_Frame to ST\_ISF3:Prepare\_Send\_Data\_Out In item b) of the list, replace "ACK Transmitted" with "ACK Received". Page: 247 Sequence number: 2 Date: 12/30/2002 10:07:04 AM Type: Highlight 9.2.6.2.3.1 State description In the second paragraph, replace "the following received" with "the following fields received". Page: 247 Sequence number: 3 Date: 12/30/2002 10:07:04 AM Type: Highlight 9.2.6.2.3.1 State description In the third paragraph, replace "the following received" with "the following fields received". Page: 247 Sequence number: 4 Date: 12/30/2002 10:07:04 AM Type: Highlight 9.2.6.2.3.1 State description In the fourth paragraph, replace "the following" with "the following fields". Page: 247 Sequence number: 5 Date: 12/30/2002 10:07:04 AM Type: Highlight 9.2.6.2.4.1 State description In the first paragraph, replace "the following" with "the following fields". Page: 247 Sequence number: 6 Date: 12/30/2002 10:07:04 AM Type: Highlight 9.2.6.2.4.1 State description In the second paragraph, replace "the following" with "the following fields". Page: 248 Sequence number: 1 Date: 2/9/2003 10:53:41 AM Type: Highlight ACCEPT - DONE (removed this transition altogether) 9.2.6.2.5.2 Transition ST\_IRD1:Receive\_Data\_In to ST\_IRD2:Process\_Received\_Data\_In Don't we only want to make this transition after verifying that everything is correct with the received DATA frame? Page: 249 Sequence number: 1 Date: 12/30/2002 10:07:04 AM Type: Highlight 9.2.6.2.8 ST\_IFR1:Initiator\_Frame\_Router state First paragraph, item d). Replace "a hard reset occurs" with "a HARD\_RESET Received indication is received". Page: 250 Sequence number: 1 Date: 12/30/2002 10:07:04 AM Type: Highlight 9.2.6.2.8 ST\_IFR1:Initiator\_Frame\_Router state Third paragraph. Replace "Frame Received (Frame Failed) or a hard reset," with "Frame Received (Frame Failed) indication or a HARD\_RESET Received indication,". Page: 250 Sequence number: 2 Date: 2/8/2003 2:29:00 PM Type: Highlight ACCEPT - DONE (deleting entire paragraph. This was passing up DONE Received (ACK/NAK Timeout vs. normal) status so the application could decide when to reuse tags. Responses to other comments make that vendor-specific, so we can remove this confirmation.) 9.2.6.2.8 ST\_IFR1:Initiator\_Frame\_Router state Fourth paragraph. How shall this state "notify the application layer"? I presume it needs to send a some kind of confirmation to the application layer. Page: 250 Sequence number: 3 Date: 2/9/2003 10:31:21 AM Type: Highlight ACCEPT - DONE 9.2.6.2.8 ST\_IFR1:Initiator\_Frame\_Router state Item c) in the last list. Replace "Data-in parameter" with "Data-in Arrived parameter" Page: 252 Sequence number: 1 Date: 2/2/2003 3:58:49 PM Type: Highlight REJECT - hard reset is more than a signal 9.2.6.3.2 ST\_TFR1:Target\_Frame\_Router state First paragraph, item c). Replace "a hard reset occurs" with "a HARD\_RESET Received indication is received". Page: 252 Sequence number: 2 Date: 2/2/2003 3:58:36 PM Type: Highlight REJECT - hard reset is more than a signal 9.2.6.3.2 ST\_TFR1:Target\_Frame\_Router state Third paragraph. Replace "a hard reset" with "a HARD\_RESET Received indication". Page: 254 Sequence number: 1 Date: 2/9/2003 10:20:11 AM Type: Strikeout ACCEPT - DONE (magic is good) 9.2.6.3.4.1 State description Second paragraph. Minimally, delete "this state" as the Send Data-In transport protocol service request was not received by this state. However, this correction implies that the ST\_TTS2 state magically knows how the ST\_TTS1 state got started. It is probably better to say, "If this state was entered from the ST\_TTS1:Request\_Response\_Router state, ...' Page: 254 Sequence number: 2 Date: 2/9/2003 10:24:38 AM Type: Highlight TODO (it's waiting to make sure the previous incoming DATA frames all got ACKed. Should really be ACK or NAK transmitted?)

9.2.6.3.4.1 State description

Fifth paragraph. Replace "ACK Transmitted" with "ACK Received".

Page: 254 Sequence number: 3 Date: 2/9/2003 10:25:23 AM Type: Highlight ACCEPT - DONE 9.2.6.3.4.1 State description Seventh paragraph. It seems odd to say this state shall receive a Transmission Status confirmation from another state machine. Perhaps we should say "this state shall wait to receive". Page: 254 Sequence number: 4 Date: 2/9/2003 10:25:44 AM Type: Highlight ACCEPT - DONE 9.2.6.3.4.1 State description Tenth paragraph. Same problem with "this state shall receive". Page: 256 Sequence number: 1 Date: 1/30/2003 4:17:20 PM Type: Highlight ACCEPT - DONE 9.2.6.3.6.1 State description Second paragraph. Replace "ST\_TS1" with "ST\_TTS1". Page: 256 Sequence number: 2 Date: 1/30/2003 4:17:34 PM Type: Highlight ACCEPT - DONE 9.2.6.3.6.1 State description First paragraph, item a). Replace "ST\_TS1" with "ST\_TTS1". Page: 259 Sequence number: 3 Date: 12/30/2002 1:54:02 PM Type: Highlight ACCEPT - DONE 9.3.2 SATA tunneling for multiple STP initiator ports Second paragraph, item d). Replace "CLOSE CLEAR AFFILIATION)" with "CLOSE (CLEAR AFFILIATION)". Page: 264 Sequence number: 1 Date: 1/30/2003 5:35:59 PM Type: Highlight ACCEPT - DONE 9.4.4.2.3.2 Transition MT\_ID2:Send to MT\_ID1:Idle Replace "and sending" with "and after sending". Page: 264 Sequence number: 2 Date: 1/11/2003 5:22:49 PM Type: Highlight ACCEPT - DONE 9.4.4.3.1 Overview Replace "MT\_TD2:Send" with "MT\_TD2:Respond". Page: 269 Sequence number: 1 Date: 12/30/2002 5:41:02 PM Type: Highlight ACCEPT - DONE 10.1.1.5 Command Complete Received transport protocol service First paragraph. Replace "not" with "to". Page: 272

Page: 272 Sequence number: 1 Date: 1/30/2003 3:27:45 PM Type: Highlight ACCEPT - DONE 10.1.1.10 Send Task Management Request transport protocol service Replace the service request with the correct one: "Send Task Management Request (IN (Nexus, Function Identifier ) )" Page: 273 Sequence number: 1 Date: 12/30/2002 6:03:26 PM Type: Highlight ACCEPT - DONE 10.1.1.11 Task Management Request Received transport protocol service Replace the service indication with the correct one: "Task Management Request Received (IN (Nexus, Function Identifier ) )" Page: 274 Sequence number: 1 Date: 12/30/2002 6:04:06 PM Type: Highlight ACCEPT - DONE 10.1.1.12 Task Management Function Executed transport protocol service Replace the service response with the correct one: "Task Management Function Executed (IN (Nexus, Service Response))" Page: 274 Sequence number: 2 Date: 12/31/2002 9:30:05 AM Type: Highlight ACCEPT - DONE 10.1.1.13 Received Task Management Function-Executed transport protocol service Replace the service confirmation with the correct one: "Received Task Management Function Executed (IN (Nexus, Service Response ) )" Page: 276 Sequence number: 1 Date: 1/30/2003 2:03:21 PM Type: Highlight **REVIEW PROTOCOL WG** ACCEPT - DONE (non-breaking space placed before each "()". It's debatable whether the () are even needed.) 10.1.3 Application client error handling Third paragraph. The "()" should not be allowed to wrap onto a new line. Does Frame have an equivalent function to Word's non-breaking space? Page: 277 Sequence number: 1 Date: 2/8/2003 11:49:20 AM Type: Highlight ACCEPT - DONE 10.1.6.1.1 Disconnect-Reconnect mode page overview First paragraph. Replace "(e.g., as if the mode page is implemented and the field is set to zero)" with "(i.e., as if the field in the mode page is implemented and the field is set to zero)". Page: 287 Sequence number: 1 Date: 12/30/2002 5:28:32 PM Type: Note ACCEPT - DONE 10.1.8 SCSI power condition states To be consistent with the other subclauses in this standard, add forward references (with links) to the relevant subclauses in the second list (items a through g should point to 10.1.8.1 through 10.1.8.7). Page: 288 Sequence number: 1 Date: 12/30/2002 5:11:26 PM Type: Highlight ACCEPT - DONE 10.1.8 SCSI power condition states Figure 103 — SCSI application layer power condition (SA\_PC) state machine for SAS

This state machine looks different from the other state machines. Minimally add the gold box.

Page: 289 Sequence number: 1 Date: 1/30/2003 1:06:04 PM Type: Highlight REJECT (already ref SPC-3 in the state description text) 10.1.8.2.2 Transition SA\_PC\_1:Active to SA\_PC\_2:Idle Item c). Replace "Power Condition mode page idle timer expires" with "Power Condition mode page idle condition timer (see SPC-3) expires". Page: 289 Sequence number: 2 Date: 1/30/2003 1:05:57 PM Type: Highlight REJECT (already ref SPC-3 in the state description text) 10.1.8.2.3 Transition SA\_PC\_1:Active to SA\_PC\_3:Standby Item c). Replace "Power Condition mode page standby timer expires" with "Power Condition mode page standby condition timer (see SPC-3) expires". Page: 289 Sequence number: 3 Date: 1/30/2003 1:05:52 PM Type: Highlight REJECT (already ref SPC-3 in the state description text) 10.1.8.3.3 Transition SA\_PC\_2:Idle to SA\_PC\_3:Standby Item c). Replace "Power Condition mode page standby timer expires" with "Power Condition mode page standby condition timer (see SPC-3) expires". Page: 291 Sequence number: 1 Date: 1/30/2003 1:24:32 PM Type: Highlight REJECT - already referenced in the intro 10.1.8.6.3 Transition SA\_PC\_5:Active\_Wait to SA\_PC\_3:Standby Item c). Replace "Power Condition mode page standby timer expires" with "Power Condition mode page standby condition timer (see SPC-3) expires". Page: 291 Sequence number: 2 Date: 1/6/2003 9:52:19 AM Type: Highlight **REJECT** - already referenced in the intro 10.1.8.6.5 Transition SA PC 5: Active Wait to SA PC 6: Idle Wait Item c). Replace "Power Condition mode page idle timer expires" with "Power Condition mode page idle condition timer (see SPC-3) expires". Page: 291 Sequence number: 3 Date: 1/6/2003 9:52:59 AM Type: Highlight REJECT - already referenced in the intro 10.1.8.7.3 Transition SA\_PC\_6:Idle\_Wait to SA\_PC\_3:Standby Item c). Replace "Power Condition mode page standby timer expires" with "Power Condition mode page standby condition timer (see SPC-3) expires". Page: 299 Sequence number: 1 Date: 1/29/2003 3:30:12 PM Type: Highlight ACCEPT - DONE (Jan WG; removed all the function result text from each function and moved into 10.3.1.1 big table for all functions. In that table, PHY DOES NOT EXIST is used whenever appropriate.) 10.3.1.4 DISCOVER function Second paragraph below table 134. Why not use a FUNCTION RESULT of PHY DOES NOT EXIST, which we define in table 136? Page: 302

Sequence number: 3 Date: 2/8/2003 12:21:06 PM Type: Highlight

TODO (check wrapping at end of editing) 10.3.1.4 DISCOVER function The paragraph between tables 138 and 139 wraps onto the next page even though there is room on the previous page for the whole paragraph. Page: 311 Sequence number: 1 Date: 12/30/2002 11:36:48 AM Type: Highlight ACCEPT - DONE 10.3.1.8 CONFIGURE ROUTE INFORMATION function Second paragraph below table 150. The link to 9.4.4.2 is wrong and does not work. Page: 312 Sequence number: 1 Date: 1/6/2003 10:20:45 AM Type: Highlight ACCEPT - DONE (fixed the reference) **10.3.1.8 CONFIGURE ROUTE INFORMATION function** Third paragraph below table 150. Either find the subclause number for the see 4.x.x.x reference or delete it. Page: 312 Sequence number: 2 Date: 1/6/2003 10:20:14 AM Type: Highlight ACCEPT - DONE 10.3.1.8 CONFIGURE ROUTE INFORMATION function Paragraph between tables 151 and 152. The reference to table 149 should be to table 152. Page: 324 Sequence number: 1 Date: 12/30/2002 2:24:46 PM Type: Highlight ACCEPT - DONE B.1 SAS phy reset sequence examples In the first paragraph, replace "Figure A.1" with "Figure B.1". Page: 324 Sequence number: 2 Date: 12/30/2002 2:24:52 PM Type: Highlight ACCEPT - DONE B.1 SAS phy reset sequence examples In the first paragraph below figure B.1, replace "Figure A.2" with "Figure B.2". Page: 324 Sequence number: 3 Date: 1/8/2003 6:11:13 PM Type: Highlight ACCEPT - DONE (An ordered list works much better. Also tossed the "valid" and "invalid" wording.) B.1 SAS phy reset sequence examples First paragraph, last sentence. This sentence does not make sense. Consider replacing "...(invalid), that phy then selects..." with "...(invalid). Both phys then select...". Page: 325 Sequence number: 1 Date: 1/8/2003 6:11:27 PM Type: Highlight ACCEPT - DONE (An ordered list works much better. Also tossed the "valid" and "invalid" wording.) B.1 SAS phy reset sequence examples Paragraph above Figure B.2, last sentence. This sentence does not make sense. Consider replacing "...invalid), that phy then selects..." with "...invalid). Both phys then select...". Page: 377 Sequence number: 1 Date: 1/25/2003 5:13:55 PM Type: Highlight ACCEPT - DONE Annex I

Global

There are several places where C comments wrap to the next line. This code will not compile correctly. We need to correct these wrapping comments.

Page: 382 Sequence number: 2 Date: 2/3/2003 2:55:59 PM Type: Note ACCEPT - DONE (tracking with another comment) Annex J SAS logo Figure J.1 — SAS logo We should change this logo to match the one selected by the SCSI Trade Association.

## Author: LSI Tim Hoglund

Page: 6 Sequence number: 17 Date: 2/6/2003 2:01:03 PM Type: Note ACCEPT - DONE (rewritten with "may contain") 3.1.35 edge expander device page 6 Definition suggests subtractive routing ports are required by edge expander - this is not the case. A simple expander may only support direct attachment. Page: 7 Sequence number: 16 Date: 1/11/2003 5:29:03 PM Type: Note ACCEPT - DONE 3.1.39 expander connection router page 7 typo: acronym (ER) should be (ECR) Page: 8 Sequence number: 16 Date: 2/7/2003 6:21:21 PM Type: Note ACCEPT - DONE (but not applying to definition of invalid dword, since K28.6 is purposely introducing an invalid dword.) Global There are many places which state that K28.5 and K28.3 are the only two control characters used by SAS. SATA\_ERROR has been defined using K28.6. Globally add K28.6 as a legal control character. Page: 30 Sequence number: 14 Date: 1/23/2003 4:49:51 PM Type: Note ACCEPT - DONE (deleted current list; replaced by sentence relating connections to SSP, STP, or SMP) 4.1.11 Connections page 30 abc list of connection types is incomplete - either remove or add all possible types, i.e SMP initiator port to expander SMP target port (or SMP through expander to another expander, etc) Page: 40 Sequence number: 2 Date: 2/9/2003 5:19:32 PM Type: Note REJECT (it is complete for all the signals coming from SP. There's on more from SL\_DWS. The rest are for XL to XL communication, which is not detailed in these tables.) 4.3.3.1 Table 10; page 40 Broadcast Event Notify (type) list incomplete (should be consistent with Table 25). Page: 49 Sequence number: 19 Date: 1/24/2003 9:48:04 AM Type: Note

ACCEPT - DONE 4.6.1 Expander device model overview page 49 a) C) SL\_IR primitive processor - typo: should be broadcast primitive processor (DONE) Page: 49 Sequence number: 21 Date: 2/4/2003 6:38:42 PM Type: Note 4.6.1 Expander device model overview page 49 also, c) an expander port available per phy - what does this mean? is this necessary? either clarify or remove. Page: 51 Sequence number: 4 Date: 1/24/2003 9:49:42 AM Type: Note ACCEPT - DONE 4.6.5 Broadcast primitive processor page 51 typo: replace SL\_IR with broadcast (twice). Page: 53 Sequence number: 11 Date: 1/24/2003 9:55:58 AM Type: Note ACCEPT - DONE 4.6.7 Figure 27 page 53 update diagram text: change Link Status to Phy Status change Send Open to Transmit Open change Send Close to Transmit Close change Send Break to Transmit Break change Send Dword to Transmit Dword Page: 114 Sequence number: 28 Date: 1/8/2003 9:34:19 AM Type: Note 6.8.3.3 SP10:SAS\_AwaitALIGN state page 114 Agree with editor's note regarding the closer coordination between SP and DWS state machines to detect ALIGNs and ALIGN1s. Prefer that more than a single ALIGN or ALIGN1 required to advance SP, i.e. use filtering provided by the DWS process. Page: 115 Sequence number: 19 Date: 1/8/2003 9:34:19 AM Type: Note 6.8.3.4 SP11:SAS\_AwaitALIGN1 state page 114 Same comment as for 6.8.3.3. Page: 140 Sequence number: 4 Date: 1/8/2003 1:07:27 PM Type: Note **REVIEW PROTOCOL WG** REJECT (the "or"ed ones can never happen simultaneously so placing a priority requirement on them is going too far.) 7.1.4.11 OPEN\_REJECT page 140 Priority list for expander devices transmitting OPEN\_REJECT is ambiguous. Clarify using the following priorities: 1) OPEN\_REJECT(BAD DESTINATION) 2) OPEN\_REJECT(NO DESTINATION) 3) OPEN\_REJECT(CONNECTION RATE NOT SUPPORTED) OPEN\_REJECT(STP RESOURCES BUSY) OPEN\_REJECT(PATHWAY BLOCKED)

Page: 163 Sequence number: 31 Date: 1/25/2003 11:29:20 AM Type: Note ACCEPT - DONE (shall wins) 7.12.3 Arbitration fairness pages 163-164 Resolve apparent inconsistency between Paragraph 2 which states expander port may include an arbitration wait timer and Paragraph 5 which states that expander ports shall include arbitration wait timers. Page: 165 Sequence number: 15 Date: 1/8/2003 9:34:19 AM Type: Note 7.12.3.1.3 Partial Pathway Timer page 165 Partial Pathway Timeout timers are maintained by each expander phy, not by the expander connection manager. Replace expander connection manager with expander phy. Page: 204 Sequence number: 6 Date: 1/8/2003 9:34:19 AM Type: Note 7.17.1 STP frame transmission page 204 Tables 84 and 85 should show where OPEN\_ACCEPT occurs relative to the frame transmission. Page: 205 Sequence number: 7 Date: 1/8/2003 9:34:19 AM Type: Note 7.17.2 STP flow control page 205 Text description correlates well with Figure 86 as far as getting into the HOLD condition but recommend including more text describing the process of releasing the HOLD condition. Page: 207 Sequence number: 11 Date: 1/21/2003 11:45:32 AM Type: Note REJECT (Brian Day's rewrite accepted instead) 7.17.3 Preparing to close an STP connection page 207 Remove Paragraph 2, starting with "In a SCSI domain." - it is misleading and provides no normative content. Recommend restricting when expander device may issue CLOSE to only include the first three cases listed (end of each frame, timeout waiting for another frame, after every n frames). Page: 259 Sequence number: 14 Date: 1/8/2003 1:05:37 PM Type: Note ACCEPT - DONE 9.3.1 Initial FIS typo: SMP REPORT SATA PORT should be SMP REPORT PHY SATA.

## Author: MSFT

Page: 259 Sequence number: 13 Date: 1/14/2003 7:13:51 PM Type: Note ACCEPT - TODO (Add text that this is intended only to lock down a target for the duration of a command or a sequence of commands, not forever. This prevents frame confusion. Bob S will prepare some text for this). REFER PROTOCOL WG 9.3.2 SATA tunneling for multiple initiator ports The affiliation mechanism creates a policy that encourages initiators to fight over resources. The policy that multiple initiators shouldn't be actively connecting to an STP target shouldn't be enforced by hardware. It should be a usage convention.

[key concern is resources coming and going as seen by an OS]

## Author: MXO Mark Evans

Page: i Sequence number: 1 Date: 12/30/2002 10:07:32 AM Type: Note Global Replace "Enable Disable SAS Link (Enable)" with "Enable Disable Link Layer (SAS Enable)". Page: i Sequence number: 2 Date: 12/30/2002 10:07:32 AM Type: Note Global Replace "Enable Disable SAS Link (Disable)" with "Enable Disable Link Layer (Disable)". Page: i Sequence number: 3 Date: 2/2/2003 12:34:40 PM Type: Note ACCEPT - DONE (changed where it is clear, e.g. SMP requests and SMP responses. Mode pages go both directions, so neither is more correct; changed to "contains" or "means" in several instances. Address frames come from any type of device; since "indicate" was predominent, left them alone.) Global Replace "indicate" and all of its forms by the correct form of "specify" when the value or action originates with the initiator. Page: x Sequence number: 1 Date: 1/7/2003 1:51:30 PM Type: Note ACCEPT - see IBM comment Table of contents, 4.3.3.4 Signals between link layer, port layer, and management application layer for all protocols Align the page number properly. Page: xvi Sequence number: 1 Date: 2/6/2003 11:43:04 AM Type: Note ACCEPT - DONE (track with IBM comment) Table of contents, 7.8.6.2.3.2 Transition SL\_IR\_RIF2:Receive\_Identify\_Frame to SL\_IR\_RIF3:Completed Align the page number properly. Page: xix Sequence number: 1 Date: 2/6/2003 11:43:08 AM Type: Note ACCEPT - DONE (track with IBM comment) Table of contents, 7.18.4.2.2.2 Transition SMP\_IL2:Indicate\_frame\_tx to SMP\_IL3:Rcv\_response\_frame Align the page number properly. Page: xx Sequence number: 1 Date: 2/6/2003 11:43:12 AM Type: Note ACCEPT - DONE (track with IBM comment) Table of contents, 9.2.6.2.2.2 Transition ST\_ISF1:Send\_Frame to ST\_ISF2:Prepare\_Command\_Request Align the page number properly. Page: xxi Sequence number: 1

Date: 2/6/2003 11:43:30 AM

Type: Note ACCEPT - DONE (track with IBM comment) Table of contents, 9.2.6.2.3.2 Transition ST\_ISF2:Prepare\_Command\_Request to ST\_ISF1:Send\_Frame Align the page number properly. Page: xxi Sequence number: 2 Date: 2/6/2003 11:43:26 AM Type: Note ACCEPT - DONE (track with IBM comment) Table of contents, 9.2.6.3.6.3 Transition ST\_TTS4:Receive Data Out to ST\_TTS5:Prepare XFER\_RDY Align the page number properly. Page: xxi Sequence number: 3 Date: 2/6/2003 11:43:18 AM Type: Note ACCEPT - DONE (track with IBM comment) Table of contents, 9.2.6.3.7.2 Transition ST\_TTS5:Prepare\_XFER\_RDY to ST\_TTS4:Receive\_Data\_Out Align the page number properly. Page: 6 Sequence number: 7 Date: 1/23/2003 2:42:37 PM Type: Highlight ACCEPT - DONE (definition from FC-MJSQ letter ballot.) 3.1.24 deterministic iitter Rewrite this definition to be something like: "Jitter from all sources for which the probability of a variation in interval occurring outside the specified bounds is zero. These sources include duty cycle distortion, data dependent jitter, sinusoidal dependent jitter, and jitter uncorrelated to the data." Page: 8 Sequence number: 7 Date: 2/7/2003 6:34:33 PM Type: Highlight TODO (Cris Simpson will think up some wording) 3.1.62 indication In this standard an indication is passed from a transport layer to an application layer only. Page: 9 Sequence number: 8 Date: 1/7/2003 2:43:04 PM Type: Highlight REJECT - expander state machines use it too 3.1.98 response In this standard a response is passed from an application layer to a transport layer only. Page: 11 Sequence number: 3 Date: 2/8/2003 10:23:28 AM Type: Note ACCEPT - DONE (with specific wording from the OPEN address frame field definition) Definitions, 3.1.x Add a definition for pathway blocked count something like the following, "Pathway blocked count (PBC): the number of times that a pathway has been blocked when attempting to open a connection." Page: 17 Sequence number: 4 Date: 1/7/2003 3:13:08 PM Type: Strikeout REJECT 3.5.2 Transitions, third paragraph Delete the word "fully". Page: 21 Sequence number: 3 Date: 1/23/2003 3:28:07 PM Type: Highlight ACCEPT - DONE

4.1.3 Ports (narrow ports and wide ports), NOTE 6 In the first sentence replace "primarily" with "e.g.," Page: 34 Sequence number: 1 Date: 1/7/2003 6:15:25 PM Type: Note ACCEPT - DONE 4.2.3 Hashed SAS address Add the following paragraph at the end of this clause: "Annex D contains information on SAS address hashing." Page: 39 Sequence number: 1 Date: 2/9/2003 5:15:35 PM Type: Note ACCEPT - TODO (not blindly replace, but merge in) 4.3.3 Signals between state machines Replace this clause with T10/03-023r0. Page: 49 Sequence number: 4 Date: 2/9/2003 12:19:17 PM Type: Highlight 4.5 I\_T nexus loss, first paragraph Change the first sentence from, "When a port receives OPEN\_REJECT (NO DESTINATION), OPEN\_REJECT (CONNECTION RATE NOT SUPPORTED), or an open connection timeout in response to a connection request, it shall retry the connection request until:" to something like, "When a port receives OPEN REJECT (NO DESTINATION), OPEN REJECT (CONNECTION RATE NOT SUPPORTED), or an open connection timeout in response to a connection request, it shall retry the connection request. After receiving an OPEN REJECT (NO DESTINATION) or after an open connection time out, the port shall use the same OPEN address frame to retry the connection. After receiving an OPEN\_REJECT (CONNECTION RATE NOT SUPPORTED), the port shall send a new OPEN address frame with the connection rate changed as described in 7.12.2.2. The connection request shall be retried until:" Page: 65 Sequence number: 1 Date: 1/31/2003 3:50:22 PM Type: Highlight ACCEPT - DONE (per SAS PHY WG Accept except use "(see SATA)" instead of "(for reference)" at the end of the sentence.) 5.1 SATA cables and connectors (informative), first paragraph Figure 31 doesn't really show the cables and connectors, so the first sentence should be changed to something like, "Figure 31 shows a schematic representation of the cables and connectors defined by SATA (for reference)." Page: 65 Sequence number: 2 Date: 1/31/2003 3:51:48 PM Type: Highlight ACCEPT - DONE (per SAS PHY WG Accept except use "analogous" for "equivalent" or "analogue".) 5.1 SATA cables and connectors (informative), first paragraph The second sentence implies too much of a similarity between SATA and SAS devices. Either delete this sentence or change it to something like, "A SATA host is an analogue to a SAS initiator device; a SATA device is an analogue to a SAS target device. Page: 66 Sequence number: 2 Date: 1/31/2003 3:53:00 PM Type: Highlight ACCEPT - DONE (per SAS PHY WG) 5.2 SAS cables and connectors As above, Figure 32 doesn't really show the cables and connectors, so the sentence should be changed to something like, "Figure 32 shows a schematic representation of the cables and connectors defined in this standard to support an external environment." Page: 71 Sequence number: 3 Date: 1/20/2003 4:28:33 PM Type: Highlight ACCEPT - DONE

5.6 READY LED pin, first paragraph Change "turn on" to "activate". Page: 71 Sequence number: 4 Date: 1/20/2003 4:50:46 PM Type: Highlight ACCEPT - DONE 5.6 READY LED pin, second paragraph In the second sentence change "when the READY LED signal is raised" to "when the READY LED signal is asserted." Page: 71 Sequence number: 5 Date: 1/20/2003 4:33:32 PM Type: Highlight REJECT (but per PHY WG deleted whole sentence) 5.6 READY LED pin, third paragraph Change the second sentence to: "The READY LED circuitry in the target device shall be ground tolerant since this pin may be connected by a system directly to power supply ground." Page: 71 Sequence number: 6 Date: 1/20/2003 4:39:00 PM Type: Highlight REJECT (but sentence deleted) 5.6 READY LED pin, fifth paragraph Change "turn on" to "activate". Page: 71 Sequence number: 7 Date: 1/20/2003 4:44:03 PM Type: Highlight ACCEPT - DONE 5.6 READY LED pin, bulleted list, item a) Change the second sentence to: "In this state the target device may be removed with no danger of mechanical or electrical damage;" Page: 71 Sequence number: 8 Date: 1/20/2003 4:46:00 PM Type: Highlight ACCEPT - DONE (per SAS PHY WG, change to: When processing a command, the target device shall toggle the READY LED signal in a vendor-specified manner (e.g., the LED is usually on, but is momentarily off when commands are processed);) 5.6 READY LED pin, bulleted list, item c) The second sentence ("When processing a command, the target device shall negate READY LED for a period long enough to be detected by an observer (i.e., LED is usually on, but flashes off when commands are processed);" is vague in the extreme. At least add some "example" times. Page: 71 Sequence number: 9 Date: 1/20/2003 4:38:48 PM Type: Highlight **REJECT** (but sentence deleted) 5.6 READY LED pin, fifth paragraph Change "...may optionally be driven..." to "...may be driven..." Page: 71 Sequence number: 10 Date: 1/20/2003 4:46:59 PM Type: Highlight ACCEPT - DONE (per phy WG, change to: If the target device is formatting the media, it shall toggle the READY LED signal in a vendor-specific manner (e.g., with each cylinder change on a disk drive).) 5.6 READY LED pin, bulleted list, item d) The first sentence ("If the target device is formatting the media, it shall toggle READY LED between asserted and negated at significant intervals during the format operation (e.g., with each cylinder change on a disk drive)." is also vague in the extreme. What is a "significant interval". At least add some "example" times. Page: 74

Date: 1/31/2003 4:58:09 PM Type: Highlight ACCEPT - DONE (per phy WG) 5.7.3.1 Eye masks overview, first paragraph In the last sentence change "sigma" to "standard deviations". Page: 77 Sequence number: 2 Date: 1/31/2003 2:45:33 PM Type: Highlight ACCEPT - DONE SAS PHY WG 5.7.4 page 77 Table 35 Change Note c: ... unpowered or during idle time of an OOB signal. 5.7.4 Transmitted signal characteristics, Table 35 - Transmitted signal characteristics at Tx compliance points In note c) change "...logically turned off..." to "...not being driven...' Page: 82 Sequence number: 1 Date: 1/20/2003 5:32:21 PM Type: Highlight ACCEPT - DONE (changed satisfies to is given by) 5.7.11 Transmitter characteristics, fourth paragraph In the last sentence replace "...satisfies the following equation." with "...shall satisfy the following equation." Page: 82 Sequence number: 2 Date: 2/9/2003 11:24:55 AM Type: Highlight REFER PHY WG (wants to change <= to = and maybe change log(e) to log(10). Equation under debate.) 5.7.11 Transmitter characteristics Replace the equation after the fourth paragraph with: | S21 | = -{20 log10 (e)} {[6,5 x 10^-6 (f^0,5)] + [2,0 x 10^-10 (f)] + [3,3 x 10^-20 (f^2)]} dB Page: 82 Sequence number: 3 Date: 1/20/2003 5:37:05 PM Type: Note ACCEPT - DONE (per phy WG, Add text at the end of the last sentence in the paragraph so that the sentence reads: "A compliance interconnect is any physical interconnect with equal or greater loss at frequencies from 150 MHz to 3,0 GHz and that also meets the ISI loss requirements shown in figures 42 and 43.") 5.7.11 Transmitter characteristics, fifth paragraph Add text at the end of the last sentence in the paragraph so that the sentence reads: "A compliance interconnect is any physical interconnect with equal or greater loss at all frequencies than that required by the TCTF and that also meets the ISI loss requirements shown in figures 42 and 43." Page: 82 Sequence number: 4 Date: 1/31/2003 5:05:29 PM Type: Highlight ACCEPT - DONE (per phy WG Delete "an" to resolve MXO comment) 5.7.10 Electrical TxRx connections, first paragraph Change "media" to "medium" (AN electrically conductive MEDIUM). Page: 86 Sequence number: 2 Date: 2/5/2003 10:07:20 AM Type: Highlight ACCEPT - DONE 6.2 Encoding (8b10b), 6.2.1 Encoding overview, first paragraph In the first sentence, change "10 bit" to "10-bit". There are four additional occurrences of different values in this clause to change. There are no other occurrences of this in the draft. Page: 86

Sequence number: 3 Date: 2/5/2003 10:07:29 AM Type: Highlight

ACCEPT - DONE 6.2 Encoding (8b10b), 6.2.1 Encoding overview, second paragraph Change "four byte" to "four-byte". Page: 86 Sequence number: 4 Date: 2/6/2003 11:12:41 AM Type: Highlight ACCEPT - DONE 6.2 Encoding (8b10b), 6.2.1 Encoding overview, third paragraph after Table 40 - Special character usage Change "10 bit" to "10-bit". Page: 86 Sequence number: 5 Date: 2/6/2003 11:12:48 AM Type: Highlight ACCEPT - DONE 6.2 Encoding (8b10b), 6.2.1 Encoding overview, third paragraph after Table 40 - Special character usage Change "8 bit" to "8-bit". Page: 86 Sequence number: 6 Date: 2/6/2003 11:12:53 AM Type: Highlight ACCEPT - DONE 6.2 Encoding (8b10b), 6.2.1 Encoding overview, third paragraph after Table 40 - Special character usage Change "10 bit" to "10-bit". Page: 86 Sequence number: 7 Date: 2/5/2003 10:21:47 AM Type: Highlight ACCEPT - DONE (added definitions for disparity and running disparity from FC-FS. Changed several uses of "disparity" to "running disparity" throughout SAS to match the definitions.) 6.2 Encoding (8b10b), 6.2.1 Encoding overview, third paragraph The term "disparity" is introduced without definition. Either add definitions for the various forms of "disparity", or reference 6.3.3 Valid and invalid transmission characters. Page: 86 Sequence number: 8 Date: 2/6/2003 11:14:01 AM Type: Strikeout REJECT (it's a significant increase, why not communicate that) 6.2.2 8b10b coding introduction, second paragraph In the second sentence, delete the word "greatly". Page: 86 Sequence number: 9 Date: 2/6/2003 11:15:37 AM Type: Strikeout REJECT (any pattern is recognizable. The fact that a comma is all zeros makes it easy to detect with simpler logic.) 6.2.2 8b10b coding introduction, second paragraph In the third sentence, delete the word "easily". Page: 87 Sequence number: 1 Date: 1/24/2003 12:06:10 PM Type: Highlight ACCEPT - DONE (and following sentence too. D vs. K is always used in the Dxx.y format; I don't think this section applies to normal data references) 6.2.3 8b10b encoding notation conventions, fourth paragraph Delete the sentence, "The control variable is typically not specified." Item a) in the following bulleted list states what the values of the control variable are. Page: 97 Sequence number: 1 Date: 2/9/2003 5:37:01 PM Type: Note ACCEPT - TODO (check in last edit)

6.5 Out of band (OOB) signals, third paragraph after Table 48 - OOB signal receiver requirements Delete the page break in this paragraph.

Page: 100 Sequence number: 3 Date: 1/8/2003 3:01:31 PM Type: Highlight ACCEPT - DONE (enters the SATA speed negotiation sequence after COMWAKE) 6.6.3 SAS to SATA phy reset sequence, sixth paragraph In the last sentence delete the word "normal" or describe an abnormal SATA reset sequence. Page: 109 Sequence number: 2 Date: 1/9/2003 6:02:45 PM Type: Note ACCEPT - DONE 6.8.2 OOB sequence states, Figure 56 - SAS phy (SP) state machine - OOB sequence states Add a "Broadcast Event Notify" confirmation from SP1:OOB\_COMINIT (this has the argument Phy Not Ready). Page: 109 Sequence number: 3 Date: 1/10/2003 5:03:28 PM Type: Highlight **REVIEW PROTOCOL WG** ACCEPT - DONE (moved SP1 to SP0, SP2 to SP1, created new SP2 to serve as a return path which honors COMINIT but not COMSAS) 6.8.2 OOB sequence states, Figure 56 - SAS phy (SP) state machine - OOB sequence states The COMSAS detect timeout transition from SP7:OOB AwaitCOMSAS cannot go to SP2:OOB AwaitCOMX because this would cause another COMSAS to be transmitted. Add another state to which this transition goes where the timer resides. Then, after the timer expires, a hot-plug timeout would cause a transition to SP1:OOB COMINIT. Page: 110 Sequence number: 1 Date: 1/8/2003 6:47:17 PM Type: Highlight ACCEPT - DONE (global) 6.8.2.1 SP1:OOB\_COMINIT state, 6.8.2.1.1 State description Change "PhyNotReady" to "Phy Not Ready". Page: 110 Sequence number: 2 Date: 1/9/2003 6:02:33 PM Type: Note ACCEPT - DONE (as "In expander devices,... Notify (Phy Not Ready) ...") 6.8.2.1 SP1:OOB COMINIT state, 6.8.2.1.1 State description Add "This state shall send a Broadcast Event Notify confirmation to the expander function." Page: 112 Sequence number: 2 Date: 1/10/2003 5:13:12 PM Type: Highlight ACCEPT - DONE (changed to the new SP2 state) 6.8.2.7.5 Transition SP7:OOB\_AwaitCOMSAS to SAS\_AwaitNoCOMX Based on a previous comment, this transition should be deleted (also, there is no SAS\_AwaitNoCOMX state). Page: 115 Sequence number: 5 Date: 12/30/2002 10:07:32 AM Type: Highlight 6.8.3.4 SP11:SAS\_AwaitALIGN1 state, 6.8.3.4.1 State description, second paragraph Change "ALIGN0" to "ALIGN1". Page: 123 Sequence number: 4 Date: 1/24/2003 6:36:36 PM Type: Note ACCEPT - DONE 6.9.3 SP DWS1:Valid1 state There is a transition description missing. Add: "6.9.4.3 Transition SP\_DWS1:Valid1 to SP\_DWS0:AcquireSync, This transition

shall occur when an invalid dword is detected."

Page: 127 Sequence number: 1 Date: 1/6/2003 1:20:23 PM Type: Highlight **REJECT** - fine as is 7.1.1 Primitives overview, first paragraph Change the second sentence to: "Primitives are neither big-endian nor little-endian; they shall be interpreted as first, second, third, and last bytes. Page: 137 Sequence number: 4 Date: 12/30/2002 10:07:32 AM Type: Highlight 7.1.4.4 BROADCAST, second paragraph after Table 59 - BROADCAST primitives In the last sentence change "dropped" to "ignored". Page: 138 Sequence number: 4 Date: 1/8/2003 1:04:19 PM Type: Highlight **REFER EDITORS WG** 7.1.4.9 NOTIFY, first paragraph It could be problematic to send a NOTIFY during the phy reset sequence. Therefore, change the first sentence to: "A NOTIFY may be sent in place of an ALIGN during rate matching and clock skew management (i.e., a NOTIFY shall not be sent in place of an ALIGN during character and dword alignment during the phy reset sequence." Page: 139 Sequence number: 1 Date: 12/30/2002 10:07:32 AM Type: Note 7.1.4.11 OPEN\_REJECT, Table 61 - OPEN\_REJECT abandon primitives, description for OPEN\_REJECT (CONNECTION RATE NOT SUPPORTED) Add a parenthetical something like the following to the last sentence, "(the connection shall be retried as described in 4.5)." Page: 139 Sequence number: 2 Date: 1/17/2003 12:12:28 PM Type: Highlight ACCEPT - TODO ("would have to be routed") 7.1.4.11 OPEN\_REJECT, Table 61 - OPEN\_REJECT abandon primitives In the description of OPEN\_REJECT (BAD DESTINATION) change "needs to be routed" to "is to be routed". Page: 142 Sequence number: 4 Date: 12/30/2002 11:23:57 AM Type: Highlight ACCEPT - DONE 7.1.5.6 RRDY (Receiver ready), Table 65 - RRDY primitives Delete RRDY (RESERVED 2) as there is no such primitive. Page: 144 Sequence number: 2 Date: 1/16/2003 7:07:27 PM Type: Highlight REJECT - TODO (this is correct as written, but the transmit rule needs to say that's for transmitting to SATA only. Add "The ALIGNs received by the expander device containing the STP/SATA bridge may not arrive in pairs" to start the note. Pull the the last sentence out of the note into the paragraph above. 7.2 Clock skew management, note 19 Delete this note. An expander device may delete all ALIGNs only so long as the rules described in Table 66 are met. Page: 145 Sequence number: 1 Date: 1/8/2003 1:18:56 PM Type: Strikeout ACCEPT - DONE 7.4.2 CRC generation, NOTE 21 Delete the word "simply".

Page: 147 Sequence number: 5 Date: 1/6/2003 2:01:15 PM Type: Strikeout ACCEPT - DONE 7.4.3 CRC checking Delete the last paragraph ("Annex B contains examples of CRC generation/checker implementations.") as this is already stated in the Overview clause (see 7.4.1). Page: 151 Sequence number: 2 Date: 12/30/2002 3:48:20 PM Type: Highlight ACCEPT - DONE 7.7.2 IDENTIFY address frame Reorder the paragraphs below Table 73 - Device types such that the descriptions of the fields are in the common-practice order of their appearance in the table (i.e., top to bottom and left to right). Page: 151 Sequence number: 3 Date: 12/30/2002 3:48:04 PM Type: Note ACCEPT - DONE 7.7.2 IDENTIFY address frame Add the following paragraph after Table 73 - Device types: "The ADDRESS FRAME TYPE field shall be set to 0h." Page: 152 Sequence number: 2 Date: 12/30/2002 3:48:38 PM Type: Note ACCEPT - DONE 7.7.3 OPEN address frame Reorder the paragraphs below Table 74 - OPEN address frame format such that the descriptions of the fields are in the common-practice order of their appearance in the table (i.e., top to bottom and left to right). Page: 155 Sequence number: 4 Date: 12/30/2002 10:07:32 AM Type: Highlight 7.8.2 Initiator device specific rules, second paragraph Reword this to: "When a discover process is performed after a link reset sequence, the application client may discover all of the devices in the SAS domain. When a discover process is performed after a BROADCAST (CHANGE), the application client may determine what has changed in the SAS domain." Page: 155 Sequence number: 5 Date: 12/30/2002 10:07:32 AM Type: Highlight 7.8.2 Initiator device specific rules, fourth paragraph Reword this to: "If during the discover process (see 4.6.11.5) the application client detects two ports with the same SAS address, it has found a routing loop. To break the loop the application client shall use the CONFIGURE ROUTE INFORMATION function (see 10.3.1.8) to disable the expander port through which the duplicate SAS address was detected." Page: 156 Sequence number: 1 Date: 1/24/2003 7:43:08 PM Type: Highlight **REVIEW PROTOCOL WG** REJECT (this state machine is not used for SATA; SATA spec covers that mode) 7.8.5 Identification and hard reset (SL\_IR) state machines, 7.8.5.1 Overview, Figure 67 - SAS link layer identification and hard reset (SL IR) state machines In the SL\_IR\_TIR1 state: delete "(SAS Enable)" as the argument for this confirmation may be either (SAS Enable) or (SATA Enable). Page: 156 Sequence number: 2

Date: 1/24/2003 7:43:03 PM Type: Highlight

**REVIEW PROTOCOL WG** REJECT (this state machine is not used for SATA; SATA spec covers that mode) 7.8.5 Identification and hard reset (SL\_IR) state machines, 7.8.5.1 Overview, Figure 67 - SAS link layer identification and hard reset (SL\_IR) state machines In the SL\_IR\_RIF1 state: delete "(SAS Enable)" as the argument for this confirmation may be either (SAS Enable) or (SATA Enable). Page: 156 Sequence number: 3 Date: 1/24/2003 7:43:13 PM Type: Highlight **REVIEW PROTOCOL WG** REJECT (this state machine is not used for SATA; SATA spec covers that mode) 7.8.5 Identification and hard reset (SL\_IR) state machines, 7.8.5.1 Overview, Figure 67 - SAS link layer identification and hard reset (SL\_IR) state machines In the SL\_IR\_IRC1 state: delete "(SAS Enable)" as the argument for this confirmation may be either (SAS Enable) or (SATA Enable). Page: 156 Sequence number: 4 Date: 12/30/2002 10:07:32 AM Type: Note 7.8.5 Identification and hard reset (SL\_IR) state machines, 7.8.5.1 Overview, Figure 67 - SAS link layer identification and hard reset (SL\_IR) state machines In the SL\_IR\_IRC2 state: Add a "HARD\_RESET Received" confirmation from this state to the upper layers. This is already partly in the text for this state, and another Maxtor comment to the text clarifies this. Page: 156 Sequence number: 5 Date: 12/30/2002 10:07:32 AM Type: Note 7.8.5 Identification and hard reset (SL\_IR) state machines, 7.8.5.1 Overview, Figure 67 - SAS link layer identification and hard reset (SL\_IR) state machines In the SL\_IR\_IRC2 state: add the "Identification Sequence Complete" confirmation to the management application layer. This is described in the corresponding text for this state. Page: 157 Sequence number: 3 Date: 12/30/2002 10:07:32 AM Type: Highlight 7.8.6 SL\_IR transmitter and receiver, third paragraph Reword this to: "The SL\_IR receiver shall ignore any primitives received inside an OPEN address frame (i.e., after an SOAF but before the subsequent EOAF) except SOAF and BREAK. If a receiver receives a second SOAF after receiving an SOAF but before receiving a subsequent EOAF, then the receiver shall ignore the dwords before the second SOAF (i.e., the receiver shall consider the second SOAF as the start of a new IDENTIFY address frame). If a receiver receives a BREAK after receiving an SOAF but before receiving a subsequent EOAF, then the receiver shall ignore the dwords before the BREAK (i.e., ignore the IDENTIFY address frame)." Page: 160 Sequence number: 6 Date: 12/30/2002 10:07:32 AM Type: Highlight 7.8.6.3.3 SL\_IR\_IRC2: Wait state, 7.8.6.3.3.1 State description, fourth paragraph Change "management application layer" to "port layer". Other Maxtor comments have the port layer sending this to the transport layer, then to the application layer. Page: 161 Sequence number: 4 Date: 1/22/2003 5:26:10 PM Type: Highlight ACCEPT - DONE (request THAT an expander device set) (but whole section deleted) 7.10 Near-end analog loopback test, second paragraph after Figure 68 - Test modes Change "...device set ... " to "...device to set ... ' Page: 161 Sequence number: 5 Date: 1/22/2003 5:26:27 PM Type: Highlight REJECT (whole section deleted)

7.10 Near-end analog loopback test, third paragraph after Figure 68 - Test modes Change "...the application client shall transmit a BREAK or CLOSE..." to "...the application client shall request that a BREAK or CLOSE be transmitted..."

Page: 162 Sequence number: 3 Date: 12/30/2002 10:07:32 AM Type: Highlight 7.12.2.1 Connection request, third paragraph Delete the clause "but they may do so" at the end of the third sentence. Page: 162 Sequence number: 4 Date: 12/30/2002 10:07:32 AM Type: Highlight 7.12.2.1 Connection request, second paragraph Change the last phrase in the second sentence from "...decides to abandon the connection request with BREAK." to "...abandons the connection request with BREAK." Page: 162 Sequence number: 5 Date: 12/30/2002 10:07:32 AM Type: Highlight 7.12.2.1 Connection request, fourth paragraph The second sentence is incorrect. Change it to: "If none of the intermediate physical links support the requested connection rate, the expander device shall return OPEN\_REJECT (CONNECTION RATE NOT SUPPORTED)." Page: 163 Sequence number: 6 Date: 12/30/2002 10:07:32 AM Type: Highlight 7.12.3 Arbitration fairness, second paragraph Change "arbitration wait timer" to "AWT timer." Page: 163 Sequence number: 7 Date: 12/30/2002 10:07:32 AM Type: Highlight 7.12.3 Arbitration fairness, second paragraph Change "arbitration wait timer" to "AWT timer." Page: 163 Sequence number: 8 Date: 12/30/2002 10:07:32 AM Type: Highlight 7.12.3 Arbitration fairness, third paragraph Change "arbitration wait timer" to "AWT timer." Page: 163 Sequence number: 9 Date: 12/30/2002 10:07:32 AM Type: Highlight 7.12.3 Arbitration fairness, third paragraph Change "arbitration wait timer" to "AWT timer." Page: 163 Sequence number: 10 Date: 12/30/2002 10:07:32 AM Type: Highlight 7.12.3 Arbitration fairness, fourth paragraph Change "arbitration wait timer" to "AWT timer." Page: 163 Sequence number: 11 Date: 12/30/2002 10:07:32 AM Type: Highlight 7.12.2.2 Connection request responses, third paragraph Change "...the target port shall set the connection rate for future requests..." to "...the source port shall set the connection rate for future requests ... "

Page: 164 Sequence number: 2 Date: 12/30/2002 10:07:32 AM Type: Highlight 7.12.3 Arbitration fairness, fifth paragraph Change "arbitration wait timer" to "AWT timer." Page: 167 Sequence number: 1 Date: 1/17/2003 6:22:20 PM Type: Highlight ACCEPT - TODO 7.12.5 Abandoning a connection request, Table 81 - Abandon connection request responses, second row Change the entry in the Response column to "Open response (see 7.12.2)". Change the entry in the Description column to "An open response arrived after the BREAK was sent. The originator shall ignore the response." Page: 167 Sequence number: 2 Date: 12/30/2002 10:07:32 AM Type: Highlight 7.12.4.3 Fanout expander devices There are too many "its" (and other wrongness) in this clause. Change it to be something like: "When a fanout expander device receives a connection request, the fanout expander shall determine if a pathway exists to the destination device by comparing the destination SAS address of the request to the SAS addresses of the devices to which the fanout expander's phys are attached. For all phys that are attached to edge expander devices, the fanout expander shall compare the destination SAS address to all of the enabled SAS addresses in the expander route table. [new paragraph] If the expander device discovers that there are one or more pathways to the device having the destination SAS address, then the expander device shall arbitrate for access and forward the connection request. [new paragraph] If the expander device does not discover a pathway to the device having the destination SAS address, then the expander device shall reply to the source of the connection request with OPEN REJECT (NO DESTINATION). If the destination phy is in the same expander port as the source phy, the expander device shall reply to the source with OPEN\_REJECT (BAD DESTINATION)." Page: 167 Sequence number: 3 Date: 12/30/2002 10:07:32 AM Type: Highlight 7.12.5 Abandoning a connection request, first paragraph after Table 81 - Abandon connection request responses Change the last phrase from "...not the target port." to "...not the destination port." Page: 174 Sequence number: 3 Date: 12/30/2002 10:07:32 AM Type: Highlight 7.13.2 SL transmitter and receiver, third paragraph Reword this paragraph to: "The SL receiver shall ignore any primitives received inside an OPEN address frame (i.e., after an SOAF but before the subsequent EOAF) except SOAF and BREAK. If a receiver receives a second SOAF after receiving an SOAF but before receiving a subsequent EOAF, then the receiver shall ignore the dwords before the second SOAF (i.e., the receiver shall consider the second SOAF as the start of a new IDENTIFY address frame). If a receiver receives a BREAK after receiving an SOAF but before receiving a subsequent EOAF, then the receiver shall ignore the dwords before the BREAK (i.e., ignore the IDENTIFY address frame)." Page: 176 Sequence number: 1 Date: 2/3/2003 3:36:09 PM Type: Highlight REJECT (trying to keep the protocols separate from source/vs destination) 7.13.4.4 Transition SL1:ArbSel to SL3:Connected, second paragraph Delete the comma in "(STP, Source Opened)". Page: 176 Sequence number: 2 Date: 2/3/2003 3:36:15 PM Type: Highlight

REJECT (trying to keep the protocols separate from source/vs destination) 7.13.4.4 Transition SL1:ArbSel to SL3:Connected, third paragraph

Delete the comma in "(SSP, Source Opened)".

Sequence number: 3 Date: 2/3/2003 3:36:19 PM Type: Highlight REJECT (trying to keep the protocols separate from source/vs destination) 7.13.4.4 Transition SL1:ArbSel to SL3:Connected, fourth paragraph Delete the comma in "(SMP, Source Opened)". Page: 177 Sequence number: 3 Date: 2/3/2003 3:36:26 PM Type: Highlight REJECT (trying to keep the protocols separate from source/vs destination) 7.13.5.3 Transition SL2:Selected to SL3:Connected, first bulleted list In item b): delete the comma in "(SSP, Destination Opened)". Page: 177 Sequence number: 4 Date: 2/3/2003 3:36:31 PM Type: Highlight REJECT (trying to keep the protocols separate from source/vs destination) 7.13.5.3 Transition SL2:Selected to SL3:Connected, second bulleted list In item b): delete the comma in "(SMP, Destination Opened)". Page: 177 Sequence number: 5 Date: 2/3/2003 3:36:35 PM Type: Highlight REJECT (trying to keep the protocols separate from source/vs destination) 7.13.5.3 Transition SL2:Selected to SL3:Connected, third bulleted list In item b): delete the comma in "(STP, Destination Opened)". Page: 190 Sequence number: 1 Date: 2/4/2003 6:23:40 PM Type: Highlight REJECT (paragraph being deleted per Brian Day comment) 7.15 Rate matching, first paragraph Change the first part of the first sentence from "Initiator ports shall use SMP to discover the negotiated physical link rate..." to "Initiator ports shall discover the negotiated physical link rate..." There are other methods besides SMP that an initiator may use, and targets are not required to support SMP. Page: 194 Sequence number: 3 Date: 12/30/2002 10:07:32 AM Type: Highlight 7.16.7 SSP link layer (SSP) state machines, 7.16.7.1 Overview, ninth paragraph Change the first sentence to: "The SSP RF state machine's function is to receive frames and to determine whether or not those frames were received successfully." Page: 199 Sequence number: 1 Date: 12/30/2002 10:07:32 AM Type: Highlight 7.16.7.4 SSP\_D1:DONE\_Wait state, 7.16.7.4.1 State description, last paragraph Change "DONE (ACK/NAK TIMEOUT) confirmation" to DONE Received (ACK/NAK TIMEOUT) confirmation". Page: 199 Sequence number: 2 Date: 12/30/2002 10:07:32 AM Type: Note 7.16.7.4 SSP\_D1:DONE\_Wait state, 7.16.7.4.1 State description, last paragraph Add an "i.e." in the last clause: "...other DONE Received confirmations (i.e., DONE Received (Close Connection) and DONE Received (Credit Timeout)) may be used by the application layer to decide when to reuse tags." Page: 199 Sequence number: 3 Date: 12/30/2002 10:07:32 AM Type: Highlight 7.16.7.5.2 Transition SSP\_TF1:Connected\_Idle to SSP\_TF2:Tx\_Wait, second paragraph

Change "Tx Frame (Balanced)" to "Tx Frame (Balance Required)".

Page: 199 Sequence number: 4 Date: 12/30/2002 10:07:32 AM Type: Highlight 7.16.7.5.2 Transition SSP\_TF1:Connected\_Idle to SSP\_TF2:Tx\_Wait, second paragraph Change "Tx Frame (Nonbalanced)" to "Tx Frame (Balance Not Required)". Page: 201 Sequence number: 1 Date: 12/30/2002 10:07:32 AM Type: Highlight 7.16.7.9 SSP\_RF1:Rcv\_Frame state, first bulleted list Change item c) from "Received Frame" to "Frame Received". Page: 210 Sequence number: 1 Date: 2/1/2003 4:36:38 PM Type: Note ACCEPT - TODO 7.18.4 SMP link layer (SMP) state machines, 7.18.4.1 Overview, Figure 89 - SMP link layer (SMP) state machines - target device Add a "Frame Transmitted" confirmation from the SMP\_TL2 state to the port layer. Page: 213 Sequence number: 1 Date: 12/30/2002 10:07:32 AM Type: Note 8 Port layer Replace this clause as described in T10/03-024r0. Page: 216 Sequence number: 4 Date: 12/30/2002 10:07:32 AM Type: Highlight 8.3 Port layer overall control (PL\_OC) state machine, 8.3.1 Overview, Figure 91 - Port layer overall control (PL\_OC) state machine In the PL\_OC2 state: delete the confirmation "Port Ready" as there is no text that describes what this is supposed to be. Page: 216 Sequence number: 5 Date: 12/30/2002 10:07:32 AM Type: Note 8.3 Port layer overall control (PL\_OC) state machine, 8.3.1 Overview, Figure 91 - Port layer overall control (PL\_OC) state machine In the PL\_OC2 state: add a Phy Enabled confirmation from the link layer to this state, as a second Phy Enabled may be received after transition from PL OC1 to PL OC2. Page: 216 Sequence number: 6 Date: 12/30/2002 10:07:32 AM Type: Note 8.3 Port layer overall control (PL\_OC) state machine, 8.3.1 Overview, Figure 91 - Port layer overall control (PL\_OC) state machine In the PL\_OC1 state: add a Enable Disable Link Layer (Enable) confirmation from the link layer to this state. This may also cause the transition to PL\_OC2. Page: 216 Sequence number: 7 Date: 12/30/2002 10:07:32 AM Type: Note 8.3 Port layer overall control (PL\_OC) state machine, 8.3.1 Overview, Figure 91 - Port layer overall control (PL\_OC) state machine In the PL\_OC2 state: add a Enable Disable Link Layer (Enable) confirmation from the link layer, as a second Phy Enabled may be received after transition from PL\_OC1 to PL\_OC2. Page: 216 Sequence number: 8 Date: 12/30/2002 10:07:32 AM Type: Note 8.3 Port layer overall control (PL\_OC) state machine, 8.3.1 Overview, Figure 91 - Port layer overall control (PL\_OC) state machine Add a Enable Disable Link Layer (Disable) confirmation from the link layer to this state machine (i.e., to all states in the state machine).

Page: 216 Sequence number: 9 Date: 12/30/2002 10:07:32 AM Type: Note 8.3 Port layer overall control (PL\_OC) state machine, 8.3.1 Overview, Figure 91 - Port layer overall control (PL\_OC) state machine Add a HARD\_RESET Received confirmation from the link layer to this state machine (i.e., to all states in the state machine). Page: 216 Sequence number: 10 Date: 12/30/2002 10:07:32 AM Type: Note 8.3 Port layer overall control (PL\_OC) state machine, 8.3.1 Overview, Figure 91 - Port layer overall control (PL\_OC) state machine In the PL\_OC1 state: add a HARD\_RESET Received confirmation going from this state to the transport layer. Page: 222 Sequence number: 1 Date: 12/30/2002 10:07:32 AM Type: Note 8.4 Port layer phy manager (PL\_PM) state machine, 8.4.1 Overview, Figure 92 - Port layer phy manager (PL\_PM) state machine (part 1) Add a Enable Disable Link Layer (Disable) confirmation from the link layer to this state machine (i.e., to all states in the state machine). Page: 222 Sequence number: 2 Date: 1/14/2003 12:15:34 PM Type: Note 8.4 Port layer phy manager (PL PM) state machine, 8.4.1 Overview, Figure 92 - Port layer phy manager (PL PM) state machine (part 1) Add a HARD RESET Received confirmation received by this state machine (i.e., to all states in the state machine) from the link layer. Page: 223 Sequence number: 1 Date: 12/30/2002 10:07:32 AM Type: Highlight 8.4 Port layer phy manager (PL\_PM) state machine, 8.4.1 Overview, Figure 93 - Port layer phy manager (PL\_PM) state machine (part 2) Delete the "Connection Failed" confirmation from this figure. Page: 223 Sequence number: 2 Date: 12/30/2002 10:07:32 AM Type: Highlight 8.4 Port layer phy manager (PL\_PM) state machine, 8.4.1 Overview, Figure 93 - Port layer phy manager (PL\_PM) state machine (part 2) The DONE Transmitted confirmation would be better shown in part 1 as it results in a Disable Tx Frames parameter being sent to the PL\_OC state machine. Page: 223 Sequence number: 3 Date: 12/30/2002 10:07:32 AM Type: Note 8.4 Port layer phy manager (PL\_PM) state machine, 8.4.1 Overview, Figure 93 - Port layer phy manager (PL\_PM) state machine (part 2) Add a DONE Received confirmation from the link layer to this state. Page: 228 Sequence number: 3 Date: 12/30/2002 1:55:08 PM Type: Highlight ACCEPT - DONE 9.2 SSP transport layer, 9.2.1 SSP frame format, Table 88 - SSP frame format Change "TIMEOUT" to "RETRANSMIT" as it is described in the text that follows the table. Page: 229

Sequence number: 2 Date: 1/22/2003 6:15:44 PM Type: Note ACCEPT - DONE (with "is" not "shall") 9.2.1 SSP frame format, fourth paragraph below Table 89 - FRAME TYPE field Change the first part of the sentence to: "The RETRANSMIT bit may be set to one for RESPONSE frames (see 9.2.4.5)..." The RETRANSMIT bit SHALL be set to one in RESPONSE frames under certain conditions (see 9.2.4.5)." Page: 229 Sequence number: 3 Date: 12/30/2002 2:09:01 PM Type: Strikeout ACCEPT - DONE (changed to "more easily") 9.2.1 SSP frame format, ninth paragraph below Table 89 - FRAME TYPE field In the first sentence delete "quickly". Page: 229 Sequence number: 4 Date: 1/22/2003 6:14:24 PM Type: Highlight ACCEPT - DONE (paragraph being rewritten) 9.2.1 SSP frame format, ninth paragraph below Table 89 - FRAME TYPE field In the fourth sentence change "Target ports that do not need this field... " to "Target ports that do not use this field... " Page: 230 Sequence number: 2 Date: 2/2/2003 11:18:49 AM Type: Note ACCEPT - DONE 9.2.1 SSP frame format Add the following paragraph as next to last in the clause: "Fill bytes shall be included so that the CRC field is aligned on a four byte boundary. The contents of the fill bytes are vendor-specific." Page: 230 Sequence number: 3 Date: 2/3/2003 1:47:46 PM Type: Highlight REJECT (what's wrong with + signs) ACCEPT - DONE (added "of"s) 9.2.1 SSP frame format, next-to-last paragraph Change the parenthetical to "(1 024 bytes of data plus a 24-bytes header plus a 4-byte CRC)." Page: 236 Sequence number: 1 Date: 1/6/2003 11:32:06 AM Type: Note REJECT - the fields are defined in the NO DATA and SENSE DATA sections 9.2.2.5.1 RESPONSE information unit overview Add a new last paragraph in this clause: "For description of the content of the STATUS field see SAM-3. For description of the content of the SENSE DATA field see SPC-3." Page: 243 Sequence number: 1 Date: 2/8/2003 2:34:31 PM Type: Note ACCEPT - DONE (the UnOrderList0Reset paragraph tag was marked to "Keep with next" which is unnecessary) 9.2.6.2 Initiator device state machines, 9.2.6.2.1 Overview After the paragraph describing the ST\_IFR state machine: there is a superfluous page break. Page: 244 Sequence number: 3 Date: 2/8/2003 2:21:47 PM Type: Note ACCEPT - DONE 9.2.6.2 Initiator device state machines, 9.2.6.2.1 Overview, Figure 98 - SSP transport layer (ST) state machines - initiator device In the ST\_ISF1 state: add an "ACK Transmitted" confirmation from the port layer. There is already text that describes this. Page: 244 Sequence number: 4 Date: 2/8/2003 2:23:21 PM Type: Highlight

ACCEPT - DONE

9.2.6.2 Initiator device state machines, 9.2.6.2.1 Overview, Figure 98 - SSP transport layer (ST) state machines - initiator device In the ST\_IFR1 state: delete the confirmation "DONE (ACK/NAK TIMEOUT) Received" as there are no words describing this, and there is already an (ACK/NAK TIMEOUT) argument for the Transmission Status confirmation. Page: 244 Sequence number: 5 Date: 12/30/2002 10:07:32 AM Type: Highlight 9.2.6.2 Initiator device state machines, 9.2.6.2.1 Overview, Figure 98 - SSP transport layer (ST) state machines - initiator device In the ST\_ISF1 state: delete the confirmation "Nexus Lost". If there is a Transmission Status with an argument other than (Frame Transmitted), this state sends a Delivery Failure (Service Delivery Subsystem Failure) parameter to the ST\_IPR state machine. This results in that state machine sending this information to the application layer. Page: 245 Sequence number: 1 Date: 12/30/2002 10:07:32 AM Type: Note 9.2.6.2.2 ST\_ISF1:Send\_Frame state, 9.2.6.2.2.1 State description, second bulleted list Add: I\_T nexus loss count. Page: 249 Sequence number: 2 Date: 12/30/2002 10:07:32 AM Type: Highlight 9.2.6.2.8 ST\_IFR1:Initiator\_Frame\_Router state, first bulleted list Change "a hard reset occurs" to "a HARD\_RESET Received confirmation is received." Other Maxtor proposals and comments supplement this change. Page: 250 Sequence number: 4 Date: 2/2/2003 3:59:47 PM Type: Highlight ACCEPT - DONE 9.2.6.2.8 ST\_IFR1:Initiator\_Frame\_Router state, fifth paragraph Change "ACK/NAK balanced)" to "(ACK/NAK Balanced)". Page: 250 Sequence number: 5 Date: 12/30/2002 10:07:32 AM Type: Highlight 9.2.6.2.8 ST\_IFR1:Initiator\_Frame\_Router state, fifth paragraph Change the first occurrence of "(ACK/NAK Not Balanced)" to "Received (ACK/NAK Unbalanced)". Page: 250 Sequence number: 6 Date: 12/30/2002 10:07:32 AM Type: Highlight 9.2.6.2.8 ST\_IFR1:Initiator\_Frame\_Router state, fifth paragraph Change the second occurrence of "(ACK/NAK Not Balanced)" to "Received (ACK/NAK Unbalanced)". Page: 250 Sequence number: 7 Date: 12/30/2002 10:07:32 AM Type: Highlight 9.2.6.2.8 ST\_IFR1:Initiator\_Frame\_Router state, third paragraph Change "hard reset" to "HARD\_RESET Received confirmation." Other Maxtor proposals and comments supplement this change. Page: 250 Sequence number: 8 Date: 2/9/2003 10:33:01 AM Type: Note REJECT (Those are part of transport protocol service requests. Added "requests" alongside "responses") 9.2.6.3 Target device state machines, 9.2.6.3.1 Overview, first bulleted list Item a) is missing from the list. Insert the following: "a) receives and processes data-in and data-out delivery service requests from the SCSI target application layer;"

Page: 251 Sequence number: 1 Date: 2/2/2003 3:45:16 PM Type: Note ACCEPT - DONE 9.2.6.3 Target device state machines, 9.2.6.3.1 Overview, Figure 99 - SSP transport layer (ST) state machines - target device In the ST\_TTS2 state: add an "ACK Transmitted" confirmation from the port layer. There is already text that describes this. Page: 251 Sequence number: 2 Date: 12/30/2002 10:07:32 AM Type: Highlight 9.2.6.3 Target device state machines, 9.2.6.3.1 Overview, Figure 99 - SSP transport laver (ST) state machines - target device In the ST\_TTS2 state, delete the "Nexus Lost" confirmation to the application layer. This information is sent to the application layer via the Data-In Delivered confirmation. Page: 252 Sequence number: 3 Date: 12/30/2002 10:07:32 AM Type: Highlight 9.2.6.3.2 ST\_TFR1:Target\_Frame\_Router state, fourth paragraph Change "(ACK/NAK Not Balanced)" to "Received (ACK/NAK Unbalanced)". Page: 252 Sequence number: 4 Date: 2/2/2003 3:30:34 PM Type: Highlight REJECT - hard reset is not just a signal from state machines 9.2.6.3.2 ST\_TFR1:Target\_Frame\_Router state, first bulleted list Change "a hard reset occurs" to "a HARD\_RESET Received confirmation is received." Other Maxtor proposals and comments supplement this change. Page: 252 Sequence number: 5 Date: 2/2/2003 3:58:10 PM Type: Highlight REJECT - hard reset is more than a signal 9.2.6.3.2 ST\_TFR1:Target\_Frame\_Router state, third paragraph Change "hard reset" to "HARD\_RESET Received confirmation." Other Maxtor proposals and comments supplement this change. Page: 254 Sequence number: 5 Date: 12/30/2002 10:07:32 AM Type: Highlight 9.2.6.3.4 ST\_TTS2:Send\_Frame state, 9.2.6.3.4.1 State description Delete the ninth paragraph ("If the confirmation is Transmission Status (Open Failed) and it includes an I\_T Nexus Lost argument, this state shall send a Nexus Lost confirmation to the application layer.") This information is sent to the application layer via the Data-In Delivered confirmation. Page: 260 Sequence number: 1 Date: 1/30/2003 5:02:44 PM Type: Highlight ACCEPT - DONE REJECT (but added "Fill bytes, if needed" row to the table so it's clear where they go) 9.4.2 SMP\_REQUEST frame, fourth paragraph after Table 102 - SMP\_REQUEST frame format Change to: "Fill bytes shall be included at the end of the data in the ADDITIONAL REQUEST BYTES field so that the CRC field is aligned on a four byte boundary. The contents of the fill bytes are vendor-specific.." Page: 260 Sequence number: 2 Date: 2/3/2003 1:48:00 PM Type: Highlight ACCEPT - DONE (added "of"s) 9.4.2 SMP\_REQUEST frame, third paragraph after Table 102 - SMP\_REQUEST frame format Change the parenthetical to "(1 024 bytes of data plus a 24-bytes header plus a 4-byte CRC)." Page: 260 Sequence number: 11 Date: 1/30/2003 4:35:43 PM

Type: Highlight ACCEPT - DONE 9.4.2 SMP\_REQUEST frame, second paragraph after Table 102 - SMP\_REQUEST frame format Change to: "The FUNCTION field specifies which function is being requested (see 10.3.1.1). Page: 260 Sequence number: 12 Date: 1/30/2003 5:22:07 PM Type: Highlight REFER PROTOCOL WG (mention this here or just in ch10 where function is defined?) 9.4.2 SMP\_REQUEST frame, second paragraph after Table 102 - SMP\_REQUEST frame format Add "If the value in the FUNCTION field is not supported, then the target port shall return a FUNCTION RESULT of SMP FUNCTION FAILED in the RESPONSE frame." Page: 260 Sequence number: 13 Date: 1/30/2003 4:41:35 PM Type: Highlight ACCEPT - DONE 9.4.2 SMP\_REQUEST frame, first paragraph after Table 102 - SMP\_REQUEST frame format Change to: "The SMP FRAME TYPE field shall be set to 40h specifying that this is an SMP\_REQUEST frame. Page: 260 Sequence number: 14 Date: 1/30/2003 5:12:34 PM Type: Highlight REFER PROTOCOL WG (not sure that is the correct response.) 9.4.2 SMP\_REQUEST frame, first paragraph after Table 102 - SMP\_REQUEST frame format Add " If the SMP FRAME TYPE field is not set to 40h, then the target port shall return a FUNCTION RESULT of SMP FUNCTION FAILED in the RESPONSE frame." Page: 261 Sequence number: 1 Date: 12/30/2002 4:02:19 PM Type: Note ACCEPT - DONE (but worded as being responded to) 9.4.3 SMP\_RESPONSE frame Add a new second paragraph after Table 103 - SMP\_RESPONSE frame format: "The FUNCTION field specifies which function is being requested (see 10.3.1.1)." Page: 261 Sequence number: 2 Date: 1/6/2003 1:14:31 PM Type: Highlight ACCEPT - DONE 9.4.3 SMP RESPONSE frame, second paragraph after Table 104 - Function results Change to: "Fill bytes shall be included at the end of the data in the ADDITIONAL REQUEST BYTES field so that the CRC field is aligned on a four byte boundary. The contents of the fill bytes are vendor-specific.." Page: 261 Sequence number: 3 Date: 2/3/2003 1:48:10 PM Type: Highlight ACCEPT - DONE (added "of"s) 9.4.3 SMP\_RESPONSE frame, first paragraph after Table 104 - Function results Change the parenthetical to "(1 024 bytes of data plus a 24-bytes header plus a 4-byte CRC)." Page: 278 Sequence number: 1 Date: 12/30/2002 4:05:50 PM Type: Highlight ACCEPT - DONE 10.1.6.1.1 Disconnect-Reconnect mode page overview, second paragraph after Table 119 - Disconnect-Reconnect mode page for SSP Change to: "The PAGE CODE (PS) field shall be set to 02h and the PAGE LENGTH field shall be set to 0Eh." Page: 280

Sequence number: 1 Date: 1/30/2003 1:38:20 PM Type: Note ACCEPT - DONE 10.1.6.2.2 Protocol-Specific Port mode page - short format Add a paragraph after Table 121 - Protocol-Specific Port Control mode page for SAS SSP - short format: "The PARAMETERS SAVEABLE (PS) bit is defined in SPC-3." Page: 280 Sequence number: 2 Date: 12/30/2002 4:08:32 PM Type: Note ACCEPT - DONE 10.1.6.2.2 Protocol-Specific Port mode page - short format Add a paragraph after the description of the SPF field after Table 121 - Protocol-Specific Port Control mode page for SAS SSP short format: "The PAGE CODE field shall be set to 19h." Page: 280 Sequence number: 3 Date: 1/30/2003 1:41:02 PM Type: Highlight ACCEPT - DONE (removed all the rejects in favor of a xref to 8.2.4 which lists them) 10.1.6.2.2 Protocol-Specific Port mode page - short format, second paragraph after Table 121 - Protocol-Specific Port Control mode page for SAS SSP - short format Delete OPEN\_REJECT (CONNECTION RATE NOT SUPPORTED). Other comments make it so that this is no longer a reason for I\_T nexus loss. Page: 281 Sequence number: 1 Date: 12/30/2002 4:09:13 PM Type: Note ACCEPT - DONE 10.1.6.2.3 Protocol-Specific Port mode page - Phy Control And Discover subpage Add a paragraph after Table 122 - Protocol-Specific Port Control mode page for SAS SSP - Phy Control And Discover subpage: "The PARAMETERS SAVEABLE (PS) bit is defined in SPC-3." Page: 281 Sequence number: 2 Date: 12/30/2002 4:11:49 PM Type: Note ACCEPT - DONE 10.1.6.2.3 Protocol-Specific Port mode page - Phy Control And Discover subpage Add a paragraph after the description of the SPF field after Table 122 - Protocol-Specific Port Control mode page for SAS SSP -Phy Control And Discover subpage: "The PAGE CODE field shall be set to 19h." Page: 287 Sequence number: 2 Date: 2/3/2003 2:15:49 PM Type: Note REJECT (deleted paragraphs. Replaced by shorter paragraph. Not supposed to be an a) b) list without a : introducing them anvwav.) 10.1.8 SCSI power condition states, first bulleted list Add a line feed before item a). Page: 287 Sequence number: 3 Date: 2/3/2003 2:15:30 PM Type: Highlight REJECT (deleted paragraph. Replaced by shorter paragraph.) 10.1.8 SCSI power condition states, first bulleted list Change the text in item a) to: "After power on, if the target device has not received a START STOP UNIT command with the START bit set to zero, the target device transitions to the active power state after receiving an ENABLE SPINUP. The target device transitions to the active state after power on without waiting for an action by the application client." Page: 287 Sequence number: 4 Date: 2/3/2003 2:15:23 PM Type: Highlight REJECT (deleted paragraph. Replaced by shorter paragraph.) 10.1.8 SCSI power condition states, first bulleted list Change the text in item b) to: "After power on, if the target device receives a START STOP UNIT command with the START bit set

to zero before receiving an ENABLE SPINUP, the target device shall wait to transition to the active power state until receiving a START STOP UNIT command with the START bit set to one and an ENABLE SPINUP. This delays the application client's request until the NOTIFY (ENABLE\_SPINUP) arrives."

Page: 289 Sequence number: 4 Date: 1/6/2003 9:48:55 AM Type: Highlight ACCEPT - DONE 10.1.8.2.2 Transition SA\_PC\_1:Active to SA\_PC\_2:Idle, and several other places in this clause "FORCE IDLE" is named "FORCE\_IDLE\_0" in the proposal to include this in SBC-2 (02-464). Page: 289 Sequence number: 5 Date: 1/6/2003 9:49:24 AM Type: Highlight ACCEPT - DONE 10.1.8.2.3 Transition SA\_PC\_1:Active to SA\_PC\_3:Standby, and several other places in this clause "FORCE STANDBY" is named "FORCE\_STANDBY\_0" in the proposal to include this in SBC-2 (02-464). Page: 289 Sequence number: 6 Date: 1/30/2003 1:04:52 PM Type: Highlight **REJECT** (leave details to SBC/SPC) 10.1.8.2.3 Transition SA\_PC\_1:Active to SA\_PC\_3:Standby, bulleted list Change item c) to: "the STANDBY bit is set to one in the Power Condition mode page, the standby condition timer is not disabled by a START STOP UNIT command, and the standby condition timer is zero." Page: 289 Sequence number: 7 Date: 12/30/2002 5:25:05 PM Type: Highlight REJECT - I'd rather keep the details of expiration in the SPC-3 model/bit descriptions 10.1.8.3.3 Transition SA\_PC\_2:Idle to SA\_PC\_3:Standby, bulleted list Change item c) to: "the STANDBY bit is set to one in the Power Condition mode page, the standby condition timer is not disabled by a START STOP UNIT command, and the standby condition timer is zero" Page: 290 Sequence number: 1 Date: 1/30/2003 1:07:58 PM Type: Note ACCEPT - DONE (per Jan CAP WG discussion) 10.1.8.4.3 Transition SA\_PC\_3:Standby to SA\_PC\_5:Active\_Wait, bulleted list Add an item to the list: "a START STOP UNIT command with the START bit set to one is received." Page: 290 Sequence number: 2 Date: 1/30/2003 1:07:20 PM Type: Note ACCEPT - DONE (per Jan CAP WG discussion) 10.1.8.5.2 Transition SA\_PC\_4:Stopped to SA\_PC\_3:Standby, bulleted list Add an item to the list: "a START STOP UNIT command with the POWER CONDITION field set to FORCE\_STANDBY\_0 is received." Page: 291 Sequence number: 4 Date: 1/30/2003 1:24:08 PM Type: Note ACCEPT - DONE (per Jan CAP WG discussion). 10.1.8.5.4 Transition SA\_PC\_4:Stopped to SA\_PC\_6:Idle\_Wait, bulleted list Add an item to the list: "a START STOP UNIT command with the POWER CONDITION field set to FORCE\_IDLE\_0 is received." Page: 291 Sequence number: 5 Date: 12/30/2002 5:19:26 PM Type: Highlight REJECT - the idle bit could be set to 1 yet the standby timer could still expire. It depends on what the timers are programmed to. I'd rather just say "the timer expires" here are let the bit definitions/model section in SPC-3 describe what that means.

10.1.8.6.3 Transition SA\_PC\_5:Active\_Wait to SA\_PC\_3:Standby, bulleted list Change item c) to: "the IDLE bit is set to zero in the Power Condition mode page, the STANDBY bit is set to one in the Power Condition mode page, the standby condition timer is not disabled by a START STOP UNIT command, and the standby condition timer is zero." Page: 291 Sequence number: 6 Date: 2/3/2003 9:25:32 AM Type: Note REJECT (Active to Standby doesn't do this. Covered by "timer expires") 10.1.8.6.3 Transition SA\_PC\_5:Active\_Wait to SA\_PC\_3:Standby, bulleted list Add item d) to the list: "the IDLE bit is set to zero in the Power Condition mode page, the STANDBY bit is set to one in the Power Condition mode page, the standby condition timer is zero, and a command completes." Page: 291 Sequence number: 7 Date: 1/30/2003 1:21:34 PM Type: Note REJECT - this is covered by "idle timer expires" 10.1.8.6.5 Transition SA\_PC\_5:Active\_Wait to SA\_PC\_6:Idle\_Wait, bulleted list Add item d) to the list: "the IDLE bit is set to one in the Power Condition mode page, the idle condition timer is not disabled by a START STOP UNIT command, and the idle condition timer is zero." Page: 291 Sequence number: 8 Date: 1/30/2003 1:22:25 PM Type: Highlight REJECT - this is covered by "the standby timer expires." The idle bit could be set to 1 yet the standby timer could still expir so this is incomplete. Let the bit definitions/model section in SPC-3 describe what that means. 10.1.8.7.3 Transition SA\_PC\_6:Idle\_Wait to SA\_PC\_3:Standby, bulleted list Change item c) to: " the IDLE bit is set to zero in the Power Condition mode page, the STANDBY bit is set to one in the Power Condition mode page, the standby condition timer is not disabled by a START STOP UNIT command, and the standby condition timer is zero." Page: 291 Sequence number: 9 Date: 2/3/2003 9:23:56 AM Type: Note REJECT (Idle to Standby doesn't do this.) 10.1.8.7.3 Transition SA\_PC\_6:Idle\_Wait to SA\_PC\_3:Standby, bulleted list Add item d) to the list: "the IDLE bit is set to zero in the Power Condition mode page, the STANDBY bit is set to one in the Power Condition mode page, the standby condition timer is zero, and a command completes." Page: 295 Sequence number: 1 Date: 12/30/2002 2:37:46 PM Type: Note ACCEPT - DONE 10.3.1.2 REPORT GENERAL function Add two paragraphs after Table 130 - REPORT GENERAL request: 1) "The SMP FRAME TYPE field shall be set to 40h (see 9.4.2)." and 2) "The FUNCTION field shall be set to 00h (see 9.4.2)." Page: 296 Sequence number: 4 Date: 12/30/2002 2:38:04 PM Type: Note ACCEPT - DONE 10.3.1.2 REPORT GENERAL function Add two paragraphs after Table 131 - REPORT GENERAL response: 1) "The SMP FRAME TYPE field shall be set to 41h." and 2) "The FUNCTION field shall be set to 00h." Page: 296 Sequence number: 5 Date: 12/30/2002 3:22:54 PM Type: Highlight

ACCEPT - DONE

10.3.1.2 REPORT GENERAL function, paragraph before Table 131 - REPORT GENERAL response Remove the indent from, remove the bulleted number from, and add a line feed after this sentence.

Page: 297 Sequence number: 1 Date: 12/30/2002 2:38:18 PM Type: Note ACCEPT - DONE 10.3.1.3 REPORT MANUFACTURER INFORMATION function Add two paragraphs after Table 132 - REPORT MANUFACTURER INFORMATION request 1) "The SMP FRAME TYPE field shall be set to 40h (see 9.4.2)." and 2) "The FUNCTION field shall be set to 01h (see 9.4.2)." Page: 297 Sequence number: 2 Date: 12/30/2002 3:30:21 PM Type: Highlight REJECT - only "edge routers" have to have tables. An edge device could have only direct routing ports and thus no table. 10.3.1.2 REPORT GENERAL function, fifth paragraph after Table 131 - REPORT GENERAL response Change the first part of the sentence from, "If an edge expander device supports an expander route table, then..." to "For an edge expander device," as an edge expander shall support this field. Page: 297 Sequence number: 3 Date: 12/30/2002 3:28:30 PM Type: Highlight ACCEPT - DONE 10.3.1.2 REPORT GENERAL function, sixth paragraph after Table 131 - REPORT GENERAL response Change the first part of the sentence from, "If a fanout expander device supports an expander route table, then..." to "For an fanout expander device," as a fanout expander shall support this field. Page: 298 Sequence number: 1 Date: 12/30/2002 3:32:41 PM Type: Note ACCEPT - DONE 10.3.1.3 REPORT MANUFACTURER INFORMATION function Add two paragraphs after Table 133 - REPORT MANUFACTURER INFORMATION response 1) "The SMP FRAME TYPE field shall be set to 41h." and 2) "The FUNCTION field shall be set to 01h." Page: 298 Sequence number: 2 Date: 12/30/2002 2:38:26 PM Type: Highlight ACCEPT - DONE **10.3.1.3 REPORT MANUFACTURER INFORMATION function** After Table 133 - REPORT MANUFACTURER INFORMATION response: delete the paragraph describing the ADDITIONAL LENGTH field, as there is no field of this name in table 133. Page: 299 Sequence number: 2 Date: 12/30/2002 2:38:35 PM Type: Note ACCEPT - DONE 10.3.1.4 DISCOVER function Add two paragraphs after Table 134 - DISCOVER request: 1) "The SMP FRAME TYPE field shall be set to 40h (see 9.4.2)." and 2) "The FUNCTION field shall be set to 10h (see 9.4.2)." Page: 300 Sequence number: 1 Date: 12/30/2002 2:38:43 PM Type: Note ACCEPT - DONE 10.3.1.4 DISCOVER function Add two paragraphs after Table 134 - DISCOVER response: 1) "The SMP FRAME TYPE field shall be set to 41h." and The FUNCTION field shall be set to 10h."

Page: 301 Sequence number: 1 Date: 12/30/2002 3:47:44 PM Type: Highlight ACCEPT - DONE (also rearranged OPEN and IDENTIFY address frame fields in ch7) 10.3.1.4 DISCOVER function, after Table 137 - Routing attributes Move the description of the ATTACHED DEVICE TYPE field to be before the description of the ROUTING ATTRIBUTE field so that they are in the common-practice order of their appearance in the table (i.e., top to bottom and left to right). Page: 301 Sequence number: 2 Date: 1/6/2003 9:56:45 AM Type: Highlight ACCEPT - DONE 10.3.1.4 Discover, paragraph after Table 138 - Attached device types The second sentence is unclear. Reword this to be something like: "The negotiated physical link rate may be less than the programmed minimum physical link rate or greater than the programmed maximum physical link rate if one of the programmed rates has been changed since the link reset sequence." Page: 302 Sequence number: 4 Date: 1/6/2003 10:04:57 AM Type: Highlight ACCEPT - DONE 10.3.1.4 DISCOVER function Part one: change the order of the following field descriptions so that they are in the common-practice order of their appearance in the table (i.e., top to bottom and left to right): PROGRAMMED MINIMUM PHYSICAL LINK RATE, HARDWARE MINIMUM PHYSICAL LINK RATE, PROGRAMMED MAXIMUM PHYSICAL LINK RATE, and HARDWARE MAXIMUM PHYSICAL LINK RATE. Page: 302 Sequence number: 5 Date: 1/6/2003 10:04:08 AM Type: Highlight **REJECT - duplicate comment** 10.3.1.4 Discover, paragraph after Table 138 - Attached device types Part two of the previous comment, and move this part of the sentence to be with the previous part. Page: 303 Sequence number: 1 Date: 1/6/2003 10:08:24 AM Type: Highlight ACCEPT - DONE 10.3.1.4 DISCOVER function Part two: change the order of the following field descriptions so that they are in the common-practice order of their appearance in the table (i.e., top to bottom and left to right): PROGRAMMED MINIMUM PHYSICAL LINK RATE, HARDWARE MINIMUM PHYSICAL LINK RATE, PROGRAMMED MAXIMUM PHYSICAL LINK RATE, and HARDWARE MAXIMUM PHYSICAL LINK RATE. Page: 303 Sequence number: 2 Date: 1/6/2003 10:07:56 AM Type: Note ACCEPT - DONE 10.3.1.5 REPORT PHY ERROR LOG function Add two paragraphs after Table 141 - REPORT PHY ERROR LOG request: 1) "The SMP FRAME TYPE field shall be set to 40h (see 9.4.2)." and 2) "The FUNCTION field shall be set to 11h (see 9.4.2)." Page: 303 Sequence number: 3 Date: 12/30/2002 2:39:03 PM Type: Note ACCEPT - DONE 10.3.1.5 REPORT PHY ERROR LOG function, first paragraph after Table 141 - REPORT PHY ERROR LOG request Add a sentence to the paragraph: "If the value is not within the range of zero to NUMBER OF PHYS (see 9.4.4.2), the target port shall return a FUNCTION RESULT of SMP FUNCTION FAILED in the response frame."

Page: 304 Sequence number: 1 Date: 12/30/2002 2:39:12 PM Type: Note ACCEPT - DONE 10.3.1.5 REPORT PHY ERROR LOG function Add two paragraphs after Table 142 - REPORT PHY ERROR LOG response: 1) "The SMP FRAME TYPE field shall be set to 41h." and 2) "The FUNCTION field shall be set to 11h." Page: 305 Sequence number: 1 Date: 12/30/2002 2:39:29 PM Type: Note ACCEPT - DONE 10.3.1.6 REPORT PHY SATA function Add two paragraphs after Table 144 - REPORT PHY SATA request: 1) "The SMP FRAME TYPE field shall be set to 40h (see 9.4.2)." and 2) "The FUNCTION field shall be set to 12h (see 9.4.2)." Page: 305 Sequence number: 2 Date: 1/6/2003 10:13:54 AM Type: Note ACCEPT - DONE 10.3.1.5 REPORT PHY ERROR LOG function Add the following paragraph after the paragraph describing the FUNCTION RESULT field: "The PHY IDENTIFIER field indicates the phy (see 4.2.6) for which physical configuration link information is being returned." Page: 305 Sequence number: 3 Date: 1/6/2003 10:12:30 AM Type: Highlight ACCEPT - DONE 10.3.1.5 REPORT PHY ERROR LOG function, the three paragraphs below Table 143 - Function results for REPORT PHY ERROR LOG Delete the parentheses around the phrase "outside of phy reset sequences". Page: 306 Sequence number: 1 Date: 12/30/2002 2:39:41 PM Type: Note ACCEPT - DONE 10.3.1.6 REPORT PHY SATA function Add two paragraphs after Table 145 - REPORT PHY SATA response: 1) "The SMP FRAME TYPE field shall be set to 41h." and 2) "The FUNCTION field shall be set to 12h." Page: 306 Sequence number: 2 Date: 1/6/2003 10:16:53 AM Type: Note ACCEPT - DONE 10.3.1.6 REPORT PHY SATA function, first paragraph after Table 144 - REPORT PHY SATA request Add a sentence to the paragraph: "If the value is not within the range of zero to NUMBER OF PHYS (see 9.4.4.2), the target port shall return a FUNCTION RESULT of SMP FUNCTION FAILED in the response frame." Page: 307 Sequence number: 1 Date: 1/6/2003 10:14:29 AM Type: Note ACCEPT - DONE 10.3.1.6 REPORT PHY SATA function Add the following paragraph after Table 146 - Function results for REPORT PHY SATA: "The PHY IDENTIFIER field indicates the phy (see 4.2.6) for which physical configuration link information is being returned." Page: 307 Sequence number: 2

Date: 1/6/2003 10:19:06 AM

Type: Strikeout ACCEPT - DONE 10.3.1.7 REPORT ROUTE INFORMATION function, first paragraph In the last sentence, delete "primarily". Page: 308 Sequence number: 1 Date: 12/30/2002 2:39:53 PM Type: Note ACCEPT - DONE 10.3.1.7 REPORT ROUTE INFORMATION function Add two paragraphs after Table 147 - REPORT ROUTE INFORMATION request: 1) "The SMP FRAME TYPE field shall be set to 40h (see 9.4.2)." and 2) "The FUNCTION field shall be set to 13h (see 9.4.2)." Page: 309 Sequence number: 1 Date: 12/30/2002 2:40:01 PM Type: Note ACCEPT - DONE 10.3.1.7 REPORT ROUTE INFORMATION function Add two paragraphs after Table 148 - REPORT ROUTE INFORMATION response: 1) "The SMP FRAME TYPE field shall be set to 41h." and 2) "The FUNCTION field shall be set to 13h." Page: 311 Sequence number: 2 Date: 12/30/2002 2:40:09 PM Type: Note ACCEPT - DONE 10.3.1.8 CONFIGURE ROUTE INFORMATION function Add two paragraphs after Table 150 - CONFIGURE ROUTE INFORMATION request: 1) "The SMP FRAME TYPE field shall be set to 40h (see 9.4.2)." and 2) "The FUNCTION field shall be set to 90h (see 9.4.2)." Page: 312 Sequence number: 3 Date: 12/30/2002 2:40:17 PM Type: Note ACCEPT - DONE 10.3.1.8 CONFIGURE ROUTE INFORMATION function Add two paragraphs after Table 151 - CONFIGURE ROUTE INFORMATION response: 1) "The SMP FRAME TYPE field shall be set to 41h." and 2) "The FUNCTION field shall be set to 90h." Page: 313 Sequence number: 1 Date: 12/30/2002 2:40:26 PM Type: Note ACCEPT - DONE 10.3.1.9 PHY CONTROL function Add two paragraphs after Table 153 - PHY CONTROL request: 1) "The SMP FRAME TYPE field shall be set to 40h (see 9.4.2)." and 2) "The FUNCTION field shall be set to 91h (see 9.4.2)." Page: 313 Sequence number: 2 Date: 1/6/2003 10:24:14 AM Type: Highlight ACCEPT - DONE 10.3.1.9 PHY CONTROL function After Table 153 - PHY CONTROL request: move the paragraph describing the CRC field to the end of the clause so that it is in the common-practice order of its appearance in the table (i.e., top to bottom and left to right). Page: 313 Sequence number: 3 Date: 1/6/2003 10:18:15 AM Type: Note ACCEPT - DONE

10.3.1.9 PHY CONTROL function, first paragraph after Table 153 - PHY CONTROL request Add a sentence to the paragraph: "If the value is not within the range of zero to NUMBER OF PHYS (see 9.4.4.2), the target port shall return a FUNCTION RESULT of SMP FUNCTION FAILED in the response frame."

Page: 315 Sequence number: 1 Date: 12/30/2002 2:32:23 PM Type: Note ACCEPT - DONE 10.3.1.9 PHY CONTROL function Add two paragraphs after Table 156 - PHY CONTROL response: 1) "The SMP FRAME TYPE field shall be set to 41h." and 2) "The FUNCTION field shall be set to 91h." Page: 317 Sequence number: 1 Date: 12/30/2002 2:26:13 PM Type: Highlight ACCEPT - DONE A.1 Compliant jitter test pattern (CJTPAT), first paragraph In the first sentence change "low-density pattern" to "low transition density pattern" in two places. Page: 317 Sequence number: 2 Date: 12/30/2002 2:40:49 PM Type: Highlight REFER PHY WG A.1 Compliant jitter test pattern (CJTPAT), paragraph below Table A.1- CJTPAT for RD+ Change this paragraph to be something like: "If the same 8b characters are used when there is negative running disparity (RD-) and when there is positive running disparity, the resulting 10b pattern generated for each disparity type is different. 8b characters used when there is RD- may not provide the critical phase shifts as the same characters used when there is RD+. To achieve the same phase shift effects with RD- as with RD+, a different 8b pattern is required to be used for each disparity type.' Page: 382 Sequence number: 3 Date: 2/3/2003 2:55:49 PM Type: Note ACCEPT - DONE (tracking with another comment) Annex J, Figure J.1 - SAS logo Replace the old logo with the new logo.

## Author: PostLB

Page: iv Sequence number: 2 Date: 2/3/2003 2:46:56 PM Type: Note ACCEPT - DONE change the 7-point blank text line to 10 points at the top of page iv (to match a common font size in the rest of the document) Page: x Sequence number: 4 Date: 1/7/2003 12:58:15 PM Type: Highlight ACCEPT - DONE Global Move top right header to the right margin (the text containing 21 November 2002) it's 0.2 inches too far to the left Page: 4 Sequence number: 3 Date: 2/6/2003 11:43:59 AM Type: Note REFER PROTOCOL WG 2.4 Other references Change some of the SATA references to ATA/ATAPI-7 Volume 3 now that T13 has started its SATA incorporation

Page: 7 Sequence number: 17 Date: 1/30/2003 5:51:48 PM Type: Highlight ACCEPT - DONE 3.1.58 I\_T\_L\_Q nexus replace this with "tagged task" to match SAM-3 definition. Better to relate to an object than a 64-bit number. Page: 7 Sequence number: 18 Date: 2/8/2003 11:40:57 AM Type: Note TODO Check (see x.y) vs . See x.y. usage for each definition. left off at initialization sequence Page: 7 Sequence number: 19 Date: 2/7/2003 6:45:16 PM Type: Strikeout ACCEPT - DONE 3.1.52 hard reset sequence remove this text, which is not in most other sequence definitions: following the SAS speed negotiation sequence Page: 8 Sequence number: 17 Date: 2/7/2003 5:57:07 PM Type: Highlight ACCEPT - DONE 3.1.78 nexus Change queue tag to tagged task to better match SAM-3's I\_T\_L\_Q definition (although this nexus definition differs from SAM-3's nexus definition) Page: 8 Sequence number: 18 Date: 2/7/2003 6:45:43 PM Type: Strikeout ACCEPT - DONE 3.1.59 identification sequence remove this text, which is not in most other sequence definitions: following the SAS speed negotiation sequence Page: 9 Sequence number: 23 Date: 2/7/2003 6:36:07 PM Type: Highlight REJECT (but replaced by definition referring to transceiver.) 3.1.84 phy SAS device object that interfaces..., or an expander device object (i.e., expander phy) that is part of the service delivery subsystem. Page: 9 Sequence number: 24 Date: 2/7/2003 6:33:50 PM Type: Note TODO (Cris Simpson will think up some wording) 3.1.96 request: A parameter passed from a higher layer state machine to a lower level state machine to initiate an action. indication: A parameter passed from a lower layer state machine to a higher level state machine derived from a request. An indication directly maps from a request. response: A parameter passed from a higher layer state machine to a lower level state machine in reply to an indication. confirmation: A parameter passed from a lower layer state machine to a higher level state machine in reply to a request. A response directly maps to a confirmation. Page: 9 Sequence number: 25 Date: 1/29/2003 12:24:47 PM Type: Highlight ACCEPT - DONE

3.1.91/92 programmed physical link rate Add cross references to the SMP function and the mode page Page: 11 Sequence number: 16 Date: 2/7/2003 6:47:36 PM Type: Strikeout ACCEPT - DONE 3.1.128 speed negotiation sequence Delete: Part of the phy reset sequence to match other sequence definitions Page: 12 Sequence number: 5 Date: 2/5/2003 10:12:06 AM Type: Note ACCEPT - DONE 3.2 Symbols and abbreviations Add CJTPAT Page: 13 Sequence number: 6 Date: 1/25/2003 4:41:07 PM Type: Highlight ACCEPT - DONE (PPT acronym later removed altogether) 3.2 Symbols and abbreviations PPT timer should be timeout Page: 13 Sequence number: 7 Date: 1/25/2003 4:40:54 PM Type: Highlight ACCEPT - DONE 3.2 Symbols and abbreviations PPT is only used about six times in this standard; remove the acronym Page: 13 Sequence number: 8 Date: 2/5/2003 10:10:48 AM Type: Note ACCEPT - DONE 3.2 Symbols and abbreviations Add Rx and Tx Page: 14 Sequence number: 3 Date: 1/24/2003 7:12:30 PM Type: Highlight ACCEPT - DONE 3.3.10 restricted Add "or for use in other data structures in this standard." Page: 14 Sequence number: 4 Date: 1/25/2003 4:30:51 PM Type: Highlight ACCEPT - DONE 3.4 Editorial conventions SCSI mode pages, SCSI log pages are mixed-case not uppercase Page: 14 Sequence number: 5 Date: 1/25/2003 4:31:20 PM Type: Note ACCEPT - DONE add mixed-case convention for parameters, requests, confirmations, responses, indications, and timers Page: 15 Sequence number: 4 Date: 12/30/2002 10:41:07 AM Type: Highlight ACCEPT - DONE 3.4 Editorial conventions Table 1 should be Table 2 Page: 18 Sequence number: 2 Date: 1/25/2003 11:20:15 AM Type: Highlight ACCEPT - DONE Mirroring an ENDL comment in the definitions section, Contains should be "This list contains" Page: 20 Sequence number: 7 Date: 1/23/2003 2:38:04 PM Type: Note ACCEPT - DONE (labeled as "SCSI device name") the SCSI device also has a SAS address (retrieve with VPD from a target...) Page: 20 Sequence number: 8 Date: 1/22/2003 10:52:01 AM Type: Highlight ACCEPT - DONE (1..\* for now) 0..\* should be 1..\* since SMP targets must be included. If Steve's proposal is accepted, this could be exactly one unless virtual phys are present Page: 20 Sequence number: 9 Date: 1/22/2003 10:54:59 AM Type: Note ACCEPT - DONE (make the SCSI boxes all higher than the SAS boxes so the inheritance arrows go in the bottom of the SCSI boxes. Page: 20 Sequence number: 10 Date: 1/22/2003 12:53:16 PM Type: Note ACCEPT - DONE Use the CIM color convention of green for aggregation lines and blue for inheritance lines Page: 20 Sequence number: 11 Date: 1/23/2003 2:38:40 PM Type: Note ACCEPT - DONE Change the SAS address in the SCSI port to "SCSI port identifier". Pure SCSI objects don't know anything about SAS attributes. Page: 21 Sequence number: 13 Date: 2/8/2003 11:12:36 AM Type: Note ACCEPT - DONE 4.1.2 Physical links and phys Add reference to the hardware/programmed minimum/maximum physical link rate fields, which specify or indicate the physical link rates. Page: 23 Sequence number: 9 Date: 1/23/2003 3:32:56 PM Type: Note ACCEPT - DONE 4.1.4 SAS devices Move the "In figures which contains ports but not phys" sentence into the SAS port section, not the SAS device section

Page: 31 Sequence number: 7 Date: 1/16/2003 5:26:21 PM Type: Note show the IDENTIFY addresses here Page: 34 Sequence number: 7 Date: 2/9/2003 4:25:01 PM Type: Highlight ACCEPT - DONE 4.2.3 Hashed SAS address to help optional addresses DSS comment in D.1 Page: 34 Sequence number: 8 Date: 1/23/2003 5:51:46 PM Type: Highlight ACCEPT - DONE 4.2.2 SAS address IEEE COMPANY IDENTIFIER small caps without 'field" Page: 34 Sequence number: 9 Date: 1/23/2003 5:59:01 PM Type: Note ACCEPT - DONE 4.2.4 Port names Note about lack of port names Don't mention login non-existence: only helpful to someone with iSCSI, SRP, or FC experience Page: 34 Sequence number: 10 Date: 2/9/2003 6:09:08 PM Type: Note ACCEPT - DONE 4.2.5 Port identifiers Add a reference to the VPD page, since target point identifiers can be retrieved. Page: 35 Sequence number: 4 Date: 2/9/2003 5:04:49 PM Type: Note ACCEPT - TODO 4.3.1 State machine overview the expander state machine stack is not described here The expander stack with an attached SATA device is also a bit different Page: 49 Sequence number: 20 Date: 1/25/2003 4:42:44 PM Type: Note ACCEPT - DONE Global: change all timers to "expire" There is inconsistent usage. Page: 49 Sequence number: 22 Date: 1/25/2003 4:43:07 PM Type: Note Global Figure out where to define expires as "goes to zero" also clarify count-up vs count-down timers Page: 49 Sequence number: 23 Date: 1/28/2003 12:32:34 PM Type: Highlight for SCSI initiator ports should be a "should" not a "shall"

(from Brian Day) Page: 50 Sequence number: 7 Date: 2/9/2003 6:09:08 PM Type: Highlight ACCEPT - DONE 4.6.1 Expander device model overview Figure 25 - Expander device model Change SAS expander to expander (several times in figure) Page: 56 Sequence number: 1 Date: 2/9/2003 6:09:08 PM Type: Highlight ACCEPT - DONE 4.6.10 Broadcast primitive processor interface In "sequence complete" capitalize S and C Page: 57 Sequence number: 4 Date: 1/29/2003 3:41:46 PM Type: Highlight ACCEPT - DONE 4.6.11.2 Expander device connection request routing ATTACHED SAS ADDRESS should be routed SAS address and it probably shouldn't be small caps (it's not exactly a field. It's a value in an internal data structure.) Page: 57 Sequence number: 5 Date: 1/29/2003 3:41:28 PM Type: Highlight ACCEPT - DONE 4.6.11.2 Expander device connection request routing attached SAS address should be routed SAS address Also change of to in Page: 58 Sequence number: 3 Date: 1/31/2003 3:45:48 PM Type: Note ACCEPT - DONE 4.6.11.3 Expander route table Figure 28 - expander route table example change <= to symbol in figure Page: 59 Sequence number: 6 Date: 2/8/2003 11:40:57 AM Type: Highlight ACCEPT - DONE 4.6.11.3 expander route table expander route table entry should be expander route entry several times in 4.6.xx.xx Page: 61 Sequence number: 5 Date: 1/24/2003 10:58:35 AM Type: Note ACCEPT - DONE 4.6.11.4 Expander route index order Table 26 - expander route table levels

Page: 62 Sequence number: 1 Date: 1/31/2003 3:45:48 PM Type: Note ACCEPT - DONE 4.6.11.4 Expander route index order figure 30 - Expander route index order change <= to symbol Page: 66 Sequence number: 5 Date: 1/31/2003 3:57:32 PM Type: Highlight ACCEPT - DONE SAS PHY WG 5.2 page 66 Replace "the connectors" with "a schematic representation of the cables and connectors" Page: 71 Sequence number: 22 Date: 1/20/2003 4:27:50 PM Type: Highlight ACCEPT - DONE SAS PHY WG 5.6 page 71 Change "may" to "shall", requiring all targets to provide READY LED. Page: 71 Sequence number: 23 Date: 1/20/2003 4:37:03 PM Type: Note ACCEPT - DONE SAS PHY WG 5.6 page 71 Change table 32 to the following (=< used for less than or equal to symbol): Driver state Test condition Requirement Negated (LED off) 0 =<V OH =<3,6 V -100 uA < I OH < 100 uA Asserted (LED on) I OL = 15 mA 0 =<V OL =<0,225 V Page: 71 Sequence number: 24 Date: 1/20/2003 4:39:23 PM Type: Note ACCEPT - DONE SAS PHY WG 5.6 page 71 Delete sentence after table 32 based on change of section name Page: 72 Sequence number: 11 Date: 2/9/2003 11:23:16 AM Type: Note ACCEPT - DONE (per Joint WG minutes in Jan: The group agreed to add the following: These signal specifications are consistent with using good quality cable assemblies constructed with shielded twinex cable with 24 gauge solid wire up to eight meters in length without using any form of equalization (e.g., transmitter pre-emphasis, receiver adaptive equalization, or passive cable equalization). George noted that the wire gauge has to be stated in ISO phrasing.) next to cable length text, mention that STP flow control assumes a 50 ns cable propagation delay (one-way). Cables that support STP shall not exceed that delay(unless the receiver has more buffers than specified by the equations). Page: 72 Sequence number: 12 Date: 1/20/2003 4:50:17 PM Type: Note ACCEPT - DONE SAS PHY WG 5.6 page 72

delete extra blank rows

Change "mechanical damage" to "mechanical or electrical damage".

Page: 74 Sequence number: 7 Date: 1/31/2003 4:54:18 PM Type: Highlight ACCEPT - DONE SAS PHY WG 5.7.2 General interface specification Table 34, Page 74 Change to: Unit interval (UI) (nominal) Page: 74 Sequence number: 8 Date: 1/31/2003 4:54:42 PM Type: Highlight ACCEPT - DONE SAS PHY WG 5.7.2 General interface specification Table 34, Page 74 Change to: Media impedance (nominal) Page: 76 Sequence number: 4 Date: 1/20/2003 5:11:24 PM Type: Highlight ACCEPT - DONE (per SAS PHY WG 5.7.3.3 page 76 ...table 36 and Z1tol and Z1op shall be defined from these slopes as follows: Page: 76 Sequence number: 5 Date: 2/1/2003 1:50:33 PM Type: Note ACCEPT - DONE 5.7.3.3 Jitter tolerance masks Format Z1tol equation using Equation editor Page: 76 Sequence number: 6 Date: 2/9/2003 3:04:20 PM Type: Highlight ACCEPT - DONE 5.7.4 Transmitted signal characteristics Change SAS expander to expander Page: 77 Sequence number: 8 Date: 1/31/2003 2:45:55 PM Type: Strikeout ACCEPT - DONE SAS PHY WG 7.5.4 page 77 Table 35 delete Condition a) to be included as note f in table 35 as follows: The maximum difference in the average differential voltage (D.C. offset) component between the burst times and the idle times of an OOB signal. Add line to table with Signal characteristic = OOB offset delta (with a reference to note f), Units = mV, and values for 1,5 and 3,0 Gbps of +/- 25.

Page: 77 Sequence number: 9 Date: 1/31/2003 2:45:42 PM Type: Strikeout

ACCEPT - DONE SAS PHY WG 7.5.4 page 77 Table 35 Condition b) and c) to be included as note g in table 35 as follows: The maximum difference in the average of the common mode voltage between the burst times and the idle times of an OOB signal. Add line to table with Signal characteristic = OOB Common mode delta (with a reference to note g), Units = mV, and value for 1,5 and 3,0 Gbps of +/- 50. Page: 77 Sequence number: 10 Date: 1/31/2003 2:45:47 PM Type: Strikeout ACCEPT - DONE SAS PHY WG 7.5.4 page 77 Characteristic requirements moved into table 35. Delete this text. Page: 79 Sequence number: 3 Date: 1/31/2003 3:32:40 PM Type: Note ACCEPT - DONE 5.7.6 Jitter Table 37 - Jitter compliance points The notes need to be referenced. a - general b - general c - total jitter columns d - total jitter columns e - deterministic and total columns f - total jitter columns Page: 79 Sequence number: 4 Date: 1/31/2003 3:45:21 PM Type: Note ACCEPT - DONE 5.7.7 Jitter tolerance Table 38 - Jitter tolerance compliance points Note a is not referenced but should be Page: 81 Sequence number: 6 Date: 2/1/2003 1:50:01 PM Type: Note ACCEPT - DONE 5.7.9 Impedance specifications Format C equation in footnote using Equation editor Page: 82 Sequence number: 12 Date: 2/1/2003 1:49:22 PM Type: Note ACCEPT - DONE 5.7.11 Transmitter characteristics Format S21 equation using Equation editor Page: 84 Sequence number: 1 Date: 1/31/2003 5:33:17 PM Type: Highlight ACCEPT - DONE 5.7.12 Receiver characteristics 10-12 remove space Page: 86 Sequence number: 11 Date: 2/6/2003 11:17:41 AM

Type: Highlight ACCEPT - DONE (only when a dash follows the 8, though) 6.2.2 8b10b coding introduction Change all the "eight-"s in this section to "8" since 10 is expressed as "10" (also see INTC comment in glossary) Page: 86 Sequence number: 12 Date: 2/6/2003 11:12:24 AM Type: Highlight ACCEPT - DONE 6.2.2 8b10b coding introduction an 10-bit should be a 10-bit Page: 86 Sequence number: 13 Date: 2/8/2003 11:40:57 AM Type: Note ACCEPT - DONE 6.2.1 Encoding overview Table 40 - Special character usage add K28.6 since ERROR uses it (to table and text) Page: 87 Sequence number: 2 Date: 1/11/2003 5:14:32 PM Type: Highlight ACCEPT - DONE 6.2.3 8b10b encoding conventions this specification should be this standard Page: 91 Sequence number: 1 Date: 2/7/2003 6:02:36 PM Type: Highlight ACCEPT - DONE 6.3.3.1 Valid and invalid transmission characters add K28.6 Page: 92 Sequence number: 2 Date: 1/24/2003 12:14:23 PM Type: Highlight ACCEPT - DONE Table 45 - delayed code violation example Change "character" labels to "first character" "second character" and "third character" Page: 97 Sequence number: 8 Date: 1/8/2003 2:04:14 PM Type: Highlight ACCEPT - DONE 6.5 OOB signals Table 48 OOB signal receiver requirements The number 1008 needs a space after the 1 to follow ISO format Page: 97 Sequence number: 10 Date: 1/8/2003 2:27:11 PM Type: Highlight ACCEPT - DONE 6.5 OOB signals Delete COMINIT Completed as it is not used Page: 97 Sequence number: 11 Date: 1/24/2003 12:46:48 PM Type: Note ACCEPT - DONE

Word this in terms of negation time, not "greater than proceeding idle time" They happen to match now, but that's not necessarily true. Page: 97 Sequence number: 12 Date: 1/24/2003 12:43:47 PM Type: Note ACCEPT - DONE (had to split into two tables to fit) idle time mays should be: >= 55 ns and < 175 ns >= 175 ns and < 525 ns (propose to SATA) >= 525 ns and < 1575 ns (propose to SATA) idle time shalls should be: >= 101,3 ns and <= 112 ns >= 304 ns and <= 336 ns >= 911,7 ns and <= 1008 ns negation time shall should be: > 175 ns > 525 ns > 1575 ns Page: 97 Sequence number: 13 Date: 1/24/2003 12:48:43 PM Type: Highlight ACCEPT - DONE 6.5 OOB signals After table 48 OOB signal receiver requirements "not an error to receive more than six" should be four, since this is the receiver section Page: 98

Sequence number: 5 Date: 2/9/2003 3:08:01 PM Type: Highlight ACCEPT - DONE 6.6.1 Overview Change Overview to Phy reset sequences overview Page: 100 Sequence number: 6 Date: 1/24/2003 2:47:51 PM Type: Highlight ACCEPT - DONE (removed sentence. The phy reset section overview says this now) 6.6.4.1 SAS OOB sequence Is hot-plug timeout a shall or a should? (see comment in timing table) Page: 101 Sequence number: 3 Date: 1/8/2003 5:35:44 PM Type: Highlight ACCEPT - DONE 6.6.4.1 SAS OOB sequence phys should be phy (two times) Page: 101

Sequence number: 4 Date: 1/24/2003 2:52:13 PM Type: Note ACCEPT - DONE add a description of replying to a COMSAS directly with COMSAS

Page: 102 Sequence number: 5 Date: 1/11/2003 5:13:03 PM Type: Highlight

ACCEPT - DONE (removed Scenario 3) 6.6.4.1 SAS OOB sequence Figure 51 - SAS to SAS OOB sequence Scenario 3: start should be starts Page: 104 Sequence number: 11 Date: 1/24/2003 3:06:49 PM Type: Note ACCEPT - DONE (removed receiver times altogether) Table 49 - SAS speed negotiation sequence timing specifications Some of these receiver times might not be used in the standard. Or it's not clearly differentiated when the transmit times apply and when the receive times apply. Page: 104 Sequence number: 12 Date: 1/24/2003 3:06:36 PM Type: Highlight ACCEPT - DONE 6.6.4.2 SAS speed neg sequence Table 49 - SAS speed neg Rate change delay should be "Rate change delay time (RCDT)" to match the other names Page: 104 Sequence number: 13 Date: 1/9/2003 3:46:16 PM Type: Highlight ACCEPT - DONE 6.6.4.2 SAS speed neg Table 49 - SAS speed neg Replace speed negotiation window time with a version in units of OOBI. Page: 106 Sequence number: 6 Date: 1/21/2003 4:10:41 PM Type: Highlight ACCEPT - DONE 6.6.4.2 SAS speed negotiation sequence Figure 54 - SAS speed negotiation Bx should be Rx Page: 106 Sequence number: 7 Date: 1/24/2003 4:03:16 PM Type: Highlight ACCEPT - DONE 6.6.5 Phy reset sequence after device is attached There is no such thing as a COMINIT sequence. Change to COMINIT signal. Global change for COMxxx sequence. Page: 107 Sequence number: 5 Date: 2/9/2003 5:41:00 PM Type: Highlight 6.6.5 Phy reset after device is attached ACCEPT - DONE (deleted the offending statement) "bypassing the normal requirement that COMINIT be both transmitted and received." with the changes earlier, this is not a violation of the "Normal"requirement anymore Page: 108 Sequence number: 6 Date: 1/8/2003 6:38:16 PM Type: Highlight ACCEPT - DONE 6.8 SP state machine Add a cross reference to the first reference to SP\_DWS state machine Page: 108 Sequence number: 7

Date: 2/9/2003 6:09:08 PM Type: Highlight ACCEPT - DONE 6.8.1 Overview Change Overview to SP state machine overview Page: 110 Sequence number: 14 Date: 2/9/2003 5:42:14 PM Type: Highlight ACCEPT - DONE 6.8.2.2.1 SP2:OOB\_AwaitCOMX state description initialized and enabled should be initialized and started Page: 111 Sequence number: 8 Date: 1/10/2003 5:11:59 PM Type: Highlight ACCEPT - DONE 6.8.2.6.1 State description (SP6) Reword "waits for COMSAS to be completely received." like the others Page: 115 Sequence number: 17 Date: 1/6/2003 9:29:43 AM Type: Highlight ACCEPT - DONE 6.8.3.5.2 Transition SP12:SAS\_AwaitALIGN1 to ... SP12:SAS\_AwaitALIGN1 should be SP12:SAS\_AwaitSNW (from muikien\_kirk@adaptec.com) Page: 115 Sequence number: 18 Date: 1/6/2003 9:29:49 AM Type: Highlight ACCEPT - DONE 6.8.3.4.3 Transition SP11:SAS\_AwaitALIGN1 to SAS\_AwaitSNW SP14:SAS\_ AwaitSNW should be SP12:SAS\_AwaitSNW (without the space and 14 changed to 12) (from muikien\_kirk@adaptec.com) Page: 118 Sequence number: 11 Date: 2/4/2003 6:57:13 PM Type: Note ACCEPT - DONE 6.8.4 SATA host emulation states Figure 58 - SP state machine SATA host emulation states The SP23:SATA\_PM\_Partial to to SP17:SATA\_AwaitCOMWAKE arc should go to SP16:SATA\_COMWAKE and The SP24:SATA\_PM\_Slumber to SP17:SATA\_AwaitCOMWAKE arc should go to SP16:SATA\_COMWAKE Page: 118 Sequence number: 12 Date: 2/9/2003 3:05:20 PM Type: Highlight ACCEPT - DONE 6.8.4 SATA host emulation states Change SAS expander to expander Page: 120 Sequence number: 21

Date: 1/11/2003 5:13:03 PM Type: Highlight ACCEPT - DONE 6.8.4.6.2 SP21:SATA\_TransmitALIGN to SP22:SATA\_PHY\_Ready when should be if Page: 121 Sequence number: 8 Date: 2/9/2003 6:09:08 PM Type: Highlight ACCEPT - DONE 6.9.1 Overview Change Overview to SP\_DWS state machine overview Page: 123 Sequence number: 20 Date: 2/7/2003 6:20:59 PM Type: Note TODO when moving the ERROR/SATA\_ERROR stuff into XL, make sure that incoming ERROR is converted to SATA\_ERROR (along with incoming invalid dwords). Page: 127 Sequence number: 3 Date: 2/7/2003 6:05:39 PM Type: Highlight ACCEPT - DONE 7.1.1 Primitives overview this standard needs a closing) Page: 131 Sequence number: 3 Date: 1/24/2003 6:38:31 PM Type: Highlight ACCEPT - DONE 7.1 Primitives and global Change NOTIFY (ENABLE\_SPINUP) to NOTIFY (ENABLE SPINUP) - the underscore is not used inside parenthesis Page: 135 Sequence number: 9 Date: 1/16/2003 6:16:57 PM Type: Note ACCEPT - TODO label the 3 CLOSEs only as the triple primitive sequence. Change CLOSE to "Triple type of primitive" idle to "another dword" show another 3 after them Then show only one or two idles and mark that the second ones aren't in a second example Do the same kind of changes for the redundant section Page: 135 Sequence number: 10 Date: 1/24/2003 6:39:45 PM Type: Highlight ACCEPT - DONE 7.1.3.4 Triple primitive sequence CLOSE should be CLOSE (NORMAL)) Page: 135 Sequence number: 11 Date: 1/16/2003 6:22:58 PM Type: Note Note: back to back BROADCAST primitives are not detected somehow...

Page: 136 Sequence number: 3 Date: 1/16/2003 6:21:50 PM Type: Note keep this picture simpler than the triple picture show where the receiver detects after 3 don't use BROADCAST, use Redundant type of primitive Page: 137 Sequence number: 11 Date: 2/9/2003 12:14:25 PM Type: Highlight ACCEPT - DONE 7.1.4.4 BROADCAST Change "end devices" and "initiator ports and target ports" to "SAS ports" in this section. Broadcast primitives should be forwarded to SAS ports inside expander devices, not just those in end devices. Potential confusion: "expander port" is not a "SAS port" - expander ports must not treat the reserved primitives the same. To help, add (i.e. SAS initiator ports and SAS target ports) after "SAS ports" in the table Page: 139 Sequence number: 7 Date: 1/13/2003 10:41:51 AM Type: Note ACCEPT - TODO (Jan WG treat as OPEN\_REJECT (WRONG DESTINATION)) what if OPEN\_REJECT (STP RESOURCES BUSY) is the reply to an SSP or SMP request? Page: 139 Sequence number: 8 Date: 1/13/2003 12:42:15 PM Type: Highlight originator could be destination phy for a native STP target Page: 142 Sequence number: 7 Date: 1/14/2003 5:05:23 PM Type: Note REFER EDITORS WG (ACCEPT Jan WG TODO) 7.1.6.3 SATA\_HOLD and HOLDA SATA's 20 dwords is too loose. Should we mandate stopping transmitting within 19 to meet a receiver expectation of 20? 26.667 ns for one primitive (At 1.5 Gbps) 5 ns/m delay 10 m external cable => 2 dwords at 1.5 Gbps; 4 at 3.0 Gbps Receive buffer approach: 1. STP data receivers shall accept (20 + 4n) dwords after sending HOLD (4n = 8 at 3 Gbps, 4 at 1.5 Gbps) 2. STP data transmitters shall send no more than 20 dwords after receiving HOLD Mention that round-trip is used to select 4. This also/mostly goes into 7.17.2. outside the scope: SATA link from expander to SATA drive follows SATA rules (should transmit only 19 dwords and receive 21 to be safe) Page: 142 Sequence number: 9 Date: 1/14/2003 1:31:46 PM Type: Highlight 7.1.6.3 and global Change SATA protocol to just SATA Page: 142 Sequence number: 10 Date: 2/7/2003 6:13:10 PM Type: Note ACCEPT - DONE 7.1.6.1 SATA ERROR Add that an incoming ERROR is also forwarded as a SATA\_ERROR Page: 144 Sequence number: 7 Date: 1/25/2003 11:02:23 AM Type: Highlight ACCEPT - DONE

dwords (i.e., is not the original source of the data)

Page: 144 Sequence number: 8 Date: 1/16/2003 6:51:43 PM Type: Highlight data sb dword all over on this page Page: 144 Sequence number: 9 Date: 1/25/2003 11:01:51 AM Type: Highlight ACCEPT - DONE 7.2 clock skew management for expander devices forwarding dwords from SAS phys to SAS phys Page: 144 Sequence number: 10 Date: 2/1/2003 1:48:43 PM Type: Note ACCEPT - DONE 7.4 CRC Format all equations with division using Equation editor Page: 147 Sequence number: 15 Date: 1/31/2003 3:45:48 PM Type: Highlight ACCEPT - DONE 7.5 Scrambling Table 68 - Scrambling types Data should be Type Page: 150 Sequence number: 3 Date: 1/24/2003 7:12:51 PM Type: Highlight ACCEPT - DONE (actually Restricted) Make this Ignored Page: 150 Sequence number: 4 Date: 1/24/2003 7:10:17 PM Type: Note ACCEPT - DONE change Ignored fields to Restricted. The IDENTIFY frame is the source for them, and should set them to 0 so other data structures can fill them in. Page: 151 Sequence number: 6 Date: 1/24/2003 7:08:29 PM Type: Note ACCEPT - DONE 7.7.3 OPEN address frame Add CRC field paragraph. Page: 151 Sequence number: 7 Date: 2/9/2003 12:13:41 PM Type: Strikeout ACCEPT - DONE 7.7.2 IDENTIFY address frame Table 73 - Attached device type Delete only since other comments make end devices distinct from with expander devices Page: 152 Sequence number: 4

Sequence number: 4 Date: 1/24/2003 7:03:09 PM Type: Highlight

ACCEPT - DONE 7.7.3 OPEN address frame Table 74 - OPEN address frame format Delete (MSB) and (LSB) Page: 152 Sequence number: 5 Date: 1/24/2003 7:05:47 PM Type: Highlight ACCEPT - DONE (per Jan WG) Change all Reserved fields here to COMPATIBLE FEATURES Transmitters shall set these to zero. Recipient shall not check these fields. Page: 153 Sequence number: 6 Date: 1/21/2003 1:29:45 PM Type: Note ACCEPT - TODO check use of pathway vs. wide links Is pathway only one physical link in the wide link (implied by ch4), or is it all the physical links in the wide link (implied by here)? ch4 wins. "to a value supported by a potential pathway. For each wide link in a potential pathway, ..." Use potential pathway throughout where needed Page: 153 Sequence number: 7 Date: 1/24/2003 7:17:23 PM Type: Strikeout ACCEPT - DONE (Per 1/21 SAS call, delete this sentence.) "The requested connection rate shall not exceed the slowest negotiated physical link rate along the pathway." Page: 153 Sequence number: 8 Date: 2/7/2003 1:54:26 PM Type: Note **REVIEW PROTOCOL WG** ACCEPT - DONE 7.7.3 OPEN address frame Table 76 - Connection rate Change 0h and 1h to 8h and 9h (for 1.5 Gbps and 3.0 Gbps) to match DISCOVER function Page: 154 Sequence number: 8 Date: 1/24/2003 7:08:11 PM Type: Note ACCEPT - DONE 7.7.3 OPEN address frame Add CRC field paragraph. Page: 154 Sequence number: 9 Date: 2/9/2003 6:09:08 PM Type: Highlight ACCEPT - DONE 7.8.1 Overview Change Overview to Identification and hard reset sequence overview Page: 154 Sequence number: 10 Date: 2/9/2003 6:09:08 PM Type: Square ACCEPT - DONE 7.7.3 OPEN address frame Reword in terms of port identifiers of SAS port. The source address is from the originator not the port transmitting (expanders port don't change it as they forward connection requests).

Page: 155 Sequence number: 14 Date: 2/9/2003 6:09:08 PM Type: Highlight ACCEPT - DONE 7.8.5.1 Overview Change Overview to SL\_IR state machine overview Page: 157 Sequence number: 17 Date: 2/9/2003 6:09:08 PM Type: Highlight ACCEPT - DONE 7.8.6.1 Overview Change Overview to SL\_IR\_TIR state machine overview Page: 158 Sequence number: 12 Date: 2/9/2003 6:09:08 PM Type: Highlight ACCEPT - DONE 7.8.6.2.1 Overview Change Overview to SL\_IR\_RIF state machine overview Page: 159 Sequence number: 8 Date: 2/9/2003 6:09:08 PM Type: Highlight ACCEPT - DONE 7.8.6.3.1 Overview Change Overview to SL\_IR\_IRC state machine overview Page: 160 Sequence number: 18 Date: 2/6/2003 11:05:45 AM Type: Highlight ACCEPT - DONE 7.9 Power management Add SSP in front of target ports Page: 162 Sequence number: 14 Date: 2/9/2003 6:09:08 PM Type: Highlight ACCEPT - DONE 7.12.1 Connection overview Change Connection to Connections Page: 163 Sequence number: 33 Date: 2/6/2003 11:08:03 AM Type: Note

ACCEPT - DONE 7.12.3 Arbitration fairness Change "initiator port, target port" to "SAS port" and change "Initiator ports and target ports" to "SAS ports" Page: 163 Sequence number: 34 Date: 2/8/2003 11:40:57 AM Type: Note ACCEPT - DONE Change Initiator ports and target ports to SAS ports (i.e. SAS initiator ports and SAS target ports) throughout this section Page: 165 Sequence number: 16 Date: 1/29/2003 1:13:16 PM Type: Highlight 7.12.3.1.3 Partial Pathway Timer Per an IBM comment in the SMP PHY control section, the 7 µs default needs to change to a recommended default not a required default. Page: 170 Sequence number: 6 Date: 2/9/2003 6:09:08 PM Type: Highlight ACCEPT - DONE 7.13.1 Overview Change Overview to SL state machine overview Page: 171 Sequence number: 4 Date: 2/9/2003 12:11:24 PM Type: Note ACCEPT - DONE 7.13.1 SL state machine overview add open timeout timer, close timeout timer, and break timeout timer to a list in front of this state machine? Page: 174 Sequence number: 13 Date: 2/3/2003 3:13:07 PM Type: Highlight ACCEPT - DONE 7.13.3.2 SL0:Idle to SL1:ArbSel link rate should be connection rate Page: 174 Sequence number: 14 Date: 2/3/2003 3:33:44 PM Type: Highlight ACCEPT - DONE 7.13.3.2 SL0:Idle to SL1:ArbSel reword <<is received and an .. is received.>> to << receiving both...and...> Page: 174 Sequence number: 15 Date: 2/3/2003 3:33:36 PM Type: Highlight ACCEPT - DONE 7.13.3.2 SL0:Idle to SL2:Selected reword <<is received and an

Page: 179 Sequence number: 2 Date: 2/9/2003 6:09:08 PM Type: Highlight ACCEPT - DONE 7.14.1 Overview Change Overview to XL state machine overview Page: 189 Sequence number: 19 Date: 1/14/2003 8:44:30 PM Type: Note ACCEPT - TODO 7.14.10.1 XL8:Close\_Wait needs to mention invalid dwords too pull out ERROR stuff from DWS; just have it output valid dword or invalid dword. Let this state machine convert invalid dwords to ERROR or SATA\_ERROR as appropriate. Page: 189 Sequence number: 20 Date: 2/9/2003 12:12:18 PM Type: Highlight REJECT (but moved time reference to intro table instead) millisecond should be ms Page: 190 Sequence number: 12 Date: 2/4/2003 6:23:51 PM Type: Note ACCEPT - DONE Delete this paragraph, which conflicts with 7.7.3 (Brian Day's comment) Page: 193 Sequence number: 8 Date: 1/21/2003 11:11:43 AM Type: Note somewhere here, and in SMP link layer, and maybe XL link layer needs to say: Unless otherwise stated within the state description, all disparity errors, illegal characters, and unexpected primitives (i.e., any primitive not described in the description of the NNN state) received within any NNN state shall be ignored. Page: 193 Sequence number: 9 Date: 2/9/2003 6:09:08 PM Type: Highlight ACCEPT - DONE 7.16.7.1 Overview Change Overview to SSP link layer state machines overview Page: 207 Sequence number: 12 Date: 1/25/2003 11:50:35 AM Type: Note ACCEPT - DONE 7.17.4 STP link layer Mention that this is modified to talk to a port layer Page: 207 Sequence number: 13 Date: 1/21/2003 11:46:38 AM

Type: Highlight ACCEPT - TODO

initiator could be a target too... change to STP ports

.. is received.>> to <<receiving both...and...>

(global search for STP initiator and check if targets are also possible)

Page: 208 Sequence number: 11 Date: 1/25/2003 11:53:02 AM Type: Highlight ACCEPT - DONE 7.18.4.1 Overview (SMP link layer) Enable Disable SSP should be Enable Disable SMP (two times on the page) Page: 208 Sequence number: 12 Date: 2/9/2003 6:09:08 PM Type: Highlight ACCEPT - DONE 7.18.4.1 Overview Change Overview to SMP link layer state machines overview Page: 209 Sequence number: 2 Date: 2/8/2003 11:41:02 AM Type: Note ACCEPT - DONE 7.18.4.1 SMP link layer overview Move the initiator picture into the initiator subclause Page: 210 Sequence number: 3 Date: 2/1/2003 3:55:21 PM Type: Note ACCEPT - DONE 7.18.4.1 SMP link layer overview Move the target picture into the target subclause Page: 210 Sequence number: 4 Date: 2/1/2003 4:36:05 PM Type: Highlight ACCEPT - DONE (renamed but kept SMP\_IL and SMP\_TL acronyms) 7.17.4.2 SMP Initiator Link state machine reword names of the SMP state machines (Link is misused) Page: 210 Sequence number: 5 Date: 2/1/2003 3:28:51 PM Type: Note 7.18.4.1 SMP link layer target picture Request Break and Request Close are broken; states within the same state machine don't send parameters to each other Page: 213 Sequence number: 7 Date: 2/9/2003 6:09:08 PM Type: Highlight ACCEPT - DONE 8.1 Overview Change Overview to Port layer overview Page: 214 Sequence number: 9 Date: 2/9/2003 6:09:08 PM Type: Strikeout ACCEPT - DONE 8.2 Port layer timers and counters

Delete: Port layer Page: 215 Sequence number: 8 Date: 2/9/2003 6:09:08 PM Type: Strikeout ACCEPT - DONE 8.3.1 Overview Change Overview to PL\_OC state machine overview Page: 221 Sequence number: 9 Date: 2/9/2003 6:09:08 PM Type: Strikeout ACCEPT - DONE 8.4.1 Overview Change Overview to PL\_PM state machine overview Page: 229 Sequence number: 28 Date: 1/25/2003 11:59:10 AM Type: Note ACCEPT - DONE 9.2.1 SSP frame format Target port transfer tag paragraph "unique for the I\_T nexus" is wrong - it should be "unique for the L\_Q portion of the nexus." The connection tag is unique for the I\_T; an SSP frame is sent inside a connection, so the I\_T is already known. This is used to distinguish between L\_Qs. Page: 229 Sequence number: 29 Date: 1/23/2003 1:31:50 PM Type: Note ACCEPT - DONE 9.2.1 SSP frame format Table 89 - frame type field Add a "Reference" column Page: 229 Sequence number: 30 Date: 2/2/2003 11:08:16 AM Type: Note ACCEPT - DONE Mention that the TASK frame TAG field serves as the optional Association argument in SAM Page: 230 Sequence number: 13 Date: 1/22/2003 5:50:09 PM Type: Highlight ACCEPT - DONE 9.2.1 SSP Frame header is should be contains Page: 230 Sequence number: 14 Date: 2/2/2003 12:12:04 PM Type: Highlight ACCEPT - DONE 9.2.1 SSP frame format Relative offset field paragraph indicates should be contains

Sequence number: 6 Date: 2/8/2003 11:40:57 AM Type: Highlight ACCEPT - DONE 9.2.2.1 COMMAND information unit ordered attribute should be ordered task attribute Page: 232 Sequence number: 5 Date: 1/6/2003 10:53:08 AM Type: Highlight ACCEPT - DONE 9.2.2.2 TASK information unit SPC-2 should be SAM-3 Page: 232 Sequence number: 10 Date: 2/2/2003 2:59:13 PM Type: Note ACCEPT - DONE 9.2.2.2 TASK information unit Table 93 - Task management functions Add columns showing when LOGICAL UNIT NUMBER and TAG OF TASK TO BE MANAGED fields are used Page: 235 Sequence number: 4 Date: 2/2/2003 12:42:20 PM Type: Note ACCEPT - DONE (per Jan WG) 9.2.2.5.1 RESPONSE IU overview Add: The maximum size of the response IU is the maximum size of any IU in an SSP frame (see 9.2.1). Page: 237 Sequence number: 7 Date: 1/6/2003 12:26:10 PM Type: Highlight ACCEPT - DONE 9.2.2.5.4 REPONSE information unit SENSE\_DATA format In the SENSE DATA paragraph, change contains to shall contain to match the wording in the other paragraphs. Page: 237 Sequence number: 10 Date: 1/22/2003 3:43:24 PM Type: Highlight ACCEPT - DONE 9.2.3 Frame sequences Change Initiator port to SSP initiator port and Target port to SSP target port in all the frame sequence figures (94, 95, 96, 97) Page: 240 Sequence number: 11 Date: 1/6/2003 3:58:16 PM Type: Highlight ACCEPT - DONE (changed to 'times out waiting for") 9.2.4.5 RESPONSE frame Change "does not receive an ACK or NAK" to "times out waiting for an ACK or NAK" Page: 241 Sequence number: 5 Date: 2/2/2003 3:04:14 PM Type: Highlight ACCEPT - DONE (Jan WG) Change may to shall Also change may to shall in the state machine 9.2.6.2.2.1

Sequence number: 6 Date: 2/2/2003 2:51:51 PM Type: Highlight ACCEPT - DONE (changed last "it' to "the command" in 3 paragraphs) 9.2.5.2 Initiator port error handling which it? Page: 241 Sequence number: 7 Date: 2/8/2003 12:34:29 PM Type: Highlight ACCEPT - TODO (03-088 makes this request) Rename this to DATA OFFSET ERROR since the relative offset field is being renamed DATA OFFSET or REQUESTED OFFSET everywhere else Page: 242 Sequence number: 21 Date: 2/8/2003 12:35:19 PM Type: Strikeout ACCEPT - DONE 9.2.6.2.1 Initiator device state machines overview delete several Page: 242 Sequence number: 22 Date: 2/9/2003 12:10:03 PM Type: Square ACCEPT - DONE 9.2.6.1 SSP transport layer state machines overview Simplify this list; merge data services in with the rest of the transport protocol services Get rid of initiator/target references Page: 242 Sequence number: 23 Date: 2/9/2003 6:09:08 PM Type: Strikeout ACCEPT - DONE 9.2.6.2.1 Overview Change Overview to <new title> overview Page: 242 Sequence number: 24 Date: 2/9/2003 6:09:08 PM Type: Highlight ACCEPT - DONE 9.2.6.1 Overview Change Overview to SSP transport layer state machines overview Page: 244 Sequence number: 10 Date: 2/9/2003 12:10:03 PM Type: Highlight ACCEPT - DONE 9.2.6.2.1 ST state machines overview Figure 96 - ST initiator device move Delivery Failure near the source of the arrow Page: 245 Sequence number: 14 Date: 1/30/2003 3:26:53 PM Type: Strikeout ACCEPT - DONE 9.2.6.2.2.1 ST\_ISF1 state description

Page: 245 Sequence number: 15 Date: 1/30/2003 3:54:10 PM Type: Highlight ACCEPT - DONE 9.2.6.2.2.1 ST\_ISF1: state description The 2nd+ a)b) lists both need to include logical unit number (it's missing in the Send Task Management list) and should list it ahead of the tag (Send SCSI Command has it second not first) Page: 245 Sequence number: 16 Date: 2/8/2003 3:00:34 PM Type: Strikeout ACCEPT - DONE Delete The request may also contain the initiator connection tag to be used in any OPEN address frame. The a)b) list above already includes initiator connection tag Page: 246 Sequence number: 16 Date: 2/8/2003 11:40:57 AM Type: Highlight ACCEPT - DONE 9.2.6.2.2.1 ST\_ISF1 Overview attribute should be parameter Page: 247 Sequence number: 12 Date: 1/30/2003 3:56:30 PM Type: Highlight ACCEPT - DONE 9.2.6.2.3.1 ST\_ISF2 state description The first two a)b) lists should include logical unit number and include it before tag Page: 247 Sequence number: 13 Date: 1/30/2003 3:58:03 PM Type: Highlight ACCEPT - DONE 9.2.6.2.4.1 ST\_ISF3 state description logical unit number should be included ahead of tag; Page: 247 Sequence number: 14 Date: 2/9/2003 12:10:03 PM Type: Highlight ACCEPT - DONE 9.2.6.2.4 ST\_ISF3 and global Change Prepare\_Send\_Data\_Out to Prepare\_Data\_Out to match other states and simplify Page: 247 Sequence number: 15 Date: 2/9/2003 12:10:03 PM Type: Highlight ACCEPT - DONE 9.2.6.2.3 ST\_ISF2 and global Change Prepare\_Command\_Request to

Prepare\_Command\_Task to match other states and simplify Page: 248 Sequence number: 9 Date: 2/9/2003 12:10:03 PM Type: Highlight ACCEPT - DONE 9.2.6.2.6 ST\_IRD2 and global Change: Process\_Received\_Data\_In to: Process\_Data\_In to match other states and simplify Page: 248 Sequence number: 10 Date: 2/9/2003 12:10:03 PM Type: Highlight ACCEPT - DONE 9.2.6.2.7 ST\_IPR1 and global Change Process\_Received\_Response to Process\_Response to match other states and simplify Page: 248 Sequence number: 11 Date: 2/9/2003 12:10:03 PM Type: Square ACCEPT - DONE 9.2.6.2.6 ST\_IRD2:Process\_Received\_Data\_In and global The ST\_IRD2:Process\_Received\_Data\_In state does nothing useful and can be merged into the ST\_IRD1 state. This reduces the ST\_IRD state machine to a single state. The name should be changed from IRD to IPD (initiator process data). Update figures and all references to ST\_IRD. Page: 249 Sequence number: 8 Date: 2/8/2003 2:30:41 PM Type: Strikeout ACCEPT - DONE Delete: a DONE Received confirmation is received; Based on other comments, it is vendor-specific how an initiator decides to reuse tags. The state machines in the standard won't pass up DONEs for this purpose. Page: 250 Sequence number: 25 Date: 2/2/2003 4:28:30 PM Type: Strikeout ACCEPT - DONE 9.2.6.3 Target device state machines overview With SAS's bizarre state machines, there are cases where ST\_TTS1 is not the initial state. Delete "(initial state)". Page: 250 Sequence number: 26 Date: 2/9/2003 12:10:03 PM Type: Note ACCEPT - DONE The target state machines do not comprehend first burst. They need to. When Receive Data-Out arrives, it must be serviced first from the first burst data buffer. When that runs out, XFER\_RDYs are generated. Data-Out may appear before the first Receive Data-Out call, so the state machine has to be ready to go to TTS4 immediately. TTS4 needs to save the first burst data in a buffer. Changes include:

\* Change the Prepare\_XFER\_RDY outbound transition from Receive\_Data\_Out to Send\_Frame directly. There is no sense in going back to Receive Data Out; it does no work. Remove the Receive Data Out to Send Frame transition. Keep the entry to Receive Data out from the frame router. This lets it check the first burst amount before deciding if an XFER\_RDY is necessary. \* Let the TTS state machine start in TTS4 if first burst data arrives. Page: 250 Sequence number: 27 Date: 2/9/2003 6:09:08 PM Type: Highlight ACCEPT - DONE 9.2.6.3.1 Overview Change Overview to <new title> overview Page: 253 Sequence number: 14 Date: 1/30/2003 3:49:59 PM Type: Highlight ACCEPT - DONE 9.2.6.3.3.1 ST\_TTS1 state description Change I\_T\_L\_x nexus (e.g., tag) to "tag" in all the a)b) lists in this section. The first list mentions the source/destination SAS addresses, which form the I\_T portion. The 2nd-4th lists should just say "tag" to match the initiator wording (and avoid confusion with the Nexus and Association arguments described in ch 10) Page: 253 Sequence number: 15 Date: 1/30/2003 3:51:11 PM Type: Note ACCEPT - DONE 9.2.6.3.3.1 ST\_TTS1 state description The 2nd-4th a)b) lists needs to include the logical unit number, which is needed for the frame headers Page: 253 Sequence number: 16 Date: 2/9/2003 12:49:44 PM Type: Highlight ACCEPT - DONE 9.2.6.3.3 ST\_TTS1 and global Rename: ST\_TTS1:Target\_Request\_Response\_Router and ST\_TTS1:Request\_response\_Router (inconsistent and verbose) to: ST\_TTS1:Start Page: 255 Sequence number: 10 Date: 1/30/2003 4:00:57 PM Type: Note ACCEPT - DONE 9.2.6.3.5.1 ST\_TTS3 state description should mention logical unit number along with tag Page: 255 Sequence number: 11 Date: 2/9/2003 12:10:03 PM Type: Highlight ACCEPT - DONE 9.2.6.3.5.1 ST\_TTS3 State description Change: to be used in the frame: to: when constructing the frame

Sequence number: 12 Date: 2/9/2003 12:10:03 PM Type: Highlight ACCEPT - DONE 9.2.6.3.5 ST\_TTS3 and Global Rename: Prepare\_Send\_Data\_In to: Prepare\_Data\_In to match other state names and simplify Page: 255 Sequence number: 13 Date: 2/9/2003 12:10:03 PM Type: Highlight ACCEPT - DONE 9.2.6.3.4.2 TTS2 to TTS3 if this state receives should be after receiving to match previous two IBM comments Page: 255 Sequence number: 14 Date: 2/9/2003 12:10:03 PM Type: Square ACCEPT - DONE 9.2.6.3.5.1 TTS3 state description Add data to the list. It is arguably implied by the first paragraph. To parallel the initiator Data\_Out preparation, though, it belongs in this list. Page: 256 Sequence number: 16 Date: 2/9/2003 12:10:03 PM Type: Note ACCEPT - DONE 9.2.6.3.6 ST\_TTS4 Second paragraph Remove "from the ST\_TS1:Request\_Response\_Router state" Page: 256 Sequence number: 17 Date: 2/9/2003 12:10:03 PM Type: Highlight ACCEPT - DONE 9.2.6.3.6.1 TTS4 state description "If the value does not match" is unclear; does not match what? Change to "is invalid" which is equally vague but not obviously broken. Page: 256 Sequence number: 18 Date: 2/9/2003 12:10:03 PM Type: Highlight ACCEPT - DONE 9.2.6.3.6.1 ST\_TTS4 State description Change DATA frame from the ST\_TFR state machine, to Data-Out Arrived parameter Page: 256 Sequence number: 19 Date: 2/9/2003 12:10:03 PM Type: Highlight ACCEPT - DONE 9.2.6.3.6.1 ST\_TTS4 State description Change

DATA frame from the ST\_TFR state machine, to Data-Out Arrived parameter Page: 256 Sequence number: 20 Date: 2/9/2003 12:10:03 PM Type: Highlight ACCEPT - DONE 9.2.6.3.6.1 ST\_TTS4 State description Change DATA frame from the ST\_TFR state machine, to Data-Out Arrived parameter Page: 256 Sequence number: 21 Date: 2/9/2003 12:10:03 PM Type: Highlight ACCEPT - DONE 9.2.6.3.6.1 ST\_TTS4 State description Change DATA frame from the ST\_TFR state machine, to Data-Out Arrived parameter Page: 256 Sequence number: 22 Date: 2/9/2003 12:10:03 PM Type: Note ACCEPT - DONE 9.2.6.3.6.1 ST\_TTS4 state description Combine the four long paragraphs about receiving Data-Out Arrived into an a)b)c)d) list. Page: 257 Sequence number: 9 Date: 1/30/2003 4:03:04 PM Type: Highlight ACCEPT - DONE 9.2.6.3.7.1 ST\_TTS5 state description logical unit should appear alognside tag; Page: 257 Sequence number: 10 Date: 2/8/2003 5:07:41 PM Type: Highlight ACCEPT - DONE Change: Receive Data-Out transport protocol service request to: application layer to match other wording and simplify Page: 257 Sequence number: 11 Date: 2/8/2003 4:58:11 PM Type: Highlight ACCEPT - DONE 9.2.6.3.7.1 ST\_TTS5 state description Change: to be used in the frame: to: when constructing the frame Page: 257 Sequence number: 12 Date: 2/9/2003 12:10:03 PM Type: Highlight

ACCEPT - DONE 9.2.6.3.8 ST\_TTS7 and Global Change: Process\_Received\_Data\_Out to: Process\_Data\_Out to match other state names and simplify Page: 258 Sequence number: 8 Date: 2/8/2003 4:53:34 PM Type: Highlight ACCEPT - DONE (also made it clear that Response Data includes a logical unit number and tag.) 9.2.6.3.9.1 ST\_TTS7 state description "this state shall use the tag received in the parameter." contradicted by "this state shall use the following received from the application layer" in the next paragraph. Page: 258 Sequence number: 9 Date: 1/30/2003 4:06:11 PM Type: Highlight ACCEPT - DONE 9.2.6.3.9.1 ST\_TTS7 state description logical unit number should appear alongside tag Page: 258 Sequence number: 10 Date: 2/8/2003 11:41:02 AM Type: Strikeout ACCEPT - DONE 9.2.6.3.9.1 ST\_TTS7:Prepare\_Response remove d) ... from the port layer state machine Page: 258 Sequence number: 11 Date: 2/8/2003 4:02:46 PM Type: Highlight ACCEPT - DONE 9.2.6.3.9 ST\_TTS7 Convert these sentences into a table. Page: 258 Sequence number: 12 Date: 2/8/2003 4:45:46 PM Type: Highlight ACCEPT - DONE 9.2.6.3.9.1 ST\_TTS7 State overview status needs a semicolon Page: 258 Sequence number: 13 Date: 2/9/2003 12:10:03 PM Type: Highlight ACCEPT - DONE 9.2.6.3.9.1 ST\_TTS7 State description Change: to be used in the frame: to: when constructing the frame Page: 259 Sequence number: 15 Date: 1/16/2003 4:41:16 PM Type: Note 9.3.4 STP transport layer state machines Mention that this is modified to interface to the port layer

Page: 259 Sequence number: 16 Date: 1/30/2003 4:25:42 PM Type: Note 9.3.2 SATA tunneling for multiple STP initiator ports Add comment that native STP devices should not support affiliations. (phrase as affiliations are only an expander function) They can put in a virtual phy and support SMP. DISCOVER and PHY CONTROL to the virtual phy could control the affiliations. Page: 259 Sequence number: 17 Date: 1/29/2003 3:28:36 PM Type: Highlight ACCEPT - DONE 9.3.2 SATA tunneling for multiple STP initiator ports Rename this to "affiliations" Page: 259 Sequence number: 18 Date: 1/30/2003 4:57:21 PM Type: Note The format of 9.4.x differs from the SSP frame format and should be restructured as follows: 9.4.1 SMP frame format (describe an SMP frame with just SMP FRAME TYPE, FUNCTION, and CRC fields). Include the frame type codes in the table listing SMP\_REQUEST and SMP\_RESPONSE. Mention that other codes are reserved. 9.4.2, 9.4.3 SMP\_REQUEST and SMP\_RESPONSE (as is) 9.4.4 Sequence of SMP frames (move the frame sequence picture into here) 9.4.5 SMP transport layer state machines (as is) Page: 259 Sequence number: 19 Date: 2/9/2003 6:09:08 PM Type: Highlight ACCEPT - DONE 9.4.1 SMP Overview Change SMP overview to SMP transport layer overview Page: 260 Sequence number: 15 Date: 1/31/2003 3:45:48 PM Type: Highlight ACCEPT - DONE 9.4.2 SMP REQUEST frame Add a sentence indicating who sends this frame and what it is for. (like SMP RESPONSE and all the SSP frames do) Page: 262 Sequence number: 6 Date: 2/9/2003 3:06:00 PM Type: Highlight ACCEPT - DONE 9.4.4.1 SMP transport layer state machine overview Change SAS expander to expander Page: 262 Sequence number: 7 Date: 2/9/2003 6:09:08 PM Type: Highlight ACCEPT - DONE 9.4.4.1 Overview Change Overview to SMP transport layer state machines overview

Page: 262 Sequence number: 8 Date: 2/9/2003 6:09:08 PM Type: Highlight ACCEPT - DONE 9.4.4.2.1 Overview Change Overview to SMP initiator port state machine overview Page: 264 Sequence number: 17 Date: 2/9/2003 3:00:49 PM Type: Highlight ACCEPT - DONE 9.4.4.3 Expander device and target device state machine Rename to "SMP target port transport layer state machine" Also check initiator name Page: 264 Sequence number: 18 Date: 2/9/2003 6:09:08 PM Type: Highlight ACCEPT - DONE 9.4.4.3.1 Overview Change Overview to SMP target port state machine overview Page: 266 Sequence number: 2 Date: 2/9/2003 6:09:08 PM Type: Highlight ACCEPT - DONE 10.1.1.1 Transport protocol services overview Change Transport protocol services overview to SCSI transport protocol services overview Page: 269 Sequence number: 5 Date: 2/2/2003 2:38:16 PM Type: Highlight ACCEPT - DONE 10.1.1.4 Send Command Complete one and the RESPONSE CODE field is INVALID FRAME (see comments in 9.2.5.1) Page: 270 Sequence number: 5 Date: 2/8/2003 11:41:02 AM Type: Highlight ACCEPT - DONE 10.1.1.5 Command Complete Received one and the RESPONSE CODE field is INVALID FRAME (see comments in 9.2.5.1) Page: 272 Sequence number: 5 Date: 12/30/2002 6:05:57 PM Type: Highlight ACCEPT - DONE 10.1.1.8 Receive Data-Out Table 112 - Receive Data-Out args usd should be used

Page: 272 Sequence number: 6 Date: 2/1/2003 2:02:44 PM Type: Note ACCEPT - DONE (put in [Association] argument to carry the TAG field, which might make it into SAM-3. Let the transport layer state machine just refer to "tag" and "tag of task to be managed" - it was not using "Nexus" so shouldn't be confused.) 10.1.1.10 Send Task Management Request transport protocol service and other sections the Q is really the "tag of task to be managed" field not the "tag" field Page: 273 Sequence number: 6 Date: 1/30/2003 3:40:32 PM Type: Highlight ACCEPT - DONE 10.1.1.10 Send Task Management Request and other sections Both I\_T\_L and I\_T\_L\_Q are supported (I\_T would be too if TARGET RESET were supported). Page: 274 Sequence number: 5 Date: 1/30/2003 2:38:19 PM Type: Highlight ACCEPT - DONE (Jan WG: make TASK MANAGEMENT FUNCTION FAILED map to service delivery or target failure in Task Management Function Executed and Received Task Management Function Executed) 10.1.1.12 Task Management Function Executed Table 116 - Task Management Function Executed arguments "d) The RESPONSE frame SNSVALID bit is set to one." is this the correct indication of severe failure for a task management function? Page: 278 Sequence number: 2 Date: 2/8/2003 11:49:39 AM Type: Highlight ACCEPT - DONE 10.1.6.1 Disconnect-Reconnect mode page Change specifies to contains or means several times in this section. Page: 279 Sequence number: 8 Date: 2/9/2003 6:09:08 PM Type: Highlight ACCEPT - DONE 10.1.6.2.1 Overview Change Overview to Protocol-Specific Port mode page overview Page: 280 Sequence number: 4 Date: 2/2/2003 12:14:08 PM Type: Highlight ACCEPT - DONE 10.1.6.2.2 Protocol-specific port mode page - short format indicates how long should be contains the time Page: 281 Sequence number: 7 Date: 12/31/2002 1:11:02 PM Type: Highlight ACCEPT - DONE Table 122 - Protocol-specific port Control mode page -Phy Control and Discover subpage The byte numbers are off. Byte 4 should be byte 2. 2 more reserved bytes are needed to keep the mode descriptors starting on byte 8.

Page: 288 Sequence number: 5 Date: 1/30/2003 1:31:48 PM Type: Highlight ACCEPT - DONE 10.1.8 Power condition states Figure 103 - SA\_PC state machine Change devices to logical units in the notes Page: 292 Sequence number: 4 Date: 1/31/2003 3:45:48 PM Type: Strikeout ACCEPT - DONE 10.1.8.7.5 Idle\_Wait to Active\_Wait Delete b) a START STOP UNIT command with the POWER CONDITION field set to FORCE ACTIVE is received; or there is no such setting called "FORCE ACTIVE" Page: 294 Sequence number: 3 Date: 2/9/2003 6:09:08 PM Type: Highlight ACCEPT - DONE 10.3.1.1 Function overview Change Function overview to SMP function overview Page: 297 Sequence number: 5 Date: 1/30/2003 12:31:18 PM Type: Note TODO 10.3.1.2 REPORT GENERAL What does configurable mean for a fanout expander? Is it required to support the REPORT ROUTE function even if it is self-programming? No, but it may. Page: 298 Sequence number: 6 Date: 1/25/2003 5:41:04 PM Type: Note **REFER EDITORS WG** ASCII strings shouldn't have (MSB)/(LSB) labels. Strings are arrays of 8-bit bytes. Each byte has an MSB/LSB. The string doesn't as a whole. [an array of dwords wouldn't be labeled thusly] Page: 299 Sequence number: 5 Date: 2/2/2003 12:18:01 PM Type: Highlight ACCEPT - DONE 10.3.1.4 DISCOVER function indicates should be specifies Page: 300 Sequence number: 2 Date: 1/25/2003 5:39:50 PM Type: Highlight ACCEPT - DONE 10.3.1.4 DISCOVER function Change SATA TARGET to SATA DEVICE Page: 300 Sequence number: 3 Date: 1/21/2003 7:12:05 PM Type: Highlight ACCEPT - DONE 10.3.1.4 DISCOVER function

Change Reserved bit to ATTACHED SATA HOST An ATTACHED SATA HOST bit of one indicates a SATA host is attached. A bit of zero ... NOTE: Support for SATA hosts is outside the scope of this standard. (from Bill Galloway, Pivot3) Page: 301 Sequence number: 6 Date: 2/6/2003 10:54:44 AM Type: Strikeout ACCEPT - DONE 10.3.1.4 DISCOVER function Table 138 - Attached device type Delete only since other comments make end devices distinct from with expander devices Page: 302 Sequence number: 11 Date: 1/29/2003 3:52:15 PM Type: Note ACCEPT - DONE ("address provided for') 10.3.1.4 DISCOVER function Mention what the ATTACHED SAS ADDRESS field contains if a SATA target is attached Page: 302 Sequence number: 13 Date: 1/29/2003 3:51:15 PM Type: Highlight ACCEPT - DONE 10.3.1.4 DISCOVER function The a) b) list belongs to ATTACHED SAS ADDRESS, not SAS ADDRESS. The SAS ADDRESS field itself should always be known. The Attached field changes based on identification/OOB sequences. Page: 302 Sequence number: 14 Date: 2/7/2003 1:52:26 PM Type: Note **REVIEW PROTOCOL WG** ACCEPT - DONE 10.3.1.4 DISCOVER function Change 4h and 5h to 8h and 9h (for 1.5 Gbps and 3.0 Gbps) Page: 303 Sequence number: 5 Date: 1/21/2003 4:43:05 PM Type: Note ACCEPT - DONE 10.3.1.5 DISCOVER function The default value shall be the hardware ... physical link rate. Page: 303 Sequence number: 6 Date: 1/29/2003 3:56:57 PM Type: Note **REVIEW PROTOCOL WG** ACCEPT - DONE (per 1/28 call) 10.3.1.4 DISCOVER function or DISCOVER page, make 0 value on the programmed rates mean "not programmable" Page: 303 Sequence number: 7 Date: 2/2/2003 12:18:59 PM Type: Highlight ACCEPT - DONE 10.3.1.5 REPORT PHY ERROR LOG indicates should be specifies Page: 303 Sequence number: 8 Date: 2/7/2003 1:52:18 PM

Type: Note ACCEPT - DONE 10.3.1.4 DISCOVER function \*\*\* Table 140 - Hardware and programmed physical link rates 5h and 6h should be 8h and 9h to match the negotiated physical link rate field. Page: 306 Sequence number: 3 Date: 2/2/2003 12:19:39 PM Type: Highlight ACCEPT - DONE 10.3.1.6 REPORT PHY SATA indicates should be specifies Page: 307 Sequence number: 4 Date: 12/30/2002 2:30:56 PM Type: Highlight ACCEPT - DONE Table 146 - Function results for REPORT PHY SATA 11h PHY DOES NOT SUPPORT SATA should mention "rest of data is invalid" Page: 307 Sequence number: 5 Date: 2/8/2003 12:21:27 PM Type: Note ACCEPT - DONE (and posted to T10 list) 10.3.1.6 REPORT PHY SATA dump PHY NOT SATA result - the first byte in the REGISTER FIS field indicates if it's not a usable SATA device dump SATA RESET HALTED result - DISCOVER's negotiated link rate field indicates spinup hold PHY DOES NOT SUPPORT SATA means everything is invalid like most other function results Page: 307 Sequence number: 6 Date: 1/29/2003 5:41:36 PM Type: Highlight ACCEPT - DONE 10.3.1.6 REPORT PHY SATA Note 25 00b should be 000b and add an (i.e. no device attached) Page: 308 Sequence number: 4 Date: 1/29/2003 6:30:23 PM Type: Highlight ACCEPT - DONE (moved into 10.3.1.1 combined table with these changes) **10.3.1.7 REPORT ROUTE INFORMATION** delete "for any EXPANDER ROUTE INDEX with the indicated phy identifier." just the shall return is enough. Plus, the EXPANDER ROUTE INDEX should have been smallcaps. Page: 308 Sequence number: 5 Date: 2/2/2003 12:20:53 PM Type: Highlight ACCEPT - DONE **10.3.1.7 REPORT ROUTE INFORMATION** indicates should be specifies (several places in the request description) Page: 309 Sequence number: 2 Date: 12/30/2002 10:41:13 AM Type: Highlight ACCEPT - DONE **10.3.1.7 REPORT ROUTE INFORMATION** Table y should be Table 148

Page: 309 Sequence number: 3 Date: 2/7/2003 11:18:01 AM Type: Highlight ACCEPT - DONE **10.3.1.7 REPORT ROUTE INFORMATION** ROUTE should be EXPANDER ROUTE throughout this subclause Page: 310 Sequence number: 1 Date: 1/29/2003 6:26:44 PM Type: Highlight ACCEPT - DONE **10.3.1.7 REPORT ROUTE INFORMATION** Change "shall not be used" to "ecm shall not use" (get rid of passive tense to match the previous sentence) Page: 311 Sequence number: 3 Date: 2/2/2003 12:22:12 PM Type: Highlight ACCEPT - DONE **10.3.1.8 CONFIGURE ROUTE INFORMATION** indicates should be specifies (3 times in request) Page: 311 Sequence number: 4 Date: 2/8/2003 11:40:57 AM Type: Highlight ACCEPT - DONE **10.3.1.8 CONFIGURE ROUTE INFORMATION** ROUTE should be EXPANDER ROUTE throughout this subclause Page: 312 Sequence number: 7 Date: 1/31/2003 3:45:48 PM Type: Highlight ACCEPT - DONE **10.3.1.8 CONFIGURE ROUTE INFORMATION** Change "shall not be used" to "ecm shall not use" (get rid of passive tense to match the previous sentence) Page: 313 Sequence number: 4 Date: 1/29/2003 12:20:15 PM Type: Note ACCEPT - DONE (put in a 0 value for the link rates, and an enable bit for PPTV) 10.3.1.9 PHY control function Options discussed at Jan WG: \* write enable bits for min+max rate, and pptv in byte 11 (Bill votes for this) DISCOVER returns these as 1 if they are writable. or: phy operations of: set PPTV (uses pptv field) link reset (uses rate field) hard reset (uses rate field) or: phy operation to return changeable fields like mode pages Page: 313 Sequence number: 5 Date: 2/2/2003 12:23:53 PM Type: Highlight ACCEPT - DONE 10.3.1.9 PHY CONTROL indicates should be specified several times in the request section Page: 313 Sequence number: 6

Date: 2/6/2003 9:28:23 AM Type: Highlight ACCEPT - DONE 10.3.1.9 PHY CONTROL function Table 153 - PHY CONTROL request row for byte 39 should be two rows for 37-39 Page: 314 Sequence number: 3 Date: 1/29/2003 12:07:53 PM Type: Highlight ACCEPT - DONE (make value of 0h be "no change") 10.3.1.9 PHY CONTROL function The programmed link rate fields shall be set in the same request where a LINK RESET or HARD RESET operation is invoked. There's no code that means "no change". Page: 314 Sequence number: 4 Date: 1/30/2003 10:13:09 AM Type: Note ACCEPT - DONE 10.3.1.9 PHY CONTROL Do LINK RESET and HARD RESET take time, or do they complete immediately? Email discussion agrees they complete immediately; add such wording to the descriptions. Page: 315 Sequence number: 3 Date: 1/30/2003 10:13:51 AM Type: Note REJECT (added an enable bit for updating PPTV instead of a new phy operation) 10.3.1.9 PHY control function Option discussed at Jan protocol WG: add a PHY OPERATION to set the PPTV. Only if that is selected is this field honored. Page: 315 Sequence number: 4 Date: 1/29/2003 12:41:58 PM Type: Highlight ACCEPT - DONE 10.3.1.9 PHY CONTROL partial pathway timeout value paragraph after zero, add (i.e., 0 us) so the time stands out Page: 315 Sequence number: 5 Date: 2/7/2003 1:52:53 PM Type: Note ACCEPT - DONE 10.3.1.9 PHY CONTROL function Table 155 - Programmed physical link rate 5h and 6h should be 8h and 9h to match the DISCOVER function negotiated physical link rate field. Page: 330 Sequence number: 3 Date: 12/30/2002 2:17:26 PM Type: Highlight ACCEPT - DONE D.3 Hash generation show should be shown Page: 330 Sequence number: 5 Date: 1/23/2003 1:44:43 PM Type: Highlight ACCEPT - DONE D.2 Hash collision probability and global vendor specific should be vendor-specific

Page: 330 Sequence number: 6 Date: 1/23/2003 1:45:36 PM Type: Highlight ACCEPT - DONE D.2 Hash collision probability Four models were used for the models for the simulations. Add : and an a)b)c)d) list of the four models. Page: 330 Sequence number: 7 Date: 2/9/2003 6:09:08 PM Type: Highlight ACCEPT - DONE D.1 Hashing overview Change Hashing overview to SAS address hashing overview Page: 331 Sequence number: 2 Date: 1/23/2003 1:47:59 PM Type: Highlight ACCEPT - DONE Figure D.1 BCH code generator The text is 12 pt and should be 10 pt Page: 333 Sequence number: 1 Date: 1/24/2003 9:10:22 AM Type: Note ACCEPT - DONE D.6 Hash examples Add all-0s and all-Fs examples Add some examples that hash to the same value Page: 336 Sequence number: 2 Date: 12/30/2002 1:15:12 PM Type: Highlight ACCEPT - DONE E Scrambling Figure E.1 — Scrambler Figure is using 8 point font; should be 10 point. Page: 336 Sequence number: 3 Date: 12/30/2002 1:15:03 PM Type: Note ACCEPT - DONE E Scrambling Hanging paragraph at top of annex Page: 336 Sequence number: 4 Date: 1/8/2003 1:27:12 PM Type: Note ACCEPT - DONE E Scrambling figure E.1 Scrambler Need to add an arrow on the line going into the left side of the Context register box Page: 343 Sequence number: 2 Date: 12/30/2002 10:29:31 AM Type: Highlight

ACCEPT - DONE G Expander handling of connections G.1 Overview Table G.1 - Column descriptions RX should be Rx, TX should be Tx Page: 343 Sequence number: 3 Date: 2/9/2003 3:01:28 PM Type: Highlight ACCEPT - DONE G.1 Expander handling of connections overview Change SAS expander to expander Page: 343 Sequence number: 4 Date: 2/9/2003 6:09:08 PM Type: Highlight ACCEPT - DONE G.1 Overview Change Overview to Expander handling of connections overview Page: 360 Sequence number: 2 Date: 2/9/2003 6:09:08 PM Type: Highlight ACCEPT - DONE H.1 Overview Change Overview to Primitive encoding overview Page: 363 Sequence number: 1 Date: 2/9/2003 6:09:08 PM Type: Highlight ACCEPT - DONE I.1 Overview Change Overview to Discover process example implementation overview

## Author: SEG Alvin E Cox

Page: 67 Sequence number: 7 Date: 1/31/2003 4:12:50 PM Type: Strikeout ACCEPT - DONE (per PHY WG - with only added to prev line too) 5.3.3 SAS internal cable receptacle connector "only" is unnecessary in this sentence and should be removed.

Page: 67 Sequence number: 8 Date: 1/31/2003 4:14:09 PM Type: Strikeout ACCEPT - DONE 5.3.4 SAS backplane receptacle connector "only" is unnecessary in this sentence and should be removed.

Page: 70 Sequence number: 2 Date: 1/31/2003 4:41:40 PM Type: Circle ACCEPT - DONE (per phy WG) 5.4.1 SAS internal cables Figure 34 — SAS internal cable assembly and destination pin assignments P11 is not bidirectional should only have one arrow on the far end. Page: 70 Sequence number: 3 Date: 1/20/2003 4:25:09 PM Type: Circle ACCEPT - DONE 5.4.1 SAS internal cables Figure 34 — SAS internal cable assembly and destination pin assignments These grounds should have an arrow on both ends as they are a shield rather than a directional signal or power function. Page: 70 Sequence number: 4 Date: 1/20/2003 4:25:01 PM Type: Circle ACCEPT - DONE 5.4.1 SAS internal cables Figure 34 — SAS internal cable assembly and destination pin assignments These grounds should have an arrow on both ends as they are a shield rather than a directional signal or power function. Page: 70 Sequence number: 5 Date: 1/20/2003 4:25:17 PM Type: Circle ACCEPT - DONE 5.4.1 SAS internal cables Figure 34 — SAS internal cable assembly and destination pin assignments These grounds should have an arrow on both ends as they are a shield rather than a directional signal or power function. Page: 72 Sequence number: 4 Date: 1/31/2003 4:48:20 PM Type: Highlight ACCEPT - DONE (per phy WG) 5.7.2 General interface specification Change "interoperability" to "compliance" Page: 72 Sequence number: 5 Date: 1/31/2003 4:48:25 PM Type: Highlight ACCEPT - DONE (per phy WG) 5.7.2 General interface specification Change "conforming" to "compliant" Page: 72 Sequence number: 6 Date: 1/31/2003 4:45:39 PM Type: Highlight ACCEPT - DONE 5.7.1 Compliance points Change "physical definition" to "description" as this is consistent with the column label in Table 33. Page: 77 Sequence number: 3 Date: 1/20/2003 5:44:54 PM Type: Highlight ACCEPT - DONE 5.7.4 Transmitted signal characteristics Table 35 — Transmitted signal characteristics at Tx compliance points

\*\*\* Change 133 to 67 Page: 93 Sequence number: 1 Date: 12/30/2002 1:41:13 PM Type: Circle ACCEPT - DONE 6.4 Bit order Figure 44 — SAS bit transmission logic Correct figure so that 16 is horizontal like the rest of the numbers instead of vertical. Page: 96 Sequence number: 1 Date: 1/8/2003 2:03:38 PM Type: Highlight ACCEPT - DONE (also added cross reference to first use of transmitter, receiver, and state machine, and changed "SAS phy" to "SP" after this) 6.5 Out of band (OOB) signals Change "SP" to "SAS phy (SP)", as this is the first occurence. Page: 97 Sequence number: 4 Date: 1/8/2003 2:07:19 PM Type: Highlight ACCEPT - DONE 6.5 Out of band (OOB) signals This is more clear if the two cases are put in the opposite order and "then" should be "than". Replace the highlighted text with: "A receiver shall not detect the same OOB signal again until it has detected lack of transitions for a time greater than the proceeding idle time (i.e., a COMINIT negation time for a COMINIT idle time or a COMSAS negation time for a COMSAS idle time) or has detected a different OOB signal (e.g., if the idle time changes). Page: 98 Sequence number: 2 Date: 1/8/2003 2:09:55 PM Type: Highlight ACCEPT - DONE 6.5 Out of band (OOB) signals Change "SAS phy (SP)" to "SP" Page: 98 Sequence number: 3 Date: 1/8/2003 2:27:28 PM Type: Circle ACCEPT - DONE 6.5 Out of band (OOB) signals Figure 47 — OOB signal detection Bracket 6 is o the wrong side of the burst. It should be at the trailing edge instead of the leading edge. Page: 100 Sequence number: 4 Date: 1/8/2003 3:00:09 PM Type: Strikeout ACCEPT - DONE 6.6.3 SAS to SATA phy reset sequence This does not have to be a "legacy" device. Page: 106 Sequence number: 2 Date: 1/8/2003 6:22:01 PM Type: Highlight REFER PHYSICAL WG (made the change, but perhaps these two sentences need better wording overall) 6.6.5 Phy reset sequence after device is attached GEnder is wrong. Change "into a receptacle." to "onto a plug." Page: 106 Sequence number: 3 Date: 1/9/2003 4:38:19 PM

Type: Highlight

REJECT (a phy does not ignore incoming COMINITs while waiting through its hot-plug timeout) 6.6.5 Phy reset sequence after device is attached This explanation needs additional detail to be clear. Make the following changes to the text by adding additional information and delting "after the attachment". In this example, SAS phy B is attached to SAS phy A some time before SAS phy B's second hot-plug timeout occurs, but while SAS phy A is still in a hot-plug timeout and unable to detect a valid COMINIT from SAS phy B. SAS phy A completes its hot-plug timeout and transmits COMINIT. SAS phy B's OOB detection circuitry detects a COMINIT, ... Page: 107 Sequence number: 3 Date: 1/24/2003 4:37:02 PM Type: Highlight ACCEPT - DONE (the labels are broken; "Rx" on the left is not true until time y... I don't think it matters if A is attached to B or B is attached to A. Tx and Rx lines separated.) 6.6.5 Phy reset sequence after device is attached Figure 55 — Hot-plug and the phy reset sequence Change "SAS phy A attached to SAS phy B" to "SAS phy B attached to SAS phy A. Phy A and Phy B Rx signals are not present until this time." Page: 107 Sequence number: 4 Date: 1/24/2003 4:42:17 PM Type: Circle **REVIEW PROTOCOL WG** ACCEPT - DONE 6.6.5 Phy reset sequence after device is attached Figure 55 — Hot-plug and the phy reset sequence The "Time y" arrowhead should be on the other side of the squiggle to have the event illustrated later in the timing sequence. Page: 321 Sequence number: 1 Date: 12/30/2002 10:14:14 AM Type: Highlight ACCEPT - DONE A.1 Compliant jitter test pattern (CJTPAT) Case of the next to the last character is incorrect. 35B5A9Edh should be 35B5A9EDh Page: 322 Sequence number: 1 Date: 12/30/2002 10:14:40 AM Type: Highlight ACCEPT - DONE A.1 Compliant jitter test pattern (CJTPAT) Case of the next to the last character is incorrect. 8CF328Eah should be 8CF328EAh Page: 323 Sequence number: 1 Date: 12/30/2002 10:16:34 AM Type: Highlight ACCEPT - DONE A.1 Compliant jitter test pattern (CJTPAT) Case of the next to the last character is incorrect. AFF087Ebh should be AFF087EBh Page: 323 Sequence number: 2 Date: 12/30/2002 10:16:29 AM Type: Highlight ACCEPT - DONE A.1 Compliant jitter test pattern (CJTPAT) Case of the next to the last character is incorrect. E21035Efh should be E21035EFh

## Author: SEG Coomesj

Page: ix Sequence number: 3 Date: 12/30/2002 10:42:45 AM Type: Highlight ACCEPT - DONE 1.19 Revision sas-r02c (21 November 2002) "sas-r02c" s.b. "sas-r03" Page: 11 Sequence number: 6 Date: 2/8/2003 10:20:10 AM Type: Highlight ACCEPT - DONE Global: To be compatible with ATA terminology STP initiator port s.b. STP host port Page: 11 Sequence number: 7 Date: 2/8/2003 10:20:03 AM Type: Highlight ACCEPT - DONE Global: To be compatible with ATA terminology STP target port s.b. STP device port Page: 13 Sequence number: 2 Date: 2/9/2003 12:17:36 PM Type: Strikeout ACCEPT - DONE (drop the - 3) 3.2 Symbols and abbreviations The - 3 in the abbreviation for SCSI s.b. dropped to be consistent with 1 Scope. Page: 21 Sequence number: 7 Date: 1/23/2003 3:16:43 PM Type: Highlight ACCEPT - DONE (reword to: This creates a wide link if more than two phys are so attached or a narrow link if only two phys are so attached.) 4.1.3 Ports (narrow ports and wide ports) Change: are To: is Page: 30 Sequence number: 8 Date: 1/25/2003 11:03:34 AM Type: Highlight ACCEPT - DONE 4.1.11 Connections Change: to To: the Page: 88 Sequence number: 1 Date: 12/30/2002 11:18:32 AM Type: Highlight ACCEPT - DONE 6.3.3.1 Definitions Change: an primitive To: a primitive

Page: 97 Sequence number: 3 Date: 1/8/2003 2:07:27 PM Type: Highlight ACCEPT - DONE 6.5 Out of band (OOB) signals Change: proceeding To: preceding Page: 101 Sequence number: 2 Date: 1/8/2003 5:40:30 PM Type: Highlight ACCEPT - DONE (reworded if phrases to the front of each of a) and b)) 6.6.4.1 SAS OOB sequence Change: COMSAS, To: COMINIT; Page: 102 Sequence number: 2 Date: 1/21/2003 12:59:52 PM Type: Highlight ACCEPT - DONE (with arrow from A's COMINIT not B's COMINIT to B's COMSAS) 6.5 Out of band (OOB) signals Figure 51Scenario 2: The figure shows a sequence, COMINIT from B to COMSAS from A to COMSAS from B. By definition, B may send its COMSAS after sending and receiveing COMINIT. B may send COMSAS even if it does not receive a COMSAS from A. The figure should be changed: Remove the arrow from A's COMSAS to B's COMSAS and add an arrow form B's COMINIT to B's COMSAS. Page: 102 Sequence number: 3 Date: 1/9/2003 3:25:10 PM Type: Highlight ACCEPT - DONE (a different scenario 3 is needed) 6.5 Out of band (OOB) signals Figure 51Scenario 3: This scenario is not very interesting. It is just a flip of senario 2. Delete? Page: 104 Sequence number: 2 Date: 1/24/2003 3:48:26 PM Type: Highlight ACCEPT - TODO (this is really a minimum not a maximum; should it be absolute or based on UI(OOB)?) SATA uses both 440 and 880 for this value. Question sent to Knut about which is correct. Might call it "Await ALIGN Timeout". 6.6.4.2 SAS speed negotiation sequence, Table 49 — SAS speed. . The value of ALIGN detect timeout maximum needs a tolerance. A minimum value is also required. The current requirement would allow a phy to not wait. Page: 104 Sequence number: 3 Date: 1/8/2003 1:57:08 PM Type: Highlight ACCEPT - DONE (deleted note a) 6.6.4.2 SAS speed negotiation sequence, Table 49 - SAS speed. . Note "a" is not referenced in the table. Page: 121 Sequence number: 1 Date: 2/9/2003 12:17:53 PM Type: Highlight REJECT (fix in SAS-2 perhaps) 6.9 SAS phy dword synchronization (SP\_DWS) state machine The DWS state machine starts with a state 0. Other state machines start with state 1.

Page: 131

Sequence number: 1 Date: 1/28/2003 9:43:50 AM Type: Highlight **REJECT (Jan WG)** 7.1.2 Primitive summary, Table 54 It would be better if the 2nd character of the CLS primitives were unique from BREAK, ERROR, and HARD\_RESET. Since there are multiple CLS primitives, the 3rd and 4th characters will be used to distinguish the types. It would be simpler for the hardware if the 2nd character for CLS (D02.0) was unique from the other primitives. Page: 131 Sequence number: 2 Date: 1/24/2003 6:37:21 PM Type: Highlight REJECT (Jan WG - too many OPEN\_REJECTs to fit in one set of encodings) 7.1.2 Primitive summary, Table 54 It would be better if the 2nd character of the OPEN\_REJECT primitives were the same rather than D31.4 and D29.7. Page: 133 Sequence number: 1 Date: 1/24/2003 6:38:43 PM Type: Highlight **REJECT** (Jan WG) 7.1.2 Primitive summary, Table 55 It would be better if the 2nd character of the NAK primitives were unique from ACK, CREDIT\_BLOCKED, and RRDY. Since there are multiple NAK primitives, the 3rd and 4th characters will be used to distinguish the types. It would be simpler for the hardware if the 2nd character for CLS was unique from the other primitives. Page: 143 Sequence number: 5 Date: 1/6/2003 1:46:31 PM Type: Highlight ACCEPT - DONE (with transmitting not originating) 7.2 Clock skew management Change: "devices" to: "originating devices" Page: 144 Sequence number: 3 Date: 12/30/2002 11:25:07 AM Type: Highlight ACCEPT - DONE 7.4.1 CRC Overview 3rd paragraph "Annex B contains. . . " s.b. "Annex C contains. . ." Page: 145 Sequence number: 2 Date: 1/6/2003 1:58:13 PM Type: Highlight REJECT - such an "initial value" assumes a certain implementation. This section has generic equations which do assume any implementation. 7.4.2 CRC generation Add a subclause: 7.4.x CRC initial value The CRC value shall be initialized with a value of FFFFFFFh before the calculation begins. Page: 147 Sequence number: 8 Date: 1/25/2003 11:09:12 AM Type: Highlight ACCEPT - DONE (Replace paragraph and table with: The polynomial shall be applied to the lower 16 bits of the 32-bit dword being transmitted or received first; the polynomial is then applied to the upper 16 bits. See 7.6 for details on how ... Move the STP bit ordering figures into 7.6 from the informative annex. Move the STP CRC figure into 7.x too.) 7.5 Scrambling There is no endianness to the scrambling process. Scrambling operates on the parallel 32 bits of a dword. Both SAS and SATA process the bits of a dword without regard to the byte significates the same way, lower 16 bits followed by the upper 16 bits. Delete this sentence and Table 69- Scrambling endianness.

Page: 147 Sequence number: 9 Date: 1/6/2003 2:02:50 PM Type: Highlight ACCEPT - DONE (removed paragraph) 7.4.3 CRC Checking "Annex B contains. . . " sb "Annex C contains. . ." Page: 147 Sequence number: 10 Date: 1/25/2003 11:09:42 AM Type: Highlight ACCEPT - DONE (Jan WG: accept without the e.g.) 7.5 Scrambling Srambling works for all repeating patterns. Change: long strings of zeros or ones To: long strings of repeating patterns, e.g., all zeros and ones, Page: 147 Sequence number: 11 Date: 1/6/2003 2:05:16 PM Type: Highlight ACCEPT - DONE (deleted entire i.e. since it's hard to describe all the cases) 7.5 Scrambling change (i.e., between frames), to: (i.e., between frames and not seding primitives) Page: 147 Sequence number: 12 Date: 1/17/2003 11:13:39 AM Type: Highlight REFER PROTOCOL WG (Jim Coomes will investigate how to word this in mathematical equations) 7.5 Scrambling The initialize value is determined by the scrambler implementation, serial or parallel. Also, a clarification: Change to: The data scrambling value shall be initialized at each SOF, SOAF, and SATA SOF by both the transmitter and receiver. The data being transmitted shall be XORed with the data scrambling value by the transmitter, and the data being received shall be XORed with the data scrambling value by the receiver. The initial value is selected to produce the required scrambling value for the first value following a reset, e.g., any SOF or device reset (see Annex E). For a given dword displacement from the last data scrambling value reset, the data scrambling value is the same. Page: 153 Sequence number: 1 Date: 1/21/2003 1:14:19 PM Type: Highlight ACCEPT - TODO (in 4.1.11 Connections, add an introduction to connection rate and include this rule with Jim's comment. Point to 4.1.11 from here and from 7.15 Rate matching). 7.7.3 OPEN address frame for clarification add: This support may use rate matching. Page: 154 Sequence number: 3 Date: 1/24/2003 7:30:46 PM Type: Highlight ACCEPT - DONE (keep this wording. Make a table with 0000, 7FFF, 8000, maybe 8001h, and FFFFh values in it.. Check rest of document for SCALE bit and AWT field references.) 7.7.3 OPEN address frame The concept of the scale bit is confusing to implementors. Suggest dropping the scale bit and describing the behavior of a 16 bit AWT by range: The ARBITRATION WAIT TIME field indicates how long the port transmitting the OPEN address frame has been waiting for a

connection request to be accepted. For values from 0000h to 7FFFh the AWT increments in 1 usec steps. For values from 8000h to FFFFh the AWT increments in 1 msec steps. The maximum value represents 32 767 ms + 32 768 µs. Also, delete table 77, the scale bit in table 74.

Page: 155 Sequence number: 6 Date: 12/30/2002 10:06:33 AM Type: Highlight 7.8.3 Fanout expander device specific rules The identify sequence completes of a port by port basis and there is no global indication of when it complete for all ports on the expander. Suggest: "After completing the identify sequence on a port, the expander connection manager within a fanout expander device shall be capable of processing connection requests from the attached device on the port. The connection manager may return OPEN\_REJECT (NO DESTINATION) if configuration is not complete." Page: 155 Sequence number: 7 Date: 12/30/2002 10:06:33 AM Type: Highlight 7.8.4 Edge expander device specific rules same comment as for 7.8.3 - The identify sequence completes of a port by port basis and there is no global indication of when it complete for all ports on the expander. Suggest: "After completing the identify sequence on a port, the expander connection manager within a edge expander device shall be capable of processing connection requests from the attached device on the port. The connection manager may return OPEN\_REJECT (NO DESTINATION) if configuration is not complete." Page: 161 Sequence number: 6 Date: 1/21/2003 1:39:22 PM Type: Highlight REJECT (Jan WG removed NEA altogether) 7.10 Near-end analog loopback test Targets should be allowed to perform loopback also. change to: "This test mode may be invoked in initiator or target devices using vendor-specific means." also add a paragraph: "Once the test is completed in a target device, the target phy shall start a phy reset sequence." Page: 163 Sequence number: 12 Date: 12/30/2002 10:06:33 AM Type: Highlight 7.12.2.2 Connection request responses The OPEN may require a rate match that is not support by the receptient. Add: "if the requested connection rate is supported." Page: 163 Sequence number: 13 Date: 1/25/2003 11:10:22 AM Type: Highlight ACCEPT - DONE (make it required for everyone) 7.12.3 Arbitration fairness may should be shall. Optional implementation may/will lead to non-interoperable devices. Also if optional, the behavior has to be described in the rest of the document. Page: 163 Sequence number: 14 Date: 1/25/2003 11:32:37 AM Type: Highlight ACCEPT - DONE (but weakened the shall set to zero since unfairness is allowed) 7.12.3 Arbitration fairness The AWT has to be mandatory. Chnane to: Initiator ports and target ports shall set the arbitration wait timer to zero for fair operation and start the timer when they transmit the first OPEN address frame for the connection request.

Sequence number: 15 Date: 12/30/2002 10:06:33 AM Type: Highlight 7.12.3 Arbitration fairness This is duplicated in 7.7.3. Delete here. The arbitration wait timer shall count in microseconds from 0 µs to 32 767 µs and in milliseconds from 32 768 µs to 32 767 ms + 32 768 µs. Page: 163 Sequence number: 16 Date: 1/25/2003 11:34:04 AM Type: Highlight ACCEPT - DONE (but as >= 8000h rather than > 7FFFh) 7.12.3 Arbitration fairness In conjunction with a comment in 7.7.3 to rmove the scale bit: Change to: However, unfair ports shall not set the ARBITRATION WAIT TIME field to a value greater than 7FFFh; this limits the amount of unfairness and helps prevent livelocks. Page: 163 Sequence number: 17 Date: 1/25/2003 11:38:00 AM Type: Highlight ACCEPT - DONE (per Jan WG) 7.12.2.2 Connection request responses \*\*\*The retry delay timer greatly complicates selecting another transfer request for a queue. If a request to a different destination has to be selected, a good deal of hardware is required. If done by a processor, the performance would be poor. Suggest deleting the retry delay. If the expander gets congested, buy more capacity. Page: 164 Sequence number: 3 Date: 12/30/2002 10:06:33 AM Type: Highlight 7.12.2.2 Connection request responses change: matching PROTOCOL and CONNECTION RATE fields. to: a matching PROTOCOL field and a supported connection rate. Page: 164 Sequence number: 4 Date: 1/25/2003 11:41:05 AM Type: Highlight ACCEPT - DONE 7.12.3 Arbitration fairness Change: the timer To: The arbitration wait timer Page: 164 Sequence number: 5 Date: 12/30/2002 10:06:33 AM Type: Highlight 7.12.3.1.1 Arbitration overview This subclause uses "primitive" in a different meaning than the rest of the draft. Also, it is an overview and should not present the attribute/confirmation details. Suggest a rewrite to: The expander connection manager shall arbitrate and assign or deny path resources for connection attempts requested by each expander phy in response to receiving valid OPEN address frames. Arbitration includes adherence to the SAS arbitration fairness algorithm and path recovery. Path recovery is used to avoid potential deadlock scenarios within the SAS topology by deterministically choosing which partial pathway(s) to tear down to allow at least one connection to complete. The expander connection manager responds to connection request with arbitration won, lost, and reject to the requesting phy. Each path request contains the Arbitration Wait Time and the Source SAS Address arguments from the received OPEN address frame. If two path requests contend, the winner shall be determined by comparing OPEN address frame field values in this order: 1) largest Arbitration Wait Time; 2) largest Source SAS Address; and 3) largest Connection Rate.

The expander connection shall generate the arbitration reject response when any of the following conditions are met:

a) the request does not map to a valid phy;

b) the request specifies an unsupported connection rate; or

c) the request specifies a destination port which contains at least one partial pathway and pathway recovery rules require this connection request to release path resources.

When two phys receive an OPEN address frame destined for each other, the expander connection manager shall provide an arbitration lost response to the phy that received the lowest priority OPEN address frame when all of the following conditions are met:

a) the request is for an available phy at a supported connection rate; and

b) the destination phy of this connection request has received a higher priority OPEN address frame with this phy as its destination. The expander connection manager shall generate the arbitration won response when all of the following conditions are met:

a) the request maps to an available phy at a supported connection rate: and

b) no higher priority connection requests are present with this phy as the destination.

Page: 164 Sequence number: 6 Date: 12/30/2002 10:06:33 AM Type: Highlight 7.12.3 Arbitration fairness The AWT is not reset on OPEN\_REJECT (PATHWAY BLOCKED). This appears to be the only exception to reseting the timer. Add: (except OPEN\_REJECT (PATHWAY BLOCKED)) Page: 164 Sequence number: 7 Date: 12/30/2002 10:06:33 AM Type: Highlight 7.12.3.1.1 Arbitration overview Why is largest Connection Rate used for compare? Does this mean that AWT and Source SAS address are the same? Page: 165 Sequence number: 2 Date: 1/25/2003 11:43:28 AM Type: Highlight ACCEPT - DONE 7.12.3.1.2 Arbitration status Change: value To: type Page: 170 Sequence number: 1 Date: 1/25/2003 11:46:34 AM Type: Highlight REJECT 7.13 SAS link layer state machine for initiator phys and target phys (SL) The SL state machine starts with 0 state. Most others start with 1. Page: 186 Sequence number: 1 Date: 1/10/2003 11:23:43 AM Type: Highlight ACCEPT - DONE 7.14.6.1 State description Spelling: Thist should be "This" Page: 190 Sequence number: 2 Date: 2/4/2003 6:30:01 PM Type: Highlight ACCEPT - DONE 7.15 Rate matching The termination of inserting ALIGNs is not covered. Add a sentence: The source shall stop inserting ALIGNs for rate matching with the first dword of CLOSE.

Page: 191 Sequence number: 1 Date: 12/30/2002 10:06:33 AM Type: Strikeout 7.16.3 SSP frame transmission Delete: NAK means the frame was received with an error; NAK (CRC ERROR) is the only defined NAK. Page: 207 Sequence number: 3 Date: 12/30/2002 10:06:33 AM Type: Highlight 7.17.3 Preparing to close an STP connection Change: detected, after To: detected or after Page: 209 Sequence number: 1 Date: 2/1/2003 4:35:36 PM Type: Highlight ACCEPT - DONE (can do in this picture by just making it square. Trouble for some other pictures though.) 7.18.4.1 Overview, Table 88 Round corners of white box to match format of other state machines Page: 214 Sequence number: 4 Date: 1/17/2003 12:36:08 PM Type: Highlight ACCEPT - TODO 8.2.2 Bus inactivity time limit timer This timer is optional by definition in SCSI. Add text: Support for the bus inactivity timer is optional. The Disconnect-Reconnect mode page may be accessed to determine support for this timer. When this timer is not supported, the bus inactivity timer shall not be treated as expired in this standard. Page: 214 Sequence number: 5 Date: 1/17/2003 12:36:17 PM Type: Highlight ACCEPT - TODO 8.2.3 Maximum connect time limit timer Add text: Support for the maximum connect time limit timer is optional. The Disconnect-Reconnect mode page may be accessed to determine support for this timer. When this timer is not support, the maximum connect time limit timer shall not be treated as expired in this standard. Page: 214 Sequence number: 6 Date: 1/17/2003 12:36:24 PM Type: Highlight ACCEPT - TODO 8.2.4 I\_T nexus loss timer Add text: Support for the I\_T nexus loss timer is optional. The Protocol-Specific Port mode page may be accessed to determine support for this timer see 10.1.6.2. When this timer is not support, the I\_T nexus loss timer shall not be treated as expired in this standard. Page: 215 Sequence number: 3 Date: 1/17/2003 12:43:02 PM Type: Highlight ACCEPT - TODO 8.2.5 Arbitration wait time (AWT) timer Add a sentence: Support of the AWT is mandatory. Page: 215 Sequence number: 4 Date: 1/17/2003 12:43:10 PM Type: Highlight

ACCEPT - TODO 8.2.6 Pathway blocked count (PBC) counter Add a sentence: Support of the PBC is mandatory. Page: 226 Sequence number: 11 Date: 12/30/2002 10:06:33 AM Type: Highlight 8.4.4.1 State description second to last paragraph The shall in the following sentence is misleading for an optional timer. the bus inactivity time limit timer shall be initialized suggest: the bus inactivity time limit timer if supported shall be initialized Page: 226 Sequence number: 12 Date: 12/30/2002 10:06:33 AM Type: Highlight 8.4.4.1 State description last paragraph The shall in the following sentence is misleading for an optional timer. the maximum connect time timer shall be initialized suggest: initialized the maximum connect time timer if supported shall be initialized Page: 229 Sequence number: 5 Date: 1/22/2003 6:14:07 PM Type: Highlight ACCEPT - DONE (it's the bit mislabeled TIMEOUT in the table) 9.2.1 SSP frame format The RETRANSMIT bit is in the text but not in Table 88. Is the function out? Page: 230 Sequence number: 4 Date: 2/8/2003 12:32:02 PM Type: Strikeout ACCEPT - DONE (moved most of the definition to 9.2.2.4 and put xrefs here to there and there to here. Deleted the redundant sentence.) 9.2.1 SSP frame format Delete. This sentence is redundant with the last paragragh in 9.2.2.4 DATA information unit. Page: 233 Sequence number: 3 Date: 1/6/2003 11:07:59 AM Type: Highlight ACCEPT - DONE (see IBM comment) 9.2.2.3 XFER\_RDY information unit - Table 94 — XFER\_RDY information unit The use of the same field name, RELATIVE OFFSET, in the header and XFR\_RDY is confusing. Suggest: XFR\_RDY\_OFFSET, REQUEST\_OFFSET, STARTING\_OFFSET, etc. **RELATIVE OFFSET** Page: 233 Sequence number: 4 Date: 12/30/2002 1:23:06 PM Type: Highlight ACCEPT - DONE 9.2.2.3 XFER\_RDY information unit reference to 10.1.1.1.5 should be 10.1.6.1.5 Page: 233 Sequence number: 5 Date: 12/30/2002 1:22:58 PM

Type: Highlight ACCEPT - DONE 9.2.2.3 XFER\_RDY information unit reference to 10.1.1.1.5 should be 10.1.6.1.5 Page: 234 Sequence number: 1 Date: 1/6/2003 11:18:03 AM Type: Strikeout ACCEPT - DONE 9.2.2.4 DATA information unit Delete: This sentence is redundant with the first paragraph on the page. Page: 239 Sequence number: 1 Date: 1/22/2003 6:41:57 PM Type: Strikeout REJECT - that is indeed the intention. There are no more frame transmissions allowed if ACK or NAK are not balanced. 9.2.4.1 COMMAND frame Delete: in the next connection This would mean the initiator would have to shutdown any queued transfer request to satisfy the next connection requirement. Page: 260 Sequence number: 3 Date: 12/30/2002 1:20:37 PM Type: Highlight ACCEPT - DONE 9.4.2 SMP\_REQUEST frame Why is this not 1 024? Page: 261 Sequence number: 4 Date: 12/30/2002 1:21:02 PM Type: Highlight ACCEPT - DONE 9.4.3 SMP\_RESPONSE frame Why is this not 1 024? Page: 263 Sequence number: 3 Date: 1/30/2003 5:35:19 PM Type: Highlight ACCEPT - DONE (removed here, and mentioned later in Transmit Frame () call that it must be set to FFFFh) 9.4.4.2.2.2 Transition MT ID1:Idle to MT ID2:Send Why is the initiator connection tag included when the SMP transfer is interlocked? Page: 287 Sequence number: 5 Date: 1/30/2003 12:38:18 PM Type: Highlight REJECT 10.1.8 SCSI power condition states SA\_PC state machine numbering is not consistent with other state machines. SA\_PC state machine start with "0", others start with "1". Page: 305 Sequence number: 4 Date: 1/25/2003 5:18:06 PM Type: Highlight REFER PROTOCOL WG (I hate to put a state machine reference crossing all the layers here...) 10.3.1.5 REPORT PHY ERROR LOG function The meaning of "outside of phy reset sequences" is not specific. Suggest substituting: "while PhyReady is valid from the SP state machine" each counter in this clause to be more specific.

Page: 324 Sequence number: 5 Date: 12/30/2002 10:19:02 AM Type: Highlight ACCEPT - DONE B.1 SAS phy reset sequence examples Figure A.1 S.B. Figure B.1 Page: 324 Sequence number: 6 Date: 12/30/2002 1:18:07 PM Type: Highlight ACCEPT - DONE B.1 SAS phy reset sequence examples Figure A.2 S.B. Figure B.2 Page: 327 Sequence number: 1 Date: 12/30/2002 2:20:21 PM Type: Highlight ACCEPT - DONE C.3 CRC implementation with XORs Change: These equations generate the 32 bit CRC for frame transmission. To: These equations generate the multiplier function shown in figures C.1 and C.2. Page: 339 Sequence number: 1 Date: 12/30/2002 10:25:08 AM Type: Highlight ACCEPT - DONE F.1 STP differences from SATA Add: h) BIST activated frames not supported. Page: 341 Sequence number: 1 Date: 12/30/2002 1:08:59 PM Type: Highlight ACCEPT - DONE F.3 Byte and bit ordering, Figure F2 change byte order to: (4th : 3rd : 2nd : 1st) to match Figure F.3 Page: 341 Sequence number: 2 Date: 12/30/2002 1:09:06 PM Type: Highlight ACCEPT - DONE F.3 Byte and bit ordering, Figure F2 change byte order to: (1st: 2nd: 3rd: 4th) to match Figure F.3 Page: 343 Sequence number: 1 Date: 12/30/2002 10:29:24 AM Type: Highlight ACCEPT - DONE G.1 Overview, Table G.1 For completeness, continue table to include representations for PHYs W & Z...should be a cut-and-paste of what's there with a replacement of X->W and Y->Z plus device A -> C and B->D.

Page: 345 Sequence number: 1 Date: 12/30/2002 10:37:23 AM Type: Highlight ACCEPT - DONE (in table G.1 instead of here) G.2 Connection request - Open accept, Figure G.2 Add reference Fig 26 and Fig 27 to help the reader understand how to interpret req/rsp and cnf/ind columns in the figures.

Page: 371 Sequence number: 1 Date: 12/30/2002 10:39:18 AM Type: Highlight ACCEPT - DONE I.3 Source file Should: header file Be: code file

## Author: SEG houlderg

Page: 6 Sequence number: 8 Date: 1/22/2003 9:49:56 AM Type: Strikeout ACCEPT - DONE (delete it. That will mean no special meaning) 3.1.25 device: A physical entity. Delete this definition of device. SAM-x, SPC-x, SPI-x, etc. have gotten along fine without defining device even though they all use the word hundreds of times. The given definition is so broad that it isn't helpful anyway.

Page: 6 Sequence number: 9 Date: 2/6/2003 1:42:35 PM

Type: Highlight ACCEPT - DONE Synonymous with SAS domain. The definition for domain should be more general purpose because several types of domains are referred to in SAS. Use the definition of domain from SAM-2 -- "An I/O system consisting of a set of devices that interact with one another by means of a service delivery subsystem" with the acronym SCSI removed so the definition can be applied to "ATA domain" which also appears in this draft.
Page: 7 Sequence number: 7 Date: 1/7/2003 2:23:48 PM
Type: Highlight ACCEPT - DONE expander connection router (ER): Change ER to ECR to be consistent withother references to this item.

Page: 8 Sequence number: 8 Date: 12/30/2002 10:06:45 AM Type: Highlight Synonymous with This is not accurate or useful. use the generic "initiator device" description here (which can also be applied to ATA initiator device) and change "SAS initiator device" to "an initiator device in SAS domain". Page: 8 Sequence number: 9 Date: 12/30/2002 10:06:45 AM Type: Highlight Synonymous with This is not accurate or useful. use the generic "initiator port" description here (which can also be applied to ATA initiator port) and change "SAS initiator port" to "an initiator port in SAS domain".

Page: 9 Sequence number: 9 Date: 1/7/2003 2:42:42 PM Type: Highlight REJECT - this is the correct direction higher layer state machine to a lower layer This wording is identical to "request" definition !! I think you mean "lower layer state machine to higher layer" Page: 10 Sequence number: 5 Date: 1/7/2003 2:56:08 PM Type: Highlight REJECT - it's referring to the SATA document defined by SATA. replace with "protocol defined by SATA industry group". Page: 11 Sequence number: 4 Date: 12/30/2002 10:06:45 AM Type: Highlight Synonymous with This is not accurate or useful. use the generic "target device" description here (which can also be applied to ATA target device) and change "SAS target device" to "a target device in SAS domain". Page: 11 Sequence number: 5 Date: 12/30/2002 10:06:45 AM Type: Highlight Synonymous with This is not accurate or useful. use the generic "target port" description here (which can also be applied to ATA target port) and change "SAS target port" to "a target port in SAS domain". Page: 13 Sequence number: 1 Date: 12/30/2002 11:04:37 AM Type: Highlight ACCEPT - DONE (also fixed millivolt and nanofarad) millisecond (10-6 seconds) Should be 10-3 seconds. Page: 14 Sequence number: 1 Date: 12/30/2002 1:43:39 PM Type: Highlight ACCEPT - DONE not:: remove the extra : after the word not. Page: 15 Sequence number: 3 Date: 12/30/2002 11:08:07 AM Type: Strikeout ACCEPT - DONE Fields containing only one bit are usually referred to as the name bit instead of the name field. Remove this sentence - it is redundant with sentence 2 paragraphs earlier (paragraph starting with "Names of fields are .."). Page: 21 Sequence number: 4 Date: 1/23/2003 3:27:39 PM Type: Highlight ACCEPT - DONE (added "8b10b coding" to definitions) 8b10b coded This term should be defined in definitions clause (3.1). Page: 21 Sequence number: 5 Date: 1/23/2003 3:18:37 PM Type: Highlight REJECT (the attached phys might have the same SAS address in a physical loopback configuration, so "different" is not necessarily true. Note 6 describes that scenario.) 4.1.3 Ports Replace "a SAS" with " a different SAS".

Page: 27 Sequence number: 1 Date: 1/23/2003 4:28:36 PM Type: Highlight ACCEPT - DONE (new "bridge" object created as requested; paragraph deleted, new picture added including bridge) 4.1.9 Domains are not required to Change to "do not". I contend that something that translates SSP to SATA is a bridge device, not an expander. Page: 29 Sequence number: 1 Date: 1/23/2003 4:42:05 PM Type: Note ACCEPT - DONE (added note that the top edge expander devices are using subtractive routing to each other) Should there be more rules to define an "edge expander device set"? For instance, it is not clear to me why this group of 6 edge expander devices is considered to be two edge expander device sets instead of one edge expander device set. I'm sure there must be a way to connect the 6 edge expander devices so that they are considered to be one expander device set. Page: 30 Sequence number: 6 Date: 1/23/2003 5:07:20 PM Type: Highlight ACCEPT - DONE (overcome by rewrite) port(s); change to "port(s) using SSP;". Page: 30 Sequence number: 7 Date: 1/23/2003 5:06:54 PM Type: Highlight ACCEPT - DONE (list removed; generic SSP, STP, and SMP references put in place) Should an example d) be added to describe a SCSI initiator port to expander port(s) using SMP? If this is inperpreted as a complete list of allowed connection types, the example must be added. Page: 69 Sequence number: 2 Date: 1/31/2003 4:22:23 PM Type: Highlight REJECT (per PHY WG Reject. Table 31 is sufficient reference.) 5.3.6 SAS external cable plug connector Table 31 defines change to "Table 31 in clause 5.3.8 defines ..." for clarity. Change both occurrances on this page. Page: 70 Sequence number: 1 Date: 2/9/2003 11:20:19 AM Type: Highlight ACCEPT - DONE itnernal spelling should be "internal". Page: 71 Sequence number: 11 Date: 1/20/2003 4:32:59 PM Type: Highlight ACCEPT - DONE The LED and the current limiting resistor may be external to the target device. \*\*\*Change this to read " The LED and the current limiting circuitry shall be external to the target device." The standard must definitely state where the current limiting circuirty and the LED are located. Page: 72 Sequence number: 2 Date: 1/20/2003 4:54:17 PM Type: Highlight ACCEPT - DONE (changed to "exceed") operate within \*\*\*Change to "meet". The word within is ambiguous.

Page: 72 Sequence number: 3 Date: 12/30/2002 1:42:58 PM Type: Highlight ACCEPT - DONE that Replace with "this". Page: 73 Sequence number: 1 Date: 1/31/2003 4:50:26 PM Type: Note REJECT (per phy WG) Figures 35 and 36 seem out of place here. Should they be moved to the Test Loads clause or somewhere else? Page: 74 Sequence number: 2 Date: 1/31/2003 4:57:37 PM Type: Highlight ACCEPT - DONE (per phy WG) 5.7.3.1 Eye masks overview change to "limits imposed on the signal at that particular compliance point". The added clarification is considered significant by AI Kramer. Page: 79 Sequence number: 1 Date: 1/31/2003 2:58:10 PM Type: Highlight ACCEPT - DONE SAS PHY WG 5.7.7 page 79 Table 38 Accept both Seagate comments but impolement as follows: Combine notes b/d and c/e as suggested but separate the applied frequency ranges to separate footnotes and reference the new footnotes in the columns where they apply. References to b, c, d, and e will now need two reference designators: one for the text and one for the frequency range. 4 notes changed into 6 notes. \*\*\*The requirements of both notes b and d should be worded the same except for the swept frequency range (first sentence of each note). Combining requirements of both should make both notes look like this: The jitter values given are normative for a combination of deterministic jitter, random jitter, and sinusoidal jitter that receivers shall be able to tolerate without exceeding a BER of 10-12. Receivers shall tolerate sinusoidal jitter of progressively greater amplitude at lower frequencies, according to the mask in figure 39 with the same deterministic jitter and random jitter levels as were used in the high frequency sweep. Page: 79 Sequence number: 2 Date: 1/31/2003 2:58:26 PM Type: Highlight ACCEPT - DONE SAS PHY WG 5.7.7 page 79 Table 38 Accept both Seagate comments but impolement as follows: Combine notes b/d and c/e as suggested but separate the applied frequency ranges to separate footnotes and reference the new footnotes in the columns where they apply. References to b, c, d, and e will now need two reference designators: one for the text and one for the frequency range. 4 notes changed into 6 notes. \*\*\*Again the requirements of notes c and e should be combined and applied to both notes: No value is given for random jitter. For compliance with this standard, the actual random itter amplitude shall be the value that brings total itter to the stated value at a probability of 10-12. The additional 0,1 UI of sinusoidal jitter is added to ensure the receiver has sufficient operating margin in the presence of external interference. Page: 97 Sequence number: 2 Date: 12/30/2002 1:42:07 PM Type: Highlight ACCEPT - DONE then

Replace with "than".

Page: 98 Sequence number: 1 Date: 1/8/2003 2:26:01 PM Type: Highlight ACCEPT - DONE (also deleted the references in the SP receiver) COMINIT Completed This transition is defined here, but is not used anywhere in the SP state machine (figure 56, page 133). Why? Page: 106 Sequence number: 1 Date: 1/8/2003 6:20:24 PM Type: Highlight REJECT (Figure 53 shows a G2-only phy B talking to a G1, G2, G3 phy A) The specification is not clear and does not have an example (either here or in Annex B) of a Phy that may only supports G2, but not G1. Thus, the speed negotiation window may be as following: G2 rate, G3 rate, then G2 rate (negotiated rate). Or is this protocol allowed? Page: 107 Sequence number: 1 Date: 1/8/2003 2:26:22 PM Type: Highlight ACCEPT - DONE COMINIT Completed; This parameter is not used anywhere in SP state machine. Page: 109 Sequence number: 4 Date: 1/10/2003 5:05:25 PM Type: Highlight ACCEPT - DONE Figure 56 SP OOB state machine COMSAS Should be "COMINIT". Page: 109 Sequence number: 17 Date: 1/10/2003 5:06:35 PM Type: Note REJECT (we don't show signals to trigger the timers... the state machine just somehow knows how to run them) Figure 56 - SP OOB (split from another comment) SP3:OOB\_AwaitCOMINIT\_Sent state: There is inconsistency between states: in SP1:OOB\_COMINIT state, there is an output "Transmit COMINIT" indicating to the SP transmitter to start transmit COMINIT and wait for COMINIT to be transmitted and/or received. However, this is no output parameter in the SP7:OOB\_AwaitCOMSAS state to start the COMSAS timer, or an output parameter in the SP2:OOB\_AwaitCOMX to start the hotplug timer. Page: 113 Sequence number: 1 Date: 1/11/2003 4:02:43 PM Type: Note REFER PROTOCOL WG (how should be specify sending "idle time" - a Transmit Idle parameter, or just say the SP transmitter does that when not instructed to do anything else?) The descriptions for SP8:SAS\_Start and SP9:SAS\_RateNotSupported indicated that the idle shall be transmitted during these states. Some of the other state are self-explanatory. However, clearly defining whether idle should be transmitted for the SP14:SAS\_Fail or SP13:SAS\_Pass would be helpful. Page: 113 Sequence number: 8 Date: 1/24/2003 6:29:59 PM Type: Note REJECT (per Jan WG; they were zero time states so didn't really represent hardware) Figure 57 - SP SAS state machine (split from another comment) Additionally, the states such as fallback state and inc\_speed states defined in sas\_r02.pdf make the speed negotiation state machine a lot more clear, but these states are removed in the current version. Page: 114 Sequence number: 3 Date: 2/9/2003 12:16:30 PM Type: Highlight ACCEPT - DONE (but when the editor's note is deleted this is moot)

(1) SP19:AwiatALIGN should be SP19:SATA\_AwiatALIGN [in the editor's note]

Page: 114 Sequence number: 29 Date: 1/11/2003 4:03:47 PM Type: Note

[split from another comment]

(2) This editor's note should be incorporated into the speed negotiation state machine. Additionally, this statement is not very clear whether the DWS state machine should be started for the speed negotiation window (G1 rate, G2 rate, G3 rate, G? rate (negotiated rate)), or the DWS state machine should be started only at the negotiated rate window?

## Author: SEG wordenj

Page: 16 Sequence number: 1 Date: 1/7/2003 3:11:46 PM Type: Highlight REFER EDITORS WG (Figures 88 and 89 seem fine. Not sure if uppercase after each \_ is needed in the state name - maybe that's the comment?) 3.5.1 -State Machine Conventions overview Figure 3 - State machine conventions Change <State designator:State name> to "STATE DESIGNATOR: State\_Name" also change SMP state machine names to agree with this (Fig 88, 89) and associated text Page: 16 Sequence number: 2 Date: 1/7/2003 3:12:45 PM Type: Highlight REJECT (the label is a brief description - not an "or") 3.5.2 Transitions change <label, a brief> to "label, or a breif> Page: 21 Sequence number: 6 Date: 1/23/2003 3:18:11 PM Type: Highlight ACCEPT - DONE (it should be 6.2.1 where "dword" is defined) 4.1.2 Physical links and phys change <(see 6.1)> to ??? (the reference is to "dwords" but 6.1 is "Phy layer overview" and not about dwords) Page: 24 Sequence number: 3 Date: 1/22/2003 3:06:57 PM Type: Highlight REJECT (STP target ports are allowed)(whole section being deleted anyway) 4.1.6 Target devices I think this wording <or STP> shouls be deleted, Page: 24 Sequence number: 4 Date: 1/22/2003 3:07:16 PM Type: Highlight REJECT (STP target ports are allowed)(whole section being deleted anyway) 4.1.6 Target devices I think this wording <, and STP target ports> should be deleted Page: 24 Sequence number: 5 Date: 1/22/2003 3:07:29 PM Type: Highlight REJECT (STP target ports are allowed)(whole section being deleted anyway) 4.1.6 Target devices I think this wording < ,STP> should be deleted

Page: 35 Sequence number: 1 Date: 2/9/2003 5:04:29 PM Type: Note ACCEPT - TODO (add a similar picture for expanders and emphasize that this picture is for non-expander devices (SAS devices).) 4.3.1 State machine overview \*\* Figure 19 - State machines Figure 20 - Transmit data path and state machines Figure 23 - STP link STP transport and ATA application layers state machines For the STP paths, these state machines are only valid for the initiator device. Also, the STP transport layer and the STP link layer are not documented in this document, and these lavers are not the same as the SATA defined lavers because they must interface to the SAS port layer in order to get a port assigned for the transmit function. This is a big hole in this document. In addition this figure is not valid for target devices. The target device can only be a SATA device with a SATA link layer (which does not support sending or receiving SAS address frames - which gets you in and out of the SAS link layer (SL)). There is also no port layer in a SATA device. the SATA devices have no concept of ports or SAS addressing. Note: These comments are also applicable to figures 20 and 23. Page: 36 Sequence number: 1 Date: 1/23/2003 6:32:45 PM Type: Note ACCEPT - DONE (crammed in a port layer box) 4.3.2 Transmit data path Figure 20 transmit datat path and state machines This picture should have a port layer box between each transport and link layer box Page: 37 Sequence number: 1 Date: 1/23/2003 6:22:39 PM Type: Highlight ACCEPT - DONE (reworded all three figure intros to mention the port layer) 4.3.2 Transmit data path chnge <link, SSP> to "link, SSP port, SSP" Page: 37 Sequence number: 2 Date: 1/23/2003 6:33:22 PM Type: Highlight ACCEPT - DONE 4.3.2 Transmit data path Figure 21title change <link, SSP> to "link, SSP port, SSP" Page: 38 Sequence number: 1 Date: 1/23/2003 6:33:41 PM Type: Highlight ACCEPT - DONE 4.3.2 Transmit data path chnge <link, SMP> to "link, SMP port, SMP" Page: 38 Sequence number: 2 Date: 1/23/2003 6:33:28 PM Type: Highlight ACCEPT - DONE 4.3.2 Transmit data path Figure 22title change <link, SMP> to "link, SMP port, SMP" Page: 38 Sequence number: 3 Date: 1/7/2003 6:20:44 PM Type: Note

REJECT (DONE is not used in SMP connections) 4.3.2 Transmit data path figure 22 SMP link, SMP transprt ... Should't there be a "DONE" box and line like in figure 21 ??? Page: 39 Sequence number: 2 Date: 1/23/2003 6:33:46 PM Type: Highlight ACCEPT - DONE 4.3.2 Transmit data path chnae <link. STP> to "link, STP port, STP" Page: 39 Sequence number: 3 Date: 1/23/2003 6:33:34 PM Type: Highlight ACCEPT - DONE 4.3.2 Transmit data path Figure 23title change <link, STP> to "link, STP port, STP" Page: 39 Sequence number: 4 Date: 1/23/2003 6:35:31 PM Type: Note REJECT (this is valid for an STP target too. True it is not describing a pure SATA target + a STP/SATA bridge - but that combination should end up with a result that equals this) 4.3.2 Transmit data path Figure 23 - STP link, STP transport and ATA application layer state machines Only valid for initiator layer. Figure 23 states that the STP transport and link layer state machines are "based" on the SATA state machines but are not documented - especially on how they interface to the port layer . This figure doesn't really agree with figure 19 - State machines Page: 42 Sequence number: 1 Date: 2/9/2003 5:20:42 PM Type: Note ACCEPT - DONE 4.3.3.1 Signals between phy layer and other layers Table 13 — Confirmations between SSP link layer, port layer, and SSP transport layer add "ACK Transmitted" as a confirmation from the link to the port layer and from the port to the transport layer. Page: 43 Sequence number: 1 Date: 2/3/2003 3:39:24 PM Type: Strikeout ACCEPT - DONE 4.3.3.3 Signals between link layer, port layer, and transport layer for SMP Table 15 — Confirmations between link layer, port layer, and SMP transport layer remove <Connection Opened (SMP,Source Opened)> (this signal is repeated in Table 16 - Confirmations between link layer and port layer Page: 43 Sequence number: 2 Date: 2/3/2003 3:39:29 PM Type: Strikeout ACCEPT - DONE 4.3.3.3 Signals between link layer, port layer, and transport layer for SMP Table 15 — Confirmations between link layer, port layer, and SMP transport layer remove <Connection Closed (Close Timeout)> (this signal is repeated in Table 16 — Confirmations between link layer and port layer Page: 43

Sequence number: 3 Date: 2/4/2003 11:19:50 AM Type: Strikeout

ACCEPT - DONE 4.3.3.3 Signals between link layer, port layer, and transport layer for SMP Table 15 — Confirmations between link layer, port layer, and SMP transport layer remove <Connection Closed (Close Timeout)> (this signal is repeated in Table 16 - Confirmations between link layer and port layer Page: 43 Sequence number: 4 Date: 12/30/2002 10:06:53 AM Type: Strikeout Timeout) Page: 43 Sequence number: 5 Date: 2/4/2003 11:18:21 AM Type: Strikeout ACCEPT - DONE 4.3.3.3 Signals between link layer, port layer, and transport layer for SMP Table 15 — Confirmations between link layer, port layer, and SMP transport layer remove <Connection Closed (Break Received)> (this signal is repeated in Table 16 — Confirmations between link layer and port layer Received) Page: 43 Sequence number: 6 Date: 2/4/2003 11:18:28 AM Type: Strikeout ACCEPT - DONE 4.3.3.3 Signals between link layer, port layer, and transport layer for SMP Table 15 — Confirmations between link layer, port layer, and SMP transport layer remove <Connection Closed (Link Broken)> (this signal is repeated in Table 16 - Confirmations between link layer and port layer Page: 43 Sequence number: 7 Date: 2/4/2003 11:18:34 AM Type: Strikeout ACCEPT - DONE 4.3.3.3 Signals between link layer, port layer, and transport layer for SMP Table 15 — Confirmations between link layer, port layer, and SMP transport layer remove <Connection Closed (Normal)> (this signal is repeated in Table 16 - Confirmations between link layer and port layer Page: 43 Sequence number: 8 Date: 2/4/2003 11:21:09 AM Type: Highlight **TODO** investigate 4.3.3.3 Signals between link layer, port layer, and transport layer for SMP Table 15 — Confirmations between link layer, port layer, and SMP transport layer change <Connection Closed> to "Transmission Status (Connection Lost) Page: 43 Sequence number: 9 Date: 2/3/2003 3:42:38 PM Type: Strikeout ACCEPT - DONE 4.3.3.3 Signals between link layer, port layer, and transport layer for SMP Table 15 — Confirmations between link layer, port layer, and SMP transport layer remove <Open Failed (Retry)> (this signal is repeated in Table 16 - Confirmations between link layer and port layer Page: 43 Sequence number: 10 Date: 2/3/2003 3:42:32 PM Type: Strikeout ACCEPT - DONE 4.3.3.3 Signals between link layer, port layer, and transport layer for SMP Table 15 — Confirmations between link layer, port layer, and SMP transport layer

remove <Open Failed (Port LayerRequest)> (this signal is repeated in Table 16 - Confirmations between link layer and port layer Page: 49 Sequence number: 5 Date: 1/7/2003 6:24:46 PM Type: Highlight ACCEPT - DONE 4.6.1 Expander device model overview change <SL\_IR primitive processor (BPP);> to "broadcast primitive processor (BPP);" Page: 71 Sequence number: 12 Date: 1/20/2003 4:37:17 PM Type: Highlight ACCEPT - DONE 5.6 READY LED pin Table 32 — Output characteristics of the READY LED signal change <LED off> to "LED off / negated" Page: 71 Sequence number: 13 Date: 1/20/2003 4:37:23 PM Type: Highlight ACCEPT - DONE 5.6 READY LED pin Table 32 — Output characteristics of the READY LED signal change <LED on> to "LED on / asserted" Page: 102 Sequence number: 1 Date: 1/8/2003 5:42:47 PM Type: Highlight ACCEPT - DONE 6.6.4.1 SAS OOB sequence change <as SAS phy.> to "as SAS phy B." Page: 107 Sequence number: 2 Date: 1/24/2003 4:36:31 PM Type: Note ACCEPT - DONE (Put in separate lines for Phy A Rx and Phy B Rx. There are already words above the figure describing it.). 6.6.5 Phy reset sequence after device is attached Figure 55 — Hot-plug and the phy reset sequence This figure is not self explainitory. It needs some words to explain what you are trying to portray. Page: 113 Sequence number: 2 Date: 1/10/2003 5:16:23 PM Type: Highlight ACCEPT - DONE 6.8.3 SAS speed negotiation states Figure 57 — SAS phy (SP) state machine - SAS speed negotiation states change <Await\_SNW> to "AwaitSNW" (will then be consistent with text) Page: 138 Sequence number: 5 Date: 12/30/2002 11:21:04 AM Type: Highlight ACCEPT - DONE 7.1.4.6 EOAF (End of address frame) change <7.4> to "7.7"

Page: 138 Sequence number: 6 Date: 12/30/2002 11:21:48 AM Type: Highlight REJECT - The SP\_DWS state machine has the text that says bad dwords are replaced by ERROR primitives, and is the correct reference. 7.1.4.7 ERROR change <6.9> t o ???? (6.9 about SAS DWORD synchronization) Page: 138 Sequence number: 7 Date: 1/6/2003 1:31:21 PM Type: Highlight ACCEPT - DONE 7.1.4.9 NOTIFY change <TBD> to a real reference (Should be no TBD's in the spec.) Page: 140 Sequence number: 2 Date: 1/8/2003 1:08:00 PM Type: Highlight ACCEPT - DONE 7.1.4.11 OPEN\_REJECT Table 62 — OPEN\_REJECT retry primitives change <devices> to "device" Page: 141 Sequence number: 2 Date: 12/30/2002 11:22:34 AM Type: Highlight ACCEPT - DONE 7.1.4.12 SOAF (Start of address frame) change <7.4> to "7.7" Page: 142 Sequence number: 5 Date: 1/6/2003 1:41:48 PM Type: Highlight ACCEPT - DONE 7.1.6.2 SATA\_PMACK, SATA\_PMNAK, SATA\_PMREQ\_P, and SATA\_PMREQ\_S (Power management acknowledgements and requests) change <7.4> to ???? (7.4 is about CRC) Page: 146 Sequence number: 2 Date: 1/6/2003 2:00:33 PM Type: Highlight ACCEPT - DONE (should be 7.6) 7.4.2 CRC generation (last sentence) change <6.5> to correct reference (reference should be to dword flow, 6.5 is about OOB signals) Page: 147 Sequence number: 6 Date: 1/6/2003 2:01:45 PM Type: Highlight ACCEPT - DONE 7.4.3 CRC checking change <6.5> to correct reference (reference should be to dword flow, 6.5 is about OOB signals)

Page: 147 Sequence number: 7

(section 7.4 is about crc)

Date: 1/8/2003 1:29:12 PM Type: Highlight ACCEPT - DONE (reference is to 7.6 Bit order) 7.5 Scrambling change <6.5> to correct reference (reference should be to dword flow, 6.5 is about OOB signals) Page: 156 Sequence number: 6 Date: 12/30/2002 10:06:53 AM Type: Note 7.8.5 Identification and hard reset (SL\_IR) state machines 7.8.5.1 Overview Figure 67 — SAS link layer identification and hard reset (SL\_IR) state machines Add a pink "out arrow up" with the text "HARD\_RESET Received" This will agree with Table 18 Page: 156 Sequence number: 7 Date: 12/30/2002 10:06:53 AM Type: Note 7.8.5 Identification and hard reset (SL\_IR) state machines 7.8.5.1 Overview Figure 67 — SAS link layer identification and hard reset (SL\_IR) state machines Add a pink "out arrow up" with the text "Identify Sequence Complete" (this will agree with the text in section 7.8.6.3.3.1 and table 18) Page: 157 Sequence number: 4 Date: 12/30/2002 10:06:53 AM Type: Highlight 7.8.6 SL\_IR transmitter and receiver change <shall not transmit the indicated primitive> to "shall transmit the indicated primitive" (section 7.7.1 says that primitives may be inserted inside an address frame) Page: 174 Sequence number: 4 Date: 12/30/2002 10:06:53 AM Type: Highlight 7.13.2 SL transmitter and receiver change <shall not transmit the indicated primitive> to "shall transmit the indicated primitive" (section 7.7.1 says you can) Page: 174 Sequence number: 5 Date: 2/3/2003 3:32:31 PM Type: Highlight ACCEPT - DONE (deleted this paragraph. SL\_IR sends Phy Enabled upstream which should suffice. No need for SSP, SMP, and STP link layers to send anything themselves.) 7.13.3 SL0:Idle state 7.13.3.1 State description <After an Enable Disable SSP Link (Enable) confirmation is received this state shall send an Enable Disable SSP Link (Enable) confirmation to the port layer.> Three things: 1) Fig 72 says "SAS Link" (not SSP) and 2) these say confirmations and if so should be denoted by pink up and down arrows in figure 72 3) This confirmation is not on the Port layer state machines or mentioned in the port layer writeup. Page: 174 Sequence number: 6 Date: 2/3/2003 3:25:05 PM Type: Highlight REJECT (it's the first one listed in table 18) 7.13.2 SL transmitter and receiver <shall send a Change Received confirmation> (this confirmation is not listed in table 18 - Confirmations between ... or application layer)

Page: 180 Sequence number: 2 Date: 12/30/2002 10:06:53 AM Type: Strikeout 7.14 SAS link layer state machine for expander phys (XL) 7.14.1 Overview remove <by receiving an> (third paragraph - after k)) Page: 194 Sequence number: 4 Date: 12/30/2002 10:06:53 AM Type: Highlight 7.16.7 SSP link layer (SSP) state machines 7.16.7.1 Overview change <The SSP\_TCM state machine contains the SP\_TCM1:Tx\_credit\_monitor state> to "The SSP\_TCM state machine contains the SP\_TCM1:Tx\_Credit\_Monitor state" Page: 194 Sequence number: 5 Date: 12/30/2002 10:06:53 AM Type: Highlight 7.16.7 SSP link layer (SSP) state machines 7.16.7.1 Overview <The SSP\_TF state machine's function it to control when the SSP\_T state machine> two things: 1) change <it> to "is" 2) change <the SSP T state machine> to "a SSP transmitter" (I can not find a <SSP\_T> state machine. Does it need to be defined ? We defined for the SL state machines in Figure 73) Page: 197 Sequence number: 1 Date: 12/30/2002 10:06:53 AM Type: Highlight 7.16.7 SSP link layer (SSP) state machines 7.16.7.1 Overview Figure 84 — SSP link layer (SSP) state machines (part 3 - primitive transmission) change <Frame> to "frame" (see text on section 7.16.7.7) Page: 197 Sequence number: 2 Date: 12/30/2002 10:06:53 AM Type: Highlight 7.16.7 SSP link layer (SSP) state machines 7.16.7.1 Overview Figure 84 — SSP link layer (SSP) state machines (part 3 - primitive transmission) change <Frame> to "frame" Page: 198 Sequence number: 1 Date: 12/30/2002 10:06:53 AM Type: Highlight 7.16.7.3 SSP\_TCM1:Tx\_credit\_monitor state change <TCM1:Tx\_credit\_monitor state> to CM1:Tx\_Credit\_Monitor state Page: 199 Sequence number: 5 Date: 12/30/2002 10:06:53 AM Type: Highlight 7.16.7.5.3 Transition SSP\_TF1:Connected\_Idle to SSP\_TF4:Indicate\_Done\_Tx change <Done> to "DONE"

Sequence number: 1 Date: 12/30/2002 10:06:53 AM Type: Highlight 7.16.7.6.3 Transition SSP\_TF2:Tx\_Wait to SSP\_TF4:Indicate\_Done\_Tx change <Connection Closed> to "Close Connection" Page: 200 Sequence number: 2 Date: 12/30/2002 10:06:53 AM Type: Highlight 7.16.7.6.3 Transition SSP\_TF2:Tx\_Wait to SSP\_TF4:Indicate\_Done\_Tx change <Done> to "DONE" Page: 200 Sequence number: 3 Date: 12/30/2002 10:06:53 AM Type: Highlight 7.16.7.6.3 Transition SSP\_TF2:Tx\_Wait to SSP\_TF4:Indicate\_Done\_Tx change <Done> to "DONE" Page: 200 Sequence number: 4 Date: 12/30/2002 10:06:53 AM Type: Highlight 7.16.7.6.3 Transition SSP\_TF2:Tx\_Wait to SSP\_TF4:Indicate\_Done\_Tx change <Done> to "DONE" Page: 200 Sequence number: 5 Date: 12/30/2002 10:06:53 AM Type: Highlight 7.16.7.6.3 Transition SSP\_TF2:Tx\_Wait to SSP\_TF4:Indicate\_Done\_Tx change <Done> to "DONE" Page: 200 Sequence number: 6 Date: 12/30/2002 10:06:53 AM Type: Highlight 7.16.7.6.3 Transition SSP\_TF2:Tx\_Wait to SSP\_TF4:Indicate\_Done\_Tx change <Done> to "DONE" Page: 200 Sequence number: 7 Date: 12/30/2002 10:06:53 AM Type: Highlight 7.16.7.8 SSP\_TF4:Indicate\_Done\_Tx state change <Done> to "DONE" Page: 201 Sequence number: 2 Date: 12/30/2002 10:06:53 AM Type: Highlight 7.16.7.8 SSP\_TF4:Indicate\_Done\_Tx state change <parameter> to "Wait For DONE (CREDIT TIMEOUT) parameter Page: 201 Sequence number: 3 Date: 12/30/2002 10:06:53 AM Type: Highlight 7.16.7.9 SSP\_RF1:Rcv\_Frame state change <Received Frame> to "Frame Received"

Page: 202 Sequence number: 2 Date: 12/30/2002 10:06:53 AM Type: Highlight 7.16.7.11 SSP\_RIM1:Rcv\_Interlock\_Monitor state change <Received Frame> to "Frame Received" Page: 202 Sequence number: 3 Date: 12/30/2002 10:06:53 AM Type: Highlight 7.16.7.11 SSP\_RIM1:Rcv\_Interlock\_Monitor state change <Received Frame> to "Frame Received" Page: 202 Sequence number: 4 Date: 12/30/2002 10:06:53 AM Type: Highlight 7.16.7.11 SSP\_RIM1:Rcv\_Interlock\_Monitor state change <Received Frame> to "Frame Received" Page: 202 Sequence number: 5 Date: 12/30/2002 10:06:53 AM Type: Highlight 7.16.7.13.1 State description change <CREDIT BLOCKED by sending> to "CREDIT\_BLOCKED be transmitted by sending" Page: 208 Sequence number: 1 Date: 2/1/2003 4:35:01 PM Type: Highlight ACCEPT - DONE (renamed all the states to shorter, mixed-case names) 7.18.4 SMP link layer (SMP) state machines 7.18.4.1 Overview change <Rcv\_response\_Frame> to "Rcv\_Response\_Frame" (in all other state diagrams the first letter of all state names are capitalized - this comment applies to all state names in the SMP section and SMP figures) Page: 208 Sequence number: 2 Date: 1/25/2003 11:54:04 AM Type: Highlight ACCEPT - DONE 7.18.4 SMP link layer (SMP) state machines 7.18.4.1 Overview change <(see 7.18.4.2)(initial state);> to (see 7.18.4.2.1)(initial state); Page: 217 Sequence number: 3 Date: 12/30/2002 10:06:53 AM Type: Highlight 8.3.3 PL\_OC2:Overall\_Control state 8.3.3.1 State description 8.3.3.1.1 State description overview Delete <a) I\_T nexus loss time;> and reorder the following arguments restarting at a) Page: 218 Sequence number: 5 Date: 12/30/2002 10:06:53 AM Type: Strikeout

(delete all of the following text. these are not wide port rules and none of the terms i.e., COMMAND, QUERY TASK, have been defined and are out of context) <An initiator port that is a wide port may transmit COMMAND frames on multiple links simultaneously. An initiator port shall not transmit a TASK frame requesting a task management function that only affects a single I\_T\_L\_Q nexus (e.g., ABORT TASK or QUERY TASK; see SAM-3) specifying an I\_T\_L\_Q nexus for which the initiator port is transmitting a frame or is waiting for a link layer acknowledgement for a frame. An initiator port shall not transmit a TASK frame requesting a function that only affects an I T L nexus (e.g., ABORT TASK SET, CLEAR TASK SET, CLEAR ACA, or LOGICAL UNIT RESET; see SAM-3) specifying an I T L nexus for which the initiator port is transmitting a frame or is waiting for a link layer acknowledgement for a frame. An initiator port shall not transmit a TASK frame requesting a function that only affects an LT nexus (see SAM-3) specifying an I\_T nexus for which the initiator port is transmitting a frame or is waiting for a link layer acknowledgement for a frame.> Page: 219 Sequence number: 2 Date: 12/30/2002 10:06:53 AM Type: Note 8.3.3.1.5 Filling in the Tx Frame arguments 4th paragraph (about I\_T nexus loss arguments. add "For each destination, the PL\_OC\_I\_T nexus loss timer is is stopped, set to zero, and asssigned a stopped status after each Connection Opened confirmation is received and after each power-on reset or hard reset function is completed " Page: 221 Sequence number: 3 Date: 12/30/2002 10:06:53 AM Type: Highlight 8.4 Port layer phy manager (PL PM) state machine 8.4.1 Overview change <PL\_OC state machine;> to "transport layer;" Page: 223 Sequence number: 4 Date: 12/30/2002 10:06:53 AM Type: Note 8.4 Port layer phy manager (PL\_PM) state machine 8.4.1 Overview Figure 93 — Port layer phy manager (PL\_PM) state machine (part 2) add a pink "In Arrow" here with text of "DONE Received" Page: 223 Sequence number: 5 Date: 12/30/2002 10:06:53 AM Type: Note 8.4 Port layer phy manager (PL\_PM) state machine 8.4.1 Overview Figure 93 — Port layer phy manager (PL\_PM) state machine (part 2) add a pink "out Arrow " here with text of "DONE Received" Page: 223 Sequence number: 6 Date: 12/30/2002 10:06:53 AM Type: Note 8.4 Port layer phy manager (PL\_PM) state machine 8.4.1 Overview Figure 93 — Port layer phy manager (PL\_PM) state machine (part 2) add a pink down arrow with a "Close Connection" text Page: 224 Sequence number: 3 Date: 12/30/2002 10:06:53 AM Type: Highlight 8.4.3.1.3 Connection Opened handling change <Tx Frame,> to "Tx Frame parameter,"

8.3.3.1.4 SSP wide port rules

Page: 225 Sequence number: 3 Date: 12/30/2002 10:06:53 AM Type: Highlight 8.4.4 PL\_PM3:Connected state 8.4.4.1 State description change <This state shall generate a Tx Frame request to the link layer when a Tx Frame parameter is received from the PL\_OC state machine.> to "This state shall generate a Tx Frame (Balanced) request to the link layer when a Tx Frame parameter with a Balance Required argument is received from the PL\_OC state machine. This state shall generate a Tx Frame (Nonbalanced) request to the link layer when a Tx Frame parameter with a Balance Not Required argument is received from the PL\_OC state machine." Page: 225 Sequence number: 4 Date: 12/30/2002 10:06:53 AM Type: Highlight 8.4.3.1.4 Open Failed handling change <Tx Frame> to "Tx Frame parameter" Page: 226 Sequence number: 5 Date: 12/30/2002 10:06:53 AM Type: Note 8.4.4.1 State description (-- for PL\_PM3: Connected state) in the area started by <for SSP ports> add " For SSP and SMP ports, this state shall send a Transmission Status (Connection Lost) confirmation to the transport layer if a Connection Closed (Break Received), Connection Closed (Close Timeout), or Conection Closed (Link Broken) confirmation is received from the link layer." Page: 226 Sequence number: 6 Date: 12/30/2002 10:06:53 AM Type: Note 8.4.4 PL\_PM3:Connected state 8.4.4.1 State description insert between c) and d) "d) DONE Received" Page: 226 Sequence number: 7 Date: 12/30/2002 10:06:53 AM Type: Highlight 8.4.4 PL\_PM3:Connected state 8.4.4.1 State description change <d)> to "e" Page: 226 Sequence number: 8 Date: 12/30/2002 10:06:53 AM Type: Highlight 8.4.4 PL\_PM3:Connected state 8.4.4.1 State description change <e)> to "f" Page: 226 Sequence number: 9 Date: 12/30/2002 10:06:53 AM Type: Highlight 8.4.4 PL\_PM3:Connected state 8.4.4.1 State description change <Tx Frame> to "Tx Frame Request" Page: 226 Sequence number: 10 Date: 12/30/2002 10:06:53 AM Type: Highlight 8.4.4 PL\_PM3:Connected state

8.4.4.1 State description change <Tx Frame> to "Tx Frame Request" Page: 228 Sequence number: 4 Date: 12/30/2002 11:29:17 AM Type: Highlight ACCEPT - DONE 9.2.1 SSP frame format Table 88 — SSP frame format change <TIMEOUT> to "RETRANSMIT" (will make definitions on next page and later text consistent) Page: 244 Sequence number: 6 Date: 2/8/2003 2:31:47 PM Type: Strikeout ACCEPT - DONE (removed it entirely) 9.2.6.2 Initiator device state machines 9.2.6.2.1 Overview Figure 98 — SSP transport layer (ST) state machines - initiator device remove (ACK/NAK TIMEOUT) Page: 244 Sequence number: 7 Date: 2/8/2003 2:21:32 PM Type: Note ACCEPT - DONE 9.2.6.2 Initiator device state machines 9.2.6.2.1 Overview Figure 98 — SSP transport layer (ST) state machines - initiator device add a pink in arrow with the nomenclature of "ACK Transmitted"on it (i.e. add a "ACK Transmitted " received confirmation here) Page: 250 Sequence number: 9 Date: 2/8/2003 2:54:23 PM Type: Highlight ACCEPT - DONE 9.2.6.2.8 ST\_IFR1:Initiator\_Frame\_Router state change <Data-in parameter> to "Data-in Arrived parameter" Page: 250 Sequence number: 10 Date: 2/2/2003 3:41:25 PM Type: Highlight ACCEPT - DONE (removed all mention of parameter names here, since this is just the overview). 9.2.6.3 Target device state machines 9.2.6.3.1 Overview change <Data-Out Received> to "Data -Out Arrived or Response Data" ( to be consisten with figure 99 - SSP Transport layer state machine - target device) Page: 251 Sequence number: 3 Date: 2/2/2003 3:45:23 PM Type: Note ACCEPT - DONE 9.2.6.3 Target device state machines 9.2.6.3.1 Overview Figure 99 — SSP transport layer (ST) state machines - target device add a pink in arrow with the nomenclature of "ACK Transmitted"on it (i.e. add a "ACK Transmitted " received confirmation here)

Sequence number: 3 Date: 1/30/2003 4:17:51 PM Type: Highlight ACCEPT - DONE 9.2.6.3.6 ST\_TTS4:Receive\_Data\_Out state 9.2.6.3.6.1 State description change <ST\_TS1 to "ST\_TTS1" Page: 263 Sequence number: 1 Date: 12/30/2002 10:06:53 AM Type: Highlight 9.4.4.2.1 Overview (for Initiator device state machine) Figure 101 - SMP transport layer state machine - initiator device change <Connection Closed> to "Transmission Status" Page: 263 Sequence number: 2 Date: 12/30/2002 10:06:53 AM Type: Highlight 9.4.4.2 Initiator device state machine 9.4.4.2.1 Overview Figure 101 — SMP transport layer state machine - initiator device (MT\_ID) remove <Connection Closed> and th pink arrow Page: 264 Sequence number: 3 Date: 12/30/2002 10:06:53 AM Type: Highlight 9.4.4.2.3.2 Transition MT\_ID2:Send to MT\_ID1:Idle change <Connection Closed> to "Transmisssion Status (Connection Lost)" Page: 264 Sequence number: 4 Date: 12/30/2002 10:06:53 AM Type: Highlight 9.4.4.2.4.2 Transition MT\_ID3:Receive to MT\_ID1:Idle change <Connection Closed> to "Transmission Status (Connection Lost)" Page: 265 Sequence number: 1 Date: 12/30/2002 10:06:53 AM Type: Highlight 9.4.4.3.3.2 Transition MT TD2:Respond to MT TD1:Idle change <Connection Closed> to "Transmission Status (Connection Lost)" Page: 265 Sequence number: 2 Date: 1/30/2003 5:42:34 PM Type: Strikeout 9.4.4.3.1 Overview Figure 102 - SMP transport layer (MT) state machines - target device Remove <Connection Closed> and the input arrow Page: 266 Sequence number: 1 Date: 2/8/2003 11:48:52 AM Type: Note ACCEPT - TODO (something mentioning the new events/signals might belong here. ch4 does mention those) This section does not talk about receiving from the transport layer the I\_T Nexus loss timer expired or not arguments or the connection lost arguments and what to do with them. It should be added. Page: 288 Sequence number: 2 Date: 12/30/2002 5:09:16 PM Type: Highlight ACCEPT - DONE

10.1.8.1.3 Transition SA\_PC\_0:Powered\_On to SA\_PC\_5:Active\_Wait change <SA\_PC\_5:Active state.> to "SA\_PC\_5:Active\_Wait state."

Page: 298 Sequence number: 3 Date: 1/22/2003 9:25:55 AM Type: Note ACCEPT - DONE (removed the field per Jan WG) 10.3.1.3 REPORT MANUFACTURER INFORMATION function the <ADDITIONAL LENGTH field> location is not listed in table 133 - report manufacture information response

Page: 324 Sequence number: 4 Date: 12/30/2002 2:24:35 PM Type: Highlight ACCEPT - DONE B.1 SAS phy reset sequence examples change <phy B> to "phy A" ?????

## Author: TI

Page: 23 Sequence number: 4 Date: 1/22/2003 9:39:55 AM Type: Note ACCEPT - DONE (In figures that show ports but no phys, the phy level of detail is not shown, but the ports always contain one or more phys.>> 4.1.4 last sentence needs work. << In figures that show ports but no phys, the ports still contain phys and may or may not be wide ports.>> should be: << In figures that show ports but no phys, the phy level of detail is not shown, the ports actually contain one or more phys.>> Page: 23 Sequence number: 5 Date: 1/22/2003 3:05:26 PM Type: Note ACCEPT - DONE (removed whole section) 4.1.5 and 4.16 first sentence does not make sense in a SAS standard, unless it is explained better. SCSI and ATA port that support SMP can be used in SAS domains. If a device supports SCSI or ATA without SMP is outside of the scope of this standard. Page: 25 Sequence number: 15 Date: 1/23/2003 4:01:38 PM Type: Note ACCEPT - TODO 3. Technical 4.1.8 should have a Fan out expander section and a description of the relationship between the expanders in a large configuration. I have seen it in presentations, but there is no clear description of it in the standard. There should be a clear definition of a fan out expander as a section. 4.1.8.1 Expander device overview 4.1.8.2 Edge expander device set 4.1.8.3 Configurable expander device Page: 70 Sequence number: 8 Date: 12/30/2002 12:53:08 PM Type: Note ACCEPT - DONE 4. Figure 34 the title has internal misspelled Page: 114 Sequence number: 26 Date: 12/30/2002 12:53:39 PM

Type: Note 5. Technical 6.8.3.3.1, 9.2.4.5 and 9.2.3.9.1 still have an editors note, this should have been addressed before the letter ballot.

## Author: Vixel

Page: 5 Sequence number: 12 Date: 1/8/2003 9:33:33 AM Type: Highlight ACCEPT - DONE Clause 3.1.3 Clause 3.1.5 Clause 3.1.6 Clause 3.1.8 Clause 3.1.9 Add -7 to ATAPI Page: 5 Sequence number: 13 Date: 1/8/2003 9:32:46 AM Type: Highlight ACCEPT - DONE 3.1.5 ATA initiator device ATAPI should be ATAPI-7 Page: 5 Sequence number: 14 Date: 1/8/2003 9:33:03 AM Type: Highlight ACCEPT - DONE 3.1.6 ATA initiator port ATAPI should be ATAPI-7 Page: 5 Sequence number: 15 Date: 1/8/2003 9:33:13 AM Type: Highlight ACCEPT - DONE 3.1.9 ATA target port ATAPI should be ATAPI-7 Page: 5 Sequence number: 16 Date: 1/8/2003 9:33:24 AM Type: Highlight ACCEPT - DONE 3.1.9 ATA target port ATAPI should be ATAPI-7 Page: 9 Sequence number: 22 Date: 1/17/2003 3:47:35 PM Type: Highlight ACCEPT - DONE (defaults clause deleted altogether) Clause 3.1.92 Should be "minimum" Page: 15 Sequence number: 5 Date: 1/17/2003 3:47:02 PM Type: Strikeout ACCEPT - DONE Clause 3.4 Remove this sentence. Duplicate of last sentence in 3rd paragraph of this section. Page: 20 Sequence number: 2 Date: 1/22/2003 10:55:09 AM Type: Note REJECT - The arrows are correct. Clause 4.1.1, Figure 4 Change direction of all arrows (inheritance) in diagram. They appear to point the wrong way. Page: 20 Sequence number: 3 Date: 1/17/2003 3:41:33 PM Type: Note REJECT (SAS device may be inside an expander device) Clause 4.1.1, Figure 4 Clarify. What is this modeling, the fact that the Expander is a SAS device, or that an SMP application must reside in an Expander device? If this illustrates that an Expander is a SAS device, this line should be an "association", not an "aggregation". Page: 20 Sequence number: 4 Date: 1/22/2003 10:50:19 AM Type: Highlight ACCEPT - DONE (2..128 per 03-064) Clause 4.1.1, Figure 4 Change to "2..64". see clause 4.1.8.1. Page: 20 Sequence number: 5 Date: 1/22/2003 10:50:00 AM Type: Highlight ACCEPT - DONE (0..127 with 03-034) Clause 4.1.1, Figure 4 Change to "0..63", should have upper bounds as specified in later clause. Page: 20 Sequence number: 6 Date: 1/22/2003 10:50:34 AM Type: Highlight ACCEPT - DONE (1..128 per 03-064) Clause 4.1.1, Figure 4 Change to "1..64". Page: 23 Sequence number: 6 Date: 1/17/2003 3:38:08 PM Type: Highlight REJECT (clause 3 has state machine conventions) Clause 4.1.4. Move to clause 3.4. Page: 23 Sequence number: 7 Date: 1/22/2003 3:05:12 PM Type: Strikeout REJECT (the SP state machine supports being a SATA initiator) (whole section deleted anyway) Clause 4.1.5 Remove this. This is outside the scope of the standard. Page: 23 Sequence number: 8 Date: 1/22/2003 3:04:41 PM Type: Strikeout REJECT (it says it is outside the scope) (whole section deleted anyway) Clause 4.1.5 Remove this. This is outside the scope of the standard. Page: 34

Sequence number: 6

Date: 1/23/2003 5:58:14 PM Type: Highlight REJECT (when a wide-capable port is split into two domains, it ends up with two ports with the same address. This violates the SCSI definition of port name which requires "unique within the protocol". However, did rewrite the note a little bit to explain this scenario better and removed the mention of logins.) Clause 4.2.4 Change to "Port names are not defined in SAS, because there is no login process in SSP to exchange port names." Removed part that conflicts with clause 4.2.2, "SAS address shall be worldwide unique." Page: 36 Sequence number: 3 Date: 1/23/2003 6:20:19 PM Type: Note ACCEPT - DONE (added key: dashed means control signal; solid means data path) Clause 4.3.2, figure 20. Define what the dashed blue lines mean in these figures, they appear to be used in a different manner than defined in clause 3.5. Page: 49 Sequence number: 17 Date: 1/24/2003 9:44:47 AM Type: Highlight ACCEPT - DONE ("... port. Each phy may then participate in new phy reset sequences and start transmitting.") Clause 4.4.2 This needs clarification. Does this mean the phy that received the hard reset, or each phy in the port? Page: 49 Sequence number: 18 Date: 1/8/2003 9:30:18 AM Type: Highlight ACCEPT - DONE (should be broadcast primitive processor) Clause 4.6.1 Clause 4.6.5 (2 instances) Please provide a definition for "SL\_IR primitive". Page: 51 Sequence number: 3 Date: 1/24/2003 9:49:51 AM Type: Highlight ACCEPT - DONE 4.6.5 Broadcast primitive processor Change SL\_IR to BPP Page: 54 Sequence number: 1 Date: 1/11/2003 5:09:24 PM Type: Highlight REJECT (changed the Links to Phys in 4.6.7 instead) Clause 4.6.8, table 23 (3 instances) Change "Phy" to "Link" to match terminology used in clause 4.6.7, figure 27 (3 times) Page: 57 Sequence number: 3 Date: 1/8/2003 9:29:25 AM Type: Highlight ACCEPT - DONE Clause 4.6.11.1 Change "may only" to "shall". "may only " not in list of keywords. Page: 58 Sequence number: 1 Date: 1/24/2003 10:23:39 AM Type: Highlight ACCEPT - DONE (add "to other fanout expander devices.") Clause 4.6.11.3 This sentence should be clarified, add "together" to the sentence. Page: 58

Sequence number: 2

Date: 1/14/2003 5:44:23 PM Type: Strikeout **REJECT (Jan WG)** Clause 4.6.11.3 This requirement is an implementation issue and should not be in the standards. Remove this. Page: 59 Sequence number: 5 Date: 1/17/2003 3:19:06 PM Type: Highlight ACCEPT - TODO (this is totally broken. Fanout expanders do this all the time; so do edge routers. It was intended to disable route entries if two edge expander sets are attached without subtractive ports.) Clause 4.6.11.3 This needs clarification. What is the purpose of setting the DISABLE ROUTE ENTRY bit here? This would seem to preclude using the expander SAS address for expander internal ports. Page: 61 Sequence number: 4 Date: 1/24/2003 11:01:17 AM Type: Highlight REJECT - DONE (but move ... over to the right for phy numbers, so the left side can mean devices) Clause 4.6.11.4 For clarity and completeness, include expanders X and Y in this example. Page: 63 Sequence number: 3 Date: 1/24/2003 11:05:41 AM Type: Highlight ACCEPT - DONE (add phy 0 to the introduction) Clause 4.6.11.4 Add a clarification that the route table in the table is for one phy on expander E0. Page: 64 Sequence number: 2 Date: 1/17/2003 3:11:30 PM Type: Highlight ACCEPT - TODO (add a picture with several levels of mixed expanders and devices, numbering them.) Clause 4.6.11.5 Add an example to clarify these rules for order of traversal. Page: 138 Sequence number: 16 Date: 1/8/2003 9:28:41 AM Type: Highlight ACCEPT - DONE Clause 7.1.4.6 Clause 7.1.4.12 Change reference to clause 7.7. Page: 154 Sequence number: 7 Date: 1/17/2003 3:06:50 PM Type: Highlight ACCEPT - TODO (use "SMP initiator port" and management application client) Clause 7.8.2 Does this requirement preclude an expander from performing the discover process? Does this require an expander to implement a full SCSI initiator if it only intends to perform the discover process? If so, this needs to be clarified so that an expander can perform the discover process without implementing a full SCSI initiator. Page: 180 Sequence number: 7 Date: 1/11/2003 5:10:43 PM Type: Strikeout ACCEPT - DONE Clause 7.14.1 Extraneous, remove.

Page: 190 Sequence number: 10 Date: 1/17/2003 3:02:49 PM Type: Highlight ACCEPT - TODO (add another level of expanders ... sample picture will be provided. Add a sentence mentioning that receivers just discard extra ALIGNs that show up.) Clause 7.15 It's ambiguous which faster phy does the insertion. Should be the transmitting faster phy? Also doesn't mention removal of ALIGNs. This should be described. Page: 297 Sequence number: 6 Date: 1/25/2003 10:59:31 AM Type: Strikeout REJECT - DONE (but change "equal to the number of phys" to "equal to the number of addressable phys") Clause 10.3.1.2 This requirement is an implementation issue and should not be in the standards. Remove this. Page: 297 Sequence number: 7 Date: 2/3/2003 3:01:40 PM Type: Strikeout ACCEPT - DONE (Jan WG vote) Clause 10.3.1.2 This fanout expander requirement is an implementation issue and should not be in the standards. Remove this. Page: 301 Sequence number: 5 Date: 1/21/2003 7:09:40 PM Type: Highlight ACCEPT - DONE (use the term "method" in the table Descriptions. Change the Name column to use "attribute" too. Then delete this sentence) Clause 10.3.1.4 This sentence is confusing because of the sentence it immediately follows. It appears to describe something that is not related to the table. It would be clearer if this sentence was made a separate paragraph, or a note.