To:T10 Technical CommitteeFrom:Rob Elliott, HP (elliott@hp.com)Date:3 February 2003Subject:T10/03-088r0 SPC-3 Rename some SAS additional sense codes

Revision History

Revision 0 (3 February 2003) first revision

Related Documents

sas-r03 - Serial Attached SCSI revision 3 02-246r1 - SPC-3 protocol-specific changes for SAS SSP 03-055 - SAS Revision 3 letter ballot comment resolution

Overview

During SAS revision 3 letter ballot, some additional sense code name changes were suggested.

Suggested Changes

In both:

- Table 153 ASC and ASCQ assignments
- Table B.1 ASC and ASCQ assignments

change:

- ILLEGAL TARGET PORT TRANSFER TAG RECEIVED
- RELATIVE OFFSET ERROR

to (respectively):

- INVALID TARGET PORT TRANSFER TAG RECEIVED
- DATA OFFSET ERROR