Accredited Standards Committee

NCITS, National Committee for Information Technology Standards

Doc: T10/97-130r0
Date: February 26, 1997
Project: X3T10.1/1146D
Ref Doc.: SSA-PH2 rev 4
Reply to: John Scheible

To: T10 Membership From: John Scheible

Subject: Letter ballot comment resolution on SSA-PH2 rev 4

# **BACKGROUND**

This proposal documents the responses to the T10 letter ballot comments for SSA-PH2 rev 4 as approved by T10.1 during its February 26, 1997 plenary meeting.

#### Ballot totals:

- 44 Yes
- 1 No
- 0 Abstain
- 1 Organization(s) did not vote
- 46 Total voting organizations
- 3 Ballot(s) included comments

This 2/3rds majority ballot passed.

## Comments attached to YesC ballot from John P. Scheible of IBM Corp.:

- IBM-1) Change header from X3T10.1 / 1146D rev 3a to X3T10.1 / 1146D rev 4 RESPONSE: Accept as written
- IBM-2) 4: Add In case of conflict, figures take precedence over tables and both figures and tables take precedence over text.

RESPONSE: Accept as written

#### Comments attached to No ballot from Edward A. Gardner of Ophidian Designs:

OPH-1) It appears, from the ballot, that VLSI's negative vote remains unresolved. I would like to see a response from X3T10.1 on VLSI's comment before approving this. If X3T10.1 has already responded to VLSI's comment, please refer me to the relevant document and I will amend my vote.

RESPONSE: VLSI s response only concerned SSA-TL2 related to adding a Unique ID to the Link Reset frame, and does not impact SSA-PH2. See SSA-TL2 comments for resolution (a note has been added).

### Comments attached to YesC ballot from Gene Milligan of Seagate Technology:

SEA-1) The file I downloaded was defective and I could not review the document. Please check the draft to see if it has the same type of problems as outlined in the other SSA drafts.

RESPONSE: The document was in the X3T10 9606 mailing and as been verified as good. The single must is removed in Annex K paragraph 2 by removing the word must. The two occurrences of can are removed by removing both occurrences of it can be seen that. See the comment resolution for either SSA-TL2 or SSA-S3P for resolution of your other concerns.

#### Web page access

X3T10.1 is planning web sites to disseminate information regarding the implementation of the standard. The following changes will be made:

Add the following to the end of clause 2.2
 Further information regarding the implementation of this standard may be available at <a href="http://www.ncits.org/t10">http://www.ncits.org/t10</a> or <a href="http://www.ssaia.org">http://www.ncits.org/t10</a> or <a href="http://www.ssaia.org">http://www.ncits.org/t10</a> or <a href="http://www.ssaia.org">http://www.ssaia.org</a>.

Sincerely,

John Scheible

Voice: (512) 823-8208 FAX: (512) 838-3822

Email: Scheible@vnet.ibm.com