

Tuesday, February 11, 1997

T10.1/97a105r0

Accredited Standards Committee
NCITS, National Committee for Information Technology Standards

Doc: T10.1/97a105r0
Date: February 6, 1997
Project: X3.295:1996
Ref Doc.: SSA-TL1
Reply to: John Scheible

To: T10.1 Membership
From: John Scheible
Subject: Possible Errata list for SSA-TL1

BACKGROUND

The following is a list of possible errata for SSA-TL1.

- 1) 8.3, paragraph after psuedocode: Change Channels 0- 127 are addressed one byte. Channels 129-16 383 to Channels 0 - 127 are addressed one byte. Channels 128 - 16 383 (128 was left out).

Sincerely,

John Scheible
Voice: (512) 823-8208
FAX: (512) 838-3822
Email: Scheible@vnet.ibm.com