

Connector Division

1501 Morse Avenue
Elk Grove Village, IL 60007
312.981.6000

November 28, 1988

John Lohmeyer, X379.2 Chairman
N.C.R. Corporation
3718 North Rock Road
Wichita, KS 67226

Lawrence J. Lamers, X379.2 General Editor
Sony Corporation of America
655 River Oaks Parkway
San Jose, CA 95134

Re: SCSI 2 - Rev. 6

Dear John:

Upon review of Rev. 6, I have noticed some errors on Page 4-7, Figure 4-4. This is a "low-density" connector and is correctly described on Page 4-3. The problems with Page 4-7 are:

1. Note 1 specifies contacts on 1.27mm (0.050 in) centers. This should be on 2.54mm (0.100 in) centers. Dimension C3 in the table correctly specifies this spacing.
2. Note 1 and the uppermost drawing describe "staggered" spacing. This cable connector mates with the device connector in Figure 4-3, Page 4-6 in which the contacts are not staggered. Not staggered should be correct.
3. Note 1 lists the overall contact width as 62.23mm (2.450 in) whereas the dimensions from Figure 4-3 are correct, i.e. 24 spaces x 2.54mm = 60.69mm.

The solution would be to redraw the contacts in the upper figure to show adjacent contacts and to have Note 1 on Figure 4-4 read the same as Note 3 on Figure 4-3.

Sincerely,


John T. Guennewig
Product Manager

JTG:js