

Implementation of Harbor Drive Carrier

Intel's Concerns:

- **Lack of resources for timely completion of:**

RV design & testing

Thermal design & qualification

Design for shock/vibration

Backplane completion for 1.00''

Need clarification on the following:

- **No clear commitment.....who pays for tooling, debug and development of plastic and die cast parts.**
- **Need definite time frame for when wrapper will become a part of standard drive carrier.**
- **Need clear production cost targets for finished carrier.**

Too many unknowns = High risk

Required actions:

- **Require commitment from more OEM's for development.**
- **Need commitment from drive manufacturers (implementation dates).**
- **Clear definition of shared tooling costs required plastic and die cast parts.**