

2004 T10 Mailing #6

<u>Announce</u>	<u>Description</u>	<u>File Type and Size</u>
jbl0406	Memorandum from the Chairman	PDF (29298)
sy0406	Table of Contents	PDF (n/a)
ann-m065	Meeting Notice: Jan 17-21, 2005 Las Vegas, NV	PDF (78399)
ann-m066	Meeting Notice: Mar 7-11, 2005 Dana Point, CA	PDF (81500)
map-m065	Meeting Map: Jan 17-21, 2005 Las Vegas, NV	PDF (42456)

<u>Document Number</u>	<u>Description</u>	<u>Author</u>	<u>File Type and Size</u>
03-245r5	SAS 1.1, adding the Terminate Data Transfer protocol service	Mark Evans	PDF (132121)
03-245r6	SAS 1.1, adding the Terminate Data Transfer protocol service	Mark Evans	PDF (126005)
03-393r2	FCP-3 SPC-3 return check condition when FCP_DL too small	Erich Oetting	PDF (52362)
03-393r3	FCP-3 SPC-3 return check condition when FCP_DL too small	David Peterson	PDF (15032)
04-162r2	ADT Letter Ballot Comment Resolution Spreadsheet	Paul Entzel	PDF (150729)
04-198r1	Background Media Scan	Gerald Houlder	PDF (378528)
04-218r5	SAT SPC-3 INQUIRY contents	Rob Elliott and Wayne Bellamy	PDF (138568)
04-222r1	SAS-1.1 More phy test patterns	Rob Elliott and Steven Fairchild	PDF (83773)
04-222r2	SAS-1.1 More phy test patterns	Rob Elliott	PDF (103887)
04-262r4	ATA Command Pass-Through	Curtis Stevens	PDF (59332)
04-262r5	ATA Command Pass-Through	Curtis Stevens	PDF (58944)
04-262r6	ATA Command Pass-Through	Curtis Stevens	PDF (61679)
04-263r4	ADI: Features for ADC-2 and ADT-2	Paul Suhler	PDF (115064)
04-274r1	SBC-2 Revision 15 T10 letter ballot comment resolution as of revision 15b	Rob Elliott	PDF (288133)
04-274r2	SBC-2 Revision 15 T10 letter ballot comment resolution as of revision 16	Rob Elliott	PDF (296607)
04-283r1	SSC-3 Reservation model cleanup	Rob Elliott	PDF (66323)
04-288r1	Minutes of SCSI CAP Working Group - Sept 14-15, 2004	Weber & Lohmeyer	PDF (107852)
04-306r1	Project Proposal: ADC-2	Paul Suhler	PDF (38085)
04-307r1	Project Proposal: ADT-2	Paul Suhler	PDF (37933)
04-312r0	SSC-3: Definition of WORM	Kevin Butt	PDF (97564)
04-322r2	Agenda for T10 Meeting #64 (November 2004)	John Lohmeyer	PDF (68849)
04-327r0	Results of letter ballot on forwarding SPC-3 to first public review	John Lohmeyer	PDF (800596)
04-327r1	Results of letter ballot on forwarding SPC-3 to first public review	John Lohmeyer	PDF (857999)
04-328r0	BD-RE Multi-Media Command Set Description	William P. McFerrin	PDF (435372)
04-328r1	BD-RE Multi-Media Command Set Description	W. McFerrin	PDF (495244)
04-328r2	BD-RE Multi-Media Command Set Description	Bill McFerrin	PDF (498422)
04-329r0	SAS 1.1 - Missing Protocol Identifier field	George O. Penokie	PDF (15074)
04-330r0	Minutes of SAS 1.1 PHY conference call September 30, 2004	Alvin Cox	PDF (13780)
04-331r0	SAS 1.1 PHY Definitions and Acronyms update	Bill Ham	PDF (159405)
04-331r1	SAS 1.1 PHY Definitions and Acronyms update	Bill Ham	PDF (377850)
04-332r0	SAS 1.1 PHY jitter MJSQ modifications	Bill Ham	PDF (198512)
04-332r1	SAS 1.1 PHY jitter MJSQ modifications	Bill Ham	PDF (274779)
04-333r0	SAS-1.1: PHY VACANT SMP Function Response	Robert Sheffield	PDF (25765)
04-334r0	Minutes: ADI Conference Call (7 October 2004)	Michael Banther	PDF (38766)
04-335r0	SSC-3: WORM Tamper Read Enable	Michael Banther	PDF (253348)
04-335r1	SSC-3: WORM Tamper Read Enable	Michael Banther	PDF (269787)
04-336r0	Minutes: ADI Conference Call (14 October 2004)	Michael Banther	PDF (31435)
04-337r0	SAS-1.1 TCTF Editorial Changes	Barry Olawsky	PDF (70233)
04-337r1	SAS-1.1 TCTF Editorial Changes	Barry Olawsky	PDF (70844)
04-338r0	Minutes: ADI Conference Call (18 October 2004)	Michael Banther	PDF (35776)
04-339r0	SAS-1.1 Remove minimum ALIGN counts from summary table	Rob Elliott	PDF (112449)
04-339r1	SAS-1.1 Remove minimum ALIGN counts from summary table	Rob Elliott	PDF (64736)

04-340r0	SAS-1.1 OPEN_REJECT BAD DESTINATION handling	Rob Elliott	PDF (154987)
04-341r0	SAS-1.1 Do not reset Arbitration Wait Time timer on incoming OPEN	Rob Elliott	PDF (69847)
04-341r1	SAS-1.1 Do not reset Arbitration Wait Time timer on incoming OPEN	Rob Elliott	PDF (80997)
04-342r0	Minutes SAS 1.1 PHY working group conference call October 14, 2004	Alvin Cox	PDF (19441)
04-343r0	Letter Ballot on recommending approval of SAM-2 FDIS	John Lohmeyer	PDF (113285)
04-344r0	Results of Letter Ballot on recommending approval of SAM-2 FDIS	John Lohmeyer	PDF (24407)
04-345r0	Project proposal for Serial Attached SCSI Driver Interface (SDI)	Steve Fairchild and Rob Elliott	PDF (91803)
04-345r1	Project proposal for Serial Attached SCSI Driver Interface (SDI)	Steve Fairchild and Rob Elliott	PDF (26469)
04-346r0	SAS-1.1 SMP initiator state machine corrections	Rob Elliott	PDF (64880)
04-347r0	Minutes: ADI Conference Call (21 October 2004)	Michael Banther	PDF (36438)
04-348r0	Add more error handling to ADT encapsulated SCSI protocol	Paul Entzel	PDF (21169)
04-348r1	Add more error handling to ADT encapsulated SCSI protocol	Paul Entzel	PDF (22880)
04-348r2	Add more error handling to ADT encapsulated SCSI protocol	Paul Entzel	PDF (22725)
04-349r0	SPC-3 MMC-5 Merge PREVENT ALLOW MEDIUM REMOVAL commands	Rob Elliott	PDF (114604)
04-349r1	SPC-3 MMC-5 Merge PREVENT ALLOW MEDIUM REMOVAL commands	Rob Elliott	PDF (114804)
04-350r0	ADT Guidance on state machines	Michael Banther	PDF (110650)
04-351r0	Letter Ballot Jeopardy - October 25, 2003	John Lohmeyer	PDF (103840)
04-352r0	SAS-1.1 Phy test functions for SMP	Rob Elliott	PDF (86098)
04-352r1	SAS-1.1 Phy test functions for SMP	Rob Elliott	PDF (33200)
04-353r0	Minutes: ADI Conference Call (28 October 2004)	Michael Banther	PDF (45744)
04-354r0	SAS 1.1 PHY common mode transient reference paper	Alvin Cox	PDF (187714)
04-355r0	Response to T10 Letter Ballot comments on SPC-3	Ralph O. Weber	PDF (1272235)
04-355r1	Response to T10 Letter Ballot comments on SPC-3	Ralph O. Weber	PDF (1638653)
04-356r0	Minutes SAS 1.1 PHY working group conference call October 28, 2004	Alvin Cox	PDF (21327)
04-357r0	SAS-1.1: Another Port Selector Detection Gap	Robert Sheffield	PDF (83534)
04-357r1	SAS-1.1: Another Port Selector Detection Gap	Robert Sheffield	PDF (77366)
04-358r0	SSC-3 Investigation of TapeAlert deficiencies	Michael Banther	PDF (55199)
04-359r0	Minutes: ADI Conference Call (1 November 2004)	Michael Banther	PDF (40660)
04-360r0	ISO IR Status Report Nov 2004	Gary S. Robinson	PDF (48813)
04-360r1	ISO Status Report	Gary S. Robinson	PDF (54085)
04-361r0	T11 Liaison Report, October 2004	Robert Snively	PDF (10854)
04-361r1	T11 Liaison Report, October 2004	Robert Snively	PDF (5143)
04-361r2	T11 Liaison Report, October 2004	Robert Snively	PDF (10852)
04-362r0	SBC-2: Proposal for USB Solid State Drive Mode Sense specification	Martin R. Furuholm	PDF (30831)
04-363r0	SAS-1.1 DONE Timeout vs ACK NAK Timeout race condition note	Rob Elliott	PDF (66726)
04-364r0	Add a new ADT Link Service IU - Device Reset IU	Matthew Bondurant	PDF (33953)
04-365r0	Minutes of SAT Working Group - Nov 9, 2004	Mark Evans	PDF (82676)
04-366r0	Minutes of SAS Protocol Working Group - Nov 8, 2004	Weber & Lohmeyer	PDF (57341)
04-367r0	Minutes of CAP Working Group - Nov 9-10, 2004	Weber & Lohmeyer	PDF (67986)
04-367r1	Minutes of CAP Working Group - Nov 9-10, 2004	Weber & Lohmeyer	PDF (68041)
04-368r0	Minutes of T10 Plenary Meeting #64 - Nov 11, 2004	Weber & Lohmeyer	PDF (252452)
04-369r0	ADT Port State Machine, IU Statements in State Sub-clause	Michael Banther	PDF (67453)
04-370r0	SAS-1.1 Merge IT and IR with XT and XR	Rob Elliott	PDF (320092)
04-372r0	SAM-4 SAS-1.1 I_T NEXUS LOSS task management function	Rob Elliott	PDF (88701)
04-372r1	SAM-4 SAS-1.1 I_T NEXUS LOSS task management function	Rob Elliott	PDF (98773)
04-373r0	SSC-3 model sub clause for WORM	Paul Entzel	PDF (19207)
04-374r0	SES-2 Define a SAS Expander element	Rob Elliott	PDF (86305)
04-375r0	SAS 1.1, Phy hot plug and transients on SAS and SAS/SATA environments	Dick Uber	PDF (31730)
04-376r0	SAM-4 SAS-1.1 Task priority cleanup	Rob Elliott	PDF (85758)
04-376r1	SAM-4 SAS-1.1 Task priority cleanup	Rob Elliott	PDF (86546)
04-377r0	SES-2 Download Microcode diagnostic page	Rob Elliott and Dennis Spicher	PDF (45938)
04-378r0	SAS-1.1 Clarification of SATA Signaling Level Specification	Barry Olawsky	PDF (2403462)
04-379r0	ADT Discarding During Port Logout	Michael Banther	PDF (52737)
04-379r1	ADT Discarding During Port Logout	Michael Banther	PDF (53923)

04-380r0	ADT Optional Hard Reset Signal	Michael Banther	PDF (61186)
04-381r0	ADT TE Sub-state Machine, IU Statements in State Description Sub-clause	Michael Banther	PDF (57417)
04-382r0	SES-2 Subenclosure Nickname diagnostic page	Rob Elliott	PDF (34695)
04-382r1	SES-2 Subenclosure Nickname diagnostic page	Rob Elliott	PDF (98232)
04-383r0	FCP-3 Clarification to TPRLO	Michael Banther	PDF (75609)
04-384r0	MMC Command Set Enabling Video Copy Protection for theDVD+R/+RW Recording Format	William P. McFerrin	PDF (199760)
04-384r1	MMC Command Set Enabling Video Copy Protection for theDVD+R/+RW Recording Format	W. McFerrin	PDF (209049)
04-385r0	Minutes: ADI Meeting (8 November 2004)	Michael Banther	PDF (64689)
04-386r0	Minutes: SMC-3 Meeting (8 November 2004)	Michael Banther	PDF (34410)
04-387r0	FCP-3: FCP_DATA IU Clarification	David Peterson	PDF (26946)
04-388r0	FCP-3: Working Group Agenda (11/9/04)	David Peterson	PDF (9756)
04-389r0	SPC-3: Log Parameter Subpages	Kevin Butt	PDF (94594)
04-390r0	Minutes: SSC-3 Nov 2004	Kevin Butt	PDF (108834)
04-391r0	SAT: Remaining Work Items	Robert Sheffield	PDF (21003)
04-393r0	SSC-3 Working Group Agenda (11/10/04)	David Peterson	PDF (10085)
04-394r0	Minutes: SAS 1.1 Physical Working Group Minutes November 2004	Alvin Cox	PDF (19996)
04-395r0	Minutes of FCP-3 Protocol Working Group - Nov 9, 2004	Bob Nixon	PDF (29836)
04-396r0	SAT: SCSI / ATA Translation November Project Status Report	Robert Sheffield	PDF (36867)
04-398r0	SNIA Liaison Report 11/2004	Roger Cummings	PDF (30768)
04-399r0	STA T10 Update - November 11, 2004	Marty Czekalski	PDF (132685)
04-400r0	Agenda for T10 Meeting #645(January 2005)	John Lohmeyer	PDF (68081)
04-401r0	T10 Project Summary - November 2004	John Lohmeyer	PDF (52751)
04-402r0	Jeopardy Letter for January 2005 meeting	John Lohmeyer	PDF (98834)
04-403r0	Multimedia Command Set Description for Write-once Blu-ray Disc (BD-R)	William P. McFerrin	PDF (147923)
04-404r0	Minutes: November 2004 MMC WG Meeting Minutes	William P. McFerrin	PDF (10789)

<u>Description</u>	<u>Rev PL / Editor</u>	<u>File Size</u>
Automation/Drive Interface - Commands (ADC)	07 Rod Wideman	PDF (451191)
Automation/Drive Interface - Transport Layer (ADT)	13a Paul Entzel	PDF (598625)
Automation/Drive Interface - Transport Layer (ADT)	14 Paul Entzel	PDF (1018702)
MultiMedia Command Set - 4 (MMC-4)	04 Bill McFerrin	PDF (3500031)
MultiMedia Command Set - 4 (MMC-4)	05 Bill McFerrin	PDF (3500375)
MultiMedia Command Set - 5 (MMC-5)	00 Bill McFerrin	PDF (3537519)
MultiMedia Command Set - 5 (MMC-5)	01 Bill McFerrin	PDF (3532567)
Object-Based Storage Devices - 2 (OSD-2)	00 Ralph Weber	PDF (1313078)
SCSI / ATA Translation	01 Bob Sheffield	PDF (849802)
SCSI Block Commands - 2 (SBC-2)	15b Rob Elliott	PDF (1206346)
SCSI Block Commands - 2 (SBC-2)	16 Rob Elliott	PDF (1170146)
SCSI Primary Commands - 3 (SPC-3)	21a Ralph Weber	PDF (2975795)
Serial Attached SCSI - 1.1 (SAS-1.1)	06 Rob Elliott	PDF (4502722)