

Accredited Standards Committee<sup>\*</sup>  
**National Committee for Information Technology Standards (NCITS)**

**Doc. No.:** T10/00-108r0

**Date:** December 1, 1999

**Project:** 1228-D

**Ref. Doc.:** T10/99-333r0

**Reply to:** John Lohmeyer  
(719) 533-7560

Mr. Paul A. Suhler  
Seagate Technology  
1650 Sunflower Ave.  
Costa Mesa, CA 97626  
paul\_a\_suhler@notes.seagate.com

Dear Mr. Suhler,

Thank you for your public review comment on NCITS BSR 333, Multimedia Commands - 2 (MMC-2), contained in T10/99-333r0 at <ftp://ftp.t10.org/t10/document.99/99-333r0.pdf>. The T10 Technical Committee elected to not make any changes to the MMC-2 draft standard and responded to your comment as follows:

"It is the opinion of the MMC working group that this bit is not required for multimedia devices. When loading CD or DVD media into changers there is no intermediate or hold position. The media is either loaded and ready to play/read or is not loaded at all."

Per the NCITS rules, I am required to inform you that you have 20 working days from the date of this letter to reply and indicate if your comments have not been satisfactorily resolved.

Once again, thank you for your interest in the Multimedia Commands - 2 draft standard.

Sincerely yours,



John Lohmeyer, Chair T10

cc: Deborah Donovan, NCITS Secretariat