

Outstanding Standards Contributions regarding ISO/IEC JTC 1/SC 25/WG 4			Gary S Robinson T10 and T11 IR	
			5/2/01	
Project No.	Short Title	last doc. published	Date	GSR Comments from/for T1n
	FDDI			
1.25.13.01.03	FDDI PHY	IS 9314-1:1989		
1.25.13.01.04	FDDI MAC	IS 9314-2:1989		
1.25.13.01.05	FDDI PMD	IS 9314-3:1990		
1.25.13.01.06	FDDI SMF-PMD	IS 9314-4:1999		
1.25.13.01.07	FDDI HRC	IS 9314-5:1995		
1.25.13.01.08	FDDI SMT	IS 9314-6:1998		
1.25.13.01.09	FDDI LCF-PMD	IS 9314-9:2000		
1.25.13.01.10	FDDI TP-PMD	FCD 9314-10 (in 01/00)		
1.25.13.01.11	FDDI MAC-2	IS 9318-8:1998		
1.25.13.01.12	FDDI PHY-2	IS 9314-6:1998		
1.25.13.01.15	FDDI CT-PICS	IS 9314-13:1998		
1.25.13.01.20	FDDI PMD-ATS	IS 9314-20:200X	3/14/01	Published
1.25.13.01.21	FDDI PHY-ATS	IS 9314-21:2000		
1.25.13.01.25	FDDI SMT-ATS	IS 9314-25:1998		
1.25.13.01.26	FDDI MAC-ATS	IS 9314-26:200X		
	IPI			
1.25.13.10.09	IPI-3 Tape	IS 9318-4:1990 -- DIS 18353 as revision (in 02/99)	3/12/01	I edited using DoC N674, RC to add Annex B, then goes to Gbarta.
1.25.13.10.18	Responsive Link	none		
	SCSI			
1.25.13.10.13, 1.25.13.11.01	SCSI-2	IS 9316:1995		
1.25.13.11.02	SCSI-2 CAM	IS 9316-2:2000		
1.25.13.11.03	SCSI-3 SPC	CD 14776-311 (in 11/97)		
1.25.13.11.08	SCSI-3 SAM	IS 14776-411:1999		
1.25.13.11.10	SCSI-3 SBC	FCD 14776-321 (in 09/00)	5/1/01	Approved NP n5463 and FCD 3/2001, voting of FCD in N692, generate DoC and insert into text. No major comments.
1.25.13.11.11	SCSI-3 SSC	CD 14776-331 (in 12/00)	5/1/01	Approved NP N704, and CD 4/2001, voting of CD in N709, generate DoC and insert into text. No major comments.
1.25.13.11.nn	SCSI-3 SSC	NP	3/12/01	NP initiate in T10 3/2001 T10 Project 0997D sc25 n678
1.25.13.11.nm	SCSI-3 SSC2			
1.25.13.11.13	SCSI-3 SMC	CD 14776-351 (in 04/98)		
1.25.13.11.15	SCSI-3 SCC	IS 14776-341:2000		
1.25.13.11.16	SCSI OMC	IS 14776-381:2000		
1.25.13.11.17	SCSI MMC-2	FCD 14776-362 (in 11/00)	5/1/01	Approved NP N706, and CD 4/2001, voting of CD in N610, generate DoC and insert into text. No major comments.
1.25.13.11.18	SCSI FCP-2	none		
1.25.13.11.19	SCSI SAM-2	none		
1.25.13.11.20	SCSI SBP-2	DIS 14776-232 (in 03/00)	5/1/01	need final IS and look at DoC 677, PJ reviewed, GSR to check document for submittal, PJohansson editor
1.25.13.11.21	SCSI SPI-2	CD 14776-112 (in 04/98)	5/1/01	G Penoki Editor, waiting for response from JTC1 Editor to fix and send final, ISO balloting on FDIS
1.25.13.11.22	SCSI-3 SES	CD 14776-371 (in 04/98)		
1.25.13.11.23	SCSI SCC-2	IS 14776-342:2000		
1.25.13.11.25	SCSI RBC	CD 14776-326 (in 10/00)	5/1/01	Approved NP N689, and CD 4/2001, voting of CD in N684, generate DoC and insert into text. No major comments.
1.25.13.11.26	SCSI SPI-3	FCD 14776-113 (in 08/00)	3/12/01	Approved SC 25 N 683

1.25.13.11.27	SCSI SPC-2	none		
1.25.13.11.28	SCSI SPC-4	none		
1.25.13.11.29	SCSI MMC-3	none		
1.25.13.11.30	SCSI RMC	none		
1.25.13.11.31	SCSI SBC-2	none		
1.25.13.11.32	SCSI SST	none		
1.25.13.11.33	SCSI SPC-3	none		
1.25.13.11.34	SCSI SVP	none		
1.25.13.13.02	SCSI-3 FCP	CD 14776-221 (in 04/98)		
	HIPPI			
1.25.13.12.01	HIPPI-PH	IS 11518-1:1995		
1.25.13.12.02	HIPPI-FP	IS 11518-2:2000		
1.25.13.12.03	HIPPI-LE	IS 11518-3:1996		
1.25.13.12.06	HIPPI-SC	IS 11518-6:2000		
1.25.13.12.08	HIPPI-ATM	IS 11518-8:1999		
1.25.13.12.09	HIPPI-Serial	IS 11518-9:1999		
1.25.13.12.10	HIPPI-6400-PH	IS 11518-10:200X	3/21/01	<i>Published</i>
1.25.13.12.11	HIPPI-6400-SC	none		
1.25.13.12.12	HIPPI-6400-OPT	none		
	FC			
1.25.13.13.01	FC-PH	DIS 14165-111 (in 05/98)	4/12/01	<i>Replace PH, PH-2, and DAM1 & DAM2 with 2 new documents</i>
1.25.13.13.04	FC-FP	IS 14165-211		
1.25.13.13.05	FC-FG	FDIS 14165-141 (in 02/01)	3/1/01	<i>Ed Grivna sent T11 results to DD</i>
1.25.13.13.06	FC-AL-2	FCD 14165-122 (in 11/00)	4/12/01	<i>Approved FCD ballot at 4/12/01 T11 meeting, sent to DD, 1the voting results and the collation of comments, SC 25 N 705, as a doc with the kind request to prepare a resolution of comments. 2 for the CD as it was distributed in SC 25; SC 25 N 672, I have no doc but I attach the pdf used with the kind request to revise the text according to the resolutions of comment ready for FDIS voting. Please use the IEC template when finishing the doc.</i>
1.25.13.13.11	FC-SB-2	NWIP approved (in 02/96)	2/8/01	<i>Got approval at T11, Rdugan, sent draft to DD for Fast Track, still in Public Review due Aug 2001</i>
1.25.13.13.12	FC-SW	IS 14165-131:2000		
1.25.13.13.14	FC-PH-2	CD 14165-141 (in 10/96)		<i>K.C. Chennarpan IBM</i>
1.25.13.13.15	FC-GS-2	NWIP approved (in 02/96)		
1.25.13.13.16	FC-PH-3	CD 14165-113 (in 10/96)		<i>Bryan Cook IBM</i>
1.25.13.13.18	FC-AV	none		
1.25.13.13.20	FC-BB	none	4/12/01	<i>IR needs to generate NP , Murali Rajagopal editor, in public review</i>
1.25.13.13.21	FC-100-TP	NWIP approved (in 09/99)		<i>need draft for review in T11</i>
1.25.13.13.22	FC-FS	none		
1.25.13.13.23	FC-GS-3	none		
1.25.13.13.24	FC-PI	none		
1.25.13.13.25	FC-SW-2	none		
1.25.13.13.26	FC-VI	none		
	ST			
1.25.13.14.01	ST	none		
1.25.13.14.02	ST-API	none	4/12/01	
1.25.13.14.nn	ST-RTP	none	4/12/01	<i>Motion to withdraw failed @ T11 4/01 meeting,</i>
	HPSB			
1.25.13.15.01	HPSB	none		
	SC25WG4_OpenItems_GSR.xls		5/2/01	2 of 4

	former SC26 projects: Microprocessor Architecture			
1.25.26.01.01	Bin Flpt Arithm	IEC 60559:1989		
1.25.26.01.02	MUFOM	IEC 60975:1989		
1.25.26.01.03	CSR	IS 13213:1994		
	former SC26 projects: Bus Architecture			
1.25.26.02.01	Multibus I - Part 1	IEC 60796-1:1990		
1.25.26.02.02	Multibus I - Part 2	IEC 60796-2:1990		
1.25.26.02.03	Multibus I - Part 3	IEC 60796-3:1990		
1.25.26.02.04	VMEbus	IEC 60821:1991, IEC 60821-am1:1999		
1.25.26.02.05	VSB, VMEbus parallel	IEC 60822:1988		
1.25.26.02.06	VSSbus, VMEbus serial	IEC 60823:1990		
1.25.26.02.07	Futurebus+	IS 10857:1994		
1.25.26.02.08	STEbus	IS 10859:1997		
1.25.26.02.09	Multibus II	IS 10861:1994		
1.25.26.02.10	VICbus	IS 11458:1993, IS 11458-am1:2000		
1.25.26.02.11	SCI	IS 13961:2000		
1.25.26.02.12	Futurebus+ Profile M	IS 14536:1995		
1.25.26.02.13	HIC	IS 14575:2000		
1.25.26.02.14	STbus	IS 14576:1999		
1.25.26.02.15	Sbus	IS 15205:2000		
1.25.26.02.16	VME64	IS 15776:200X		
1.25.26.03.01	Terminology	IEC 60824:1988		
1.25.26.03.02	Pin allocations	IEC 60828:1988		
Note(s):				