

Outstanding Standards Contributions regarding ISO/IEC JTC 1/SC 25/WG 4				Gary S Robinson T10 and T11 T11/01-289v0	
				6/6/01	
Project No.	Short Title	Project #	last doc. published	Date	GSR Comments from/for T1n
	<b>FDDI</b>				
1.25.13.01.03	FDDI PHY		IS 9314-1:1989		
1.25.13.01.04	FDDI MAC		IS 9314-2:1989		
1.25.13.01.05	FDDI PMD		IS 9314-3:1990		
1.25.13.01.06	FDDI SMF-PMD		IS 9314-4:1999		
1.25.13.01.07	FDDI HRC		IS 9314-5:1995		
1.25.13.01.08	FDDI SMT		IS 9314-6:1998		
1.25.13.01.09	FDDI LCF-PMD		IS 9314-9:2000		
1.25.13.01.10	FDDI TP-PMD		FCD 9314-10 (in 01/00)		
1.25.13.01.11	FDDI MAC-2		IS 9318-8:1998		
1.25.13.01.12	FDDI PHY-2		IS 9314-6:1998		
1.25.13.01.15	FDDI CT-PICS		IS 9314-13:1998		
1.25.13.01.20	FDDI PMD-ATS		IS 9314-20:200X	3/14/01	Published
1.25.13.01.21	FDDI PHY-ATS		IS 9314-21:2000		
1.25.13.01.25	FDDI SMT-ATS		IS 9314-25:1998		
1.25.13.01.26	FDDI MAC-ATS		IS 9314-26:200X		
	<b>IPI</b>				
1.25.13.10.09	IPI-3 Tape		IS 9318-4:1990 -- DIS 18353 as revision (in 02/99)	7/12/01	I edited using DoC N674, RC to add Annex B, in mail, then goes to Gbarta. IN publication process
1.25.13.10.18	Responsive Link		none		
	<b>SCSI</b>				
1.25.13.10.13, 1.25.13.11.01	SCSI-2	0375-m	IS 9316:1995		
1.25.13.11.02	SCSI-2 CAM		IS 9316-2:2000		
1.25.13.11.03	SCSI-3 SPC	0995-m	CD 14776-311 (in 11/97)		
1.25.13.11.08	SCSI-3 SAM	0994-m	IS 14776-411:1999		
1.25.13.11.10	SCSI-3 SBC	0996-m	FCD 14776-321 (in 09/00)	7/12/01	CoC n712 FCD, nxst FDIS, Sent et & DoC WVP, out for approval as IS
1.25.13.11.11	SCSI-3 SSC	0997-d	CD 14776-331 (in 12/00)	7/12/01	CoC n709 CD, nxst FCD, uet to WVP, being edited to conform to ISO style, then will go to ballot
1.25.13.11.nm	SCSI-3 SSC2	1434-d			
1.25.13.11.13	SCSI-3 SMC	0999-m	CD 14776-351 (in 04/98)		
1.25.13.11.15	SCSI-3 SCC		IS 14776-341:2000		
1.25.13.11.16	SCSI OMC		IS 14776-381:2000		
1.25.13.11.17	SCSI MMC-2	1228-d	FCD 14776-362 (in 11/00)	7/12/01	Approved NP N706, and CD 4/2001, voting of CD in N610 , sent DoC to WVP, out for approval as IS
1.25.13.11.18	SCSI FCP-2	1144-d	none		
1.25.13.11.19	SCSI SAM-2	1157-d	none		
1.25.13.11.20	SCSI SBP-2	1155-m	DIS 14776-232 (in 03/00)	5/11/01	FT, DIS n677,xst IS, et sent to GVA & WVP, PJ editor
1.25.13.11.21	SCSI SPI-2	1142-m	CD 14776-112 (in 04/98)	7/12/01	G P Editor, FDIS approved , being published as IS
1.25.13.11.22	SCSI-3 SES	1212-m	CD 14776-371 (in 04/98)		
1.25.13.11.23	SCSI SCC-2	1225-m	IS 14776-342:2000		
1.25.13.11.25	SCSI RBC	1240-d	CD 14776-326 (in 10/00)	6/26/01	CoC n714 CD, nxst FDIS, n715, Sent et & DoC WVP
1.25.13.11.26	SCSI SPI-3	1302-d	FCD 14776-113 (in 08/00)	3/12/01	Approved SC 25 N 683
1.25.13.11.27	SCSI SPC-2	1236-d	none		
1.25.13.11.28	SCSI SPC-4		none		

1.25.13.11.29	SCSI MMC-3	1363-d	none		
1.25.13.11.30	SCSI RMC	1364-d	none		
1.25.13.11.31	SCSI SBC-2	1417-d	none		
1.25.13.11.32	SCSI SST	1380-d	none		
1.25.13.11.33	SCSI SPC-3	1416-d	none		
1.25.13.11.34	SCSI SRP	1415-d	none		
1.25.13.13.02	SCSI-3 FCP	0993-m	CD 14776-221 (in 04/98)		
	OSD	1355-d			
	SDV	1378-DT			
	SMC-2	1383-D			
	SPI-4	1365-D			
	PIP	1439-D			
	SSM	1414-DT			
	MMC	1048-M			
	SBP-2	1467-D			
	<b>HIPPI</b>				
1.25.13.12.01	HIPPI-PH		IS 11518-1:1995		
1.25.13.12.02	HIPPI-FP		IS 11518-2:2000		
1.25.13.12.03	HIPPI-LE		IS 11518-3:1996	6/5/01	reafirm vote @ T11 6/7/01
1.25.13.12.06	HIPPI-SC		IS 11518-6:2000		
1.25.13.12.08	HIPPI-ATM		IS 11518-8:1999		
1.25.13.12.09	HIPPI-Serial		IS 11518-9:1999		
1.25.13.12.10	HIPPI-6400-PH		IS 11518-10:200X	3/21/01	Published
1.25.13.12.11	HIPPI-6400-SC		none		
1.25.13.12.12	HIPPI-6400-OPT		none		
	<b>FC</b>				
1.25.13.13.01	FC-PH		DIS 14165-111 (in 05/98)	6/5/01	Document not available, what do we do ????
1.25.13.13.04	FC-FP		IS 14165-211		
1.25.13.13.05	FC-FG		FDIS 14165-141 (in 02/01)	5/18/01	WVP sent text to GVA
1.25.13.13.06	FC-AL-2		FCD 14165-122 (in 11/00)	6/5/01	Approved FCD ballot at 4/12/01 T11 meeting, sent to DD. CoC n705, nxst FDIS, need to send DoC to WVP
1.25.13.13.11	FC-SB-2		NWIP approved (in 02/96)	2/8/01	Got approval at T11, Rdugan, sent draft to DD for Fast Track, still in Public Review due Aug 2001
1.25.13.13.12	FC-SW		IS 14165-131:2000		
1.25.13.13.14	FC-PH-2		CD 14165-141 (in 10/96)		K.C. Chennarpan IBM
1.25.13.13.15	FC-GS-2		NWIP approved (in 02/96)		
1.25.13.13.16	FC-PH-3		CD 14165-113 (in 10/96)		Bryan Cook IBM
1.25.13.13.18	FC-AV		none		
1.25.13.13.20	FC-BB		none	4/12/01	IR needs to generate NP , Murali Rajagopal editor, in public review
1.25.13.13.21	FC-100-TP		NWIP approved (in 09/99)		need draft for review in T11
1.25.13.13.22	FC-FS		none		
1.25.13.13.23	FC-GS-3		none		
1.25.13.13.24	FC-PI		none		
1.25.13.13.25	FC-SW-2		none		
1.25.13.13.26	FC-VI		none		
	<b>ST</b>				
1.25.13.14.01	ST		none		
1.25.13.14.02	ST-API		none	4/12/01	
1.25.13.14.nn	ST-RTP		none	4/12/01	Motion to withdraw failed @ T11 4/01 meeting,
	<b>HPSB</b>				
1.25.13.15.01	HPSB		none		

	<b>former SC26 projects: Microprocessor Architecture</b>				
1.25.26.01.01	Bin Flpt Arithm		IEC 60559:1989		
1.25.26.01.02	MUFOM		IEC 60975:1989		
1.25.26.01.03	CSR		IS 13213:1994		
	<b>former SC26 projects: Bus Architecture</b>				
1.25.26.02.01	Multibus I - Part 1		IEC 60796-1:1990		
1.25.26.02.02	Multibus I - Part 2		IEC 60796-2:1990		
1.25.26.02.03	Multibus I - Part 3		IEC 60796-3:1990		
1.25.26.02.04	VMEbus		IEC 60821:1991, IEC 60821-am1:1999		
1.25.26.02.05	VSB, VMEbus parallel		IEC 60822:1988		
1.25.26.02.06	VSSbus, VMEbus serial		IEC 60823:1990		
1.25.26.02.07	Futurebus+		IS 10857:1994		
1.25.26.02.08	STEbus		IS 10859:1997		
1.25.26.02.09	Multibus II		IS 10861:1994		
1.25.26.02.10	VICbus		IS 11458:1993, IS 11458-am1:2000		
1.25.26.02.11	SCI		IS 13961:2000		
1.25.26.02.12	Futurebus+ Profile M		IS 14536:1995		
1.25.26.02.13	HIC		IS 14575:2000		
1.25.26.02.14	STbus		IS 14576:1999		
1.25.26.02.15	Sbus		IS 15205:2000		
1.25.26.02.16	VME64		IS 15776:200X		
1.25.26.03.01	Terminology		IEC 60824:1988		
1.25.26.03.02	Pin allocations		IEC 60828:1988		
1.25.13.15.01	1394 x				
Note(s):					