

Outstanding Standards Contributions regarding ISO/IEC JTC 1/SC 25/WG 4			Gary S Robinson T10/01-275r0 and T11/01-395v2		
				8/31/01	
Project No.	Short Title	Project #	last doc. published	Date	GSR Comments from/for T1n
	FDDI				
1.25.13.01.03	FDDI PHY		IS 9314-1:1989		
1.25.13.01.04	FDDI MAC		IS 9314-2:1989		
1.25.13.01.05	FDDI PMD		IS 9314-3:1990	31-Aug	Do we need to revise (replace EIA ref with IEC ref) N575
1.25.13.01.06	FDDI SMF-PMD		IS 9314-4:1999		
1.25.13.01.07	FDDI HRC		IS 9314-5:1995	8/1/01	5yr review confirmed
1.25.13.01.08	FDDI SMT		IS 9314-6:1998		
1.25.13.01.09	FDDI LCF-PMD		IS 9314-9:2000		
1.25.13.01.10	FDDI TP-PMD		FCD 9314-10 (in 01/00)		
1.25.13.01.11	FDDI MAC-2		IS 9318-8:1998		
1.25.13.01.12	FDDI PHY-2		IS 9314-6:1998		
1.25.13.01.15	FDDI CT-PICS		IS 9314-13:1998		
1.25.13.01.20	FDDI PMD-ATS		IS 9314-20:200X	3/14/01	Published
1.25.13.01.21	FDDI PHY-ATS		IS 9314-21:2000		
1.25.13.01.25	FDDI SMT-ATS		IS 9314-25:1998		
1.25.13.01.26	FDDI MAC-ATS		IS 9314-26:200X		
	IPI				
1.25.13.10.09	IPI-3 Tape		IS 9318-4:1990 -- DIS 18353 as revision (in 02/99)	8/1/01	In publication process
1.25.13.10.18	Responsive Link		none		
	SCSI				
1.25.13.10.13, 1.25.13.11.01	SCSI-2	0375-m	IS 9316:1995	8/1/01	5yr review confirmed
1.25.13.11.02	SCSI-2 CAM		IS 9316-2:2000	31-Aug	published
1.25.13.11.03	SCSI-3 SPC	0995-m	CD 14776-311 (in 11/97)	31-Aug	Ato withdrawal in JTC1, US to drop, need T10 motion
1.25.13.11.08	SCSI-3 SAM	0994-m	IS 14776-411:1999	31-Aug	Editorial error being corrected by WVP for next review cycle
1.25.13.11.10	SCSI-3 SBC	0996-m	FCD 14776-321 (in 09/00)	8/16/01	DoC n712A, FDIS ballot, standard is n631
1.25.13.11.11	SCSI-3 SSC	0997-d	CD 14776-331 (in 12/00)	8/31/01	DoC n709a, nxst FCD n717, motion for FCD done
1.25.13.11.nm	SCSI-3 SSC2	1434-d			
1.25.13.11.13	SCSI-3 SMC	0999-m	CD 14776-351 (in 04/98)	31-Aug	N799, waiting for FCD text
1.25.13.11.15	SCSI-3 SCC		IS 14776-341:2000	31-Aug	published
1.25.13.11.16	SCSI OMC		IS 14776-381:2000	31-Aug	published, US comments too late, not included
1.25.13.11.17	SCSI MMC-2	1228-d	FCD 14776-362 (in 11/00)	8/31/01	Approved NP N706, and CD 4/2001, voting of CD in N610 , sent DoC to WVP, RoC n718, FDIS sent to ITTF
1.25.13.11.18	SCSI FCP-2	1144-d	none	31-Aug	waiting for NP and document, need status
1.25.13.11.19	SCSI SAM-2	1157-d	none		
1.25.13.11.20	SCSI SBP-2	1155-m	DIS 14776-232 (in 03/00)	8/31/01	FT, DIS n677,xst IS, et sent to GVA & WVP, PJ editor, waiting for publication
1.25.13.11.21	SCSI SPI-2	1142-m	CD 14776-112 (in 04/98)	8/1/01	G P Editor, sent to GVA for final processing, FDIS approved, need revised patent letter
1.25.13.11.22	SCSI-3 SES	1212-m	CD 14776-371 (in 04/98)	31-Aug	waiting for FCD test, N529, need status
1.25.13.11.23	SCSI SCC-2	1225-m	IS 14776-342:2000	31-Aug	published
1.25.13.11.25	SCSI RBC	1240-d	CD 14776-326 (in 10/00)	8/31/01	CoC n684 CD, nxst FDIS, Sent et & DoC WVP, DoC 714, FCD n715 ballot
1.25.13.11.26	SCSI SPI-3	1302-d	FCD 14776-113 (in 08/00)	8/31/01	Editor GP, FCD Approved, CoC SC 25 N 683, sent to GP for DoC and updating, DoC finished, text updated, send to WVP, need T10 motion
1.25.13.11.27	SCSI SPC-2	1236-d	none	31-Aug	waiting for NP and document, need status

1.25.13.11.28	SCSI SPC-4	1365-d	none	8/31/01	<i>need NP and document, need status</i>
1.25.13.11.29	SCSI MMC-3	1363-d	none	31-Aug	<i>need NP and document, need status</i>
1.25.13.11.30	SCSI RMC	1364-d	none	31-Aug	<i>cancelled</i>
1.25.13.11.31	SCSI SBC-2	1417-d	none	31-Aug	<i>need NP and document, need status</i>
1.25.13.11.32	SCSI SST	1380-d	none	31-Aug	<i>need NP and document, need status</i>
1.25.13.11.33	SCSI SPC-3	1416-d	none	31-Aug	<i>need NP and document, need status</i>
1.25.13.11.34	SCSI SRP	1415-d	none	31-Aug	<i>need NP and document, need status</i>
	OSD	1355-d			
	SDV	1378-DT			
	SMC-2	1383-D			
	SPI-4	1365-D			
	PIP	1439-D			
	SSM	1414-DT			
	MMC	1048-M			
	SBP-2	1467-D			
	HIPPI				
1.25.13.12.01	HIPPI-PH		IS 11518-1:1995		
1.25.13.12.02	HIPPI-FP		IS 11518-2:2000		
1.25.13.12.03	HIPPI-LE		IS 11518-3:1996	8/1/01	<i>5yr review reaffirmed</i>
1.25.13.12.06	HIPPI-SC		IS 11518-6:2000		
1.25.13.12.08	HIPPI-ATM		IS 11518-8:1999		
1.25.13.12.09	HIPPI-Serial		IS 11518-9:1999		
1.25.13.12.10	HIPPI-6400-PH		IS 11518-10:200X	3/21/01	<i>Published</i>
1.25.13.12.11	HIPPI-6400-SC		none	31-Aug	<i>waiting for NP, need status</i>
1.25.13.12.12	HIPPI-6400-OPT		none	31-Aug	<i>waiting for NP, need status</i>
	FC				
1.25.13.13.01	FC-PH		DIS 14165-111 (in 05/98)	8/31/01	<i>Document not available, request withdrawal in future, to be replaced by PI and FS</i>
1.25.13.13.02	SCSI-3 FCP	0993-m	CD 14776-221 (in 04/98)		
1.25.13.13.04	FC-FP		IS 14165-211		IS 14165-211: 99-02
1.25.13.13.05	FC-FG		FDIS 14165-141 (in 02/01)	8/31/01	<i>published</i>
1.25.13.13.06	FC-AL-2		FCD 14165-122 (in 11/00)	8/31/01	<i>CoC N705, FCD DoC generated, HT making changes to .WP file, next FDIS ballot, need to send DoC and text to WVP</i>
1.25.13.13.11	FC-SB-2		NWIP approved (in 02/96)	8/31/01	<i>NWIP approved, send FCD text with ISO changes</i>
1.25.13.13.12	FC-SW		IS 14165-131:2000	31-Aug	<i>published</i>
1.25.13.13.14	FC-PH-2		CD 14165-112 (in 10/96)	31-Aug	<i>to be dropped</i>
1.25.13.13.15	FC-GS-2		NWIP approved (in 02/96)	8/31/01	14165-412, JTC1 N5881/N6025, waiting for FCD test
1.25.13.13.16	FC-PH-3		CD 14165-113 (in 10/96)	8/31/01	<i>to be dropped</i>
1.25.13.13.18	FC-AV		14165-321	31-Aug	<i>waiting for NP, need status</i>
1.25.13.13.20	FC-BB		14165-241	8/16/01	<i>Generated NP, SC25 will issue NP, MR editor, in public review, may add BB-2 as comments to CD</i>
1.25.13.13.21	FC-100-TP		NP14165-114	31-Aug	<i>need draft for review in T11, JTC! N5813, from Germany in Sep 2001</i>
1.25.13.13.22	FC-FS		Res14165-251	31-Aug	<i>JTC! N5813, need NP, need status</i>
1.25.13.13.23	FC-GS-3		Res14165-413	31-Aug	<i>need NP, need status</i>
1.25.13.13.24	FC-PI		Res14165-115	31-Aug	<i>need NP, need status</i>
1.25.13.13.25	FC-SW-2		Res14165-132	31-Aug	<i>need NP, need status</i>
1.25.13.13.26	FC-VI		Res14165-331	31-Aug	<i>need NP, need status</i>
	ST				
1.25.13.14.01	ST		none	31-Aug	<i>need status, do we need NP or FT</i>
1.25.13.14.02	ST-API		none	8/31/01	<i>need status, do we need NP or FT</i>
1.25.13.14.nn	ST-RTP		none	4/12/01	<i>Motion to withdraw failed @ T11 4/01 meeting,</i>
	HPSB				
1.25.13.15.01	HPSB		none		

	former SC26 projects: Microprocessor Architecture				
1.25.26.01.01	Bin Flpt Arithm	754	IEC 60559:1989	31-Aug	<i>Reaffirm, Pritchard wants to revise, do we revise or reaffirm ?</i>
1.25.26.01.02	MUFOM		IEC 60975:1989	31-Aug	<i>withdrawn</i>
1.25.26.01.03	CSR		IS 13213:1994	31-Aug	<i>confirmed 5yr</i>
	former SC26 projects: Bus Architecture				
1.25.26.02.01	Multibus I - Part 1		IEC 60796-1:1990		
1.25.26.02.02	Multibus I - Part 2		IEC 60796-2:1990		
1.25.26.02.03	Multibus I - Part 3		IEC 60796-3:1990		
1.25.26.02.04	VMEbus		IEC 60821:1991, IEC 60821-am1:1999	31-Aug	<i>confirm</i>
1.25.26.02.05	VSB, VMEbus parallel		IEC 60822:1988	31-Aug	<i>confirm</i>
1.25.26.02.06	VSSbus, VMEbus serial		IEC 60823:1990	31-Aug	<i>drop</i>
1.25.26.02.07	Futurebus+		IS 10857:1994	31-Aug	<i>drop</i>
1.25.26.02.08	STEBus		IS 10859:1997		
1.25.26.02.09	Multibus II		IS 10861:1994		
1.25.26.02.10	VICbus		IS 11458:1993, IS 11458-am1:2000	31-Aug	<i>published</i>
1.25.26.02.11	SCI		IS 13961:2000	31-Aug	<i>published</i>
1.25.26.02.12	Futurebus+ Profile M		IS 14536:1995	31-Aug	<i>need status</i>
1.25.26.02.13	HIC		IS 14575:2000	31-Aug	<i>published</i>
1.25.26.02.14	STbus		IS 14576:1999	31-Aug	<i>published</i>
1.25.26.02.15	Sbus		IS 15205:2000	31-Aug	<i>published</i>
1.25.26.02.16	VME64		IS 15776:200X		
1.25.26.03.01	Terminology		IEC 60824:1988		
1.25.26.03.02	Pin allocations		IEC 60828:1988		
1.25.13.15.01	1394 x			8/31/01	<i>NP in ballot in US, document still being prepared</i>
Note(s):					