Voting Results on T10 Letter Ballot 01-300r0 on Forwarding SRP to first public review

Organi zati on	Name	S Vote Add'l Info
Adaptec, Inc.	Ron Roberts	P Yes
Amphenol Interconnect	Mi chael Wingard	P Yes
Ancot Corp.	Bart Raudebaugh	P Yes
Andiamo Systems, Inc.	Claudio DeSanti	P Yes
BREA Technologies, Inc.	Bill Galloway	P Yes
Brocade Comm. Systems, Inc.	Brian Forbes	A YesC Cmnts
Cisco Systems, Inc.	David Peterson	P Yes
Compaq Computer Corp.	Robert C. Elliott	P YesC Cmnts
Congruent Software, Inc.	Peter Johansson	P Yes
Crossroads Systems, Inc.	Robert Griswold	P Yes
Dallas Semi conductor	Ti tkwan Hui	P Yes
Dell Computer Corp.	Kevin Marks	P Yes
EMC	Gary S. Robinson	P Yes
Emulex		DNV
ENDL Texas	Ralph O. Weber	P Yes
Exabyte Corp.	Joe Breher	P Yes
FCI	Douglas Wagner	P Yes
Fujitsu	Eugene Lew	P Yes
General Dynamics	Nathan Hastad	P Yes
Genroco, Inc.	Donald Woelz	P Yes
Hewlett Packard Co.		DNV
Hitachi Cable Manchester	Randy Wasylak	A Yes
IBM / Tivoli Systems	George O. Penoki e	P No Cmnts
Intel Corp.	Cris Simpson	P No Cmnts
lomega Corp.	Tim Bradshaw	P Yes
Knowl edgeTek, Inc.	Dennis Moore	P Yes
LSI Logic Corp.	John Lohmeyer	P Yes
Maxtor Corp.	Mark Evans	P Yes
Mi crosoft Corp.		DNV
Molex Inc.		DNV
Ni shan Systems Inc.	Charles Monia	P Yes
Ophi di an Desi gns	Edward A. Gardner	P No Cmnts
Panasoni c Technol ogi es, Inc	Terence J. Nelson	P Yes
Philips Electronics/CD Edge	William P. McFerrin	P Yes
Pirus Networks	Chi a lama	DNV
QLogi c Corp.	Skip Jones	P Yes
Quantum Corp.	Paul Entzel	P Yes
Seagate Technology	Gerald Houlder	P Yes
Storage Technology Corp. Sun Microsystems, Inc.	Erich Oetting	P Yes
Texas Instruments	Kenneth Moe	P Yes P YesC Cmnts
	Paul D. Aloisi	P Yes
Toshiba America Elec. Comp. Troika Networks, Inc.	Tasuku Kasebayashi	DNV
	Charles Brill	P Yes
TycoEl ectronics Veritas Software	Charles Billi	
Woven Electronics	Doug Piper	DNV P Abs Cmnts
MOAGII FLECTIONIC2	body Fipel	I MUS CIIIITES
Ballot totals: (35: 3: 1: 7=46) 35 Yes		

- 3 No
- 1 Abstain
- 7 Organization(s) did not vote 46 Total voting organizations
- 7 Ballot(s) included comments

This 2/3rds majority ballot passed.

35 Yes is at least a majority of the membership [greater than 23] AND 35 Yes is at least 26 (2/3rds of those voting, excluding abstentions [38])

Key:

Ρ Voter is principal member Α Voter is alternate member Yes with comments vote YesC

Abs Abstain vote

DNV Organization did not vote

Comments were included with ballot NoCmnts No comments were included with a vote that requires comments Duplicate ballot (last ballot received from org. is counted) **PSWD** The password was not correct (vote not counted) ORG? Organization is not voting member of T10 (vote not counted) ************** Comments attached to YesC ballot from Mr. Brian Forbes of Brocade Comm. Systems, Inc.: Brocade1 001 (E) Page: Many Locator: Many Problem Description: The word 'which' is used inappropriately in many places. Suggested Solution: Do a global search for the word which and replace it with one of the following corrections: A) the word 'that'. B) a new sentence construction that does not require the word. C) nothing. (Which can simply be removed in many cases.) Brocade1 002 (E) Page: 59 Locator: B.7, figure B.6 Problem Description: The word 'must' is used inappropriately. Suggested Solution: The line 'At least one IB I/O controller must be present' should be replaced. I am not sure if this is a requirement that at one or more controllers shall be present. If so, wording like 'At least one IB I/O controller shall be present' is appropriate. Brocade1 003 (E) Page: vii Locator: Foreword, line 3 Problem Description: X3.269 is not the proper name Suggested Solution: This value is not correct and should be marked as TBD or XXX or something like that. In any case, it is an NCITS document, not an X3 document. Brocade1 004 (E) Page: vii Locator: Foreword, line 8 Problem Description: "by National' s/b 'by the National'" Suggested Solution: Correct as requested. Brocade1 005 (E) Page: viii Locator: Introduction, line 7 Problem Description: "The working draft SCSI' s/b 'The SCSI'" Suggested Solution: This correction should be made now, even though the document is still a working draft, because it is clearly labeled in lots of places that it is a draft, but the text in it is intended to be the content of the standard. Brocade1 006 (E) Page: 1 Locator: Title, line 6 Problem Description: '"The working draft SCSI' s/b 'The SCSI'" Suggested Solution: This correction should be made now, even though the document is still a working draft, because it is clearly labeled in lots of places that it is a draft, but the text in it is intended to be the content of the standard. Brocade1 007 (E) Page: 3 Locator: 2.1, lines 32-35 Problem Description: Global Engineering should be included here as well, since the drafts are not available from ANSI or NCITS. Suggested Solution: Include Global Engineering as a document source. Include www.t10.org as a document source for standards in development.

Locator:

Brocade 0 001

Problem Description:

(E) Page:

The draft now seems to equate 'SRP target port' and 'IB service', so an SRP target port is designated by a ServicelD. This implies there can be many ports per IOC. This is a significant change from prior drafts where the target port was equated with an IOC, and there was just a single ServicelD per port. It requires a different model for software (OSs or whatever) to manage which hosts have access to which devices in a multi-host environment. Previously, access control was needed only to the level of IOCs, the draft now implies a need to manage not only who can use which IOCs, but which devices within an IOC.

Suggested Solution:

No solution required if interpretation is correct and implications are understood

Brocade 0 002 (E) Page: 52 Locator: B. 3. 1. 2, lines 22-23

Problem Description:

The definition of 'IB channel adapter GUID' implies it is the Node GUID but doesn't say so; might as well be explicit Suggested Solution:

'An IB Node GUID that uniquely identifies an IB channel adapater'

Brocade 0 003 (E) Page: 52 Locator: B. 3. 1. 9, lines 39-40 Problem Description:

The definition of 'IB I/O controller GUID' implies it is the

IOControllerProfile GUID but doesn't say so; might as well be explicit Suggested Solution:

'An IB IOControllerProfile GUID that uniquely identifies an IB channel adapater'

Brocade 0 004 (E) Page: 54 Locator: Line 50

Problem Description:

IB GIDs can have link-local scope and thus may not be 'globally' unique Suggested Solution:

Change to 'unique within a subnet', or 'either unique within a subnet or globally unique'

Brocade 0 005 (E) Page: 55 Locator: Table B. 1, lines 16-17 Problem Description:

IB GIDs can have link-local scope and thus may not be unique 'worldwide' Suggested Solution:

Change 'worldwide' to 'IB subnet or worldwide'

Brocade 0 006 (E) Page: 55 Locator: Figure B. 3

Problem Description:

Figure B.3's equating of 'SRP Target Ports' with 'IB consumers' is problematic. A 'target port' is a sort of service access point---somewhere where interested parties initially go to obtain service, but without any implication that that's where the service is actually provided. (In IB, it's the Connection Manager that receives the initial connection request, interprets the ServiceID contained therein, and performs some magic that results in the instantiation of a QP bound to some entity that actually provides the target services). This target-services-providing entity fits the definition of 'IB consumer'. But the mapping of ServiceIDs-cum-SRP target ports onto such entities is clearly a matter of implementation, and could be one-to-many, many-to-one, or many-to-many Suggested Solution:

One possibility: to the left of the IB Consumers show a table/list of service IDs within each IB I/O unit and label these entries as SRP Target Ports; use arrows to show a mapping from the entries to the IB Consumers, with e.g. one Consumer mapped to two IDs and another mapped to one ID to show that the mappings are not always 1 to 1. A further refinement might be to use another set of arrow between the Consumers and the QPs to show that the this mapping is also not 1 to 1

Brocade 0 007 (E) Page: 56 Locator: Line 16

Problem Description:

Missing word

Suggested Solution:

'used by the SRP initiator port'?

Brocade 0 008 (E) Page: 56 Locator: Line 21

Problem Description:

Names of IB attributes are incomplete

Suggested Solution:

'IOUnitInfo, IOControllerProfile, and ServiceEntries'

Brocade 0 009 (E) Page: 56 Locator: Lines 48-49

Problem Description:

'I/O' is broken across lines (and pages)

Suggested Solution:

Make sure the slash in 'I/O' is non-breaking

Brocade 0 010 (E) Page: 56 Locator: Lines 48-49

Problem Description:

The phrase 'processor unit or IB I/O controller' makes an incorrect distinction; target ports can only be found on IB I/O controllers by definition, whether or not the I/O controller embodies a processor unit Suggested Solution:

Omit 'processor unit or'

Brocade 0 011 (E) Page: 57 Locator: Lines 13-14

Problem Description:

'IB I/O controllers acting as SRP target ports' could be construed as a 1-to-1 correspondence between controllers and target ports Suggested Solution:

'IB I/O controllers making SRP target ports available' or 'IB I/O controllers hosting SRP target ports'?

Brocade 0 012 (E) Page: 61 Locator: Line 1

Problem Description:

'An IB I/O controller acting as an SRP target ports' could be construed as a 1-to-1 correspondence between controllers and target ports Suggested Solution:

'And IB I/O controller making SRP target ports available' or 'An IB I/O controller hosting SRP target ports'?

Brocade 0 013 (E) Page: 61 Locator: Lines 4-5

Problem Description:

'IB I/O controllers acting as SRP target ports' could be construed as a 1-to-1 correspondence between controllers and target ports Suggested Solution:

'IB I/O controllers making SRP target ports available' or 'IB I/O controllers hosting SRP target ports'?

Comments attached to YesC ballot from Mr. Robert C. Elliott of Compaq Computer Corp.:

CPQ #1 Page a (comment 1 on page)

Title page

Remove:

American National Standard for Information Systems - and change "working draft SCSI RDMA Protocol" to "SCSI RDMA Protocol"

CPQ #2 Page a (comment 2 on page)

General

Update the PDF properties title and author

CPQ #3 Page ii (comment 1 on page)

General

Remove revision history, line numbers, change bars, etc. from final version

CPQ #4 Page 2 (comment 1 on page)

Section 1

Delete CAM from figure 1

Delete these SCSI-2 standards from the example standards list:

Serial Storage Architecture SCSI-2 Protocol SSA-S2P [ANSI X3. 294: 1996]

Common Access Method:

SCSI Common Access Method CAM [ISO/IEC 9316-421] [ANSI X3. 232: 1996] CPQ #5 Page 2 (comment 2 on page) Section 1 Change Fiber to Fibre CPQ #6 Page 5 (comment 1 on page) Add: 3.1.8 autosense data: Sense data (see 3.1.49) that is returned in the SRP_RSP IU payload. See SAM-2. 3.1.49 sense data: Data returned to an application client as a result of an autosense operation, asynchronous event report, or REQUEST SENSE command. See SPC-2. CPQ #7 Page 16 (comment 1 on page) Section 5.3 This section should mention the SRP_CRED_REQ and SRP_CRED_RSP IUs, which are dedicated to flow control service. CPQ #8 Page 18 (comment 1 on page) Section 5.4.2.1 Table 2 Remove period from "NO DATA BUFFER DESCRIPTOR PRESENT." CPQ #9 Page 18 (comment 2 on page) Section 5.4.2.1 Table 2 There is no reference to note b. It probably needs to be in the 2h row buffer descriptor length cell, where "count" is used CPQ #10 Page 18 (comment 3 on page) Section 5.4.2.1 Table 2 Add a period at the end of note c. CPQ #11 Page 19 (comment 1 on page) Section 5.4.2.4 Add a fairly content-free table showing a direct data buffer containing a memory descriptor so this section has a visual reference like the indirect section. CPQ #12 Page 20 (comment 1 on page) Section 5.4.2.5 Table 5 note a count should be defined with a note b similar to that in table 2 CPQ #13 Page 20 (comment 2 on page) Section 5.4.2.5 If n is zero in 16*n+19, then the table shows byte 20 followed by byte 19. Remove the 20 and that numbering problem is eluded. CPQ #14 Page 25 (comment 1 on page) Section 6.2 Change: "maxi mum length" "maximum length in bytes CPQ #15 Page 25 (comment 2 on page) Section 6.2 and elsewhere I thought we decided that TAG fields don't have bits labeled (MSB)/(LSB). CPQ #16 Page 25 (comment 3 on page) Section 6.2 Table 9 The REQUIRED BUFFER FORMATS cell is missing the horizontal lines present in other multibyte cells

```
CPQ #17 Page 26 (comment 1 on page)
Section 6.2
Table 10
Remove period from first Reserved. row
CPQ #18 Page 27 (comment 1 on page)
Section 6.3
Change (two places):
maximum length
"maximum length in bytes"
CPQ #19 Page 29 (comment 1 on page)
Section 6.4
Table 14
Capitalize Reserved
CPQ #20 Page 29 (comment 2 on page)
Section 6.4
Table 13
The SUPPORTED BUFFER FORMATS cell is missing the horizontal lines present
in other multibyte cells
CPQ #21 Page 31 (comment 1 on page)
Section 6.6
Table 17
Add period after Reserved or remove from other rows
CPQ #22 Page 33 (comment 1 on page)
Section 6.7
Rename TASK MANAGEMENT FLAGS to TASK MANAGEMENT FUNCTION. It doesn't really
contain flags.
CPQ #23 Page 33 (comment 2 on page)
Section 6.7
Table 19
end each row with a period (or don't)
CPQ #24 Page 33 (comment 3 on page)
Section 6.7
Table 19
Change Codes to Code.
CPQ #25 Page 33 (comment 4 on page)
Section 6.7
Table 19
Remove small caps from TABLE.
CPQ #26 Page 34 (comment 1 on page)
Section 6.8
Table 20
Per Patrick Fitzgerald at JNI, please require that DATA-OUT BUFFER
DESCRIPTOR and DATA-IN BUFFER DESCRIPTOR start
on 8-byte aligned boundaries. The ADDITIONAL CDB field is only 4 byte
al i gned.
CPQ #27 Page 34 (comment 2 on page)
Section 6.8
Table 20 footnotes
Change:
Length
to:
length in bytes
CPQ #28 Page 35 (comment 1 on page)
Section 6.8
Table 21
SAM-2 rev 20 still requires that untagged tasks be supported by all
protocols. 01-318 will remove this requirement and make SRP legal.
```

Section 7.1

CPQ #29 Page 35 (comment 2 on page) Section 6.8 Table 21 Change a to an in the ACA row CPQ #30 Page 35 (comment 3 on page) Section 6.8 Table 21 Remove small caps from TABLE CPQ #31 Page 38 (comment 1 on page) Section 6.9 After: The STATUS field contains the status of a task that completes. See the SAM-2 standard for a list of status codes. Add this sentence and a table: Some of the status codes defined in SAM-2 are listed in table xx. Table xx - Some STATUS codes 00h G00D 02h CHECK CONDITION 08h BUSY 18h RESERVATION CONFLICT 28h TASK SET FULL 30h ACA ACTIVE 40h TASK ABORTED This helps save the reader a reference to SAM-2 for the most popular CPQ #32 Page 39 (comment 1 on page) Section 6.9 Remove from 2nd sentence of SENSE DATA paragraph: as specified by the SCSI Primary Commands-2 standard. CPQ #33 Page 39 (comment 2 on page) Section 6.9 Reword the SENSE DATA paragraph to focus on the term autosense which is defined in SAM-2 rather than the REQUEST SENSE command in SPC-2. Change: The SENSE DATA field contains the information specified by the SCSI Primary Commands-2 standard for presentation by the REQUEST SENSE command. The proper sense data shall be presented when a SCSI status byte of CHECK CONDITION is presented by the SCSI Primary Commands -2 standard. The SENSE DATA field contains the autosense data (see SCSI Architecture Model - 2) when a SCSI STATUS byte of CHECK CONDITION is presented. CPQ #34 Page 41 (comment 1 on page) Section 6.12 Change report an asynchronous event. report an asynchronous event (see SAM-2). CPQ #35 Page 41 (comment 2 on page) Section 6.12 Add sentence to first paragraph: Parameters managing the use of asynchronous event reporting are contained in the Control mode page (see SPC-2). This sentence is in SAM-2, but a direct reference from SRP seems helpful. CPQ #36 Page 42 (comment 1 on page) Section 6.13 Reword the SENSE DATA paragraph like in 6.9, but don't call it autosense here, call it "sense data for the event". CPQ #37 Page 43 (comment 1 on page)

Table 29 Section 7.3 LUN should be LU

(this is broken in SPC too) - the logical unit number is irrelevent here.

CPQ #38 Page 52 (comment 1 on page)

Annex B

Change (many places):

Infi ni band

to:

Infini Band

CPQ #39 Page 52 (comment 2 on page)

Annex E

There are too many TMs. There only needs to be one per page or one per the whole section.

CPQ #40 Page 62 (comment 1 on page)

Annex (

Ralph Weber agreed to put alias formats for each protocol in SPC-3, so this annex can be removed.

Comments attached to No ballot from Mr. George O. Penokie of IBM $\!\!/$ Tivoli Systems:

General

In my comments the notation 'Page xx' refers to all pages in the standard not roman numeral xx. All comments are editorial unless indicated with a '(T)' at the start of the comment.

PDF Page 3

1: Tivoli comment from George Penokie

Page c - The page numbering in first part of the front matter is a, b, c, and d instead of roman numerals. This needs to be corrected.

PDF Page 4

2: Tivoli comment from George Penokie

Page c - d - The Revision list needs to be removed before public review.

3: Tivoli comment from George Penokie

All - All the line numbers need to be removed throughout the document.

PDF Page 6

4: Tivoli comment from George Penokie

 All - The printing date information at the bottom of every page needs to be removed.

PDF Page 11

5: Tivoli comment from George Penokie

Page vii - Forward - the BSR number x3.269-199x is not correct for this standard. It should be 'NCITS.xxx-200x' until the actual number is assigned. PDF Page 12

6: Tivoli comment from George Penokie

Page viii - Llne 7 - The statement ' The working draft SCSI RDMA Protocol (SRP) standard is divided into the following clauses: ' should be 'The SCSI RDMA Protocol standard is divided into the following clauses:

7: Tivoli comment from George Penokie

All - The acronym SRP should be replaced with 'SCSI RDMA Protocol' in all cases in this document.

PDF Page 13

8: Tivoli comment from George Penokie

Page 1-2 - The following standards should be removed from the list: FC-AL, FC-PH, FC-PH-2, SPI-3, FCP, SPC, and RMC. PDF Page 16

9: Tivoli comment from George Penokie

Page 4 - section 3.1.1 - The last sentence implies that SRP_LOGIN_RSP is the only use for accept data. I believe this is not correct. This should be stated to be an example of accept data.

10: Tivoli comment from George Penokie

All - The full name of a standard should always be used instead of the acronym. This should be change throughout the document.

11: Tivoli comment from George Penokie

Page 4 - line 19 and others - when SRP is used and it is referring to this document then it should be changed to 'this standard'. Line 19 is one case where this appears to be true.

12: Tivoli comment from George Penokie

Page 4 - section 3.1.13 - The statement 'An externally addressable object...' should be 'An. addressable object...'. The term externally implies that the addressing is outside the standard.

13: Tivoli comment from George Penokie

Page 4 - section 3.1.15 - The last sentence implies that SRP_LOGIN_REQ is the only use for login data. If this is not correct. Then this should be stated to be an example of login data.

14: Tivoli comment from George Penokie

Page 4 - section 3.1.15 - The statement '...server agent or consumer...' should be '....server agent or server consumer...'

15: Tivoli comment from George Penokie

Page 4 - section 3.1 - The terms client consumer, server agent, and server consumer should be definitions is the glossary.

PDF Page 17

16: Tivoli comment from George Penokie

Page 5 - section 3.1.22 - The statement '...server agent or consumer...' should be '....server agent or server consumer...'

17: Tivoli comment from George Penokie

Pave 5 - section 3.2 - line 34 - The acronym for SRP implies that in almost all cases SRP should be changed to 'this standard'.

PDF Page 20

18: Tivoli comment from George Penokie

Page 8 - line 5 - The statement 'by means of' should be change to 'using'. 19: Tivoli comment from George Penokie

Page 8 - line 44 - The statement 'established and disconnected' should be either 'established and removed' or 'connected and disconnected'. It this case I think the first option is better. The wording in the remaining document must

20: Tivoli comment from George Penokie

then be make to match this change.

Pages 8 - 11 - section 4.2 - This clause should be broken in subclauses and there should be references added between the steps in the figure and the text descriptions of those steps. This will help the reader relate the figures flow to the text.

PDF Page 21

21: Tivoli comment from George Penokie

Page 9 - lines 7-9 - The for example text should be change to (e.g.,). 22: Tivoli comment from George Penokie

Page 9 - line 2 - The statement '...directed to a server and, if...' is not clear because there is a server agent and a server consumer. Which is this server supposed to be?

23: Tivoli comment from George Penokie

Page 9 - line5 - The statement '...identify the server with which...' is not clear because t there is a server agent and a server consumer. Which is this server supposed to be?

24: Tivoli comment from George Penokie

Page 9 - Figure 3 - line 40 - The arrow exiting to the right seems to dead end. Where does the flow go from there. All the other exit points are clear that one is not.

PDF Page 22

25: Tivoli comment from George Penokie

(T) Page 10 - line 12 - This states '...the server identifier shall identify one or more SRP target ports, and the login data...'. How is it possible for a single server identifier to identify more that one SRP port.? SCSI requires all target port identifiers be unique within a domain.

26: Tivoli comment from George Penokie

Page 10 - at least lines $2-1\overline{5}$ - The term 'server' is used by itself several times. There needs to be a qualifier on server so the reader does not assume that server equates to server agent and server consumer.

27: Tivoli comment from George Penokie

Page 10 - lines 28 - 29 - The statement 'With SRP the reject data includes an SRP_LOGIN_REJ response (see 6.4).' Is confusing in that it implies the SRP (which is this standard) has additional requirements than what was just specific in the sentence before. That does not compute and needs to be fixed. 28: Tivoli comment from George Penokie

Page 10 - lines 31 -32 - Is it possible for an RDMA channel to be successfully

11/2/2001

01-301r0. txt established and not operational? If not then the statement 'and is operational' should be deleted. If so then it needs to be explained how it is 29: Tivoli comment from George Penokie Page10 - line 34 - The statement '...server agent or consumer...' should be '....server agent or server consumer...'. This needs to be looked for throughout the document and corrected. 30: Tivoli comment from George Penokie Page 10 - line 35 - The statement With SRP the accept data includes an SRP_LOGIN_RSP response (see 6.3).' Is confusing in that it implies the SRP (which is this standard) has additional requirements than what was just specific in the sentence before. That does not compute and needs to be fixed. 31: Tivoli comment from George Penokie Page 10 - Lines 44-45 - The statement 'With SRP the Login data includes an SRP_LOGIN_REQ request (see 6.2)...' Is confusing in that it implies the SRP (which is this standard) has additional requirements than what was just specific in the sentence before. That does not compute and needs to be fixed. 32: Tivoli comment from George Penokie Page 10 - lines 43 - 44 - The sentence 'The server agent is provided the Login data from the client consumer's request in addition to RDMA communication service specific data.' is awkward. It would be better stated as 'The server agent receives the login data and RDMA communication service specific data from the client consumer's request.'. PDF Page 23 33: Tivoli comment from George Penokie Page 11 - line 2 - The statement 'With SRP the reject data shall contain an SRP_LOGIN_REJ response (see 6.4).' Is confusing in that it implies the SRP (which is this standard) has additional requirements than what was just specific in the sentence before. That does not compute and needs to be fixed. 34: Tivoli comment from George Penokie Page 11 - lines 5 - 6 - The statement 'With SRP the accept data shall contain an SRP_LOGIN_RSP response (see 6.3)...' Is confusing in that it implies the SRP. (which is this standard) has additional requirements than what was just specific in the sentence before. That does not compute and needs to be fixed. 35: Tivoli comment from George Penokie Page 11 - line 11 - The term 'such' should be deleted. 36: Tivoli comment from George Penokie Page 11 - lines 30-31 - The statement '... to deliver the message to the other consumer associated with the specified RDMA channel (the receiving consumer).' should be changed to '... to deliver the message to the receiving consumer. There is no need to redefine what a receiving consumer is as that is done in the first paragraph of this section. 37: Tivoli comment from George Penokie Pages 11 - 12 - section 4.4 - This clause should be broken in subclauses. For example at least an overview, one for read RDMA, and one for write RDMA. PDF Page 24 38: Tivoli comment from George Penokie Page 12 - line 5 - The statement 'as well' should be deleted. 39: Tivoli comment from George Penokie Page 12 - line 14 - The following statement 'Such information may be communicated by an application protocol.' Does not seem relevant to this standard and should be deleted. 40: Tivoli comment from George Penokie Page 12 - lines 41-43 - This paragraph contains information that is not useful and should be deleted. It essentially states that RDMA communication has characteristics defined here and those not defined here are out side the scope of this standard. That is true but it is also true for every clause in this standard. 41: Tivoli comment from George Penokie Page 12 - line 45 - The statement 'or else' should be just 'or'. 42: Tivoli comment from George Penokie Page 12 - line 46 - The term 'exactly' should be deleted. There is no difference between 'exactly once' and 'once'. 43: Tivoli comment from George Penokie Page many - The terms Write and Read in RDMA Write and RDMA Read should not be capi tal i zed.

PDF Page 25

44: Tivoli comment from George Penokie Page 13 - line 14 - The term 'satisfy' should be changed to 'meet'. PDF Page 26

45: Tivoli comment from George Penokie Page 14 - line 8 - The statement 'I_T nexus' is correct but there is no reference to where one would find out more about what it is. This needs to be added. 46: Tivoli comment from George Penokie Page 14 - line 7 - The statement 'for its lifetime' is not clear. It should be stated as 'as long as it is established'. This ties it to the previous section. Note this assumes that the term established in 4.2 is not changed. 47: Tivoli comment from George Penokie Page 14 - lines 24-28 - This whole paragraph does not look like it belongs here or anywhere and it should be deleted. It appears to be attempting to defines things that are either already defined in section 4 or don't need to be defined. 48: Tivoli comment from George Penokie Page 14 - line 40 - The statement 'that were contained in SRP_CMD requests (see 6.8)' should be deleted as it is redundant with the statement outstanding SCSI tasks'. 49: Tivoli comment from George Penokie (T) Page 14 - Line 43 - The statement '...an SRP target port should send an...' gives inadequate guidance to a target implementor. This should be required to send the SRP_T_LOGOUT or not send it. Or it should be specified when it is required to be sent and when it is not required to be sent. 50: Tivoli comment from George Penokie PDF Page 27 (T) Page 15 - line 4 - I recommend adding into this list a statement that other SCSI related parameters (e.g., mode pages, logs) not be effected by the disconnect. This should avoid the hole the FC has doug for itself in this area. 51: Tivoli comment from George Penokie Page 15 - line 18 - The statement '...operation, if accepted, may allow...' should be '...operation may allow...'. The if accepted is redundant with may. 52: Tivoli comment from George Penokie Page 15 - line 36 - The term 'may' should be deleted. 53: Tivoli comment from George Penokie Page 15 - lines 36-40 - the format of the e.g is incorrect. It should be...'standards (e.g., ...).'. 54: Tivoli comment from George Penokie Page 15 - line 49 - The statement 'as well as' should be 'or'. PDF Page 28 55: Tivoli comment from George Penokie Page 16 - line 3 - The term 'initiation' should be 'start' or 'beginning'. 56: Tivoli comment from George Penokie Page 16 - line 5 - The term 'all' should be 'the'. 57: Tivoli comment from George Penokie Page 16 - lines 7-8 - I am not aware of a SCSI command that specifies that status not be returned. If there is such a thing then an e.g., would be helpful. If there is no such thing then this item should be deleted. 58: Tivoli comment from George Penokie Page 16 - line 18 - What is the 'it' referring to? The 'it' needs to be replaced with whatever 'it' is. 59: Tivoli comment from George Penokie Page 16 - line 23 - The term 'might' should be 'may'. 60: Tivoli comment from George Penokie Page 16 - line 23 - What is the 'it' referring to? The 'it' needs to be replaced with whatever 'it' is. 61: Tivoli comment from George Penokie Page 16 - Line 24 - The statement '...to at most one...' seems redundant. It should be '...to one...'. 62: Tivoli comment from George Penokie Page 16 - lines 28-29 - The statement '...present in most information units...' is troublesome. There either needs to be a list of the IUs that have the field or a reference to a place that would tell my which IUs have or do not have the field. 63: Tivoli comment from George Penokie Page 16 and others? - The when to use small caps rule is not being followed here. The rule is that small caps are only used when the field is being named (e.g., xxx field would have the xxx in small caps). When contents of the field is being called out it is not in small caps (e.g. request limit and request limit delta are both signed...').

64: Tivoli comment from George Penokie

Page 16 - line 49 - The sentence starting with 'An SRP port shall not specify a negative...' should be a separate item in the list.

65: Tivoli comment from George Penokie

(T) Page 16 - section 5.3 - This section on flow control seems overly complex for what appears to be actually needed. The only SRP request that even needs to have multiple outstanding requests in the command. All others should not be streamed but should be interlocked and some should be allowed to occur at any time. This all needs to be looked at to make sure the design point is what we really want.

PDF Page 29

66: Tivoli comment from George Penokie

Page 17 - Figure 4 - The way the arrows are pointing for the virtual address implies that it is not the address of the first byte of the memory segment. It currently implies that it is the space from the memory handle to the beginning of the memory segment which is the memory region. It is also not clear as to what the boundaries are of the memory region. The current drawing implies it is only the area above the memory segment. I do not believe that is correct so it needs to be fixed.

67: Tivoli comment from George Penokie

Page 17 - line 26 - There is no indication as to what kind of value the memory handle is. This would normally not be a problem except that the other two fields to explicitly indicate that they are unsigned integer values. I generally consider all fields to be unsigned integers but in this case there is doubt cast about that assumption.

PDF Page 30

68: Tivoli comment from George Penokie

Page 18 - Line 1 - The statement 'A SRP...' should be 'An SRP...' This needs to be checked for throughout the document and corrected.

69: Tivoli comment from George Penokie

Page 18 - line 3 - The statement '...within its memory segment.' should be '...within the memory segment.'.

70: Tivoli comment from George Penokie

Page 18 - line 2 - The statement 'SRP target ports shall only issue the appropriate type of RDMA operation for a memory descriptor' appears to be restating what was stated in the previous sentence and therefore should be deleted. The sentence would then read 'SRP target ports shall ensure that each RDMA operation...'.

71: Tivoli comment from George Penokie

Page 18 - line 3 - There needs to be a connection between the text above the a.b.c list and the list. Something like 'segment by using the following rules:'.

72: Tivoli comment from George Penokie

Page 18 - lines 15-17 - The sentences 'The format of each data buffer descriptor is specified by a format code value. Some data buffer descriptor format code values use the contents of a count field to further specify the data buffer descriptor format.' should be deleted as the information is a duplicate of what is in table 2.

73: Tivoli comment from George Penokie

Page 18 - table 2 - line 35 - footnote c - There statement 'and and' should be just 'and' and there is not period at the end of the sentence.

74: Tivoli comment from George Penokie

Page 18 - table 2 - line 27 - The equation 20+16*count should be change to 20 + 16 x count. This change from * to x should be make throughout the document. 75: Tivoli comment from George Penokie

Page 18 - table 2 - footnote b - This should have a reference from the cell with 'count' in it.

76: Tivoli comment from George Penokie

Page 18 - lines 43-45 - The sentence 'An SRP initiator port shall not specify a data buffer descriptor format that was not indicated in the REQUIRED BUFFER FORMATS field value for that RDMA channel.' does not make sense. How can the initiator port be indicating the buffer formats in the REQUIRED BUFFER FORMATS field and at the same time not specifying the buffer formats in the REQUIRED BUFFER FORMATS field that were not indicated in the in the REQUIRED BUFFER FORMATS field. This is circular and needs to be fixed.

77: Tivoli comment from George Penokie

Page 18 - line 41 - There should be a reference to table 2 as follows 'data buffer descriptor formats (see table 2)'.

78: Tivoli comment from George Penokie

Page 18 - line 47 - The statement '...RDMA channel and...' should be '...RDMA channel request and...'.

79: Tivoli comment from George Penokie

Page 18 - line 49 - The statement '...RDMA channel and...' should be '...RDMA channel request and...'.

80: Tivoli comment from George Penokie

Page 18 - line 40 - There should be a reference to table 3 as follows 'The REQUIRED BUFFER FORMATS field (see table 3)...'.

81: Tivoli comment from George Penokie

Page 19 - line 4 - I believe the 'and' should be an 'or'. I don't believe a target port would do both IU at the same time.

82: Tivoli comment from George Penokie

Page 19 - lines 3-4 - There should be a reference to table 3 as follows 'The SUPPORTED BUFFER FORMATS field (see table 3)...'.

83: Tivoli comment from George Penokie

Page 19 - line 8 - The statement '...contents of the REQUIRED BUFFER...' should be '...contents of both the REQUIRED BUFFER....'.

84: Tivoli comment from George Penokie

(T) Page 19 - line 18 and line 28 - Why is that when the IDBD bit and the DDBD bit is set to zero it is a should instead of a shall? This should be changed to a shall unless there is some good reason.

85: Tivoli comment from George Penokie

Page 19 - note 2 - This note should note be a note. It should be part of the main text. It should also be restated as: 'The length of requests sent by an SRP initiator port, as determined by the data buffer descriptor formats, shall be limited to the MAXIMUM INITIATOR TO TARGET IU LENGTH field (see xxx) returned in the SRP_LOGIN_RSP response.

86: Tivoli comment from George Penokie

(T) Page 19 - lines 39 - 40 - The sentence 'SRP target ports are not required to check the contents of the count field.' should be changed to 'SRP target ports shall ignore the contents of the count field.'.

87: Tivoli comment from George Penokie

(T) Page 19 - lines 44 - 45 - The sentence 'SRP target ports are not required to check the contents of the count field.' should be changed to 'SRP target ports shall ignore the contents of the count field.'.

88: Tivoli comment from George Penokie

Page 19 and others - line 39 and others - The term 'count field' is used in many places. First there are two of them so it should be 'count fields'. Second is not clear that these are the count fields in the SRP_CMD request. I recommend changing 'count field' to 'count fields in the SRP_CMD request' in all places in the main body text.

PDF Page 32

89: Tivoli comment from George Penokie

Page 20 - line 8 - The statement 'count field' should be 'DATA-OUT BUFFER DESCRIPTOR COUNT field (or DATA-IN BUFFER DESCRIPTOR COUNT field)'.

90: Tivoli comment from George Penokie

Page 20 - line 12 - A reference to table 5 should be added to the end of the paragraph.

91: Tivoli comment from George Penokie

Page 20 - table 4 - line 29 - Footnote a - It's not clear which count field is being referred to. Is it the one in table 2 or the ones in the SRP_CMD_ request. This needs be fixed with the proper terminology and a reference to the correct place.

92: Tivoli comment from George Penokie

Page 20 - line 34 - The statement 'The DATA LENGTH field of the INDIRECT TABLE MEMORY DESCRIPTOR field value contains...' is not correct. It should be 'The DATA LENGTH field of the memory descriptors in the indirect table contains...'

93: Tivoli comment from George Penokie

Page 20 - line 39 - The sentence 'SRP target port behavior when the TOTAL LENGTH field contains any other value is vendor specific.' should be moved to the end of the paragraph and restated as 'If the TOTAL LENGTH field value is not equal to the to sum of the DATA LENGTH field values the SRP target port's behavior shall be vendor specific.'.

94: Tivoli comment from George Penokie

Page 20 - line 42 - It's not clear which count field is being referred to. Is it the one in table 2 or the ones in the $SRP_CMD_$ request. This needs be fixed with the proper terminology and a reference to the correct place.

95: Tivoli comment from George Penokie

Page 20 - line 47 - This should be the start of a new subclause. Something like 'SRP target port indirect data restrictions'.

PDF Page 33 96: Tivoli comment from George Penokie Page 21 - line 7 - This paragraph should be the start of a new subclause titled something like 'Examples of Indirect data buffers'. 97: Tivoli comment from George Penokie (T) Page 20 and 21 - The possibility of having both a data-in and a data-out buffer is not described here. Why not? This needs to be fixed. 98: Tivoli comment from George Penokie Page 21 - lines 12 and 13 - The term 'might' should be changed to 'may'. This should be done throughout this document. PDF Page 35 99: Tivoli comment from George Penokie Page 23 - line 48 - The statement 'A requestor shall provide a TAG value in each SRP request that is unique among all of the requestor's outstanding SRP requests with a particular responder. A responder shall copy the TAG value from each SRP request to the SRP request's SRP response. Responders are not required to check whether the TAG values of outstanding SRP requests are unique.' should be 'Each SRP request shall contain a TAG value that is unique among all of the outstanding SRP requests from a particular SRP initiator port. Each SRP response shall contain a copy of the TAG value from the corresponding SRP request. Responders are not required to check whether the TAG values are unique.' PDF Page 37 100: Tivoli comment from George Penokie Page 25 - line 2 - The term 'conveys' should be changed to 'sends'. 101: Tivoli comment from George Penokie Page 25 - Line 42 - The statement '...wishes to send...' should be changed to '...sends...'. 102: Tivoli comment from George Penokie Page 25 - line 42 - The statement '....be 64 or larger.' should be '....be greater than or equal to 64.' or '...be greater than 63.'. PDF Page 38 103: Tivoli comment from George Penokie Page 26 - lines 1-2 - The statement 'The MULTI-CHANNEL ACTION field identifies how an SRP target port treats any existing RDMA channel associated with the same I_T nexus. The MULTI-CHANNEL ACTION field is defined in table 10.' should be changed to 'The MULTI-CHANNEL ACTION field (see table 10) indicates how an SRP target port handles existing RDMA channels associated with the same I_T nexus.'. 104: Tivoli comment from George Penokie Page 26 - table 10 - All the codes except for the 2 that are defined need to be listed as reserved. The row should have '02h - FFh' in the action column and 'reserved' in the description column. PDF Page 39 105: Tivoli comment from George Penokie Page 27 - line 2 - The term 'conveys' should be changed to 'sends'. PDF Page 40 106: Tivoli comment from George Penokie Page 28 - lines 1-2 - The statement 'MULTI-CHANNEL RESULT identifies how the SRP target port treated existing RDMA channels associated with the same I_T nexus. Table 12 defines this field.' should be changed to 'The MULTI-CHANNELRESULT field (see table 12) indicates how an SRP target port handles existing RDMA channels associated with the same I_T nexus.'. 107: Tivoli comment from George Penokie Page 28 - table 12 - All the codes except for the 3 that are defined need to be listed as reserved. The row should have 'O3h - FFh' in the action column and 'reserved' in the description column. PDF Page 42 108: Tivoli comment from George Penokie Page 30 - line 4 - The statement '...failed, rendering it non-operational.' should be changed to '...failed.'. PDF Page 43 109: Tivoli comment from George Penokie Page 31 - line 4 - The statement '...failed, rendering it non-operational.' should be changed to '...failed.'. PDF Page 44 Page 32 - line 2 - The term 'conveys' should be changed to 'sends'. 110: Tivoli comment from George Penokie Page 32 - lines 37-38 - The statement '...logical unit component of the nexus

for the task management request.' should be changed to '...logical unit to

11/2/2001

01-301r0. txt which to send task management request.'. PDF Page 46 111: Tivoli comment from George Penokie Page 34 - line 2 - The term 'conveys' should be changed to 'sends'. 112: Tivoli comment from George Penokie Page 34 - 35 - Table 20 - This table splits up a paragon and worse a sentence. This needs to be fixed. 113: Tivoli comment from George Penokie Page 34 - table 20 - The notation 'do' and 'di' are confusing when placed into a sentence (as in the footnotes). They should be changed to 'x' and 'y'. PDF Page 48 114: Tivoli comment from George Penokie Page 36 - line 2 - The term 'conveys' should be changed to 'sends'. 115: Tivoli comment from George Penokie Page 36 - line 6 - The statement '...message capable of containing...' should be changed to '...message containing...'. PDF Page 49 116: Tivoli comment from George Penokie Page 37 - The statement 'set to 1' should be 'set to one' and the statement 'set to 0' should be 'set to zero' in all cases throughout this document. 117: Tivoli comment from George Penokie Page 37 - line 44 - The statement 'are not reliable and' should be deleted as it contains no useful information. PDF Page 50 118: Tivoli comment from George Penokie Page 38 - line 3 - Add a reference to the RSP_CODE values table (table 24) at the end of this paragraph. 119: Tivoli comment from George Penokie (T) Page 38 - lines 15-17 - The statement 'If DOUNDER is set to 1, a transfer that did not use the entire data-out buffer was performed and the value of DATA-OUT RESIDUAL COUNT shall be equal to: data-out buffer length - highest offset of any data-out byte transferred - 1' needs to be changed to 'If DOUNDER is set to one and a transfer that did not fill the entire data-out buffer was performed the value of DATA-OUT RESIDUAL COUNT is defined as follows: DATA-OUT RESIDUAL COUNT = (data-out buffer length) - (highest offset of any data-out byte transmitted + 1)' 120: Tivoli comment from George Penokie (T) Page 38 - lines 22-23 - The statement 'DATA-OUT RESIDUAL COUNT shall be equal to: data-out transfer length required by command - data-out buffer length' needs to be changed to 'The DATA-OUT RESIDUAL COUNT is defined as follows: DATA-OUT RESIDUAL COUNT = (Transfer Length required by command) - (data-out buffer length)' 121: Tivoli comment from George Penokie (T) Page 38 - lines 34-36 - The statement 'If DIUNDER is set to 1, a transfer that did not fill the entire data-in buffer was performed and the value of DATA-IN RESIDUAL COUNT shall be equal to: data-in buffer length - highest offset of any data-in byte transferred - 1' needs to be changed to ''If DIUNDER is set to one and a transfer that did not fill the entire data-in buffer was performed the value of DATA-IN RESIDUAL COUNT is defined as follows: DATA-IN RESIDUAL COUNT = (data-in buffer length) - (highest offset of any data-in byte transmitted + 1)' 122: Tivoli comment from George Penokie (T) Page 38 - Lines 41-43 - The statement 'DATA-IN RESIDUAL COUNT shall be equal to: data-in transfer length required by command - data-in buffer length' needs to be changed to ''The DATA-IN RESIDUAL COUNT is defined as follows: DATA-IN RESIDUAL COUNT = (Transfer Length required by command) - (data-in buffer length)'.

PDF Page 51

123: Tivoli comment from George Penokie

Page 39 - line 1 -The term 'certain' should be deleted.

124: Tivoli comment from George Penokie

(T) Page 39 - lines 30 - 41 - All this should be deleted and replaced with 'The SENSE DATA field contains the autosense data specified by the SCSI Primary Commands-2 standard. The proper SENSE DATA shall be presented when the SCSI status byte of CHECK CONDITION is presented as specified by the SCSI Primary Commands-2 standard. If no conditions requiring the presentation of SCSI sense data have occurred, the SENSE DATA field shall not be included in

the SRP_RSP response and the RSPVALID bit shall be zero. SRP devices shall perform autosense.' PDF Page 53 125: Tivoli comment from George Penokie Page 41 - line 2 - The term 'conveys' should be changed to 'sends'. PDF Page 54 126: Tivoli comment from George Penokie (T) Page 42 - Lines 3-13 - All this should be deleted and replaced with the following ''The SENSE DATA field contains sense data specified by the SCSI Primary Commands-2 standard.'. This is AER not a check condition they are different things. The only thing that should be stated here is that sense data is returned. PDF Page 56 127: Tivoli comment from George Penokie Page 44 and others - line 16 and others - The term 'set to 0' and 'set to 1' should be 'set to one' and 'set to zero'. 128: Tivoli comment from George Penokie Page 44 - line 19 - The term 'all' should be deleted as it is redundant. PDF Page 58 129: Tivoli comment from George Penokie Page 46 - figure A. 2 and A. 3 - line 15 and 43 - The statement '(SRP initiator' should be '(SRP initiator port)'. 130: Tivoli comment from George Penokie Page 46 and others- lines 22-26 and others - The 1, 2, 3 list should not have line spaces between numbered items. This should be fixed in all cases PDF Page 64 131: Tivoli comment from George Penokie Page 52 - line 20 - The term 'executes' should be changed to 'processes'. 132: Tivoli comment from George Penokie Page 52 - line 32 - The statement '...a device or component...' should be 'an IB device or component...'. PDF Page 65 133: Tivoli comment from George Penokie Page 53 - line 20 - There seems to be no definition of what a 'connection manager' is. This should, at least, be added to the glossary. 134: Tivoli comment from George Penokie Page 53 - section B.3.2 - The abbreviation IOC needs to be added to the list. PDF Page 67 135: Tivoli comment from George Penokie Page 55 - lines 1-2 - The sentence 'The IB more IB LIDs and IB GIDs corresponding to an IB port GUID or IB channel adapter GUID.' does not seem to be a complete sentence and is not clear as to what it is trying to state. This needs to be fixed. PDF Page 68 136: Tivoli comment from George Penokie (T) Page 56 - line 2 - Why is the should not a shall. I believe it should be changed to a shall. 137: Tivoli comment from George Penokie Page 56 - line 15 - The statement '...field should an IB GUID...' should be '...field should be an IB GUID...'. 138: Tivoli comment from George Penokie Page 56 - line15 - The statement '...port, e.g. the...SRP initiator port.' should be '...port (e.g., the...SRP initiator port).'. 139: Tivoli comment from George Penokie Page 56 - Lines 15-16 - The statement 'the LB channel adapter GUID for an LB channel adapter used the SRP initiator port.' is not very clear as to what it is. This needs to be fixed. 140: Tivoli comment from George Penokie Page 56 - line 20 - There is not clue as what a 'device management agent' is. This could be fixed by replacing 'device management agent' with the more generic term 'entity'. 141: Tivoli comment from George Penokie Page 56 - line 22 - The term 'indicated' is confusing in this sentence. A better term would be 'identified'. 142: Tivoli comment from George Penokie Page 56 - line 39 - The term 'indicated' is confusing in this sentence. A better term would be 'identified'. 143: Tivoli comment from George Penokie

Page 56 - lines 41-42 - This sentence seems out of place here. I should be

moved to right after figure B. 3.

144: Tivoli comment from George Penokie

Page 56 - line 49 and page 57 - line 1 - The term ' IB I/O ' has been split across lines (and in this case across pages) at the /. This needs to be fixed so it will not happen. There is an option in frame that if selected will prevent this. It should be enabled for this document.

PDF Page 69

145: Tivoli comment from George Penokie

Page 57 - line 34 - The 'it' at the beginning of the sentence should be replaced with whatever the 'it' is.

146: Tivoli comment from George Penokie

Page 57 - line 46 and page 58 - line 1 - Why is the receive data-out mapped to RDMA requests and send data-in mapped to RDMA WRITE packets? One is a 'request' the other a 'packet' this seems strange shouldn't they be the same? PDF Page 73

147: Tivoli comment from George Penokie

Page 61 - table B.8 - line 31 - The statement '(binary zeros)' should be '(i.e., binary zeros)'.

148: Tivoli comment from George Penokie

SRP does not define any format for the 3rd party device identifier for third party reservations. This needs to be added to comply with requirements in SPC-3.

Comments from IBM on SRP rev 10:

1. IBM Comment

p50 line 11. "See 4x1" is a typo. I think this should be "See 4.4".

2. IBM Comment

p50 line 14. "Sever" should be "server".

3. IBM Comment

p50 line 35. "Sever" should be "server".

4. IBM Comment

p57 section B.6.5. The descriptions for data-in and data-out are not symmetrical. One is described in terms of an "RDMA READ Request" and the other in terms of "one or more RDMA WRITE packets". I think the rules are the same for both data-in and data-out (please let me know if I'm incorrect in that assumption). Describing them differently implies that they are somehow different, and generates unnecessary confusion. (This is the same as Tivoli comment number 146).

Comments attached to No ballot from Mr. Cris Simpson of Intel Corp.:

intel 0001 Sect: 1 Pg: 1 Ln: 32

Transport protocol s/b 'SCSI Protocol'

Suggest shading box to clarify what we're doing inthis spec

intel 0002 Sect: 1 Pg: 1 Ln: 37

Remove 'Physical'

intel 0003 Sect: 3.1.11 $\,$ Pg: 4 $\,$ Ln: 27 inconsistent use of 'the' before SRP - suggest no 'the'

intel 0004 Sect: 3. 1. 14 Pg: 4 Ln: 34

Is it necessary to specify field size in definition?

intel 0005 Sect: 3. 1. 15 Pg: 4 Ln: 35

'Application protocol' is not defined, thus what constitutes app proto data is uncl ear

intel 0006 Sect: 3. 1. 16 Pg: 4 Ln: 39

Key feature is that data placement is under control of receiver

intel 0007 Sect: 3. 1. 17 Pg: 4 Ln: 41 'path' is a poor term, implies routing

intel 0008 Sect: 3. 1. 17 Pg: 4 Ln: 43 C

'a transport protocol or service' - which is it?

There appears to be an abstraction layering problem Using 'service' to define a service suggests we don't have a clean definition we don't intel 0009 Sect: 3. 1. 23 Pg: 5 Ln: 6 rewrite as 'specific to an RDMA comm service' intel 0010 Sect: 3. 1. 27 Pg: 5 Ln: 12 C TP ID' within an RDMA comm service' - another abstraction issue - what is a servi ce? intel 0011 Sect: 3. 1. 28 Pg: 5 Ln: 15 Any reason to spec field size? intel 0012 Sect: 3. 3. 9 Pg: 6 Ln: 12 reported as AN error intel 0013 Sect: 4 Pg: 8 Ln: 1 C Clause 4 alternates between being a generic overview of RDMA, including discussion of features not used by SRP (e.g., solicited events in 4.3), and normative (numerous SHALLs), which seems out of place in a clause entitled ...model' Suggest separating the architectural model from the normative. intel 0014 Sect: 4. 2 Pg: 8 Ln: 46 Seems redundant to Line 10 above. intel 0015 Sect: 4.2 Pg: 9 Ln: 2 C Model is unclear: "A client consumer requests that the RDMA communication service establish an RDMA channel." But RDMA_CS is defined as a protocol. The sense should be that the client requests a SERVICE PROVIDER establish a channel. intel 0016 Sect: 4.2 Pa: 9 Ln: 2 "The request is directed to a server" - Ambiguous There are several standard meanings for 'server' - a piece of HW, a process, etc. intel 0017 Sect: 4. 2 Pg: 9 Ln: 29 Should we add 'and validate' to 'Determine'? intel 0018 Sect: 4. 2 Pg: 9 Ln: 50 C We need a similar diagram for channel teardown. intel 0019 Sect: 4. 2 Pg: 10 Ln: 17 (Many places in this clause) Some formatting is needed to set off model-specific terms such as "channel establishment failure response" - suggest bold or small caps. This would making parsing and understanding much easier. intel 0020 Sect: 4.2 Pg: 10 Ln: 22 Given the vague definition of RDMA CS, it's hard to tell what 'internal to the RDMA communication service' does or does not mean. intel 0021 Sect: 4.2 Pg: 10 Ln: 26 "An RDMA channel rejected response returns reject data" s/b "Rejection" data intel 0022 Sect: 4. 2 Pg: 10 Ln: 28 'With SRP the reject data includes' - near duplicate of page 11, Line 2 intel 0023 Sect: 4. 2 Pg: 10 Ln: 30 'service specific data' s/b 'service-specific data' (global replace)

intel 0024 Sect: 4. 2 Pg: 10 Ln: 42

```
'requests that are acceptable to the RDMA communication service shall be
passed to the server agent.
(SHALL in model clause. )
What does it mean to be acceptable to the service?
As there is no mapping of 'Server Agent' to any entity, on what is this
requirement placed?
Can this requirement be stated in SRP or Annex B -specific terms?
intel 0025 Sect: 4. 2 Pg: 11 Ln: 2
'reject(ion) data shall contain an SRP_LOGIN_REJ...' (SHALL)
Do we need a subclause similar to '4.5 Ordering and Reliability' to capture
size issues.
so we can specify requirements on underlying interconnects? (e.g., Must be
able to return
_REJ as part of connection establishment protocol.)
intel 0026 Sect: 4. 2 Pg: 11 Ln: 5
'accept data' s/b 'acceptance data'
intel 0027 Sect: 4. 2 Pg: 11 Ln: 9
It is unclear how an RDMA comm svc requests that a channel be disconnected.
intel 0028 Sect: 4.2 Pg: 11 Ln: 9
Need to discuss the case of a channel being destroyed due to an error.
intel 0029 Sect: 4. 2 Pg: 11 Ln: 13
'A disconnect request causes an RDMA channel to become non-operational.'
Is this a request by a consumer to the local CS provider, or to the remote
client.
server agent, ...?
intel 0030 Sect: 4. 2 Pg: 11 Ln: 16
'may or may not'
Since 'May' and 'May Not' are both defined to be equivalent to 'May or May
Not',
there appears to be no reason to include both.
(global)
intel 0031 Sect: 4.2 Pg: 11 Ln: 16
Suggest: 'The completion status of operations... is indeterminate.'
intel 0032 Sect: 4.2 Pg: 11 Ln: 13
'disconnect request' s/b 'disconnection request'
(global)
intel 0033 Sect: 4.3 Pg: 11 Ln: 18
'An RDMA channel may allow its consumers to exchange messages.'
One that did not would be useless for the present case, wouldn't it?
intel 0034 Sect: 4.3 Pg: 11 Ln: 21
'may provide normal and solicited message reception notification,'
Since not used by SRP, why included?
intel 0035 Sect: 4.3 Pg: 11 Ln: 24
'providing the following to an RDMA communication service'
Again, CS model issue - how do you provide this to a protocol?
intel 0036 Sect: 4.4 Pg: 12 Ln: 23 C
  'An RDMA communication service is not required to provide a way for a
requesti ng
 consumer to determine whether the data has been written into the specified
range
 of addresses in registered memory.'
If the target does not know whether a write has completed, how does it know
send status, and whether status is good or not?
intel 0037 Sect: 4.5 Pg: 12 Ln: 45
       'or else disconnect the RDMA channel.'
```

'destroy' is a better term to reflect the error case.

```
intel 0038 Sect: 4.5 Pg: 13 Ln: 15
disconnect s/b destroy
intel 0039 Sect: 5. 1. 1 Pg: 14 Ln: 20
   'An SRP target port shall not accept a new RDMA channel unless its SRP
    port identifier matches the value in the SRP_LOGIN_REQ request.'
As we have not defined 'match', do we need to explicitly allow wildcards?
intel 0040 Sect: 5. 1. 1 Pg: 14 Ln: 26
Addtional - spelling
intel 0041 Sect: 5. 1. 1 Pg: 14 Ln: 31
   Prior to requesting that an RDMA channel be disconnected,
    an SRP initiator port may send an SRP_I_LOGOUT'
s/b SHALL send
intel 0042 Sect: 5. 1. 1 Pg: 14 Ln: 44
     'Prior to requesting that an RDMA channel be disconnected, an SRP target
      should send an SRP_T_LOGOUT request'
s/b 'SHALL send'
intel 0043 Sect: 5. 1. 3 Pg: 15 Ln: 16
  'Following acceptance of a login specifying single RDMA channel operation
  single RDMA channel'
Add comma after 'operation'
intel 0044 Sect: 5. 1. 3 Pg: 15 Ln: 22
'shall not accept such a login'
What _REJ reason code is returned?
intel 0045 Sect: 5. 1. 3 Pg: 15 Ln: 27
i denti foer
intel 0046 Sect: 5. 1. 3 Pa: 15 Ln: 36
Break E.g. sentence into two or more sentences, or write as a note.
intel 0047 Sect: 5. 3 Pg: 16 Ln: 24
Suggest creating 5.3.1 Initiator Requests, and 5.3.2 Target Requests, to
di scuss
separatel y.
_Many_ reviewers have become confused with 'SRP target ports shall limit...'
Add pointer to Table 7 and emphasis that these are target-initiated SRP
requests.
_not_ RDMA requests.
intel 0048 Sect: 5.3 Pg: 16 Ln: 27
'credit based' s/b 'credit-based'
intel 0049 Sect: 5.3 Pg: 16 Ln: 40 C
     An SRP initiator port shall not send an SRP request on any RDMA channel
     whose REQUEST LIMIT has a value less than or equal to zero.'
What is Target Port response to this?
intel 0050 Sect: 5.3 Pg: 16 Ln: 42 C
    'To ensure that task management requests may be sent, an SRP initiator
      may choose to send commands only when REQUEST LIMIT is greater than one'
Since TargPort can remove an arbitrary number of credits at any time, Init Port
prohibited from performing Task Mgmt or sending SRP_I_LOGOUT.
intel 0051 Sect: 5.3 Pg: 16 Ln: 46 C
     'An SRP initiator port shall add...whenever it receives an information
unit on
      that RDMA channel'
```

What does 'receive' mean?

Received at what layer?

There may be a significant delay between receiving and reading.

intel 0052 Sect: 5.3 Pg: 16 Ln: 46 C

Target Port maintains, implicitly or explicitly, a value representing its view of the

number of free request contexts (Call this Target Request Limit $\,$ TRL) When there are no

requests outstanding, TRL will be equal to the initiator's REQUEST LIMIT (IRL).

The description in 5.3 only describes IRL, but TRL may differ from IRL, and there

is no definition of when IRL is changed. Specifically, when TargPort sends SRP_CRED_REQ with a negative value, when does TP update TRL?

It only makes sense to update upon receipt of SRP_CRED_RSP , but that is not stated.

Rewrite to describe with state variable at IP and at TP, and rules for updating.

intel 0053 Sect: 5.3 Pg: 16 Ln: 46 C

When can TPort be sure that I Port has seen the REQ_LIMIT_DELTA in an SRP_RSP? (Receipt of transport ACK is not enough)

intel 0054 Sect: 5.3 Pg: 17 Ln: 1

'An SRP target port shall not specify a negative value of REQUEST LIMIT DELTA that

might cause REQUEST LIMIT to drop below -2^31'

Given wrapping, it's impossible to drop below -2^31 in 32-bit 2's comp. Would -2^16 be negative enough?

intel 0055 Sect: 5.3 Pg: 17 Ln: 1 C

 $\,$ ^ An SRP target port shall account for all possible race conditions to meet these requirements. $\,$

Remove this sentence.

intel 0056 Sect: 5. 4. 1 Pg: 17 Ln: 6

'memory segment' and 'memory region' need to be defined before use.

intel 0057 Sect: 5. 4. 1 Pg: 17 Ln: 6

'identifies the byte address'

Isn't the interpretation of a VA up to the particular interconnect/transport?

intel 0058 Sect: 5. 4. 1 Pg: 17 Ln: 6

(Memory Handle) 'The SRP initiator port shall use this value to locate the region.' $\,$

It doesn't appear to be within our scope to define initiator memory controller implementations. Remove this sentence.

intel 0059 Sect: 5. 4. 1 Pg: 17 Ln: 36

Drawing seems to indicate that memory addresses increase moving downward. Should be explicit.

intel 0060 Sect: 5. 4. 1 Pg: 18 Ln: 2

'SRP target ports shall only issue the appropriate type of RDMA operation for a memory descriptor,'

 $\operatorname{Add}:$ 'depending on whether the descriptor was a DATA-IN or DATA-OUT descriptor'

intel 0061 Sect: 5. 4. 1 Pg: 18 Ln: 4

'a) The RDMA operations VIRTUAL ADDRESS shall be greater' Should specify STARTING address.

Although VIRTUAL ADDRESS is a field name in Table 1, the field may have a different name in a particular interconnect's request format. Should not be in CAPS.

intel 0062 Sect: 5. 4. 1 Pg: 18 Ln: 4

'Some data buffer descriptor format code values'

s/b 'descriptor formats'

intel 0063 Sect: 5. 4. 1 Pg: 18 Ln: 17

'use the contents of a count field to further specify the data buffer descriptor format.' $\,$

specify -> describe

intel 0064 Sect: 5. 4. 1 Pg: 18 Ln: 17 C

'count' is essentially a pointer to another field someplace, but this is far

obvious when reading.

Suggest we define a format for 'virtual fields', e.g, '*COUNT', or 'vCOUNT', which

the reader could easily recognize. Clause 3 would contain a table allowing $^{\star}\text{COUNT}$

to be looked up as

'SRP_CMD DATA_OUT BUFFER DESCRIPTOR COUNT or SRP_CMD DATA_IN BUFFER DESCRIPTOR COUNT, as appropriate'

intel 0065 Sect: 5.4.1 Pg: 18 Ln: 24 Remove period after PRESENT

intel 0066 Sect: 5. 4. 1 Pg: 18 Ln: 32

Note 'b' is not referenced above, probably s/b on 'count'

intel 0067 Sect: 5. 4. 1 Pg: 18 Ln: 43

'initiator port may specify in SRP_CMD requests (see 6.8) sent on that RDMA channel. An SRP initiator port shall not specify a data buffer descriptor format

that was not indicated in the REQUIRED BUFFER FORMATS field value for that RDMA channel. '

What is target response if it does?

'SRP target ports are not required to check SRP_CMD requests

for data buffer descriptor formats that were not indicated in the REQUIRED $\ensuremath{\mathsf{BUFFER}}$

FORMATS field value.'

Not clear - are they required to validate that they did a valid format?

intel 0068 Sect: 5. 4. 1 Pg: 18 Ln: 47

'An SRP target port may accept an RDMA channel and' s/b 'channel establishment request'

intel 0069 Sect: 5. 4. 2. 2 Pg: 18 Ln: 49

shall reject the RDMA channel and return after channel, add 'establishment request'

intel 0070 Sect: 5.4.2.2 Pg: 19 Ln: 16 indirect data buffer descriptor (IDBD)

Use caps or formatting to set off these field names

intel 0071 Sect: 5. 4. 2. 2 Pg: 19 Ln: 16

if the SRP initiator port may specify the INDIRECT s/b 'if the TP will accept...'

intel 0072 Sect: 5. 4. 2. 2 Pg: 19 Ln: 18

does not use

(Sense is that IP forebears use of indirect) shall not use?

intel 0073 Sect: 5. 4. 2. 4 Pg: 19 Ln: 44

'sixteen bytes'

Previously defined in Table 2 - eschew multiple definitions

intel 0074 Sect: 5. 4. 2. 4 Pg: 19 Ln: 48

target port shall only issue RDMA Read operations using the memory descriptor $% \left(1\right) =\left(1\right) \left(1\right) +\left(1\right) \left(1\right) \left(1\right) +\left(1\right) \left(1\right) \left$

contained in the direct data buffer descriptor.

Statement does not have desired effect - limits what you can read, but does not accesses to READs. s/b 'shall issue only RDMA Reads when using' intel 0075 Sect: 5. 4. 2. 4 Pg: 20 Ln: 1 shall issue only RDMA Writes... intel 0076 Sect: 5. 4. 2. 5 Pg: 20 Ln: 6 format code value 'value' appears to be superfluous intel 0077 Sect: 5. 4. 2. 5 Pg: 20 Ln: 8 'The Length....sixteen bytes.' Drop sentence - redundant to Table 2 intel 0078 Sect: 5. 4. 2. 5 Pg: 20 Ln: 10 'An indirect data buffer is comprised of one or more memory segments' Need a real definition. intel 0079 Sect: 5. 4. 2. 5 Pg: 20 Ln: 11 segments may or may not be contiguous. s/b 'may be discontiguous' intel 0080 Sect: 5. 4. 2. 5 Pg: 20 Ln: 11 remove 'may be in a single memory region' intel 0081 Sect: 5. 4. 2. 5 Pg: 20 Ln: 12 of the memory segments (ADD: listed in an IBDB) intel 0082 Sect: 5. 4. 2. 5 Pg: 20 Ln: 13 may have any length As the length field is finite, so is the segment length intel 0083 Sect: 5. 4. 2. 5 Pg: 20 Ln: 29 value contained in the data buffer descriptor\u2019s count field. Implies that the field is contained within the DBD intel 0084 Sect: 5. 4. 2. 5 Pg: 20 Ln: 29 'count' Suggest replacing with 'PMDL Length' intel 0085 Sect: 5. 4. 2. 5 Pg: 20 Ln: 31 DESCRIPTOR field value is a memory descriptor Suggest: DESCRIPTOR field contains a memory descriptor intel 0086 Sect: 5. 4. 2. 5 Pg: 20 Ln: 33 concatenated together 'together' is redundant Stamp Out and Abolish Redundancy! intel 0087 Sect: 5. 4. 2. 5 Pg: 20 Ln: 35 contains the number of memory descriptors in the indirect table times Suggest: contains the length, in bytes, of the indirect table (16 bytes * number of descriptors in table) intel 0088 Sect: 5. 4. 2. 5 Pg: 20 Ln: 36 MEMORY DESCRIPTOR field value contains any other drop 'value' intel 0089 Sect: 5. 4. 2. 5 Pg: 20 Ln: 43 list of n memory descriptors Use bold or something to set off n intel 0090 Sect: 5. 4. 2. 5 Pg: 20 Ln: 47 shall only issue s/b shall issue only

intel 0091 Sect: 5. 4. 2. 5 Pg: 21 Ln: 1 shall only issue s/b shall issue only (also Ln 4) intel 0092 Sect: 5. 4. 2. 5 Pg: 21 Ln: 12 All four..., each might..., or several might be... Awkward - generalize to: segments may be in different memory regions intel 0093 Sect: 5. 4. 2. 5 Pg: 21 Ln: 44 value contains Drop: value (i.e.,) Add: in bytes intel 0094 Sect: 6.1 Pg: 23 Ln: 7 Add M/O column, or statement that all are mandatory. intel 0095 Sect: 6.1 Pg: 23 Ln: 24 Add space between Tables 6 and 7 to clarify distinction between I>T and T>I requests. intel 0096 Sect: 6.1 Pg: 23 Ln: 46 shall send SRP_T_LOGOUT What reason code? intel 0097 Sect: 6.1 Pg: 23 Ln: 48 Need to define requestor, responder. Much reviewer confusion wrt Targ as requestor. intel 0098 Sect: 6.1 Pg: 24 Ln: 2 C Responders are not required to check whether the TAG values of outstandi ng SRP requests are unique. Since duplicate tags would likely cause a credit leak (one response for two requests), this could lead to deadlock, as InitReqLimit and TRL would be out of sync. We either need to require verification of uniqueness, or provide a ReqLimit re-sync mechanism. intel 0099 Sect: 6.2 Pg: 24 Ln: 2 shall only be sent during RDMA s/b: shall be sent only during RDMA intel 0100 Sect: 6.2 Pg: 24 Ln: 41 maxi mum length Add: in bytes intel 0101 Sect: 6.3 Pg: 27 Ln: 4 shall only be sent s/b: shall be sent only intel 0102 Sect: 6.3 Pg: 27 Ln: 40 maximum length Add: in bytes intel 0103 Sect: 6.3 Pg: 27 Ln: 45 C 52 or larger AER_REQ requires 56 intel 0104 Sect: 6.4 Pg: 29 Ln: 3 a(n) SRP target intel 0105 Sect: 6.4 Pg: 29 Ln: 40 too large Need a way to specify, so that Init does not have to guess intel 0106 Sect: 6.5 Pg: 30 Ln: 20 delay a vendor specific time Wait for transport ACK or timeout error at least

```
intel 0107 Sect: 6.6 Pg: 31 Ln: 3 C
    An SRP_T_LOGOUT request may also be used to notify
    the SRP initiator port that an RDMA channel has failed,
    rendering it non-operational.
If the channel has failed, it won't be able to carry this IU.
We DO need a way to report failures.
intel 0108 Sect: 6.6 Pg: 31 Ln: 30
There are no references in spec to reason codes 2, 3, 6-9.
Do we need some SHALLS pointing to them?
intel 0109 Sect: 6.6 Pg: 31 Ln: 45
  del ay a vendor...
Reference: xport ack or timeout
intel 0110 Sect: 6.8 Pg: 34 Ln: 14
Change to PMDL Length
intel 0111 Sect: 6.8 Pg: 34 Ln: 40
  Add ref a, b to notes below
intel 0112 Sect: 6.9 Pg: 36 Ln: 36
  Since SENSE DATA length is 7 bytes + a one-byte length field, at least the
top two bytes s/b reserved. We may want to have this field be that one-byte
length field, with 7 assumed, as in SPC.
intel 0113 Sect: 6. 9 Pg: 37 Ln: 9
     length of the...buffer
Ref 5.4 for length determination
intel 0114 Sect: 6. 9 Pg: 37 Ln: 26
  indicates (that) the contents .... shall be ignored and (that) the
intel 0115 Sect: 6.9 Pg: 37 Ln: 26
     The (value of the) SENSE DATA LIST LENGTH field (be a multiple of four).
intel 0116 Sect: 6.9 Pg: 37 Ln: 26 C
   SENSE DATA LIST LENGTH shall contain the length of the truncated SENSE DATA
field.
This is at odds with SPC-2, which returns the total length. How would you know
that you had
missed some Sense Data?
intel 0117 Sect: 6. 9 Pg: 37 Ln: 47
     shall contain a length of 4
Also defined in Table 23 - refer to table instead
intel 0118 Sect: 6. 9 Pg: 38 Ln: 17
   structure eqn as DOBL - (offset + 1)
Much easier to understand
(global change to all similar egns)
Formatting - more white space above and below, use bold font
intel 0119 Sect: 6. 9 Pg: 38 Ln: 24
  may or may not
not is the more worrisome case
(more so for Ln 25)
intel 0120 Sect: 6.9 Pg: 38 Ln: 31
    Some commands may have a non-zero residual
Add: e.g., INQUIRY
intel 0121 Sect: 6.9 Pg: 38 Ln: 45
 may not
intel 0122 Sect: 6.9 Pg: 39 Ln: 1
    certian (SRP) protocol errors
```

intel 0123 Sect: 6. 9 Pg: 39 Ln: 18 Would there ever be a case where a RSP of NO FAILURE was returned? intel 0124 Sect: 6.9 Pg: 39 Ln: 31 sense data shall be presented presented s/b returned Al so Ln 32, 33 intel 0125 Sect: 6.9 Pg: 39 Ln: 33 whose Use whose wrt people only intel 0126 Sect: 6. 9 Pg: 39 Ln: 30 SPC-2 Annnex C references SPC-3 - which? intel 0127 Sect: 6. 11 Pg: 40 Ln: 43 C See comments on 5.3 for CRED_RSP issues intel 0128 Sect: 6. 12 Pg: 41 Ln: 31 Don't need four bytes for SENSE data length (7 + 1 byte) intel 0129 Sect: 6. 12 Pg: 41 Ln: 43 The (value of) the SENSE DATALen field (shall be a multiple of four.) intel 0130 Sect: 6.12 Pg: 41 Ln: 44 C If no sense data is provided, What would the point be - to force Init to issue Req Sense Request? Should this be allowed? intel 0131 Sect: 6. 12 Pg: 42 Ln: 1 SENSE DATA LIST LENGTH shall contain the length of the truncated SENSE DATA field. Appears to violate SPC-2. intel 0132 Sect: 6. 12 Pg: 42 Ln: 7 presented s/b (returned in response to) intel 0133 Sect: 7. 2 Pg: 43 Ln: 21 The following subclause defines the fields in the di sconnect-reconnect mode Nope - same subclause intel 0134 Sect: 7. 2 Pg: 43 Ln: 25 Gray-out or mark as Reserved the fields that are reserved for SRP. There's a lot of noise for the two fields that are used... intel 0135 Sect: 7.2 Pg: 44 Ln: 1 SRP devices shall only use (the) disconnect-reconnect page parameter Use formatting for disconnect-reconnect intel 0136 Sect: 7. 2 Pg: 44 Ln: 1 SRP devices shall only use ... fields defined below. What about the standard mode page header fields? intel 0137 Sect: 7.2 Pg: 44 Ln: 7 field shall not be implemented by SRP target ports Define in terms of behavior, not implementation. Appears to have been covered by para above. intel 0138 Sect: 7. 2 Pg: 44 Ln: 17 If the EMDP bit is set to 0, the SRP target port shall generate (RDMA requests with) continuously increasing () addresses for a single SCSI command. intel 0139 Sect: 7. 2 Pg: 44 Ln: 19 affect the order of frames within an RDMA.

What's a frame? Within an RDMA what?

intel 0140 Sect: 7.2 Pg: 44 Ln: 24

intel 0141 Sect: 7.2 Pg: 44 Ln: 24
 protocol specific
s/b protocol -specific
(also Ln 27)

intel 0142 Sect: 7. 2 Pg: 44 Ln: 28 LUN -> PORT

intel 0143 Sect: A. 1 Pg: 45 Ln: 11 Top right box s/b Device Server?

intel 0144 Sect: A. 1 Pg: 45 Ln: 29
 four step, two step
s/b four-step, two-step
(gl obal)

intel 0145 Sect: A. 1 Pg: 46 Ln: 16 Need close paren after initiator

intel 0146 Sect: A. 1 Pg: 46 Ln: 43 Close paren

intel 0147 Sect: A. 3 Pg: 47 Ln: 11
 See table A. 1 for the definitions of the names used within
Don't see names there - objects?

intel 0148 Sect: A. 4.1 Pg: 48 Ln: 44 Use bold for EXECUTE COMMAND

intel 0149 Sect: B. 3. 1. 7 Pg: 52 Ln: 35 IBTA uses caps for G S I

intel 0150 Sect: B. 3. 1. 2 Pg: 52 Ln: 23

Do we need to define, spell out GUID?

intel 0151 Sect: B. 3. 1. 14 Pg: 53 Ln: 1 Ports also present on switches.

intel 0152 Sect: B. 3. 1. 16 Pg: 53 Ln: 5 Speel out QP, use IBTA definitition.

intel 0153 Sect: B. 3. 2 Pg: 53 Ln: 20 IBTA uses caps for R T U

intel0156 Sect: B.5 Pg: 56 Ln: 2
An SRP initiator device is one or more IB consumers may consist of

intel 0160 Sect: B. 5 Pg: 56 Ln: 41

The service delivery subsystem contains queue pairs, IB channel adapters, IB ports, and the InfiniBand TM Architecture fabric.

Contains exclusively?

How does this map to Clause 4 RDMA Comm Service?

intel 0161 Sect: B. 5 Pg: 56 Ln: 47
 general service interface
IBTA uses caps

intel 0162 Sect: B. 5 Pg: 56 Ln: 48 I/ (breaks across page) 0

Remove slash from FRAME list of characters for line breaks.

intel 0163 Sect: B. 6.2 Pg: 57 Ln: 13 open IBA connections use establish instead

intel 0164 Sect: B. 6. 3 Pg: 57 Ln: 25

Port and CM Redirection or Port Redirection.

Very hard to parse - use bold or underscores inside the names

intel 0165 Sect: B. 6. 4 Pg: 57 Ln: 38 SRP_LOGOUT IU

list as T_LOGOUT, I_LOGOUT or define as a virtual field

intel 0167 Sect: B. 6. 4 Pg: 57 Ln: 38

The sender may disconnect if its send queue has transitioned to (THE) error state.

What do you mean by disconnect here - local action?

intel 0168 Sect: B. 6. 4 Pg: 57 Ln: 42

The receiver of an SRP_LOGOUT IU shall respond with an InfiniBand TM Architecture transport acknowledgement and disconnect.

Destroy QP, send DREQ, ...?

intel 0170 Sect: B. 6.5 Pg: 58 Ln: 1 WRITE packets

WRITE requests

intel 0171 Sect: B. 7 Pg: 58 Ln: 37 outcommands

intel 0172 Sect: B. 7 Pg: 59 Ln: 7

Why list ChangelD and OptionROM to say we don't care about them?

intel 0173 Sect: B. 7 Pg: 60 Ln: 23 C

Send Message Depth

Reserved -> Maximum Initiator Request Limit

This allows initiators to efficiently allocate buffers

intel 0174 Sect: B. 7 Pg: 60 Ln: 24 C

RDMA Read Depth

reserved -> Maximum IOC-issued RDMA depth

Allows inits to effficiently allocate RDMA resources

intel 0175 Sect: B. 7 Pg: 60 Ln: 26 C Send Message Si ze rsvd -> MAXIMUM INITIATOR TO TARGET IU SIZE Eliminates need to guess this value intel 0176 Sect: B. 7 Pg: 60 Ln: 46 C This field is expected to be marked obsolete in future versions of the Infini Band TM Archi tecture Not for T10/ANSI to say intel 0177 Sect: B. 7 Pg: 61 Ln: 13 C Is : reserved a literal? If not, express as : zzzz, explain below that it is reserved. intel 0178 Sect: B. 7 Pg: 61 Ln: 16 No references to Table notes. intel 0179 Sect: B. 7 Pg: 61 Ln: 16 padded s/b extended *************** Comments attached to No ballot from Mr. Edward A. Gardner of Ophi di an Desi gns: see 01-325 **************** Comments attached to YesC ballot from Mr. Paul D. Aloisi of Texas Instruments: This has the appearance of a draft copy, not a final review copy. Change bars and line numbers should not be on a letter ballot document. ***************** Comments attached to Abs ballot from Mr. Doug Piper of Woven Electronics: Can not Contribute