SSC-3: Obsolete GAP SIZE field (T10/05-066r0)

(110/05-066r0) Dave Peterson, CNT

As a result of addressing an action item to remove references to inter-block gaps and erase gaps I propose that the GAP SIZE field in the Device Configuration mode page be made obsolete in SSC-3.