

SSC-3: Obsolete RSMK and setmarks

(T10/05-067r0)

Dave Peterson, CNT

I propose that the RSMK bit in the Device Configuration mode page and all setmark functionality be made obsolete in SSC-3.