

To: Membership of X3T10

From: Edward Lappin  
Exabyte Corporation  
tedl@exabyte.com  
(303) 447-7718

Date: March 9, 1995

Subject: Addition of ASC/ASCQ codes for cleaning cartridges.

**Background**

For sequential devices, particularly tape, there is a need to determine when a cleaning cartridge is required. This type of notification could be termed a maintenance request.

Additionally, the cleaning cartridge may be defective or completely used up. This requires some notification as well. Whether or not the cartridge is ejected after a cleaning attempt is device-specific.

**Proposal**

I am requesting that we add the following ASC/ASCQ pairs to SCSI-3 SPC.

<u>ASC</u>	<u>ASCQ</u>	<u>DTLPWRSOMCA</u>	<u>Description</u>
00	17	DTL WRSOM A	CLEANING REQUESTED
30	07	DTL WRSOM A	CLEANING CARTRIDGE FAILURE