

April 28, 1995

X3T10/95-241r0

Ms. Lynn Barra  
ITI  
1250 Eye Street, NW Suite 200  
Washington, D.C. 20005

Subject: SCC Public Review Comments

Dear Ms. Barra:

The following are IBM's public review comments on the SCSI-3 Controller Commands Standard (X3T10/1047D):

If an SCC device changes its configuration in response to task management functions or losses of power, commands which are in-flight to the device may overwrite data which they were not intended to access. To ensure that this does not occur, a statement such as the following is needed:

All SCC devices shall save their current configurations throughout all task management functions and power outages.

This statement might be put in section 5.2.2.14, Volume Sets. Other locations may be more appropriate, however.

Sincerely,

Joel Urman

JU/kc