X3T10/96-164 revision 0

To: X3T10 Committee (SCSI)

From: George Penokie (IBM)

Subject: SCC-2 Proposals

Attached are several changes that have been requested by incorporated into SCC-2:

These changes include:

- -Adding a new redundancy method
- -Indication that a redundancy group is overlaid
- -Making it illegal to modify an object without specifying the object
- -Allow a space to be configured to cover all like objects within a target in one service action
- -Add disable, enable, and report disabled volume set service actions
- -Add a report device identification service action

The above changes are attached.

1 SCC-2 Proposals