

Charles Monia
Digital Equipment Corp.



X3T10/96-192R0
July 11, 1996

From: Charles Monia
Digital Equipment Corp.
Email: monia@shr.dec.com
Voice: 508-841-6757
Fax: 508-841-6100

To: Members of X3T10

Subject: X3T10/96-192R0 -- Request for Firmware Boot/Restart ASC/ASCQ

Discussion

SCSI devices indicate a firmware boot/restart by issuing an ASC/ASCQ of 29 00 ("power on occurred"). To facilitate error logging and diagnosis, it is requested that a new ASCQ code be allocated, preferably in the ASC 29 group, to report a boot/restart event.