

Date: March 30, 2000

To: T10 Committee (SCSI)

From: Jim Hafner (IBM) (hafner@almaden.ibm.com)

Subject: A Detailed Proposal For Access Controls

ABSTRACT:

A SAN (storage area network) is a network environment where multiple hosts machines (clients/initiators) have access to a collection of storage devices (targets). Unless there is significant collaboration between the initiators, it is desirable in this environment, to partition, fence or otherwise restrict access to some storage devices by different hosts. The current SAN protocols (either at the transport layer or in the SCSI layer) are not well-suited to this purpose.

In this proposal, we detail new SCSI commands and target actions to implement access control management. Two new commands are proposed which allow configuration (Data-Out) and reporting (Data-In) of access control management functions at the target. The new commands and actions are not restricted to storage devices but are applicable to any target.

Earlier revisions reflected comments, questions and suggestions from folks at LSI Logic, Sun Microsystems, Adaptec, Compaq and others at IBM.

Revision 5 was based on extensive discussions between Ralph Weber (ENDL Technologies), David Chambliss (IBM) and the author. The general framework of the model is joint work. But the author is responsible for the content of this document, particularly for inconsistencies, incompleteness, errors, or blunders.

In particular, revision 5 attempted to merge the requirements presented in 00-123r0 (for what has been dubbed LUN Mapping) and the additional features of 99-245r4.

Revision 6 modifies the model for the LUN Map owner from target enforced rules to explicitly defined by PAM. This change was a requirement from a number of companies, including LSI Logic and Compaq.

Revision 7 settles most of the Open Questions raised in rev. 6. It expands on the "log" and specifies an "override key" model which seemed not to raise any red-flags.

This revision has no specific provision for access controls on subcomponents.

1.0 Introduction

A SAN (storage area network) is a network environment where multiple hosts machines (clients/initiators) have access to a collection of storage devices (targets). Unless there is significant real-time collaboration between all the initiators, it is desirable in this environment, to partition, fence or otherwise restrict access to some storage devices by different hosts. The current SAN protocols are not well-suited to this purpose of access control management.

In our view, access controls should have the following properties:

- a) they should be enforced at the target;
- b) they should be granted to a host (i.e., at the OS-image or virtual machine level) and not to particular initiators (or ports or HBAs) within a host if at all possible;
- c) they should be configured by some application client which is responsible for overseeing access controls over the entire SAN;
- d) a configuration of access controls should not be associated with the particular initiator from which the configuration command was sent.

The last three points imply that SCSI reservations are inadequate to the task unless there is a single (real-time) application client coordinating reservations for *all* initiators in the SAN simultaneously. Such an application in a complex, multi-OS, multi-initiator environment would be expensive and difficult to manage.

To enable the protection required for access to devices in a simpler and easier to manage way, we propose a new SCSI-based protocol for access controls. This protocol is independent of the transport layer and is suited for any SAN environment whose higher level protocol is SCSI (e.g., FCP).

A general scenario is the following. A client application (what we call the Partition Access Manager or PAM¹) has knowledge of all the initiators and target devices on the SAN. PAM can instruct a given target device to restrict access to some or all of its logical units by all initiators except those from some small set. Such a set might be a single host. Within the set, data integrity, locking, etc., is coordinated by existing protocols (like reservations) via a separate application client operating within the scope of this group. One might say that such a set is a “shared access group”. Hosts outside this group are denied (most) access to the device. In particular, these hosts can not preempt a reservation, issue read/write commands and the like. (Provisions for quality of service or resource allocations within a “shared access group” are outside the scope of this proposal.)

Note the following features of this scenario. PAM need only have one in-band communication channel to the target devices. PAM does not need to have any active presence on all the initiators, because the configuration commands are initiator independent. Furthermore, access restrictions are enforced at the target devices. This means that new hosts added to the SAN have no access to restricted targets unless expressly added by PAM. Also, hosts need have no special application client running in order to “fence” them from target devices to which they should not access or to gain access to devices to which they have been granted access.

The proposal can be applicable to any kind of target, not just storage devices. Resource requirements at the target can vary so that even limited function devices such as disk drives themselves might be capable of implementing these functions. However, it is more likely that larger devices such as controllers, devices with an embedded controller, medium changers, intelligent bridges (e.g., FC to SCSI) and the like would implement these functions.

There are two new commands with different service actions proposed. There is a Data-In command typically used to query various status information of the target with respect to access control functions and a

1. PAM is not part of the proposed standard, nor is it necessarily a real application. Mainly it is a pseudonym for the management application overseeing access controls for the SAN. It can be instantiated by a real application or instantiated more generally by the use of the defined protocol by users.

Data-Out command typically used to configure different kinds of access controls. These are detailed in later sections. However, use of configuration commands are limited with respect to application clients or initiators. Initiators with access to a device have the right to issue proxy rights to other third party initiators without PAM's direct intervention. On the other hand, PAM's configuration tools (MANAGE ACL service action) can only be used by an application client (namely PAM) which shares a key with the target. This key identifies PAM as the originator of the command independent of which initiator she uses for command delivery. The key is maintained as part of the access control information of the target and must be preserved through power cycles.

An model for override of the target's key (in the unlikely event that PAM forgets it) is provided. This model allows for a lockout state where the key overrides are not allowed and an unlocked state where a simple override can occur with a defined command and service action. The lockout state can be easily maintained by PAM through management of a countdown timer; restart of the timer requires little overhead and does not even require PAM's "key". The initial value of the timer is configurable by PAM.

Hosts (or OS-images) can be identified by a new AccessID as defined in this proposal. The reasons for the new identifier are the following. First, the new AccessID is transport independent and so is applicable to all current and future transport protocols. Second, (as noted above) access rights are naturally associated with the host machine (or virtual machine), not the individual initiators (ports/HBAs) on that machine. Transport layer identifiers, either transitory (e.g., FC N_Port) or persistent world wide identifiers (e.g., FC World Wide Nodename) are cumbersome and inadequate. Because they are bound to the given HBA within a machine, they are portable. This would require PAM to maintain continual knowledge of host hardware configuration simply to manage access rights. However, for additional function, the design contains provisions for transport-layer as well as vendor-specific identifiers.

The intent of the AccessID is to assign a permanent identifier to a given host machine (actually OS-image) without regard to the number of ports/HBAs on that host or any actions which change the hardware configuration of the machine. This makes management by PAM of the target's access controls much simpler. But it also implies requirements on the part of target to maintain associations between the AccessID and a given hosts initiator port or ports. These requirements are similar to but in some cases less restrictive than those already required by reservations.

For Fibre Channel, the use of Process Associators allows multiple virtual machines to share the same hardware connection to the fabric. From the point of view of the target, however, each N_PortID/Process Associator pair appears as a separate SCSI initiator (in our understanding). Consequently, AccessIDs can enable finer grained access management than what is available by use of persistent transport identifiers such as WWNs. They don't require management by PAM of the specific assignment of Process Associators at the fabric layer and so further simplify PAM's job.

Though AccessIDs create a new identifier name space that PAM must manage, it is our opinion that the gains in simplicity, stability and transport independence outweigh this concern.

What follows this main section is a detailed description of the new commands and target requirements and constitutes the normative part of the proposal. Section 2.0 discusses the model, raises some design questions and issues and documents the revision history. Section 3.0 proposed changes to the glossary and acronyms clauses. Sections 4.0 is proposed as an additional sub-clause in the model clause of SPC-x. Sections 5.0 and 6.0 are proposed as additional command definition clauses to SPC-x. The appendices propose additional small changes to other standards documents.

AUTHOR'S NOTE: *AUTHOR'S NOTES are intended to generate small questions and expose small issues for possible further action. Ideally, later revisions of this document will have these issues addressed and the notes removed. In any case, they should not be included in the final editorial changes included in SPC-x. Larger issues are listed in the next section.*

2.0 Additional major issues or questions¹

2.1 The new model and open issues

There are significant changes to the basic access controls model introduced in revision 5 and continued here. We summarize the new model in more detail in what follows, but begin by highlighting a few of the major differences with the old model.

The earlier drafts (revision 4 and earlier) all shared the “visible but inaccessible” approach to access denial. That is: all logical units are visible to all initiators (meaning that they are discoverable under INQUIRY and REPORT LUNS) but non-privileged initiators are denied service (in particular I/O service) by specific CHECK CONDITIONS. This new draft replaces the “visible but inaccessible” model with what has been dubbed LUN Mapping. This has two features. First, it “hides” logical units which are not accessible to a given initiator. So, to such an initiator INQUIRY to some logical units will report “no device present” and REPORT LUNS will only show a set of LUN values representing a subset of the complete set of logical units on the target device. The second feature of LUN Mapping is that the LUN values reported in REPORT LUNs are initiator-specific. That is, for each initiator a given LUN will only be a pointer to an specific logical unit and that pointer is a function of the initiator. Thus, the same (shared) logical unit may be addressed by one initiator at LUN1 and by another initiator at LUN2. A consequence is that LUN values are no longer global addresses for specific logical units within a target. This complicates a number of shared functions (such as third party copy operations). This “mapping” function however is seen as a functional requirement.

Because of the changes required for LUN Mapping, the proxy model has changed significantly. This is discussed in more detail in 2.1.2.

The new model begins with the following assumptions and requirements:

- a) PAM knows best what the LUN Map should look like for a given initiator; she needs this ability to minimize the “move LUN” problem when access controls rights are changed for a given initiator (this is changed from revision 5);
- b) most hosts can handle gaps in there LUN list (this is changed from revision 5); PAM assumes the responsibility for this if required;
- c) host resources for never-accessible logical units should not be wasted;
- d) some hosts require access to a specific logical unit at LUN0 (for boot?) (this is unchanged from revision 5 but the implementation of this is different);
- e) facilitate third-party operations in a simple way (proxy);
- f) need an interlock with hosts to assist them with enrollment requirements;
- g) LUN Map changes should be minimized and managed so that data integrity is protected and host efforts to recover from LUN Map changes are minimized (this is better facilitated by giving PAM ownership of the LUN Map);
- h) provide a simple mechanism to both allow for the override of PAM's shared key, under controlled conditions, and to easily manage these conditions.

With these in mind, the model has the following characteristics.

First, PAM tells the target device to grant access to a particular logical unit to a given initiator under a specific LUN value (in other words, PAM instructs the target to create a LUN Map entry of a particular type for the specified initiator).

An initiator can be identified to the target by either a TransportID (available at connection time, say, FC-login) or by AccessID (available only after an enrollment action by the initiator). Since the latter can

1.This section is primarily to discuss the model, raise discussion points and to log changes to the various revisions; it is not part of the proposed standard.

only come after the connection, the target will always map TransportID-accessible logical units before mapping AccessID-accessible logical units. Furthermore, an initiator (such as a copy manager) may get access (have its LUN Map changed) through proxy functions.

Because of the independence of the LUN Maps defined for TransportID and AccessID, it is possible that PAM can instruct the target to create a LUN Map which can not be instantiated. There are two possibilities that need to be dealt with:

- a) PAM instructs the target to map a specific LUN value to one logical unit under a TransportID and to another under an enrolled AccessID;
- b) PAM instructs the target to map a specific logical unit by one LUN value under TransportID and by another LUN value under an enrolled AccessID.

Note that neither of these conflicts may be detected at the time PAM instantiates the configuration (that is, when PAM issues the MANAGE ACL service action), without additional functionality; these conflicts might only be detected at the time of an enrollment. Consequently, the target needs a rule to handle conflict resolution on the fly and also needs a means to report that to PAM on request. To handle this, we require that the target maintain some log of conflict resolutions (the log is limited by the resources of the target in implementation dependent ways). The minimal log is a counter of the number of conflict resolutions which the target had to handle. The log may also contain a list of conflicts which occurred and were resolved by the target (until log resources were exhausted). The log can be queried by PAM and cleared by PAM via specific service actions. Additional log features are also specified.

The TransportID and AccessID portions of the LUN Map have the following properties:

- a) LUNs in these portions normally appear during system (host) startup and remain unchanged from one boot to the next;
- b) more than one LUN can appear in either of these portions as a result of a single action on the part of the initiator (e.g., PLOGI or enrollment);
- c) automated loss of access (e.g., LIP) can be corrected by repeating the PLOGI or enrollment;
- d) only one LUN value shall be assigned to a logical unit under both TransportIDs and AccessIDs (that is, for logical units accessible under both TransportIDs and AccessIDs, the mapping is one-to-one).

The Proxy portion differs as follows:

- a) LUNs in this portion do not appear normally during system startup and may change dynamically during the life of the system;
- b) exactly one new LUN appears in this portion as the result of a single action by the initiator (ASSIGN PROXY LUN service action);
- c) automated loss of access will not be corrected by the same mechanisms that work for TransportIDs and AccessIDs.
- d) multiple LUN values assigned under proxy may reference the same logical unit.

Note that a logical unit may be addressable by a given initiator at a single LUN value in the TransportID or AccessID portion and/or via one or more LUN values in the proxy portion.

The TransportID portion of a LUN Map for an initiator after a target reset will be restored. The AccessID portion may not (in an implementation-specific manner) be restored. But such an initiator will easily detect the failure, recognize the potential reasons and take the necessary action (enroll) to restore access.

We assume three possible states for an initiator with respect to a target:

- a) "enrolled" - in this state, LUN Map contains entries for logical units to which the enrolled AccessID has been granted access;
- b) "de-enrolled" - in this state, which is the transition state from enrolled because of automated loss of access (e.g., LIP) or PAM-initiated event (e.g., Flush in MANAGE ACL service action), the

AccessID accessible logical units stay in the LUN Map, but are “inaccessible” with status and sense indicating that the enrollment was invalidated;

- c) “not-enrolled” - in this state, the target has no association of an AccessID for the initiator; the initiator’s LUN map contains only references to logical units for that initiator’s TransportID.

Simply, the first enrollment action by an initiator merges the LUN Map entries for the enrolled AccessID into the existing LUN Map and puts the initiator in the “enrolled” state. Events (outside of the initiator’s control) may cause the initiator to go into the de-enrolled state. The LUN Map doesn’t change, but commands to the affected logical units are failed with sense data sufficient to trigger the initiator to re-enroll. This would put the initiator back into the enrolled state. The initiator switches between these two states under normal operation.

An initiator can go into the not-enrolled state under two events. The first is by its own actions (CANCEL ENROLLMENT). This should be used by an initiator prior to shutdown so the target can free up enrollment resources. This is not required, however. The second event is an action by PAM which causes a change in the LUN Map for that initiator. Such events are (or should be) rare but they have the potential to adversely affect the host and its data. This scenario is described in 2.1.1.

We propose the existence of a new entity in a device. We call this the “access controls coordinator”¹. This entity is the repository of the access controls data, the coordinator of access rights, the handler of enrollments and the builder of LUN maps. This entity spans multiple logical units as well as spans all the ports in a multi-ported device. In effect, it creates an interface between the ports and the logical units for the purpose of restricting access, and managing the LUN Maps for initiators. This entity is addressable only (or “should” be only) via LUN0. [We’ve allowed for access control commands to go to any LUN, to facilitate the difficulties of host/OSs which do LUN offsetting or LUN mapping internally.]

2.1.1 Host/target/PAM interlock for LUN Map changes

Actions by PAM to the ACLs for a given TransportID or AccessID may cause a change in the LUN Map for some initiators. If not coordinated carefully with the affected initiators, this can have undesirable effects on the user data. E.g., if a host has a string of I/Os queued (at the host) addressed to a LUN value and intended for a particular logical unit, and PAM changes the LUN Map so that this LUN value no longer addresses the same logical unit, the queued I/Os will (without a specific interlock) go to the wrong logical unit, thereby both corrupting the data on the newly addressed logical unit and the hosts view of that data consistency.

Note that this issue arises only if a LUN value “moves” to a new logical unit; not if the LUN value is “added” to the LUN Map or if the LUN value is “deleted” from the LUN Map. For the added case, there would be no active I/Os, even though the initiator will need to take some action to “discover” the new logical unit. For the “deleted” case, all I/Os will fail with “logical unit not supported”, and no data is transferred.

To address this problem, we first postulate that PAM will never take this sort of action unless she has sufficient knowledge that such risks to data integrity have been minimized. This might mean making sure that the affected hosts are shutdown (or quiesced) and that sufficient rediscovery of the LUN Map by the host will correct the problem.

Second, a tight interlock between PAM and the host is actually only required for that portion of the LUN Map in the TransportID portion. The AccessID portion can be handled by relying on the enrollment process itself (see below). TransportIDs will (should) only be used in a couple of cases. In the first case, if the host does not participate in the access controls protocol (e.g., a legacy system). In this case, PAM will need a direct interlock with the host. In the second case applies to perhaps a very limited set of logical units (e.g., for boot devices) for hosts which do participate in the enrollment protocol; most of their LUN Map should be

1. Alternatives to “coordinator” are “enforcer” or “manager” or “enforcement manager”. Enforcer is an unpleasant word and manager might be confused with PAM, so we chose coordinator.

in the AccessID portion. In this case, there is less likelihood of an action by PAM affecting the LUN Map, so less need for direct PAM/host interlock.

Third, and most important, since PAM owns the LUN Map, she can implement a policy which significantly reduces or eliminates this problem.

For the AccessID portion, we propose the following host/target interlock. If PAM initiates a LUN-move change to the LUN Map for a given AccessID, the target immediately places all affected initiators in the not-enrolled state; all formerly addressable logical units become “not supported”. This error message will be sufficient notification to the host that something dramatic has happened (either the map changed or the target reset). In either case, the host should suspend IO, re-enroll and redrive the LUN-discovery process (at the affected target) to clean up its internal references to logical units.

2.1.2 The proxy model

In a previous revision, an initiator would grant a third party (based on an identifier for that third party) proxy access to a logical unit to which the granting initiator already had access. This had a couple of limitations (e.g., a copy manager given proxy access couldn't farm out part of its job to another party). In the presence of LUN Mapping, however, the problem is more pronounced in that there is no longer global addressing of logical units (by LUN). Consequently, if initiator A wanted initiator B to have access, A would need to grant proxy right (at the target) to B, somehow find out what LUN got generated for that logical unit in B's LUN Map and use this value when requesting services from B (e.g., in EXTENDED COPY target descriptors). In this revision, we change the proxy model significantly. An initiator, instead of granting access to a third party by initiator identifier, requests a proxy token from the target for a specific logical unit, passes the token to the third party, and that third party uses the token to request a LUN value for that logical unit.

This has the following advantages:

- a) global addressing of logical units by LUN is no longer required in the presence of a LUN Map;
- b) proxy tokens can be forwarded from one third party to another;
- c) multiple proxy tokens can be used for the same logical unit;
- d) each token held by a third party can be used to assign a separate LUN value (for the same logical unit); this allows the third party like a copy manager to separate the required tasks by LUN);
- e) separation of proxies between initiators sharing a given logical unit; e.g., if initiator A and B have forwarded proxy tokens for a shared logical unit, they can invalidate their own tokens without affecting the other initiator.

We have proposed changes to the EXTENDED COPY target descriptors to include Proxy Tokens as handles or references to logical units.

We propose that proxy tokens can be invalidated by an initiator which knows the proxy token, by any initiator with PAM-granted access to the logical unit (to invalidate all proxy tokens for a given logical unit) or by PAM either by individual proxy token or for all proxy tokens at a target.

In revision 5, we mapped out two variants of a protocol for the third party to get a LUN value for a Proxy Token. The preferred method is that the third party initiator specifies a preferred LUN value when requesting the access to the logical unit (that is, the initiator asks “can I have LUN=x for Proxy Token=t?”). The alternative is the third party initiator requests the target generate a LUN value for the token (that is, “what LUN value can I have for Proxy Token=t?”). In revision 6, we stabilize on the preferred method. Unfortunately, this model can open up the “twenty questions” problem. To alleviate this, we've specified that the target include an alternative LUN value embedded in the sense data of the failed request. See 6.1.8.

2.1.3 Override of Management Identifier Key

This design requires that the Management Identifier Key be used by an application client (PAM) whenever it wants to change access controls at a target. We expect that this application will reliably maintain this

information and do not expect that PAM will “forget” the key. However, we need to allow for some mechanism to override the existing key, just in case. Many alternatives have been proposed. In this revision (rev 7) we propose the following model, which incorporates the notion of a “state machine” (to allow override only if the device is in a special state) and “fingerprints” (to record attempts, both failed and successful, to override the key). The curious thing about this model is that the default state is to allow unrestricted override; only in a changed state is the override prevented. Maintaining a device in this special state is simple and requires very little overhead.

The access controls coordinator maintains a configurable timer (a non-negative integer) which decrements approximately once per second (until it reaches zero).

If the timer is zero, the override attempt (via the OVERRIDE MGMT ID KEY service action) shall succeed. If the timer is not zero, any attempt to override the key shall fail. Furthermore, all attempts to override the key are logged with the TransportID of the initiator sending the service action, the state of the timer and additional implementation-dependent data (e.g., real-time clock, if available).

The timer is managed with the MANAGE OVERRIDE LOCKOUT TIMER service action. This has two possible functions:

- a) reset the initial (starting) value for the timer, check the current value of the timer, and restart the timer (this action requires validation with the Management Identifier Key);
- b) restart the timer (this does not require validation with the Management Identifier Key).

In other words, PAM (and only she) can define the initial state of the timer and get the current value for the timer. Any initiator can restart the timer.

An initial setting of zero for the timer effectively disables the timer.

This enables PAM to easily maintain all the devices she manages in the override locked state (make sure all the timers are positive) in a manner consistent with objectives and policies of a particular deployment. There is very little overhead for her to maintain this state for all the target devices.

If for any reason PAM forgets the keys she uses to manage a device (or all devices), she can allow the timer to lapse, and then issue the override.

We are requiring that the timer be restarted under each of the following conditions:

- a) on demand, with successful completion of MANAGE OVERRIDE LOCKOUT TIMER;
- b) target resets and power-cycles.

Furthermore, we require that the initial setting of the timer be persistent and non-volatile.

We do not require a real-time clock or even a very accurate timer. PAM can (approximately) measure the timer’s internal accuracy (deviation from once per second decrements) by experiment, namely, querying the current value of the timer.

2.1.4 Access controls log

Revision 6 specified a somewhat incomplete access controls log. That version contained only a log for recording LUN Mapping conflicts which arise because an initiator’s AccessID LUN Map was incompatible in some respect with the LUN Map created for that initiator’s TransportID.

Revision 7 expands on the log and defines its behavior more carefully.

There are three portions to the log, for recording different events. These are: (a) attempts to override the Management Identifier Key, (b) use of commands with invalid key and (c) LUN Mapping conflicts (as

before). Each portion of the log minimally contains a counter of the number of such events and optionally additional information about each occurrence of these special events.

We have defined two service actions to deal with the log, both in the ACCESS CONTROLS IN command. One is designed to report the contents of the log; the other to clear the log. Note that the “override keys” portion of the log cannot be cleared. Reading this portion of the log does not require knowledge of the Management Identifier Key. If it did, someone could override the key and either clear the log (erasing the “fingerprints”) or prevent the real PAM from reading the log (hiding the fingerprints).

We intentionally did not put the log under the LOG SENSE/SELECT command for a number of reasons:

- a) these commands are blocked by access controls so are not available to PAM unless she (or an agent) have direct access rights to LUN0 (i.e., the logical unit through which the access controls coordinator is addressable);
- b) these commands are available to anyone with access rights (not just PAM, assuming she had granted herself access) and some of the data (e.g., AccessID’s) is information that ideally should not be readily accessible to all initiators;
- c) not using these commands better encapsulates the changes to SPC-x for access controls.

The last point here is not really that strong a point as there are many places where this proposal impacts other parts of the standard. However, in most of those cases, the changes are minimal (one paragraph and a field change in some parameter data); changes to LOG SENSE/SELECT for this purpose would be much more intrusive.

On the other hand, the other two points are stronger arguments in favor of encapsulating this part of the model within key-validated (with exceptions) access control commands.

2.1.5 OPEN QUESTIONS

As far as the author is concerned, all issues are closed, with one exception noted in the next subsection. However, the reader may not share this opinion. The author is open to comments and suggestions for changes both to the basic model, the resource requirements, specifics in parameter data structures and editorial issues.

2.1.5.1 SUPPORTED LUN-MASK FORMAT in REPORT LU DESCRIPTORS header

The REPORT LU DESCRIPTORS service action (DataIn) is intended to give PAM sufficient inventory information about logical units as well as other information to help her perform her duties, even if PAM (or her agents) have no access rights to the logical units. Included in this should be some concise description of the LUN values that the target (access controls coordinator) can support in LUN Maps for initiators.

In revision 6, we defined an 8-byte field in the parameter data called the SUPPORTED MAX-LUN FORMAT. This was four 2-byte fields. Within each field, the target indicated the largest value that can be supported within that field. This allowed for (but didn’t require, even if the wording was somewhat misleading on this point) support the hierarchical model of LUN addressing as well as for a flat-addressing model. However, to support the hierarchical model required setting an entire (or most of a) 2-byte field to the maximum value (in order to set the upper most significant bits).

In revision 7, we change this 8-byte field to what is now called the SUPPORTED LUN-MASK FORMAT. This is also partitioned into four 2-byte fields. Within each field, any bits set to zero are not supported by the target in a LUN Map entry. (Actually, there is little need for partitioning into separate 2-byte fields in this case, but it is intended to help clarify the exposition.) Any bits set to one may be set in some combination with other bits to a supported LUN. Not all bit combinations need be valid.

The point of this revision is to better enable a description of the supported LUN values when the target wants to either support or simulate support for the hierarchical model. In the flat model, the two methods are essentially equivalent.

The open questions here are:

- a) is this new mask format better than the max format?
- b) is this information sufficient enough to be useful for PAM?
- c) are there better alternatives?

Certainly, there are much more complex alternatives. One goal in this is to make the specification simple and not require too many bytes, even if the data is not completely informative (and only hints or sets guidelines).

2.2 Access controls on sublogical unit entities

Revision 4 and 5 have no notion of access control granularity below the logical unit level, though earlier revisions did. There may be a reason in the future to extend access controls to sublogical unit entities. In one context (medium changer) this might be elements. In the up-and-coming Object-based Storage Device model, this might be for access controls on Object Groups (this would provide some simple access controls without the need for complex encryption and authentication protocols - admittedly, this is not a complete solution to the long term objectives of OSDs, but might provide an interim solution).

It would be possible to extend the current model to allow such finer grained controls. The fundamental question however is what direction that can take. There are two alternatives:

- a) Access grant to a logical unit (either by PAM or by proxy token) grants access only to the higher level entity and not any addressable subentity, unless specified otherwise.
- b) Access grant to a logical unit (either by PAM or by proxy token) grants complete access to all sublogical unit entities, unless specified otherwise.

In the first case, we would need service actions and/or parameter structures to extend rights to sublogical unit entities. For example, give initiator A and B access to the logical unit, but they can't use "elements" X or Y within the logical unit. Then we expressly extend A's rights to X and B's rights to Y.

In the second case, we need service actions and/or parameter structures to limit rights. For example, give A and B access to the logical unit and they both can use X and Y. Then we expressly restrict A's access to only X and B's to only Y.

Revision 3 had a different, somewhat intermediate, model. In that version, explicit grant to a full logical unit gave rights to all subentities (similar to case two above); explicit grant to a subentity was limited to that subentity and the top level entity (similar to case one above). This doesn't quite work in this case, mostly because such semantics don't fit (in the author's opinion) very well with LUN Mapping syntax. The proposed options above separate the LUN Mapping service action/parameter data syntax from the subentity extend or restrict syntax.

For example, suppose we adopt case two. Initiator A has access to some or all of a logical unit and wants B to do some copy services for it, but limited to only a subset of A's access. A requests a proxy token from the target which is initially valid for the entire context of A's rights. A follows that request with a specific request to the target to limit the validity of the proxy token to a specific subset of its accessible subentities. A then forwards the proxy token to B with the assurance that B can't get access to that part of the logical unit not accessible to A and not included in the subset scoped by the proxy. (Similar syntax can be used by PAM, to first map a LUN value for a given logical unit and then restrict the range of validity of that access.)

The author has no particular preference for either model at this time.

2.3 Changes from previous revisions

2.3.1 Changes for revision 3

A TransportID is defined for SPI devices.

The language concerning the effects of changes on access controls to commands already in the task manager has been clarified and simplified. It is modeled on the language from PERSISTENT RESERVATIONS.

There is a new OUT service action, RESET AC, which provides a Management Identifier Key validated reset function and a template for vendor-specific reset functions (which might provide an override mechanism for the Key).

There are additions to Table 8 of SPC-2 defining the device server's actions in the presence of reservations when access control commands are issued.

The table of new ASC/ASCQs for access controls has been updated with specific values, consistent with the proposal 99-314r1.

The model for access controls on elements (or more generally on subcomponents of the logical unit) has been significantly redone. There is a definition for an "access controllable component (ACC)" and revised specification of an initiator's access rights when granted access only to such a component. Also, there is now only one ACL at the device server (not one per ACC and the logical unit) and so there is only one ACL Enabled or Disabled state for the device. This was done both to simplify the model (and hopefully clarify it) and to enable a simple evolution to the next revision where this model is deleted (so access controls are only defined at the full logical unit). At the moment there is no driving force behind having this finer granularity, which is why it will be excised from the next revision. We are archiving this revision with the revised model in the event that a future need arises for access controls at a granularity below the full logical unit. For example, the model described here could work with elements of medium changers as originally expected or it could be applicable to access controls on object-groups as might be defined in the Object-based Storage Device proposal currently under review (99-315r0).

This change in the "element" model removes a certain functionality, namely, of disabling access controls on specific ACCs within the device while still maintaining access controls at the full logical unit. There are two possible approaches to this. One is to have a configuration command which can change the classification of a subcomponent from an ACC to a non-ACC component (though this might be hard to define carefully). A second approach is to define a "universal AccessID" which all initiators are automatically enrolled under (so a sort of wild-card AccessID). Granting access to this universal AccessID would be functionally equivalent to disabling access controls at the specific ACC.

Other wording changes of an editorial nature are included here as well.

2.3.2 Changes for revision 4

The model for access controls on subcomponents of the logical unit has been removed.

2.3.3 Changes for revision 5

This is a major revision, and so has substantial changes.

There have been some name changes. E.g., Manage ACL Key is now called the Management Identifier Key. The RESET AC service action has been renamed to DISABLE ACCESS CONTROLS. Many service actions have been changed, added or removed. The parameter data for some commands has changed as well. The set of required ASC/ASCQs has also changed. These changes are detailed in the sections which follow.

There is an additional section (Appendix D.2) which proposes changes to the EXTENDED COPY command's target descriptors to accommodate proxy tokens.

The SCSI Address field in TransportID for SPI-x has a reference to the glossary for this name.

The TransportID for FCP-x has been changed. N_PortID has been removed and the fields rearranged a little. The use N_PortID was only required for proxy purposes. With the changes to that protocol, there is no further need for this addressing field.

We've removed from MANAGE ACL the ability to set the device back to the factory default unconstrained state. This is now only available in the DISABLE ACCESS CONTROLS service action.

PTPL (Persist Through Power-Loss) is now required. Our current feeling is that vendors will implement this feature in all cases, so having this optional only complicated the model unnecessarily.

2.3.4 Changes for revision 6

In this revision, the LUN Map owner switches from the target (access controls coordinator) to PAM. This affects the overall model in small ways, changes the parameter data for a number of service actions and more importantly, adds additional target requirements and service actions (mostly to deal with conflict resolutions issues).

Note that configuration conflicts can be detected by the access controls coordinator under two circumstances:

- a) while processing a MANAGE ACL service action when the parameter data contains conflicting instructions; in this case, the target rejects the command;
- b) when an initiator enrolls an AccessID whose ACL LUN Map instructions conflict with the ACL LUN Map instructions for that initiator's TransportID; in this case, we are suggesting that the target recover as best as possible (namely instantiate all non-conflicting parts of the LUN Map and log all conflicting parts).

We've changed the target-reset/power-cycle volatility of Proxy Tokens. In this revision, the Proxy Tokens are required to persist through these events, but any LUN Map entries created by ASSIGN PROXY LUN service actions are not (this is open for discussion however).

We've also documented in one place (2.1.5) all the open questions (that we are aware of).

2.3.5 Changes for revision 7

Closed on most of the open issues in section 2.1.3 of rev 6.

Changed the notion of iLUN to "default LUN", the LUN value used to address a logical unit in the absence of the access controls coordinator generating LUN Maps (e.g., the LUN values as seen in the default state or as would be "mapped" under the GrantAll page for MANAGE ACL).

Modified the REPORT LU DESCRIPTORS (formerly called DESCRIPTIONS) parameter data to include optional INQUIRY EVPD Page 83 identifier, change iLUN to "default LUN", added a generation value to the header, defined the additional data field. Modified the description of the parameter data used to indicate the range of LUN values the device can map.

Added generation value (for default LUN identifiers) to the MANAGE ACL service action.

Formalized on Proxy Tokens preserving through resets but that LUN Map entries created by REQUEST PROXY LUN disappear through a reset.

Added a section (Appendix D.3) for requesting a bit in Standard INQUIRY data to indicate presence of an access controls coordinator.

Removed the REPORT LUN MAP service action. This contained no useful data (and to some folks, data which should not be made available to a generic initiator, namely the iLUN).

Fixed the length of all currently defined initiator identifiers (TransportID, both SPI and FCP, and AccessID) to 24 bytes, but left the extensibility of the MANAGE ACL and REPORT ACL parameter data structure with variable lengths.

Modified the specifics for ASC/ASCQ assignments per the request from Compaq (Rob Elliot). We have added additional ASC/ASCQ sense codes for OVERRIDE LOCKOUT and for LUN MAPPING CONFLICT (see 4.12).

Removed the VS bit and related facility from the DISABLE ACCESS CONTROLS service action. This now is defined to only reset the access controls to the default state when supplied with the correct key. Vendors who want to implement alternatives can use a VS-specific service action. This change was made because we feel that the model we've proposed for override of lost Management Identifier Key is sufficient to address this issue.

The current host/target/PAM interlock for LUN Map changes been accepted (by the author) as sufficient.

Defined a new method and model for override of lost keys (i.e., if PAM forgets her Management Identifier for a target).

Expanded the log concept and function to include other events (namely, key override events and invalid key events).

Added a section to the model clause to better encapsulate the resource requirements for access controls.

3.0 Glossary and Acronyms

The following additions to the glossary and acronyms section of SPC-x are proposed.

AUTHOR'S NOTE: *it is quite possible that not all these entries need to be in the glossary. They might be better suited for the Access Controls model clause instead.*

3.1 Glossary

Access Controls: An optional feature that restricts initiator access to specific logical units and the information about logical units sent to initiators in the parameter data of INQUIRY and REPORT LUNS commands. (See 5.x.).

Access Control List: The data used by a target to provide access controls for initiators.

Access Controls Coordinator: The entity within a device which coordinates the management and enforcement of access controls for all logical units within the device. This is always addressable through LUN0.

AccessID: An identifier used for granting or revoking access rights to a logical unit. An initiator may enroll an AccessID with the ACCESS CONTROL OUT command and ACCESS ID ENROLL service action so that the device server is able to determine the access rights for that initiator.

enrolled: The state an initiator enters as a consequence of a successful completion of an ACCESS CONTROL OUT command with ACCESS ID ENROLL service action.

de-enrolled: The state an initiator enters from the enrolled state as a consequence of certain events in the service delivery subsystem or by certain access control management actions (e.g., ACCESS CONTROL OUT with MANAGE ACL service action).

not-enrolled: The state of an initiator not in either the enrolled or de-enrolled state. This is the default state of an initiator in the absence of any ACCESS CONTROL OUT command with ACCESS ID ENROLL service action from that initiator. This is also the state after successful completion of the ACCESS CONTROL OUT command with ENROLLMENT CANCEL service action.

Default Logical Unit Number: Used in conjunction with the Access Controls feature (see 3.1.xx) to identify logical units before they are mapped to logical unit numbers under Access Controls; this is the LUN value that would be presented to all initiators under REPORT LUNS for a given logical unit when the access controls coordinator is in the default state (access controls are disabled).

AUTHOR'S NOTE: *Per the discussion in teleconf. of 3/15 (but not by complete consensus), this notion of the default LUN is replacing the notion of the iLUN. That is, this change in the model is equivalent to requiring an implementation of iLUNs where each iLUN would equal the default LUN.*

TransportID: A protocol or interconnect-defined identifier used for granting or revoking access rights to a logical unit.

LUN Map: an initiator-specific list of pairs consisting of a LUN value and default LUN value together with its associated logical unit. The list of LUN values shall be the same as that returned by the REPORT LUNS command.

Proxy Token: An identifier for a logical unit which can be used to gain temporary access to that logical unit.

3.2 Acronyms

ACL: Access Control List

4.0 Access Controls

Access controls are an optional target feature that application clients may use to allow only specified initiators or groups of initiators to access specified logical units. Access controls are handled at the target by an access controls coordinator. The access controls coordinator maps a logical unit to different logical unit numbers depending on which initiator accesses the device. Access to a logical unit affects whether the logical unit appears in the parameter data returned by a REPORT LUNS command and how the logical unit responds to INQUIRY commands. An initiator can be identified uniquely by an access identifier, called an AccessID, as defined in 4.4 or by a protocol-specific identifier, called a TransportID, as defined in the relevant protocol standards.

AUTHOR'S NOTE: *See Annexes A-E for the changes required in other standards documents.*

An application client may add or remove restrictions on an initiator using access control commands.

The methods of managing access controls are identified by the commands:

- a) ACCESS CONTROL IN - primarily used to query the access control information; and
- b) ACCESS CONTROL OUT - primarily used to create, change or revoke access controls.

The access control management commands are not subject to reservation conflicts.

AUTHOR'S NOTE: *See Annex D for the changes required to Table 8 of SPC-2 (rev 14) with respect to reservation conflicts.*

The access controls model provides three states for an initiator with respect to a specific target. The states and key features of each state are as follows:

- a) not-enrolled: the default state for an initiator and the state entered into by the initiator in response to an ACCESS CONTROL OUT command with CANCEL ENROLLMENT service action;
- b) enrolled: the state an initiator enters as a consequence of a successful ACCESS CONTROL OUT command with ACCESS ID ENROLL service action;
- c) de-enrolled: the state an initiator enters as a consequence of specific events in the service delivery subsystem or by specific service actions (and parameter settings) in the ACCESS CONTROL OUT command.

4.4.1 describes each state in detail and the mechanisms that produce transitions between the states.

4.1 Resource requirements for Access Controls

If a device supports the access control commands (has an access controls coordinator), then the device shall be able to maintain the following data structures:

- a) an ACL (access controls list) consisting of a list of initiator identifiers, the list of pairs, each pair consisting of a LUN and a logical unit, to which that identifier has been granted access;
- b) an 8-byte (64 bit integer) called the Management Identifier Key;
- c) a 4-byte (32 bit integer) called the Default LUNs Generation;
- d) a 2-byte (16 bit integer) called the Initial Override Lockout Timer (see 4.6);
- e) a log of access controls related events containing at least the following (see 4.10):
 - a) a 2-byte (16 bit integer) called the Key Overrides Counter;
 - b) a 2-byte (16 bit integer) called the Invalid Keys Counter;
 - c) a 2-byte (16 bit integer) called the LUN Mapping Conflicts Counter.

The access controls coordinator shall be able to maintain at least one entry in its ACL for each of its logical unit. In this way, each logical unit can be dedicated to at least one initiator and so restrict access to competing initiators. The default ACL is empty.

The default value for the Management Identifier Key is zero. This value is changed by an application client with the MANAGE ACL and/or OVERRIDE MGMT ID KEY service actions.

The Default LUNs Generation is managed by the access controls coordinator in an implementation dependent manner. The intent of this value is to time-stamp the association of default LUN values to logical units, in order that an application client referencing a logical unit by default LUN can be assured that it is using a valid association. Consequently, if for any reason (either beyond or within the scope of this standard or related standards, e.g., SCC) the association of default LUNs to logical units changes, the access controls coordinator should change the Default LUNs Generation value.

The Initial Override Lockout Timer is managed by an application client with the MANAGE OVERRIDE LOCKOUT TIMER service action.

The access controls log counters are incremented according to the specifications of 4.10. They are (with noted exceptions) reset to the default value of zero by an application client with the CLEAR ACCESS CONTROLS LOG service action.

Persistence of these data structures through power-cycles or target resets is described in 4.7.

4.2 LUN Mapping

The access controls model specifies that the access controls coordinator modify the device servers' response to INQUIRY commands to a logical unit and to REPORT LUNS commands in initiator-specific ways. The access controls coordinator maps LUN values to its logical units in a manner dependent on the requesting initiator and the ACL data. This feature is called LUN Mapping. The access controls coordinator creates a LUN Map for an initiator according to the rules in its current ACL data as established by successful completion of MANAGE ACL service actions.

LUN values are assigned by the access controls coordinator to logical units (that is, entries are added to a LUN Map) for a given initiator first on the basis of that initiator's TransportID, if there are any such access rights in the ACL data. If the initiator enrolls an AccessID, the access controls coordinator merges into the existing LUN Map for that initiator any entries as specified in the ACL data for the enrolled AccessID. Configuration conflicts can occur at this point. In this case, the responsibilities of the access controls coordinator are detailed in 4.2.1. Additional LUN Map entries may be added based on Proxy Tokens (see 4.5.1).

Note that an initiator's LUN Map may have multiple LUN values referencing the same logical unit; there will be at most one such LUN value assigned via TransportID or AccessID, but multiple values may be assigned under proxy tokens (even to logical units already accessible under either the TransportID or AccessID).

The parameter data returned in response to an INQUIRY command addressed to a LUN which is not mapped to an accessible logical unit shall set the Peripheral Device Type to 1Fh and Peripheral Qualifier to 011b (the device server is not capable of supporting a device at this logical unit).

The parameter data returned in response to a REPORT LUNS command addressed to LUN0 will return only the list of LUN values which are mapped to accessible logical units. If the initiator is in the enrolled or de-enrolled state, this list includes any LUN values mapped to logical units accessible by virtue of the AccessID enrolled by that initiator. If the initiator is in the not-enrolled state, then no such LUN values are included in the parameter data. If the initiator has access to any logical units by virtue of proxy tokens, the corresponding LUN values are included in the parameter data.

4.2.1 LUN Map conflict resolution

Two types of LUN Mapping configuration conflicts can occur at the time an initiator in the not-enrolled state enrolls an AccessID (ACCESS ID ENROLL service action). These are:

- a) if the TransportID and AccessID each require that the access controls coordinator map a single LUN value to different logical units;
- b) if the TransportID and AccessID each require that the access controls coordinator map different LUN values to the same logical unit.

In both cases, the access controls coordinator shall perform the following actions as part of its handling of the enrollment service action:

- a) disregard that portion of the ACL data for the AccessID which creates the conflict (that is, the TransportID LUN Map entry takes precedence);
- b) record the event in the access controls log as described in 4.10.

Furthermore, when such an event occurs, the sense data returned to the enrolling initiator indicates that a conflict arose (see 6.1.3) and that recovery actions were taken.

4.3 Establishment of Access Controls and other tasks

The time at which access controls are established or revoked with respect to other tasks being managed by the device server is vendor specific. Successful completion of an access control command (MANAGE ACL or DISABLE ACCESS CONTROLS service actions) indicates that a new access control state is established. Changes in the access control state may cause a change in the LUN Map for a specific initiator. Such changes shall not apply to any tasks queued before completion of the access control command; these commands shall be handled by the task manager of the logical unit to which they were addressed according to the LUN Map in place at the time the tasks were queued. The new LUN Map shall apply to all tasks received by the device server after successful completion of the access control command by the access controls coordinator. The execution of any access control command shall be performed as a single indivisible event.

Multiple access control commands (both ACCESS CONTROL IN and ACCESS CONTROL OUT) may be queued at the same time. The order of execution of such commands is defined by the tagged queuing restrictions, if any, but each is executed as a single indivisible command without any interleaving of actions that may be required by other access control commands.

4.3.1 Existing reservations and LUN Map changes

If a logical unit is reserved by one initiator and that logical unit is added to another initiator's LUN Map by any access control command, there shall be no changes in the reservation state of that logical unit.

If a logical unit is reserved by an initiator and that logical unit is removed from that initiator's LUN Map by any access control command or other event, there shall be no changes in the reservation. Existing mechanisms in the RESERVE/RELEASE and Persistent Reservations allow for other initiators with access to that logical unit to clear the reservation.

4.4 Identifying initiators

Access rights are granted or revoked on the basis of either a TransportID (as defined in the relevant protocol or interconnect standard) or an AccessID. An AccessID is enrolled with the access controls coordinator by an ACCESS ID ENROLL service action.

Access to logical units granted on the basis of a TransportID (and the related portion of the LUN Map) shall not be affected by events in the service delivery subsystem which might change non-persistent address identifiers for the initiator.

NOTE: The requirement here is similar to that in the following requirement from FCP-2, rev 02, 5.3): “the relationship between address identifier of the initiator and a persistent reservation for a logical unit can be adjusted as defined in SPC-2 during those reconfiguration events that may change the S_ID of the initiator”. In other words, if the non-persistent service delivery subsystem address of an initiator changes because of events in the subsystem, the target is required to maintain the LUN Map and access rights of that initiator as determined by TransportID identifiers of that initiator.

AUTHOR’S NOTE: *The above note is probably more for reviewers in this context but perhaps the sentiment of the note should be added to FCP-2 explicitly or at least to the addendum in this document.*

4.4.1 Initiator enrollment states

Initiators may enroll an AccessID with an access controls coordinator in order to gain access to logical units accessible via such an identifier. There are three states that an initiator can be in with respect to such an enrollment: not-enrolled, enrolled, de-enrolled. Each of these states and the mechanisms that cause transitions between these states are detailed in the following three clauses.

4.4.1.1 Not-enrolled state

This is the default state for an initiator. An initiator stays in this state until it successfully completes the ACCESS CONTROL OUT command with ACCESS ID ENROLL service action. See 4.4.1.2.

An initiator in the enrolled or de-enrolled state can transition to the not-enrolled state as follows:

- a) by successful completion of the ACCESS CONTROL OUT command with CANCEL ENROLLMENT service action;
- b) as a consequence of a certain change in the LUN Map effected by successful completion of an ACCESS CONTROL OUT command with MANAGE ACL service action from any initiator.

NOTE: this requirement provides only a simple interlock to assist an initiator in detecting a change in its LUN Map which might be caused by events or actions not taken by that initiator. The use of the ACCESS CONTROL OUT with MANAGE ACL service action by the managing application client should be coordinated with the affected initiators to ensure proper data integrity. Such coordination is beyond the scope of this standard.

When in the not-enrolled state, the LUN Map for an initiator shall only contain LUN values which reference logical units accessible to that initiator via a TransportID or via proxy tokens.

4.4.1.2 Enrolled state

The initiator enters the enrolled state from either the not-enrolled or de-enrolled state by successful completion of the ACCESS CONTROL OUT command with ACCESS ID ENROLL service action. This service action is successful only under the following conditions:

- a) the initiator was in the not-enrolled state and the AccessID in the parameter data of the service action matches entries in the ACL data (so that this AccessID has rights to one or more logical units); in this case, the LUN Map is modified according to the rules of 4.2 for the logical units accessible via the enrolled AccessID;
- b) the initiator was in the enrolled or de-enrolled state and the AccessID in the parameter data matches that of the current enrolled AccessID for that initiator; in this case, no changes to the LUN

Map are effected, however commands to the affected logical units are handled according to the rules of 4.9.

The AccessID enrollment of an initiator (in either the enrolled or not-enrolled state) may be kept in non-volatile memory in an implementation dependent manner subject to the rules in 4.7.

Transitions out of the enrolled state are described in the subclauses for the not-enrolled and de-enrolled states.

NOTE: This standard does not preclude implicit enrollments through mechanisms in the service delivery subsystem.

An initiator in the not-enrolled state may have entries in its LUN Map based on proxy tokens (that is, created by ASSIGN PROXY LUN service action) which would be affected by an enrollment. In this case, the LUN Map entries for the proxy tokens are implicitly released (as if the initiator sent the RELEASE PROXY LUN service action) and the LUN Map is then modified according to the rules of 4.2.

4.4.1.3 De-enrolled state

An initiator shall enter the de-enrolled state only from the enrolled state, and as a consequence of the following:

- a) any event in the service delivery subsystem which causes the access controls coordinator to question whether the AccessID of an initiator in the enrolled state has changed (e.g., a PRLO or LOGO in FCP);
- b) successful completion of an ACCESS CONTROLS OUT command (from any initiator) with MANAGE ACL service action and FLUSH bit set to one;
- c) optionally after a target reset, as described in 4.7.

While in the de-enrolled state, the LUN Map for the initiator does not change; that is, the AccessID portion of the LUN Map is as if the initiator were in the enrolled state. However, commands to the affected logical units are handled according to the rules of 4.9.

4.4.2 Identifier Type and Initiator Identifier

Initiators are identified in parameter data with an IDENTIFIER TYPE code and INITIATOR IDENTIFIER field as defined in Table 1.

TABLE 1. IDENTIFIER TYPE and INITIATOR IDENTIFIER values.

| Code | Description | Length |
|---------|-----------------|--------|
| 00h | AccessID | 24 |
| 01h | TransportID | 24 |
| 02h-7Fh | Reserved | n/a |
| 80h-FFh | Vendor-specific | VS |

Use of the TransportID is protocol and interconnect-specific. Each SCSI protocol standard shall specify the description of the TransportID structure but shall fix the length of the identifier field at 24 bytes.

Additionally, there is provision for vendor-specific initiator identification types.

The format of the AccessID data structure is described in Table 2. There are sixteen (16) bytes of significant data in this structure.

TABLE 2. AccessID data structure

| Byte | Bit | | | | | | | |
|------|----------|---|---|---|---|---|---|-----|
| | 7 | 6 | 5 | 4 | 3 | 2 | 1 | 0 |
| 0 | MSB | | | | | | | |
| 15 | ACCESSID | | | | | | | LSB |
| 16 | RESERVED | | | | | | | |
| 23 | | | | | | | | |

4.5 Granting and revoking access rights

The MANGE ACL service action of the ACCESS CONTROL OUT command is used to grant or revoke access to one or more logical units to an initiator based on the AccessID identifier or TransportID identifier. This same service action can selectively or universally revoke all proxy rights.

An initiators can gain access to a logical unit also via proxies. See 4.5.1.

An initiator's access right to a logical unit is the logical 'or' of all rights granted under both MANAGE ACL for any identifier which corresponds to that initiator and under proxy. For example, an initiator may have rights granted under MANAGE ACL action under both its enrolled AccessID and TransportID. Similarly, it may have multiple proxy rights granted under proxy tokens. Revocation of that initiator's access rights occurs only when all such access rights have been revoked; this means removal of all entries in the LUN Map for that initiator which referenced the logical unit.

When an initiator's access rights to a logical unit are changed (granted or revoked), the rules of 4.3 shall apply with respect to all commands from that initiator.

4.5.1 Proxy tokens and proxy access

An initiator with access to a logical unit on the basis of either a TransportID or AccessID may allow a third party temporary access to the same logical unit via the proxy mechanism.

The initiator requests from the access controls coordinator a Proxy Token for a specific logical unit via the ACCESS CONTROL IN command with REQUEST PROXY TOKEN service action. The access controls coordinator generates this Proxy Token in an implementation specific manner; it is recommended that all active Proxy Tokens created by the access controls coordinator be unique.

The initiator can then forward the Proxy Token to a third party (e.g., in a target descriptor in the parameter data of the EXTENDED COPY command; see Appendix D.2).

The third party uses the Proxy Token to request an entry be created in its LUN Map for the referenced logical unit via the ACCESS CONTROLS OUT command with ASSIGN PROXY LUN service action.

As long as the Proxy Token is valid and no power-cycles or target resets have occurred, this entry in the third party's LUN Map is valid.

A Proxy Token shall be invalidated under the following events:

- a) an initiator with access to the logical unit revokes the Proxy Token by the ACCESS CONTROL OUT command with the REVOKE PROXY TOKEN service action or with the REVOKE ALL PROXY TOKENS service action;

- b) an application client issues the ACCESS CONTROL OUT command with MANAGE ACL service action and appropriate Revoke Proxy Token or Revoke All Proxy Tokens parameter pages.

A proxy LUN value for the third party (entry in the LUN Map based on a Proxy Token) shall be valid unless one of the following occurs:

- a) the third party releases the LUN value with the ACCESS CONTROL OUT command and RELEASE PROXY LUN service action;
- b) the Proxy Token is invalidated, as above;
- c) an event in the service delivery subsystem causes the access controls coordinator to question whether the third party initiator that created the LUN value has changed (and may no longer be in possession of the Proxy Token).

In the latter two cases, the third party can reissue the ASSIGN PROXY LUN in an attempt to re-establish its proxy rights. In case (b), the access controls coordinator shall fail the request.

4.6 Override of Management Identifier Key

The Management Identifier Key is, under normal conditions, managed (initialized and changed) by the ACCESS CONTROLS OUT command with MANAGE ACL service action. However, conditions may arise when this key needs to be replaced and the current key is not available to the application client. In this case, the ACCESS CONTROLS OUT command with OVERRIDE MGMT ID KEY service action is specified (see 6.1.5). This service action is intended only for failure scenarios; the MANAGE ACL service action should be used in normal conditions. To facilitate protection of the key under normal conditions, the access controls coordinator shall support the following.

The access controls coordinator shall maintain a 16 bit non-negative integer-valued timer, called the Override Lockout Timer. This timer, if non-zero, shall decrement approximately once per second. When this timer is non-zero, an OVERRIDE MGMT ID KEY service action shall fail with CHECK CONDITION status and sense data indicating that the timer has not expired. If this counter is zero, then the OVERRIDE MGMT ID KEY shall succeed. Both of these events are logged according to the specifications of 4.10.

To manage the state of the timer, including its initial restart value and to restart it, the ACCESS CONTROL IN command with MANAGE OVERRIDE LOCKOUT TIMER service action is provided (see 5.1.5). This service action has two functions, depending on whether the Management Identifier Key is supplied in the CDB or not.

- a) If the Management Identifier Key is not supplied in the CDB, then the access controls coordinator shall restart the Override Lockout Timer, that is, reset it to its current initial value.
- b) If a Management Identifier Key is supplied in the CDB but it is incorrect, the access controls coordinator shall restart the Override Lockout Timer.
- c) If the Management Identifier Key is supplied in the CDB and is correct, then the access controls coordinator shall do the following:
 - 1. report the prior initial value and the current value of the timer;
 - 2. reset the Initial Override Lockout Timer according to data in the CDB;
 - 3. restart the timer to the new initial value.

This model has the following features:

- a) an application client can easily maintain a positive value for the Override Lockout Timer, since any initiator can force a restart (no Management Identifier Key is required);
- b) the managing application client (the one which manages the Management Identifier Key) can establish the policy for protecting the key from inadvertent override in a manner consistent with deployment policies;

- c) by reporting the prior initial and current value, the managing application client can approximately measure the real-time accuracy of the timer used by the access controls coordinator;
- d) by logging all override events, the managing client application may be able to ascertain if an inadvertent override was attempted or occurred and which initiator was involved.

Note that a value of zero for the Initial Override Timer effectively disables the timer and allows for the OVERRIDE MGMT KEY service action to succeed at any time.

4.7 Preserving access control information (power-cycles and target resets)

The access controls coordinator is required to maintain in non-volatile form the entire access controls data as described in 4.1 with the exception of the Default LUNs Generation. This includes the access controls log (see 4.10).

If the device's non-volatile memory is not ready (to read the access controls data), the device server shall return on all addressed logical units a CHECK CONDITION status, a sense key of NOT READY and additional sense data as defined in the TEST UNIT READY command (see SPC-2, rev 14, 7.27) for all commands except INQUIRY.

Additionally, all Proxy Tokens associated with logical units shall be preserved through a power-cycle or target reset. However, any LUN Map entries created by a REQUEST PROXY LUN from an initiator shall not be preserved.

It is implementation specific what effects either a power cycle or target reset may have on the AccessID enrollment and enrolled state of initiators. An access controls coordinator may preserve the enrollment; if it does, the following holds after the reset is complete:

- a) all initiators formerly in the enrolled or de-enrolled state enter the de-enrolled state until changed by an initiator ACCESS ID ENROLL service action;
- b) all entries in an initiator's LUN Map corresponding to an enrolled AccessID are restored.

If the access controls coordinator does not preserve enrollment across a power cycle or target reset, the following holds after the reset is complete:

- a) all initiators enter the not-enrolled state until changed by an initiator ACCESS ID ENROLL service action;
- b) all entries in an initiator's LUN Map shall correspond only to access rights granted under a TransportID.

4.8 Reporting access control information

There are two ways to request a report from the access controls coordinator about its access controls data and state.

A service action (REPORT ACL) shall report all ACL data for the access controls coordinator independent of the requesting initiator.

In this case, the information includes the following:

- a) the list of initiator identifiers and their access rights currently in effect;
- b) the list of proxies currently in effect.

The REPORT ACCESS CONTROLS LOG service action may be used by an application client to read the access controls log.

4.9 Verifying access rights for initiators

When the access controls coordinator has access controls enabled, access rights from a given initiator are validated in the following manner.

If the initiator has access to a logical unit by virtue of a TransportID or a valid proxy token, then all commands are handled in the normal fashion.

If the initiator has access to a logical unit by virtue of an AccessID enrolled by that initiator and the initiator is in the enrolled state, then all commands are handled in the normal fashion.

If the initiator has access to a logical unit by virtue of an AccessID enrolled by that initiator and the initiator is in the de-enrolled state, then commands are handled according to the following:

- a) INQUIRY, ACCESS CONTROL OUT and ACCESS CONTROL IN are handled in the normal fashion;
- b) all other commands receive a CHECK CONDITION status with sense key ILLEGAL REQUEST and ASC/ASCQ set to ACCESS DENIED - INITIATOR DE-ENROLLED and no data is transferred.

This last case may cause the initiator to issue the ACCESS ID ENROLL service action and then retry the failed command.

In all other cases, the commands are rejected with CHECK CONDITION status, ILLEGAL REQUEST and ASC/ASCQ set to LOGICAL UNIT NOT SUPPORTED.

4.10 Access Controls Log

The access controls log is a record of events related to the access controls state and its history.

The log has three portions recording different classes of events. These are:

- a) key override events (when an attempt is made to override the Management Identifier Key, whether this attempt fails or succeeds);
- b) invalid key events (when the Management Identifier Key in a CDB or parameter data does not match the current value maintained by the access controls coordinator);
- c) LUN Mapping conflict events (when the access controls coordinator detects at an initiator's enrollment that the LUN Map for that initiator's TransportID and AccessID cannot be merged without a recovery action).

Each portion of the log minimally contains a counter of the events. The counters initialize to zero and are incremented whenever the appropriate event occurs. Additionally, each portion may contain additional records with more specific information about each event.

The override key events occur when an initiator sends the ACCESS CONTROLS IN command with OVERRIDE MGMT KEY service action. When such an event occurs, the access controls coordinator shall increment the Key Overrides Counter. Optionally, if the log has sufficient resources, the access controls coordinator shall prepend to this portion of the log a record which includes the TransportID of the initiator which sent the command, a flag which indicates if the override was successful, the current value and initial setting of the Override Lockout Timer, and a 32 bit integer time-stamp.

The invalid key events occur whenever an access controls command requires checking a field either in the CDB or in the parameter data against the current Management Identifier Key and this check fails, that is, the value in the field does not equal the current value maintained by the access controls coordinator. When such an event occurs, the access controls coordinator shall increment the Invalid Keys Counter. Optionally, if the log has sufficient resources, the access controls coordinator shall prepend to this portion of the log a

record which includes the TransportID of the initiator which sent the command, the operation code of the command and its service action, the invalid key and a 32 bit integer time-stamp.

The LUN Mapping conflict events occur as specified in 4.2.1. When such an event occurs, the access controls coordinator shall record the event in the LUN Mapping conflicts portion of the access controls log. Optionally, if the log has sufficient resources, the access controls coordinator shall prepend to this portion of the log a record which includes the Default LUNs Generation, the TransportID and its associated LUN/default LUN map entry and the AccessID and its associated LUN/default LUN map entry, and a 32 bit integer time-stamp.

The time-stamp or time-stamps used in each event record is or are implementation dependent and may be always zero if the device has no such resources.

Selected portions of the log may be reported to an application client by the ACCESS CONTROLS IN command with REPORT ACCESS CONTROLS LOG service action (see 5.1.3). With the exception of the key overrides portion, selected portions of the log can be cleared and the counters reset to zero by an application client with the ACCESS CONTROLS IN command with CLEAR ACCESS CONTROLS LOG service action (see 5.1.4).

4.11 Access Control Service Actions

Table 3 gives a summary list of the access control service actions.

TABLE 3. Access Control Commands and Service Actions

| Code | Name | Type | Section |
|---------------------------------|-------------------------------|------|---------|
| ACCESS CONTROL IN (OPCODE 86h) | | | |
| 00h | REPORT ACL | M | 5.1.1 |
| 01h | REPORT LU DESCRIPTORS | M | 5.1.2 |
| 02h | REPORT ACCESS CONTROLS LOG | M | 5.1.3 |
| 03h | CLEAR ACCESS CONTROLS LOG | M | 5.1.4 |
| 04h | MANAGE OVERRIDE LOCKOUT TIMER | M | 5.1.5 |
| 05h | REQUEST PROXY TOKEN | O | 5.1.6 |
| 06h-0Fh | Reserved | | |
| 10h-1Fh | Vendor-specific | V | |
| ACCESS CONTROL OUT (OPCODE 87h) | | | |
| 00h | MANAGE ACL | M | 6.1.1 |
| 01h | DISABLE ACCESS CONTROLS | M | 6.1.2 |
| 02h | ACCESS ID ENROLL | M | 6.1.3 |
| 03h | CANCEL ENROLLMENT | M | 6.1.4 |
| 04h | OVERRIDE MGMT ID KEY | M | 6.1.5 |
| 05h | REVOKE PROXY TOKEN | O | 6.1.6 |
| 06h | REVOKE ALL PROXY TOKENS | O | 6.1.7 |
| 07h | ASSIGN PROXY LUN | O | 6.1.8 |
| 08h | RELEASE PROXY LUN | O | 6.1.9 |
| 09h-0Fh | Reserved | | |
| 10h-1Fh | Vendor-specific | V | |

4.12 Access Control Additional Sense Codes

Table 4 contains a list of the Additional Sense Code and Additional Sense Code Qualifiers relevant to access controls.

TABLE 4. Access Control Additional Sense Codes and Qualifiers

| ASC | ASCQ | Name | Function |
|-----|------|---------------------------------------|--|
| 20h | 01h | ACCESS DENIED - INITIATOR DE-ENROLLED | An initiator in the de-enrolled state sends a restricted command to a logical unit accessible under the enrolled AccessID. |
| 20h | 02h | ACCESS DENIED - NO ACCESS RIGHTS | An initiator in the not-enrolled state sends an ACCESS ID ENROLL service action and the given AccessID has no access rights in the ACL data. |
| 20h | 03h | ACCESS DENIED - INVALID MGMT ID KEY | The Management Identifier Key value is does not match the value maintained by the access controls coordinator. |
| 20h | 04h | ACCESS DENIED - ENROLLMENT CONFLICT | An initiator in the enrolled or de-enrolled state issues an ACCESS ID ENROLL service action under a different AccessID. |
| 20h | 05h | ACCESS DENIED - INVALID LU IDENTIFIER | A LUN or default LUN value in a CDB field or parameter data is not valid. |
| 20h | 06h | ACCESS DENIED - INVALID PROXY TOKEN | The Proxy Token is not valid; it does not correspond to a logical unit. |
| 20h | 07h | ACCESS DENIED - LUN MAPPING CONFLICT | The enrollment was successful but a LUN Mapping conflict occurred. |
| 20h | 08h | ACCESS DENIED - OVERRIDE LOCKOUT | The Override Lockout Timer has not expired. |
| 55h | 05h | INSUFFICIENT ACCESS CONTROL RESOURCES | The access controls coordinator has exhausted its resources for the requested access controls action. |

5.0 ACCESS CONTROL IN command

The ACCESS CONTROL IN command (see Table 5) is used to obtain information about the access controls that are active within the access controls coordinator and to facilitate other functions. The command shall be used in conjunction with the ACCESS CONTROL OUT command. It shall not be affected by reservations, persistent reservations or access controls.

This command should only be sent to LUN0 and processed by the access controls coordinator. It should be rejected by the device server if addressed to any other LUN with CHECK CONDITION status, sense key of ILLEGAL REQUEST and additional sense code of INVALID OPCODE.

TABLE 5. ACCESS CONTROL IN command

| Byte | Bit | | | | | | | |
|------|--------------------------------------|---|---|----------------|---|---|---|-----|
| | 7 | 6 | 5 | 4 | 3 | 2 | 1 | 0 |
| 0 | OPERATION CODE (86h) | | | | | | | |
| 1 | RESERVED | | | SERVICE ACTION | | | | |
| 2 | MSB | | | | | | | |
| 9 | SERVICE ACTION-SPECIFIC DATA | | | | | | | LSB |
| 10 | MSB SERVICE ACTION-SPECIFIC DATA2 or | | | | | | | |
| 13 | ALLOCATION LENGTH | | | | | | | LSB |
| 14 | RESERVED | | | | | | | |
| 15 | CONTROL | | | | | | | |

The SERVICE ACTION-SPECIFIC DATA is described in the appropriate subclause for each service action.

The SERVICE ACTION-SPECIFIED DATA2 field or the ALLOCATION LENGTH field are distinguished in the appropriate subclause for each service action. When the field is interpreted as an Allocation Length, the ALLOCATION LENGTH shall conform to the requirements of clause 4.2.5 (of SPC-2 revision 15) unless otherwise specified in the clause for a specific service action.

The actual length of the ACCESS CONTROL IN parameter list is, in most cases, available in a parameter list field. The ALLOCATION LENGTH field in the CDB indicates how much space has been reserved for the returned parameter list.

5.1 ACCESS CONTROL IN Service Actions

5.1.1 REPORT ACL service action (Mandatory)

The REPORT ACL service action of the ACCESS CONTROL IN command is used by an application client to query the complete ACL data currently maintained by the access controls coordinator.

If the access controls coordinator is in the default state where there is no ACL data, and the Management Identifier Key is zero, the device server shall respond with GOOD status and return no data, regardless of the value of any other field in the CDB.

If the access controls coordinator has a non-empty ACL data (including an established Management Identifier Key), the SERVICE ACTION-SPECIFIC DATA field in the CDB shall contain the current Management Identifier Key maintained by the access controls coordinator. If this is not the case, the device server shall return no data and respond with CHECK CONDITION, sense key ILLEGAL REQUEST, additional sense data set to ACCESS DENIED - INVALID MGMT ID KEY and the access controls coordinator shall record the event in the invalid keys portion of the access controls log.

The ALLOCATION LENGTH shall be at least eight (8), sufficient for the header information. If the Allocation Length is less than eight (8), then the device server shall return CHECK CONDITION with sense key ILLEGAL REQUEST and additional sense code of INVALID FIELD IN CDB.

The format of the returned data shall conform to the specification in 5.1.1.1.

5.1.1.1 REPORT ACL parameter data format

The format of the parameter data provided in response to an ACCESS CONTROL IN command with REPORT ACL service actions is shown in Table 6. The ACL ENTRY PAGE(S) are described in 5.1.1.1.1 and 5.1.1.1.2.

TABLE 6. REPORT ACL parameter data format

| Byte | Bit | | | | | | | |
|------|-----------------------------|---|---|---|---|---|---|-----|
| | 7 | 6 | 5 | 4 | 3 | 2 | 1 | 0 |
| 0 | MSB | | | | | | | |
| 3 | ADDITIONAL LENGTH ($n-3$) | | | | | | | LSB |
| 4 | MSB | | | | | | | |
| 7 | DEFAULT LUNS GENERATION | | | | | | | LSB |
| 8 | | | | | | | | |
| n | ACL ENTRY PAGE(S) | | | | | | | |

The ADDITIONAL LENGTH field shall contain a count of the number of bytes in the remaining parameter data. The value in this field shall contain the actual number of bytes available without consideration for insufficient ALLOCATION LENGTH in the requesting CDB.

The DEFAULT LUNS GENERATION shall be set to the current value of the Default LUNS Generation integer maintained by the access controls coordinator according to the rules in 4.0.

The ACL ENTRY PAGE(S) shall contain a description of the ACL maintained by the access controls coordinator. Each ACL Entry Page is identified by a Page Code. The list of Page Codes and their definitions is given in Table 7 and the detailed description of the pages are in subsequent subclauses.

TABLE 7. ACL Entry PAGE CODE definitions for REPORT ACL service action

| Page Code | Description | Clause |
|-----------|-------------|-----------|
| 00h | Granted | 5.1.1.1.1 |
| 01h | Granted All | 5.1.1.1.1 |
| 02h | Proxy Token | 5.1.1.1.2 |
| 03b-FFh | Reserved | |

5.1.1.1.1 REPORT ACL parameter data Granted and Granted All page formats

The Granted and Granted All page formats for the REPORT ACL service action is specified in Table 8.

TABLE 8. Granted and Granted All page formats

| Byte | Bit | | | | | | | |
|-------|-----------------------------|---|---|---|---|---|-----|---|
| | 7 | 6 | 5 | 4 | 3 | 2 | 1 | 0 |
| 0 | PAGE CODE (00h-01h) | | | | | | | |
| 1 | RESERVED | | | | | | | |
| 2 | PAGE LENGTH ($n-3$) | | | | | | | |
| 3 | | | | | | | | |
| 4 | RESERVED | | | | | | | |
| 5 | IDENTIFIER TYPE | | | | | | | |
| 6 | IDENTIFIER LENGTH ($n-7$) | | | | | | | |
| 7 | | | | | | | | |
| 8 | MSB | | | | | | | |
| n | INITIATOR IDENTIFIER | | | | | | LSB | |
| $n+1$ | LUN/DEFAULT LUN LIST | | | | | | | |
| m | | | | | | | | |

The PAGE LENGTH field shall indicate the number of additional bytes required for this page.

The IDENTIFIER TYPE and INITIATOR IDENTIFIER fields are specified in 4.4.2. The IDENTIFIER LENGTH field indicates the number of bytes following taken up by the INITIATOR IDENTIFIER.

NOTE: All currently defined Identifier Types require the Identifier Length be set to 24 (see Table 1).

The LUN/DEFAULTLUN LIST shall contain a list of LUN/default LUN pairs (eight bytes for each component of the pair) which define the LUN Map entries for the specific initiator identifier. The default LUN values in these pairs shall be consistent with the Default LUNs Generation value in the header of the parameter data.

For the Granted All page, the LUN/DEFAULTLUN LIST is empty.

If the INITIATOR IDENTIFIER does not have access to all logical units at the device, then the access controls coordinator shall include one Granted page for that identifier and shall include in this page the complete list of LUN/default LUN pairs assigned to the LUN Map for that initiator or those initiators.

If the INITIATOR IDENTIFIER has access to all logical units at the device and has the default LUN Map, the access controls coordinator may include one Granted page for that identifier and shall include in this page the complete list of LUN/default LUN pairs (the default mapping) for the device. Alternatively, the access controls coordinator may include one Granted All page for that identifier.

One and only one Granted or Granted All page shall be returned for a given INITIATOR IDENTIFIER.

5.1.1.1.2 REPORT ACL parameter data Proxy Tokens page format

The Proxy Tokens page format for the REPORT ACL service action is specified in Table 9.

TABLE 9. Proxy Tokens page format

| Byte | Bit | | | | | | | |
|------|-----------------------------|---|---|---|---|---|---|---|
| | 7 | 6 | 5 | 4 | 3 | 2 | 1 | 0 |
| 0 | PAGE CODE (02h) | | | | | | | |
| 1 | RESERVED | | | | | | | |
| 2 | PAGE LENGTH ($n-3$) | | | | | | | |
| 3 | | | | | | | | |
| 4 | PROXY TOKEN/DEFAULTLUN LIST | | | | | | | |
| m | | | | | | | | |

The PAGE LENGTH field shall indicate the number of additional bytes required for this page.

If there are no active Proxy Tokens at the access controls coordinator, the access controls coordinator may either not include the Proxy Tokens page in the parameter data or may include one such page with an empty PROXY TOKEN/DEFAULTLUN LIST.

At most one Proxy Token page shall be included in the parameter data.

The PROXY TOKEN/DEFAULTLUN LIST shall contain a list of Proxy Token/default LUN pairs (eight bytes for each component of the pair) indicating the association of Proxy Token to logical unit. The default LUN values in these pairs shall be consistent with the Default LUNs Generation value in the header of the parameter data.

5.1.2 REPORT LU DESCRIPTORS service action (Mandatory)

The REPORT LU DESCRIPTORS service action of the ACCESS CONTROL IN command is used by an application client to obtain from the access controls coordinator inventory information about the logical units for which access controls can be handled and other properties of the access controls coordinator.

If the access controls coordinator is in the default state where there is no ACL data, and the Management Identifier Key is zero, the device server shall respond with GOOD status and return no data, regardless of the value of any other field in the CDB.

NOTE: In this case, all logical units are accessible; existing commands such as INQUIRY, REPORT LUNS, READ CAPACITY, etc., can be used to collect this information if needed.

If the access controls coordinator has a non-empty ACL data (including an established Management Identifier Key), the SERVICE ACTION-SPECIFIC DATA field in the CDB shall contain the current Management Identifier Key maintained by the access controls coordinator. If this is not the case, the device server shall return no data and respond with CHECK CONDITION, sense key ILLEGAL REQUEST, additional sense data set to ACCESS DENIED - INVALID MGMT ID KEY and the access controls coordinator shall record the event in the invalid keys portion of the access controls log.

The ALLOCATION LENGTH shall be at least twenty (20), sufficient for the header information. If the Allocation Length is less than twenty (20), then the device server shall return CHECK CONDITION with sense key ILLEGAL REQUEST and additional sense code of INVALID FIELD IN CDB.

The format of the returned data shall conform to the specification in 5.1.2.1.

5.1.2.1 REPORT LU DESCRIPTORS parameter data format

The format for the parameter data provided in response to an ACCESS CONTROL IN command with REPORT LU DESCRIPTORS service action is shown in Table 10.

TABLE 10. REPORT LU DESCRIPTORS parameter data format

| Byte | Bit | | | | | | | |
|------|-----------------------------|---|---|---|---|---|---|-----|
| | 7 | 6 | 5 | 4 | 3 | 2 | 1 | 0 |
| 0 | MSB | | | | | | | |
| 3 | ADDITIONAL LENGTH ($n-3$) | | | | | | | LSB |
| 4 | MSB | | | | | | | |
| 7 | NUMBER OF LOGICAL UNITS | | | | | | | LSB |
| 8 | SUPPORTED LUN-MASK FORMAT | | | | | | | |
| 16 | MSB | | | | | | | |
| 19 | DEFAULT LUNs GENERATION | | | | | | | LSB |
| 20 | LOGICAL UNIT DESCRIPTORS | | | | | | | |
| n | | | | | | | | |

The ADDITIONAL LENGTH field shall contain a count of the number of bytes in the remaining parameter data. The value in this field shall contain the actual number of bytes available without consideration for insufficient ALLOCATION LENGTH in the requesting CDB.

The NUMBER OF LOGICAL UNITS is a count of the number of logical units managed by the access controls coordinator (this shall be the same as the number of LOGICAL UNIT DESCRIPTORS which follow in the remaining parameter data).

The SUPPORTED LUN-MASK FORMAT contains a summary the LUN values which the access controls coordinator can support in a LUN Map for an arbitrary initiator. The format is specified in Table 11.

TABLE 11. SUPPORTED MAX-LUN FORMAT data format

| Byte | Bit | | | | | | | |
|------|---------------------|---|---|---|---|---|---|-----|
| | 7 | 6 | 5 | 4 | 3 | 2 | 1 | 0 |
| 0 | MSB | | | | | | | |
| 1 | LUN-MASK PART ONE | | | | | | | LSB |
| 2 | MSB | | | | | | | |
| 3 | LUN-MASK PART TWO | | | | | | | LSB |
| 4 | MSB | | | | | | | |
| 5 | LUN-MASK PART THREE | | | | | | | LSB |
| 6 | MSB | | | | | | | |
| 7 | LUN-MASK PART FOUR | | | | | | | LSB |

Each of the four 2-byte fields specifies a mask of which bits may be set within each field that the access controls coordinator can support for that portion of a LUN.

For example, if the access controls coordinator uses a flat addressing model and can only support LUN values at the top level and up to 256 LUNs, then the LUN-MASK PART ONE field should be set to 255 (00FFh) and the LUN-MASK PART TWO, THREE and FOUR shall be set to zero.

The use of the mask format allows the access controls coordinator to suggest that it can support or simulate the hierarchical addressing model.

NOTE: this is intended only as a summary of the supported LUN values and not a complete description. It is possible that some bit combinations valid with respect to the Supported LUN-Mask Format are not valid in practice. However, any bit combination not valid with respect to the Supported LUN-Mask Format shall not be valid.

The DEFAULT LUNS GENERATION shall be set to the current value of the Default LUNs Generation integer maintained by the access controls coordinator according to the rules in 4.0.

The LOGICAL UNIT DESCRIPTORS shall contain a description of the logical units managed by the access controls coordinator. Each descriptor is device-type specific but has the general format specified in Table 12.

TABLE 12. LOGICAL UNIT DESCRIPTOR data format

| Byte | Bit | | | | | | | |
|------|--|---|---|------------------------|---|---|---|-----|
| | 7 | 6 | 5 | 4 | 3 | 2 | 1 | 0 |
| 0 | RESERVED | | | PERIPHERAL DEVICE-TYPE | | | | |
| 1 | RESERVED | | | | | | | |
| 2 | MSB | | | | | | | |
| 3 | ADDITIONAL LENGTH ($n-3$) | | | | | | | LSB |
| 4 | MSB | | | | | | | |
| 11 | DEFAULT LUN | | | | | | | LSB |
| 12 | RESERVED | | | | | | | |
| 13 | INQUIRY IDENTIFICATION DESCRIPTOR LENGTH (m) | | | | | | | |
| 14 | RESERVED | | | | | | | |
| 15 | DEVICE IDENTIFIER LENGTH (k) | | | | | | | |
| 16 | MSB | | | | | | | |
| 47 | INQUIRY IDENTIFICATION DESCRIPTOR | | | | | | | LSB |
| 48 | MSB | | | | | | | |
| 79 | DEVICE IDENTIFIER | | | | | | | LSB |
| 80 | MSB | | | | | | | |
| n | DEVICE-TYPE SPECIFIC ADDITIONAL DATA | | | | | | | LSB |

The PERIPHERAL DEVICE-TYPE field shall be set according to the device type of the referenced logical unit as specified in Table 54 (of SPC-2, rev 15).

The ADDITIONAL LENGTH field indicates the total number of bytes remaining in the descriptor.

The DEFAULT LUN field indicates the default LUN value associated to the referenced logical unit, as would be used in other commands (e.g., ACCESS CONTROL OUT command with MANAGE ACL service action) to identify the logical unit. This value shall be consistent with the Default LUNs Generation value in the header of the parameter data.

The INQUIRY IDENTIFICATION DESCRIPTOR field shall be supported if the device supports the INQUIRY command with EVPD bit set to one and Page Code set to 83h (Device Identification Page) and at least one identification descriptor has Association value of 0h (as defined in SPC-2 rev 15 8.4.3). In this case, the INQUIRY IDENTIFICATION DESCRIPTOR field shall be derived from one of these identification descriptors as follows:

- a) if the identification descriptor has length less than or equal to thirty-two (32) bytes, then the INQUIRY IDENTIFICATION DESCRIPTOR field shall be set to the value of the descriptor in the most significant bytes of the field and the remainder of the field shall be padded with zero in the least significant bytes; additionally, the INQUIRY IDENTIFICATION DESCRIPTOR LENGTH field shall be set to the length of the descriptor;

- b) if the identification descriptor has length greater than thirty-two (32) bytes, then the INQUIRY IDENTIFICATION DESCRIPTOR field shall be set to the thirty-two (32) most significant bytes of the descriptor; additionally, the INQUIRY IDENTIFICATION DESCRIPTOR LENGTH field shall be set to 32;
- c) the same descriptor shall always be returned in this parameter data for the same logical unit; the choice of descriptor is implementation dependent.

If no such identification descriptor is available through INQUIRY, then the INQUIRY IDENTIFICATION DESCRIPTOR LENGTH shall be set to zero and the INQUIRY IDENTIFICATION DESCRIPTOR field shall have all bytes set to zero.

The DEVICE IDENTIFIER field shall be supported if a device identifier has been established by a SET DEVICE IDENTIFIER command. In this case, the DEVICE IDENTIFIER field shall be derived from this device identifier (what would be returned in response to a successful REPORT DEVICE IDENTIFIER command) as follows:

- a) if the device identifier has length less than or equal to thirty-two (32) bytes, then the DEVICE IDENTIFIER field shall be set to the value of the device identifier in the most significant bytes of the field and the remainder of the field shall be padded with zero in the least significant bytes; additionally, the DEVICE IDENTIFIER LENGTH field shall be set to the length of the device identifier;
- b) if the device identifier has length greater than thirty-two (32) bytes, then the DEVICE IDENTIFIER field shall be set to the thirty-two (32) most significant bytes of the descriptor; additionally, the DEVICE IDENTIFIER LENGTH field shall be set to 32.

If no such identifier has been established by a SET DEVICE IDENTIFIER command, then the DEVICE IDENTIFIER LENGTH shall be set to zero and the DEVICE IDENTIFIER field shall have all bytes set to zero.

AUTHOR'S NOTE: *the point of this truncation in both identifiers to 32 bytes is to reduce the amount of data that needs to be returned in this descriptor to manageable and consistent levels (we really don't want these logical unit descriptors to be arbitrarily large (device identifiers can be 2³² bytes long!)). PAM probably doesn't need the full device identifier, just enough to help her keep track of devices. However, if need for more bytes from either identifier is required, an additional service action could be defined to request the complete information on an individual logical unit basis.*

The DEVICE-TYPE SPECIFIC ADDITIONAL DATA field shall not be included unless otherwise specified in the device-type specific command set standard.

AUTHOR'S NOTE: *Appendix E defines the format for this field for device-types under SBC-x, RBC-x and MMC-x. All other device-types do not seem to require any additional data of this type (at least, that's the author's current point of view).*

5.1.3 REPORT ACCESS CONTROLS LOG (Mandatory)

The REPORT ACCESS CONTROLS LOG service action of the ACCESS CONTROL IN command is used by an application client to obtain from the access controls coordinator information from the access controls log.

The SERVICE ACTION-SPECIFIC DATA2 field in the CDB shall have the structure specified in Table 13.

TABLE 13. REPORT ACCESS CONTROLS LOG and CLEAR ACCESS CONTROLS LOG SERVICE ACTION-SPECIFIC DATA2 field

| Byte | Bit | | | | | | | |
|------|-------------------|---|---|---|---|---|-------------|---|
| | 7 | 6 | 5 | 4 | 3 | 2 | 1 | 0 |
| 0 | RESERVED | | | | | | | |
| 1 | RESERVED | | | | | | LOG PORTION | |
| 2 | MSB | | | | | | | |
| 3 | ALLOCATION LENGTH | | | | | | LSB | |

The LOG PORTION field indicates to which portion of the log this service action applies, as specified in Table 14.

TABLE 14. LOG PORTION field definitions for REPORT and CLEAR ACCESS CONTROLS LOG service actions

| LOG PORTION | Description | Clause |
|-------------|-----------------------|---------|
| 00b | key overrides | 5.1.3.1 |
| 01b | invalid keys | 5.1.3.2 |
| 10b | LUN Mapping conflicts | 5.1.3.3 |
| 11b | Reserved | |

If the access controls coordinator is in the default state where there is no ACL data and no Management Identifier Key, then the SERVICE ACTION-SPECIFIC DATA field shall be ignored. If the LOG PORTION field is set to any value except 00b (key overrides) then the device server shall return status GOOD and return no data. If the LOG PORTION field is set to 00b (key overrides), then the device server shall return in parameter data the contents of the key overrides portion of the log, as specified in the following and as if the SERVICE ACTION-SPECIFIC DATA field met the criterion below.

The ALLOCATION LENGTH field in the SERVICE ACTION-SPECIFIC DATA2 field shall be at least eight (8). If the ALLOCATION LENGTH is less than eight (8), then device server shall return CHECK CONDITION with sense key ILLEGAL REQUEST and additional sense code of INVALID FIELD IN CDB.

If the ALLOCATION LENGTH field in the SERVICE ACTION-SPECIFIC DATA2 field is at least eight (8), and the access controls coordinator has a non-empty ACL data (including an established Management Identifier Key), the SERVICE ACTION-SPECIFIC DATA field in the CDB shall contain the current Management Identifier Key maintained by the access controls coordinator. If this is not the case (and the LOG PORTION field does not indicate key overrides), the device server shall return no data and respond with CHECK CONDITION, sense key ILLEGAL REQUEST, additional sense data set to ACCESS DENIED - INVALID MGMT ID KEY and the access controls coordinator shall record the event in the invalid keys portion of the access controls log.

If the ALLOCATION LENGTH field in the SERVICE ACTION-SPECIFIC DATA2 field is at least eight (8) and either the SERVICE ACTION-SPECIFIC DATA field matches the current Management Identifier Key or the LOG PORTION indicates key overrides, then the device server shall return in parameter data that portion of the log indicated in the LOG PORTION field, as specified in 5.1.3.1, 5.1.3.2, and 5.1.3.3.

For any value of the LOG PORTION field, if the access controls coordinator only supports the relevant event counter in the log and not the additional information, then the returned parameter data shall only contain the header information.

5.1.3.1 REPORT ACCESS CONTROLS LOG parameter data format for Key Overrides

The format of the parameter data returned in response to an ACCESS CONTROL IN command with REPORT ACCESS CONTROLS LOG service action and LOG PORTION field in the CDB indicating key overrides is shown in Table 15.

TABLE 15. REPORT ACCESS CONTROLS LOG parameter data format for key overrides

| Byte | Bit | | | | | | | |
|------|-----------------------------|---|---|---|---|---|-------------|-----|
| | 7 | 6 | 5 | 4 | 3 | 2 | 1 | 0 |
| 0 | MSB | | | | | | | |
| 3 | ADDITIONAL LENGTH ($n-7$) | | | | | | | LSB |
| 4 | RESERVED | | | | | | | |
| 5 | RESERVED | | | | | | LOG PORTION | |
| 6 | MSB | | | | | | | |
| 7 | KEY OVERRIDES COUNTER | | | | | | | LSB |
| 8 | | | | | | | | |
| n | KEY OVERRIDES LOG PAGE(S) | | | | | | | |

The ADDITIONAL LENGTH field shall contain a count of the number of bytes in the remaining parameter data. The value in this field shall contain the actual number of bytes available without consideration for insufficient ALLOCATION LENGTH in the requesting CDB.

The LOG PORTION field shall be set to 00b to indicate which portion of the access controls log is reflected in the rest of the parameter data.

The KEY OVERRIDES COUNTER shall contain the Key Overrides Counter maintained by the access controls coordinator.

The KEY OVERRIDES LOG PAGE(S) shall contain a description of the key overrides log entries as recorded by the access controls coordinator (see 4.2.1). The format for these pages is found in Table 16.

TABLE 16. KEY OVERRIDES LOG PAGE(S) data format

| Byte | Bit | | | | | | | |
|------|--------------------------------|---|---|---|---|---|---|---------|
| | 7 | 6 | 5 | 4 | 3 | 2 | 1 | 0 |
| 0 | | | | | | | | |
| 3 | RESERVED | | | | | | | SUCCESS |
| 4 | MSB | | | | | | | |
| 7 | TIME STAMP | | | | | | | LSB |
| 8 | MSB | | | | | | | |
| 31 | TRANSPORTID | | | | | | | LSB |
| 32 | MSB | | | | | | | |
| 33 | INITIAL OVERRIDE LOCKOUT TIMER | | | | | | | LSB |
| 34 | MSB | | | | | | | |
| 35 | OVERRIDE LOCKOUT TIMER | | | | | | | LSB |

The SUCCESS bit of one indicates that the specific ACCESS CONTROLS OUT command with OVERRIDE MGMT ID KEY service action event recorded in the log was successful. A value of zero indicates that the command did not succeed.

The TRANSPORTID field shall contain the TransportID of the initiator that issued the command.

The INITIAL OVERRIDE LOCKOUT TIMER field, the OVERRIDE LOCKOUT TIMER field and the TIME STAMP field shall be set to the values for the Initial Override Lockout Timer, Override Lockout Timer and (optional) time stamp, respectively, at the time the key override event was recorded. See 4.10.

5.1.3.2 REPORT ACCESS CONTROLS LOG parameter data format for Invalid Keys

The format of the parameter data returned in response to an ACCESS CONTROL IN command with REPORT ACCESS CONTROLS LOG service action and LOG PORTION field in the CDB indicating invalid key events is shown in Table 17.

TABLE 17. REPORT ACCESS CONTROLS LOG parameter data format for invalid keys

| Byte | Bit | | | | | | | |
|------|-----------------------------|---|---|---|---|---|-------------|-----|
| | 7 | 6 | 5 | 4 | 3 | 2 | 1 | 0 |
| 0 | MSB | | | | | | | |
| 3 | ADDITIONAL LENGTH ($n-7$) | | | | | | | LSB |
| 4 | RESERVED | | | | | | | |
| 5 | RESERVED | | | | | | LOG PORTION | |
| 6 | MSB | | | | | | | |
| 7 | INVALID KEYS COUNTER | | | | | | | LSB |
| 12 | | | | | | | | |
| n | INVALID KEYS LOG PAGE(S) | | | | | | | |

The ADDITIONAL LENGTH field shall contain a count of the number of bytes in the remaining parameter data. The value in this field shall contain the actual number of bytes available without consideration for insufficient ALLOCATION LENGTH in the requesting CDB.

The LOG PORTION field shall be set to 01b to indicate which portion of the access controls log is reflected in the rest of the parameter data.

The INVALID KEYS COUNTER shall contain the Invalid Keys Counter maintained by the access controls coordinator.

The INVALID KEYS LOG PAGE(S) shall contain a description of the invalid keys log entries as recorded by the access controls coordinator (see 4.2.1). The format for these entries is found in Table 18.

TABLE 18. INVALID KEYS LOG PAGE(S) data format

| Byte | Bit | | | | | | | |
|------|-------------|---|---|---|----------------|---|---|-----|
| | 7 | 6 | 5 | 4 | 3 | 2 | 1 | 0 |
| 0 | | | | | | | | |
| 1 | RESERVED | | | | | | | |
| 2 | OPCODE | | | | | | | |
| 3 | RESERVED | | | | SERVICE ACTION | | | |
| 4 | MSB | | | | | | | |
| 7 | TIME STAMP | | | | | | | LSB |
| 8 | MSB | | | | | | | |
| 31 | TRANSPORTID | | | | | | | LSB |
| 32 | MSB | | | | | | | |
| 39 | INVALID KEY | | | | | | | LSB |

The OPCODE and SERVICE ACTION fields shall be set to the respective values from the CDB of access controls command which contained the invalid key (in either the CDB or the associated parameter data).

The TIME STAMP field shall be set to the value of the (optional) time stamp at the time the invalid key event was recorded. See 4.10.

The TRANSPORTID field shall contain the TransportID of the initiator that issued the command.

The INVALID KEY field shall be set to the value of the invalid key detected by the access controls coordinator in the command or associated parameter data. (The key is typically in the CDB for ACCESS CONTROL IN commands and in the parameter data for ACCESS CONTROL OUT commands.)

5.1.3.3 REPORT ACCESS CONTROLS LOG parameter data format for LUN Mapping Conflicts

The format of the parameter data returned in response to an ACCESS CONTROL IN command with REPORT ACCESS CONTROLS LOG service action and LOG PORTION field indicating LUN Mapping conflicts is shown in Table 19.

TABLE 19. REPORT ACCESS CONTROLS LOG parameter data format for LUN Mapping conflicts

| Byte | Bit | | | | | | | |
|------|-----------------------------------|---|---|---|---|---|-------------|-----|
| | 7 | 6 | 5 | 4 | 3 | 2 | 1 | 0 |
| 0 | MSB | | | | | | | |
| 3 | ADDITIONAL LENGTH ($n-7$) | | | | | | | LSB |
| 4 | RESERVED | | | | | | | |
| 5 | RESERVED | | | | | | LOG PORTION | |
| 6 | MSB | | | | | | | |
| 7 | LUN MAPPING CONFLICTS COUNTER | | | | | | | LSB |
| 12 | | | | | | | | |
| n | LUN MAPPING CONFLICTS LOG PAGE(S) | | | | | | | |

The ADDITIONAL LENGTH field shall contain a count of the number of bytes in the remaining parameter data. The value in this field shall contain the actual number of bytes available without consideration for insufficient ALLOCATION LENGTH in the requesting CDB.

The LOG PORTION field shall be set to 10b to indicate which portion of the access controls log is reflected in the rest of the parameter data.

The LUN MAPPING CONFLICTS COUNTER shall contain the LUN Mapping Conflicts Counter maintained by the access controls coordinator.

The LUN MAPPING CONFLICTS LOG PAGE(S) shall contain a description of the LUN Mapping conflict log entries as recorded by the access controls coordinator (see 4.2.1). The format for these entries is found in Table 20.

TABLE 20. LUN MAPPING CONFLICTS LOG PAGE(S) data format

| Byte | Bit | | | | | | | |
|------|-------------------------|---|---|---|---|---|---|-----|
| | 7 | 6 | 5 | 4 | 3 | 2 | 1 | 0 |
| 0 | MSB | | | | | | | |
| 3 | DEFAULT LUNs GENERATION | | | | | | | LSB |
| 4 | MSB | | | | | | | |
| 7 | TIME STAMP | | | | | | | LSB |
| 8 | MSB | | | | | | | |
| 31 | TRANSPORTID | | | | | | | LSB |
| 32 | MSB | | | | | | | |
| 39 | TRANSPORTID LUN | | | | | | | LSB |
| 40 | MSB | | | | | | | |
| 47 | TRANSPORTID DEFAULT LUN | | | | | | | LSB |
| 48 | MSB | | | | | | | |
| 71 | ACCESSID | | | | | | | LSB |
| 72 | MSB | | | | | | | |
| 79 | ACCESSID LUN | | | | | | | LSB |
| 80 | MSB | | | | | | | |
| 87 | ACCESSID DEFAULT LUN | | | | | | | LSB |

The DEFAULT LUNs GENERATION shall be set to any value of the Default LUNs Generation integer maintained by the access controls coordinator which is consistent with the Default LUN fields in the remaining portion of the page. This may be the current value (preferred) or the value at the time the event was recorded.

The TIME STAMP field shall be set to the value of the (optional) time stamp at the time the LUN Mapping conflict event was recorded. See 4.10.

The remaining portion of the page shall indicate details of the LUN Mapping conflict event.

The TRANSPORTID portion of the page shall indicate the entry from the ACL which applies to the initiator issuing the command (ACCESS CONTROLS OUT with ACCESS ID ENROLL service action) which precipitated the LUN Mapping conflict event.

The ACCESSID portion of the page shall indicate the entry from the ACL which applies to the AccessID enrolled by the initiator issuing the command which precipitated the event.

Note that in both the TransportID and AccessID portions, the DEFAULT LUN fields shall be consistent with the DEFAULT LUNs GENERATION value in the top portion of the page.

5.1.4 CLEAR ACCESS CONTROLS LOG service action (Mandatory)

The CLEAR ACCESS CONTROLS LOG service action of the ACCESS CONTROL IN command is used by an application client to instruct the access controls coordinator to reset a specific access control log counter to zero and to clear a portion of the access controls log.

The SERVICE ACTION-SPECIFIC DATA2 field in the CDB shall have the structure specified in Table 13 and the LOG PORTION of this field shall be interpreted according to Table 14.

The LOG PORTION shall not indicate key overrides (00b). If this is the case, then the device server shall return CHECK CONDITION status, with sense data set to ILLEGAL REQUEST, INVALID FIELD IN CDB.

If the access controls coordinator is in the default state where there is no ACL data and no Management Identifier Key, the device server shall respond with GOOD status and return no data, regardless of the value of any other field in the CDB.

If the access controls coordinator has a non-empty ACL data (including an established Management Identifier Key), the SERVICE ACTION-SPECIFIC DATA field in the CDB shall contain the current Management Identifier Key maintained by the access controls coordinator. If this is not the case, the device server shall return no data and respond with CHECK CONDITION, sense key ILLEGAL REQUEST, additional sense data set to ACCESS DENIED - INVALID MGMT ID KEY and the access controls coordinator shall record the event in the invalid keys portion of the access controls log and take no other action.

The ALLOCATION LENGTH in the CDB shall be zero; no data shall be transferred. If the ALLOCATION LENGTH is not zero, then device server shall return CHECK CONDITION with sense key ILLEGAL REQUEST and additional sense code of INVALID FIELD IN CDB.

If the LOG PORTION field indicates any value other than key overrides and the SERVICE ACTION-SPECIFIC DATA field matches the Management Identifier Key, then the access controls coordinator shall reset the counter to zero and clear the additional log information for that portion of the log specified by the LOG PORTION field. The device server shall return status GOOD.

5.1.5 MANAGE OVERRIDE LOCKOUT TIMER service action (Mandatory)

The MANAGE OVERRIDE LOCKOUT TIMER service action of the ACCESS CONTROLS IN command is used by an application client to manage the Override Lockout Timer (see 4.6).

The SERVICE ACTION-SPECIFIC DATA2 field in the CDB shall have the structure specified in Table 21.

TABLE 21. MANAGE OVERRIDE LOCKOUT TIMER SERVICE ACTION-SPECIFIC DATA2 field

| Byte | Bit | | | | | | | |
|------|--------------------------------|---|---|---|---|---|---|-----|
| | 7 | 6 | 5 | 4 | 3 | 2 | 1 | 0 |
| 0 | MSB | | | | | | | |
| 1 | INITIAL OVERRIDE LOCKOUT TIMER | | | | | | | LSB |
| 2 | MSB | | | | | | | |
| 3 | ALLOCATION LENGTH | | | | | | | LSB |

If the access controls coordinator is in the default state where there is no ACL data and no Management Identifier Key, the device server shall respond with GOOD status and return no data, regardless of the value of any other field in the CDB.

If the ALLOCATION LENGTH field in the SERVICE ACTION-SPECIFIC DATA2 field is zero, then the SERVICE ACTION-SPECIFIC DATA field and the INITIAL OVERRIDE LOCKOUT TIMER field of the SERVICE ACTION-SPECIFIC DATA2 field shall be ignored. In this case, the access controls coordinator shall restart the Override Lockout Timer. That is, it shall reset the value of this timer to the current Initial Override Lockout Timer. The device server shall respond with status GOOD and transfer no data.

AUTHOR'S NOTE: *we are overloading the meaning of the Allocation Length field. If zero, then restart the timer. If not zero, then it must be at least 8, sufficient to transfer the response parameter data. Furthermore, it also means that all other fields in the CDB must be checked.*

If the ALLOCATION LENGTH field in the SERVICE ACTION-SPECIFIC DATA2 field is not zero, then this field shall be at least eight (8). If the ALLOCATION LENGTH is not zero and less than eight (8), then device server shall

return CHECK CONDITION with sense key ILLEGAL REQUEST and additional sense code of INVALID FIELD IN CDB.

If the ALLOCATION LENGTH field in the SERVICE ACTION-SPECIFIC DATA2 field is at least eight (8), and the access controls coordinator has a non-empty ACL data (including an established Management Identifier Key), the SERVICE ACTION-SPECIFIC DATA field in the CDB shall contain the current Management Identifier Key maintained by the access controls coordinator. If this is not the case, the device server shall return no data and respond with CHECK CONDITION, sense key ILLEGAL REQUEST, additional sense data set to ACCESS DENIED - INVALID MGMT ID KEY and the access controls coordinator shall record the event in the invalid keys portion of the access controls log and take no other action.

If the ALLOCATION LENGTH field in the SERVICE ACTION-SPECIFIC DATA2 field is at least eight (8) and the SERVICE ACTION-SPECIFIC DATA field matches the current Management Identifier Key, then the following shall be performed by the access controls coordinator:

- 1.prepare the parameter data as spiffiest in Table 22;
- 2.reset the Initial Override Lockout Timer to the value of the INITIAL OVERRIDE LOCKOUT TIMER in the SERVICE ACTION-SPECIFIC DATA2 field in the CDB;
- 3.restart the Override Lockout Timer to the new initial value.

In this case, the device server shall respond with GOOD status and return the parameter data to the application client.

TABLE 22. MANAGE OVERRIDE LOCKOUT TIMER parameter data format

| Byte | Bit | | | | | | | |
|------|--------------------------------------|---|---|---|---|---|---|-----|
| | 7 | 6 | 5 | 4 | 3 | 2 | 1 | 0 |
| 0 | | | | | | | | |
| 1 | RESERVED | | | | | | | |
| 2 | MSB | | | | | | | |
| 3 | CURRENT OVERRIDE LOCKOUT TIMER | | | | | | | LSB |
| 4 | MSB | | | | | | | |
| 5 | PRIOR INITIAL OVERRIDE LOCKOUT TIMER | | | | | | | LSB |
| 6 | MSB | | | | | | | |
| 7 | KEY OVERRIDES COUNTER | | | | | | | LSB |

The CURRENT OVERRIDE LOCKOUT TIMER shall be set to the current value of the Override Lockout Timer.

The PRIOR INITIAL OVERRIDE LOCKOUT TIMER shall be set to the value of the Initial Override Lockout Timer as established by the last successful MANAGE OVERRIDE LOCKOUT TIMER service action. (This is value prior to instantiating any change as a consequence of the present service action.)

The KEY OVERRIDES COUNTER shall be set to the value of the Key Overrides Counter in the access controls log (see 4.10).

5.1.6 REQUEST PROXY TOKEN service action (Optional)

The REQUEST PROXY TOKEN service action of the ACCESS CONTROL IN command is used by an initiator to obtain from the access controls coordinator a Proxy Token that it can use to grant a third-party temporary access to a logical unit to which it already has non-proxy access. This is used in conjunction with the other PROXY service actions of the ACCESS CONTROL IN and ACCESS CONTROL OUT commands. If this service action is not supported by the access controls coordinator, the device server shall

return CHECK CONDITION status, with sense data indicating ILLEGAL REQUEST - INVALID FIELD IN CDB.

The ALLOCATION LENGTH in the CDB shall be at least eight (8), sufficient for a Proxy Token. If the ALLOCATION LENGTH is less than eight (8), then device server shall return CHECK CONDITION with sense key ILLEGAL REQUEST and additional sense code of INVALID FIELD IN CDB.

The SERVICE ACTION-SPECIFIC DATA field shall contain a Logical Unit Number as might be reported in the REPORT LUNS command.

If the Logical Unit Number corresponds to a logical unit accessible through either a TransportID or an enrolled AccessID for an initiator in the enrolled state, and the access controls coordinator has sufficient resources, then the device server shall respond with GOOD status and return in the parameter data an eight (8) byte Proxy Token. This token (while valid, see 4.5.1) can be used by any initiator to gain temporary access to the associated logical unit via a ASSIGN PROXY LUN service action.

If the Logical Unit Number does not correspond to an accessible logical unit as indicated above, then the following rules apply:

- a) if the Logical Unit Number does not correspond to an accessible logical unit, then the device server shall respond with CHECK CONDITION status, sense key of ILLEGAL REQUEST and ASC/ASCQ set to ACCESS DENIED - INVALID LU IDENTIFIER;
- b) if the Logical Unit Number corresponds to a logical unit accessible only through a proxy token, then the device server shall respond with CHECK CONDITION status, sense key of ILLEGAL REQUEST and ASC/ASCQ set to ACCESS DENIED - INVALID LU IDENTIFIER;
- c) if the Logical Unit Number corresponds to a logical unit accessible only through an enrolled AccessID for that initiator and the initiator is in the de-enrolled state, then the device server shall respond with CHECK CONDITION status, sense key of ILLEGAL REQUEST and ASC/ASCQ set to ACCESS DENIED - INITIATOR DE-ENROLLED.

In these cases, no parameter data is returned.

If the access controls coordinator does not have enough resources to create and manage a new Proxy Token, the device server shall respond with CHECK CONDITION status, sense key of ILLEGAL REQUEST and ASC/ASCQ set to INSUFFICIENT ACCESS CONTROL RESOURCES.

6.0 ACCESS CONTROL OUT Command

The ACCESS CONTROL OUT command (see Table 23) is used to request service actions by the access controls coordinator to limit or grant access to the logical units to initiators. The command shall be used in conjunction with the ACCESS CONTROL IN command. This command shall not be affected by reservations or persistent reservations.

This command should only be sent to LUN0 and processed by the access controls coordinator. It should be rejected by the device server if addressed to any other LUN with CHECK CONDITION status, sense key of ILLEGAL REQUEST and additional sense code of INVALID OPCODE.

TABLE 23. ACCESS CONTROL OUT command

| Byte | Bit | | | | | | | |
|------|-----------------------|---|---|----------------|---|---|-----|---|
| | 7 | 6 | 5 | 4 | 3 | 2 | 1 | 0 |
| 0 | OPERATION CODE (87h) | | | | | | | |
| 1 | RESERVED | | | SERVICE ACTION | | | | |
| 2 | RESERVED | | | | | | | |
| 9 | | | | | | | | |
| 10 | MSB | | | | | | | |
| 13 | PARAMETER LIST LENGTH | | | | | | LSB | |
| 14 | RESERVED | | | | | | | |
| 15 | CONTROL | | | | | | | |

Fields in the ACCESS CONTROL OUT parameter list specify the information required to perform a particular access control service action.

A description of the additional fields in this command are found in the subclause for each service action.

6.1 ACCESS CONTROL OUT Service Actions

6.1.1 MANAGE ACL service action (Mandatory)

The MANAGE ACL version of the ACCESS CONTROL OUT command is used by an application client to authorize access or revoke access to a logical unit or logical units by initiators. This service action adds, changes or removes an entry or multiple entries in the access controls coordinator's ACL. This service action is mandatory if the ACCESS CONTROL OUT command is supported.

The PARAMETER LIST LENGTH field indicates the amount of data which the initiator shall send to the access controls coordinator in the Data-Out buffer. The structure of the data is as described in 6.1.1.1. If this value is zero, then no data shall be transferred. This is not an error condition and shall result in no changes to the access controls coordinator's state.

Any of the following conditions in any parameter page or header require the device server to respond with CHECK CONDITION, sense key ILLEGAL REQUEST, and additional sense code INVALID FIELD IN PARAMETER DATA and also make no changes to the access controls coordinator's state:

- a) the INITIATOR TYPE field indicates an unsupported value;
- b) the INITIATOR TYPE=01h (TransportID) and the INITIATOR IDENTIFIER field is invalid as specified in the relevant protocol standard;
- c) two ACL Entry Pages contain the same INITIATOR TYPE and INITIATOR IDENTIFIER;
- d) the LUNS GENERATION field in the header of the parameter data does not match the current value maintained by the access controls coordinator.

NOTE: it is the responsibility of the application client to get (via the REPORT LU DESCRIPTORS service action) the current association of default LUN values to logical units (and the generation value for that association) prior to issuing this service action.

If the access controls coordinator cannot complete the command because it has insufficient resources to implement the command, the device server shall return a CHECK CONDITION with sense key ILLEGAL REQUEST and additional sense data of INSUFFICIENT ACCESS CONTROL RESOURCES. In this case, no changes shall be made to the access controls coordinator's state.

6.1.1.1 MANAGE ACL parameter list format

The format of the parameter list provided for an ACCESS CONTROL OUT command with MANAGE ACL service action is shown in Table 24. The ACL ENTRY PAGE(S) are described in 6.1.1.1.1 and 6.1.1.1.2.

TABLE 24. MANAGE ACL parameter list format

| Byte | Bit | | | | | | | |
|----------|-------------------------------|----------|---|---|---|---|---|-----|
| | 7 | 6 | 5 | 4 | 3 | 2 | 1 | 0 |
| 0 | MSB | | | | | | | |
| 7 | MANAGEMENT IDENTIFIER KEY | | | | | | | LSB |
| 8 | MSB | | | | | | | |
| 15 | NEW MANAGEMENT IDENTIFIER KEY | | | | | | | LSB |
| 16 | RESERVED | | | | | | | |
| 17 | FLUSH | RESERVED | | | | | | |
| 18 | RESERVED | | | | | | | |
| 19 | RESERVED | | | | | | | |
| 20 | MSB | | | | | | | |
| 23 | LUNS GENERATION | | | | | | | LSB |
| 24 | | | | | | | | |
| <i>n</i> | ACL ENTRY PAGES(s) | | | | | | | |

The MANAGEMENT IDENTIFIER KEY is used to compare with the current Management Identifier Key maintained by the access controls coordinator. If the access controls coordinator is in the default state, then this field is ignored. Otherwise, if the MANAGEMENT IDENTIFIER KEY in the parameter list does not match the access controls coordinator's current Management Identifier Key, the device server shall return CHECK CONDITION with sense key ILLEGAL REQUEST, additional sense data set to ACCESS DENIED - INVALID MGMT ID KEY and take no other action and the access controls coordinator shall record the event in the invalid keys portion of the access controls log. If the access controls coordinator successfully implements the requested service action, the access controls coordinator resets its Management Identifier Key to the value specified in the NEW MANAGEMENT IDENTIFIER KEY field.

The FLUSH bit of one instructs the access controls coordinator to move any initiator in the enrolled state into the de-enrolled state.

The LUNS GENERATION shall be set to the current value of the Default LUNs Generation integer maintained by the access controls coordinator.

The ACL ENTRY PAGE(S) that may follow in the parameter list provide additional changes to the ACL data.

Implementation of changes to the access control state of the device follow these rules:

- a) no change to the access control state of the device shall occur if the command cannot be processed with status GOOD;
- b) if the command can result in status GOOD, the following shall be instantiated as a single indivisible event:

- 1.changes dictated in the fields in the header of the parameter list are implemented;
- 2.changes dictated by ACL Entry Pages are implemented;
- 3.multiple ACL Entry Pages are implemented sequentially;
- 4.if an ACL Entry Page contains conflicting instructions, the last instruction within the page takes precedence;
- 5.if an initiator's LUN Map on the basis of an enrolled AccessID is changed in such a way that a LUN value in the current LUN Map would change the logical unit to which it refers (that is, the LUN value would point to a different logical unit in the new LUN Map), then the affected initiator shall be transitioned to the not-enrolled state.

An ACL Entry Page contains conflicting instructions if either of the following occurs:

- a) two LUN/default LUN pairs appear with the same LUN value and different default LUN values, or
- b) two LUN/default LUN pairs appear with the same default LUN value and different LUN values.

The structure of ACL Entry pages and the action to be taken is determined by a PAGE CODE field as defined in Table 25. Details of the contents of each page are described in subsequent subclauses.

TABLE 25. ACL Entry PAGE CODE definitions

| Page Code | Action | Clause |
|-----------|-------------------------|-----------|
| 00h | Grant | 6.1.1.1.1 |
| 01h | Revoke | 6.1.1.1.1 |
| 02h | Grant All | 6.1.1.1.1 |
| 03h | Revoke All | 6.1.1.1.1 |
| 04h | Revoke Proxy Token | 6.1.1.1.2 |
| 05h | Revoke All Proxy Tokens | 6.1.1.1.2 |
| 06b-FFh | Reserved | |

6.1.1.1.1 MANAGE ACL parameter data Grant, Revoke, Grant All, Revoke All page formats

The Grant, Revoke, Grant All and Revoke All page formats for the MANAGE ACL service action is given in Table 26.

TABLE 26. Grant, Revoke, Grant All, Revoke All page formats

| Byte | Bit | | | | | | | |
|-------|---|---|---|---|---|---|---|-----|
| | 7 | 6 | 5 | 4 | 3 | 2 | 1 | 0 |
| 0 | PAGE CODE (00h-03h) | | | | | | | |
| 1 | RESERVED | | | | | | | |
| 2 | PAGE LENGTH ($m-3$) | | | | | | | |
| 3 | | | | | | | | |
| 4 | RESERVED | | | | | | | |
| 5 | IDENTIFIER TYPE | | | | | | | |
| 6 | IDENTIFIER LENGTH ($n-7$) | | | | | | | |
| 7 | | | | | | | | |
| 8 | MSB | | | | | | | |
| n | INITIATOR IDENTIFIER | | | | | | | LSB |
| $n+1$ | LUN/DEFAULTLUN LIST (Grant) or DEFAULTLUN LIST (Revoke) | | | | | | | |
| m | | | | | | | | |

The IDENTIFIER TYPE and INITIATOR IDENTIFIER fields are described in 4.4.2. The IDENTIFIER LENGTH is described in 5.1.1.1.1.

NOTE: All currently defined Identifier Types require the Identifier Length be set to 24 (see Table 1).

The PAGE LENGTH field shall indicate the number of additional bytes required for this page.

For the Grant page, the LUN/DEFAULTLUN LIST shall contain a set of LUN/default LUN pairs (eight (8) bytes for each component of the pair). If any default LUN value is not valid at the access controls coordinator or any LUN value cannot be supported in a LUN Map, the device server shall fail the command with CHECK CONDITION status, sense key of ILLEGAL REQUEST and additional sense code of ACCESS DENIED - INVALID LU IDENTIFIER.

The Grant page instructs the access controls coordinator to allow access to the referenced by the listed default LUNs in each pair and to the initiator or initiators identified by the specified INITIATOR IDENTIFIER. The target shall modify each affected initiator's LUN Map by adding entries for the specified LUN/default LUNs and adjusting the LUN Map according to the rules of 4.2.

For the Revoke page, the DEFAULTLUN LIST shall contain a list of default LUNs (eight bytes each). If any default LUN value is not valid, the device server shall disregard this entry in the list. The Revoke page instructs the access controls coordinator to disallow access to the listed logical units by the initiator or initiators identified by the specified INITIATOR IDENTIFIER. The access controls coordinator shall modify each affected initiator's LUN Map by removing entries for the specified logical units. It is not an error condition if the default LUN references a valid logical unit, but that logical unit is not accessible to the specified initiator(s).

The Grant All and Revoke All pages shall contain an empty LUN/DEFAULT LUN LIST or DEFAULT LUN LIST. That is, there shall be no data in this page after the last byte of the INITIATOR IDENTIFIER field. The Grant All pages allows access to all logical units to the specified initiator(s). The access controls coordinator modifies the LUN Map for each affected initiator by establishing a default LUN Map. (The default LUN Map is the map that would be created if the access controls coordinator were in the default state.) The Grant All page is implemented in the same manner as if the corresponding Grant page contained a complete list of valid LUN/default LUN pairs which would instantiate the default LUN Map. The Revoke All pages removes access to all logical units by the specified initiator(s). The Revoke All page is implemented in the same manner as if the corresponding Revoke page contained the complete list of valid default LUNs.

6.1.1.1.2 MANAGE ACL parameter data Revoke Proxy Token and Revoke All Proxy Tokens page formats

The Revoke Proxy Token and Revoke All Proxy Tokens page formats for the MANAGE ACL service action is given in Table 27.

TABLE 27. Revoke Proxy Token and Revoke All Proxy Tokens page formats

| Byte | Bit | | | | | | | |
|------|-----------------------|---|---|---|---|---|---|---|
| | 7 | 6 | 5 | 4 | 3 | 2 | 1 | 0 |
| 0 | PAGE CODE (04h-05h) | | | | | | | |
| 1 | RESERVED | | | | | | | |
| 2 | | | | | | | | |
| 3 | PAGE LENGTH ($m-3$) | | | | | | | |
| 4 | | | | | | | | |
| m | PROXY TOKEN LIST | | | | | | | |

The PAGE LENGTH field shall indicate the number of additional bytes required for this page.

For the Revoke Proxy Token page, the PROXY TOKEN LIST shall contain a list of Proxy Tokens (eight (8) bytes each). This instructs the access controls coordinator to revoke each of the listed Proxy Tokens. It is not an error condition if a Proxy Token specified in this page is not currently valid. In this case, no action is taken by the access controls coordinator with respect to this token.

For the Revoke All Proxy Tokens page, the PROXY TOKEN LIST shall be empty. This instructs the access controls coordinator to revoke all existing Proxy Tokens.

Multiple Revoke Proxy Token and Revoke All Proxy Tokens pages may be included in the parameter data. They are processed sequentially.

6.1.2 DISABLE ACCESS CONTROLS service action (Mandatory)

The DISABLE ACCESS CONTROLS service action of the ACCESS CONTROL OUT command is used by an application client to return the access controls coordinator to its default state where there are no access controls or ACL data.

For the DISABLE ACCESS CONTROLS service action, the parameter list is described in Table 28. The PARAMETER LIST LENGTH field in the CDB shall be set to at twelve (12). If not, the device server shall return CHECK CONDITION, sense key ILLEGAL REQUEST and additional sense code INVALID FIELD IN CDB.

TABLE 28. DISABLE ACCESS CONTROLS and OVERRIDE MGMT ID KEY parameter list format

| Byte | Bit | | | | | | | |
|------|---------------------------|---|---|---|---|---|---|---|
| | 7 | 6 | 5 | 4 | 3 | 2 | 1 | 0 |
| 0 | RESERVED | | | | | | | |
| 3 | | | | | | | | |
| 4 | MSB | | | | | | | |
| 11 | MANAGEMENT IDENTIFIER KEY | | | | | | | |
| | LSB | | | | | | | |

The MANAGEMENT IDENTIFIER KEY is used to compare with the current Management Identifier Key maintained by the access controls coordinator. If the MANAGEMENT IDENTIFIER KEY in the parameter list does not match the access controls coordinator's current Management Identifier Key, the device server shall return CHECK CONDITION with sense key ILLEGAL REQUEST, additional sense data of ACCESS DENIED - INVALID MGMT ID KEY and take no other action and the access controls coordinator shall record the event in the invalid keys portion of the access controls log.

Successful completion of the service action requires the access controls coordinator to clear all access restrictions for all logical units, change all initiator LUN Maps to the default map (where LUN equals default LUN for all logical units), change all initiators into the not-enrolled state, set the Management Identifier Key to zero, clear the access controls log (including resetting counters to zero) with the exception of the key overrides portion of the log, and remove any ACL data from persistent memory. Optionally, the access controls coordinator may reset the Default LUNs Generation to its factory default.

6.1.3 ACCESS ID ENROLL service action (Mandatory)

The ACCESS ID ENROLL service action of the ACCESS CONTROL OUT command is used by an initiator to enroll an AccessID with the access controls coordinator. The access controls coordinator shall use this information to possibly modify that initiator's LUN Map and associated access rights and change the enrolled state of the initiator. This service action is mandatory if the ACCESS CONTROL OUT command is supported.

The parameter list contains the AccessID in the format of Table 2. The PARAMETER LIST LENGTH field shall be twenty-four (24). If not, then the device server shall return CHECK CONDITION, sense key ILLEGAL REQUEST, and additional sense code INVALID FIELD IN CDB.

If the initiator is in the enrolled or de-enrolled state under a given AccessID and the parameter data contains a different AccessID, then the device server shall respond with CHECK CONDITION status, with sense key set to ILLEGAL REQUEST and ASC/ASCQ set to ACCESS DENIED - ENROLLMENT CONFLICT.

If the initiator is in the enrolled or de-enrolled state under given AccessID and the parameter data contains a matching AccessID, then the device server shall respond with GOOD status, and the access controls coordinator shall place the initiator in the enrolled state and make no change to the LUN Map for that initiator.

If the initiator is in the not-enrolled state, and the AccessID in the parameter data has any access rights associated with it in the ACL data, the access controls coordinator shall place the initiator into the enrolled state and modify the LUN Map according to the specification in 4.2. Further, the device server shall respond according to the following:

- a) if the enrollment does not create a LUN Mapping conflict (see 4.2.1), the device server shall respond with GOOD status;
- b) if the enrollment creates a LUN Mapping conflict, the device server shall respond with CHECK CONDITION status, and sense key of RECOVERED ERROR, with additional sense data of ACCESS DENIED - LUN MAPPING CONFLICT and the access controls coordinator shall record the event in the LUN Mapping conflicts portion of the access controls log.

NOTE: The above informs the initiator that a LUN Mapping conflict occurred but allows for the access controls coordinator to instantiate as much of the AccessID LUN Map as possible. The initiator may (through means beyond the scope of this standard) inform the application client managing access controls that a conflict occurred so that the application may take whatever corrective action is necessary.

If the AccessID in the parameter data has no access rights associated with it, then the initiator stays in the not-enrolled state and the device server responds with CHECK CONDITION status, sense key of ILLEGAL REQUEST and additional sense code set to ACCESS DENIED - NO ACCESS RIGHTS.

6.1.4 CANCEL ENROLLMENT service action (Mandatory)

The CANCEL ENROLLMENT service action of the ACCESS CONTROL OUT command is used by an initiator to remove its enrollment with the access controls coordinator. Successful completion of this command changes the state of the initiator to the not-enrolled state.

This service action shall always return status GOOD regardless of the enrolled state of the initiator. The affect of this command is to remove from that initiator's LUN Map any entries which were included as a result of an enrollment by that initiator. Any subsequent commands addressed to the logical units no longer accessible are handled according to the rules of 4.9.

This command should be used by an initiator prior to any period where use of its accessible logical units will be suspended for an extensive period of time (e.g., if the host is preparing to shutdown). This allows the access controls coordinator to free any resources allocated to manage the enrollment for that initiator.

There is no parameter data for this command. The PARAMETER LIST LENGTH in the CDB for this service action shall be set to zero.

6.1.5 OVERRIDE MGMT ID KEY service action (Mandatory)

The OVERRIDE MGMT ID KEY service action of the ACCESS CONTROLS OUT command is used by an application client to override the current Management Identifier Key maintained by the access controls coordinator. This is intended to be used in a failure situation where the managing application client no longer has access to its copy of this key.

Successful completion of this service action depends on the state of the Override Lockout Timer managed by the access controls coordinator.

The PARAMETER LIST LENGTH field in the CDB shall be set to twelve (12). If not, then the device server shall respond with CHECK CONDITION status and sense data of ILLEGAL REQUEST, INVALID FIELD IN CDB. If this field is set to twelve (12), then the parameter data shall be as specified in Table 28. The MANAGEMENT IDENTIFIER KEY field shall contain a new Management Identifier Key.

If the Override Lockout Timer managed by the access controls coordinator is non-zero, then the device server shall respond with CHECK CONDITION status, sense key of ILLEGAL REQUEST, and additional sense code set to ACCESS DENIED - OVERRIDE LOCKOUT.

If the Override Lockout Timer managed by the access controls coordinator is zero, then the access controls coordinator shall reset the current Management Identifier Key to the value in the parameter data. The device server shall respond with GOOD status.

In both cases of the setting for the Override Lockout Timer, the access controls coordinator shall record this event in the key overrides portion of the access controls log according to the specification in 4.10. No other action shall be taken with respect to the access controls state of the device.

6.1.6 REVOKE PROXY TOKEN service action (Optional)

The REVOKE PROXY TOKEN service action of the ACCESS CONTROL OUT command is used by an initiator to cancel all proxy access rights to a logical unit which were granted to third parties under the specified Proxy Token. This is used in conjunction with the other PROXY-related service actions of the ACCESS CONTROL IN and ACCESS CONTROL OUT commands.

If supported by the access controls coordinator, this service action shall always return status GOOD. Otherwise, the device server shall return CHECK CONDITION status, and sense data of ILLEGAL REQUEST, INVALID FIELD IN CDB.

The PARAMETER LIST LENGTH field in the CDB shall be set to eight (8) bytes. If not, then the device server shall respond with CHECK CONDITION status and sense data of ILLEGAL REQUEST, INVALID FIELD IN CDB. If this field is set to eight (8), then the parameter data shall contain one eight (8) byte field specifying a Proxy Token.

If the Proxy Token in the parameter data is not valid, that is, not associated with any logical unit at the access controls coordinator, then no further action is taken by the access controls coordinator.

If the Proxy Token in the parameter data is valid, that is, associated with a logical unit at the access controls coordinator, then the access controls coordinator shall take the following additional actions:

- a) invalidate the Proxy Token;
- b) deny access to that logical unit by any initiator whose rights were granted under that Proxy Token by a REQUEST PROXY LUN service action; that is, remove from all such initiator's LUN Map all proxy entries for this logical unit.

6.1.7 REVOKE ALL PROXY TOKENS service action (Optional)

The REVOKE ALL PROXY TOKENS service action of the ACCESS CONTROL OUT command is used by an initiator to cancel all proxy access rights to a logical unit which were granted to third parties under all Proxy Tokens. This is used in conjunction with the other PROXY-related service actions of the ACCESS CONTROL IN and ACCESS CONTROL OUT commands.

If supported by the access controls coordinator, this service action shall always return status GOOD. Otherwise, the device server shall return CHECK CONDITION status, and sense data of ILLEGAL REQUEST, INVALID FIELD IN CDB.

The parameter data for this command shall be eight (8) bytes long. It shall contain a LUN value.

If the LUN value is not in the LUN Map for the requesting initiator, then no further action is taken by the access controls coordinator.

If the LUN value is in the LUN Map for the requesting initiator but this entry was established on the basis of a Proxy Token, then no further action is taken by the access controls coordinator.

If the LUN value is in the LUN Map for the requesting initiator and was established on the basis of a non-proxy access right, then the access controls coordinator shall take the following additional actions:

- a) invalidate all Proxy Tokens associated to the logical unit referenced by the LUN value in the requesting initiator's LUN Map;
- b) deny access to that logical unit by any initiator whose rights were granted under any Proxy Token by a REQUEST PROXY LUN service action; that is, remove from all such initiator's LUN Map all proxy entries for this logical unit.

6.1.8 ASSIGN PROXY LUN service action (Optional)

The ASSIGN PROXY LUN service action of the ACCESS CONTROL OUT command is used by an initiator to request the access controls coordinator grant access to a logical unit under the rights of a Proxy Token and to assign that logical unit a particular LUN value in that initiator's LUN Map. This is used in conjunction with the other PROXY-related service actions of the ACCESS CONTROL IN and ACCESS CONTROL OUT commands.

If this service action is not supported by the access controls coordinator, the device server shall return CHECK CONDITION status, and sense data of ILLEGAL REQUEST, INVALID FIELD IN CDB.

The PARAMETER LIST LENGTH field in the CDB shall be set to sixteen (16). The parameter data shall contain the eight (8) byte Proxy Token associated with a logical unit followed by an eight (8) byte LUN value.

If the Proxy Token is not valid, then the device server shall return CHECK CONDITION status, sense key set to ILLEGAL REQUEST and ASC/ASCQ set to ACCESS DENIED - INVALID PROXY TOKEN.

If the Proxy Token is valid but the access controls coordinator cannot assign the requested LUN value to the associated logical unit (that is, modify the initiator's LUN Map with an entry with this LUN referencing the logical unit), then the device server shall return CHECK CONDITION status, sense key set to ILLEGAL REQUEST and ASC/ASCQ set to ACCESS DENIED - INVALID LU IDENTIFIER. Furthermore, the sense data shall be modified as follows. The SENSE-KEY SPECIFIC bit shall be set as described in 7.22.1 (of SPC-2 revision 15) with the FIELD POINTER field indicating the first byte of the requested LUN (as counted within the full parameter data) which differs from a value which can be supported by the access controls coordinator. Additionally, the next eight bytes (if available) beyond the last byte of the FIELD POINTER may include a LUN value which the access controls coordinator can support for this proxy token. In this case, the LUN Map for the initiator shall not be changed.

NOTE: Such a failure scenario can happen only in two rare cases. First, the LUN is already assigned in the initiator's LUN Map. The initiator can know this in advance, however, and should not be making this request. Second, if the LUN value, for any reason, cannot be supported by the access controls coordinator.

If the Proxy is valid but the access controls coordinator has insufficient resources to perform the requested action, then the device server shall respond with CHECK CONDITION status, sense key of ILLEGAL REQUEST and additional sense data of INSUFFICIENT ACCESS CONTROL RESOURCES.

If the Proxy is valid and the access controls coordinator has sufficient resources, then the device server shall return status GOOD and modify the LUN Map for that initiator as requested.

6.1.9 RELEASE PROXY LUN service action (Optional)

The RELEASE PROXY LUN service action of the ACCESS CONTROL OUT command is used by an initiator to remove a LUN from its LUN Map which was created with a Proxy Token and the ASSIGN PROXY LUN service action. This is used in conjunction with the other PROXY-related service actions of the ACCESS CONTROL IN and ACCESS CONTROL OUT commands.

If this service action is not supported by the access controls coordinator, the device server shall return CHECK CONDITION status, and sense data of ILLEGAL REQUEST, INVALID FIELD IN CDB.

This command should be used by an initiator when its access to that logical unit is no longer required under its proxy rights (e.g., when a copy server has completed a specific third party copy service under the proxy). This allows the access controls coordinator to free any resources allocated to manage the proxy for that initiator.

The PARAMETER LIST LENGTH field in the CDB shall be set to eight (8). The parameter data shall contain the eight (8) byte LUN value as was used in the ASSIGN PROXY LUN service action.

If the LUN value was not assigned in the LUN Map to a logical unit by an ASSIGN PROXY LUN service action, the device server shall return CHECK CONDITION status, with sense data ILLEGAL REQUEST and additional sense data of INVALID FIELD IN PARAMETER DATA.

If the LUN value was assigned in the LUN Map to a logical unit by an ASSIGN PROXY LUN service action, the access controls coordinator shall remove this entry from the LUN Map and the device server shall return status GOOD.

A. Changes required in SAM-x.

This section contains some changes required in SAM-x to deal with Task Management in the presence of access control. (Section numbers correspond to SAM-2, rev. 10).

A.1. Changes for the end of section 6.0.

The device server response to task management requests is subject to the access control state of the access controls coordinator (as instantiated by ACCESS CONTROL OUT commands) as follows:

- a) a task management request of ABORT TASK, ABORT TASK SET or CLEAR ACA shall be unaffected by the presence of access restrictions;
- b) a task management request of CLEAR TASK SET or LOGICAL UNIT RESET received from an initiator that is denied access to the logical unit (either because it has no access rights or because it is in the de-enrolled state) shall cause no change to the logical unit, but shall receive a response of FUNCTION COMPLETE.
- c) a TARGET RESET task management request shall initiate a logical unit reset as described in 5.6.7 for all logical units to which the initiator has access, and shall cause no change to any logical units to which the initiator is denied access. A response of FUNCTION COMPLETE shall be returned in the absence of any other error condition.

A.2 Additions for section 5.6.6

While the device server response to task management requests is subject to the access rights of the requesting initiator, a target hard reset in response to a reset event within the service delivery subsystem shall be unaffected by access control.

B. Changes required in FCP-x.

This section contains the changes required in FCP-x. This includes the description of the TransportID. (Section numbers correspond to FCP-2, rev. 02).

B.1. Specification of the TransportID

The TransportID structure is 24 bytes long and is described in Table 29.

TABLE 29. TransportID for FCP.

| Byte | Bit | | | | | | | | |
|------|--------------------|---|---|---|---|--------|--------|--------|--|
| | 7 | 6 | 5 | 4 | 3 | 2 | 1 | 0 | |
| 0 | RESERVED | | | | | PA_VAL | PN_VAL | NN_VAL | |
| 1 | | | | | | | | | |
| 3 | RESERVED | | | | | | | | |
| 4 | MSB | | | | | | | | |
| 7 | PROCESS ASSOCIATOR | | | | | | LSB | | |
| 8 | MSB | | | | | | | | |
| 15 | WWPORTNAME | | | | | | LSB | | |
| 16 | MSB | | | | | | | | |
| 23 | WWNODENAME | | | | | | LSB | | |

A PA_VAL bit of one indicates that the PROCESS ASSOCIATOR field is valid. Similarly, the PN_VAL and NN_VAL bits of one indicate that the corresponding WWPORTNAME and WWNODENAME fields, respectively, are valid. A value of zero for any of these bits indicate that the corresponding field is invalid and shall be ignored. At least one of these validity bits must be set to one. If not, then the TransportID is invalid.

If any of the valid fields are inconsistent, that is, they do not correspond to a device in the fabric, then the TransportID is invalid.

B.2. Changes to 6.3

CHANGE:

All tasks, reservations, mode page parameters ...that are logged out are not affected.

TO:

All tasks, reservations, mode page parameters, AccessID enrollment states, and status for image pairs removed by the PRLO operation are set to the state they would have after a SCSI hard reset or power on reset. Only the specified image pairs are logged out. Open exchanges for logged out image pairs shall be terminated by a recovery abort operation. (See 8.1.2.2.) Tasks, reservations, mode page parameters, AccessID enrollment states, and status for image pairs other than those that are logged out are not affected.

B.3. Additional rows required in Table 4:**TABLE 30.** Changes to Table 4 of FCP-2: Clearing effects of SCSI Initiator Actions

| | POWER | RESETLIP | LOGO, PLOGI | ABTS | PRLI, PRLO | TPRLO | TGTRESET | CLEAR | ABORT | LURESET |
|--|----------------|----------|----------------|------|----------------|----------------|----------------|-------|-------|---------|
| ACL and Management Identifier Key | N | N | N | N | N | N | N | N | N | N |
| AccessID enrollment state to de-enrolled state | | | | | | | | | | |
| For all SCSI initiators in enrolled state | Y ^a | Y | Y ^b | N | Y ^b | Y ^c | Y ^a | N | N | N |
| Only for SCSI initiator port initiating action in enrolled state | - | - | Y ^b | N | Y | - | N | N | N | N |

- a. Transition is to de-enrolled or not-enrolled state in implementation dependent manner
- b. For PRLO only and for explicit or implicit LOGO only
- c. Only for the initiator attached to the port in the third party logout page.

C. Changes required in SPI-x.

This section contains the changes required in SPI-x. This includes the description of the TransportID. (Section numbers correspond to SPI-3, rev. 10).

C.1. Specification of the TransportID

The TransportID structure is 24 bytes long and is described in Table 31.

TABLE 31. TransportID for SPI.

| Byte | Bit | | | | | | | |
|------|--------------|---|---|---|---|---|-----|---|
| | 7 | 6 | 5 | 4 | 3 | 2 | 1 | 0 |
| 0 | RESERVED | | | | | | | |
| 1 | | | | | | | | |
| 2 | MSB | | | | | | | |
| 3 | SCSI ADDRESS | | | | | | LSB | |
| 4 | RESERVED | | | | | | | |
| 23 | | | | | | | | |

The SCSI ADDRESS field indicates the SCSI address of the initiator. (See the glossary in SPI-3, 3.1.77.)

C.1. Volatility of the AccessID enrollments

AccessID enrollment state of initiators (established initially with the ACCESS CONTROL OUT command with ACCESS ID ENROLL service action) shall be transitioned by the following events or states:

- a) power cycle of the device server;
- b) hard reset bus condition.

The transition state is implementation dependent subject to the rules of 4.7 (of this proposal).

D Changes to SPC-2 (rev 15)

D.1 Changes to Table 8 of SPC-2 (rev 14)

The following additional line(s) need to be added to Table 8 of SPC-2 (rev 14).

TABLE 32. Additional rows for Table 8, SPC-2 (rev 14)

| Command | Addressed LU is reserved by another initiator [A] | Addressed LU has this type of persistent reservation held by another initiator [B] | | | | |
|-----------------------|---|--|-------------|--|-------------------------------|------------------|
| | | From any initiator | | From registered initiator (RO all types) | From initiator not registered | |
| | | Write Excl | Excl Access | | Write Excl RO | Excl Access - RO |
| ACCESS CONTROL IN/OUT | Allowed | Allowed | Allowed | Allowed | Allowed | Allowed |

D.2 Changes to EXTENDED COPY

In the target descriptors of clauses 7.4.5.1-7.4.5.4, make the following changes. Addition of a 2-bit field called LU ID TYPE in byte 3 (bits 0-1) of the target descriptor which can be used to define the interpretation of the LOGICAL UNIT NUMBER field in bytes 4-11. Change the name of this field to LU IDENTIFIER. Its contents would be interpreted according to the value of the LU ID TYPE as defined in the Table 33.

TABLE 33. LU ID TYPE and LU IDENTIFIER description

| LU ID TYPE | LU IDENTIFIER description |
|------------|---------------------------|
| 00b | Logical Unit Number |
| 01b | Proxy Token |
| 10b-11b | Reserved |

D.3 Changes to Standard INQUIRY parameter data

In the standard INQUIRY data format, Table 52 of SPC-2 rev 15, make the following change. Byte 5, bit 6 is changed from Reserved to ACC (for Access Controls Coordinator). The following additional text be added after the paragraph describing the SCCS bit:

An Access Controls Coordinator (ACC) bit of one indicates that the device contains an access controls coordinator which can be addressed through this logical unit. An ACC bit of zero indicates that no access controls coordinator is present.

E Changes to SBC-x, RBC-x and MMC-x

AUTHOR'S NOTE: *In all of these sections, we're assuming that the LONGLBA bit is defined and supported in the standard (see 99-259r4). Additionally, we leave to the editor of the relevant documents the appropriate clause or subclause under which these changes should be placed.*

We need to add an additional section to each of these standards which describes the DEVICE-TYPE SPECIFIC ADDITIONAL DATA field in the REPORT LU DESCRIPTORS logical unit descriptor parameter data. This new section should contain the following information.

E.1 Changes to SBC-x for REPORT LU DESCRIPTORS service action

The DEVICE-TYPE SPECIFIC ADDITIONAL DATA field in the logical unit descriptor parameter data for the ACCESS CONTROLS IN command with REPORT LU DESCRIPTORS service action shall be defined as follows.

For all Peripheral Device Types covered by this standard, if the RMB bit in the Standard INQUIRY data indicates non-removable medium (RMB equal zero), then this field shall be twelve (12) bytes long. The data shall match the data which would be returned for a successful READ CAPACITY command with LONGLBA bit set to one, and RELADR and PMI bits set to zero. If the RMB bit indicates removable medium (RMB equal to one), this field shall be empty (zero bytes long).

E.2 Changes to RBC-x for REPORT LU DESCRIPTORS service action

The DEVICE-TYPE SPECIFIC ADDITIONAL DATA field in the logical unit descriptor parameter data for the ACCESS CONTROLS IN command with REPORT LU DESCRIPTORS service action shall be defined as follows. For RBC devices, this field shall be twelve (12) bytes long. The data shall match the data which would be returned for a successful READ CAPACITY command with LONGLBA bit set to one, and RELADR and PMI bits set to zero.

E.3 Changes to MMC-x for REPORT LU DESCRIPTORS service action

The DEVICE-TYPE SPECIFIC ADDITIONAL DATA field in the logical unit descriptor parameter data for the ACCESS CONTROLS IN command with REPORT LU DESCRIPTORS service action shall be defined as follows.

For all Peripheral Device Types covered by this standard, if the RMB bit in the Standard INQUIRY data indicates non-removable medium (RMB equal zero), then this field shall be twelve (12) bytes long. The data shall match the data which would be returned for a successful READ CAPACITY command with LONGLBA bit set to one, and RELADR and PMI bits set to zero. If the RMB bit indicates removable medium (RMB equal to one), this field shall be empty (zero bytes long).