

EXABYTE

Exabyte Corporation
1745 38th Street
Boulder, Colorado 80301
Phone (303) 442-4333
Fax (303) 442-4269
Telex 361740

X3T9.2/91-45

April 16, 1991

TO: John Lohmeyer, Chairman X3T9.2

FROM: Chris Pisciotta
Exabyte Corporation
1745 38th Street
Boulder CO 80301
(303) 447-7251

SUBJ: Sequential Access Density Code Corrections

We have recently discovered that the density specifications for 8mm technology in table 9-22, pg 9-41 of rev 10c of the SCSI-2 document are in error. The numbers that are specified for bpmm(bpi) are 2126 (54000). These numbers are actually flux densities, not bit densities. The correct numbers should be 1703 bpmm (43245 bpi). Also, the reference document should be changed to X3B5/89-136B.

Since rev 10d of the SCSI-2 spec is being edited now, I would request that the committee approve this minor change. If this is not possible, then I would submit these changes for inclusion into the SCSI-3 document.